EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			Hole In Air Bag Replace Front Left													
T617	Wodonga - Workshop	Susp\AIR BAG	(Parts Supplied By Maxi-Parts P/O: WW135561)			11/09/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Holes In Guards			11/09/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/09/2026	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	Insp\ANN INSP		15/07/2026	543870	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/07/2026	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\DAMAGE	Upright repair			13/05/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		09/05/2026	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\EBS FAULTS	ABS ISSUES PUSHING FEED BACK INTO PRIME MOVER.		Pending	09/05/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Repair L/H Upright.			09/05/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
					Replace right hand curtain ratchet											
T617	Wodonga - Workshop	Body\STRAPS	Broken handle right front		completed by John	22/04/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\FIFTH WHEE	Replace bushes			08/04/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/04/2026	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			01/04/2026	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
T617	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			01/04/2026	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
			617													
T617	Wodonga - Workshop	Body\TRL REPS	LEFT SIDE CURTAIN RATCHET NOT WORKING			25/03/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Pad slap needed soon	06/03/2026	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	R/H Curtain Ratchet to be Replaced.		completed by KR	26/02/2026	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/12/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
					CALL OUT											
T617	Wodonga - Workshop	Tyres\TP05	Tyres\TP05		Shaun has approved the call out fee on this invoice.	08/12/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
			CURTAIN BUCKLE STRAP													
T617	Wodonga - Workshop	Body\TRL REPS	TIGHTEN UP CURTAIN RATCHETS			27/11/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		27/11/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/10/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
					After hours callout - bp south bound											
					check over indicator issues on trailers											
			Elect\INDICATORS		Found damaged wring behind plug, repair as required											
T617	Wodonga - Workshop	Elect\INDICATORS	WW097333		Repin trailer base on trailer and test all lights -ok	10/10/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	HOT SPARK AUTO ELECTRICAL	TRAILER
T617	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture 27			09/10/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
T617	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			09/10/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
					CHECK NO INDICATORS LHS TRAILER - HAVE INDICATOR ON TRUCK [168] 356.25											
					CHECK OVER - REMOVE PLUGS & FIT TESTER.											
					FOUND INDICATOR WIRED TO REVERSE CIRCUIT & OTHER LIGHTS IN											
					WRONG ORDER.											
					RECTIFY & TEST WITH LIGHT CIRCUIT TESTER - FOUND NO POWER											
					FOR SPECIFIC LIGHT & WIRED INCORRECTLY.											
					INSPECT LOOM & FOUND BREAKS - REMOVE WIRING HARNESS & FIT											
					NEW 7 PIN SOCKET AS REQUIRED.											
T617	Wodonga - Workshop	Elect\INDICATORS	Elect\INDICATORS		FIT SUZI COIL LIGHT WIRE - SECURE & TEST OPERATION	14/08/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	TATIARA TRUCK & TRAILER REPAIRS	TRAILER
T617	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			08/08/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
T617	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 24			06/08/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BORDER BANDAG PTY LTD	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/08/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL FLOOR	Front of floor lifting			03/07/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		03/07/2025	543870	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TOOLBOX	REPAIR TOOLBOX			03/07/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\TRL LEGS	LEGS NEED LUBE.			30/06/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		30/06/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL FLOOR	FRONT OF FLOOR LIFTING.		Unable to to do due to being loaded,,,,pending	30/06/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TOOLBOX	Repair Toolbox hinges.			17/05/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Replace left front curtain ratchet.			15/05/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/05/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	CURTAIN RATCHETS BROKEN.			14/05/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS			23/04/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	IFIX TRUCK CURTAINS	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/04/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/03/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-2-3-4-5-6-7-8-9-10-11-12			26/02/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BEAUREPAIRES	TRAILER
T617	Wodonga - Workshop	Elect\BRK LIGHT	No brake lights.			26/02/2025	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			11/02/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BEAUREPAIRES	TRAILER
T617	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			11/02/2025	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BEAUREPAIRES	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/02/2025	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	13 INCH RIP IN CURTAIN LEFT SIDE.			20/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	No ubolts or shock straps	20/12/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\AIR BAG	Diagnoze Air-Bag Issue.			20/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\AIR BAG	Replace left front air bag.			05/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	Reline Brakes.			04/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Repair Pelmet Rubber.			02/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	FIRST THREE BUCKLES HOLES IN CURTAIN LEFT SIDE.			02/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRAKE ADJ	Grease 5 cams.			02/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis	RH ratchet broken			02/12/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		24/11/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		17/10/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Repair/Patch Tare In L/H Curtain Middle Of Curtain @ Deck Height			17/10/2024	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11	Tyres\TP11			24/09/2024	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BEAUREPAIRES	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Replace Turntable.			14/08/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/08/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Replace left front curtain ratchet.			07/08/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Replace Right Side Curtain Ratchet.		Job was Done by Andrew on 17/7/24.	17/07/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		11/07/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\AIR FITTIN	REPAIRED AIRLEAK@ RR AIRBAG. REPLACED AIR COUPLINGS TO B TRAILER.			14/06/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2024	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Curtain very hard to slide			03/05/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN GETTING STUCK IN THE MIDDLE (LHS SOUNDS LIKE IT WANTS TO AS WELL)			03/05/2024	543870	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/05/2024	543870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\DAMAGE	Side rail roof support brackets are cracked			23/03/2024	284065	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2024	284065	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	ADJUST ALL WHEEL BEARINGS.			22/03/2024	284065	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\HCV	RIDE HEIGHT.			22/03/2024	284065	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/03/2024	284065	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Unknown	OVERDUE SERVICE.			22/03/2024	284065	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\DAMAGE	Side rail roof support brackets are cracked			22/03/2024	284065	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	CURTAIN ROLLERS BAD.			15/03/2024	282839	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			15/02/2024		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Albury Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			30/01/2024		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Albury Workshop	TRAILER
T617	Wodonga - Workshop	Elect\TRL LIGHTS	park lights tripping fuse			06/01/2024		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	ADJUST ALL WHEEL BEARINGS.			20/12/2023	247490	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/12/2023	247490	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect\INDICATORS	NO TRAILER INDICATORS.			20/12/2023	247490	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/12/2023	247490	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		20/12/2023	247490	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect\TRL LIGHTS	REPLACE LIGHT DUTY PLUG.			31/10/2023	236159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect\INDICATORS	No Indicators On Trailers			24/10/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2023	233718	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2023	233718	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\PANELS	REAR BAR NEEDS STRAIGHTENING AND RAISED.		CHECKED. OK.	20/10/2023	233718	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist													
T617	Wodonga - Workshop	VehService\DS	Trailer has been at Maxitrans Since April.	VehService\DS		27/09/2023		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	WHEEL BEARINGS NEED ADJUSTMENT.			26/09/2023	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
			Skid Plate repairs													
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Maxitans Derrimut			26/09/2023	543870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2023	232956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
			CRACKS BOTH SIDE OF FOUNDATION.													
T617	Wodonga - Workshop	Chassis\SKID PLATE	PLEASE TAKE PHOTOS			20/04/2023	232956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/04/2023	232956	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\PANELS	REAR BAR NEEDS STRAIGHTENING AND RAISED.			20/04/2023	232956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	WHEEL BEARINGS NEED ADJUSTMENT.			20/04/2023	232956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2023	231689	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/03/2023	231689	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\SKID PLATE	CRACKS BOTH SIDE OF FOUNDATION.			22/03/2023	231689	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist													
T617	Wodonga - Workshop	VehService\DS	PO# WW076738	VehService\DS		19/02/2023		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	BARRY MANEY - 3	TRAILER

T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023	218642	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2023	218642	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			08/12/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Albury Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			08/12/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Albury Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		01/12/2022	206074	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2022	206074	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Steering\WHEEL ALGN	wheel alignment recommended			01/12/2022	206074	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	ADJUST RM WHEEL BEARING. UNDER WARRANTY.			01/12/2022	206074	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\ABS	Trailer ABS is faulty, it not the truck as dash light does not light up with other new ABS trailers.			01/12/2022	206074	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2022	206074	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2022	195914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2022	195914	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP06	puncture repair			30/08/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\HCV	change height control valve			05/08/2022	170086	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Checked and adjusted ride hieght Tightened loose mud guards Tightened loose shockers	22/07/2022	164600	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	split trailers and greased T/Table.	22/07/2022	164600	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\TRL LEGS	REPLACED BROKEN LEG HANDLE.			13/07/2022	160448	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/06/2022	156139	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/06/2022	156139	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\SUZI COIL	Suzi lines leaking			24/06/2022	156139	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2022	143353	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WHEEL BRGS	RF, RR, need adjustment			24/05/2022	143353	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	LF Needs adjustment. (Under Warranty)			24/05/2022	143353	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	CURTAIN TRACK ROLLERS R/HAND SIDE.			24/05/2022	143353	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP08	OUTSIDE RIGHT MIDDLE OFF BEAD FLD FLAT.			24/05/2022	143353	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/05/2022	143353	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	ADJUST RM WHEEL BEARING. UNDER WARRANTY.			24/05/2022	143353	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2022	126157	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	need reline			07/04/2022	126157	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	reline asap			07/04/2022	126157	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2022	126157	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	REPLACED FL RATCHET.			17/03/2022	119215	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2022	117302	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/03/2022	117302	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TOOLBOX	REPAIRED LH TOOL BOX HINGE DAMAGED AND SNAPPED OFF. STRAIGHTENED DOOR AND BOLTED HINGE BACK ON.			11/02/2022	105644	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	need reline			04/02/2022	102648	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	reline asap			04/02/2022	102648	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\AIR FITTIN	Inspect for loose fittings in front of trailer		REPLACED.	04/02/2022	102648	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\PANELS	REPAIRED/ WELDED CRACKS ON REAR BAR.			04/02/2022	102648	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/01/2022	100039	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/01/2022	100039	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\MUDGUARDS	REPLACED LR GUARD AND MUDFLAPS. ADJUSTED OUTRIGGER			26/01/2022	100039	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\PANELS	REPAIRED WEIGHT GUAGE LID			26/01/2022	100039	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job LR RR MUDGUARDS HAVE HOLES			25/12/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Rosewood Workshop	TRAILER
T617	Wodonga - Workshop	Body\MUDGUARDS	These are not big enough, keep monitoring to next service.			25/12/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Rosewood Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/12/2021		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Rosewood Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			03/12/2021	86550	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/11/2021	79532	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/11/2021	79532	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\MUDGUARDS	LR RR MUDGUARDS HAVE HOLES			18/11/2021	79532	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		18/11/2021	79532	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP9+10	supply and fit 4 tyres			11/11/2021	75838	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12 1 x 275 70 22.5 Tyre 1 X New Alloy Rim 1 X Fit			11/11/2021	75838	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\AH Callout	1 X After Hours Callout			05/11/2021	74252	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP05	puncture repair			17/09/2021	760224	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP1+2	Supply and fit 6 tyres and 1 runout to POS 11			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11	Tyre Position 11			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Rear Right mudgaurd has a hole in it.		Inspected OK.	02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntable bushes need to be replaced next service.		Replace turntable bushes and pins.	02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2021	37529	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	LF, RF, LM tyres need replacing.			02/09/2021	37529	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP03	Fit Runout Record Check Results As Attached To This Job			27/07/2021	165741	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	All axels except LHM have been relined.			27/07/2021	16547	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/07/2021	16547	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	Move assets T617 + T618 from the service bay.			27/07/2021	16547	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	RF both inner + outter U/S			27/07/2021	16547	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/06/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist Regulator valve not working.	VehService\DS		17/06/2021		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\HCV	Trailer height needs adjustment.			17/06/2021		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Rear Right mudgaurd has a hole in it.			17/06/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntable bushes need to be replaced next service.			17/06/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	Brake reline ML axle.			17/06/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Unknown	Service due.			17/06/2021		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BREAKDOWN	air leak in suzi line			21/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up move and park trailers.			16/05/2021	525098	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\STRAPS	LH upright broken			16/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\AIR LEAK	air leaks			16/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	replace guard			16/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Left hand upright broken.			16/05/2021		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\AIR LEAK	Air leaks			16/05/2021		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Guards need replacing.			16/05/2021		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2021	519474	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	LF Needs adjustment. (Under Warranty)			01/05/2021	519474	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2021	519474	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Upright on left side rivets need replacing.		Repair LH upright as per R&R	21/04/2021	514671	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\AIR LEAK	air leaking from front axle		MJD diesel repairs POww063016	25/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WHEEL BRGS	RF, RR, need adjustment			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	need reline			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	reline asap			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/03/2021	495010	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/03/2021	495010	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\CLEAN	clean up and set up auto bleeder for air			16/03/2021	495010	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	reline asap			16/03/2021	495010	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP01	Repair and refit tyre			11/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\MUDGUARDS	Fitted new guard R/Centre			29/01/2021	472022	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021	472022	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/01/2021	472022	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	R.M, guard has missing			29/01/2021	472022	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WHEEL BRGS	RF, RR, need adjustment			29/01/2021	472022	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	need reline			29/01/2021	472022	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP07	replace tyre		Narrabri	22/01/2021	469806	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			21/12/2020	449335	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\EXTENSION	Job Added From Invoice			21/12/2020	449335	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			21/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		replaced with 2 clean skins	21/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP9+10	tyre blow out		POww060455	15/12/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		needs reline- not done	11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Ttable needs dog bones			11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	RHR needs reline monitor		relined L/front + R/rear+ move asset to beer shed, after job is done cleaning	11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted (bushes and pins to be replaced next service)			11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Guard needs replacing		job no. 317255 related with this	11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	Reline ASAP		as per job #317251	11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	needs guards replaced		LR GUARDS REPALCED	11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	needs dogbones			11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER

T617	Wodonga - Workshop	Susp\SHOCK ABS	RR shocky leaking		JOB COMPLETE		11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	needs reline		AS PER JOB #317251		11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/12/2020	452794	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	LEFT MUDGUARD IS MISSING				11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\SHOCK ABS	RR SHOCK IS LEAKING RELINED L/FRONT: 2MM				11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	RELINED R/REAR; 5MM				11/12/2020	452794	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\DRV TYRES	flat tyre LHR outter tyre: call beaurepairs to fix				06/12/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\DRV TYRES	LHR inner tyres blown out at Barmedman call beaurepairs out and getting guard fitted at inland trucks in dubbo				06/12/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting		inspected ok		04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing need adjusting at maxi trans		inspected ok		04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/10/2020	418805	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	needs guards replaced				04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	needs dogbones				04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\SHOCK ABS	RR shocky leaking				04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	needs reline				04/10/2020	418805	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\AIR BAG	Job Added From Invoice				02/10/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect	Replace L/duty elec base				30/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/09/2020	406136	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/09/2020	406136	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		As per #304270		05/09/2020	406136	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	Guard needs replacing				05/09/2020	406136	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	Reline ASAP				05/09/2020	406136	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	As per #304269		05/09/2020	406136	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			05/09/2020	406136	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	cancelled		02/09/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/07/2020	381143	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	RHR needs reline monitor				15/07/2020	381143	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted (bushes and pins to be replaced next service)				15/07/2020	381143	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/07/2020	381143	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				13/06/2020	359543	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				13/06/2020	359543	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				13/06/2020	359543	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				06/06/2020	357726	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/05/2020	357727	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	RHR needs reline monitor				16/05/2020	357727	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted (bushes and pins to be replaced next service)				16/05/2020	357727	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/05/2020	357727	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers				16/05/2020	357727	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice				26/04/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/04/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				26/04/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				26/04/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				25/04/2020	340913	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	yard check cleaning				31/03/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\CLEAN	clean up after service				31/03/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting				31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\STEER TYRE	R&L front inner		previously done drums appear to be oversized		31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	brake squeal		monitor next service		31/03/2020	335024	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			31/03/2020	335024	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WHEEL BRGS	bearing need adjusting at maxi trans				31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	Ttable needs dog bones				31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes\BRK RELINE	RHR needs reline monitor				31/03/2020	335024	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	bring 617/618 into trailer shed				01/03/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\MOVE ASSET	take 617/618 out & drop in paddock				01/03/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Brake test results attached				01/03/2020	320906	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service	VehService\DS			01/03/2020	320906	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	brake squeal				29/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	Service overdue	VehService\DS			29/02/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				17/01/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				17/01/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice				17/01/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				17/01/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	replaced RHF curtain ratchet				09/01/2020	293489	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/01/2020	291589	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	move trailers		03/01/2020	291589	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\STEER TYRE	R&L front inner				03/01/2020	291589	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Steering\WHEEL ALGN	wheel alignment recommended				03/01/2020	291589	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2019	284367	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres	LHF LHM duels need inspecting		Inspected ok		11/12/2019	284367	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting		Needs to go back to the manufacturer		11/12/2019	284367	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\SUSPENSION	bushes in spring arm u/s		Inspected ok		11/12/2019	284367	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/12/2019	284367	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11	RHR inner u/s		previously done		12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres	LHF LHM duels need inspecting				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted, JB checked feet, has checked plate				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\SUSPENSION	bushes in spring arm u/s				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\PAINT/REST	split, clean legs and paint legs				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	pick up trailers		12/11/2019	267604	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\TRL LEGS	Prepare & paint legs				12/11/2019	267604	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				23/10/2019	251462	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				23/10/2019	251462	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				23/10/2019	251462	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\MUDGUARDS	replace LH rear guard				21/10/2019	254368	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\AIR BAG	RHM bag leaking		Replaced RHM bag & check for other leaks in A trailer		16/10/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/10/2019	251465	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/10/2019	251465	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\TP11	RHR inner u/s				16/10/2019	251465	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Susp\AIR BAG	slow leak RHM				16/10/2019	251465	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				13/09/2019	315115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				13/09/2019	315115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice				13/09/2019	315115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/09/2019	227659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\AIR BAG	RHM bag leaking				05/09/2019	227659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/09/2019	227659	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			05/09/2019	227659	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes					05/09/2019	227659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/08/2019	207748	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect\ELECT P&W	Electrical repairs to front base plugs				02/08/2019	207748	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\AIR FITTIN	Replaced air hoses with new ones				02/08/2019	207748	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/08/2019	207748	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				01/08/2019	203461	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\BALANCE	Job Added From Invoice				01/08/2019	203461	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	Replace curtain ratchet				03/07/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/07/2019	188184	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/07/2019	188184	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service	VehService\DS			02/07/2019	188184	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				18/06/2019	176060	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL GATES	Job Added From Invoice				24/05/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/05/2019	155697	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/05/2019	155697	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\REFLECTORS	replaced reflectors				07/05/2019	155697	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/03/2019	127198	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/03/2019	127198	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/01/2019	101318	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/01/2019	101318	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\HOUSEKEEP	weld load bars near skid plate		Aldonga completed		04/12/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2018	68167	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/12/2018	68167	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Workshop\CLEAN	clean workshop area				01/12/2018	68167	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice				13/11/2018	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER

T617	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		30/10/2018	51072	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	30/10/2018	51072	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	VehService\DS	Completed by TCTC	VehService\DS	13/09/2018		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Body\TRL REPS	replace front right curtain ratchet		12/09/2018	20209	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER
T617	Wodonga - Workshop	Elect\ELECT P&W	changed all plug from 7 to 5 pin		09/08/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074954	Wodonga Workshop	TRAILER