EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie on service	01/10/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	Long Sign Bend Back Side?			01/10/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	NEEDS 7 PIECES PLY BOARD.			01/10/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes\VALVES	BRAKE STICKING ON. WON'T RELEASE FOR LONG TIME.			01/10/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
					Labour- Mobile											
					Travelled to Coomera BP Northbound											
					Removed all gates from hanger											
					Cut damaged section off and made sure gate rack was secure											
T620	Wodonga - Workshop	Body\MOUNTS	Body\MOUNTS		Travelled back to Brisbane	07/07/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	WARREGO TRANSPORT REPAIRS	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/06/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	tool box door hinge fallen of			25/06/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes\AIR FITTIN	Air fitting's between A & B trailer's are leaking and need to be replaced.			25/06/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	Toolbox door hinge's need to be repaired.			25/06/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\REFLECTORS	Body\REFLECTORS		LIGHT LED REAR IND/STOP/REV	19/06/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	toolbox hinge needs replacing		Pending	07/04/2026	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/04/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			27/03/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BORDER BANDAG PTY LTD	TRAILER
T620	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			27/03/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BORDER BANDAG PTY LTD	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	comoleted SMc MN	28/02/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS.5-6 + 7-8			02/02/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BORDER BANDAG PTY LTD	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/02/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	REPLACE REQUIRED CURTAIN RATCHETS			07/01/2026	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/01/2026	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	D/S CURTAIN ROLLER STOPPER FELL OFF. ROLLER CAME OUT. REPLACE BOLT. CURTAIN RAIL HOLDERS ARE CRACKED. FRONT NEED TO BE WELDED BACK ON.		Unable to do doe to tags on curtains	06/12/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/12/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		06/12/2025	627881	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/12/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/09/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAIN RATCHET LOOSE P/S. CHECK O/S.			23/09/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	UPRIGHTS NEED TO BE FIXED STILL (BOLT NOT RIVET) Replace King Pin.			23/09/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\KING PIN	(Elite Diesel P/O: WW096900)			12/09/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	ELITE DIESEL REPAIRS	TRAILER
T620	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 24			01/09/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BORDER BANDAG PTY LTD	TRAILER
T620	Wodonga - Workshop	Tyres\TP10	Tyres\TP10 (30)			01/09/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BORDER BANDAG PTY LTD	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CHECK RATCHETS LOOSE.			30/07/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service Repair Damaged Curtain's.	VehService\DS		30/07/2025	627881	Service	Comoleted	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	(I Fix Curtains P/O: WW095210)			27/06/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	IFIX TRUCK CURTAINS	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	PATCH CURTAIN. REAR L/H BOTTOM.			27/06/2025	627881	Fault	Comoleted	FL Green Distribution	Tliner	Wodonaa	LHB	074957	IFIX TRUCK CURTAINS	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		26/06/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	M & G CURTAINS- RESEAL ROOF, CORNERS AND NOSE CONE.			30/05/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	M & G TRUCK CURTAIN REPAIRS	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	S.McCABE	17/04/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes\BRK RELINE	RELINED LF RF LM RM RR.		S.McCABE	17/04/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\FITMENT	Tyres\FITMENT 3			25/03/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BEAUREPAIRES	TRAILER
T620	Wodonga - Workshop	Body\MUDGUARDS	Replace right front guard.			20/03/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/03/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP11	Tyres\TP11			04/03/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BEAUREPAIRES	TRAILER
T620	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			04/03/2025	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BEAUREPAIRES	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	Straighten/Repair Rear Bar L/H/S.			28/02/2025	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		30/01/2025	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/12/2024	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-12			11/12/2024	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BEAUREPAIRES	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		29/11/2024	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	VehService\DS		29/11/2024	627881	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		26/09/2024	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\AIR BAG	Replace right rear airbag.			22/08/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\AIR LEAK	Find Air leaks.			21/08/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\AIR LEAK	Repair Air Leaks.			21/08/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		15/08/2024	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	Replace Right Side Angle Carrier Door.			23/07/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\MUDGUARDS	Replace right rear guard			23/07/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		17/07/2024	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	ANGLE DOOR MISSING IN TOOLBOX.			17/07/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	NEEDS SERVICE.			17/07/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\AIR BAG	CURTAIN RESTRAINT STRAP HANGING L/H FRONT.			17/07/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			14/06/2024	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			14/06/2024	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			14/06/2024	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	BEAUREPAIRES	TRAILER
T620	Wodonga - Workshop	Body\MUDGUARDS	Replace middle left and left rear gaurds also third outrigger.			14/06/2024	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service	VehService\DS	trailer has not moved since last service 14/04/24	17/05/2024	627481	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED TO BE REPAIRED AT TC GRAPHICS.			04/05/2024	627481	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/04/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/04/2024	25399	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED TO BE REPAIRED AT TC GRAPHICS.			13/04/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	LR COMMING RAIL DAMAGED.			13/04/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	LM-LR WHEEL BEARINGS NEED TO BE ADJUSTED-WARRANTY-FREIGHTER.			13/04/2024	25399	Repair	Comoleted	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes\BRK RELINE	RELINE.			13/04/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Tyres\TP07	Tyre Position 7			13/04/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshoo	TRAILER
T620	Wodonga - Workshop	Tyres\TP08	Tyre Position 8			26/03/2024	25399	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Curtain repair required both sides rear.			22/03/2024		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rips in curtains			22/03/2024		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS U/S.			22/03/2024		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	RHS REAR CURTAIN HAS TEAR.			22/03/2024		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	RHS REAR BUCKLE HAS TORN CURTAIN.			22/03/2024		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Driver Side Curtain Has Two Tear In It At The Back			22/03/2024		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rips in curtains			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS U/S.			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Curtain repair required both sides rear.			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes	BRAKES REQUIRE ATTENTION - LOUD SQUEALING AND NOT WORKING 100%		checked during service - OK	08/12/2023	518293	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX DOOR NEED FIXING.		checked during service - OK	08/12/2023	518293	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	RHS REAR CURTAIN HAS TEAR.			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	RHS REAR BUCKLE HAS TORN CURTAIN.			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Driver Side Curtain Has Two Tear In It At The Back			08/12/2023	518293	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Passenger Side Front Upright Is Broken		previously completed	08/12/2023	518293	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2023	518293	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	REPLACED 6 CURTAIN STRAPS. PATCHED HOLES IN CURTAINS. REPAIRED LF UPRIGHT.			29/11/2023	515290	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP1+2	replace tyres			25/11/2023	514140	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/10/2023	499122	Service	Comoleted	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Susp\SPRING HANG	front trailline arm bush's to be monitored			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS U/S.			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonaa	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Curtain repair required both sides rear.			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection			10/10/2023	499122	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings need adjustment (warranty)			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rips in curtains			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\SPRING HANG	front trailling arm bush's to be monitored			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS U/S.			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX U/S.			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX DOOR ONLY HELD ON BY ONE HINGE. (NEEDS REPAIR ASAP)			07/09/2023	490159	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/09/2023	490159	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			07/09/2023	490159	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/08/2023	485007	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL WALL	cracks in back wall			04/08/2023	485007	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\SPRING HANG	front trailling arm bush's to be monitored			04/08/2023	485007	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/08/2023	485007	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS U/S.			04/08/2023	485007	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX U/S.			04/08/2023	485007	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\PRES CHECK	1-12			04/08/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	REPAIR SLIDE POLE P/S.		RIVOTTED SLIDE POLE.	23/06/2023		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			06/06/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/06/2023	467412	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings need adjustment (warranty) LF LR WHEEL BEARINGS NEED ADJUSTING			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	TO BE COMPLETED BY VAWDRY.			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP04	Drivers side outer tyre is low on oressure and has a slice in side wil front axle.			06/06/2023	467412	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Tyres\TP02	Passenaer side inner has a chunk out of front axle.			06/06/2023	467412	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rips in curtains			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Brakes\AIR LEAK	leaks in multiple hoses			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonaa Workshoo	TRAILER
T620	Wodonga - Workshop	Body\TRL WALL	cracks in back wall			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\SPRING HANG	front trailling arm bush's to be monitored			06/06/2023	467412	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP02	Tyre Position 2			23/04/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\TP04	Tyre Position 4			23/04/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER

			D Service As Per Attached Checklist																
T620	Wodonga - Workshop	VehService\DS	Barry Maney PO# WW077905	VehService\DS		21/04/2023	627881	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2023	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	RIPS IN CURTAIN.			21/04/2023	627881	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	DRIVER'S SIDE REAR CURTAIN. REPAIR AND BUCKLES PULL THROUGH CURTAIN BOTH SIDES.			21/04/2023	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Unknown	SERVICE.			21/04/2023	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\MUDGUARDS	P/S MID AXLE MUDGUARD MISSING.			21/04/2023	627881	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		21/04/2023	627881	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings need adjustment LF LR WHEEL BEARINGS NEED ADJUSTING			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	TO BE COMPLETED BY VAWDRY.			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	RIPS IN CURTAIN.			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	DRIVER'S SIDE REAR CURTAIN, REPAIR AND BUCKLES PULL THROUGH CURTAIN BOTH SIDES.			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\MUDGUARDS	Replace Middle Axle Mudguard (Damage)			01/03/2023	445409	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED MALE BRAKE COUP[LING.	01/03/2023	445409	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	Multiple bearings need adjustment			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	front axle bearings			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	LF LR WHEEL BEARINGS NEED ADJUSTING			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/01/2023	432583	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	RIPS IN CURTAIN.			08/01/2023	432583	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			19/11/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			19/11/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			19/11/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			19/11/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Albury Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/11/2022	416275	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\DAMAGE	safety rail bent			19/11/2022	416275	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TOOLBOX	PRODUCT HOSE CARRIER MISSING END CAP.			19/11/2022	416275	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/11/2022	416275	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Susp\SHOCK ABS	REPLACED RM SHOCK.			19/11/2022	416275	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/08/2022	369454	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	FIT ANGLE RACK- REMOVE UNDER RUN BARS EITHER SIDE AND FIT FRONT OF TRI FRONT AXLE BEHIND GATE RACK.			09/08/2022	369454	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED STOP. TAIL AND INDICATOR LIGHTS.	09/08/2022	369454	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	Repairs to upright			17/06/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Workshop\CLEAN	Clean up			17/06/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2022	335307	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/05/2022	335307	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.			24/05/2022	335307	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	LF LR WHEEL BEARINGS NEED ADJUSTING			24/05/2022	335307	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP5+6	supply and fit 2tyres			13/04/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2022	317116	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\DAMAGE	safety rail bent			07/04/2022	317116	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2022	317116	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\TRL LEGS	REPAIR LANDING LEG HANDLE.		REPAIRED LANDING LEG HANDLE/ WINDER.	08/03/2022	301201	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2 tyres			11/02/2022	287075	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job rear bar no bump stops			10/02/2022	287075	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain chanels bent. safety rails u/s		CAN'T FIT. WILL BE OVERSIZE.	10/02/2022	287075	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\DAMAGE	safetv rail bent			10/02/2022	287075	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/02/2022	287075	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\MUDGUARDS	REPLACED GUARD AND OUTRIGGER			10/02/2022	287075	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2021	271938	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	bearings need adjusting			31/12/2021	271938	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist New Tyre Fitted Beaurepairs Eastern Creek	VehService\DS		31/12/2021	271938	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\FITMENT	PORWW069320			23/12/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2021	265961	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2021	265961	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		01/12/2021	265961	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			07/11/2021	258256	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2021	245351	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	LF need adjust			12/10/2021	245351	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\HOUSEKEEP	needs 2ply sheets			12/10/2021	245351	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\Punct	Nail in Tyre - Rear Left			12/10/2021	245351	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\AIR LEAK	Air leak in tri			12/10/2021	245351	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/10/2021	245351	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP09	supply and fit 1 tyre			08/10/2021	244221	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\PRES CHECK	pressure maintenance & wheelnut indicators			22/09/2021	236261	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Rosewood - Workshop	DrivLine\ALT	finish off installation of new alternator and belts			01/09/2021	494143	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/08/2021	225095	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/08/2021	225095	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Rosewood - Workshop	Elect\ALT	remove alternator to try to match it and belts needed jump start and test alternator output			17/08/2021	494143	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER			
T620	Rosewood - Workshop	Elect\ALT	#not charging, will replace alternator asap			10/08/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP3+4	Supply and fit 2 tyres			28/07/2021	205914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP07	fit 1 runout			28/07/2021	205914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/07/2021	205914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres	R front axle inner layer pelled off			28/07/2021	205914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/07/2021	205914	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	Right front too corner inside three bolts are missine.			28/07/2021	205914	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/06/2021	180033	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/06/2021	180033	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Rosewood - Workshop	Engine\ELECT P&W	jump start			20/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER			
T620	Rosewood - Workshop	Body\FIFTH WHEE	hook up to spare trailers			20/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER			
T620	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up and move into trailer shed for Andrew.			28/04/2021	158532	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\DAMAGE	Damage Repairs Crash Bar, Outrigger and Mudguard. 2 tyres supplied and fitted.		Crash bar still in order Replaced rear guard, outrigger, both sides mudflap	28/04/2021	158532	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\CLEANSKIN	Rane store to find out wheel POS but thev were unable to tell me			24/04/2021	153127	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			07/04/2021	149201	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Workshop\MOVE ASSET	Load Shifted		Take trailers down to freight shed and fix load. Load (Bulker Bag) petruding through curtain. Assist freight shed reposition load and then oark in trailer vard.	07/04/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		07/04/2021		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2021	149201	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2021	149201	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\TP5+6	Supply and ift 2 tyres			01/04/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2021	136508	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/03/2021	136508	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	LF need adjust			11/03/2021	136508	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	Replace R/Hand curtain ratchet			21/01/2021	109603	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TOOLBOX	Repair T/Box lid		repair	21/01/2021	109603	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2020	103417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/12/2020	103417	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	bearinas need adiustine			31/12/2020	103417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			21/12/2020	99893	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			21/12/2020	99893	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Workshop\MOVE ASSET	meeting with Dean			11/12/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Workshop\MOVE ASSET	sort paperwork			11/12/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			05/12/2020	89208	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			05/12/2020	89208	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/11/2020	99915	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\DAMAGE	bars down the back near spare wheel carrier broken and hanging down			28/11/2020	99915	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/11/2020	99915	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Susp\SUSPENSION	Cross bracing cracks		previously done	23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Suso\WHEEL ALGN	Wheel alignment recommended			23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body\TRL REPS	Rios in curtains		previously done	23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/10/2020	77627	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres	R front axle inner layer pelled off			23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	front axle bearings			23/10/2020	77627	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2020	65417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\CHAS CRACK	small cracks starting on gussets		where?	22/09/2020	65417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\FIFTH WHEE	around skid plate			22/09/2020	65417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes\AIR FITTIN	Check emergency coupling		previous job	22/09/2020	65417	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace plug	22/09/2020	65417	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Body	Patch R/hand curtain and replace rollers			12/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2020	550057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/08/2020	550057	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes\AIR FITTIN	Check emerencnv couplline			22/08/2020	550057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			12/08/2020	41587	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			12/08/2020	41587	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Elect\TAIL LIGHT	repair wiring prolems and replace clearance light			08/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Elect\TAIL LIGHT	take out			08/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2020	37752	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			
T620	Wodonga - Workshop	Chassis\FIFTH WHEE	around skid plate			18/07/2020	37752	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER			

T620	Wodonga - Workshop	Body\TRL REPS	Rips in curtains			18/07/2020	37752	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Rieht rear curtain torn and 2 bottom buckles		As per #295462	18/07/2020	37752	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/07/2020	37752	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2020	13177	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2020	13177	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			23/06/2020	4681	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Frid Serv\TEMP CAL	check and record calibration test. Complete and send calibration certificate.			04/06/2020	11883	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/06/2020	13129	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/06/2020	13129	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	Multiple bearings need adjustment			03/06/2020	13129	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Rips in curtains			03/06/2020	13129	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	curtain repairs		replacebuckles & straps	29/05/2020	12054	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice			13/05/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\PANELS	LH oelment rubber needs to be ooo revited back on			09/05/2020	2990	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rail bent			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rails bent			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	LH side needs inspection			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	L side rails bent			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	bent side rail L - bent R side curtain pole rail			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL WALL	rear right where curtain goes in bent		Previously completed	01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings need adjustment			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	hubs have movement			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\FIFTH WHEE	around skid plate			01/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Rosewood - Workshop	Brakes\BOOSTER	check for air leaks. LHF brake booster bad leak. Reolaced. RHF mav need reolacine also. will monitor			08/04/2020	494116	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/04/2020	277659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/04/2020	277659	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\CHAS CRACK	small cracks starting on gussets			02/04/2020	277659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\FIFTH WHEE	around skid plate			02/04/2020	277659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WHEEL BRGS	hubs have movement			02/04/2020	277659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\HOUSEKEEP	underside ok			02/04/2020	277659	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	weld new tie rails under front of trailer (both sides)			02/04/2020	277659	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	fix rope rails wouldn't build air in trailers			22/03/2020		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Rosewood - Workshop	Engine\GOV VALVE	adjusted governor pressure, tested, all good			06/03/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Rosewood Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Brake test results attached			02/03/2020	263507	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Weld new tie rails under front of trailer (both sides) side bar's broken side bar's on tyre rack pushed back			02/03/2020	263507	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL GATES	angle rack needed		As per #274834	02/03/2020	263507	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WINCH/STRP	fit full length rope rails to front of trailer		As per #274834	02/03/2020	263507	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service	VehService\DS	Drop trailers in paddock	02/03/2020	263507	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	fit rope rails to front of trailer fit angle rack		As per #274834	02/03/2020	263507	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\SUSPENSION	Cross bracing cracks			02/03/2020	263507	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Susp\WHEEL ALGN	Wheel alianment recommended			02/03/2020	263507	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Found LHS curtain had rollers that had oulled out of track		Reoaired rollers & tracks	13/02/2020	255196	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers			13/02/2020	255196	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	Resecure LHF pelmet rubber mount			09/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	weld new tie rails under front of trailer (both sides) side bar's broken side bar's on tyre rack pushed back		Parts on order for side bars Side bar on tyre rack LHS completely removed & remounted	06/02/2020	252807	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL GATES	angle rack needed		RHS still to be done	06/02/2020	252807	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear L/H side trailer needs repair where curtain posts sit			06/02/2020	252807	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain post holder bent needs to be straightened			06/02/2020	252807	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WINCH/STRP	fit full length rope rails to front of trailer			06/02/2020	252807	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job rear bar no bump stops			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain chanels bent, safety rails u/s			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings need adjustment			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2020	247362	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear L/H side trailer needs repair where curtain posts sit			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain post holder bent needs to be straightened			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WINCH/STRP	fit full length rope rails to front of trailer			25/01/2020	247362	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	need new tie down point on front end of trailer			25/01/2020	247362	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\AIR LEAK	air connection between A & B leaks			25/01/2020	247362	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist rear bar no bump stops	VehService\DS		18/12/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain chanels bent. safety rails u/s			18/12/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearinas need adiustment			18/12/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/12/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			23/11/2019	220559	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			23/11/2019	220559	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/11/2019	220559	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			23/11/2019	220559	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		04/11/2019	619875	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rail bent			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rails bent			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	LH side needs inspection			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	L side rails bent			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	bent side rail L - bent R side curtain pole rail			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL WALL	rear right where curtain goes in bent			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	weld new tie rails under front of trailer (both sides) side bar's broken side bar's on tyre rack pushed back			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL GATES	angle rack needed			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear L/H side trailer needs repair where curtain posts sit			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear curtain post holder bent needs to be straightened			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Chassis\WINCH/STRP	fit full length rope rails to front of trailer			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	need new tie down point on front end of trailer			04/11/2019	619875	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	RHM bearings 14 thou in, 8 thou out measured on top of hubcap LHFbearing 10 thou in 10 thou out RHF bearing 15 thou in 10 thou out	04/11/2019	619875	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/10/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/10/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2019	190415	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/09/2019	190415	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/08/2019	177684	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/08/2019	177684	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2019	158388	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	flat spots		job previously comeleted	10/07/2019	158388	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DAMAGE	6x tyre's flat spots		job previously completed	10/07/2019	158388	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/07/2019	158388	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL WALL	rear right where curtain goes in bent			10/07/2019	158388	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2019	154352	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2019	154352	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			03/07/2019	154352	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			03/07/2019	154352	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2019	154840	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2019	154840	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			03/07/2019	154840	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			30/06/2019	10	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	flat spots			19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	FL axle has bent dust cover		previously completed	19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	LH side needs inspection		as per job#232461	19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/06/2019	147956	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DAMAGE	6x tyre's flat spots			19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	L side rails bent			19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	bent side rail L - bent R side curtain pole rail			19/06/2019	147956	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL GATES	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2019	139502	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	rear L/H side trailer needs repair where curtain posts sit		job pending	23/05/2019	139502	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2019	139502	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	LH side needs inspection			23/05/2019	139502	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rails bent			23/05/2019	139502	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/03/2019	107063	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/03/2019	107063	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Tyres\DRV TYRES	flat spots			19/03/2019	107063	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	safety rail bent			19/03/2019	107063	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\DAMAGE	FL axle has bent dust cover			19/03/2019	107063	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2019	84899	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TOOLBOX	no lid on toolbox		has new box	02/02/2019	84899	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2019	84899	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2018	64563	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2018	64563	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER

T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/10/2018	41934	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	driver side curtain ratchet needs new cutter pin		could not fault	31/10/2018	41934	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/10/2018	41934	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body	Job Added From Invoice			24/10/2018	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\TRL REPS	replace RHF curtain ratchet			18/10/2018	35513	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice			25/09/2018	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/09/2018		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER
T620	Wodonga - Workshop	Body\HOUSEKEEP	fit service label holder to trailer			13/09/2018	16397	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074957	Wodonga Workshop	TRAILER