EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/09/2026	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL FLOOR	REPAIRED FLOOR & REPLACE MONO BOLTS.			03/09/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/07/2026	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	The Latch On Left Need Attention As Not Latching			15/07/2026	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist AS ABOVE (ABS) ((T617- ABS ISSUES PUSHING FEED BACK INTO PRIME MOVER))	Insp\ANN INSP		15/07/2026	541203	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\EBS FAULTS			Pending	09/05/2026	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		09/05/2026	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	Repair Toolbox door.			29/04/2026	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Replace L/H curtain ratchet & fix Upright.			29/04/2026	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\ELECT P&W	Clearance light missing half way along trailer.			29/04/2026	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/04/2026	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			01/04/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			06/03/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/03/2026	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP06	Tyres\TP06 (26)		LOW	02/02/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		LOW	02/02/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 25		Travelled to site Inspected trailer Found one roller has come out of the rail and second roller half half come off and gotten stuck partway down the rail Travelled to Bunnings and to get a ladder Travelled back to site Found bit of damage to rail causing roller to not move Removed the damaged and moved roller down to the end by hand Removed roller and reinstalled correctly Installed second roller and siliconed piece of metal into rail to replace the missing stop block	02/02/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	Body\CHN/RLR/MN	Body\CHN/RLR/MN		Verified curtain works	16/01/2026	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	WARREGO TRANSPORT REPAIRS	TRAILER
T618	Wodonga - Workshop	Susp\SHOCK ABS	Replace Middle Left, Middle Right & Left Rear Shock Absorber's.			16/12/2025	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/12/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		27/11/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/10/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL GATES	GATE HOLDER FALLING OFF. BROKEN IT'S BEEN STRAPPED UP. THE TRAILER WERE SERVICED ON 1/10/25. WHY WASN'T THIS PICKED UP & FIXED.			23/10/2025	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			06/08/2025	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BORDER BANDAG PTY LTD	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service REPAIR CRACKS IN SKID PLATE FOUNDATION.	VehService\DS		02/08/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	(Parts Supplied By Steel Suppliies P/O: WW095644)		Replaced skid plate and foundation fixed liftine floor	03/07/2025	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL FLOOR	FRONT OF TRAILER- FLOOR IS LIFTING.			03/07/2025	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		03/07/2025	541203	PreventativeMaintenance	Unlocked	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Elect\ELECT P&W	Extend light harness in skid plate		-wiring repaired and extended as required	03/07/2025	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		30/06/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/05/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS			23/04/2025	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	IFIX TRUCK CURTAINS	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/04/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/03/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-2-3-4-5-6-7-8-9-10-11-12			26/02/2025	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			11/02/2025	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		06/02/2025	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	N/A for this service ubolts or shock straps	20/12/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\BRK RELINE	Brake and Hub Reline. (Parts Supplied By Ultimate Fasteners P/O: WW090930)			17/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\BRK RELINE	Full Brake & Bearing Reline			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	R/H side curtain catching when try to slide			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL FLOOR	Floor is Lifting @ Join			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	upright pole rivets broken LHS second from front.			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Curtain very hard to slide			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body	REPAIR RH INTRUSION BAR.			07/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\BRAKE ADJ	Grease S cams			02/12/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		24/11/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT			19/11/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2+7+8			19/11/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			19/11/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES - 4	TRAILER
T618	Wodonga - Workshop	Tyres\TP7+8	Replace Tyres Position 7+8. (Wodonga Tyre & Auto P/O: WW090094)			13/11/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	Replace Tyres Position 1+2. (Wodonga Tyre & Auto P/O: WW090094)			13/11/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BEAUREPAIRES	TRAILER
T618	Wodonga - Workshop	Tyres\RUN OUT	Fit Spare Tyre To Tyre Rack		Informed the tyre fitter removed spare parts on order	26/10/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		17/10/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Repair/Patch Holes In L/H Curtain, Holes Are @ The Front Two Buckles On L/H Side Of Trailer.			17/10/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\HCV	Adjust Ride Height			01/10/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	I	13/08/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	LHSM GUARD MISSING.			13/08/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		11/07/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	Left middle guard missing.			11/07/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\AIR FITTIN	REPLACED AIR COUPLINGS.			13/06/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\HCV	Air bags seem to be high			03/05/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	RHS CURTAIN GETTING STUCK IN THE MIDDLE 2 SPOTS, COULDN'T OPEN ALL THE WAY AND BUCKLES HIT ME IN THE FACE WHILE TRYING TO OPEN.			03/05/2024	541203	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/05/2024	541203	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\DAMAGE	Rear bar and side crash bars damaged			23/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\DAMAGE	Side rail roof support brackets cracked			23/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Curtain rollers			22/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	curtain repairs			22/03/2024	420057	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	Guards			22/03/2024	420057	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService	service			22/03/2024	420057	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\TRL LEGS	landing legs to be replaced.			22/03/2024	420057	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\DAMAGE	Rear bar and side crash bars damaged			22/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\DAMAGE	Side rail roof support brackets cracked			22/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Floor lifting above skid plate			22/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/03/2024	420057	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\TRL LEGS	REMOVED DAMAGED LANDING LEGS.			19/03/2024	418868	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP01	Tyre Position 1 curtain rollers damaged			19/03/2024	420057	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Albury Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	order number WW084821			18/03/2024	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	TWIN CITY GRAPHICS	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Repair Curtain Roller Track.and Remove r Rear Left Side Crash Barrier.			15/03/2024	418840	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/12/2023	383715	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Elect\INDICATORS	AS ABOVE. (NO TRAILER INDICATORS)			20/12/2023	383715	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/12/2023	383715	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		20/12/2023	383715	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2023	369994	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2023	369994	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			27/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	Trailer has been at Maxitrans Since April. WHEEL BEARING REQUIRE ADJUSTMENT. TO BE DONE BY FREIGHTER AS IS UNDER WARRANTY. PHOTOS TAKEN. Maxitrans PO# WW081283	VehService\DS		27/09/2023		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	Approved by Dean Salmon. SKID PLATE WORN. FREIGHTER TO REPAIR. (UNDER WARRANTY)			27/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	PHOTOS TAKEN.			27/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job WHEEL BEARING REQUIRE ADJUSTMENT. TO BE DONE BY FREIGHTER AS IS UNDER WARRANTY.			20/04/2023	369238	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	PLEASE TAKE PHOTOS OF ALL HUBS SKID PLATE WORN. FREIGHTER TO REPAIR. (UNDER WARRANTY)			20/04/2023	369238	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	PLEASE TAKE PHOTOS OF ALL WEAR AREAS.			20/04/2023	369238	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/04/2023	369238	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	SKID PLATE WORN. FREIGHTER TO REPAIR. (UNDER WARRANTY)			24/03/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2023	367981	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres	FRONT R/HAND NEEDS REPLACING.			22/03/2023	367981	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	SKID PLATE WORN.			22/03/2023	367981	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/03/2023	367981	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	WHEEL BEARING REQUIRE ADJUSTMENT. TO BE DONE BY FREIGHTER AS IS UNDER WARRANTY.			22/03/2023	367981	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			15/03/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Albury Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			15/03/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Albury Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2023	36664	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BARRY MANEY - 3	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FREIGHTER NEED TO ADJUST WHEEL BEARINGS UNDER WARRANTY.			19/02/2023	36664	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BARRY MANEY - 3	TRAILER

T618	Wodonga - Workshop	Tyres	FRONT R/HAND NEEDS REPLACING.			19/02/2023	36664	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BARRY MANEY - 3	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	SKID PLATE WORN. D Service As Per Attached Checklist			19/02/2023	36664	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BARRY MANEY - 3	TRAILER
T618	Wodonga - Workshop	VehService\DS	PO# WWO76739	VehService\DS	REPAIRED UPRIGHT FOR CURTAIN STRAP. ADJUSTED TOOLBOX CATCHES.	19/02/2023	36664	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	BARRY MANEY - 3	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023	354993	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2023	354993	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\DAMAGE	Rear bar has been bent forward on left hand side		STRAIGHTENED REAR BAR & FITTED NEW LIGHT ASSEMBLY. CLEANED UP.	25/01/2023	354993	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FREIGHTER NEED TO ADJUST WHEEL BEARINGS UNDER WARRANTY.			25/01/2023	354993	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\PANELS	REAR LIGHT BAR BROKEN.			25/01/2023	354993	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\ABS	Trailer ABS is faulty, it not the truck as dash light does not light up with other new ABS trailers.			25/01/2023	354993	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			08/12/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Albury Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		01/12/2022		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	LR & LM Needs adjustment(Under Warranty)			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	RF LM LR RR WHEEL BEARINGS REQUIRE ADJUSTMENT. UNDER WARRANTY.			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	HOLES THROUGHOUT CURTAINS.			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\DAMAGE	Rear bar has been bent forward on left hand side			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FREIGHTER NEED TO ADJUST WHEEL BEARINGS UNDER WARRANTY.			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2022	342511	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes\ABS	Trailer ABS is faulty, it not the truck as dash light does not light up with other new ABS trailers.			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\PANELS	REAR LIGHT BAR BROKEN.			01/12/2022	342511	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2022	332403	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2022	332403	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FREIGHTER NEED TO ADJUST WHEEL BEARINGS UNDER WARRANTY.			25/10/2022	332403	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\Re-Tor	Re-Torque			18/10/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyres			15/10/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\HCV	HEIGHT CONTROL VALVE REPLACED.			07/09/2022		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\BREAKDOWN	air bags wont pump up at eastern creek		G&S Diesel assit POww073216	04/08/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/07/2022	301289	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\HCV	Replace HCV			22/07/2022	301289	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Tightened loose mudflap bolts brown & hurley at chinderah	22/07/2022	301289	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\BREAKDOWN	air bags wont pump up		POww072835	19/07/2022	541203	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/06/2022	292885	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\DAMAGE	Rear bar has been bent forward on left hand side			24/06/2022	292885	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/06/2022	292885	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/05/2022	280233	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/05/2022	280233	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	RF LM LR RR WHEEL BEARINGS REQUIRE ADJUSTMENT. UNDER WARRANTY.			24/05/2022	280233	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	HOLES THROUGHOUT CURTAINS.			24/05/2022	280233	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2022	263181	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2022	263181	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	REPLACED RR GUARD. RESET LR GUARD. REPLACED REAR MUD FLAPS.			07/04/2022	263181	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2022	254391	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/03/2022	254391	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2 tyres			04/02/2022	239877	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	small crack in X member behind skid plate (monitor)			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\DAMAGE	rear bar bent		CHECKED.	04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	cracks above skid plate and support behind 5mm wear Record Check Results As Attached To This Job			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline Due soon. Record Check Results As Attached To This Job			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline reouired.			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	Foundation cracks.			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate worn.		CHECKED. OK.	04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate foundation has a crack both sides.			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP01	LF HAS CUT			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\AIR FITTIN	Inspect air fittings and bulkheads at front of trailer		CHECKED	04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	REPLACED LF GUARD AND REPAIRED OUTRIGGER. PARKED.			04/02/2022	239871	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP04	supply and fit 1 tyre			03/02/2022	239876	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP01	LF HAS CUT			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job Record Check Results As Attached To This Job			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline Due soon. Record Check Results As Attached To This Job			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline required.			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	Foundation cracks.			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate worn.			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	Right Middle has hole in it.		REPLACED GUARD. REPAIRED OUTRIGGER	26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Missing strap.			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate foundation has a crack both sides.			26/01/2022	237303	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/01/2022	237303	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/12/2021	230999	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Elect\TRL LIGHTS	Right side clearance light broken			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	LF outrigger is bent			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	Right Middle has hole in it.			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Missing strap.			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate foundation has a crack both sides.			25/12/2021	230999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Rosewood Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP09	Tyre Position 9			14/12/2021	226099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			03/12/2021	223042	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/11/2021	216971	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\SUSPENSION	Need a strut on the left side of gate rack.			18/11/2021	216971	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/11/2021	216971	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		18/11/2021	216971	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP5+6	supply and fit 4 tyres			18/11/2021	216971	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			18/11/2021	216971	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP07	Puncture repair			02/09/2021	175053	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		PAD Slaped FL and ML	02/09/2021	175052	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2021	175052	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP07	Middle axle inner tyres U/S			02/09/2021	175052	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	Foundation cracks.			02/09/2021	175052	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate worn.			02/09/2021	175052	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	Replaced right hand curtain ratchet.			16/08/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP3+4	Supply and fit 4 tyres; pressure Maintenance POS 1-2 &5-10			27/07/2021	153741	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			27/07/2021	153741	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check Record Check Results As Attached To This Job			27/07/2021	153741	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline required.			27/07/2021	153747	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	lock has broken			27/07/2021	153747	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3x guards need replacing			27/07/2021	153747	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP04	RF Outter tyre needs to be replaced. Yard check and hook up truck.		RF inner and RR outter replaced by tyre fitter.	27/07/2021	153747	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Workshop\MOVE ASSET	Clean service rea before starting service.			27/07/2021	153747	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist Record Check Results As Attached To This Job	VehService\DS		27/07/2021	153747	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Reline Due soon.			17/06/2021	137115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP04	RF Outter tyre needs to be replaced.			17/06/2021	137115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Elect\BRK LIGHT	No Brake lights.		Completed.	17/06/2021	137115	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/06/2021	137115	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Unknown	Service due.			17/06/2021	137115	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\AIR LEAK	Air Leaks		Check all areas for air leaks couldn't find any.	16/05/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\AIR LEAK	air leaks		Check over trailer cant fault. Replaced Left hand front.	16/05/2021	121770	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	replace guards		Rotated Right hand front & right hand middle.	16/05/2021	121770	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\AIR LEAK	Air leaks.			16/05/2021	121770	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	Guards need replacing.			16/05/2021	121770	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2021	116101	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2021	116101	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	LR & LM Needs adjustment(Under Warranty)			01/05/2021	116101	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			25/03/2021	96615	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	small crack in X member behind skid plate (monitor)			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	lock has broken			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3x guards need replacing			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\DAMAGE	rear bar bent			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	cracks above skid plate and support behind 5mm wear			24/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/03/2021	91037	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3x guards need replacing			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER

T618	Wodonga - Workshop	Chassis\DAMAGE	rear bar bent			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\SKID PLATE	cracks above skid plate and support behind 5mm wear			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Workshop\MOVE ASSET	yard check, pick up service repair suzi lines on 607			16/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP11	Fit Runout			14/03/2021	91037	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	WODONGA SPRING WORKS-4	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021	67499	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/01/2021	67499	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	lock has broken		change toolbox lock	29/01/2021	67499	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Workshop\MOVE ASSET	park in the yard			29/01/2021	67499	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3 guards need replacing			29/01/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP1+2	replace 2 tyres			20/01/2021	64570	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/12/2020	47854	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3 guards need replacing			11/12/2020	47854	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/12/2020	47854	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/10/2020	13045	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/10/2020	13045	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	3 guards need replacing			04/10/2020	13045	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/10/2020	13045	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			27/09/2020	12291	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			27/09/2020	12291	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice			15/09/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/09/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		05/09/2020		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	cancelled	02/09/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/07/2020	683488	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	2 x guaerds R and M (no guards in stock)		na	15/07/2020	683488	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FL small knock at bottom (monitor) AO and ME		na	15/07/2020	683488	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/07/2020	683488	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			13/06/2020	361398	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			13/06/2020	361398	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	replace l/h curtain rachet			12/06/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			06/06/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2020	359528	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/05/2020	359528	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\MUDGUARDS	2 x guaerds R and M (no guards in stock)			17/05/2020	359528	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	FL small knock at bottom (monitor) AO and ME			17/05/2020	359528	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\CHAS CRACK	small crack in X member behind skid plate (monitor)			17/05/2020	359528	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearings have top and bottom knock			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	RHM & LHR guards			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate supports cracked			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	LHM guard side worn out			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	small holes, over streched at poles			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\WHEEL BRGS	all need doing			16/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	rips in curtain LHS			16/05/2020		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/05/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			05/05/2020	347374	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			05/05/2020	347374	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			05/05/2020	347374	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			05/05/2020	347374	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			26/04/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			26/04/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			25/04/2020	342212	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\DAMAGE	RHS car bars broken			04/04/2020		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TANK RAIL	repair damaged safety rail RHS			04/04/2020	338107	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
					need to go Freighter for											
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearings have top and bottom knock		Paul needs to work out what style of grease we will use after warranty	31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/03/2020	336066	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	RHM & LHR guards		RHM guard worn on side	31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate supports cracked			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\SHOCK ABS	RHM shock leaking		previously done	31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
					normal wear and tear observed											
T618	Wodonga - Workshop	Brakes	brake squeal		all ok	31/03/2020	336066	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	LHM guard side worn out			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	small holes, over streched at poles			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\WHEEL BRGS	all need doing			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\FIFTH WHEE	loaded, under side ok			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers and drop in yard			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Workshop\MOVE ASSET	get next service			31/03/2020	336066	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres	Job Added From Invoice			19/03/2020	321693	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			19/03/2020	321693	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			19/03/2020	321693	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Brake test results attached			01/03/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\MUDGUARDS	RHM & LHR guards			01/03/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate supports cracked			01/03/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Susp\SHOCK ABS	RHM shock leaking			01/03/2020	321666	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		01/03/2020	321666	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	brake squeal			29/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	Service overdue	VehService\DS		29/02/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	curtain repairs			24/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/01/2020	229282	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/01/2020	229282	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FAILURE	L/R & L/F		Previously completed	11/12/2019	285059	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP19	RHM inner u/s		Previously completed	11/12/2019	285059	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearings have top and bottom knock		to be completed by Freighter	11/12/2019	285059	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Brake test results attached			11/12/2019	285059	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	as per checklist	VehService\DS		11/12/2019	285059	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/11/2019	268206	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FAILURE	L/R & L/F			12/11/2019	268206	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP19	RHM inner u/s			12/11/2019	268206	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/11/2019	268206	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearings have top and bottom knock			12/11/2019	268206	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			23/10/2019	252049	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/10/2019	252049	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			23/10/2019	252049	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2019	252049	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/10/2019	252049	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\TP19	RHM inner u/s			16/10/2019	252049	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			29/09/2019	228213	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			29/09/2019	228213	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			12/09/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			12/09/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2019	228213	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/09/2019	228213	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Tyres\FAILURE	L/R & L/F			05/09/2019	228213	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		05/09/2019	228213	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes				05/09/2019	228213	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/08/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/07/2019	188912	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/07/2019	188912	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		02/07/2019	188912	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL GATES	gates			28/05/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL GATES	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2019	156335	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/05/2019	156335	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/03/2019	127771	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/03/2019	127771	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/01/2019	101870	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/01/2019	101870	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\HOUSEKEEP	weld load bars near skid plate		aldonga completed	04/12/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2018	68731	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TOOLBOX	fit pallet angle carrier			01/12/2018	68731	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2018	68731	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\TRL REPS	fit/weld tie down bars			01/12/2018	68731	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice			13/11/2018	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2018	51503	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/10/2018	51503	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/09/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER

T618	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	13/09/2018		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Body\CHN/RLR/MN	replaced ratchet		05/09/2018	16767	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER
T618	Wodonga - Workshop	Elect\ELECT P&W	changed all plug 7 to 5 pin		09/08/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074955	Wodonga Workshop	TRAILER