EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T619	Wodonga - Workshop	Body\TRL REPS	Curtain roller's are getting stuck in curtain roller track's at the rear of the trailer, the driver is asking for the curtain rail's to be replaced.			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie on service	01/10/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\VALVES	BRAKES STICKING ON. WON'T RELEASE FOR A LONG TIME.			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR LEAK	Air Leak Air Bag			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	Air bag leak			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Apparently the trailer need's New Curtain Rail's as the curtain's are getting caught, as noted by the driver [N, Greening]			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	RHS REAR INDICATOR & TAIL LIGHT NOT WORKING			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL WALL	needs new curtain rails getting caught			01/10/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/09/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Upright need's a bolt ????			25/09/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL WALL	upright needs bolt not sure if a or b			25/09/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
					Respond To Breakdown Call Mangers Report, Brakes Locked on Unsure Why Travel From Callaway workshops											
					To Site At Ravenhall (Labour Charge)35Mins											
					$90.30											
T619	Wodonga - Workshop	Elect\SUZI COIL	Elect\SUZI COIL leak		Found Female Coueline On Rear Suzie Coils Leakine.Remove and Replace Female Coueline.Test Sxstem AllOk	25/05/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	CALLAWAY DIESEL	TRAILER
T619	Wodonga - Workshop	Susp\AIR LEAK	Air Leak in fitting's between trailer's.			16/06/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/04/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			27/03/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			27/03/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	completed SMc - MN	28/02/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Right side curtain roller repair.			10/02/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/02/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	PATCH CURTAIN. R/H REAR TOP.			02/02/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 23			21/01/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	Tyres\TP07	Tyres\TP07 (27)			21/01/2026	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/01/2026	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Left front curtain ratchet to be replaced.			06/01/2026	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Driver Side Rear Of Curtain At The Top Is Broken Away And Curtain Jams Also Rear Roller Buggered			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\STRAPS	Fix load restraint strap back to curtain			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	CURTAIN OFF LOAD RESTRAINT STRAP D/S.			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\SKID PLATE	Skid plate at its wear point			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	GREASE TURNTABLE			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	HAVE THE PINS IN TURNTABLE BEEN REPLACED			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/12/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	RUBBER AT TOP D/S.			06/12/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		06/12/2025	635505	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/11/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\MUDGUARDS	L/S REAR GUARD BRACKET LOOSE. ADJUST GUARDS BACK UP.			06/11/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			25/09/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/09/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX LID KEEPS COMING OPEN. CHANGE LOCK.			23/09/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	D/S CURTAIN TRACK FINGERED. CURTAIN GETS STUCK.		Pending	23/09/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\MUDGUARDS	RIGHT FRONT GUARD NEEDS ADJUSTING			23/09/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Curtain rail needs to be looked at. Getting caught D/S rear. Check rollers. Channel not good when I looked			23/09/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
			Replace King Pin.													
T619	Wodonga - Workshop	Chassis\KING PIN	ISUzu Diesel P/O: WW0986991			12/09/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	ELITE DIESEL REPAIRS	TRAILER
T619	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS.10			31/07/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			31/07/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	RI slack adjuster needs replacing...on backorder # unable to split due to heavy load .. applied tug and rock test no moment in table	30/07/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	upright rivets coming out or missing both sides			16/07/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			11/07/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BORDER BANDAG PTY LTD	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Right rear palmat rubber needs repair.			27/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
			Repair Damaged Curtain's.													
T619	Wodonga - Workshop	Body\TRL REPS	II Fix Curtains P/O: WW0952091			26/06/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	ITK TRUCK CURTAINS	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Unable to split due to heavy load ____ paper reels	26/06/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Right Side Last Roller Stuck			26/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	REAR TOP D/S PELMET AND CURTAIN JAMS WHEN PULL TO OPEN.			26/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	CHECK RATCHETS LOOSE.			26/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	CURTAIN STRAP			26/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\SLACK ADJ	Rear left slack adjuster not working properly			26/06/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Missing Stopper In The End			07/05/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Refit right side curtain,.			07/05/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	Reline on FL FR ML MR RR Hubs			17/04/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/04/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/03/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\MUDGUARDS	Straighten or replace gaurd flat bar			28/02/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\MUDGUARDS	New Guard's Needed. Maybe Outrigger's as well ?			06/02/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP5+6	Replace Tyres On Positions 5&6. (Yaxa Tyres P/O: WW091857)			03/02/2025	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BEAUREPAIRES	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	New Electric Plug Needed. (7 Pin)			30/01/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	L/H/Side Front Upright - Can't Open Pole Has Been Bent and Can't Open as Pin Hole has been bent and can't lift pin thru hole to open.			30/01/2025	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		30/01/2025	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/12/2024	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-12			12/12/2024	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	BEAUREPAIRES	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		29/11/2024	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\AIR LEAK	Check For Air Leaks & Repair, Brakes Dragging.(Gilbert & Roach Huntingwood P/O: WW0899931)			02/11/2024	635505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	PACCAR PARTS FLEET SERVICES	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	!	26/09/2024	635505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	Replace right front and left airbags, middle left and left rear airbags.			22/08/2024	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR LEAK	Find Air leaks.			21/08/2024	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR LEAK	Repair Air Leaks.			21/08/2024	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Replace Curtain Rail Stopper Bolt.			19/08/2024	635505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		19/08/2024	630505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	NEEDS SERVICE.			17/07/2024	630505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Replaced right hand rear air bag	17/07/2024	630505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	CURTAIN RATCHET HANDLE BROKEN OFF R/H.			17/07/2024	630505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			14/06/2024	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			14/06/2024	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service	VehService\DS	trailer has not moved since last service 14/04/24	17/05/2024	630505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			04/05/2024	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			23/04/2024	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Albury Workshop	TRAILER
T619	Wodonga - Workshop	Body\DAMAGE	REPLACED/ REPAIRED SIDE CRASH BARS.			20/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	Susp\AIR BAG			19/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/04/2024	301443	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DrvLine\WARRANTY	RF LM WHEEL BEARINGS REQUIRE ADJUSTMENT-WARRANTY. FREIGHTER TO COMPPLETE.			13/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			13/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			13/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis	REPAIRED BULK HEAD PLATE.			04/04/2024	301443	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\TRL LEGS	REPLACED BROKEN LEG HANDLE.			22/03/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			16/03/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Albury Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		re-line soon	08/12/2023	242425	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			08/12/2023	242425	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	BRAKES REQUIRE ATTENTION- LOUD SQUEALING AND NOT WORKING 100%.		checked during service - OK	08/12/2023	242425	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX DOOR LOOSE.		previously done	08/12/2023	242425	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2023	242425	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP11+12	replace tyres			22/11/2023	238228	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	PASSENGER SIDE CURTAIN RATCHET NEEDS ROLL PIN.			22/11/2023	238228	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			10/10/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			10/10/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection			10/10/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/10/2023		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/09/2023	214319	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
			RF RM LR WHEEL BEARINGS NEED ADJUSTMENT. UNDER WARRANTY.													
T619	Wodonga - Workshop	DrvLine\WHEEL BRGS	TO BE COMPLETED BY VAWOREY.			07/09/2023	214319	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			07/09/2023	214319	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/09/2023	214319	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			07/09/2023	214319	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/08/2023	209170	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			04/08/2023	209170	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	left front airbag required		PREVIOUSLY DONE.	04/08/2023	209170	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/08/2023	209170	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	1-12			04/08/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Albury Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			04/07/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Albury Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			06/06/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Albury Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2023	191678	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/06/2023	191678	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	holes in curtains			06/06/2023	191678	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	left front airbag required			06/06/2023	191678	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist													
T619	Wodonga - Workshop	VehService\DS	Barro Maxex POR WW077904	VehService\DS		21/04/2023	630505	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2023	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE.			21/04/2023	630505	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Unknown	SERVICE.			21/04/2023	630505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		21/04/2023	630505	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	FRONT POLE P/S VERY BENT.			21/04/2023	630505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\AIR FITTIN	AIR FITTING BETWEEN A & B LEAK.			21/04/2023	630505	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	RF CLEARANCE LIGHT OUT.			01/03/2023	169860	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2023	169860	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	0749S6	Wodonga Workshop	TRAILER
			RF RM LR WHEEL BEARINGS NEED ADJUSTMENT. UNDER WARRANTY.													
T619	Wodonga - Workshop	DrvLine\WHEEL BRGS	TO BE COMPLETED BY VAWOREY.			01/03/2023	169860	Repair	Completed	FL Green Distribution	Tilner	Wodonga

T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/11/2022	140952	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			19/11/2022	140952	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\MUDGUARDS	REPLACED LR GUARD.				19/11/2022	140952	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\RETREAD	Retread				03/10/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Albury Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			09/08/2022		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TANK RAIL	SAFETY RAIL BENT/ BROKEN				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX LOCK/ LATCH JAMMED CLOSED.				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body	REPLACE PELMET RUBBER.				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP1+2	supply and fit 4 tyres				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP3+4	supply and fit 2tyres				20/07/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	put curtain back in and put stopper in				06/07/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.				24/05/2022	62380	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/05/2022	62380	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			24/05/2022	62380	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DrivLine\WHEEL BRGS	RF RM LR WHEEL BEARINGS NEED ADJUSTMENT. UNDER WARRANTY.				24/05/2022	62380	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX LOCK/ LATCH JAMMED CLOSED.				24/05/2022	62380	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2022	44439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	Bushes worn				07/04/2022	44439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon		RELINED REAR AXLE.		07/04/2022	44439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TANK RAIL	SAFETY RAIL BENT/ BROKEN				07/04/2022	44439	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\STRAPS	RATCHET NEEDS REPLACING L/H/S.				07/04/2022	44439	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			07/04/2022	44439	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\SUSPENSION	Cross bracing cracking				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\DAMAGE	rear bar cracks/bent from jack				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	rear cross member start to crack both side				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\DAMAGE	rear bar cracked				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in rear bar need to be shortened.				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	Cross member rear axle on both sides has crack.				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL WALL	AT BACK OF TRAILER ONE SUPPORT PLATE IS OFF				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	CROSS MEMBER CRACKED BEHIND MIDDLE AXLE.				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			10/02/2022	14811	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TANK RAIL	SAFETY RAIL BENT/ BROKEN				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\AIR FITTIN	REPAIRED SUZI LINES.				10/02/2022	14811	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\DAMAGE	TYRE DAMAGE. REMOVED LR GUARD, BRACKET, MUDFLAP AND TAIL LIGHT FROM T613 AND FITTED TO TRAILER.				29/01/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyres				29/01/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	r/front and rear axle need adjust				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	L.F. wheel bearing need adjustment				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			31/12/2021	0	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	CROSS MEMBER CRACKED BEHIND MIDDLE AXLE.				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\AIR FITTIN	REPLACED AIR FITTINGS AND HUBBO. PARKED.				31/12/2021	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2021	559438	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\AIR BAG	Small air leak left side 3rd axle airbag.		CHECKED		01/12/2021	559438	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			01/12/2021	559438	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			01/12/2021	559438	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL WALL	REPAIRED REAR WALL.				01/12/2021	559438	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL WALL	AT BACK OF TRAILER ONE SUPPORT PLATE IS OFF				01/12/2021	559438	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check				07/11/2021	551806	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DrivLine\WHEEL BRGS	Need adjustment				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	G. bearings need adjusting				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	Running board on toolbox flaping around.				12/10/2021	539021	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\AIR LEAK	Big Air Leak Tri.		Replaced left rear air bag.		12/10/2021	539021	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	Cross member rear axle on both sides has crack.				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	Put into yard.				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			12/10/2021	539021	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/10/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			12/10/2021		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\Re-Tor	PDS 5,6 2 x failed air bags. Directed to G&S Diesel Wetherill Park.				12/10/2021	539021	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\BREAKDOWN	POWW0007309				09/10/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP5+6	fit run out & check wheelnut indicators				22/09/2021	259907	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check				22/09/2021	259907	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\MUDGUARDS	L.H. mudflap half ripped off		Inspected OK.		31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\FITMENT	Left hand rear duels need replacing.		Inspected OK.		31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	Will change Turn table bushes next service.				31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			31/08/2021	518647	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\SUZI COIL	Replaced EBS Lead and Changed Suzi Coils.				31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in rear bar need to be shortened. Clean up from weekend work.				31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\CLEAN	Movine trucks around.				31/08/2021	518647	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP9+10	fit 2 runouts				28/07/2021	519614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Pad slapped front axle.		28/07/2021	499614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\MUDGUARDS	L.H. mudflap half ripped off				28/07/2021	499614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			28/07/2021	499614	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\FITMENT	Left hand rear duels need replacing.				28/07/2021	499614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	Will change Turn table bushes next service. Hook up and move out from shed and park outside.				28/07/2021	499614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	Move into yard + smoko brakes.				28/07/2021	499614	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP3+4	replace 2 tyres				08/07/2021	517139	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP1+2	Supply and fit 4 tyres				08/06/2021	473805	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				08/06/2021	473805	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/06/2021	473809	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS	hook up with A&B and park out of shed as well		08/06/2021	473809	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\PRES CHECK	LF RR LHM inner tyre scalloped				08/06/2021	473809	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\DAMAGE	rear bar cracked				08/06/2021	473809	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon front Right curtain tensioner broken.				08/06/2021	473809	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Rear right slidine support pole broken.		Comoleted		28/04/2021	452322	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Right side curtain ratchet tensioner broken.		Replace front right curtain ratchet.		27/04/2021	451601	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			07/04/2021		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2021	443070	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			07/04/2021	443070	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2021	430251	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\TRL LIGHTS	needs reverse light bars fitted		as per discussion with supervisor		11/03/2021	430251	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			11/03/2021	430251	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\CROSS MBR	rear cross member start to crack both side				11/03/2021	430251	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP1+2	replace 2 tyres				12/02/2021	380250	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\TP3+4	fit 2 run outs				11/02/2021	415568	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/12/2020	397568	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			31/12/2020	397568	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	yard check, clean up, pack away parts and bolts				31/12/2020	397568	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	yard check				31/12/2020	397568	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	G. bearings need adjusting				31/12/2020	397568	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2020	387174	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			28/11/2020	387174	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\MUDGUARDS	R.R mudflap plate has bent				28/11/2020	387174	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	L.F. wheel bearing need adjustment				28/11/2020	387174	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\DAMAGE	rear bar cracks/bent from jack				23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp\WHEEL ALIGN	Wheel alignment recommended				23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\FIFTH WHEE	Bushes worn		checked - ok		23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			23/10/2020	372048	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\MUDGUARDS	L.H. mudflap half ripped off				23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\WHEEL BRGS	r/front and rear axle need adjust				23/10/2020	372048	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				25/09/2020	360051	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				25/09/2020	360051	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DrivLine	Job Added From Invoice				24/09/2020	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/09/2020	36005	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS	suzie lines and abs repair removed curtain replaced rollers moved trailers		22/09/2020	36005	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	right curtain jamed only goes half way		rehune curtain		12/09/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	curtain wont slide, jamming up				12/09/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	curtain rollers jamming in track on RHS				12/09/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	curtain rollers jamming in track on RHS		inspected rollers RH side of A		04/09/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	curtain wont slide, jamming up		Rollers L/S reolace asap		04/09/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	right curtain jamed only goes half way				04/09/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis\SUZI COIL	replace suzi couplings between A and B				04/09/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	park combination				04/09/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/08/2020	349850	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\2DS	D Service As Per Attached Checklist	VehService\2DS			22/08/2020	349850	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				12/08/2020	332681	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				12/08/2020	332681	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\HOUSEKEEP	angle rack needed		RR's pre Jan 20 (system clean out) 05/08/20		06/08/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	check curtains rollers		replace rollers in curtain repair to truck end and rehang curtain and park up		24/07/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/07/2020	33268	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres	5x tyres needed		Previously completed		18/07/2020	33268	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\DAMAGE	Repair damage to protection. repair damage to protection				18/07/2020	33268	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	right curtain jammed only goes half way				18/07/2020	33268	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TRL REPS	Curtain wont sl

T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		01/05/2020	295449	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|DAMAGE	front left tyre's spot's		Previously completed	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	all airbags		Airbags ok	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DriveLine|WHEEL BRGS	need adjustment		Previously completed	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|HOUSEKEEP	hubs have movement		Hubs ok	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|FIFTH WHEE	needs dogbones and rollback pins		Turntable ok	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	RH curtain hard to move forward		Curtain moves ok in both directions	01/05/2020	295449	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	Move trailer set into shed		Move set out	01/05/2020	295449	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		02/04/2020	279162	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes|BRAKE ADJ	to be greased			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|HOUSEKEEP	hubs have movement			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|FIFTH WHEE	needs dogbones and rollback pins			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|HOUSEKEEP	underside checked			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|CHAS CRACK	need more bars welded in under deck for straps			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	weld new tie rails under front of trailer (both sides)			02/04/2020	279162	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR LEAK	locate air leak			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|SUZI COIL	repair suzi coil base			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	hook up & drop out in yard			02/04/2020	279162	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	grease t619/620	VehService|DS		02/04/2020	279162	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	fix rope rails			22/03/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	clean up			04/03/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	repair intrusion bar			03/03/2020	679857	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	inspect curtain rollers , suggest replacing RH rollers			03/03/2020	679857	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	RH curtain hard to move forward			03/03/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|FITMENT	bottom intrusion bar broken RHS			03/03/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Brake test results attached			02/03/2020	264930	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|WHEEL ALGN	Wheel alignment recommended			02/03/2020	264930	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|SUSPENSION	Cross bracing cracking			02/03/2020	264930	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	Weld new tie rails under front of trailer (both sides)			02/03/2020	264930	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	fit rope rails to front of trailer curtains not rolling correctly			02/03/2020	264930	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	repair damage to underrun protection			02/03/2020	264930	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service	VehService|DS		02/03/2020	264930	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|CROSS MBR	Crossmembers cracked			06/02/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	weld new tie rails under front of trailer (both sides)			06/02/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|HOUSEKEEP	angle rack needed			06/02/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
			rope rails at front of trailer are to high up making it near impossible to hook up straps													
			fit full length rope rails to front at trailer													
T619	Wodonga - Workshop	Chassis|WINCH/STRP	fit anele rack		AS per #270583 & #270582	06/02/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	repair damage to protection		Made minor repairs & ordered parts	06/02/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|MUDGUARDS	replace l/centre and l/rear guards			05/02/2020	495908	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	clean up			05/02/2020	495908	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	move assets			05/02/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DriveLine|WHEEL BRGS	need adjustment			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	weld new tie rails under front of trailer (both sides)			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|HOUSEKEEP	angle rack needed			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
			rope rails at front of trailer are to high up making it near impossible to hook up straps													
			fit full length rope rails to front at trailer													
T619	Wodonga - Workshop	Chassis|WINCH/STRP	fit anele rack			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	repair damage to protection		Need to order parts	25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	need new tie down points on front end of trailer		As per #269033	25/01/2020	248832	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|AIR LEAK	air connection between A&B leaks			25/01/2020	248832	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		25/01/2020	248832	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|AIR FITTIN	Suzi couplings leaking			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|CROSS MBR	Crossmembers cracked			25/01/2020	248832	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	yard check pick up service			24/01/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|CHAS CRACK	need more bars welded in under deck for straps			18/12/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	DriveLine|WHEEL BRGS	need adjustment			18/12/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		18/12/2019		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		18/12/2019		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|Air Callout	Job Added From Invoice			26/11/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|Punct	Job Added From Invoice			26/11/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect|ELECT P&W	electrical plug problems			25/11/2019	0	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect|INDICATORS	no indicators left side trailers			25/11/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|CASE STOCK	Job Added From Invoice			23/11/2019	221791	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|PRES CHECK	Job Added From Invoice			23/11/2019	221791	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice			23/11/2019	221791	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|RETREAD	Job Added From Invoice			23/11/2019	221791	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|Punct	Job Added From Invoice			23/11/2019	223428	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	Move & hook set up			10/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	Clean up from job			10/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	Replace air bags			10/11/2019	221790	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	Hook set together			10/11/2019	221790	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp|ANN INSP	Annual Inspection As Per Checklist	Insp|ANN INSP		04/11/2019	221790	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Chassis|FIFTH WHEE	Ttable pins and bushes need replacing			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect|TRL LIGHTS	needs reverse light bars fitted			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
					C-26773x6 required. On order											
					docking valve was left in dump posittion also											
T619	Wodonga - Workshop	Susp|AIR BAG	6x airbags tops leaking		x6 replaced	04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|DAMAGE	front left tyre's spot's			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	rear bar cracks/bent from jack		rear bar to low	04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	rear bar			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	crack in rear bar			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR BAG	lm leaking			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	weld new tie rails under front of trailer (both sides)			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|HOUSEKEEP	angle rack needed			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
			rope rails at front of trailer are to high up making it near impossible to hook up straps													
			fit full length rope rails to front at trailer													
T619	Wodonga - Workshop	Chassis|WINCH/STRP	fit anele rack			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	repair damage to protection			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|BOOSTER	new bolt for lap winder			04/11/2019	217137	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	need new tie down points on front end of trailer			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	all airbags			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	all airbags			04/11/2019	217137	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
					SVC incomplete trailer too low due to faulty airbags and being loaded. Needs to be unloaded and brought back for repairs											
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	included movine trailers and smoko	04/11/2019	217137	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	organise repairs for next day			29/10/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice			23/10/2019	208276	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|CASE STOCK	Job Added From Invoice			23/10/2019	208276	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|RETREAD	Job Added From Invoice			23/10/2019	208276	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/10/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		22/10/2019		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	crack in rear bar			15/09/2019	191836	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR BAG	lm leaking			15/09/2019	191836	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2019	191836	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		15/09/2019	191836	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR BAG	AIR BAGS WONT PUMP UP			28/08/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/08/2019	179154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		16/08/2019	179154	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	Back light bar crack, RHS safety bar broken			16/08/2019	179154	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect|BREAKDOWN	T619 and T620 left indicator ringing and brought on the reverse alarm.			31/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	p/s curtain ratchet broken			12/07/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	cleaning			10/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	6x airbags tops leaking		still pending	10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|DAMAGE	front left tyre's spot's		job still pending	10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	rear bar cracks/bent from jack			10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|DAMAGE	rear bar			10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|SHOCK ABS	6x airbags tops leaking			10/07/2019	195853	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		10/07/2019	195853	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	R/H ratchet not working		G&S Diesel to repairs	03/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL REPS	L/H ratchet broken			02/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	6 air bags (26773 (leaking)			19/06/2019	146274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	6x airbags tops leaking			19/06/2019	146274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR LEAK	air leak air bag middle tri?		as per job#232453	19/06/2019	146274	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR BAG	airbags seem low		as per job#232453	19/06/2019	146274	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR LEAK	leaking air bag RHS back axle		as per job#232453	19/06/2019	146274	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	trl axle airbags seem to sitting low nowhere to put angles		as per job#232453	19/06/2019	146274	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D service	VehService|DS		19/06/2019	146274	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Tyres|DAMAGE	front left tyre's spot's			19/06/2019	146274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2019	146274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|TRL GATES	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|CLEAN	cleaning workshop per service			23/05/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop|MOVE ASSET	picking up trailers			23/05/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|HOUSEKEEP	angle rack needed			23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR LEAK	air leak air bag middle tri?		warranty job all 6 need to be done	23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR BAG	airbags seem low		as per job#226481	23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR LEAK	leaking air bag RHS back axle		as per job #226481	23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS		23/05/2019	140624	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|FIFTH WHEE	needs new pins and dog bones			23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|AIR BAG	6x airbags tops leaking			23/05/2019	140624	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body|AIR LEAK	sorwed bars and booster lines for air leaks found 2 3/4 air lines leakine tightned hose clamos and all 6 air bags leakine IT17CA3 loaded with board and did not have enouah airbaes movine trailers and			11/05/2019	133410	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Susp|HCV	inspect 619/620 for ride height as trailers where sitting low, used dock valve to raise and then reset, trailers reset at normal level could not fault height while unloaded			10/05/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHS	0745956	Wodonga Workshop	TRAILER
			fit new airbag hook trailers back together found maxi line split while taking back down the yard pulled back into shed replaced maxi line and service also noticed RHR airbag leaking												

T619	Wodonga - Workshop	Body\TOOLBOX	Job Added From Invoice				30/01/2019	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	Electrical Parts & Wiring			investigate light problem and make up 5pin to 7pin adapter	18/01/2019	77883	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailers				29/12/2018	442082	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Body\TOOLBOX	removed tool box				29/12/2018	442082	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			completed	08/12/2018	64865	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Completed		08/12/2018	64865	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/10/2018	42029	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			31/10/2018	42029	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	Job Added From Invoice				28/09/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\LTRL LIGHTS	Job Added From Invoice				28/09/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice				25/09/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	rewire light plug adaptor on trailer, from 7-pin set up to 5-pin set up				21/09/2018	19356	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Elect\ELECT P&W	make standard to heavy duty adaptor				19/09/2018	19201	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/09/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/09/2018		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER
T619	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers and fit service label holder to trailer				13/09/2018	16413	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074956	Wodonga Workshop	TRAILER