EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie on service	05/10/2026	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\PANELS	rear light bar bent			05/10/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Metal Plate On Top Of Trailer Ripped On Both Sides			14/07/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie and cheyne on service	14/07/2026	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\AIR LEAK	Repair Air Leak/s On Brake Hose Between A & B Trailers		completed by KR	18/06/2026	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP01	Tyres\TP01 POS 21			04/06/2026	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BORDER BANDAG PTY LTD	TRAILER
T613	Wodonga - Workshop	Elect\TRL LIGHTS	clearance lights fix			21/04/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL WALL	lh upright needs securing			21/04/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\Punct	Tyres\Punct POS 24			10/04/2026	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BORDER BANDAG PTY LTD	TRAILER
T613	Wodonga - Workshop	Brakes\BRK RELINE	Reline due middle axle			08/04/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/04/2026	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\AIR LEAK	Suzie lines leaking			08/04/2026	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP Annual Inspection As Per Checklist	Insp\ANN INSP		08/04/2026	285154	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/02/2026	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/01/2026	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			05/12/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BORDER BANDAG PTY LTD	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/12/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES.			02/12/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Replace curtain roller's.			14/11/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/11/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	LUBE OR CLEAN CURTAIN ROLLER TRACK		Pending	30/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	→BOTH SIDE CURTAINS ROLLERS ARE STIFF. VERY DIFFICULT TO MOVE CURTAINS.		Pending	30/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	L/H/S Curtain Doesn't Slide Properly, Catches All Time		Pending	30/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	BOTH CURTAINS VERY HARD TO PULL.			30/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\ELECT P&W	Replace light duty socket.			30/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\AIR LEAK	REPLACE BRAKE HOSE			28/10/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHF UPRIGHT POLE RIVOTS BROKEN.			14/10/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/10/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 25			08/09/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BORDER BANDAG PTY LTD	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	CURTAINS VERY HARD TO MOVE BACKWARDS BOTH SIDES AND UPRIGHTS NEEDS REPAIR.			04/09/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		27/08/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHF upright pole rivets broken			27/08/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline On 4 Positions.			27/08/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			29/07/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BORDER BANDAG PTY LTD	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Unable to split due to heavy load ,,,, paper reels	24/07/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	lube or clean curtain roller track			24/07/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
					Self adjusters....checked seem to be fine tested fl and was at correct adjustment											
T613	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjust brakes			24/07/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres	Tyres - NO POS GIVEN			14/07/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEEL GREASE TURNTABLE ON A TRAILER			10/07/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Unable to split due to heavy load,,, paper reels	28/06/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LM LR			23/05/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	L/H Upright Pole Rivets Broken			12/05/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		10/05/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Various Small Holes In Curtains Both Sides		5 Repairs to drivers side 30 inches	28/04/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	IFIX TRUCK CURTAINS	TRAILER
T613	Wodonga - Workshop	Elect\TAIL LIGHT	REPLACED RH TAIL LIGHT AND INDICATOR.			04/04/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body	Broken weld above middle x member.			04/04/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			29/03/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			29/03/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		28/03/2025	285154	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Curtains have some holes			28/03/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\MUDGUARDS	LH guard mount bent by forklift			28/03/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	LHR upright pole rivets broken			28/03/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		15/03/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\MUDGUARDS	Fabricate right rear guard mounting plate.			12/02/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		01/02/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\LIGHTS	RH taillight missing			01/02/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\MUDGUARDS	RHR Gurad missing + mudflap			01/02/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	RHR clearance light missing			01/02/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP06	Tyres\TP06			29/01/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			14/01/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			14/01/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			14/01/2025	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		11/01/2025	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Replace left front curtain ratchet.			10/01/2025	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		04/11/2024	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP01	Fit Run Out Tyre To Position 1. (Wodonga Tyre & Auto P/O: WW090083)			04/11/2024	285154	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	BEAUREPAIRES	TRAILER
T613	Wodonga - Workshop	Susp\HCV	Adjust Ride Height			19/10/2024	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		21/09/2024	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		17/08/2024	285154	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Replace right front curtain ratchet.			07/08/2024	285154	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			08/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			08/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Contract\WHEEL BRGS	bearings have movement D Service As Per Attached Checklist			08/09/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	Trailer not used since last service.	VehService\DS		08/09/2023		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		08/09/2023		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis	Onsite and weld lug back on chassis			04/02/2023		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Albury Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			24/05/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	Has not been moved since last service 14/04.	VehService\DS		24/05/2022		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate foundation broken			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Contract\WHEEL BRGS	bearings have movement			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\SKID PLATE	cracks in foundation Record Check Results As Attached To This Job			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Needs Reline ASAP.		RELINED.	15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/04/2022	547680	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\MUDGUARDS	REPLACED LRGUARD, REAR MARKERS AND LR LIGHT ASSEMBLY. RESET RR GUARD.			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\AIR LEAK	LOCATED AND RECTIFIED AIR LEAKS. CLEANED UP.			15/04/2022	547680	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			12/03/2022		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	Has not moved since Oct 2021.	VehService\DS		12/03/2022		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	MOVE OUT OF SHED			10/10/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL WALL	Repair Rear Wall and Curtain Track Brackets. 1 x length 75 x 5 Flat Bar Rear Wall Repairs Don Sparks Steel		REPAIRED REAR WALL AND CURTAIN	09/10/2021	547662	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL WALL	PO# WW067668			09/10/2021	547662	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
					Perform laser wheel alignment on triaxle											
T613	Wodonga - Workshop	Susp\WHEEL ALGN	DROP OFF AT HTT. PICK UP.		trailer	07/10/2021	547655	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\KING PIN	Replace Kingpin.			02/10/2021	547628	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\MUDGUARDS	Replace RHR Guard - Includes straightening outrigger. Record Check Results As Attached To This Job			02/10/2021	547628	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Neeeds Reline ASAP.			29/08/2021	535196	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist ATTENDED AFTER HOURS CALLOUT TO ALPINE MDF FOUND A TRAILER FRONT TRAILER LIGHT SOCKET DAMAGED REPLACED & TESTED ALL LIGHTS	VehService\DS		29/08/2021	535196	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	RETURN TO WORKSHOP			12/08/2021	524493	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/07/2021	522552	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Curtain Roller Jam at Back of trailer		Checked OK.	23/07/2021	522552	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/07/2021	522552	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER

			Pick up from yard.															
T613	Wodonga - Workshop	Workshop\MOVE ASSET	Drop off after service into the yard.			23/07/2021	522552	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\AIR LEAK	REPLACED SUZI COUPLINGS ON BACK			17/07/2021	518543	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP0S	Puncture repair			11/07/2021	515573	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP7+8	Supply and fit 2 tyres			22/06/2021	507167	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		19/05/2021		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2021	496268	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/05/2021	496268	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Unknown	Trailer due for service			19/05/2021	496268	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\AIR TANKS	Main Air Tank two clamps loose.		Completed by Sunny.	19/05/2021	496268	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		10/04/2021		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/04/2021	480338	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/04/2021	480338	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CROSS MBR	Cross bracing cracked			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate foundation broken			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Contract\WHEEL BRGS	bearings have movement		LF,RR has little movement, it is under warranty. Has to go Freigther	10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\SKID PLATE	cracks in foundation			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHS curtain rollers need replacement			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	curtains rollers notchy			10/03/2021	468645	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	repair worn out curtain rollers			10/03/2021	468645	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/03/2021	468645	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		10/03/2021	468645	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	yard check, move trailers for service			10/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\CLEAN	drop off and clean up			10/03/2021		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2021	441577	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	axles not jacked due to being loaded with paper reels and driver time constraints	20/01/2021	441577	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	curtains rollers notchy			20/01/2021	441577	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TP9+10	replace 2 tyres			11/01/2021	435228	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			30/12/2020	427432	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			30/12/2020	427432	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job blown tyre in the rack needs replacing and refitting on centre axle RHS inside			05/12/2020	422356	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TPS1	please check all other tyres			05/12/2020	422356	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/12/2020	422356	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/11/2020	404929	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/11/2020	404929	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\TP06	cracks in cross member at rear axle			05/11/2020	404929	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted			05/11/2020	404929	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			30/10/2020	395288	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			30/10/2020	395288	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/09/2020	38440	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate foundation broken		still pending	24/09/2020	38440	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\SUZI COIL	air line got caught up and pulled ABS plug off front of trailer		previously done	24/09/2020	38440	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/09/2020	38440	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Contract\WHEEL BRGS	bearings have movement			24/09/2020	38440	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\SKID PLATE	cracks in foundation			24/09/2020	38440	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted			24/09/2020	38440	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHS curtain rollers need replacement		maxiparts for parts Poww058254	24/09/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	DrivLine	Job Added From Invoice			24/09/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		carry out D service	01/09/2020	374384	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	BrakesLab\BOOSTER	RHF Booster			01/09/2020	374384	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2020	374384	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	curtain rollers need replacing			01/09/2020	374384	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	carry out D service	01/09/2020	374384	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/09/2020	374384	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			27/08/2020	369571	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			27/08/2020	369571	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			27/08/2020	369571	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\EBS FAULTS	Replaced EBS female plug			19/08/2020	367686	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			12/08/2020	360021	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			12/08/2020	360021	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body	Job Added From Invoice			08/08/2020	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	DrivLine\WHEEL BRGS	Bearings need adjustment		Completed during service	01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate foundation broken gate rack bent/ twisted			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	BrakesLab\BOOSTER	RHF Booster			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CROSS MBR	Cross bracing cracked			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\MUDGUARDS	LHR mount bent		Previously completed Checked OK	01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	DrivLine\WHEEL BRGS	check wheel bearings		Double checked by Adon	01/08/2020		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/08/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHS curtain rollers need replacement			01/08/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\REFLECTORS	cut old reflector bracket off (bent) make and fit new one move			31/07/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/07/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/07/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2020	34405	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2020	34405	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/06/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\MUDGUARDS	LHR mount bent			23/06/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\MUDGUARDS	fixed outrigger on l/h/s rear			22/06/2020	344405	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/05/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			02/05/2020	315928	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			02/05/2020	315928	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			02/05/2020	315928	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			02/05/2020	315928	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			17/04/2020	305098	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	modify corner bracket & take bolts out & put in top			14/04/2020	307226	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\TRAINING	operate forklift			14/04/2020	307226	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/04/2020	305099	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BOOSTER	RHF Booster			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\CROSS MBR	Cross bracing cracked			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Susp\SUSPENSION	Bushes worn			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Susp\SUSPENSION	Suspension			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers for a service			07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BOOSTER	tighten booster bolts remove curtain replace 2 rear rollers		remove and inspect for damage	07/04/2020	305099	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	& replace curtain			13/03/2020	294180	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted		Completed on 06/03/2020	13/03/2020	294180	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			13/03/2020	294180	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	RHS curtain 2 rear curtain rollers not working properly		Both replaced	13/03/2020	294180	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres	check tyres pressure and tread		Tyre fitters job	13/03/2020	294180	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Completed on 06/03/2020	13/03/2020	294180	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	move trailors			07/03/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			07/03/2020	290521	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			07/03/2020	290521	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER

T613	Wodonga - Workshop	Body\TRL REPS	RHS curtain 2 rear curtain rollers not working properly			07/03/2020	290521	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/03/2020	290521	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	DrivLine\WHEEL BRGS	Bearings need adjustment			07/03/2020	290521	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate foundation broken			07/03/2020	290521	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			03/03/2020	28685	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/02/2020		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2020	273058	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL FLOOR	loaded - under side ok			02/02/2020	273058	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	yard check - brought back 613/614 for service			02/02/2020	273058	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2020	273058	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	annual inspection as per check list			02/02/2020	273058	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	Drop T613-614 on back fence			02/02/2020		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	replace plug on A trailer			31/12/2019	259047	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	trace wiring issue			31/12/2019	259047	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job gate rack bent/ twisted			31/12/2019	259047	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			31/12/2019	259047	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TRA	tyre rotation and pressure check		OK by tyrefitter	31/12/2019	259047	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\TY	pressure check and rotate tyres		Ok by tyre fitter	31/12/2019	259047	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/12/2019	259047	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			25/12/2019	250214	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			25/12/2019	250214	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			25/12/2019	250214	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\TRL REPS	RHS curtain 2 rear curtain rollers not working properly			19/12/2019		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\DRV TYRES	check tyres pressure and thread			19/12/2019		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\WHL HUB	check wheel bearings			19/12/2019		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			11/12/2019	249471	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/12/2019	246679	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	moving trailers	02/12/2019	246679	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Chassis\FIFTH WHEE	adjusted Ttable			02/12/2019	246679	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			22/11/2019	239858	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			22/11/2019	239858	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			22/11/2019	239858	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	Change trailer base plug			08/11/2019	234868	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		29/10/2019		PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/10/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/10/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/09/2019	206727	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/09/2019	206727	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\MUDGUARDS	L rear needs replacing (guard) gate rack bent/ twisted		Completed previously	31/07/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	*Parts on order*			31/07/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/07/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			14/07/2019	164954	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes\BRAKE ADJ	Record Check Results As Attached To This Job			26/06/2019	164244	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/06/2019	164244	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			25/06/2019	10	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			25/06/2019	10	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2019	147470	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/05/2019	147470	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\MUDGUARDS	L rear needs replacing (guard)			28/05/2019	147470	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	gate rack bent/ twisted			28/05/2019	147470	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL GATES	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2019	117560	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL FLOOR	loaded			04/04/2019	117560	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist Service	VehService\DS		04/04/2019	117560	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	warranty elec work refer Dean	VehService\DS	previously repaired	04/04/2019	117560	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/02/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/02/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	moving trailer			26/02/2019	100444	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/02/2019	100444	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	Service	VehService\DS		26/02/2019	100444	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL FLOOR	loaded			20/01/2019	83999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2019	83999	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	Service	VehService\DS		20/01/2019	83999	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			01/01/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/12/2018	63982	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL WALL	rear wall of trailer needs repairs		job pending	11/12/2018	63982	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\ELECT P&W	rewire to 5 pin		previously done	11/12/2018	63982	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/12/2018	63982	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2018	50452	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/11/2018	50452	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\W/S MAINT	Workshop Tool Maintenance		remove air jack from ynder the trailer	13/11/2018	50134	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL WALL	rear wall of trailer needs repairs			27/10/2018	43103	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	curtain roller end bolts need to be replaced (requested by Visy)			27/10/2018	43103	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		complete during service	17/10/2018	38555	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/10/2018	38555	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TOOLBOX	remove toolbox door from T615 and fit on T613			10/10/2018	35389	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice			25/09/2018	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\TRL REPS	Replace LHF ratchet			13/09/2018	19610	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService	Fit service sticker with todays date			13/09/2018	19610	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	VehService\DS	First service TCTC	VehService\DS		13/09/2018	19610	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Body\DAMAGE	body repairs			28/08/2018	10310	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			28/08/2018	10310	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER
T613	Wodonga - Workshop	Elect\TRL LIGHTS	no driving lights on trailers			24/08/2018		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	0748S6	Wodonga Workshop	TRAILER