EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1027	Wodonga - Workshop	Engine\ADBLUE	exhaust gas aftertreatment fault		needs to go to damele	06/10/2026	1228756	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	Right parking globe not working		- parker globe replaced on right hand side, moisture getting into headlights causing globes to blow, will need new headlight units to stop globes from blowing.	14/07/2026	1191560	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					NOTIFIED OF BREAKDOWN											
					ORGANISED PARTS											
					DROVE TO VEHICLE											
					INSPECTED FOUND NO CRANK NO START											
					TESTED VOLTAGE AT EXCITER WIRE ALL OK											
					STARTER SOLENOID WOULD CLICK BUT NOT ENGAGE											
					REMOVED AND REPLACED STARTER MOTOR.											
					STARTED VEHICLE											
1027	Wodonga - Workshop	Engine\START MOTR	Engine\START MOTR		PACKED UP TOOLS	22/08/2026	1183053	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Elect\TAIL LIGHT	prime mover back light not working parking light		completed by KR	04/08/2026	1174859	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					S.SINGH											
1027	Wodonga - Workshop	DrCabRep\HOUSEKEEP	REPAIR WIND GUARD		completed and tested	09/05/2026	1172755	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					S.SINGH											
1027	Wodonga - Workshop	Elect\HEAD LIGHT	LEFT SIDE DIPPED BEAM FAULTY?		completed and tested	09/05/2026	1172755	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	REPAIR HEADLIGHTS		remove /replace	03/05/2026	1169181	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			02/05/2026	1168630	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	Assess/replace Head Light's			27/03/2026	1151545	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 9			18/02/2026	1142372	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		22/01/2026	1129110	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\FIFTH WHEE	Turntable bushes worn need to be replaced			22/01/2026	1129110	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					Labour- Mobile Breakdown											
					Callout for suspected coolant leak											
					Travelled to workshop to collect equipment and parts											
					Travelled to Avenel Roadhouse											
					Found coolant line to be split on fire wall											
					Removed hose and cut off split section and fit back to truck											
					Fill with water and start engine											
			Cooling\COOL LEAKS		Checked coolant level- All okay. Travelled back to											
1027	Wodonga - Workshop	Cooling\COOL LEAKS	WWO88471		workshop	05/01/2026	1119834	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	WARRIEGO TRANSPORT REPAIRS	P/MOVER
			Check For Coolant Leaks & Repair													
1027	Wodonga - Workshop	Cooling\COOL LEAKS	(Parts Supplied By Daimler Trucks Albury P/O: WWO88437)			29/12/2025	1119781	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\FUEL TANK	ADBLUE LID BROKEN INSIDE		REPLACED INSERT ASSEMBLY	23/12/2025	1116237	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	DrCabRep\ELECT P&W	Ad Blu led broken inside.			23/12/2025	1116237	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Susp\AIR BAG	Air Bag Oil Leak			20/11/2025	1121504	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	VehService\BS	B Service	VehService\BS		20/11/2025	1121504	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	DrivLine\DIL LEAK	Front diff pinion seal leaking		M.NEWLEY 2½ HOURS	20/11/2025	1121504	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	VehService\AS	VehService\AS A Service	VehService\AS		20/11/2025	1102308	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					Drove to the breakdown.											
					Consulted the driver.											
					Tested gear shifting - ALL OK											
					Driver drove back and forward to test - ALL OK											
					Plugged in diagnostic scanner, found no active transmission fault codes.											
					Checked EBS stored terminal 15 fault, inspected it.											
					could not fault.											
					Consulted the workshop foreman and drove back to workshop.											
					Vehicle brought to workshop for inspection on 05/11/25											
					Connected diagnostic scanner to the truck.											
					No transmission fault codes found but found a stored code for "EBS under voltage at terminal 15".											
					Inspected EBS plugs, pins and wires - ALL OK											
			Transmission Won't Select Gears.		Inspected conectivity from EBS to SSAM - ALL OK											
1027	Wodonga - Workshop	DrivLine\BREAKDOWN	(Daimler Albury P/O: WWO97927		Test Drove - ALL OK	06/11/2025	1129227	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Chassis\FUEL TANK	Repair Leaking Fuel Tank.			11/10/2025	1080551	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	Replace L/H High Beam Globe.			01/10/2025	1079539	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			03/09/2025	1069276	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
			Repair HVAC.													
1027	Wodonga - Workshop	Air Con\AIR CON	(Daimler Trucks Albury P/O: WWO96128)			07/08/2025	1129494	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			Brake Reline Rear Drive Axle & Replace Brake Rotors.													
1027	Wodonga - Workshop	Brakes\BRK RELINE	(Daimler Trucks Albury P/O: WWO96128)			07/08/2025	1129494	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			Replace Cooler Protector Screen.													
1027	Wodonga - Workshop	Body\PANELS	(Daimler Trucks Albury P/O: WWO96128)			07/08/2025	1129494	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Brakes\BRK RELINE	REPLACED PADS AND ROTORS ON REAR DRIVES.			06/08/2025	1056472	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			A Service.													
1027	Wodonga - Workshop	VehService\AS	(Daimler Albury P/O: WWO962671	VehService\AS		06/08/2025	1056472	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Steering\PWR STEER	Power steering fluid low		TOPPED UP. OK.	06/08/2025	1056472	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 8-9			04/07/2025	1042742	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BORDER BANDAG PTY LTD	P/MOVER
1027	Wodonga - Workshop	Elect\BRK LIGHT	No Brake Lights For Trailers			03/07/2025	1042159	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\TRL LIGHTS	Need New Plug			03/07/2025	1042159	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			air bag air leek.													
1027	Wodonga - Workshop	Susp\AIR BAG	(Daimler Trucks Albury P/O: WWO94901)			25/06/2025	1129494	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			air bag oil leek.													
1027	Wodonga - Workshop	DrivLine\DIL LEAK	(Daimler Trucks Albury P/O: WWO94901)			25/06/2025	1129494	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			air bag leek air oil leek.													
1027	Wodonga - Workshop	Susp\AIR BAG	(Daimler Trucks Albury P/O: WWO94901)			25/06/2025	1129494	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Body\MOUNTS	Tighten loose out rigger on RHF drive guard			12/06/2025	1035801	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\DRV LIGHT	Left side dipped beam faulty		/	22/05/2025	1025325	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	DrCabElec\INST/GAUGE	right side dipped beam fault		-replaced h7 drivers side headlight globe	12/05/2025	1019208	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\LUZI COIL	Truck to Trailer Plug Faulty.			09/04/2025	1004113	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.			09/04/2025	1004113	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService\AS	VehService\AS	VehService\AS	Cant acess brakes according to dash they are good till next year	09/04/2025	1004113	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService\AS	Dew serves			09/04/2025	1004113	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Prime mover air leak back side													
			R & R RHS FRONT BRAKE BOOSTER													
			INSPECT CAUSE OF LEAK WHEN BRAKES APPLIED- SUPPLY HOSE TO RHS BRAKE BOOSTER LEAKING- PUSH IN													
			FITTINGS WORN AND LOOSE.													
			REPLACE HOSE AND REQUIRED PUSH IN UNIONS.													
			SECURE ABS SENSOR AND BRAKE WEAR SENSOR TO HOSE.		Rhs front booster hoose leaking											
1027	Wodonga - Workshop	Brakes\AIR LEAK	TEST- ALL OK		Air diver leakine	01/04/2025	1000137	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\INDICATORS	right side turn signal lamp faulty			28/03/2025	998413	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					INSPECT CAUSE OF LEAK WHEN BRAKES APPLIED- SUPPLY HOSE TO RHS BRAKE BOOSTER LEAKING- PUSH IN												
					FITTINGS WORN AND LOOSE.											
					REPLACE HOSE AND REQUIRED PUSH IN UNIONS.											
1027	Wodonga - Workshop	Brakes\AIR LEAK	Repair Air Leak @ Front R/H Booster (Steer). (Daimler Trucks Albury P/O: WWO93226)		SECURE ABS SENSOR AND BRAKE WEAR SENSOR TO HOSE.	27/03/2025	998094	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Body\MUDGUARDS	TIGHTEN MUDGUARD OUTRIGGER.			12/03/2025	992664	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			07/03/2025	988725	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			07/03/2025	988725	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Susp\SUSPENSION	STARTING VIBRATING.			18/02/2025	980580	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
			staring vibration													
1027	Wodonga - Workshop	Steering\HOUSEKEEP	call -shaun			18/02/2025	980580	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\BALANCE	Tyres\BALANCE TRUCK - OFF VEHICLE			18/02/2025	980580	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Steering\WHEEL ALGN	Steering\STEERING VIBRATION			18/02/2025	980580	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
			MULTIPLE LIGHTS INOP S174.76													
			REPLACED RHS PARK LIGHT GLOBE - FOUND BLOWN													
			REPAIRED WIRING OF RHS BRAKE LIGHT - FOUND MULTIPLE BROKEN WIRES													
			REPLACED RHS FOG LIGHT UNIT - FOUND INOP AND BROKEN													
1027	Wodonga - Workshop	Elect\ELECT P&W	TESTED OPERATION - OK			12/02/2025	1130077	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	Tyres\STEER TYRE 7-8-9-10			07/02/2025	976473	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			07/02/2025	976473	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1 -10			07/02/2025	976473	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
			Right side mirror cover put new 1													
1027	Wodonga - Workshop	Body\MIRRORS	completed at daimler under work order #193596			05/02/2025	976157	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			left side mirror cover issue? fix it?													
1027	Wodonga - Workshop	Body\MIRRORS	completed at daimler under work order #193596			05/02/2025	976157	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Body\MOUNTS	Driver's Door Hinge , Binding and Sticking.			05/02/2025	976157	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			VehService\CS													
1027	Wodonga - Workshop	VehService\CS	Booked into Daimler	VehService\CS		05/02/2025	976157	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Body\HOUSEKEEP	drivers side door binding & catching very badly			05/02/2025	976157	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
			Body\MIRRORS													
			RHS MIRROR COVER MISSING													
			REPLACED MIRROR COVERS AS REQUESTED BY CUSTOMER													
1027	Wodonga - Workshop	Body\MIRRORS	SECURED WITH SILICONE			05/02/2025	976157	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		05/02/2025	976157	PreventativeMaintenance	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	DAIMLER TRUCKS ALBURY	P/MOVER
1027	Wodonga - Workshop	Tyres\Punct	Repair Punctured Tyre On Position 8. (Wodonga Tyre & Auto P/O: WWO91087)			19/12/2024	958743	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\FITMENT	Tyres\FITMENT 9			17/12/2024	957130	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1 -10			17/12/2024	957130	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Elect\ELECT P&W	ELECTRIC FAULT AUTOMATIC HAZARD LIGHTS ON TRAILERS- THURSDAY- TRUGANINA, ELECTRIC MECHANIC FIXED TEMPORARILY. CALLED SHAUN.		Previously completed	13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\ADBLUE	Fix Adblue Inside Ruber			13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					Raised and lowered airbags there is a leak from a bleed port fix front air bag this has been previously pulled apart and Shaun notified of the problem. Either Daimler to repair or part to be ordered.											
1027	Wodonga - Workshop	Susp\AIR LEAK	PRIME MOVER AIRBAGS. AIR LEAK COMING SOUND AIR LEEK. EVERY TIME PARK TRUCK DUMP AIR.		Move to oendine	13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	RIGHT SIDE DIPPED BEAM FAULTY		Lights have been tested both low and high beam are working correctly and no fault is evident. Need to remove code from dash this is a Daimler issue	13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\FIFTH WHEE	FRONT END OVERWEIGHT? ASK CODY HE SAID TO PARK BEHIND THE WORKSHOP?		Operations have spoken to driver as to how to load trailers correctly	13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\ELECT P&W	Side Light Fault, Right Parking Lamp Fault,		Daimler needed to clear Codes	13/11/2024	941321	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\ADBLUE	Engine\ADBLUE		FOUND COOLANT IN ADBLUE. SENT TO DAIMLER.	16/10/2024	930884	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					LHS STANDING LIGHT COVER BROKEN & LOOSE -											
					REMOVED AND REPLACED COVER.											
1027	Wodonga - Workshop	Body\PANELS	Replace Light Cover. (Daimler Albury P/O: WWO89428)		TESTED LIGHTING - ALL OK	15/10/2024	930852	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
					LHS GUARD LOOP KIT BROKEN & MISSING BOLTS -											
					REMOVED BROKEN LOOP KIT.											
1027	Wodonga - Workshop	Chassis\MUDGUARDS	Replace Damaged Loop Kit. (Daimler Trucks Albury P/O: WWO89428)		FITTED NEW LOOP KIT WITH NEW BOLTS AND TENSIONED.	15/10/2024	930852	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK STEER			11/10/2024	930242	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
			RIGHT SIDE MIRROR SWITCH BROKEN.													
1027	Wodonga - Workshop	Body\MIRRORS	HAND MIRROR UP DOWN.		SWITCH IS WORKING.	29/08/2024	910936	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\BELTS/TENS	BELT COMING NOISES SOUND? FRONT SIDE IS ALL READY SAID SHANE?		PREVIOUSLY COMPLETED.	29/08/2024	910936	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService\AS	A Service	VehService\AS		29/08/2024	910936	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		29/08/2024	910936	PreventativeMaintenance	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	COMING SIGN ENGINE FAULT.		CHECKED. NO ENGINE LIGHT.	29/08/2024	910936	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	ENGINE SIGN COMING ON DASH?		CHECKED. NO LIGHTS ON DASH.	29/08/2024	910936	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\DRV LIGHT	PUT NEW UGHT BULLBAR NIGHT TIME HARD DRIVE.		CHECKED. ALL WORKING.	29/08/2024	910936	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			TRAVEL TO SITE													
			07/07/2024 CALLOUT AFTER HOURS													
			CHECK ALL LIGHTS ON TRUCK													
			FOUND TRAILER PLUG TO BE DAMAGED													
			REMOVE AND REPLACE FAULTY TRAILER PLUG													
1027	Wodonga - Workshop	Elect\ELECT P&W	TEST OPERATION			18/08/2024	907458	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER
			Hazard Lights Coming On By Themselves (Pitstop Auto Electrical P/O: WWO87219)													
1027	Wodonga - Workshop	Elect\INDICATORS				05/07/2024	887322	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	PITSTOP AUTO ELECTRICAL	P/MOVER
			Hazzard Lights Stuck On (Pitstop Auto Electrical P/O: WWO87142)													
1027	Wodonga - Workshop	Elect\BREAKDOWN				05/07/2024	887322	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	PITSTOP AUTO ELECTRICAL	P/MOVER
1027	Wodonga - Workshop	Tyres\TP06	Tyres\TP06			29/06/2024	887007	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Tyres\Re-Tor	tension wheel			29/06/2024	887007	PreventativeMaintenance	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	DrivLine\CONGUMABLE	LEFT SIDE FRONT TYRE NUT LOOSE. SCREW-			13/06/2024	876481	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	BEAUREPAIRES	P/MOVER
1027	Wodonga - Workshop	Body\PANELS	REATTACHED RH SIDE SKIRTING UNDER CAB.			04/06/2024	872327	Fault	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	DrCabElec\GPS	4G update			24/05/2024	868024	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	ARKON AUTO ELECTRICAL	P/MOVER

1027	Wodonga - Workshop	Engine|FAULT CODE	multiple engine warnings on display					02/05/2024	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr|Cab|Reg|DAMAGE	damaged window switch					02/05/2024	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService|BS	Service As Per Attached Checklist	VehService|BS				23/02/2024	885795	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					23/02/2024	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Unknown	WARNING COME UP. MAINTENANCE DUE. MB OIL RECOMMENDED BUT OIL CHECK SAYS OK.					23/02/2024	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|HEAD LIGHT	Put new headlight in bumper					23/02/2024	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drive Line|OIL LEAK	oil leak near frontdiff top sender					23/02/2024	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr|Cab|Reg|WIPERS	replace wiper blades					23/02/2024	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drive Line|GEARBOX	TRUCK JUMPS IN AND OUT OF REVERSE UNDERLOAD.					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr|Cab|Reg|SEAT	SITE BELT NOT ROLLE BACK?. SITE BELTE NOT ROLLE BACK?					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|EJECT P&W	FLARING NEXT LIGHT ON DRIVER'S SIDE MISSING.					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MIRRORS	PASSENGER SIDE MIRROR MISSING BACKING COVER & LIGHT IS DAMAGED.					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						LHF MUDGUARD INSECURE - $169.73															
						INSPECTED AND FORM BROKEN GUARD HANGER															
						REMOVED GUARD ASSEMBLY															
						REMOVED AND REPLACED GUARD HANGER AND TENSIONED															
1027	Wodonga - Workshop	Body|MUDGUARDS	LEFT SIDE THE COVE TOUCH TIRE (LEFT GUARD TOUCHING TYRE)			ALL OK		28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|EJECT P&W	TRUCK RIGHT SIDE GLOB FUSE?					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drive Line|OIL LEAK	OIL LEAK R/H FRONT DRIVE.					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MIRRORS	Left Side Mirror Cover Change					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|PANELS	Both Side Front Light Cover Fixed Ask Me RMSA Today Bradford?					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|FUEL TANK	DIESEL TANK HAS PIPE LEAK.					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|EJECT P&W	LEFT SIDE MARKER LAMP FUSE?					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|EJECT P&W	LEFT SIDE MARKER LIGHT NOT WORKING?					28/12/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP3+2	replace tyres					05/11/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
						FOUND L/H FRONT HEADLIGHT GLOBE N/W															
1027	Wodonga - Workshop	Elect|HEAD LIGHT	Left Side truck light globe.			REMOVE AND REPLACE		06/10/2023		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|ADBLUE	Exhaust gas after treat faulty.			OPERATION OK		18/09/2023	885795	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			TRAVEL TO DEPOT																		
			LOCATE INDICATORS SHORTING																		
			TRACE SHORT- LOCATE SHORT IN WIRING UNDERNEARTH TRUCK																		
			REPAIR AS REQUIRED																		
1027	Wodonga - Workshop	Elect|INDICATORS	CHECK OPERATION OK					05/09/2023	769768	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
						ADDITIONAL PARTS REQUIRED NOT COVERED IN THE REFURBISHMENT KIT															
						AIR INTAKE ELBOW BROKEN															
						AIR COMPRESSOR SUCTION LINE CONNECTION BROKEN AND HELD ON BY A CABLE TIE															
						A NUMBER OF CLAMPS, GLOBES AND SEAL THAT ALSO REQUIRED REPLACING AS THEY WERE NON SERVICEABLE AND															
1027	Wodonga - Workshop	Engine|COMPRESSOR	BAD AIR LEAK FRONT OF TRUCK.			NOT COVERED UNDER THE PROGRAM.		27/08/2023	769768	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|ENG REBLD	refurbish truck					27/08/2023	769768	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Insp|ANN INSP	annual inspection					27/08/2023	769768	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	VehService|BS	B service	VehService|BS				27/08/2023	769768	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
			check trailer plug found trailer plug not outputting powell fromn susi coil for trailer indicator																		
			check power coming out of pollack socket ok clean polacksocket replug susi coil test ok																		
1027	Wodonga - Workshop	Elect|SUZI COIL	found trailer olue has a diamane oin remove restace trailer olue test ok					13/08/2023	769768	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
			LOW COOLANT LIGHT ON DASH $148.14																		
			CONNECT XENTRY																		
			PRINT OUT DOWNLOAD AND CHECK FAULT CODES																		
			FOUND NO FAULT CODES REGARDING LOW COOLANT																		
			CHECK COOLANT LEVEL, FOUND IT FULL																		
			UNPLUG LEVEL SENSOR, FOUND LOTS OF DUST IN THE COOLANT LEVEL SENSOR																		
			BLOW OUT SENSOR AND CONNECTOR																		
1027	Wodonga - Workshop	Engine|FAULT CODE	RE-CHECK LIGHT ON DASH. NO LONGER ACTIVE					06/06/2023	745395	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Body|FUEL TANK	INSPECTED FUEL LEAKS. FOUND TANK CROSSOVER FITTINGS LEAKING. DROPPED OFF DAIMLER.					19/05/2023	745379	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP3+4	Tyre Position 3 = 4					18/05/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP5+6	Tyre Position 5 = 6					18/05/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP7+8	Tyre Position 7 = 8					16/05/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP9+10	Tyre Position 9 = 10					16/05/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|Punct	Repair Tyre Punchure L/H Steer					15/05/2023	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Fuel Tank Leaking, and onto Axle two suspension. Reuires full clean from fuel tank to axle three.																		
			As per defect notice HVN065313.																		
1027	Wodonga - Workshop	Insp|RWC COMP	Part Inspection reauired.			Sent to Daimler for Reairs.		11/05/2023	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			On Right – Tail light inoperative.																		
			As per defect notice HVN065274?																		
1027	Wodonga - Workshop	Insp|DEFECT	Self Clearing					09/05/2023	885795	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|Re-Tor	Re-Torque					29/04/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|BATTERY	JUMP STARTED. FOUND POSITIVE TERMINAL LOOSE. POST IS DAMAGED. ZIP TIED TERMINAL FOR TIME BEING.					01/05/2023	713936	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Engine Replacement															
1027	Wodonga - Workshop	Engine|COOL LEAKS	Coolant Leaks			Truck sent to Daimler for reairs.		02/03/2023	885601	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|OIL LEAK	CHECK OVER BACK OF MOTOR. LOOKS AWFULLY WET WITH OIL.			NO LEAKS FOUND.		24/01/2023		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|OIL LEAK	OIL LEAKS.			NO LEAKS FOUND.		24/01/2023		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drive Line|GEARBOX	TRUCK JUMPS IN AND OUT OF REVERSE UNDERLOAD.			DAIMLER TO INSPECT.		24/01/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Unknown	WARNING COME UP. MAINTENANCE DUE. MB OIL RECOMMENDED BUT OIL CHECK SAYS OK.					24/01/2023		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|WINDSCREEN	Autocrown Windscreen Replacement			#PONW076252		20/01/2023	885601	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP3+2	Needs new steer tyres.					16/01/2023		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
			Using excessive coolant																		
			Directed to Daimler Mt Gambier.																		
1027	Wodonga - Workshop	Engine|BREAKDOWN	Truck under Contract Maintenace					06/12/2022	885599	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MUDGUARDS	MUD GUARD LEFT.			REPLACED LR.		02/12/2022		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|HEAD LIGHT	LEFT HEADLIGHT			REPAIRED.		02/12/2022		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MUDGUARDS	Tightened Outrigger And Bracket LHR					10/11/2022	685441	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|BATTERY	Jump Start					24/10/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|BATTERY	JUMP START.					18/10/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis|MUDGUARDS	Replaced LHR Outriggers,Mudguard And Brackets					14/10/2022	675937	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Onsite breakdown repairs																		
1027	Wodonga - Workshop	Susp|AXLES	travel to Fyshwick market, remove 3rd axle mud guard bracket front & rear as requested by owner, return to workshop					14/10/2022	675494	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICK UP DAIMLER.					02/10/2022	607269	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	DROP OFF DAIMLER.					15/09/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|ENG REBLD	Cylinder Head Replacement.					15/09/2022	671000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drive Line|GEARBOX	Transmission Replaced.					15/09/2022	671000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Service As Per Attached Checklist																		
1027	Wodonga - Workshop	VehService|BS	Serviced Bv Daimler Albury.	VehService|BS				15/09/2022	671000	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|HEAD LIGHT	REPLACE RH HEADLIGHT GLOBE.					02/09/2022	668312	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|START MOTR	Starter motor replaced.					30/07/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|ENG TUNE	Valve set replaced.					30/07/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService|AS	Service As Per Attached Checklist	VehService|AS				30/07/2022		Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	UNHOOKED. DROPPED OFF DAIMLER.					30/07/2022	651126	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Refer Attached report for repairs.															
1027	Wodonga - Workshop	Engine|EXHAUST	EGR Fault			Daimler Albury		20/05/2022	603457	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Refer Attached report for repairs.															
1027	Wodonga - Workshop	Engine|ENG FAN	Noisy Fan			Daimler Albury		20/05/2022	603457	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Refer Attached report for repairs.															
1027	Wodonga - Workshop	Engine|ENG TUNE	Rough Idle.			Daimler Albury		20/05/2022	603457	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICK UP DAIMLER.					14/05/2022	603506	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICK UP ASH DAIMLER.					12/05/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Inspect ignition, power and earth to unit. Found ST52 light consistantly															
						flashing. Reset unit and power back up. Still not tracking. Fit new SD															
						card and ring MT Data to set unit up with latest software. Unit now tracking.															
						Pair supplied tablet and fit supplied cradle. Test correct operation.															
						New tags 026781, 026784															
						Old tags: 012075, 012076															
1027	Wodonga - Workshop	Dr|Cab|Elect|GPS	Not Tracking			Trackine unit # 619004175		10/05/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICK UP AIRCON					10/05/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICKED UP DAIMLER.					12/04/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	DROP OFF DAIMLER.					10/04/2022	588375	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			RH BRAKE LIGHT MISSING -																		
			FOUND RH BRAKE LIGHT MISSING PRIOR TO SERVICE.																		
			CLEANED PLUG AND CONNECTIONS.																		
			FITTED NEW BRAKE LIGHT AND TESTED.																		
			INSTALLED INTO LIGHT POD.																		
			SECURED WIRING WITH CABLE TIES.																		
1027	Wodonga - Workshop	Elect|BRK LIGHT	ALL OK.					10/04/2022	588375	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService|BS	Service As Per Attached Checklist	VehService|BS				29/03/2022	588391	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP3+2	supply and fit 8 tyres					27/03/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP5+6	Tyre Position 5 = 6					27/03/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP7+8	Tyre Position 7 = 8					27/03/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP9+10	Tyre Position 9 = 10					27/03/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	DROP OFF DAIMLER.					06/03/2022	564984	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|HD	DROP AT DAIMLER.					20/02/2022	553308	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	DROP OFF DAIMLER					30/01/2022		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr|Cab|Reg|WINDSCREEN	replace windscreen					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|FAULT CODE	electrical faults on computer					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|LIGHTS	replace clearance light under r/side					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr|Cab|Elect|INST/GAUGE	active fault on computer fuel tank					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine|JAKE BRAKE	exhaust brake faulty					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Cooling|COOL LEAKS	SMALL LEAK IN COOLANT					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MIRRORS	MIRROR PLASTICS HAVE FLOWN AWAY.					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Cooling|COOL LEAKS	SMALL COOLANT LEAK.					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body|MIRRORS	MIRROR PLASTICS					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Insp	SEE R&R 124253					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect|EJECT P&W	L/H REAR GUARD LIGHTS.					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						REPLACE STOP / TAIL LAMPS WITH LED LIGHTS															
						INSPECT AND FOUND TAIL LIGHTS TO BE AFTER MARKET															
1027	Wodonga - Workshop	Elect|EJECT P&W	R/H BRAKE LIGHT, REVERSE LIGHT AND PARKERS			FIT WITH 2 X NEW LEDS		29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Unknown	SERVICE					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Unknown	SERVICE					29/01/2022	536945	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService|BS	Service As Per Attached Checklist	VehService|BS				29/01/2022	536945	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP3+4	supply and fit 2tyres					11/01/2022	529870	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	TAKE TO DAIMLER ALBURY AND GATHER PARTS FROM WODONGA DEPOT.					19/12/2021	518120	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			REPLACE LHR GUARD, LIGHT POD AND MUDFLAPS - CUSTOMER REQUEST - MOST PARTS SUPPLIED.																		
			INSPECTED AND CONFIRMED GUARD BADLY DAMGED - ALL I BRACKETS AND MOUNT VERY LOOSE -																		
			UNBOADWORTHY.																		
			REMOVED OLD GUARD ASSEMBLY.																		
			ALIGNED NEW GUARD, MARKED AND DRILLED MOUNT HOLES.																		
			FITTED AND TENSIONED MOUNT BRACKETS TO NEW GUARD.																		
			FITTED AND TENSIONED GUARD ASSEMBLY.																		
			FITTED AND TENSIONED NEW LOOP KIP (NOT SUPPLIED)																		
			FITTED NEW MUDFLAP AND DELINIATOR.																		
			SWAPPED LIGHTS TO NEW POD.																		
			FITTED NEW REVERSE LIGHT (MISSING - NOT SUPPLIED).																		
			FITTED NEW LIGHT POD ASSEMBLY.																		
1027	Wodonga - Workshop	Body|DAMAGE	TESTED OPERATION - ALL OK.					19/12/2021	518120	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres|TP08	SUPPLY AND FIT 1 TYRE					16/12/2021	515652	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop|MOVE ASSET	PICKED UP FROM DAIMLER ALBURY.					13/12/2021	513314	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	W

						Inspect light plug due to missing a pin.													
						Found wired as a 7 pin using 5 wires.													
						Replaced plug and wired as a 5 pin.													
1027	Wodonga - Workshop	Elect\INDICATORS	No Indicators to trailers.			Tested and confirmed operation.			15/09/2021	465700	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Park Combination.						15/09/2021	465700	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Take truck to Daimler.						12/09/2021	464282	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\JAS	Service As Per Attached Checklist	Veh\Service\JAS					12/09/2021	464282	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			REPLACE AD-BLUE BRACKETS AFTER ACCIDENT			REPLACE RIGHT HAND REAR GUARD													
			FIT NEW ADBLUE FUEL TANK SUPPORT BRACKETS AND ISOLATORS BETWEEN THE AD BLUR AND FUEL TANK ON THE			REMOVE GUARD, MEASURE AND DRILL HOLES TO NEW GUARD													
1027	Wodonga - Workshop	Engine\ADBLUE	LEFT HAND SIDE OF TRUCK			ALIGN NEW GUARD TO TRUCK AND FIT WITH EXISTING BOLTS			12/09/2021	464282	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	Left hand headlight U/S			Replace left hand headlight.			09/09/2021	462300	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Travel from Wodongs to Daimler to pick up 1027.																
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Travel back to Wodonga.						05/08/2021		Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			ENGINE LIGHT ON DASH																
			INSPECT AND FOUND ADBLUE HEATER SOLENOID OPEN CIRCUIT DUE TO SOLENOID CONNECTOR BROKEN			GENERAL CHECK OVER AFTER ACCIDENT REPAIRS													
			DRAIN RADIATOR			FOUND AIR TANK MISSING MOUNT BOLTS - ADJUST AND FIT MISSING BOLTS													
			REMOVE AND REPLACE HEATER SOLENOID AND REFILL WITH COOLANT			ADBLUE TANK STRAPS FOUND LOOSE - RETENSION													
			CLEAN CODES AND BLEED SYSTEM			CUT CABLE TIES TO J BRACKET TO PREVENT RUBBING													
1027	Wodonga - Workshop	Dr\CabElect\INST/GAUGE	RUN UP AND TEST - ALL OK			J BRACKET SUPPORT MOUNTS TO BE FITTED AT NEXT SERVICE TO SECURE TANK			05/08/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	DROP OFF AT DAIMLER						31/07/2021	440714	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						Paint J Brackets													
						Fit J brackets													
						Throw out damaged parts ana asist Grahame													
						Refit Tail shaft.													
						Fit Ad Blu tank.													
1027	Wodonga - Workshop	Engine\FUEL TANK	Fuel Tank Damage repairs			Fit new tank. straps iumo start and fuel truck.			13/07/2021		Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\DAMAGE	Inspect damage and guide Tow truck to drop truck						09/07/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\DAMAGE	passenger fuel tank damaged on bolard at Logic centre			tow truck back to yard - AAA Towing			09/07/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Insp\DEFECT	Clear RMS defect notice number HVN50101332						29/06/2021	434324	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body	Job Added From Invoice						25/06/2021	0	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect	Job Added From Invoice						25/06/2021	0	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	Replaced RHR Guard as per defect notice.						24/06/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\TAIL LIGHT	Replaced RHR Brake light as per defect notice.						24/06/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Take to TCTC to clear defect and pick Ash up from Cummins.						24/06/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			Ran out of fuel in the trailer yard.																
1027	Wodonga - Workshop	Engine\FUEL TANK	Put fuel in truck and entrue fuel svstem.						22/06/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect	Job Added From Invoice						09/06/2021	0	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Susp\AIR BAG	PM 1027 airbags not working properly						09/06/2021	426819	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\HEAD LIGHT	replace RH headlight globe						05/05/2021	425657	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	Replace RH Rear guard.						05/05/2021	409056	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\CONSUMABLE	Low Oil, come in refilled with 3 litres of oil and refilled 20 litre top up drum.						06/04/2021	390172	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP01	Supply and fit 1 tyre						23/03/2021	383779	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\LIGHTS	TCTC Supply Tail Light Cover						23/03/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	rotation of steer tyres			new steer tyres fitted			19/03/2021	383780	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						R/H previously replaced													
1027	Wodonga - Workshop	Chassis\MUDGUARDS	Replace Rear Left & Right Gaurds			L/H suund. liaht oad. mudflap and boo-kit reolaed on the 22/3/21			19/03/2021	383780	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabElect\INST/GAUGE	Warning Lamp on Dash (Brake Lamp Faulty)			previously completed			19/03/2021	383780	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	electrical faults on computer						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\LIGHTS	replace clearance light under r/side						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabElect\INST/GAUGE	active fault on computer fuel tank						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drivline\CLUTCH	look at clutch						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\AKE BRAKE	exhaust brake faulty						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	active fault on computer (brake characteristics changed)						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\AKE BRAKE	exhaust brake faulty						03/03/2021	370000	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\AS	A Service Due soon	Veh\Service\AS					03/03/2021	370000	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP02	Supply and fit 1 tyre						19/02/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Albury Workshop	P/MOVER
1027	Wodonga - Workshop	Brakes\BREAKDOWN	brake fault codes - say contact dealer immediately come on dash, call daimler straight away in QLD						12/02/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BLOWOUTS	repaired from RHR drive tyre blow out. New guard, tail lights (including rewiring 24v tailights with unusual wiring color coded)						04/02/2021	361995	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	fit mudflap and readjust guard						04/02/2021	361995	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\CLEAN	parts away and clean workshop						04/02/2021	361995	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BLOWOUTS	RH rear inner tyre has blown and damaged the lights and guard			called beaurepaires and daimler wagga			03/02/2021	361881	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP3+4	beaurapaire wodonga: new drives: position: 3+4+5+6						24/01/2021	32277	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\TP5+6	fitting tyres						24/01/2021	32277	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BALANCE	tyre balance						24/01/2021	32277	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\SCRAP TYRE	recycle tyres						24/01/2021	32277	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	fit new guard straighten Cevron signs and mudflap holders						16/01/2021		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
						obrians Powo0611099													
1027	Wodonga - Workshop	Body\WINDSCREEN	windscreen replace			Daimler truck re-calibrated windscreen camera's			13/01/2021	352105	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	yard check						12/01/2021	352090	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\BATTERY	jump start						12/01/2021	352090	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	drop off to Dainlar						12/01/2021	352090	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\SLID COL	replace susl leads						31/12/2020	348205	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\JAS	Service As Per Attached Checklist	Veh\Service\JAS		due at 360,000Kms			27/11/2020	330848	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\JAS	Service As Per Attached Checklist	Veh\Service\JAS					27/11/2020	330848	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			pick up from Lavington																
1027	Wodonga - Workshop	Workshop\MOVE ASSET	measure truck - 5360mm from Tiabble sin to bullbar						25/11/2020	330988	Reair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\FUEL TANK	fuel line connection			daimler albury Powo059870			24/11/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	drop off at Daimler Albury						24/11/2020	330832	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\FUEL TANK	replace fuel sender unit			fitted new sender unit			18/11/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\JAS	Service As Per Attached Checklist	Veh\Service\JAS					15/11/2020		Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						30/10/2020	309442	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BETBEAD	Job Added From Invoice						30/10/2020	309442	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			inspect vehicle for airleaks no fault found at time of inspection, inspect air leaks.																
1027	Wodonga - Workshop	Body\AIR LEAK	Hartwigs Queenbeyan: WW0581152						22/09/2020	287454	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	Job Added From Invoice						19/09/2020	0	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	Job Added From Invoice						17/09/2020	288275	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						17/09/2020	288275	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BALANCE	Job Added From Invoice						17/09/2020	288275	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drivline\WHEEL ALIGN	PERFORM LASER WHEEL ALIGNMENT ON ACTROS PM						11/09/2020	287455	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\SELECT P&W	clearance lights in OF, found clearance light in sp, remove and replace with new, test all ok						11/09/2020	287455	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Veh\Service\AS	Service As Per Attached Checklist	Veh\Service\AS					11/09/2020	287455	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	pick up from tristar						10/09/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	drop off to Hartwigs						09/09/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\DAMAGE	another truck reversed into truck while driver was sleeping damaging the windscreen.						02/09/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	steer tyres			RR's Pre Jan 2020 (system clean up) 04/08/20			06/08/2020		Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\BREAKDOWN	ligth issue			mechnnika motor Powo056466			22/07/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\SELECT P&W	gave driver a 7 pin plug to a 5 pin plug adaptor						03/07/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\SELECT P&W	drivers characteristics changed, ABS light playing up on the dash: transmission has been shifting differently. Also to Boost speed to 100Kms						26/05/2020	228583	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	update exhaust gas aftertreatment Co (ACM)			updated software for exhaust gas after treatment control			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\PANELS	Quote panels in front of drivers door missing						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\WIPERS	rectify both wiper arm lower covers have fallen off			missing on both sides			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\WINDSCREEN	rectify RH side windscreen side panel not secure			clips broken			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\PANELS	rectify drivers step loose			Loose			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\DAMAGE	rectify driver RH armrest falling apart			material defect of arm rest foam/cushion, replaced drivers's LH armrest			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	Rectify RH front mudguard top clips not secure			Loose			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FUEL TANK	Rectify RH fuel tank vent line filter missing			missing			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\SELECT P&W	Quote RH tank mounted side marker broken			broken			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	tension loose rear guards, guards arms. Reposition tank strap reubbers that have removed						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\EXHAUST	Quote LH tank sender unit plug is broken			broken			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\MOUNTS	tension yellow grab handle at LH rear of cabin						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FUEL TANK	rectify RH tank, centre strap pin circlip						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\PANELS	re-secure walk plate						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Chassis\MUDGUARDS	rectify LH front mudguard missing bolt						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Cooling\RADIATOR	rectify A/C lines chaffing on radiator top cover			modified radiator top cover in order to stop chaffing			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Cooling\RADIATOR	rectify header tank coolant hose chaffing on maintenance						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\WINDOW REG	rectify washer fluid cap has fallen off			missing			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Susp\SHOCK ABS	rectify LH cab shock is leaking			internal defect of oil seal causing shocker to leak replaced both front shockers			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\TURBO	rectify turbo heatshield at back is cracked			R&R exhaust heatshield			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Air Con\AIR CON	check and rectify A/C not working			no fault found			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabRep\WINDOW REG	rectify drivers window switch stage 2 not working. No aut up function.			internal mechanical defect within RH window switch replaced window switch assembly, tested ok.			24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\ALT2 DR	check for cause batteries not holding charge						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Drivline\WHEEL ALIGN	carry out for wheel alignment						24/04/2020	213568	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			carry out service as per live data recording.																
1027	Wodonga - Workshop	Veh\Service\JAS	Insapection service due. carried out service reolaced air filter.	Veh\Service\JAS					24/04/2020	213568	Service	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	Job Added From Invoice						15/04/2020	103382	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						15/04/2020	103382	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\BALANCE	Job Added From Invoice						15/04/2020	103382	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Elect\SELECT P&W	loose wire in trailer in trailer plug , light issue						24/03/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						17/03/2020	185655	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\CLEANSEN	Job Added From Invoice						17/03/2020	185655	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice						17/03/2020	185655	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabElect\SLID COL	replaced trailer plug						03/03/2020	108203	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\LIGHTS	L/S rear light assembly broken off						22/02/2020	176648	Fault	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Dr\CabElect\SLID COL	changed susl leads & use battery cover off 1020						19/02/2020	175253	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Drop at Hartwigs						02/02/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Pick up from Hartwigs						02/02/2020		Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Tyres\STEER TYRE	rotation of steer tyres						02/02/2020	166010	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Engine\FAULT CODE	electrical faults on computer						02/02/2020	166010	Repair	Completed	FL Green Distribution	MBD015Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
			where hartwigs mechanic cut wires around batteries																
1027	Wodonga - Workshop	Elect\SELECT P&W	battery cover						02/02/2020

1027	Wodonga - Workshop	DrCabElect/GPS	truck not tracking, sub contractor will be investiagting and repairing truck on Saturday			07/07/2019		Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Workshop\MOVE ASSET	Drop truck off to Hartwigs			04/07/2019		Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Brakes	AS PER CHECK LIST			25/06/2019	37155	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	VehService\AS	Service As Per Attached Checklist		VehService\AS	25/06/2019	37155	Service	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Comp\FBS	Job Added From Invoice			04/06/2019	0	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\VICLSEKEEP	Job Added From Invoice			11/04/2019	0	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	Body\CONSUMABLE	Job Added From Invoice			11/04/2019	0	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER
1027	Wodonga - Workshop	DrCabElect/GPS	Job Added From Invoice			19/02/2019	0	Repair	Completed	FL Green Distribution	MBDD15Hwy	Wodonga	LHB	XV298Z	Wodonga Workshop	P/MOVER