

External Visual Inspections (05-0112)

Inspection Date : 2026-06-17

Created By: Ben Stewart

Facility

Northern Tank Inspections Ltd.
108-25535 117 Ave
Acheson,, AB, T7X 6C2

Client

Daniel Van Oort
Advance Group LTD
7209-99 ST
Email: [\[email protected\]](#)
Peace River, AB, T8S-1B3
Ph. No. - 1-780-617-4031

Tank

Ser. No.	05-0112	Unit Number	03-60
TC Spec.	TC 407/412	Service Type	["Vacuum Load"]
Date of mfr.	2005-12	Cert. date	2005-12
Tank mfr.	Proxy Weld Industries		

External Visual Inspection

Inspection Date	2026-06-17	Inspection Expiry Date	2026-12-17
-----------------	------------	------------------------	------------

Inspection

Inspect jacketing for dents, digs, scrapes, gouges, perforations, stains, or other defects or signs of damage to the inner vessel or any other condition that might make it unsafe as per 7.2.1(a)
Not Applicable

Inspect the entire area of head and shell for dents, gouges, bulges, corrosion, abrasion, cracks, or signs of leakage or other conditions that might render it unsafe for transport as per 7.2.1(a)
Pass

Inspect the entire length of every weld for cracks, defects or signs of leakage as per 7.2.1(a)
Pass

Ensure devices for tightening manhole covers are operative and covers are leak tight as per 7.2.1(b)
Pass

Check all valves, vents, emergency devices and remote closures for corrosion, distortion, cracks, signs of weakness and loose or missing fasteners as per 7.2.1(c)
Pass

Ensure all required markings are legible including manway, PRV, couplings, valves and specification plate as per 7.2.1(e)
Pass

Inspect supporting structures, pads, bolsters, tie-downs and protective devices for dents, distortion, cracks, signs of weakness and loose or missing fasteners as per 7.2.1(f)
Pass

Ensure accompanying or mounted hoses comply with inspection and marking requirements as per 7.2.10.4 and 7.2.10.6
Pass

Check to ensure voids are unplugged and show no signs of leakage as per 7.2.1.2
Not Applicable

Corroded or abraded areas are thickness tested as per 7.2.1.3
Pass

All pressure relief devices are inspected for corrosion or damage as per 7.2.1.4
Pass

If lading is corrosive to PRV: re-closing pressure relief valves are replaced or tested as per 7.2.1.4(b)
Pass

Gaskets on full opening rear head is inspected and replaced if cut, cracked or split as per 7.2.1.5
Pass

Internal self closing valve and off truck emergency shut down system tested as per 7.2.1.6
Pass

Ensure that all bolts or nuts on any flanged connection or blank flange are in place and properly tightened

Pass


Defects

No defects found.


Tank Disposition

Current Disposition	Passed / No Defects Found
---------------------	---------------------------

Approval



Inspector
Signed by Ben Stewart



Tester
Signed by Ben Stewart