

December 9, 2025

Hours: 1272.2

- Diagnosed block heater not working
- Coolant thermostat housing leaking
- Changed the block heater
- Changed oil
- Changed oil and fuel filters

March 12, 2026

- Replaced coolant sensor

February 21, 2026

Hours: 1296.6

Kilometers: 2691.62

- Installed winter front and clips
- Replaced coolant level sensor
- Repaired derate / cleared codes
- Advised ECM recall update

April 20, 2026

Hours: 1312.3

Kilometers: 2756.14

- Full service
- Got an oil change and new oil filter
- All drives are worn out on the tires
- Greased the full unit
- Fixed the working light on passenger side tail
- Checked the hydraulic oil levels
- Inspected all tires on air pressure and condition
- Inspected lights, signals, and work lights

02-44

Aug7/26

13356 Hrs.

285733km

- Front steady bearing new strap kit
- needs drag link
- grease unit
- right side second light from back out
- driver side mirror light out

02-44

Sept13/26

- check front hubs
- spool winch and rewrap toil cable
- check rigging/grease deck
- check service