

WORK ORDER REPORT

5061

DATE: *Mar 4/25* UNIT: *2018* MAKE/MODEL: *W/STAR* SERIAL NUMBER: *JPD 3036* PART NUMBER DESCRIPTION

WORK PERFORMED *396232*

Repair Heated Mirrors
Replace All Drive Brakes & Drums
Replace Both Front Axle Wheel Seals
Replace LF Drive U-Bolts
Replace All Shock Absorbers
Replace Drag Links
Replace Tie Rods & Tubuli
Replace Forward Drive Torque Rod
Replace Both Steer All Hub-caps
Tighten fenders
Rebuild fifth wheel
Replace Window Regulator & Winders
Retorque All Wheels @ 396231
Check Code & Replace DEF filter
Re & Re ATCM Harness to Repair

NOTES:

Vehicle Inspection Certificate Number: SM00AC15

Start Date / Time: Mar 17, 2025, 1:12 PM

End Date / Time: Apr 4, 2025, 12:53 PM

VEHICLE/ENGINE INFORMATION		CHASSIS	ENGINE
Plate#: BP75298	Year: 2018	Year:	
VIN: 5KJJALDR0JPJD3036	Make: WESTERN STAR/AUTO	Make:	
GVMR(kg): 28123	Model: CONVENTIONAL	Size (L):	
Odometer: 396233	Fleet ID:		

SAFETY INSPECTION RESULT	PASS
--------------------------	------

SAFETY SYSTEM INSPECTION RESULTS
All Safety System Components Passed Inspection

MANDATORY ITEMS		
Inspection Item	Result	
Axle 1, Driver Side Tire		
Tire Tread Depth (mm)	9	9
Initial Tire Pressure (kPa)	586	601
Drum Brakes Bolted/riveted block		
Shoe Lining Thickness (mm)	13	12
Drum Inside Diameter (mm)	420.78	420.91
Within OEM specifications?	Yes	Yes
S-Cam Drum Brakes		
Chamber Type (size)	24LS	24LS
Brake Stroke (mm)	31	31

Inspection Item	Result	
Axle 2, Driver Side, Inner Tire		
Tire Tread Depth (mm)	15	15
Initial Tire Pressure (kPa)	652	655
Axle 2, Driver Side, Outer Tire		
Tire Tread Depth (mm)	14	15
Initial Tire Pressure (kPa)	646	698
Drum Brakes Bolted/riveted block		

Drum Inside Diameter (mm)	419.27	Drum Inside Diameter (mm)	419.14
Within OEM specifications?	Yes	Within OEM specifications?	Yes
S-Cam Drum Brakes		S-Cam Drum Brakes	
Chamber Type (size)	30LS	Chamber Type (size)	30LS
Brake Stroke (mm)	38	Brake Stroke (mm)	38

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	605
Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	616
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	14
Drum Inside Diameter (mm)	419.22
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30LS
Brake Stroke (mm)	38

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	650
Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	644
Drum Brakes Bolted/riveted block	
Shoe Lining Thickness (mm)	14
Drum Inside Diameter (mm)	419.22
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30LS
Brake Stroke (mm)	38

Vehicle Inspection Centre #: 12575 SURGENOR TRUCK GROUP 261 BINNINGTON COURT KINGSTON, ON K7M9H2 613-548-1100 Software Version: 2024.08.21.1	Technician #: 369506 Name: HUNTER LLOYD Report Number: 104 Tablet ID: 4621 STO ID/Account: 18009889 Trade Code: 310T
---	---

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to
<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>

5077

NOTES:

WORK ORDER REPORT

5084

[illegible]

WORK ORDER REPORT

5091

DATE: Jan/14/2026 UNIT: 2018

MAKE/MODEL: Westex Insco SERIAL NUMBER: _____

PART NUMBER

DESCRIPTION

WORK PERFORMED 440028

49000

Ran diagnostics on the truck for outlet NOX sensor installed new inlet and outlet NOX sensor attempted to force Regen 3 times truck would not Regen. also noticed damage to plug on inlet NOX sensor. truck sent to westbrook Full service

NOTES:

WORK ORDER REPORT

5094

[illegible]

WORK ORDER REPORT

5096

[illegible]

WORK ORDER REPORT

5099

[illegible]

WORK ORDER REPORT

51112

DATE: <i>Apr 7/26</i>	UNIT: <i>2018</i>	MAKE/MODEL: <i>4900</i>	SERIAL NUMBER: <i>JD3036</i>	PART NUMBER	DESCRIPTION
WORK PERFORMED <i>467207</i>					
<i>Replace Rad</i> <i>Replace Water Pump</i> <i>Check over for Pre Safety</i>					
				NOTES:	

51121

Apr 14/26

2018

W/STAR

TP3034

DESCRIPTION

469803

Replaced LFD Moxi Piggyback
FULL Service

NOTES:

Vehicle Inspection Certificate Number: IG00AC45

Start Date / Time: Apr 30, 2026, 1:09 PM

End Date / Time: Apr 30, 2026, 1:46 PM

VEHICLE/ENGINE INFORMATION		CHASSIS	ENGINE
Plate#: BP75298	Year: 2018	Year:	
VIN: 5KJJALDR0JPJD3036	Make: WESTERN STAR/AUTO	Make:	
GVWR(kg): 28123	Model: CONVENTIONAL	Size (L):	
Odometer: 477493	Fleet ID:		

SAFETY INSPECTION RESULT	PASS
--------------------------	------

SAFETY SYSTEM INSPECTION RESULTS
All Safety System Components Passed Inspection

MANDATORY ITEMS		
Inspection Item	Result	
Axle 1, Driver Side Tire		
Tire Tread Depth (mm)	11	10
Initial Tire Pressure (kPa)	723	723
Drum Brakes (Limited Inspection) Bolted/riveted block		
Shoe Lining Thickness (mm)	13	12
Drum Inside Diameter (mm)	420.76	420.73
Within OEM specifications?	Yes	Yes
S-Cam Drum Brakes (Limited Inspection)		
Chamber Type (size)	24	24
Brake Stroke (mm)	38	38

Inspection Item	Result	Result
Axle 2, Driver Side, Inner Tire		
Tire Tread Depth (mm)	9	7
Initial Tire Pressure (kPa)	725	724
Axle 2, Driver Side, Outer Tire		
Tire Tread Depth (mm)	9	7
Initial Tire Pressure (kPa)	724	723
Drum Brakes (Limited Inspection) Bolted/riveted block		

Drum Inside Diameter (mm)	419.64
Within OEM specifications?	Yes
S-Cam Drum Brakes (Limited Inspection)	
Chamber Type (size)	30LS
Brake Stroke (mm)	40

Drum Inside Diameter (mm)	419.57
Within OEM specifications?	Yes
S-Cam Drum Brakes (Limited Inspection)	
Chamber Type (size)	30LS
Brake Stroke (mm)	40

Inspection Item	Result
Axle 3, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	726
Axle 3, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	7
Initial Tire Pressure (kPa)	724
Drum Brakes (Limited Inspection) Bolted/riveted block	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419.44
Within OEM specifications?	Yes
S-Cam Drum Brakes (Limited Inspection)	
Chamber Type (size)	30LS
Brake Stroke (mm)	40

Inspection Item	Result
Axle 3, Driver Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	724
Axle 3, Driver Side, Outer Tire	
Tire Tread Depth (mm)	7
Initial Tire Pressure (kPa)	725
Drum Brakes (Limited Inspection) Bolted/riveted block	
Shoe Lining Thickness (mm)	Over 15
Drum Inside Diameter (mm)	419.31
Within OEM specifications?	Yes
S-Cam Drum Brakes (Limited Inspection)	
Chamber Type (size)	30LS
Brake Stroke (mm)	40

Vehicle Inspection Centre #: 11629 KENWORTH ONTARIO - KINGSTON 191 BINNINGTON CT KINGSTON, ON K7M8R7 613-544-1212 Software Version: 2025.06.18.1	Technician #: 359198 Name: KYLE SHAW Report Number: 131 Tablet ID: 2061 STO ID/Account: 13323454 Trade Code: 310T
---	--

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to
<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>

WORK ORDER REPORT

51157

DATE: May 29/26	UNIT: 2018	MAKE/MODEL: W/STAR	SERIAL NUMBER: JFD 3036	PART NUMBER	DESCRIPTION
WORK PERFORMED 47620 Replaced Speedo with Western Star Certified Mileage Replaced Trig Fuel Line Bracket. Check for Check Engine light on - Codes for Engine Brake Solenoid Open Circuit & #3 Injector Needle Valve open circuit Traced to loose Wiring Harness Plug at Valve Cover PassThrough - Test Drive OK,					
NOTES:					

WORK ORDER REPORT

51173

DATE: *Time 1/26* UNIT: *2018* MAKE/MODEL: *W/STAR* SERIAL NUMBER: *JPD3036* PART NUMBER DESCRIPTION

WORK PERFORMED *478628*

Replace R fley pipe to Stack
Extract Broken L RD Fender Bolt from frame
Replace L RD Forward Fender Mount
Replace RR Mudflap & Hanger
Check SPN 3719 FMIL6 & SPN 3246 FMIO.
Trace to Damaged wiring to Differential Pressure
Sensor & Force Regen
Greased Unit & General Inspection

NOTES:

WORK ORDER REPORT

51190

DATE: June 18/26	UNIT: 2018	MAKE/MODEL: Star 1900	SERIAL NUMBER:	PART NUMBER	DESCRIPTION
------------------	------------	-----------------------	----------------	-------------	-------------

WORK PERFORMED 484,134

Changed oil / oil filter / changed Fuel filter
 Changed cab Filters / greased Truck /

NOTES:

STAR

WORK ORDER REPORT

51209

DATE: <i>July 19/26</i>	UNIT: <i>2018</i>	MAKE/MODEL: <i>RR</i>	SERIAL NUMBER: <i>AD3036</i>	PART NUMBER	DESCRIPTION
-------------------------	-------------------	-----------------------	------------------------------	-------------	-------------

WORK PERFORMED <i>991276</i> <i>Adjust linkage for Clutch Brake</i> <i>Replace leaking fittings under CAT Valve</i> <i>for Pump Hydraulics</i> <i>Replaced RR fender</i>					
NOTES:					

WORK ORDER REPORT

51244

DATE: <u>Aug 18/26</u>	UNIT: <u>2018</u>	MAKE/MODEL: <u>W/STAR</u>	SERIAL NUMBER: <u>JPTD 3036</u>	PART NUMBER	DESCRIPTION
------------------------	-------------------	---------------------------	---------------------------------	-------------	-------------

WORK PERFORMED	<u>495223</u>
----------------	---------------

Drain Transmission Re Seal Splitter Cylinder Re + Re Regulator & Hoses to Inspect for Oil Refill Transmission Replace Oil Pan Gasket / changed oil filter LS King Pin Not taking grease due to blown out Seal. Put new seal in now taking grease Full Service Full Service	
--	--

NOTES:	