



Commercial Vehicle Inspection Report

Decal Number: GN28453
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21827129

Inspection Result:

PASS

ACILITY: MOUNTAIN MECHANICAL SALES & SERVICE / S7267
INSPECTOR: Smith, Tristan / 300888
WORK ORDER #: RK14509
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Jun-10 03:24 PM MDT
INSP. COMPLETE: 2026-Jun-26 03:25 PM MDT
VEHICLE JUR: British Columbia
PLATE #: VW7691
LICENCED GVW(kg): 43100
VEHICLE YEAR: 1986
MAKE: FORD
MODEL:
REGI: 05786536
UNIT/FLEET#:
BODY STYLE: Dump Truck
ODOMETER: 649711 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2BGC06123GVA53351
OWNER/LESSEE NAME: HOTSHOTSHIBAS TRANSPORT., .
ADDRESS: 904 STEEPVIEW DR NW
Cranbrook, British Columbia
V1C5L3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed with Caution #2L AXLE SEAL STARTING TO LEAK
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed with Caution POWER STEERING WEAK
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) NO LOW AIR ALARM, SPEEDO, TAC OR AIR GLUGE LIGHT
Section 6 - Lamps	Repaired (same day) CAB INDICATORS NOT SECURE, NO BACKUP LIGHTS ON REVERSE, UNDERDOOR MARKER LIGHTS OUT
Section 7 - Electrical System	Repaired (same day) UNSECURE WIRING IN FOOTWELL
Section 8 - Frame and Body	Repaired (same day) LOOSE BOLTS ON BUMPER, HOOD CRACKED INSIDE DRIVERSIDE
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Wedge	N/A	Not Applicable	0	0
2	Clamp	30	Automatic	41	42
3	Clamp	30	Automatic	39	40

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9			10	✓
17	17	17	17	
17	17	17	17	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	77	71
3	79	82

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	14
Lining (Shoe)	15	17
Lining (Shoe)	14	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

Road Tester:

Inspector: Smith, Tristan

This Inspection Report was submitted to CVSE on 2026-Jun-26 03:25 PM MDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/26/2026 3:25:20 PM MDT