TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/09/2022	6451

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/10/2022

Description	Amount
27.09.22 - Freightliner Argosy. (Rego 1MF8BK - Speedo 1,330,260 K's) Diagnose air leak in dash. Fit new brake valve to see if issue would rectify. Found no change. Remove new brake valve and fit original valve. Remove and replace cabin air switch.	295.00
Parts - Air switch. Freight.	36.37

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	$331.37
Tax	$33.14
TOTAL	$364.51
Payments/Credits	$0.00
Balance Due	$364.51

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/12/2022	6658

[redacted]

P.O. No.	Terms	Due Date
	Net 15	14/01/2023

Description	Amount
03.12.22 - Freightliner (Rego: 1MF 8BK; Speedo: 1,339,576km). Carry out general check over on Freightliner truck and write up list of repairs. Check drive line oils. Tighten L/H fuel tank light bracket. Re-route L/H air tank drain cable.	180.00
17.12.22 - Freightliner. Pull shift cables forward so they are not pulling on floor when cab is tilted. Repair floor where shift cables go through. Locate A/C leak. Found rubbed hole in steel line on bolt. Needs low side A/C line replaced. Need new A/C pressure switch. Order parts for repair to be fitted at a later date. Remove and replace height control valve and fittings and try and locate air leaks. Drop A/C parts off to Beamsy so that A/C could be repaired.	720.00
Parts - 3 x air fittings, 2 x bottles T-Rex Power silicone, Hendickson height control valve with clamp, freight, consumables.	338.29

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	$1,238.29
Tax	$123.83
TOTAL	$1,362.12
Payments/Credits	$0.00
Balance Due	$1,362.12

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
27/02/2023	6881

[redacted]

P.O. No.	Terms	Due Date
	Net 15	14/03/2023

Description	Amount
24.02.23 - Freightliner Argosy (Rego 1MF8BK - Speedo 1,357,090 K's) Carry out general service and check over. Jack up front end and check steering and suspension components, grease front end, adjust steer brakes. Lift truck with hoist, check drive line oils for level and condition, found OK. Grease drive line, adjust drive brakes. Drain engine oil, replace oil filters, replace fuel filter and fuel water separator. Lower truck to ground, fill with engine oil, source and fit replacement air cleaner elements. Jack cabin over, check drive belts and idlers. Remove and replace cabin sway bar mount bushes. Remove and replace air dryer filter. Lower cabin down. Check all lights, found L/H front side indicator not working, customer is aware of fault and will repair themselves. Lift truck with hoist, remove front engine mount bolts, found unable to be re-used, jack engine away from cross member, remove failed engine mount and fit new one with new nuts, bolts and washers. Steam clean engine bay.	840.00
25.02.23 - Freightliner Argosy. Fit new air tank drains and secure drain cables for easy access, lubricate driver's step for smoother operation. Carry out road test.	240.00
Parts - 36 Ltrs E900 engine oil, filter kit, fuel/water separator filter, air dryer filter, 2 x air cleaners, set of cabin sway bar mount bushes, front engine mount rubbers and bolt kit, 2 x air tank drain cocks. Freight. Consumables.	1,886.64

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	$2,966.64
Tax	$296.66
TOTAL	$3,263.30
Payments/Credits	$0.00
Balance Due	$3,263.30

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
17/04/2023	6975

[redacted]

P.O. No.	Terms	Due Date
	Net 15	2/05/2023

Description	Amount
01.04.23 - BT50. Drain oil, change filter, re-fill engine oil (Oil filter supplied).	120.00
Parts - 7.5 Ltrs E900 engine oil (BT50), consumables	86.23

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	$206.23
Tax	$20.62
TOTAL	$226.85
Payments/Credits	$0.00
Balance Due	$226.85

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/04/2023	6992

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/05/2023

Description	Amount
01.04.23 - Maxi Trans ST3 trailer (Rego N/N - VIN 6F8T25000YB060338) Check over for RWC. Needs all brake drums and linings replaced, also one leaking airbag needs replacement.	120.00
11.04.23 - Fridge trailer. Back trailer into shed, jack up trailer and support axles, remove wheels from front and middle axle, remove hubs and brake linings.	240.00
12.04.23 - Fridge trailer. Remove slack adjusters and S-cams, remove and replace S-cam bushes. Fit new S-cams to front and middle axle, fit new slack adjusters. Fit new brake shoe sets. Remove all brake drums from hubs. Clean all hubs, wash and inspect all wheel bearings. Found R/H/F wheel bearings unserviceable, remove and replace bearings in that hub. Re-pack all bearings and hubs, fit new hub seals, re-fit hubs to axles, tension wheel bearings. Re-fit all wheels and tension wheel nuts. Remove stands and lower to ground. Jack up and support rear axle. Remove wheels from rear axle. Remove hubs and brake shoes.	1,440.00
13.04.23 - Fridge trailer. Remove slack adjusters, remove S-cams and S-cam bushes. Found L/H rear S-cam and S-cam inboard carrier bracket both bent, bracket had been repaired previously. Place order for new carrier bracket, cut bent bracket off axle and buff axle surface. Chain up rear axle, remove stands and move out of shed until order arrives.	360.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	
Tax	
TOTAL	
Payments/Credits	
Balance Due	

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/04/2023	6992

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/05/2023

Description	Amount
17.04.23 - Fridge trailer. Weld in new inboard S-cam bracket. Fit new S-cam bushes, fit new S-cams, fit new slack adjusters. Fit new brake linings to each wheel end. Wash and inspect wheel bearings and hubs, re-pack and fit wheel bearings to hubs, replace hub seals, fit new brake drums to hubs, re-fit hubs and tension wheel bearings. Re-fit wheel and tension wheel nuts. Remove and replace length of hose and both clamps on L/H/R brake booster, remove and replace damaged L/H/R brake booster assembly, remove and replace L/H/F air bag assembly, including inlet house and fitting. Grease trailer. Adjust brakes. Check trailer king pin for wear, found OK. Fit new backing plate to lower half of L/H wheels (3 plates) Fit new slack adjuster return springs.	1,320.00
Parts - 6 x boxes Bendix brake shoes, 3 x L/H S-cams, 3 x R/H S-cams, 3 x S-cam bush kits (1 per axle), 6 x HD slack adjusters, 6 x return springs, 6 x brake drums, 1 x inner and outer wheel bearing, 6 x hub seals, 3 x lower backing plates, 1 x S-cam stand off bracket, 1 x air bag assembly, 1 x brake booster, 2 x brass fittings, 200mm 12mm nylon air line, 300mm 1/2" rubber brake hose, 4 x HD hose clamps. Freight. Consumables.	4,302.12

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB
BSB: 083 543
A/C No. 5972 33332

Subtotal	$7,782.12
Tax	$778.21
TOTAL	$8,560.33
Payments/Credits	$0.00
Balance Due	$8,560.33

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
6/06/2023	7152

[redacted]

P.O. No.	Terms	Due Date
	Net 30	6/07/2023

Description	Amount
02.06.23 - Freightliner Argosy. (Rego 1FM8BK - Speedo 1,368,786 K's) Remove and replace L/H ABS steer valve, remove and replace all slack adjusters on drive brakes, adjust drive and steer brakes. Fit new air tank drain cock, found evidence of water in air tanks, remove and replace air dryer filter. Adjust trailer brakes.	450.00
Parts - ABS valve, 4 x HD slack adjusters, air dryer filter, 1.4 air tank drain cock, 4 x brass air fittings. Freight. Consumables.	743.41

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$1,193.41
Tax	$119.34
TOTAL	$1,312.75
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due $1,312.75

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
26/06/2023	7172

[redacted]

P.O. No.	Terms	Due Date
	Net 30	26/07/2023

Description	Amount
09.06.23 - Freightliner Argossy (Rego: 1MF 8BK; Speedo; 1,369,687km). Diagnose brake issue. Remove turntable and found emergency SR7 valve failed. Source new SR7 valve from Thackers Trucks. Remove and replace SR7 relay valve. Test and found all good. Remove rear walk plates and order 4 x new locks. Remove and repair R/H windscreen quarter panel.	480.00
Parts - park brake relay valve, 4 x walk plate locks (still to be fitted), freight, consumables	933.54

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$1,413.54
Tax	$141.35
TOTAL	$1,554.89
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$1,554.89

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/06/2023	7235

[redacted]

P.O. No.	Terms	Due Date
	Net 30	30/07/2023

Description	Amount
30.06.23 - Freightliner Argosy. (Rego 1MF8BK - Speedo 1,371,473 K's) Remove and replace starter motor. Fit locks to walk plate, repair wiring to walk plate marker lights, re-fit walk plate and adjust locks to close securely.	360.00
Parts - New starter motor (Locks previously charged), consumables	653.70

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$1,013.70
Tax	$101.37
TOTAL	$1,115.07
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$1,115.07

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
21/08/2023	7326

[redacted]

P.O. No.	Terms	Due Date
	Net 30	20/09/2023

Description	Amount
4.8.23 - 5.8.23 - Freightliner (Rego: 1MF 8BK; Speedo; 1,375,589km). Carry out service and checkover on Freightliner truck. Change engine oil and replace 2 x oil filters, 2 x fuel filters. Grease. Adjust brakes. Adjust clutch and clutch brake. Make up plates to lock walk plates down. Bolt walk plate down. Diagnopse R/H rear indicator not working. Spread terminals and plug back in and test. Found OK. Top up coolant. Grease turntable. Top up washer bottle. Replace 2 x 21inch wiper blades. Steam clean and test drive. Jack cab to safety catch. Fold out driver's step and support step. Remove shims and adjust shim height. Lube driver's step mechanism. NOTE: front tailshaft has slight movement. Transverse rod bushes worn & broken. Track rod bushes worn and broken. Wheel bearings have movement. King pins need replacing.	1,081.80
Parts - 2 x 21inch wiper blades, 38lt E900 engine oil, fuel water separator, filter, filter kit, 4 x 5/8 cone lock nuts & bolts, 4 x hardened shocker washers	645.54
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$1,777.34
Tax	$177.73
TOTAL	$1,955.07
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$1,955.07

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
17/10/2023	7491

[redacted]

P.O. No.	Terms	Due Date
	Net 15	1/11/2023

Description	Amount
13.10.23 - Freightliner Argosy. (Rego 1MF8BK - Speedo 1,383,007 K's) Lift vehicle with hoist, undo and remove bolts from rear drive spring packs, press out old spring eye bushes, press in new ones, re-fit bolts and tension. Undo and remove bolts from front drive spring eye bushes, press out old bushes and press in new ones, re-fit bolts and tension. Lower vehicle to ground, remove walk plate from forward of the turntable, remove upper differential transverse rod, assemble and weld together new transverse rod assembly, fit new assembly, re-fit bolts and tension. Re-fit forward walk plate. Remove rear walk plate, remove upper differential transverse rod, assemble and weld together new transverse rod assembly, fit new assembly, re-fit bolts and tension. Weld nuts onto brackets that secure rear walk plate, re-fit and secure rear walk plate. Road test vehicle.	1,527.24
Parts - 2 x Euclid weld together transverse rod kits, 4 x Airliner spring eye bushes.	1,116.18
Workshop consumables, environmental levy & waste disposal levy	30.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$2,673.42
Tax	$267.34
TOTAL	$2,940.76
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$2,940.76

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
31/12/2023	7680

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/01/2024

Description	Amount
08.12.23 - Freightliner Argosy. (Rego 1MF8BK - Speedo 1,391,032 K's) Carry out general service and check over. Jack up front end and check steering and suspension components, grease front end and adjust brakes. Lift vehicle with hoist, check drive line oils for level and condition, grease drive line, adjust drive brakes. Drain engine oil, remove and replace both oil filters, fuel filter and fuel water separator. Lower vehicle to ground, tilt cabin over. Fill with engine oil. Remove alternator belt for alternator replacement, found automatic tensioner not returning properly, source new tensioner assembly. Remove and replace alternator, fit new tensioner, re-fit belt. Steam clean engine bay and road test vehicle.	1,018.16
09.12.23 - Freightliner. Check alternator charge rate at alternator and at batteries, all OK.	63.64
Parts - Donaldson filter kit, 38 Ltrs E900 engine oil, belt tensioner, alternator. Freight inwards.	1,502.50
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$2,634.30
Tax	$263.43
TOTAL	$2,897.73
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$2,897.73

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
25/03/2024	7963

[redacted]

P.O. No.	Terms	Due Date
	Net 15	9/04/2024

Description	Amount
20.03.24 - Freightliner (Rego: 1MF 8BK; Speedo: 1,401,013km). Carry out A-service on Freightliner. Check over truck. Grease. Adjust brakes. Check all oils. Remove and replace air dryer filter. Locate air con leak. Remove and replace R/H fuel tap. Remove existing fuel balance pipe and fabricate new pipe and ends. Fit up new fuel pipe. Remove front cross over bar and straighten. Re-fit bar with new clamps. Weld studs to rear mud flap bracket. Steam clean underneath around fuel tanks.	462.00
21.03.24 - 23.3.24 - Trailer (Rego: YV16GP). Check over Trailer. Grease and adjust brakes. Adjust all R/H side wheel bearings. Cut off old bumper. Fit and align new bumper. Weld bumper and fit new rubber. Remove and replace 8 x nut serts. Weld on mud flap brackets. Mount light in mudflaps and mount. Wire up lights and paint bumper. Re-rivet centre checker plate. Cut patch out of floor and screw new patches to floor.	1,650.00
Parts - 2 x -10 fuel hose ends, 2m x -10 fuel hose, -10 fuel tap, 6 x 25mm p-clamps, 6 x bolts & nuts (owner supplied air dryer filter)	231.31
Workshop consumables, environmental levy & waste disposal levy (including welding)	90.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$2,433.31
Tax	$243.33
TOTAL	$2,676.64
Payments/Credits	$0.00

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.

This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.

A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

Balance Due	$2,676.64

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
31/05/2024	8140

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/06/2024

Description	Amount
31.05.24 - Freightliner Argosy. (Rego 1MF8BK - Speedo 1,409,105 K's) Carry out general service and check over. Jack up front end and check steering and suspension components, grease front end, adjust steer brakes. Lift vehicle with hoist, check drive line oils for level and condition, grease drive line, adjust drive brakes. Drain engine oil, remove and replace both oil filters, remove and replace fuel filter, remove and replace fuel/water separator. Lower vehicle to ground, tit cabin over. Fill with engine oil. Fit washer fluid level sender, fit plate to walk plate bolt. Adjust clutch, steam clean engine bay and road test vehicle. Remove and replace both air cleaners. NOTE: Slight oil leak at L/H front of engine. (Supply 5 Ltrs of engine oil, put in bottle in cabin)	726.00
Parts - 2 x oil filters, fuel filter, fuel/water separator, 2 x air cleaners, 38 Ltrs E900 engine oil, 2 x air cleaners, 5 Ltrs E900 engine oil. Freight inwards.	971.35
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$1,747.35
Tax	$174.74
TOTAL	$1,922.09
Payments/Credits	$0.00
Balance Due	$1,922.09

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
17/09/2024	8450

[redacted]

P.O. No.	Terms	Due Date
	Net 15	2/10/2024

Description	Amount
09.09.24 - Freightliner Argosy (Rego 1MF8BK - Speedo 1,420,164 K's). Lift vehicle with hoist, remove universal joints, remove and steam clean tail shaft, remove gearbox yoke. Send tail shaft for repair and balancing.	214.50
12.09.24 - Freightliner. Remove and replace 3 x brake boosters (supplied) Remove and replace R/H/R drive emergency brake hose. Adjust all brakes. Remove and replace air dryer filter (supplied)	500.50
13.09.24 - Freightliner. Grease and check over truck. Replace gearbox yoke and nut. Fit new tail shaft and tension, adjust clutch. Road test vehicle. Check over. Tighten upper radiator hose clamps. Locate source of air leak while foot brake is applied, found leak present at R/H drive ABS modulator valve, place order for replacement valve.	500.50
14.09.24 - Freightliner. Remove and replace modulating valve beneath turn table. Run truck and re-check for leaks. NOTE: Engine oil leaks present, shackle bushes show excess wear, rear drive brakes show excess wear.	107.25
Parts - ABS modulator valve, 21" air brake hose, gearbox yoke, yoke nut, tail shaft repairs and balancing, 1 x 1/2 BSP - 5/8 air line fitting. Freight inwards.	2,957.07
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$4,329.82
Tax	$432.99
TOTAL	$4,762.81
Payments/Credits	$0.00
Balance Due	$4,762.81

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/09/2024	8501

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/10/2024

Description	Amount
25.9.24 -26.9.24 - Freightliner Argosy (Rego: 1MF 8BK; Speedo: 1,421,325km). Remove turbo intake and exhaust piping to check turbo. Found turbo unserviceable. Remove turbo. Check intercooler for metal and found metal in the bottom. Remove radiator and cooler assembly. Remove intercooler and clean out metal. Pressure wash radiator. Re-assemble radiator and cooler assembly. Re-fit to truck. Re-fit all piping. Replace 45 degree coolant hose on engine. Swap over all fittings into new turbo. Replace all o-rings and weld up turbo drain pipe. Replace 4 x turbo dump studs. Fit up new turbo. Fit all coolant lines and piping. Re-fill coolant. Program turbo actuator. Check air filters for metal and found OK. Get running. Steam clean and test drive.	2,002.00
Parts - turbo assembly, freight inwards	6,289.52
Parts - 4 x (M8x38x1.25) studs, 10 x small Cummins o-rings, 1 x 45 deg coolant hose, 30cm x 1inch silicon hose, 1 x 7.5inch boost clamp, 4 x 20-32mm hose clamps, 1 x 60-80mm hose clamp, set x mount, drain & feed gaskets, 2 x 4inch boost clamps, freight inwards	409.05
Workshop consumables, environmental levy & waste disposal levy	40.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$8,740.57
Tax	$874.06
TOTAL	$9,614.63
Payments/Credits	$0.00
Balance Due	$9,614.63

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
30/11/2024	8733

[redacted]

P.O. No.

Terms	Due Date
Net 15	15/12/2024

Description	Amount
29.11.24 - Freightliner Argosy (Rego 1MF8BK - Speedo 1,427,627 K's). Carry out general service and check over. Jack up front end and check steering and suspension components, grease front end, adjust steer brakes. Lift vehicle with hoist, check drive line oils for level and condition, grease drive line. Adjust drive brakes. Drain engine oil, remove and replace oil filter, remove and replace fuel filter. Lower vehicle to ground and tilt cabin over. Fill with engine oil. Remove and replace driver's step motor. Test operation. Remove and replace passenger side mirror assembly with supplied unit. Steam clean engine bay and road test vehicle. NOTE: Shackle pins and bushes show excess wear.	1,287.00
Parts - Filter kit, 38 Ltrs E900 engine oil, driver's step motor. Freight inwards.	1,179.30
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$2,516.30
Tax	$251.63
TOTAL	$2,767.93
Payments/Credits	$0.00
Balance Due	$2,767.93

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
31/12/2024	8842

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/01/2025

Description	Amount
31.12.24 - Freightliner (Rego: 1FM 8BK; Speedo: 1,430,231km). Remove and replace L/H front drive air bag. Remove thru shaft nut and clean up nut and yoke. Re-fit and tighten nut with loctite and silastic to stop oil from coming under nut. Remove and replace 2 x drive air bags.	357.50
Parts - 2 x airliner air bags, 1 x air fitting.	430.58

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$788.08
Tax	$78.81
TOTAL	$866.89
Payments/Credits	$0.00
Balance Due	$866.89

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
28/02/2025	9042

[redacted]

P.O. No.	Terms	Due Date
	Net 15	15/03/2025

Description	Amount
27.02.25 - 28.2.25 - Argosy (Rego: 1MK 8BK; Speedo: 1,435,533km). Cut wiring to front bumper. Remove front bumper and sit to the side. Set truck up on stands. Remove spring packs and oxy off hangers. Push pins & bushes out in press. Press new pins & bushes in. Re-fit hangers with new bolts. Put spring packs back in and tension u-bolts. Re-fit front bumper and re-wire bumper lights and test operation. Remove and replace all drive bakes and drums. Found coolant leak. Tighten coolant pipe hose clamps and replace 1 x hose clamp as required. Steam clean. Road test.	2,431.00
Parts - 6 x shackle pins & bushes,4 x brake drums, 8 x 5/8" - 4" bolts and conelocks, 16 hardened washers to suit, 5 x crimp joiners, 1 x hose clamp (owner supplied 4 x brake shoes)	2,459.57
Workshop consumables, environmental levy & waste disposal levy	50.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$4,940.57
Tax	$494.06
TOTAL	$5,434.63
Payments/Credits	$0.00
Balance Due	$5,434.63

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.

TRIPLETT MECHANICAL PTY LTD
ABN: 57 898 227 409

20 Gunyah Lane, Goornong VIC 3557
PO Box 338, Eaglehawk VIC 3556

Mobile 0409 971 776 **Parts** 0447 730 494
Email admin@triplettmechanical.com.au

Tax Invoice

Date	Tax Invoice #
22/07/2025	9495

[redacted]

P.O. No.

Terms	Due Date
Net 15	6/08/2025

Description	Amount
21.07.25 - Freightliner Argosy (Rego 1MF8BK - Speedo 1,444,453 K's) (Trailer Rego YV16GP). Back trailer into shed. Check all lights, repair wiring for R/H top marker light. Jack up each axle and check all wheel bearings - adjust all L/H side wheel bearings, grease each axle, adjust all brakes. Adjust ride height to raise body. Un-hook in yard. Truck: Check all lights. Jack up front end and check steering and suspension components, grease front end. Lift vehicle with hoist, check drive line oils for level and condition, grease drive line, adjust all brakes. Lower vehicle to ground, tilt cabin over. Check engine oil level and condition of belts, idlers and pulleys. Adjust clutch free travel and clutch brake. Supply 5 Ltrs of E900 engine oil. NOTE: Alternator belt has excess wear, foot valve has slight air leak.	715.00
Parts - 5 Ltrs E900 engine oil.	47.70
Workshop consumables, environmental levy & waste disposal levy	25.00

Thank you for your business.

Banking Details:
A/C Name: Triplett Mechanical Pty Ltd
Bank: NAB BSB: 083 543 A/C No. 5972 33332

Subtotal	$787.70
Tax	$78.77
TOTAL	$866.47
Payments/Credits	$0.00
Balance Due	$866.47

The property in and title to the goods listed on this invoice will be registered on the PPSR as a security interest and shall remain with Triplett Mechanical PL & does not pass to the customer until all monies payable pursuant to the invoice have been paid in full to Triplett Mechanical PL.
This is a payment claim for professional services and is due as per the terms stated, except as otherwise provided by written agreement.
A charge of 10% per month will be added to your invoice total should payment not be received within the specified terms and will continue to be applied on a monthly basis until payment is received in full.