Exodas Pty Ltd

Work Order History

Asset	Registration	Work	Work Order	Service	RM	Task	Employee	Product	W/H	Supplier	Invoice
RP23	975QWX	15619	01/01/2013	BEARPK	1	LABOUR	MECH	Labour - Internal			
RP23	975QWX	2831	07/07/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2832	07/18/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2833	07/29/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2834	08/15/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2835	09/21/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2835	09/21/2016	TRB	1	LABOUR	MECH	Labour			
RP23	975QWX	2836	10/12/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2837	11/07/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2838	11/21/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2839	12/12/2016	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2840	01/18/2017	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	2840	01/18/2017	TRB	1	LABOUR	MECH	Labour			
RP23	975QWX	5014	01/27/2017	FRIVCAL	1	LABOUR	Labour				0
RP23	975QWX	5014	01/27/2017	FRIVCAL	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RP23	975QWX	2947	02/22/2017	TRA	0	LABOUR	MECH	Labour - Internal			
RP23	975QWX	2947	02/22/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	2947	02/22/2017	TRA	16	CON		YAT Consumables			
RP23	975QWX	3090	02/22/2017	TYRES	15	TYRFIT		TYRMOR01	EX00000841		Tyre Fitting,975-QWX RP23
RP23	975QWX	3090	02/22/2017	TYRES	15	TYR11R22.5BRI		YAT TYR11R.22.5 Bridgestone			
RP23	975QWX	3090	02/22/2017	TYRES	15	TYRFIT		TYRMOR01	11670		Tyre Fitting,975-QWX RP23
RP23	975QWX	3450	04/05/2017	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	3450	04/05/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	3450	04/05/2017	TRA	16	CON		YAT Consumables			
RP23	975QWX	4073	05/17/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	4073	05/17/2017	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	4073	05/17/2017	TRA	16	CON		YAT Consumables			
RP23	975QWX	4073	05/17/2017	TRA	NO						
RP23	975QWX	4482	05/31/2017	GEN	35	123		QTKGRO01	EX00001778		LOW REFRIGERANT CODES,
RP23	975QWX	4482	05/31/2017	GEN	35	123		QTKGRO01	SI-099013		LOW REFRIGERANT CODES,
RP23	975QWX	5013	06/15/2017	FRIVANA	1	LABOUR	Labour				0
RP23	975QWX	5013	06/15/2017	FRIVANA	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RP23	975QWX	4902	06/21/2017	FRIVANA	1	LABOUR	MECH	Labour			

RP23	975QWX	4902	06/21/2017	FRIVANA	PERFORMED A SERVICE ON UNIT BY QTK - SI-100321							
RP23	975QWX	4667	06/23/2017	TRA	1	LABOUR	Labour					0
RP23	975QWX	4667	06/23/2017	TRA	0	LABOUR	MECH1	Labour - Internal				
RP23	975QWX	4667	06/23/2017	TRA	0	LABOUR	APPREN	Labour - Internal				
RP23	975QWX	4667	06/23/2017	TRA	16	CON		YAT	Consumables			
RP23	975QWX	5432	06/26/2017	TYRES	15	33000084		BRIAUS01		EX00002331	FIT TBR TYRE,RP23	
RP23	975QWX	5432	06/26/2017	TYRES	15	77000180		BRIAUS01		EX00002331	CASE STOCK 11-22.5,RP23	
RP23	975QWX	5432	06/26/2017	TYRES	15	11002831		YAT	TYRE 11R22.5 146/143L			
RP23	975QWX	5432	06/26/2017	TYRES	FIT UP NEW TYRE.							
RP23	975QWX	5432	06/26/2017	TYRES	15	33000084		BRIAUS01		4.42E+09	FIT TBR TYRE,RP23	
RP23	975QWX	5432	06/26/2017	TYRES	15	77000180		BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	100417		QTKGRO01		EX00002598	Filter Service Kit, Fridge Motor, SLX-400,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		EX00002598	Consumab	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	418851		QTKGRO01		EX00002598	Regulator Alt,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	15W40		QTKGRO01		EX00002598	ENGINE OIL,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		EX00002598	Consumab	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		EX00002598	Consumab	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CC		QTKGRO01		EX00002598	CALIBRATION CETIFICATE,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	LABEXT		QTKGRO01		EX00002598	Labour External,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	QTK COMPLETED FRIDGE 'B' SERVICE.							
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	100417		QTKGRO01		SI-104891	Filter Service Kit, Fridge Motor, SLX-400,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		SI-104891	Consumab	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	418851		QTKGRO01		SI-104891	Regulator Alt,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		SI-104891	Consumab les ,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	15W40		QTKGRO01		SI-104891	ENGINE OIL,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CON		QTKGRO01		SI-104891	Consumab les ,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	CC		QTKGRO01		SI-104891	CALIBRATION CETIFICATE,RP23	
RP23	975QWX	5818	08/30/2017	FRIVANSE	1	LABEXT		QTKGRO01		SI-104891	Labour External,RP23	
RP23	975QWX	5737	08/31/2017	TRA	1	LABOUR	Labour					0
RP23	975QWX	5737	08/31/2017	TRA	0	LABOUR	MECH	Labour - Internal				
RP23	975QWX	5737	08/31/2017	TRA	0	LABOUR	MECH	0	85	0		
RP23	975QWX	5737	08/31/2017	TRB	1	LABOUR	Labour					0
RP23	975QWX	5737	08/31/2017	TRB	0	LABOUR	MECH1	Labour - Internal				
RP23	975QWX	5737	08/31/2017	TRB	0	LABOUR	TRADEA	Labour - Internal				
RP23	975QWX	5737	08/31/2017	TRB	16	CON		YAT	Consumables			
RP23	975QWX	5737	08/31/2017	TRB	FIT UP MAINTENANCE LABEL AND REGO LABEL.							

RP23	975QWX	6671	10/31/2017	TRA		1	LABOUR	Labour			0
RP23	975QWX	6671	10/31/2017	TRA		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	6671	10/31/2017	TRA	COMPLETED. REPAIRED NUMBER PLATE LIGHT. TIGHTENED BOLTS ON THE AIR TANK. NEEDS LHS FRONT ROOF LIGHT REPAIRED, IT NEEDS TO BE RUN TOO NEW POWER SOURCE. 2 HOURS NEEDED FOR THIS REPAIR.	16	CON	YAT	Consumables		
RP23	975QWX	7136	11/29/2017	FRIVANA		1	CON	QTKGRO01	EX00003413	Consumables,RP23	
RP23	975QWX	7136	11/29/2017	FRIVANA		1	LABEXT	QTKGRO01	EX00003413	Labour External,RP23	

RP23	975QWX	7136	11/29/2017	FRIVANA	QTK COMPLETED THE 'A' SERVICE. R/R AND LUBRICATED THE DAMPER BUSHES.						
RP23	975QWX	7136	11/29/2017	FRIVANA	1	CON		QTKGRO01		SI-111070	Consumables ,RP23
RP23	975QWX	7136	11/29/2017	FRIVANA	1	LABEXT		QTKGRO01		SI-111070	Labour External,RP23
RP23	975QWX	7257	12/08/2017	TRA	1	LABOUR	Labour				0
RP23	975QWX	7257	12/08/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7257	12/08/2017	TRA	16	CON		YAT	Consumables		
RP23	975QWX	7257	12/08/2017	TRA	SERVICE COMPLETED.						
RP23	975QWX	7513	12/28/2017	TYRES	15	33000096		BRIAUS01		EX00003701	PUNCTURE REPAIR TBR,RP23
RP23	975QWX	7513	12/28/2017	TYRES	15	PART		BRIAUS01		EX00003701	RETORQUE WHEEL,RP23
RP23	975QWX	7513	12/28/2017	TYRES	15	33000125		BRIAUS01		EX00003701	ETA MIN FEE,RP23
RP23	975QWX	7513	12/28/2017	TYRES	15	33000084		YAT	FIT TBR TYRE		
RP23	975QWX	7513	12/28/2017	TYRES	AFTER HOURS CALL OUT. BY BUDERKIN TYRE SERVICE, BRIDGESTONE.						
RP23	975QWX	7513	12/28/2017	TYRES	15	33000096		BRIAUS01		95299532	PUNCTURE REPAIR TBR,RP23
RP23	975QWX	7513	12/28/2017	TYRES	15	PART		BRIAUS01		95299532	RETORQUE WHEEL,RP23
RP23	975QWX	7513	12/28/2017	TYRES	15	33000125		BRIAUS01		95299532	ETA MIN FEE,RP23
RP23	975QWX	7654	01/09/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	7654	01/09/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7654	01/09/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7654	01/09/2018	TRA	16	CON		YAT	Consumables		
RP23	975QWX	7654	01/09/2018	TRA	SERVICE COMPLETED.						
RP23	975QWX	7915	01/20/2018	FRIVANA	1	CON		QTKGRO01		EX00003915	Consumables ,RP23
RP23	975QWX	7915	01/20/2018	FRIVANA	1	LABEXT		QTKGRO01		EX00003915	Labour External,RP23
RP23	975QWX	7915	01/20/2018	FRIVANA	QTK COMPLETED THE SERVICE AND/OR REPAIRS.						
RP23	975QWX	7915	01/20/2018	FRIVANA	1	CON		QTKGRO01		SI-114233	Consumables ,RP23
RP23	975QWX	7915	01/20/2018	FRIVANA	1	LABEXT		QTKGRO01		SI-114233	Labour External,RP23
RP23	975QWX	7968	01/22/2018	FRIVANA	1	COO		JC&SL01		EX00003965	Coolant Allcool K/worth ,RP23

RP23	975QWX	7968	01/22/2018	FRIVANA	1	CON		JC&SL01	EX00003965	Consumables ,RP23
RP23	975QWX	7968	01/22/2018	FRIVANA	1	LABEXT		JC&SL01	EX00003965	Labour External,RP23
RP23	975QWX	7968	01/22/2018	FRIVANA	JC & SL TOTAL TRANSPORT REFRIGERATION COMPLETED THE SERVICE/REPAIR.					
RP23	975QWX	7968	01/22/2018	FRIVANA	1	LABEXT		JC&SL01	8112	Labour External,RP23
RP23	975QWX	7968	01/22/2018	FRIVANA	1	CON		JC&SL01	8112	Consumables ,RP23
RP23	975QWX	7968	01/22/2018	FRIVANA	1	COO		JC&SL01	8112	Coolant Allcool K/worth ,RP23
RP23	975QWX	7943	01/24/2018	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	7943	01/24/2018	DEFECT	Reported Defect :- Defect Code : 00000669 Defect Reference : W/O 6671 Date : 31/10/2017 Description of Defect : NEEDS LHS FRONT ROOF LIGHT REPAIRED, IT NEEDS TO BE RUN TOO NEW POWER SOURCE. 2 HOURS					

RP23	975QWX	7944	01/24/2018	EXOINS	1	LABOUR	Labour				0
RP23	975QWX	7944	01/24/2018	EXOINS	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7944	01/24/2018	EXOINS	0	LABOUR	MECH1	Labour - Internal Luke			
RP23	975QWX	7944	01/24/2018	EXOINS	PASSED						
RP23	975QWX	7943	01/24/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	7943	01/24/2018	TRB	1	LABOUR	Labour				0
RP23	975QWX	7943	01/24/2018	TRC	1	LABOUR	Labour				0
RP23	975QWX	7943	01/24/2018	TRC	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7943	01/24/2018	TRC	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	7943	01/24/2018	TRC	14	2051-BULK		YAT	Frt Position LED marker		
RP23	975QWX	7943	01/24/2018	TRC	16	CON		YAT	Consumables		
RP23	975QWX	7943	01/24/2018	TRC	SERVICE COMPLETED. FITTED UP A MARKER LIGHT LHS TOP, REWIRED ALSO. STRAIGHTENED GUARD BRACKETS.						
RP23	975QWX	8365	02/13/2018	FRIVANA	1	2030740		JC&SL01		EX00004245	R404A REFRIGERANT GAS,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	COIL		JC&SL01		EX00004245	COIL CLEAN, EVAPORATOR/CONDENSOR,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	SUND		JC&SL01		EX00004245	SUNDRIES,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	LABEXT		JC&SL01		EX00004245	Labour External,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	JC & SL COMPLETED THE SERVICE/REPAIRS.						
RP23	975QWX	8365	02/13/2018	FRIVANA	1	LABEXT		JC&SL01		8198	Labour External,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	SUND		JC&SL01		8198	SUNDRIES,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	COIL		JC&SL01		8198	COIL CLEAN, EVAPORATOR/CONDENSOR,RP23
RP23	975QWX	8365	02/13/2018	FRIVANA	1	2030740		JC&SL01		8198	R404A REFRIGERANT GAS,RP23
RP23	975QWX	8480	02/22/2018	TYRES	15	77000180		BRIAUS01		EX00004306	CASE STOCK 11-22.5,RP23
RP23	975QWX	8480	02/22/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RP23	975QWX	8480	02/22/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP23	975QWX	8480	02/22/2018	TYRES	15	77000180		BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP23
RP23	975QWX	8553	03/02/2018	tra	1	LABOUR	MECH	Labour			

RP23	975QWX	8553	03/02/2018	tra	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	8553	03/02/2018	tra	0	LABOUR	TRADEA	Labour - Internal		
RP23	975QWX	8553	03/02/2018	tra	16	CON		YAT	Consumables	
RP23	975QWX	8553	03/02/2018	tra	SERVICE COMPLETED.					
RP23	975QWX	8717	03/07/2018	TYRES	15	77000180		BRIAUS01	EX00004438	CASE STOCK 11-22.5,RP23
RP23	975QWX	8717	03/07/2018	TYRES	15	33000084		YAT	FIT TBR TYRE	
RP23	975QWX	8717	03/07/2018	TYRES	15	33000370		YAT	TYRE HELD FOR RUNOUT	
RP23	975QWX	8717	03/07/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP23	975QWX	8717	03/07/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK	
RP23	975QWX	8717	03/07/2018	TYRES	15	77000180		BRIAUS01	4.42E+09	CASE STOCK 11-22.5,RP23
RP23	975QWX	8949	03/27/2018	TRA	1	LABOUR	Labour			0
RP23	975QWX	8949	03/27/2018	TRA	0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	8949	03/27/2018	TRA	16	CON		YAT	Consumables	
RP23	975QWX	8949	03/27/2018	TRA	SERVICE COMPLETED.					
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	15W40		JC&SL01	EX00005006	ENGINE OIL,RP23
										Coolant
										Allcool
										K/worth
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	COO		JC&SL01	EX00005006	,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	Nov-41		JC&SL01	EX00005006	FUEL FILTER EMI2000 HOUR,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	Nov-82		JC&SL01	EX00005006	OIL FILTER, FRIDGE MOTOR,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	119300		JC&SL01	EX00005006	QTK Fridge A/Filter EMI 3000,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	78-0629		JC&SL01	EX00005006	SB series fridge motor fanbelt,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	78-0603		JC&SL01	EX00005006	SB Series Fridge motor fanbelt,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	COIL		JC&SL01	EX00005006	COIL CLEAN, EVAPORATOR/CONDENSOR,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	SUND		JC&SL01	EX00005006	SUNDRIES,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	LABEXT		JC&SL01	EX00005006	Labour External,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	SERVICE COMPLETED BY JC & SL REFRIGERATION.					
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	LABEXT		JC&SL01	8464	Labour External,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	SUND		JC&SL01	8464	SUNDRIES,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	COIL		JC&SL01	8464	COIL CLEAN, EVAPORATOR/CONDENSOR,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	78-0603		JC&SL01	8464	SB Series Fridge motor fanbelt,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	78-0629		JC&SL01	8464	SB series fridge motor fanbelt,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	119300		JC&SL01	8464	QTK Fridge A/Filter EMI 3000,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	Nov-82		JC&SL01	8464	OIL FILTER, FRIDGE MOTOR,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	Nov-41		JC&SL01	8464	FUEL FILTER EMI2000 HOUR,RP23
										Coolant
										Allcool
										K/worth
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	COO		JC&SL01	8464	,RP23
RP23	975QWX	9566	05/02/2018	FRIVANSE	1	15W40		JC&SL01	8464	ENGINE OIL,RP23
RP23	975QWX	9791	05/18/2018	TRA	1	LABOUR	Labour			0
RP23	975QWX	9791	05/18/2018	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	9791	05/18/2018	TRA	0	LABOUR	MECH1	Labour - Internal		

RP23	975QWX	9791	05/18/2018	TRA	SERVICE COMPLETED. COULD NOT CHECK INSIDE, IT WAS LOADED.	16	CON		YAT	Consumables		
RP23	975QWX	9791	05/18/2018	TRA								
RP23	975QWX	9880	05/23/2018	TYRES								
RP23	975QWX	9880	05/23/2018	TYRES		15	LABOUR	Labour				0
RP23	975QWX	9880	05/23/2018	TYRES		15	33000188		YAT	B FLEET PRESSURE CHECK		
RP23	975QWX	9950	05/28/2018	TYRES		15	77000232		BRIAUS01		EX00005248	CASE STOCK 11R22.5 ECOPIA,RP23
RP23	975QWX	9950	05/28/2018	TYRES		15	33000084		YAT	FIT TBR TYRE		
RP23	975QWX	9950	05/28/2018	TYRES		15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP23	975QWX	9950	05/28/2018	TYRES		15	77000232		BRIAUS01		4.42E+09	CASE STOCK 11R22.5 ECOPIA,RP23
RP23	975QWX	10736	07/07/2018	DEFECT		1	LABOUR	MECH	Labour			
RP23	975QWX	10736	07/07/2018	DEFECT	Reported Defect :- Defect Code : 00001366 Defect Reference : 9478 Date : 15/05/2018 Description of Defect : BOTTOM RAIL INSIDE VAN NEEDS TO BE REPAIRED. REPAIRED							

RP23	975QWX	10736	07/07/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	10736	07/07/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	10736	07/07/2018	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva		
RP23	975QWX	10736	07/07/2018	TRA	16	CON		YAT	Consumables		
RP23	975QWX	10736	07/07/2018	TRA	SERVICE COMPLETED. REPAIRED 600MM OF 'F' TRACK. REPLACED RHF MARKER LIGHT.						
RP23	975QWX	11788	08/29/2018	FRIVANA	1	15W40		JC&SL01		EX00006333	ENGINE OIL,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	COO		JC&SL01		EX00006333	Coolant Allcool K/worth ,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	SUND		JC&SL01		EX00006333	SUNDRIES,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	LABEXT		JC&SL01		EX00006333	Labour External,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	FRIDGE A SERVIC E COMPLETED TOPPED UP OIL & COOLANT						
RP23	975QWX	11788	08/29/2018	FRIVANA	1	LABEXT		JC&SL01		8916	Labour External,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	SUND		JC&SL01		8916	SUNDRIES,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	COO		JC&SL01		8916	Coolant Allcool K/worth ,RP23
RP23	975QWX	11788	08/29/2018	FRIVANA	1	15W40		JC&SL01		8916	ENGINE OIL,RP23
RP23	975QWX	11619	08/29/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	11619	08/29/2018	TRB	1	LABOUR	Labour				0
RP23	975QWX	11619	08/29/2018	TRB	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	11619	08/29/2018	TRB	0	LABOUR	MECH1	Labour - Internal			

RP23	975QWX	11619	08/29/2018	TRB		13	91700BL	YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	11619	08/29/2018	TRB		40	3413005	YAT	OIL 15W-40, CK 4/E9	
RP23	975QWX	11619	08/29/2018	TRB		13	37FW1	YAT	HOOD HOOK LATCH, RUBBER,	
RP23	975QWX	11619	08/29/2018	TRB		16	CON	YAT	Consumables	
RP23	975QWX	11619	08/29/2018	TRB	SERVICE COMPLETED TOOL BOX U/S FITTED SAFETY LATCH ON FRIDGE DOORS TOPPED UP ENGINE OIL FITTED NEW MARKERLAMP ON LHS					
RP23	975QWX	12617	10/29/2018	FRIVANSE		1	R404A	RIXREF01	EX00006865	GAS R404A,RP23
RP23	975QWX	12617	10/29/2018	FRIVANSE		1	LABEXT	RIXREF01	EX00006865	Labour External,RP23
RP23	975QWX	12617	10/29/2018	FRIVANSE		1	SUND	RIXREF01	EX00006865	SUNDRIES,RP23
RP23	975QWX	12617	10/29/2018	FRIVANSE	SERVICE COMPLETED R&R OIL/FUEL FILTERS, ALTERNATOR, DISCHARGE CLAMP CALIBRATED UNIT					
RP23	975QWX	12617	10/29/2018	FRIVANSE		1	SUND	RIXREF01	18388	SUNDRIES,RP23
RP23	975QWX	12617	10/29/2018	FRIVANSE		1	LABEXT	RIXREF01	18388	Labour External,RP23

RP23	975QWX	12617	10/29/2018	FRIVANSE	1	R404A		RIXREF01		18388	GAS R404A,RP23
RP23	975QWX	12644	10/29/2018	GEN	39	LABOUR	Labour				0
RP23	975QWX	12644	10/29/2018	GEN	6	10-417		YAT	Filter Service Kit, Fridge Motor, SLX-400		
RP23	975QWX	12644	10/29/2018	GEN	3	452589		YAT	Alternator, QTK Fridge,		
RP23	975QWX	12644	10/29/2018	GEN	3	91-0372		YAT	CLAMP TUBE, FRIDGE MOTOR		
RP23	975QWX	12644	10/29/2018	GEN	PARTS SUPPLIED FOR SERVICING BY RIXON						
RP23	975QWX	12615	11/02/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	12615	11/02/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	12615	11/02/2018	TRA	16	CON		YAT	Consumables		
RP23	975QWX	12615	11/02/2018	TRA	SERVICE COMPLETED						
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		EX00006974	OIL FILETRS,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		EX00006974	FUEL FILTERS,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		EX00006974	AIR CLEANER,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	LABEXT		RIXREF01		EX00006974	Labour External,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	SUND		RIXREF01		EX00006974	SUNDRIES,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	12825	11/05/2018	FRIVANSE	SERVICE COMPLETED R&R OIL, OIL FILTERS, FUEL FILETRS, AIR CLEANER						
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		18467	OIL FILETRS,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		18467	FUEL FILTERS,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	PART		RIXREF01		18467	AIR CLEANER,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	LABEXT		RIXREF01		18467	Labour External,RP23
RP23	975QWX	12825	11/05/2018	FRIVANSE	1	SUND		RIXREF01		18467	SUNDRIES,RP23
RP23	975QWX	13090	11/19/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007115	Labour External,RP23
RP23	975QWX	13090	11/19/2018	FRIVANA	1	SUND		RIXREF01		EX00007115	SUNDRIES,RP23
RP23	975QWX	13090	11/19/2018	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	13090	11/19/2018	FRIVANA	1	LABEXT		RIXREF01		18559	Labour External,RP23
RP23	975QWX	13090	11/19/2018	FRIVANA	1	SUND		RIXREF01		18559	SUNDRIES,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	1	44-6544		RIXREF01		EX00007188	SOLENOID. HIGH SPEED. FRIDGE MOTOR,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007188	Labour External,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	1	SUND		RIXREF01		EX00007188	SUNDRIES,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	SERVICE COMPLETED R&R SPEED SOLENOID						

RP23	975QWX	13235	11/23/2018	FRIVANA	1	SUND		RIXREF01		18616	SUNDRIES,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	1	LABEXT		RIXREF01		18616	Labour External,RP23
RP23	975QWX	13235	11/23/2018	FRIVANA	1	44-6544		RIXREF01		18616	SOLENOID. HIGH SPEED. FRIDGE MOTOR,RP23
RP23	975QWX	13222	11/26/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007183	Labour External,RP23
RP23	975QWX	13222	11/26/2018	FRIVANA	1	SUND		RIXREF01		EX00007183	SUNDRIES,RP23
RP23	975QWX	13222	11/26/2018	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	13222	11/26/2018	FRIVANA	1	SUND		RIXREF01		18621	SUNDRIES,RP23
RP23	975QWX	13222	11/26/2018	FRIVANA	1	LABEXT		RIXREF01		18621	Labour External,RP23
RP23	975QWX	13335	11/30/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007256	Labour External,RP23
RP23	975QWX	13335	11/30/2018	FRIVANA	1	SUND		RIXREF01		EX00007256	SUNDRIES,RP23
RP23	975QWX	13335	11/30/2018	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	13335	11/30/2018	FRIVANA	1	SUND		RIXREF01		18638	SUNDRIES,RP23
RP23	975QWX	13335	11/30/2018	FRIVANA	1	LABEXT		RIXREF01		18638	Labour External,RP23
RP23	975QWX	13379	12/03/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007283	Labour External,RP23
RP23	975QWX	13379	12/03/2018	FRIVANA	1	SUND		RIXREF01		EX00007283	SUNDRIES,RP23
RP23	975QWX	13379	12/03/2018	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	13379	12/03/2018	FRIVANA	1	SUND		RIXREF01		18695	SUNDRIES,RP23
RP23	975QWX	13379	12/03/2018	FRIVANA	1	LABEXT		RIXREF01		18695	Labour External,RP23
RP23	975QWX	13286	12/05/2018	TYRES	15	77000180		BRIAUS01		EX00007224	CASE STOCK 11-22.5,RP23
RP23	975QWX	13286	12/05/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP23	975QWX	13286	12/05/2018	TYRES	R&R TYRES						
RP23	975QWX	13286	12/05/2018	TYRES	15	77000180		BRIAUS01		96373630	CASE STOCK 11-22.5,RP23
RP23	975QWX	13669	12/13/2018	FRIVANA	1	LABEXT		RIXREF01		EX00007414	Labour External,RP23
RP23	975QWX	16446	12/13/2018	FRIVANA	1	LABCON		RIXREF01		EX00008938	LABOUR & CONSUMABLES,RP23
RP23	975QWX	13669	12/13/2018	FRIVANA	1	SUND		RIXREF01		EX00007414	SUNDRIES,RP23
RP23	975QWX	16446	12/13/2018	FRIVANA	1	LABCON		RIXREF01		18745	LABOUR & CONSUMABLES,RP23
RP23	975QWX	13669	12/13/2018	FRIVANA	SERVICE COMPLETED REMOVE/ REFIT EVAPORATOR PROBE, CLAIBRATED SENSOR						
RP23	975QWX	13430	12/13/2018	TRA	1	LABOUR	Labour				0
RP23	975QWX	13430	12/13/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	13430	12/13/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	13430	12/13/2018	TRA	16	CON		YAT	Consumables		
RP23	975QWX	13430	12/13/2018	TRA	SERVICE COMPLETED						
RP23	975QWX	14059	01/06/2019	GEN	39	78-1341		BRIVAL01		EX00007641	SB fridge motor fanbelt,RP23

RP23	975QWX	14059	01/06/2019	GEN	39	CON		BRIVAL01		EX00007641	Consumables,RP23
RP23	975QWX	14059	01/06/2019	GEN	39	LABEXT		BRIVAL01		EX00007641	Labour External,RP23
RP23	975QWX	14059	01/06/2019	GEN	R&R DISCHARGE CLAMP & ALTERNATOR BELT						
RP23	975QWX	14059	01/06/2019	GEN	13	91-0372		YAT	CLAMP TUBE, FRIDGE MOTOR		
RP23	975QWX	14059	01/06/2019	GEN	39	LABEXT		BRIVAL01		37	Labour External,RP23
RP23	975QWX	14059	01/06/2019	GEN	39	CON		BRIVAL01		37	Consumables,RP23
RP23	975QWX	14059	01/06/2019	GEN	39	78-1341		BRIVAL01		37	SB fridge motor fanbelt,RP23
RP23	975QWX	14279	01/18/2019	FRIVANA	1	LABEXT		BRIVAL01		EX00007734	Labour External,RP23
RP23	975QWX	14279	01/18/2019	FRIVANA	1	CON		BRIVAL01		EX00007734	Consumables,RP23
RP23	975QWX	14279	01/18/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	14279	01/18/2019	FRIVANA	1	CON		BRIVAL01		47	Consumables,RP23
RP23	975QWX	14279	01/18/2019	FRIVANA	1	LABEXT		BRIVAL01		47	Labour External,RP23
RP23	975QWX	14294	01/18/2019	GEN	39	91-0373		BRIVAL01		EX00007736	CLAMP TUBE FRIDGE MOTOR,RP23
RP23	975QWX	14294	01/18/2019	GEN	39	LABEXT		BRIVAL01		EX00007736	Labour External,RP23
RP23	975QWX	14294	01/18/2019	GEN	REPLACED U/S DISCHARGE CLAMPS						
RP23	975QWX	14294	01/18/2019	GEN	39	LABEXT		BRIVAL01		50	Labour External,RP23
RP23	975QWX	14294	01/18/2019	GEN	39	91-0373		BRIVAL01		50	CLAMP TUBE FRIDGE MOTOR,RP23
RP23	975QWX	14073	01/18/2019	TRA	1	LABOUR	Labour				0
RP23	975QWX	14073	01/18/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	14073	01/18/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	14073	01/18/2019	TRA	16	CON		YAT	Consumables		
RP23	975QWX	14073	01/18/2019	TRA	SERVICE COMPLETED						
RP23	975QWX	14163	01/21/2019	TYRES	15	77000180		BRIAUS01		EX00007698	CASE STOCK 11-22.5,RP23
RP23	975QWX	14163	01/21/2019	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP23	975QWX	14163	01/21/2019	TYRES	R&R TYRES						
RP23	975QWX	14163	01/21/2019	TYRES	15	77000180		BRIAUS01		96507215	CASE STOCK 11-22.5,RP23
RP23	975QWX	14560	01/23/2019	FRIVANA	1	LABCON		BRIVAL01		EX00007908	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14560	01/23/2019	FRIVANA	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	14560	01/23/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	14560	01/23/2019	FRIVANA	1	LABCON		BRIVAL01		77	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14613	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		EX00007920	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14628	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		EX00007923	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14613	01/30/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	14628	01/30/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	14613	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		91	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14628	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		94	LABOUR & CONSUMABLES,RP23

RP23	975QWX	15584	02/08/2019	FRIVANA	1	LABCON	BRIVAL01		EX00008496	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15584	02/08/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	15584	02/08/2019	FRIVANA	1	LABCON	BRIVAL01		109	LABOUR & CONSUMABLES,RP23
RP23	975QWX	14732	02/08/2019	GEN	39	78-603	BRIVAL01		EX00008004	SB Fridge Fan belt,RP23
RP23	975QWX	14732	02/08/2019	GEN	39	78-629	BRIVAL01		EX00008004	BELT,RP23
RP23	975QWX	14732	02/08/2019	GEN	39	LABEXT	BRIVAL01		EX00008004	Labour External,RP23
RP23	975QWX	14732	02/08/2019	GEN	14	NX120-7	YAT	BATTERY		
RP23	975QWX	14732	02/08/2019	GEN	REPLACED BATTERY (EXODAS SUPPLIED) R&R FAN SHAFT BELTS DRAINED FUEL TANK SUMP & TREATED "FUEL BUG" IN LINES & TANK					
RP23	975QWX	14732	02/08/2019	GEN	39	LABEXT	BRIVAL01		112	Labour External,RP23
RP23	975QWX	14732	02/08/2019	GEN	39	78-629	BRIVAL01		112	BELT,RP23
RP23	975QWX	14732	02/08/2019	GEN	39	78-603	BRIVAL01		112	SB Fridge Fan belt,RP23
RP23	975QWX	15922	03/04/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		EX00008643	LABOUR & CONSUMABLES,RMP23, HOURS 18705
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		243	LABOUR & CONSUMABLES,RMP23, HOURS 18705
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		EX00010591	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		EX00010595	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		743	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15922	03/04/2019	FRIVANA	1	LABCON	BRIVAL01		785	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON	BRIVAL01		EX00008384	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON	BRIVAL01		169	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON	BRIVAL01		EX00008689	LABOUR & CONSUMABLES,RP23, HOURS 18808
RP23	975QWX	15394	03/08/2019	FRIVANA	1	ROUNDING	BRIVAL01		EX00008689	ROUNDING,
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON	BRIVAL01		EX00008691	LABOUR & CONSUMABLES,RP23, HOURS 18808
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON	BRIVAL01		256	LABOUR & CONSUMABLES,RP23, HOURS 18808

RP23	975QWX	15394	03/08/2019	FRIVANA	1	ROUNDING		BRIVAL01	257	ROUNDING,
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	257	LABOUR & CONSUMABLES,RP23, HOURS 18808
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009140	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	378	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009294	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	416	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009449	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009475	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009476	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	312	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	450	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	431	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009559	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	331	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009723	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009749	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009750	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009751	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	537	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	534	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	538	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	510	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009962	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	580	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010118	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	631	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010240	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15394	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	665	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15381	03/15/2019	TRA	1	LABOUR	Labour			0
RP23	975QWX	15381	03/15/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	15381	03/15/2019	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	15381	03/15/2019	TRA	16	CON		YAT	Consumables	
RP23	975QWX	15381	03/15/2019	TRA	SERVICE COMPLETED					
RP23	975QWX	15493	03/18/2019	TYRES	15	77000180		BRIAUS01	EX00008448	CASE STOCK 11-22.5,RP23
RP23	975QWX	15493	03/18/2019	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP23	975QWX	15493	03/18/2019	TYRES	R&R TYRES					
RP23	975QWX	15493	03/18/2019	TYRES	15	77000180		BRIAUS01	96686039	CASE STOCK 11-22.5,RP23
RP23	975QWX	15710	03/20/2019	FRIVANA	1	LABCON		BRIVAL01	EX00008556	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15710	03/20/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	15710	03/20/2019	FRIVANA	1	LABCON		BRIVAL01	216	LABOUR & CONSUMABLES,RP23
RP23	975QWX	15810	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00008598	LABOUR & CONSUMABLES,RP23 HOUR 18769
RP23	975QWX	16028	03/27/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	16032	03/27/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	17348	03/27/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	15810	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	252	LABOUR & CONSUMABLES,RP23 HOUR 18769

RP23	975QWX	15902	04/02/2019	FRIVANSE	1	FILKIT		BRIVAL01		EX00008640	FILTER KIT FRIDGE,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	R404A		BRIVAL01		EX00008640	GAS R404A,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	CON		BRIVAL01		EX00008640	Consumables ,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	LABEXT		BRIVAL01		EX00008640	Labour External,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	15902	04/02/2019	FRIVANSE	SERVICE COMPLETED CALIBRATED UNIT UNIT FOUND NOT COOLING - TRACED TO LEAKING CONDENSER, RECLAIMED GAS & REPAIRED, RECHARGED GAS						
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	LABEXT		BRIVAL01		261	Labour External,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	CON		BRIVAL01		261	Consumables ,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	R404A		BRIVAL01		261	GAS R404A,RP23
RP23	975QWX	15902	04/02/2019	FRIVANSE	1	FILKIT		BRIVAL01		261	FILTER KIT FRIDGE,RP23
RP23	975QWX	17403	04/12/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	17634	04/23/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	16855	05/15/2019	FRIVANA	Service Completed						
RP23	975QWX	17157	05/28/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	17040	05/28/2019	TRA	1	LABOUR	Labour				0
RP23	975QWX	17040	05/28/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	17040	05/28/2019	TRA	16	CON		YAT	Consumables		

RP23	975QWX	17040	05/28/2019	TRA	SERVICE COMPLETED REPLACED BOLT FOR LEG WINDER					
RP23	975QWX	17425	05/29/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	17482	06/03/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	17233	06/05/2019	BEARPK	1	LABOUR	Labour - Internal			0
RP23	975QWX	17233	06/05/2019	BEARPK	BEARING INSPECTED & FRESH GREASE - DIESEL SERVICES					
RP23	975QWX	17232	06/05/2019	EXOINS	1	LABOUR	Labour			0
RP23	975QWX	17232	06/05/2019	EXOINS	PASSED DIESEL SERVICES					
RP23	975QWX	17231	06/05/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009437	LABOUR & CONSUMABLES,RP23,18902.0
RP23	975QWX	17231	06/05/2019	FRIVANA	1	LABCON		BRIVAL01	270	LABOUR & CONSUMABLES,RP23,18902.0
RP23	975QWX	17231	06/05/2019	TRA	1	LABOUR	Labour			0
RP23	975QWX	17231	06/05/2019	TRB	1	LABOUR	Labour			0
RP23	975QWX	17231	06/05/2019	TRC	1	LABOUR	Labour			0
RP23	975QWX	17231	06/05/2019	TRC	SERVICE COMPLETED BY DIESEL SERVICES R&R RH FRONT, LH REAR, LH MIDDLE GAURDS REMOVED, CHECKED CLEAN, REPACKED & REFIT ALL WHEEL BEARINGS REPLACED SEALS R&R TRAILER SOCKET R&R RING FEEDER WEAR PLATE					

RP23	975QWX	17231	06/05/2019	TRC	11	3.12E+08		YAT	ECO PLUS DUST SEAL BPW		
RP23	975QWX	17231	06/05/2019	TRC	13	91700BL		YAT	Clearance Light, LED Amber, Narva		
RP23	975QWX	17231	06/05/2019	TRC	10	BP1802.BAG		YAT	Air Bag BPW		
RP23	975QWX	17231	06/05/2019	TRC	11	2.57E+08		YAT	Hub Seal Grease, BPW, Eco Plus		
RP23	975QWX	17231	06/05/2019	TRC	11	3.12E+08		YAT	ECO PLUS DUST SEAL BPW		
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		EX00009436	Labour External (C&D),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		EX00009436	Labour External (MUDGUARD),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		EX00009436	Labour External (AIRBAG_),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		EX00009436	Labour External (LIGHT REPLACEMENT),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		EX00009436	Labour External (GENERAL REPAIR),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	CON		DIESER01		EX00009436	Consumables,RP23
RP23	975QWX	17231	06/05/2019	TRC	13	MG630-R		YAT	MUDGUARD RED		
RP23	975QWX	17231	06/05/2019	TRC	14	82062		YAT	7 Pin Female Trailer Plug		
RP23	975QWX	17231	06/05/2019	TRC	13	TCK1036		YAT	50MM WEAR PAD RINGFEEDER		
RP23	975QWX	17231	06/05/2019	TRC	13	DR554		YAT	Docking Rubber (DR4421000)		
RP23	975QWX	17231	06/05/2019	TRC	1	CON		DIESER01		24265	Consumables,RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		24265	Labour External (GENERAL REPAIR),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		24265	Labour External (LIGHT REPLACEMENT),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		24265	Labour External (AIRBAG_),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		24265	Labour External (MUDGUARD),RP23
RP23	975QWX	17231	06/05/2019	TRC	1	LABEXT		DIESER01		24265	Labour External (C&D),RP23
RP23	975QWX	18028	06/19/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18174	06/26/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18187	06/27/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18199	06/28/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18646	07/08/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18673	07/10/2019	FRIVANA	SERVICE COMPLETED						
RP23	975QWX	18349	07/10/2019	TRA	1	LABOUR	Labour				0
RP23	975QWX	18349	07/10/2019	TRB	1	LABOUR	Labour				0
RP23	975QWX	18349	07/10/2019	TRB	0	LABOUR	MECH1	Labour - Internal			

RP23	975QWX	18349	07/10/2019	TRB	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	18349	07/10/2019	TRB	13	B310-30KG-PP		YAT	WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH	
RP23	975QWX	18349	07/10/2019	TRB	14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	18349	07/10/2019	TRB	16	CON		YAT	Consumables	
RP23	975QWX	18349	07/10/2019	TRB	SERVICE COMPLETED FITTED WEIGHT GAUGE AS REQUIRED FITTED FIRE EXTINGUISHER AS REQUIRED REPLACED CLEARANCE LIGHT AS REQUIRED					
RP23	975QWX	18681	07/11/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009959	LABOUR & CONSUMABLES,RP23
RP23	975QWX	18681	07/11/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009961	LABOUR & CONSUMABLES,RP23
RP23	975QWX	18681	07/11/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	18681	07/11/2019	FRIVANA	1	LABCON		BRIVAL01	569	LABOUR & CONSUMABLES,RP23
RP23	975QWX	18681	07/11/2019	FRIVANA	1	LABCON		BRIVAL01	577	LABOUR & CONSUMABLES,RP23
RP23	975QWX	18424	07/12/2019	TYRES	15	33000241		BRIAUS01	EX00009874	SCRAP TYRES TBR,RP23
RP23	975QWX	18424	07/12/2019	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187	
RP23	975QWX	18424	07/12/2019	TYRES	R&R TYRES					
RP23	975QWX	18424	07/12/2019	TYRES	15	33000241		BRIAUS01	97052627	SCRAP TYRES TBR,RP23
RP23	975QWX	18953	07/22/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	19005	07/30/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010115	LABOUR & CONSUMABLES,RP23
RP23	975QWX	19005	07/30/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	19005	07/30/2019	FRIVANA	1	LABCON		BRIVAL01	608	LABOUR & CONSUMABLES,RP23
RP23	975QWX	19299	08/09/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	19996	08/27/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	19695	08/27/2019	TRA	1	LABOUR	Labour			0
RP23	975QWX	19695	08/27/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	19695	08/27/2019	TRA	0	LABOUR	MECH1	Labour - Internal		

RP23	975QWX	19695	08/27/2019	TRA	13	2559		YAT	Number Plate Light (Hella)	
RP23	975QWX	19695	08/27/2019	TRA	16	CON		YAT	Consumables	
RP23	975QWX	19695	08/27/2019	TRA	SERVICE COMPLETED STOPPED AIR LINES FROM RUBBING REPLACED NUMBER PLATE LIGHT REPLACED MALE AIR FITTING ON FRONT OF TRAILER REPLACED MISSING BOLTS OUT OF FRIDGE MOTOR COVER					
RP23	975QWX	19713	08/28/2019	TYRES	15	33000096		BRIAUS01	EX00010471	PUNCTURE REPAIR TBR,RP23
RP23	975QWX	19713	08/28/2019	TYRES	PUNCTURE REPAIR					
RP23	975QWX	19713	08/28/2019	TYRES	15	33000096		BRIAUS01	97201566	PUNCTURE REPAIR TBR,RP23
RP23	975QWX	20045	09/02/2019	FRIVANA	SERVICE COMPLETED					
RP23	975QWX	20420	09/19/2019	GEN	39	LABEXT		FLEWRI01	EX00010791	Labour External,RP23
RP23	975QWX	20420	09/19/2019	GEN	S&I SIGNAGE TO B TRAILER AS REQUIRED. NO REAR DOOR					
RP23	975QWX	20420	09/19/2019	GEN	39	LABEXT		FLEWRI01	INV-6982	Labour External,RP23
RP23	975QWX	20485	09/24/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010810	LABOUR & CONSUMABLES,RP23
RP23	975QWX	20485	09/24/2019	FRIVANA	SERVICE COMPLETED 23.09.2019					
RP23	975QWX	20485	09/24/2019	FRIVANA	1	LABCON		BRIVAL01	900	LABOUR & CONSUMABLES,RP23
RP23	975QWX	20720	10/08/2019	TRA	1	LABOUR	Labour			0
RP23	975QWX	20720	10/08/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	20720	10/08/2019	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	20720	10/08/2019	TRA	16	CON		YAT	Consumables	
RP23	975QWX	20720	10/08/2019	TRA	SERVICE COMPLETED					

RP23	975QWX	22109	11/09/2019	TRA	1	LABOUR	Labour				0
RP23	975QWX	22109	11/09/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	22109	11/09/2019	TRA	16	CON		YAT	Consumables		
						SERVICE COMPLETED. CARRY OUT "A"					
RP23	975QWX	22109	11/09/2019	TRA		SERVICE					
						FRIDGE VAN PRE-CHECK COMPLETED					
						PRE-CHECK COMPLETED BY BVR					
RP23	975QWX	23307	11/26/2019	FVPRE		.					
RP23	975QWX	22829	11/30/2019	GEN	13	PART		QTKGRO01		EX00011834	CAP FLARE 1 4 BRASS,
RP23	975QWX	22829	11/30/2019	GEN	13	PART		QTKGRO01		EX00011834	CAP,

						ED BY QTK GROUP 30.11.19 INVOICE # SI-165616 REMOVE AND REPLACE MISSING SERVICE CAPS. WARRANTY: INSPECT UNIT - REMOVE AND REPLACE FAULTY HEAD GASKET AS REQUIRED - FLUSH UNIT X 3 -				
RP23	975QWX	22829	11/30/2019	GEN	RAN ON					
RP23	975QWX	22829	11/30/2019	GEN		13	PART	QTKGRO01	SI-165616	CAP,
RP23	975QWX	22829	11/30/2019	GEN		13	PART	QTKGRO01	SI-165616	CAP FLARE 1 4 BRASS,
RP23	975QWX	24141	12/20/2019	FVPRE		1	LABCON	BRIVAL01	EX00012621	LABOUR & CONSUMABLES,RP23
RP23	975QWX	27626	12/20/2019	FVPRE	SERVICE COMPLETED BY BVR 17.12.2019					
RP23	975QWX	27671	12/20/2019	FVPRE		1	LABCON	BRIVAL01	EX00014314	LABOUR & CONSUMABLES,RP23
RP23	975QWX	24141	12/20/2019	FVPRE	SERVICE COMPLETED BY BVR 18.12.2019					
RP23	975QWX	27671	12/20/2019	FVPRE		1	LABCON	BRIVAL01	1360	LABOUR & CONSUMABLES,RP23
RP23	975QWX	24141	12/20/2019	FVPRE		1	LABCON	BRIVAL01	1361	LABOUR & CONSUMABLES,RP23
RP23	975QWX	23244	12/20/2019	TRB		13	LABEXT	BRIVAL01	EX00012049	RP23,
RP23	975QWX	23244	12/20/2019	TRB		16	CON	BRIVAL01	EX00012049	RP23,
RP23	975QWX	23244	12/20/2019	TRB		13	PART	BRIVAL01	EX00012049	RP23,FILTER KIT TRAILER
RP23	975QWX	23244	12/20/2019	TRB		40	15W40	BRIVAL01	EX00012049	RP23,ENGINE OIL

RP23	975QWX	23244	12/20/2019	TRB	COMPLETED BY BVR 17.12.19 INVOICE # 00001355 B SERVICE OIL 14L (CUSTOMER SUPPLIED) CALIBRATION CERTIFICATE R & R ENGINE OIL R & R FILTERS CHECK COOLANT CHECK & ADJUST BELTS CHECK				
RP23	975QWX	23244	12/20/2019	TRB		40	15W40	BRIVAL01	1355	RP23,ENGINE OIL

RP23	975QWX	23244	12/20/2019	TRB	13	PART		BRIVAL01	1355	RP23,FILTER KIT TRAILER	
RP23	975QWX	23244	12/20/2019	TRB	16	CON		BRIVAL01	1355	RP23,	
RP23	975QWX	23244	12/20/2019	TRB	13	LABEXT		BRIVAL01	1355	RP23,	
RP23	975QWX	23269	12/23/2019	TRA	1	LABOUR	Labour				0
RP23	975QWX	23269	12/23/2019	TRA	SERVICE COMPLETED BY SEAN / BEN / KEIRAN 23.12.19 REPLACED MIDDLE AND REAR RIGHT AIRBAGS						
RP23	975QWX	23269	12/23/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	23269	12/23/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	23269	12/23/2019	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	23269	12/23/2019	TRA	16	CON		YAT	Consumables		
RP23	975QWX	24373	02/10/2020	TRA	1	LABOUR	Labour				0

RP23	975QWX	24373	02/10/2020	TRA	COMPLETED BY SEAN / KEIRAN 10.02.2020 R & R FIRE EXTINGUISHER R & R REAR FEMALE AIR FITTING TOP LHS CORNER INSIDE TRAILER MISSING ALMOST ALL OF ITS RIVETS (DEFECT CREATED) REPAIRED RHS REAR						
RP23	975QWX	24373	02/10/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	24373	02/10/2020	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	24373	02/10/2020	TRA	13	ASA93-23		YAT	Air Fitting, 1/2 Female Adapter.		
RP23	975QWX	24373	02/10/2020	TRA	16	CON		YAT	Consumables		
RP23	975QWX	25090	03/10/2020	TRA	1	LABOUR	Labour				0
RP23	975QWX	25090	03/10/2020	TRA	SERVICE COMPLETED BY BILLY / KEIRAN 10.03.2020						
RP23	975QWX	25090	03/10/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RP23	975QWX	25090	03/10/2020	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	25090	03/10/2020	TRA	16	CON		YAT	Consumables		
RP23	975QWX	25355	03/12/2020	FVPRE	1	LABCON		BRIVAL01		EX00013256	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25355	03/12/2020	FVPRE	SERVICE COMPLETED BY BVR 06.03.2020						
RP23	975QWX	25355	03/12/2020	FVPRE	1	LABCON		BRIVAL01		1797	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	92-374		BRIVAL01		EX00013281	LATCH SLAM,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-603		BRIVAL01		EX00013281	SB Fridge Fan belt,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-629		BRIVAL01		EX00013281	BELT,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-1341		BRIVAL01		EX00013281	SB fridge motor fanbelt,RP23

RP23	975QWX	25401	03/17/2020	FVGEN	16	CON	BRIVAL01	EX00013281	Consumables ,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	LABEXT	BRIVAL01	EX00013281	Labour External,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	COMPLETED BY BVR 17.03.2020 INVOICE # 00001825 REPLACED ALL BELTS DUE TO CRACKING REPLACED UNSERVICEABLE DOOR HINGES UNIT RUN ON TEST PRETRIP PASSED				
RP23	975QWX	25401	03/17/2020	FVGEN	13	LABEXT	BRIVAL01	1825	Labour External,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	16	CON	BRIVAL01	1825	Consumables ,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-1341	BRIVAL01	1825	SB fridge motor fanbelt,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-629	BRIVAL01	1825	BELT,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	78-603	BRIVAL01	1825	SB Fridge Fan belt,RP23
RP23	975QWX	25401	03/17/2020	FVGEN	13	92-374	BRIVAL01	1825	LATCH SLAM,RP23
RP23	975QWX	25786	03/17/2020	FVPRE	1	LABCON	BRIVAL01	EX00013455	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25786	03/17/2020	FVPRE	SERVICE COMPLETED BY BVR 16.03.2020				

RP23	975QWX	25786	03/17/2020	FVPRE	1	LABCON		BRIVAL01	1818	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25824	03/20/2020	FVPRE	1	LABCON		BRIVAL01	EX00013458	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25824	03/20/2020	FVPRE	SERVICE COMPLETED BY BVR 19.03.2020					
RP23	975QWX	25824	03/20/2020	FVPRE	1	LABCON		BRIVAL01	1852	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25866	03/30/2020	FVPRE	1	LABCON		BRIVAL01	EX00013461	LABOUR & CONSUMABLES,RP23
RP23	975QWX	25866	03/30/2020	FVPRE	SERVICE COMPLETED BY BVR 20.03.2020					
RP23	975QWX	25866	03/30/2020	FVPRE	1	LABCON		BRIVAL01	1878	LABOUR & CONSUMABLES,RP23
RP23	975QWX	26231	04/17/2020	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	26231	04/17/2020	DEFECT	Reported Defect :- Defect Code : 00003601 Defect Reference : 03799 Date : 15/01/2020 Description of Defect : LEGS ARE BENT DEFECT CLEARED BY SEAN 17.04.2020					
RP23	975QWX	26231	04/17/2020	TRA	1	LABOUR	Labour			0

RP23	975QWX	26231	04/17/2020	TRA	SERVICE COMPLETED BY BILLY / SEAN 17.04.2020 RE-RIVETED TOP LHT CORNER INSIDE TRAILER AS REQUIRED - MONITOR FOR RESULTS STRAIGHTENED LANDING LEGS						
RP23	975QWX	26231	04/17/2020	TRA		0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	26231	04/17/2020	TRA		0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	26231	04/17/2020	TRA		16	CON		YAT	Consumables	
RP23	975QWX	27218	05/19/2020	TRA		1	LABOUR	Labour			0

RP23	975QWX	27218	05/19/2020	TRA	SERVICE COMPLETED BY BILLY / KEIRAN / BEN 19.05.2020 FITTED LATCH TO FRIDGE DOORS AS REQUIRED FITTED REVERSE ALARM, TOGGLE SWITCH AS REQUIRED						
RP23	975QWX	27218	05/19/2020	TRA		0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	27218	05/19/2020	TRA		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	27218	05/19/2020	TRA		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	27218	05/19/2020	TRA		13	60058BL		YAT	SEAL-BOOT RUBBER WATERPROOF	
RP23	975QWX	27218	05/19/2020	TRA		14	72602		YAT	Reverse Beeper (Narva)	
RP23	975QWX	27218	05/19/2020	TRA		16	CON		YAT	Consumables	
RP23	975QWX	27218	05/19/2020	TRA		13	60056BL		YAT	TOGGLE SWITCH	
RP23	975QWX	27351	05/21/2020	WEICAL		0	LABOUR	Labour			0

					AIR GAUGE: 13.8 ADJUSTED: 14.75 WEIGHBRIDGE: 14.4						
RP23	975QWX	27351	05/21/2020	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP23	975QWX	28188	06/24/2020	FRIVANA	SERVICE COMPLETED BVR 19/06/2020						
RP23	975QWX	28444	06/24/2020	FRIVANA		1	LABCON		BRIVAL01	EX00014520	LABOUR & CONSUMABLES,RP23
RP23	975QWX	28444	06/24/2020	FRIVANA		1	LABCON		BRIVAL01	2569	LABOUR & CONSUMABLES,RP23
RP23	975QWX	28547	07/10/2020	EXOINS		1	LABOUR	Labour			0

RP23	975QWX	28547	07/10/2020	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 2 INSPECTION COMPLETED BY HUNTER TAPPING - BROWN AND HURLEY YATALA 10.07.2020				
RP23	975QWX	28548	07/10/2020	TRA		1	LABOUR	Labour	0
RP23	975QWX	28548	07/10/2020	TRA	SERVICE COMPLETED.				
RP23	975QWX	28548	07/10/2020	TRB		1	LABOUR	Labour	0
RP23	975QWX	28548	07/10/2020	TRB	SERVICE COMPLETED.				
RP23	975QWX	28548	07/10/2020	TRC		1	LABOUR	Labour	0

RP23	975QWX	28548	07/10/2020	TRC	SERVICE COMPLETED BY HUNTER TAPPING (B+H) 10.07.2020 TOP LHS FRONT OF TRAILER, CLEARANCE LIGHT NON EXISTENT LHS FRONT AXLE MUD GUARD DAMAGED. INTERIOR TRAILER LIGHTS U/S.						
RP23	975QWX	28548	07/10/2020	TRC		1	LABEXT		BROHUR01	EX00014670	Labour External,
RP23	975QWX	28548	07/10/2020	TRC		1	ENVLEV		BROHUR01	EX00014670	ENVIRONMENTAL LEVY,
RP23	975QWX	28548	07/10/2020	TRC		1	CON		BROHUR01	EX00014670	Consumables,
RP23	975QWX	28548	07/10/2020	TRC		1	CON		BROHUR01	1954692	Consumables,
RP23	975QWX	28548	07/10/2020	TRC		1	ENVLEV		BROHUR01	1954692	ENVIRONMENTAL LEVY,
RP23	975QWX	28548	07/10/2020	TRC		1	LABEXT		BROHUR01	1954692	Labour External,
RP23	975QWX	29001	07/17/2020	DEFECT		1	LABOUR	MECH	Labour		
RP23	975QWX	29001	07/17/2020	DEFECT							
RP23	975QWX	29001	07/17/2020	DEFECT	DEFECT CLEARED.						
RP23	975QWX	29001	07/17/2020	ROTDRI		15	LABOUR	Labour			0

RP23	975QWX	29001	07/17/2020	ROTDRI	DRIVE TYRE ROTATION COMPLETED. COMPLETED BY BRIDGESTONE -						
RP23	975QWX	29001	07/17/2020	TYRES							
RP23	975QWX	29001	07/17/2020	TYRES	15	LABOUR	Labour				0
RP23	975QWX	29001	07/17/2020	TYRES	15	11002831		YAT	TYRE 11R22.5 146/143L M766		
RP23	975QWX	29074	07/21/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014895	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29074	07/21/2020	FRIVANA	1	LABCON		BRIVAL01		2781	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29074	07/21/2020	FRIVANA	SERVICE COMPLETED BVR						
RP23	975QWX	29019	07/23/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014891	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29019	07/23/2020	FRIVANA	1	LABCON		BRIVAL01		2802	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29019	07/23/2020	FRIVANA	SERVICE COMPLETED BVR						
RP23	975QWX	29793	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015310	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29802	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015312	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29793	08/24/2020	FRIVANA	SERVICE COMPLETED BVR						
RP23	975QWX	29802	08/24/2020	FRIVANA	SERVICE COMPLETED BVR						
RP23	975QWX	29793	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		3092	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29802	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		3091	LABOUR & CONSUMABLES,RP23

RP23	975QWX	29886	08/25/2020	DEFECT	CLEARED BY SEAN 26.08.2020 "IS WORKING" Reported Defect :- Defect Code : 00004559 Defect Reference : W/O 28548 Date : 10/07/2020 Description of Defect : TOP LHS FRONT OF TRAILER,

RP23	975QWX	29886	08/25/2020	DEFECT	CLEARED BY SEAN 26.08.2020 "COULDN'T FAULT" Reported Defect :- Defect Code : 00004561 Defect Reference : W/O 28548 Date : 10/07/2020 Description of Defect : INTERIOR TRAILER LIGHTS U/S.

RP23	975QWX	29886	08/25/2020	DEFECT	CLEARED BY SEAN 26.08.2020 "STILL OK" Reported Defect :- Defect Code : 00004560 Defect Reference : W/O 28548 Date : 10/07/2020 Description of Defect : LHS FRONT AXLE MUD GUARD				
RP23	975QWX	29886	08/25/2020	TRA		1	LABOUR	MECH1	Labour

RP23	975QWX	29886	08/25/2020	TRA	SERVICE COMPLETED BY SEAN AND BEN 25.08.2020 LHS TOP, MIDWAY DOWN, RIVETS MISSING ON WALL.						
RP23	975QWX	29886	08/25/2020	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	29886	08/25/2020	TRA	16	CON		YAT	Consumables		
RP23	975QWX	29911	08/27/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015345	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29920	08/27/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015348	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29911	08/27/2020	FRIVANA	SERVICE COMPLETED BVR 25/08/2020						
RP23	975QWX	29920	08/27/2020	FRIVANA	SERVICE COMPLETED BVR 25/08/2020						
RP23	975QWX	29911	08/27/2020	FRIVANA	1	LABCON		BRIVAL01		3145	LABOUR & CONSUMABLES,RP23
RP23	975QWX	29920	08/27/2020	FRIVANA	1	LABCON		BRIVAL01		3146	LABOUR & CONSUMABLES,RP23
RP23	975QWX	30081	09/03/2020	TRA	1	LABOUR	MECH1	Labour			
RP23	975QWX	30081	09/03/2020	TRA	SERVICE COMPLETED BY SEAN & BEN 03/09/2020.						
RP23	975QWX	30081	09/03/2020	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	30081	09/03/2020	TRA	16	CON		YAT	Consumables		
RP23	975QWX	30771	09/25/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015757	LABOUR & CONSUMABLES,RP23
RP23	975QWX	30771	09/25/2020	FRIVANA	1	LABCON		BRIVAL01		3454	LABOUR & CONSUMABLES,RP23
RP23	975QWX	30736	09/25/2020	FRIVANB	1	10-417		BRIVAL01		EX00015744	FILTER KIT (FRIDGE MOTOR), HOUR 22521
RP23	975QWX	30736	09/25/2020	FRIVANB	1	15W40		BRIVAL01		EX00015744	ENGINE OIL,CUSTOMER SUPPLIED, HOURS 22521
RP23	975QWX	30736	09/25/2020	FRIVANB	1	Nov-80		BRIVAL01		EX00015744	HAND PRIMER, HOURS 22521
RP23	975QWX	30736	09/25/2020	FRIVANB	1	CC		BRIVAL01		EX00015744	CALIBRATION CETIFICATE,
RP23	975QWX	30736	09/25/2020	FRIVANB	1	LABCON		BRIVAL01		EX00015744	LABOUR & CONSUMABLES,
RP23	975QWX	30736	09/25/2020	FRIVANB	1	LABCON		BRIVAL01		3446	LABOUR & CONSUMABLES,
RP23	975QWX	30736	09/25/2020	FRIVANB	1	CC		BRIVAL01		3446	CALIBRATION CETIFICATE,
RP23	975QWX	30736	09/25/2020	FRIVANB	1	Nov-80		BRIVAL01		3446	HAND PRIMER, HOURS 22521
RP23	975QWX	30736	09/25/2020	FRIVANB	1	15W40		BRIVAL01		3446	ENGINE OIL,CUSTOMER SUPPLIED, HOURS 22521
RP23	975QWX	30736	09/25/2020	FRIVANB	1	10-417		BRIVAL01		3446	FILTER KIT (FRIDGE MOTOR), HOUR 22521
RP23	975QWX	30980	09/30/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015841	LABOUR & CONSUMABLES,RP23
RP23	975QWX	30980	09/30/2020	FRIVANA	1	LABCON		BRIVAL01		3499	LABOUR & CONSUMABLES,RP23
RP23	975QWX	31537	10/19/2020	TYRES	15	33000517		BRIAUS01		EX00016115	REMOVAL: CUSTOMER PULL POINT,

RP23	975QWX	31537	10/19/2020	TYRES	15	77000180		BRIAUS01	EX00016115	CASE STOCK 11-22.5,
RP23	975QWX	31537	10/19/2020	TYRES	15	11001573		BRIAUS01	EX00016115	TYRE 11R22.5 148/145L 16 FS T559,OWN STOCK
RP23	975QWX	31537	10/19/2020	TYRES	15	33000084		BRIAUS01	EX00016115	FIT TBR TYRE,
RP23	975QWX	31537	10/19/2020	TYRES	15	33000517		BRIAUS01	99321114	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	31537	10/19/2020	TYRES	15	77000180		BRIAUS01	99321114	CASE STOCK 11-22.5,
RP23	975QWX	31537	10/19/2020	TYRES	15	11001573		BRIAUS01	99321114	TYRE 11R22.5 148/145L 16 FS T559,OWN STOCK
RP23	975QWX	31537	10/19/2020	TYRES	15	33000084		BRIAUS01	99321114	FIT TBR TYRE,
RP23	975QWX	31590	10/20/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016128	LABOUR & CONSUMABLES,RP23
RP23	975QWX	31590	10/20/2020	FRIVANA	1	LABCON		BRIVAL01	3665	LABOUR & CONSUMABLES,RP23
RP23	975QWX	31888	10/28/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016243	LABOUR & CONSUMABLES,RP23
RP23	975QWX	31888	10/28/2020	FRIVANA	1	LABCON		BRIVAL01	3740	LABOUR & CONSUMABLES,RP23
RP23	975QWX	31969	11/01/2020	TRA	1	LABOUR	APPREN	Labour		
RP23	975QWX	31969	11/01/2020	TRA		SERVICE COMPLETED BY KEIRAN 01/11/20 REPAIRED RH REAR GAURD FITTED DUMMY ABS PLUG				
RP23	975QWX	31969	11/01/2020	TRA	16	CON		YAT	Consumables	
RP23	975QWX	31969	11/01/2020	TRA	14	82196		YAT	EBS Plug, 7 pin 12/24v	
RP23	975QWX	32073	11/03/2020	TYRES	15	33000517		BRIAUS01	EX00016322	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	32073	11/03/2020	TYRES	15	77000180		BRIAUS01	EX00016322	CASE STOCK 11-22.5,
RP23	975QWX	32073	11/03/2020	TYRES	15	11001464		BRIAUS01	EX00016322	TYRE 11R22.5 148/145L 16 BS R187,
RP23	975QWX	32073	11/03/2020	TYRES	15	33000084		BRIAUS01	EX00016322	FIT TBR TYRE,
RP23	975QWX	32073	11/03/2020	TYRES	15	33000084		BRIAUS01	99399153	FIT TBR TYRE,
RP23	975QWX	32073	11/03/2020	TYRES	15	11001464		BRIAUS01	99399153	TYRE 11R22.5 148/145L 16 BS R187,
RP23	975QWX	32073	11/03/2020	TYRES	15	77000180		BRIAUS01	99399153	CASE STOCK 11-22.5,
RP23	975QWX	32073	11/03/2020	TYRES	15	33000517		BRIAUS01	99399153	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	32146	11/05/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016392	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32146	11/05/2020	FRIVANA	1	LABCON		BRIVAL01	3860	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32307	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016496	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32313	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016497	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32307	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	3905	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32313	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	3906	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32317	11/11/2020	FVGEN	35	PART		BRIVAL01	EX00016500	GENERAL PART CODE,100W 12V SOLAR PANEL

RP23	975QWX	32317	11/11/2020	FVGEN	35	LABCON		BRIVAL01	EX00016500	LABOUR & CONSUMABLES,
RP23	975QWX	32317	11/11/2020	FVGEN	35	LABCON		BRIVAL01	3917	LABOUR & CONSUMABLES,
RP23	975QWX	32317	11/11/2020	FVGEN	35	PART		BRIVAL01	3917	GENERAL PART CODE,100W 12V SOLAR PANEL
RP23	975QWX	32627	11/24/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016689	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32627	11/24/2020	FRIVANA	1	LABCON		BRIVAL01	4038	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32882	12/07/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016833	LABOUR & CONSUMABLES,RP23
RP23	975QWX	32882	12/07/2020	FRIVANA	1	LABCON		BRIVAL01	4114	LABOUR & CONSUMABLES,RP23
RP23	975QWX	33053	12/11/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016926	LABOUR & CONSUMABLES,RP23
RP23	975QWX	33053	12/11/2020	FRIVANA	1	LABCON		BRIVAL01	4217	LABOUR & CONSUMABLES,RP23
RP23	975QWX	33577	01/08/2021	FRIVANA	1	LABCON		BRIVAL01	EX00017163	LABOUR & CONSUMABLES,RP23
RP23	975QWX	33577	01/08/2021	FRIVANA	SERVICE COMPLETED BY BVR 04/01/2021.					
RP23	975QWX	33577	01/08/2021	FRIVANA	1	LABCON		BRIVAL01	4437	LABOUR & CONSUMABLES,RP23
RP23	975QWX	33828	01/15/2021	TYRES	15	77000180		BRIAUS01	EX00017323	CASE STOCK 11-22.5,RP23
RP23	975QWX	33828	01/15/2021	TYRES	15	77000180		BRIAUS01	85233981	CASE STOCK 11-22.5,RP23
RP23	975QWX	34057	01/27/2021	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	34057	01/27/2021	DEFECT	Reported Defect :- Defect Code : 00005414 Defect Reference : 08161 Date : 19/11/2020 Description of Defect : LEFT CLEARANCE LIGHT NEEDS REPLACING DEFECT CLEARDED BY SEAN 27/01/2021					

RP23	975QWX	34057	01/27/2021	TRA	0	LABOUR	MECH1	Labour		
RP23	975QWX	35569	01/27/2021	TRA	1	LABOUR	Labour			0
					BOOSTER AIRLINES ABOVE FRONT AXLE ADJUSTED ALL WHEEL BEARINGS REPLACED 1 X MARKER LIGHT LHS REPLACED REAR REFLECTIV E SIGNS SERVICE COMPLET ED BY SEAN AND BEN					
RP23	975QWX	34057	01/27/2021	TRA	27/01/20					
RP23	975QWX	35569	01/27/2021	TRA	SERVICE COMPLETED.					
RP23	975QWX	34057	01/27/2021	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	34057	01/27/2021	TRA	16	CON		YAT	Consumables	
RP23	975QWX	34057	01/27/2021	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	34057	01/27/2021	TRA	16	84062BL		YAT	RED REFLECTOR SELF ADHESIVE	
RP23	975QWX	35569	01/27/2021	TRB	0	LABOUR	MECH1	Labour		

RP23	975QWX	35569	01/27/2021	TRB	SERVICE COMPLETED BY ADJUSTED BOOSTER AIRLINES ABOVE FRONT AXLE ADJUSTED ALL WHEEL BEARINGS REPLACED 1X MARKER LIGHT LHS REPLACED REAR REFLECTIVE SIGNS

RP23	975QWX	35569	01/27/2021	TRB	0	LABOUR	APPREN	2	85	170	
RP23	975QWX	35569	01/27/2021	TRB	16	CON	YAT	Consumables			
RP23	975QWX	35569	01/27/2021	TRB	14	91700BL	YAT	Clearance Light, LED Amber, Narva			
RP23	975QWX	34520	01/29/2021	FRIVANA	1	LABCON	BRIVAL01	EX00017560			LABOUR & CONSUMABLES,RP23
RP23	975QWX	34555	01/29/2021	FRIVANA	1	LABCON	BRIVAL01	EX00017561			LABOUR & CONSUMABLES,RP23
RP23	975QWX	34520	01/29/2021	FRIVANA	SERVICE COMPLETED BY BVR 27/01/2021.						
RP23	975QWX	34555	01/29/2021	FRIVANA	SERVICE COMPLETED BY BVR 28/01/2021.						
RP23	975QWX	34520	01/29/2021	FRIVANA	1	LABCON	BRIVAL01		4728		LABOUR & CONSUMABLES,RP23
RP23	975QWX	34555	01/29/2021	FRIVANA	1	LABCON	BRIVAL01		4729		LABOUR & CONSUMABLES,RP23

					AIR GAUGE: 18000 ADJUSTED : 19000 WEIGHBRIDGE: 18550							
RP23	975QWX	34466	02/08/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.							
RP23	975QWX	35046	02/23/2021	TRA		0	LABOUR	APPREN	Labour			
					SERVICE COMPLETED BY KEIRAN AND BEN							
RP23	975QWX	35046	02/23/2021	TRA	FITTED BREAKDOWN KIT							
RP23	975QWX	35046	02/23/2021	TRA		0	LABOUR	APPREN	1	85	85	
RP23	975QWX	35046	02/23/2021	TRA		16	CON		YAT	Consumables		
RP23	975QWX	35425	02/25/2021	FRIVANA		1	LABCON		BRIVAL01		EX00017983	LABOUR & CONSUMABLES,RP23
RP23	975QWX	35425	02/25/2021	FRIVANA	SERVICE COMPLETED BY BVR 23/02/2021.							
RP23	975QWX	35425	02/25/2021	FRIVANA		1	LABCON		BRIVAL01		5021	LABOUR & CONSUMABLES,RP23
RP23	975QWX	35151	03/01/2021	FRIVANA		1	LABCON		BRIVAL01		EX00017919	LABOUR & CONSUMABLES,RP23
RP23	975QWX	35151	03/01/2021	FRIVANA	SERVICE COMPLETED BY BVR 25/02/2021.							
RP23	975QWX	35151	03/01/2021	FRIVANA		1	LABCON		BRIVAL01		5096	LABOUR & CONSUMABLES,RP23
RP23	975QWX	35129	03/01/2021	FVGEN		39	CON		BRIVAL01		EX00017915	Consumables ,RP23
RP23	975QWX	35129	03/01/2021	FVGEN		39	LAB		BRIVAL01		EX00017915	Labour,RP23

RP23	975QWX	35129	03/01/2021	FVGEN	SERVICE COMPLETED BY BVR 24/02/2021.					
RP23	975QWX	35129	03/01/2021	FVGEN	39	LAB	BRIVAL01	5081	Labour,RP23	
RP23	975QWX	35129	03/01/2021	FVGEN	39	CON	BRIVAL01	5081	Consumables ,RP23	
RP23	975QWX	35227	03/03/2021	WEICAL	AIR GAUGE: 19800 ADJUSTED: 19400 WEIGHBRIDGE: 19000					
RP23	975QWX	35745	03/08/2021	FRIVANA	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP23	975QWX	35745	03/08/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018130	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	35745	03/08/2021	FRIVANA	SERVICE COMPLETED BY BVR 05/03/2021.					
RP23	975QWX	35745	03/08/2021	FRIVANA	1	LABCON	BRIVAL01	5224	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	35859	03/17/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018196	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	35859	03/17/2021	FRIVANA	SERVICE COMPLETED BY BVR 15/03/2021					
RP23	975QWX	35859	03/17/2021	FRIVANA	1	LABCON	BRIVAL01	5284	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36181	03/18/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018300	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36181	03/18/2021	FRIVANA	SERVICE COMPLETED BY BVR 16/03/2021					
RP23	975QWX	36181	03/18/2021	FRIVANA	1	LABCON	BRIVAL01	5328	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36195	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018301	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36214	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018302	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36236	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018303	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36553	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018452	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36967	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	EX00018588	LABOUR & CONSUMABLES,RP23	
RP23	975QWX	36195	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 17/03/2021					
RP23	975QWX	36214	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 18/03/2021					
RP23	975QWX	36236	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 19/03/2021					
RP23	975QWX	36553	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 18/03/2021					
RP23	975QWX	36195	03/22/2021	FRIVANA	1	LABCON	BRIVAL01	5350	LABOUR & CONSUMABLES,RP23	

RP23	975QWX	36236	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	5376	LABOUR & CONSUMABLES,RP23
RP23	975QWX	36553	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	5351	LABOUR & CONSUMABLES,RP23
RP23	975QWX	36279	03/25/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018304	LABOUR & CONSUMABLES,RP23
RP23	975QWX	36279	03/25/2021	FRIVANA	SERVICE COMPLETED BY BVR 22/03/2021.					
RP23	975QWX	36279	03/25/2021	FRIVANA	1	LABCON		BRIVAL01	5391	LABOUR & CONSUMABLES,RP23
RP23	975QWX	36814	04/14/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018541	LABOUR & CONSUMABLES,RP23
RP23	975QWX	36814	04/14/2021	FRIVANA	SERVICE COMPLETED BY BVR 09/04/2021					
RP23	975QWX	36814	04/14/2021	FRIVANA	1	LABCON		BRIVAL01	5601	LABOUR & CONSUMABLES,RP23
RP23	975QWX	37422	05/07/2021	TRA	0	LABOUR	MECH1	Labour		
					SERVICE COMPLETED BY RYAN REPALCED THE BROKEN TRAILER LIGHT					
RP23	975QWX	37422	05/07/2021	TRA	SOCKET					
RP23	975QWX	37422	05/07/2021	TRA	16	CON		YAT	Consumables	
RP23	975QWX	37422	05/07/2021	TRA	14	82161BL		YAT	7 PIN PLUG TRAILER	
RP23	975QWX	37512	05/10/2021	GEN	0	LABOUR	MECH1	Labour		
					REPAIR COMPLETED BY SEAN R&R RHS FRONT LOWER MARKER					
RP23	975QWX	37512	05/10/2021	GEN	LIGHT					
RP23	975QWX	37512	05/10/2021	GEN	16	CON		YAT	Consumables	
RP23	975QWX	37512	05/10/2021	GEN	14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	37657	05/17/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018924	LABOUR & CONSUMABLES,RP23
RP23	975QWX	37657	05/17/2021	FRIVANA	SERVICE COMPLETED BY BVR 10/05/2021					
RP23	975QWX	37657	05/17/2021	FRIVANA	1	LABCON		BRIVAL01	5930	LABOUR & CONSUMABLES,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	45-2258		BRIVAL01	EX00018918	120 AMP ALTERNATOR,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	44-9181		BRIVAL01	EX00018918	SPEED SOLENOID,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	CON		BRIVAL01	EX00018918	Consumables,RP23

RP23	975QWX	37611	05/17/2021	FVGEN	39	LAB		BRIVAL01	EX00018918	Labour,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	SERVICE COMPLETED BY BVR 10/05/2021					
RP23	975QWX	37611	05/17/2021	FVGEN	39	45-2258		BRIVAL01	5935	120 AMP ALTERNATOR,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	44-9181		BRIVAL01	5935	SPEED SOLENOID,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	CON		BRIVAL01	5935	Consumables,RP23
RP23	975QWX	37611	05/17/2021	FVGEN	39	LAB		BRIVAL01	5935	Labour,RP23
RP23	975QWX	38298	06/08/2021	TRA	0	LABOUR	MECH1	Labour		
RP23	975QWX	38298	06/08/2021	TRA	SERVICE COMPLETED BY SEAN AND BEN CLEANED BREATHER FOR FUEL TANK ADJUSTED RIDE HEIGHT REPLACED RHS REAR INDICATOR					
RP23	975QWX	38298	06/08/2021	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	38298	06/08/2021	TRA	16	CON		YAT	Consumables	
RP23	975QWX	38298	06/08/2021	TRA	14	94800		YAT	Indicator Light LED	
RP23	975QWX	38418	06/10/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019287	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38418	06/10/2021	FRIVANA	SERVICE COMPLETED BY BVR 08/06/2021					
RP23	975QWX	38418	06/10/2021	FRIVANA	1	LABCON		BRIVAL01	6263	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38409	06/10/2021	FVGEN	39	42-0100		BRIVAL01	EX00019282	STOP FUEL SOLENOID, FRIDGE MOTORS,RP23
RP23	975QWX	38409	06/10/2021	FVGEN	39	CON		BRIVAL01	EX00019282	Consumables,RP23
RP23	975QWX	38409	06/10/2021	FVGEN	39	LAB		BRIVAL01	EX00019282	Labour,RP23
RP23	975QWX	38409	06/10/2021	FVGEN	SERVICE COMPLETED BY BVR 08/06/2021					
RP23	975QWX	38409	06/10/2021	FVGEN	39	LAB		BRIVAL01	6247	Labour,RP23

										Consumables
RP23	975QWX	38409	06/10/2021	FVGEN	39	CON		BRIVAL01	6247	,RP23
RP23	975QWX	38409	06/10/2021	FVGEN	39	42-0100		BRIVAL01	6247	STOP FUEL SOLENOID, FRIDGE MOTORS,RP23
RP23	975QWX	38471	06/11/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019295	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38471	06/11/2021	FRIVANA	SERVICE COMPLETED BY BVR 09.06.2021					
RP23	975QWX	38471	06/11/2021	FRIVANA	1	LABCON		BRIVAL01	6300	LABOUR & CONSUMABLES,RP23
										Consumables
RP23	975QWX	38446	06/11/2021	FVGEN	39	CON		BRIVAL01	EX00019292	,RP23
RP23	975QWX	38446	06/11/2021	FVGEN	39	LAB		BRIVAL01	EX00019292	Labour,RP23
RP23	975QWX	38446	06/11/2021	FVGEN	SERVICE COMPLETED BY BVR 09.06.2021					
RP23	975QWX	38446	06/11/2021	FVGEN	39	LAB		BRIVAL01	6284	Labour,RP23
										Consumables
RP23	975QWX	38446	06/11/2021	FVGEN	39	CON		BRIVAL01	6284	,RP23
RP23	975QWX	38477	06/11/2021	GEN	0	LABOUR	APPREN	Labour		
					REPAIR COMPLETED BY KEIRAN REPLACED FRIDGE BATTERIES AS FRIDGE WOULD NOT START AND FITTED MISSING R CLIP MADE NEW ROD FOR BATTERY HOLD DOWN					
RP23	975QWX	38477	06/11/2021	GEN	CLAMP					

RP23	975QWX	38477	06/11/2021	GEN	16	CON		YAT	Consumables	
RP23	975QWX	38477	06/11/2021	GEN	14	MF70ZZDT		YAT	BATTERY DEEP CYCLE & TRUCK	
RP23	975QWX	38596	06/16/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019362	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38596	06/16/2021	FRIVANA	1	LABCON		BRIVAL01	6318	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38706	06/17/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019390	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38747	06/17/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019392	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38706	06/17/2021	FRIVANA	SERVICE COMPLETDED BY BVR 14/06/2021					
RP23	975QWX	38747	06/17/2021	FRIVANA	SERVICE COMPLETDED BY BVR 16/06/2021					
RP23	975QWX	38706	06/17/2021	FRIVANA	1	LABCON		BRIVAL01	6345	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38747	06/17/2021	FRIVANA	1	LABCON		BRIVAL01	6347	LABOUR & CONSUMABLES,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	10-417		BRIVAL01	EX00019389	FILTER KIT (FRIDGE MOTOR),RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	45-2256		BRIVAL01	EX00019389	ALTERNATOR 65 AMP,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	44-9181		BRIVAL01	EX00019389	SPEED SOLENOID,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	CON		BRIVAL01	EX00019389	Consumables,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	LAB		BRIVAL01	EX00019389	Labour,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	SERVICE COMPLETED BY BVR 14/06/2021					
RP23	975QWX	38664	06/17/2021	FRIVANB	39	LAB		BRIVAL01	6343	Labour,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	CON		BRIVAL01	6343	Consumables,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	44-9181		BRIVAL01	6343	SPEED SOLENOID,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	45-2256		BRIVAL01	6343	ALTERNATOR 65 AMP,RP23
RP23	975QWX	38664	06/17/2021	FRIVANB	39	10-417		BRIVAL01	6343	FILTER KIT (FRIDGE MOTOR),RP23
RP23	975QWX	38857	06/17/2021	TYRES	15	77000180		BRIAUS01	EX00019474	CASE STOCK 11-22.5,RP23
RP23	975QWX	38857	06/17/2021	TYRES	15	77000180		BRIAUS01	86056061	CASE STOCK 11-22.5,RP23
RP23	975QWX	39012	06/24/2021	FRIVANA	1	LABCON		BRIVAL01	EX00019550	LABOUR & CONSUMABLES,RP23
RP23	975QWX	39012	06/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 17.06.2021					
RP23	975QWX	39012	06/24/2021	FRIVANA	1	LABCON		BRIVAL01	6339	LABOUR & CONSUMABLES,RP23
RP23	975QWX	39529	07/12/2021	GEN	39	LABOUR	Labour			0
					REPAIR COMPLETED. ESN-86528404					
RP23	975QWX	39529	07/12/2021	GEN	2652960					
RP23	975QWX	39536	07/12/2021	TRA	0	LABOUR	MECH	Labour		
RP23	975QWX	39544	07/12/2021	TRA	0	LABOUR	APPREN	Labour		

RP23	975QWX	39536	07/12/2021	TRA	SERVICE COMPLETED BY KEIRAN AND MICK FITTED SOLAR TRACKER
RP23	975QWX	39544	07/12/2021	TRA	SERVICE COMPLETED BY KEIRAN AND MICK FITTED TRACKER TO ROOF (SOLAR) COULDN'T CHECH INSIDE AS IT WAS LOADED

RP23	975QWX	39536	07/12/2021	TRA	0	LABOUR	APPREN	1	85	85		
RP23	975QWX	39544	07/12/2021	TRA	0	LABOUR	MECH	1	85	85		
RP23	975QWX	39536	07/12/2021	TRA	16	CON	YAT	Consumables				
RP23	975QWX	39544	07/12/2021	TRA	16	CON	YAT	Consumables				
RP23	975QWX	40594	08/03/2021	FRIVANA	1	LABCON	BRIVAL01		EX00020146		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	40594	08/03/2021	FRIVANA	SERVICE COMPLETED BY BVR 03/08/2021							
RP23	975QWX	40594	08/03/2021	FRIVANA	1	LABCON	BRIVAL01		6961		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	41644	08/04/2021	FRIVANA	1	LABCON	BRIVAL01		EX00020474		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	41644	08/04/2021	FRIVANA	SERVICE COMPLTED BY BVR 04/08/2021							
RP23	975QWX	41644	08/04/2021	FRIVANA	1	LABCON	BRIVAL01		6988		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	40776	08/09/2021	FRIVANA	1	LABCON	BRIVAL01		EX00020198		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	40776	08/09/2021	FRIVANA	SERVICE COMPLETED BY BVR 09/08/2021							
RP23	975QWX	40776	08/09/2021	FRIVANA	1	LABCON	BRIVAL01		7052		LABOUR & CONSUMABLES,RP23	
RP23	975QWX	41396	08/23/2021	FRIVANA	1	LABCON	BRIVAL01		EX00020394		LABOUR & CONSUMABLES,RP23	

RP23	975QWX	41396	08/23/2021	FRIVANA	SERVICE COMPLETED BY BVR 23/08/2021					
RP23	975QWX	41396	08/23/2021	FRIVANA	1	LABCON		BRIVAL01	7215	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41339	08/24/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020383	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41339	08/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 24/08/2021					
RP23	975QWX	41339	08/24/2021	FRIVANA	1	LABCON		BRIVAL01	7222	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41668	09/02/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020478	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41668	09/02/2021	FRIVANA	SERVICE COMPLTED BY BVR 02/09/2021					
RP23	975QWX	41668	09/02/2021	FRIVANA	1	LABCON		BRIVAL01	7339	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41829	09/06/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020547	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41829	09/06/2021	FRIVANA	SERVICE COMPLETED BY BVR 06/09/2021					
RP23	975QWX	41829	09/06/2021	FRIVANA	1	LABCON		BRIVAL01	7411	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41857	09/07/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020548	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41857	09/07/2021	FRIVANA	SERVICE COMPLETED BY BVR 07/09/2021					
RP23	975QWX	41857	09/07/2021	FRIVANA	1	LABCON		BRIVAL01	7401	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41780	09/07/2021	GEN	39	PART		DIESER01	EX00020520	GENERAL PART CODE,RP23
RP23	975QWX	41780	09/07/2021	GEN	39	lab		DIESER01	EX00020520	Labour,rp23
RP23	975QWX	41780	09/07/2021	GEN	39	LAB		DIESER01	EX00020520	Labour,rp23
RP23	975QWX	41780	09/07/2021	GEN	39	CON		DIESER01	EX00020520	Consumables,RP23
RP23	975QWX	41780	09/07/2021	GEN	39	CON		DIESER01	26794	Consumables,RP23
RP23	975QWX	41780	09/07/2021	GEN	39	LAB		DIESER01	26794	Labour,rp23
RP23	975QWX	41780	09/07/2021	GEN	39	lab		DIESER01	26794	Labour,rp23
RP23	975QWX	41780	09/07/2021	GEN	39	PART		DIESER01	26794	GENERAL PART CODE,RP23
RP23	975QWX	41591	09/08/2021	EXOINS	1	LABOUR	MECH	Labour		
RP23	975QWX	41591	09/08/2021	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES					

RP23	975QWX	41953	09/08/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020565	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41953	09/08/2021	FRIVANA	SERVICE COMPLETED BY BVR 08/09/2021					
RP23	975QWX	41953	09/08/2021	FRIVANA	1	LABCON		BRIVAL01	7456	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41591	09/08/2021	TRA	1	LABOUR	Labour			0
RP23	975QWX	41591	09/08/2021	TRA	SERVICE COMPLETED.					
RP23	975QWX	41591	09/08/2021	TRB	1	LABOUR	Labour			0
RP23	975QWX	41591	09/08/2021	TRB	SERVICE COMPLETED.					
RP23	975QWX	41591	09/08/2021	TRC	1	LABOUR	Labour			0
					COMPLETED BY DIESEL SERVICES INV: 41591 C&D SERVICE WITH GREASE CLEAN AND RE-PACK BEARINGS REPLACE HUB SEALS, CARRIER ORINGS, DUST COVERS, LOCK WEDGES AND LOCK CLIPS					
RP23	975QWX	41591	09/08/2021	TRC	DEGREASE					
RP23	975QWX	41869	09/09/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020549	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41869	09/09/2021	FRIVANA	SERVICE COMPLETED BY BVR 09/09/2021					
RP23	975QWX	41869	09/09/2021	FRIVANA	1	LABCON		BRIVAL01	7467	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41928	09/10/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020564	LABOUR & CONSUMABLES,RP23
RP23	975QWX	41928	09/10/2021	FRIVANA	SERVICE COMPLETED BY BVR 10/09/2021					
RP23	975QWX	41928	09/10/2021	FRIVANA	1	LABCON		BRIVAL01	7483	LABOUR & CONSUMABLES,RP23

RP23	975QWX	42168	09/16/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020650	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42168	09/16/2021	FRIVANA	SERVICE COMPLETED BY BVR 16/09/2021						
RP23	975QWX	42168	09/16/2021	FRIVANA	1	LABCON		BRIVAL01		7544	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42262	09/17/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020658	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42262	09/17/2021	FRIVANA	SERVICE COMPLETED BY BVR 17/09/2021						
RP23	975QWX	42262	09/17/2021	FRIVANA	1	LABCON		BRIVAL01		7584	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42018	09/21/2021	GEN	39	LAB		RCCLOW01		EX00020590	Labour,975QWX
RP23	975QWX	42072	09/21/2021	GEN	39	5.81E+08		BROHUR01		EX00020624	NUT AND WASHER KIT,RP23
RP23	975QWX	42018	09/21/2021	GEN	39	PART		RCCLOW01		EX00020590	GENERAL PART CODE,975QWX
RP23	975QWX	42072	09/21/2021	GEN	39	5.81E+08		BROHUR01		2290824	NUT AND WASHER KIT,RP23
RP23	975QWX	42018	09/21/2021	GEN	39	PART		RCCLOW01		28196	GENERAL PART CODE,975QWX
RP23	975QWX	42018	09/21/2021	GEN	39	LAB		RCCLOW01		28196	Labour,975QWX
RP23	975QWX	42441	09/28/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020727	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42441	09/28/2021	FRIVANA	SERVICE COMPLETED BY BVR 28/09/2021						
RP23	975QWX	42441	09/28/2021	FRIVANA	1	LABCON		BRIVAL01		7749	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42714	10/06/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020871	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42714	10/06/2021	FRIVANA	SERVICE COMPLETED BY BVR 06/10/2021						
RP23	975QWX	42714	10/06/2021	FRIVANA	1	LABCON		BRIVAL01		7853	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42901	10/11/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020930	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42901	10/11/2021	FRIVANA	SERVICE COMPLTED BY BVR 11/10/2021						
RP23	975QWX	42901	10/11/2021	FRIVANA	1	LABCON		BRIVAL01		7896	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42935	10/14/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020936	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42935	10/14/2021	FRIVANA	SERVICE COMPLETED BY BVR 14/10/2021						
RP23	975QWX	42935	10/14/2021	FRIVANA	1	LABCON		BRIVAL01		7945	LABOUR & CONSUMABLES,RP23
RP23	975QWX	42796	10/14/2021	TRA	0	LABOUR	MECH1	Labour			
RP23	975QWX	42796	10/14/2021	TRA	SERVICE COMPLETED BY SEAN AND BEN R&R LHS FRONT SIDE MARKER LIGHT						
RP23	975QWX	42796	10/14/2021	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	42796	10/14/2021	TRA	16	CON		YAT	Consumables		
RP23	975QWX	42796	10/14/2021	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva		
RP23	975QWX	43731	11/19/2021	GEN	39	CON		BRIVAL01		EX00021348	Consumables,RP23
RP23	975QWX	43731	11/19/2021	GEN	39	LAB		BRIVAL01		EX00021348	Labour,RP23
RP23	975QWX	43731	11/19/2021	GEN	39	LAB		BRIVAL01		8294	Labour,RP23

											Consumables
RP23	975QWX	43731	11/19/2021	GEN	39	CON		BRIVAL01		8294	,RP23
RP23	975QWX	44515	01/05/2022	TRA	1	LABOUR	Labour				0
RP23	975QWX	44515	01/05/2022	TRA	SERVICE COMPLETED KEIRAN						
RP23	975QWX	44515	01/05/2022	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	44515	01/05/2022	TRA	16	CON		YAT	Consumables		
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	PART		BRIVAL01		EX00021998	GENERAL PART CODE,RP23
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	CON		BRIVAL01		EX00021998	Consumables ,RP23
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	LAB		BRIVAL01		EX00021998	Labour,RP23
RP23	975QWX	44651	01/12/2022	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	44651	01/12/2022	FRIVANSE	REPAIR COMPLETED BY BVR 12.01.2022						
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	LAB		BRIVAL01		8798	Labour,RP23
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	CON		BRIVAL01		8798	Consumables ,RP23
RP23	975QWX	44651	01/12/2022	FRIVANSE	39	PART		BRIVAL01		8798	GENERAL PART CODE,RP23
RP23	975QWX	44964	01/31/2022	TRA	0	LABOUR	MECH1	Labour			
RP23	975QWX	44964	01/31/2022	TRA	SERVICE COMPLETED BY IAN *TRAILER HAS ACCIDENT DAMAGED TO L/H SIDE ASKED QUESTION WAS APPARENTLY OLD DAMAGE HUBMETER U/S						

RP23	975QWX	44964	01/31/2022	TRA	16	CON		YAT	Consumables		
RP23	975QWX	46279	03/23/2022	TRA	1	LABOUR	Labour				0
RP23	975QWX	46279	03/23/2022	TRA	SERVICE COMPLETED.						
RP23	975QWX	46279	03/23/2022	TRB	0	LABOUR	APPRENB	Labour			
RP23	975QWX	46279	03/23/2022	TRB	SERVICE COMPLETED BY BEN AND BRENDAN CHECK EBS SYSTEM - NOT EQUIPPED						
RP23	975QWX	46279	03/23/2022	TRB	0	LABOUR	SUBMEC	Labour - Internal			
RP23	975QWX	46279	03/23/2022	TRB	16	CON		YAT	Consumables		
RP23	975QWX	47542	05/12/2022	GEN	39	CON		BRIVAL01		EX00023616	Consumables,RP23
RP23	975QWX	47542	05/12/2022	GEN	39	LAB		BRIVAL01		EX00023616	Labour,RP23
RP23	975QWX	47542	05/12/2022	GEN	SERVICE COMPLETED BY BVR 12.05.2022						
RP23	975QWX	47542	05/12/2022	GEN	39	LAB		BRIVAL01		10616	Labour,RP23
RP23	975QWX	47542	05/12/2022	GEN	39	CON		BRIVAL01		10616	Consumables,RP23
RP23	975QWX	47627	05/17/2022	TRA	0	LABOUR	APPRENK	Labour			
RP23	975QWX	47627	05/17/2022	TRA	SERVICE COMPLETED BY BEN AND BRENDAN REPLACED AMBER PARK LIGHT LHS BOTTOM						

RP23	975QWX	47627	05/17/2022	TRA	0	LABOUR	SUBMEC	Labour - Internal	
RP23	975QWX	47627	05/17/2022	TRA	16	CON		YAT	Consumables
RP23	975QWX	47627	05/17/2022	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva
RP23	975QWX	48111	05/24/2022	WEICAL	AIR GAUGE: 15.500 ADJUSTED : 15.750 WEIGHBRIDGE: 15.280				
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RP23	975QWX	48598	06/28/2022	TRA	0	LABOUR	APPRENB	Labour	
RP23	975QWX	48598	06/28/2022	TRA	SERVICE COMPLETED BY BEN AND BRENDAN				
RP23	975QWX	48598	06/28/2022	TRA	0	LABOUR	SUBMEC	Labour - Internal	
RP23	975QWX	48598	06/28/2022	TRA	16	CON		YAT	Consumables

					AIR GAUGE: 19.250 ADJUSTED : 19.000 WEIGHBRIDGE: 18.600					
RP23	975QWX	48887	06/28/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP23	975QWX	48820	07/05/2022	TYRES		15	77000180		BRIAUS01	EX00024288	CASE STOCK 11-22.5,RP23
RP23	975QWX	48820	07/05/2022	TYRES		15	77000180		BRIAUS01	88003093	CASE STOCK 11-22.5,RP23
RP23	975QWX	50004	08/19/2022	TYRES		15	11004117		BRIAUS01	EX00024796	11R22.5 148/145L FS FT469,RP23
RP23	975QWX	50004	08/19/2022	TYRES		15	33000241		BRIAUS01	EX00024796	SCRAP TYRES TBR,RP23
RP23	975QWX	50004	08/19/2022	TYRES		15	33000241		BRIAUS01	88239684	SCRAP TYRES TBR,RP23
RP23	975QWX	50004	08/19/2022	TYRES		15	11004117		BRIAUS01	88239684	11R22.5 148/145L FS FT469,RP23
RP23	975QWX	50140	08/24/2022	DEFECT		1	LABOUR	MECH	Labour		
RP23	975QWX	50140	08/24/2022	DEFECT							
RP23	975QWX	50140	08/24/2022	DEFECT	DEFECT CLEARED.						

RP23	975QWX	50141	08/24/2022	DEFECT	Reported Defect :- Defect Code : 00007276 Defect Reference : 44964 Date : 31/01/2022 Description of Defect : *TRAILER HAS ACCIDENT DAMAGED TO L/H SIDE ASKED QUESTION WAS APPARENTLY OLD DAMAGE				
RP23	975QWX	50140	08/24/2022	TRA		1	LABOUR	Labour	0
RP23	975QWX	50141	08/24/2022	TRA		1	LABOUR	Labour	0
RP23	975QWX	50140	08/24/2022	TRA	SERVICE COMPLETED.				

RP23	975QWX	50141	08/24/2022	TRA	SERVICE COMPLETED BY MICK AND TYLER * INTERIOR LIGHT NOT WORKING . THINK IT'S A PROBLEM AT THE SWITCH * NEEDS TO GO TO TRAILER SALES FOR INTERNAL REPAIRS - PANEL BEATED LADDER

RP23	975QWX	50141	08/24/2022	TRA	0	LABOUR	MECH	Labour - Internal			
RP23	975QWX	50141	08/24/2022	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	50141	08/24/2022	TRA	16	CON		YAT	Consumables		
RP23	975QWX	50704	09/14/2022	GEN	39	100417		BRIVAL01		EX00025202	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	78-1341		BRIVAL01		EX00025202	SB fridge motor fanbelt,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	91-0373		BRIVAL01		EX00025202	CLAMP TUBE FRIDGE MOTOR,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	91-0372		BRIVAL01		EX00025202	CLAMP TUBE, FRIDGE MOTOR,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	91-4043		BRIVAL01		EX00025202	SNUBBER MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	91-7709		BRIVAL01		EX00025202	VIBRATION MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	91-4159		BRIVAL01		EX00025202	VIBRATION MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	CON		BRIVAL01		EX00025202	Consumables ,RP23
RP23	975QWX	50704	09/14/2022	GEN	39	LAB		BRIVAL01		EX00025202	Labour,RP23

RP23	975QWX	50704	09/14/2022	GEN	COMPLETED BY BVR 14.09.2022 CARRY OUT B SERVICE REMOVE AND REPLACE U/S ALTERNATOR BELT REMOVE AND REPLACE U/S DISCHARGE PIPE CLAMPS REMOVE AND REPLACE U/S ENGINE MOUNTS						
RP23	975QWX	50704	09/14/2022	GEN		39	LAB		BRIVAL01	12236	Labour,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	CON		BRIVAL01	12236	Consumables,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	91-4159		BRIVAL01	12236	VIBRATION MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	91-7709		BRIVAL01	12236	VIBRATION MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	91-4043		BRIVAL01	12236	SNUBBER MOUNT,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	91-0372		BRIVAL01	12236	CLAMP TUBE, FRIDGE MOTOR,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	91-0373		BRIVAL01	12236	CLAMP TUBE FRIDGE MOTOR,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	78-1341		BRIVAL01	12236	SB fridge motor fanbelt,RP23
RP23	975QWX	50704	09/14/2022	GEN		39	100417		BRIVAL01	12236	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	50802	09/19/2022	EXOINS		1	LABOUR	MECH	Labour		

RP23	975QWX	50802	09/19/2022	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES						
RP23	975QWX	50801	09/19/2022	GEN	39	PART		DIESER01	EX00025252	GENERAL PART CODE,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	EX00025252	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	EX00025252	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	EX00025252	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	CON		DIESER01	EX00025252	Consumables,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	CON		DIESER01	27900	Consumables,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	27900	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	27900	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	LAB		DIESER01	27900	Labour,RP23	
RP23	975QWX	50801	09/19/2022	GEN	39	PART		DIESER01	27900	GENERAL PART CODE,RP23	
RP23	975QWX	50801	09/19/2022	TRA	1	LABOUR	MECH	Labour			
RP23	975QWX	50801	09/19/2022	TRA	SERVICE COMPLETED.						
RP23	975QWX	50801	09/19/2022	TRB	1	LABOUR	MECH	Labour			
RP23	975QWX	50801	09/19/2022	TRB	SERVICE COMPLETED.						
RP23	975QWX	50801	09/19/2022	TRC	1	LABOUR	MECH	Labour			

					COMPLETED BY DIESEL SERVICES INV#00027900				
RP23	975QWX	50801	09/19/2022	TRC	COMPLETE C&D SERVICE NO GREASE, CHECK WHEEL BEARING ADJUSTMENT, ADJUST BRAKES, CHECK SUSPENSION POINTS. REPLACE HUBCAP ORING. TENSION				
RP23	975QWX	50801	09/19/2022	TRC		11	2.57E+08	YAT	BPW O Rings

RP23	975QWX	50977	09/29/2022	WEICAL	AIR GAUGE: 19.00 ADJUSTED : 18.60 WEIGHBRIDGE: 18.91						
RP23	975QWX	50977	09/29/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP23	975QWX	51480	10/18/2022	TRA		1	LABOUR	MECH	Labour		
RP23	975QWX	51480	10/18/2022	TRA	SERVICE COMPLETED BY KEIRAN AND TYLER - REPLACED RH FRONT MARKER LIGHT						
RP23	975QWX	51480	10/18/2022	TRA		0	LABOUR	MECH1	Labour - Internal		
RP23	975QWX	51480	10/18/2022	TRA		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	51480	10/18/2022	TRA		16	CON		YAT	Consumables	
RP23	975QWX	51480	10/18/2022	TRA		14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	52113	11/17/2022	TRA		0	LABOUR	APPRENB	Labour		
RP23	975QWX	52113	11/17/2022	TRA	SERVICE COMPLETED BY BEN AND TYLER						
RP23	975QWX	52113	11/17/2022	TRA		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	52113	11/17/2022	TRA		16	CON		YAT	Consumables	
RP23	975QWX	52583	12/05/2022	FVGEN		39	PART		BRIVAL01	EX00026196	452753 YANMAR STARTER MOTOR,RP23

RP23	975QWX	52583	12/05/2022	FVGEN		39	CON		BRIVAL01	EX00026196	Consumables ,RP23
RP23	975QWX	52583	12/05/2022	FVGEN		39	LAB		BRIVAL01	EX00026196	Labour,RP23
RP23	975QWX	52583	12/05/2022	FVGEN	SERVICE COMPLETED BY BVR - 28.11.2022 Travel to site and inspect unit - remove and replace u/s starter motor - unit run on test - pretrip passed						
RP23	975QWX	52583	12/05/2022	FVGEN		39	CON		BRIVAL01	13375	Consumables ,RP23
RP23	975QWX	52583	12/05/2022	FVGEN		39	PART		BRIVAL01	13375	452753 YANMAR STARTER MOTOR,RP23
RP23	975QWX	52583	12/05/2022	FVGEN		39	LAB		BRIVAL01	13375	Labour,RP23
RP23	975QWX	52866	12/19/2022	GEN		0	LABOUR	APPREN	Labour		

RP23	975QWX	52866	12/19/2022	GEN	FLAT BATTERY AND LEGS NOT WINDING PROPERLY REPLACED BATTERY COULD NOT FAULT LEGS REPAIRS COMPLTE D BY TYLER						
RP23	975QWX	52866	12/19/2022	GEN		14	MF70ZZDT	YAT	BATTERY DEEP CYCLE & TRUCK		
RP23	975QWX	52866	12/19/2022	GEN		16	CON	YAT	Consumables		
RP23	975QWX	52936	12/20/2022	TYRES		15	11004117	BRIAUS01		EX00026451	11R22.5 148/145L FS FT469,RP23
RP23	975QWX	52936	12/20/2022	TYRES		15	77000180	BRIAUS01		EX00026451	CASE STOCK 11-22.5,RP23
RP23	975QWX	52936	12/20/2022	TYRES		15	11004117	BRIAUS01		88892253	11R22.5 148/145L FS FT469,RP23
RP23	975QWX	52936	12/20/2022	TYRES		15	77000180	BRIAUS01		88892253	CASE STOCK 11-22.5,RP23
RP23	975QWX	53776	01/22/2023	WEICAL	AIR GAUGE: 18.75 ADJUSTED : 19.50 WEIGHBRI DGE:19.08						
RP23	975QWX	53776	01/22/2023	WEICAL	AIR GAUGE CALIBRATI ON COMPLET ED CORRECTL Y.						

RP23	975QWX	54377	02/21/2023	FVGEN	39	CON	BRIVAL01	EX00027322	Consumables,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	781847	BRIVAL01	EX00027322	Idler Assembly Clutch QTK Fridge,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	772900	BRIVAL01	EX00027322	IDLER ASSEMBLY PLAIN PULLEY,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	772901	BRIVAL01	EX00027322	IDLER ASSEMBLY GROOVED PULLEY,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	781831	BRIVAL01	EX00027322	BELT ENG TO MOTOR SLX400E,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	R404A	BRIVAL01	EX00027322	GAS R404A,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	LAB	BRIVAL01	EX00027322	Labour,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	92-8922	BRIVAL01	EX00027322	Bracket Bottom Block,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	61-8820	BRIVAL01	EX00027322	Valve Throttle Elect,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	77-3189	BRIVAL01	EX00027322	SLX Tensioner,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	77-3065	BRIVAL01	EX00027322	Tensioner Support Brac,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	13-0340TK	BRIVAL01	EX00027322	Tappet Cover Gasket,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	99-0214	BRIVAL01	EX00027322	Unit Mounting Bolts,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	ROCKER ASSEMBLY	BRIVAL01	EX00027322	Rocker Assembly,RP23

RP23	975QWX	54377	02/21/2023	FVGEN	COMPLETED BY BVR - 21.02.2023 21/02/2023 - Travel to site and inspect unit - disconnect fuel lines and wiring - remove panels - remove SB unit off wall - fit SLXI400 to wall (S/N: 500 123 5029) - install compressor belt					
RP23	975QWX	54377	02/21/2023	FVGEN		39	ROCKER ASSEMBLY	BRIVAL01	00014735A	Rocker Assembly,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	99-0214	BRIVAL01	00014735A	Unit Mounting Bolts,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	13-0340TK	BRIVAL01	00014735A	Tappet Cover Gasket,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	77-3065	BRIVAL01	00014735A	Tensioner Support Brac,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	77-3189	BRIVAL01	00014735A	SLX Tensioner,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	61-8820	BRIVAL01	00014735A	Valve Throttle Elect,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	92-8922	BRIVAL01	00014735A	Bracket Bottom Block,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	LAB	BRIVAL01	00014735A	Labour,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	R404A	BRIVAL01	00014735A	GAS R404A,RP23
RP23	975QWX	54377	02/21/2023	FVGEN		39	781831	BRIVAL01	00014735A	BELT ENG TO MOTOR SLX400E,RP23

RP23	975QWX	54377	02/21/2023	FVGEN	39	772901		BRIVAL01	00014735A	IDLER ASSEMBLY GROOVED PULLEY,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	772900		BRIVAL01	00014735A	IDLER ASSEMBLY PLAIN PULLEY,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	781847		BRIVAL01	00014735A	Idler Assembly Clutch QTK Fridge,RP23
RP23	975QWX	54377	02/21/2023	FVGEN	39	CON		BRIVAL01	00014735A	Consumables ,RP23
RP23	975QWX	55262	03/31/2023	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	55262	03/31/2023	DEFECT						
RP23	975QWX	55262	03/31/2023	DEFECT	DEFECT CLEARED.					
RP23	975QWX	55262	03/31/2023	TRA	1	LABOUR	MECH	Labour		
RP23	975QWX	55262	03/31/2023	TRA	SERVICE COMPLETED.					
RP23	975QWX	55262	03/31/2023	TRB	0	LABOUR	MECH 3	Labour		
RP23	975QWX	55262	03/31/2023	TRB	SERVICE COMPLETED. ENTRY LADDER & LOCK REQUIRED REPAIR INTERIOR LIGHT TO BE REPAIRED					
RP23	975QWX	55262	03/31/2023	TRB	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	55262	03/31/2023	TRB	16	CON		YAT	Consumables	
RP23	975QWX	55399	04/05/2023	TYRES	15	11004117		BRIAUS01	EX00027923	11R22.5 148/145L FS FT469,
RP23	975QWX	55399	04/05/2023	TYRES	15	77000180		BRIAUS01	EX00027923	CASE STOCK 11-22.5,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000084		BRIAUS01	EX00027923	FIT TBR TYRE,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000517		BRIAUS01	EX00027923	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000085		BRIAUS01	EX00027923	ROTATE TBR TYRE,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000085		BRIAUS01	89449146	ROTATE TBR TYRE,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000517		BRIAUS01	89449146	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	55399	04/05/2023	TYRES	15	33000084		BRIAUS01	89449146	FIT TBR TYRE,
RP23	975QWX	55399	04/05/2023	TYRES	15	77000180		BRIAUS01	89449146	CASE STOCK 11-22.5,
RP23	975QWX	55399	04/05/2023	TYRES	15	11004117		BRIAUS01	89449146	11R22.5 148/145L FS FT469,

					AIR GAUGE: 8500 ADJUSTED : 8750 WEIGHBRIDGE: 8500				
RP23	975QWX	56426	05/05/2023	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RP23	975QWX	56080	05/08/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	56080	05/08/2023	DEFECT					
RP23	975QWX	56080	05/08/2023	DEFECT	DEFECT CLEARED.				

RP23	975QWX	56080	05/08/2023	DEFECT	Reported Defect :- Defect Code : 00009007 Defect Reference : RP23 Date : 31/03/2023 Description of Defect : ENTRY LADDER & LOCK REQUIRES REPAIRS INTERIOR LIGHT TO BE REPAIRED				
RP23	975QWX	56080	05/08/2023	TRA		0	LABOUR	MECH 3	Labour
RP23	975QWX	56080	05/08/2023	TRA	SERVICE COMPLETED. REPAIRED ENTRY LADDER BRACKET RHS REAR				
RP23	975QWX	56080	05/08/2023	TRA		0	LABOUR	APPRENF	Labour - Internal
RP23	975QWX	56080	05/08/2023	TRA		16	CON		YAT Consumables
RP23	975QWX	57590	06/28/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	57590	06/28/2023	DEFECT					
RP23	975QWX	57590	06/28/2023	DEFECT	DEFECT CLEARED.				

RP23	975QWX	57590	06/28/2023	TRA	0	LABOUR	APPRENF	Labour			
					SERVICE COMPLETED.						
					REPLACED THE AIR BAGS REAR LHS REPLACED TRAILER						
RP23	975QWX	57590	06/28/2023	TRA	LEG RHS						
RP23	975QWX	57590	06/28/2023	TRA	0	LABOUR	MECH 3	Labour - Internal			
RP23	975QWX	57590	06/28/2023	TRA	16	SP0022ASPM		YAT	AIRBAG ASSBLY D36 PLASTIC PISTON		
RP23	975QWX	57590	06/28/2023	TRA	16	PART		YAT	JOST LEG		
RP23	975QWX	57590	06/28/2023	TRA	16	CON		YAT	Consumables		
RP23	975QWX	57626	06/29/2023	TYRES	15	11004117		BRIAUS01		EX00029306	11R22.5 148/145L FS FT469,
RP23	975QWX	57626	06/29/2023	TYRES	15	77000180		BRIAUS01		EX00029306	CASE STOCK 11-22.5,
RP23	975QWX	57626	06/29/2023	TYRES	15	33000084		BRIAUS01		EX00029306	FIT TBR TYRE,
RP23	975QWX	57626	06/29/2023	TYRES	15	33000517		BRIAUS01		EX00029306	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	57626	06/29/2023	TYRES	15	33000517		BRIAUS01		89901185	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	57626	06/29/2023	TYRES	15	33000084		BRIAUS01		89901185	FIT TBR TYRE,
RP23	975QWX	57626	06/29/2023	TYRES	15	77000180		BRIAUS01		89901185	CASE STOCK 11-22.5,
RP23	975QWX	57626	06/29/2023	TYRES	15	11004117		BRIAUS01		89901185	11R22.5 148/145L FS FT469,
RP23	975QWX	58411	07/19/2023	FVGEN	39	CON		BRIVAL01		EX00029705	Consumables ,RP23
RP23	975QWX	58411	07/19/2023	FVGEN	39	LAB		BRIVAL01		EX00029705	Labour,RP23
RP23	975QWX	58411	07/19/2023	FVGEN	Service completed by BVR 19/07/2023 - Travel to site and inspect unit -Relocate evap coil sensor to bottom of coil and insulate as required - Unit run on test						
RP23	975QWX	58411	07/19/2023	FVGEN	39	CON		BRIVAL01		17138	Consumables ,RP23
RP23	975QWX	58411	07/19/2023	FVGEN	39	LAB		BRIVAL01		17138	Labour,RP23
RP23	975QWX	58295	07/25/2023	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	58295	07/25/2023	DEFECT							
RP23	975QWX	58295	07/25/2023	DEFECT	DEFECT CLEARED.						
RP23	975QWX	58295	07/25/2023	DEFECT	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	58295	07/25/2023	DEFECT	Service completed by BVR 17/07/2023 - Carry out B Service as per BVR Specifications - Remove and replace u/s RPM sensor and comp belt - Fit oil drain valve as						
RP23	975QWX	58295	07/25/2023	FRIVANB	0	LABOUR	MECH	Labour			

RP23	975QWX	58295	07/25/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

										Consumab les
RP23	975QWX	58295	07/25/2023	FRIVANB	39	CON		BRIVAL01	EX00029621	,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	CC		BRIVAL01	EX00029621	CALIBRATION CETIFICATE,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	100417		BRIVAL01	EX00029621	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	78-1831		BRIVAL01	EX00029621	GEN SLX Compressor Belt,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	44-9298		BRIVAL01	EX00029621	RPM SENSOR, FRIDGE MOTOR,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	Nov-38		BRIVAL01	EX00029621	VALVE OIL DRAIN,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	LAB		BRIVAL01	EX00029621	Labour,RP23
										Consumab les
RP23	975QWX	58295	07/25/2023	FRIVANB	39	CON		BRIVAL01	17110	,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	CC		BRIVAL01	17110	CALIBRATION CETIFICATE,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	100417		BRIVAL01	17110	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	78-1831		BRIVAL01	17110	GEN SLX Compressor Belt,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	44-9298		BRIVAL01	17110	RPM SENSOR, FRIDGE MOTOR,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	Nov-38		BRIVAL01	17110	VALVE OIL DRAIN,RP23
RP23	975QWX	58295	07/25/2023	FRIVANB	39	LAB		BRIVAL01	17110	Labour,RP23
RP23	975QWX	58295	07/25/2023	FRIVCAL	1	LABOUR	MECH	Labour		
RP23	975QWX	58850	08/14/2023	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	58850	08/14/2023	DEFECT						
RP23	975QWX	58850	08/14/2023	DEFECT	DEFECT CLEARED.					
RP23	975QWX	58850	08/14/2023	TRA	1	LABOUR	MECH 3	Labour		

RP23	975QWX	58850	08/14/2023	TRA	SERVICE COMPLETED BY MATT, NICK & TYLER ON 11/08/2023. REPLACED 3 SIDE CLEARANCE LIGHTS. REPLACED 2 REAR MARKER LIGHTS AT TOP RHS. R&R LH FRONT SPRING EYE BUSH					
RP23	975QWX	58850	08/14/2023	TRA		0	LABOUR	MECH 1	Labour - Internal	
RP23	975QWX	58850	08/14/2023	TRA		0	LABOUR	APPREN	Labour - Internal	
RP23	975QWX	58850	08/14/2023	TRA		16	CON		YAT	Consumables
RP23	975QWX	58850	08/14/2023	TRA		14	91700BL		YAT	Clearance Light, LED Amber, Narva
RP23	975QWX	58850	08/14/2023	TRA		14	91632		YAT	LED Marker Light, Red. Narva
RP23	975QWX	58850	08/14/2023	TRA		16	CON		YAT	65MM SPRING BUSH
RP23	975QWX	59044	08/17/2023	DEFECT		1	LABOUR	MECH	Labour	
RP23	975QWX	59044	08/17/2023	DEFECT						
RP23	975QWX	59044	08/17/2023	DEFECT	DEFECT CLEARED.					
RP23	975QWX	59044	08/17/2023	GEN		39	LABOUR	MECH 3	Labour	

RP23	975QWX	59044	08/17/2023	GEN	REPAIR COMPLETED ON 17/08/2023 BY MATT & JOSEPH. CHECK FOR AIR LEAKS, CHECK FOR DRAGGING SHOES, CHECK AIRBAGS FOR LEAKS AND ADJUST BRAKES..					
RP23	975QWX	59044	08/17/2023	GEN		0	LABOUR	APPRENJ	Labour - Internal	
RP23	975QWX	59044	08/17/2023	GEN		16	CON		YAT	CONSUMABLES
RP23	975QWX	59886	09/12/2023	WEICAL	AIR GAUGE: 19250 ADJUSTED: 19750 WEIGHBRIDGE: 19500 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					

RP23	975QWX	59943	09/18/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	59943	09/18/2023	DEFECT					
RP23	975QWX	59943	09/18/2023	DEFECT	DEFECT CLEARED.				
RP23	975QWX	59943	09/18/2023	TRA		1	LABOUR	APPRENB	Labour
RP23	975QWX	59943	09/18/2023	TRA	SERVICE COMPLETED BY BEN ON 14/09/2023.				
RP23	975QWX	59943	09/18/2023	TRA		16	CON	YAT	Consumables
RP23	975QWX	60409	09/18/2023	WEICAL	AIR GAUGE: 17700 ADJUSTED: 17700 WEIGHBRIDGE: 17320 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RP23	975QWX	60601	10/09/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	60602	10/09/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	60601	10/09/2023	DEFECT					
RP23	975QWX	60602	10/09/2023	DEFECT					
RP23	975QWX	60601	10/09/2023	DEFECT	DEFECT CLEARED.				
RP23	975QWX	60602	10/09/2023	DEFECT	DEFECT CLEARED.				
RP23	975QWX	60602	10/09/2023	EXOINS		1	LABOUR	MECH	Labour

RP23	975QWX	60602	10/09/2023	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY NQFM ON 25/09/2023 INVOICE NO. 35806 NO DEFECTS FOUND					
RP23	975QWX	60602	10/09/2023	EXOINS		2	PART	YAT	BRAKE SHOE SETS	
RP23	975QWX	60602	10/09/2023	EXOINS		1	LABEXT	RCCLOW01	EX00030785	CARRY OUT C & D SERVICE WITH BEARINGS,
RP23	975QWX	60602	10/09/2023	EXOINS		39	LABEXT	RCCLOW01	EX00030785	INSPECT ALL LIGHTS AND REPAIR AS REQUIRED,
RP23	975QWX	60602	10/09/2023	EXOINS		1	CON	RCCLOW01	EX00030785	HUB CAP O-RINGS,
RP23	975QWX	60602	10/09/2023	EXOINS		1	PART	RCCLOW01	EX00030785	BEARING KITS,
RP23	975QWX	60602	10/09/2023	EXOINS		39	PART	RCCLOW01	EX00030785	LED SIDE MARKER AMBER,
RP23	975QWX	60602	10/09/2023	EXOINS		1	2.57E+08	RCCLOW01	EX00030785	BPW ECO GREASE,
RP23	975QWX	60602	10/09/2023	EXOINS		16	CON	RCCLOW01	EX00030785	DEGREASING FLUID,
RP23	975QWX	60602	10/09/2023	EXOINS		16	CON	RCCLOW01	EX00030785	FILTER AND OIL DISPOSAL, Consumables,
RP23	975QWX	60602	10/09/2023	EXOINS		16	ENVLEV	RCCLOW01	EX00030785	ENVIRONMENTAL LEVY,
RP23	975QWX	60602	10/09/2023	EXOINS		16	ENVLEV	RCCLOW01	35806	ENVIRONMENTAL LEVY,

										Consumables
RP23	975QWX	60602	10/09/2023	EXOINS	16	CON		RCCLOW01	35806	,
RP23	975QWX	60602	10/09/2023	EXOINS	16	CON		RCCLOW01	35806	FILTER AND OIL DISPOSAL,
RP23	975QWX	60602	10/09/2023	EXOINS	16	CON		RCCLOW01	35806	DEGREASING FLUID,
RP23	975QWX	60602	10/09/2023	EXOINS	1	2.57E+08		RCCLOW01	35806	BPW ECO GREASE,
RP23	975QWX	60602	10/09/2023	EXOINS	39	PART		RCCLOW01	35806	LED SIDE MARKER AMBER,
RP23	975QWX	60602	10/09/2023	EXOINS	1	PART		RCCLOW01	35806	BEARING KITS,
RP23	975QWX	60602	10/09/2023	EXOINS	1	CON		RCCLOW01	35806	HUB CAP O-RINGS,
RP23	975QWX	60602	10/09/2023	EXOINS	39	LABEXT		RCCLOW01	35806	INSPECT ALL LIGHTS AND REPAIR AS REQUIRED,
RP23	975QWX	60602	10/09/2023	EXOINS	1	LABEXT		RCCLOW01	35806	CARRY OUT C & D SERVICE WITH BEARINGS,
RP23	975QWX	60601	10/09/2023	TRA	1	LABOUR	MECH	Labour		
RP23	975QWX	60601	10/09/2023	TRA	SERVICE COMPLETED.					
RP23	975QWX	60601	10/09/2023	TRB	1	LABOUR	MECH	Labour		
RP23	975QWX	60601	10/09/2023	TRB	SERVICE COMPLETED.					
RP23	975QWX	60601	10/09/2023	TRC	1	LABOUR	MECH	Labour		
RP23	975QWX	60601	10/09/2023	TRC	COMPLETED BY NQFM ON 25/09/2023. INVOICE NO. 35806 Carry out C & D service on vehicle as required Removed all hubs, bearings and cups. Cleaned all hubs and refit new bearings and cups. Removed all brake shoes and					

RP23	975QWX	61106	10/20/2023	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	61106	10/20/2023	DEFECT					
RP23	975QWX	61106	10/20/2023	DEFECT	DEFECT CLEARED. Reported Defect :- Defect Code : 00007928 Defect Reference : WO 50141 Date : 24/08/2022 Description of Defect : * INTERIOR LIGHT NOT WORKING . THINK IT'S A PROBLEM AT THE SWITCH				
RP23	975QWX	61106	10/20/2023	DEFECT	DEFECT CLEARED				

RP23	975QWX	61106	10/20/2023	TRA	1	LABOUR	MECH 3	Labour	
RP23	975QWX	61106	10/20/2023	TRA	SERVICE COMPLETED BY MATT & FLYNN ON 20/10/2023. REPAIR INTERIOR LIGHT CIRCUIT AND FIT NEW SWITCH CARRY OUT A-SERVICE REPLACE RH CENTRE AXLE LOCK TAB (DAMAGED)				
RP23	975QWX	61106	10/20/2023	TRA	0	LABOUR	APPRENF	Labour - Internal	
RP23	975QWX	61106	10/20/2023	TRA	16	CON		YAT	Consumables
RP23	975QWX	61106	10/20/2023	TRA	16	CON		YAT	BPW CLUTCH NUT
RP23	975QWX	61106	10/20/2023	TRA	16	CON		YAT	WEATHERPROOF SWITCH
RP23	975QWX	61972	11/14/2023	DEFECT	1	LABOUR	MECH	Labour	
RP23	975QWX	61972	11/14/2023	DEFECT					
RP23	975QWX	61972	11/14/2023	DEFECT	DEFECT CLEARED.				
RP23	975QWX	61972	11/14/2023	TRA	1	LABOUR	MECH	Labour	

RP23	975QWX	61972	11/14/2023	TRA	COMPLETED BY NQFM ON 14/11/2023 INVOICE NO. 36100 Carry out A service on trailer as required Remove and replace right hand middle leaking airbag Inspect lights found left hand rear side light unservice				
RP23	975QWX	61972	11/14/2023	TRA	1	LABEXT	RCCLOW01	EX00031438	CARRY OUT 'A' SERVICE ON TRAILER,
RP23	975QWX	61972	11/14/2023	TRA	39	LABEXT	RCCLOW01	EX00031438	REMOVE & REPLACE RIGHT HAND MIDDLE LEAKING AIRBAG,
RP23	975QWX	61972	11/14/2023	TRA	39	LABEXT	RCCLOW01	EX00031438	INSPECT LIGHTS, FOUND LH REAR SIDE LIGHT UNSERVICABLE.,REMOVED, REPLA(
RP23	975QWX	61972	11/14/2023	TRA	10	AIRBAG	RCCLOW01	EX00031438	AIRBAG,
RP23	975QWX	61972	11/14/2023	TRA	31	PART	RCCLOW01	EX00031438	LED SIDE MARKER,
RP23	975QWX	61972	11/14/2023	TRA	16	CON	RCCLOW01	EX00031438	Consumables,
RP23	975QWX	61972	11/14/2023	TRA	16	ENVLEV	RCCLOW01	EX00031438	ENVIRONMENTAL LEVY,
RP23	975QWX	61972	11/14/2023	TRA	16	ENVLEV	RCCLOW01	36100	ENVIRONMENTAL LEVY,

											Consumab les
RP23	975QWX	61972	11/14/2023	TRA	16	CON		RCCLOW01		36100	,
RP23	975QWX	61972	11/14/2023	TRA	31	PART		RCCLOW01		36100	LED SIDE MARKER,
RP23	975QWX	61972	11/14/2023	TRA	10	AIRBAG		RCCLOW01		36100	AIRBAG,
RP23	975QWX	61972	11/14/2023	TRA	39	LABEXT		RCCLOW01		36100	INSPECT LIGHTS, FOUND LH REAR SIDE LIGHT UNSERVICABLE.,REMOVED, REPLA(
RP23	975QWX	61972	11/14/2023	TRA	39	LABEXT		RCCLOW01		36100	REMOVE & REPLACE RIGHT HAND MIDDLE LEAKING AIRBAG,
RP23	975QWX	61972	11/14/2023	TRA	1	LABEXT		RCCLOW01		36100	CARRY OUT 'A' SERVICE ON TRAILER,
RP23	975QWX	63213	01/03/2024	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	63213	01/03/2024	DEFECT							
RP23	975QWX	63213	01/03/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	63213	01/03/2024	TRA	1	LABOUR	APPREN	Labour			
RP23	975QWX	63213	01/03/2024	TRA	SERVICE COMPLETED BY TYLER, BEN, JOE & MICK ON 03/01/2024. FOUND A SHORT CIRCUIT IN THE RHT CLEARANCE LIGHT CAUSING ALL LIGHTS AT TOP TO GO OUT.						
RP23	975QWX	63213	01/03/2024	TRA	0	LABOUR	APPRENB	Labour - Internal			
RP23	975QWX	63213	01/03/2024	TRA	0	LABOUR	APPRENJ	Labour - Internal			
RP23	975QWX	63213	01/03/2024	TRA	0	LABOUR	MECH	Labour - Internal			
RP23	975QWX	63213	01/03/2024	TRA	16	CON		YAT	Consumables		
RP23	975QWX	63750	01/19/2024	TYRES	15	11002822		BRIAUS01		EX00032357	11R2.5 148L 16 BS R168,OWN STOCK
RP23	975QWX	63750	01/19/2024	TYRES	15	99015526		BRIAUS01		EX00032357	RUNOUT TYRE,
RP23	975QWX	63750	01/19/2024	TYRES	15	77000180		BRIAUS01		EX00032357	CASE STOCK 11-22.5,
RP23	975QWX	63750	01/19/2024	TYRES	15	33000084		BRIAUS01		EX00032357	FIT TBR TYRE,

RP23	975QWX	63750	01/19/2024	TYRES		15	33000517		BRIAUS01	EX00032357	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	63750	01/19/2024	TYRES		15	33000118		BRIAUS01	EX00032357	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	63750	01/19/2024	TYRES		15	11002822		BRIAUS01	1.88E+08	11R2.5 148L 16 BS R168,OWN STOCK
RP23	975QWX	63750	01/19/2024	TYRES		15	99015526		BRIAUS01	1.88E+08	RUNOUT TYRE,
RP23	975QWX	63750	01/19/2024	TYRES		15	77000180		BRIAUS01	1.88E+08	CASE STOCK 11-22.5,
RP23	975QWX	63750	01/19/2024	TYRES		15	33000084		BRIAUS01	1.88E+08	FIT TBR TYRE,
RP23	975QWX	63750	01/19/2024	TYRES		15	33000517		BRIAUS01	1.88E+08	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	63750	01/19/2024	TYRES		15	33000118		BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	64247	01/23/2024	DEFECT		1	LABOUR	MECH	Labour		
RP23	975QWX	64247	01/23/2024	DEFECT							
RP23	975QWX	64247	01/23/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	64247	01/23/2024	FRIVANB		0	LABOUR	MECH	Labour		
					VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL							
RP23	975QWX	64247	01/23/2024	FRIVANB	R+R						

RP23	975QWX	64247	01/23/2024	FRIVANB	--, --, -- 24 - CARRY OUT B SERVICE AS PER SPECIFICA TIONS REMOVE BELTS AND CHECK ALL PULLEYS AND BEARINGS - REMOVE CROSS SHAFT ASSEMBLY AND REPLACE BEARINGS . REMOVE FAN BELT TENSIONE R

RP23	975QWX	64247	01/23/2024	FRIVANB	OUT B SERVICE AS PER BCR SPECIFICATIONS 23/01/2024 REMOVE BELTS AND CHECK ALL PULLEYS AND BEARINGS . REMOVE CROSS SHAFT ASSEMBLY ANS REPLACE BEARINGS - REMOVE FAN BELT TENSIONE						
RP23	975QWX	64247	01/23/2024	FRIVANB		40	3413005	YAT	OIL 15W-40, CK 4/E9		
RP23	975QWX	64247	01/23/2024	FRIVANB		39	CON	BRIVAL01		EX00032613	Consumables,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	CC	BRIVAL01		EX00032613	CALIBRATION CETIFICATE,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	10-417	BRIVAL01		EX00032613	FILTER KIT (FRIDGE MOTOR),
RP23	975QWX	64247	01/23/2024	FRIVANB		39	77-3125	BRIVAL01		EX00032613	CROSS SHAFT BEARING,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	PART	BRIVAL01		EX00032613	1/4 CAP,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	R404A	BRIVAL01		EX00032613	GAS R404A,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	LAB	BRIVAL01		EX00032613	Labour,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	77-3124	BRIVAL01		EX00032613	IDLER BEARING,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	CON	BRIVAL01		INV-00019580	Consumables,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	CC	BRIVAL01		INV-00019580	CALIBRATION CETIFICATE,
RP23	975QWX	64247	01/23/2024	FRIVANB		39	10-417	BRIVAL01		INV-00019580	FILTER KIT (FRIDGE MOTOR),

RP23	975QWX	64247	01/23/2024	FRIVANB	39	77-3125		BRIVAL01	INV-00019580	CROSS SHAFT BEARING,
RP23	975QWX	64247	01/23/2024	FRIVANB	39	PART		BRIVAL01	INV-00019580	1/4 CAP,
RP23	975QWX	64247	01/23/2024	FRIVANB	39	R404A		BRIVAL01	INV-00019580	GAS R404A,
RP23	975QWX	64247	01/23/2024	FRIVANB	39	LAB		BRIVAL01	INV-00019580	Labour,
RP23	975QWX	64247	01/23/2024	FRIVANB	39	77-3124		BRIVAL01	INV-00019580	IDLER BEARING,
RP23	975QWX	64247	01/23/2024	FRIVCAL	1	LABOUR	MECH	Labour		
RP23	975QWX	64410	02/09/2024	DEFECT						
RP23	975QWX	64410	02/09/2024	DEFECT	DEFECT CLEARED. Defect :- Defect Code : 00008983 Defect Reference : 11828A Date : 26/03/2023 Description of Defect : HAS A DRY WIND IN FRIDGE MOTOR SOMETIMES DEFECT CLEARED 09/02/2024 FRIDGE SOUNDS FINE AND						
RP23	975QWX	64410	02/09/2024	TRA	1	LABOUR	APPRENB	Labour		

RP23	975QWX	64410	02/09/2024	TRA	SERVICE COMPLETED BY BEN ON 09/02/2024. FRIDGE SOUNDS FINE AND RUNNING OKAY (OLD DEFECT)					
RP23	975QWX	64410	02/09/2024	TRA		16	CON		YAT	Consumables
RP23	975QWX	64970	02/23/2024	WEICAL	AIR GAUGE: 19250 ADJUSTED: 19350 WEIGHBRIDGE: 19080 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP23	975QWX	65435	03/14/2024	DEFECT		1	LABOUR	MECH	Labour	
RP23	975QWX	65435	03/14/2024	DEFECT						
RP23	975QWX	65435	03/14/2024	DEFECT	DEFECT CLEARED.					
RP23	975QWX	65435	03/14/2024	TRA		1	LABOUR	MECH 4	Labour	

RP23	975QWX	65435	03/14/2024	TRA	SERVICE COMPLETED BY ETHAN & JOSEPH ON 14/03/2024. REPLACED RHS FRONT LIGHT						
RP23	975QWX	65435	03/14/2024	TRA		0	LABOUR	APPRENJ	Labour - Internal		
RP23	975QWX	65435	03/14/2024	TRA		16	CON		YAT	Consumables	
RP23	975QWX	65435	03/14/2024	TRA		14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP23	975QWX	66181	03/29/2024	WEICAL	AIR GAUGE: 18500 ADJUSTED: 18500 WEIGHBRIDGE: 18200						
RP23	975QWX	66225	04/09/2024	DEFECT	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.	1	LABOUR	MECH	Labour		
RP23	975QWX	66225	04/09/2024	DEFECT							
RP23	975QWX	66225	04/09/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	66281	04/09/2024	FVGEN		39	CON		BRIVAL01	EX00033803	Consumables,RP23
RP23	975QWX	66281	04/09/2024	FVGEN		39	LAB		BRIVAL01	EX00033803	Labour,RP23
RP23	975QWX	66281	04/09/2024	FVGEN		39	41-7852		BRIVAL01	EX00033803	SLX Damper Motor,RP23

RP23	975QWX	66281	04/09/2024	FVGEN	Service completed by BVR 09/04/2024 - Travel to site and inspect unit for reported damper circuit alarm code - Remove and replace u/s damper motor - Test dar						
RP23	975QWX	66281	04/09/2024	FVGEN		39	CON		BRIVAL01	INV-00020600	Consumables ,RP23
RP23	975QWX	66281	04/09/2024	FVGEN		39	LAB		BRIVAL01	INV-00020600	Labour,RP23
RP23	975QWX	66281	04/09/2024	FVGEN		39	41-7852		BRIVAL01	INV-00020600	SLX Damper Motor,RP23
RP23	975QWX	66225	04/09/2024	TRA		1	LABOUR	APPRENT2	Labour		
RP23	975QWX	66225	04/09/2024	TRA	'A' SERVICE COMPLETED BY TYSON & JOSEPH ON 09/04/2024.						
RP23	975QWX	66225	04/09/2024	TRA		0	LABOUR	APPRENJ	Labour - Internal		
RP23	975QWX	66225	04/09/2024	TRA		16	CON		YAT	Consumables	
RP23	975QWX	66928	05/09/2024	DEFECT		1	LABOUR	MECH	Labour		
RP23	975QWX	66928	05/09/2024	DEFECT							
RP23	975QWX	66928	05/09/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	66928	05/09/2024	TRA		1	LABOUR	MECH	Labour		
RP23	975QWX	66928	05/09/2024	TRA	SERVICE COMPLETED.						
RP23	975QWX	66928	05/09/2024	TRB	SERVICE COMPLETED BY WORKSHOP 09/05/2024	0	LABOUR	MECH 4	Labour		
RP23	975QWX	66928	05/09/2024	TRB	RIVITED F TRACKS ON IN TRAILER.						
RP23	975QWX	66928	05/09/2024	TRB		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	66928	05/09/2024	TRB		16	CON		YAT	Consumables	
RP23	975QWX	67060	05/10/2024	GEN		15	11002821		BRIAUS01	EX00034199	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	67060	05/10/2024	GEN		15	77000232		BRIAUS01	EX00034199	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	67060	05/10/2024	GEN		15	33000084		BRIAUS01	EX00034199	FIT TBR TYRE,
RP23	975QWX	67060	05/10/2024	GEN		15	33000517		BRIAUS01	EX00034199	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	67060	05/10/2024	GEN		15	33000085		BRIAUS01	EX00034199	ROTATE TBR TYRE,
RP23	975QWX	67060	05/10/2024	GEN		15	33000118		BRIAUS01	EX00034199	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	67060	05/10/2024	GEN		15	11002821		BRIAUS01	1.89E+08	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	67060	05/10/2024	GEN		15	77000232		BRIAUS01	1.89E+08	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	67060	05/10/2024	GEN		15	33000084		BRIAUS01	1.89E+08	FIT TBR TYRE,
RP23	975QWX	67060	05/10/2024	GEN		15	33000517		BRIAUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	67060	05/10/2024	GEN		15	33000085		BRIAUS01	1.89E+08	ROTATE TBR TYRE,
RP23	975QWX	67060	05/10/2024	GEN		15	33000118		BRIAUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,

RP23	975QWX	67395	05/22/2024	FVGEN		39	CON	BRIVAL01	EX00034376	Consumables,
RP23	975QWX	67395	05/22/2024	FVGEN		39	LAB	BRIVAL01	EX00034376	Labour,
RP23	975QWX	67395	05/22/2024	FVGEN		39	CON	BRIVAL01	INV-00021128	Consumables,
RP23	975QWX	67395	05/22/2024	FVGEN		39	LAB	BRIVAL01	INV-00021128	Labour,
RP23	975QWX	67930	05/29/2024	WEICAL	AIR GAUGE: 19500 ADJUSTED: 19500 WEIGHBRIDGE: 19140					
RP23	975QWX	70672	06/07/2024	CONCLE	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
					FRIDGE MOTOR CONDENSOR CLEAN COMPLETED ON					
					AT LOCATION:					

RP23	975QWX	70672	06/07/2024	DEFECT	1	LABOUR	MECH	Labour	
RP23	975QWX	70672	06/07/2024	DEFECT					
RP23	975QWX	70672	06/07/2024	DEFECT	DEFECT CLEARED.				
					TRAILER SANITISATION COMPLETED ON 07/06/2024				
RP23	975QWX	70672	06/07/2024	SANI	AT LOCATION : YATALA				
RP23	975QWX	68115	06/10/2024	DEFECT	1	LABOUR	MECH	Labour	
RP23	975QWX	68115	06/10/2024	DEFECT					
RP23	975QWX	68115	06/10/2024	DEFECT	DEFECT CLEARED.				
RP23	975QWX	68115	06/10/2024	TRA	1	LABOUR	MECH 5	Labour	
					'A' SERVICE COMPLETED BY BEN & ETHAN ON 10/06/2024. REPLACED MARKER				
RP23	975QWX	68115	06/10/2024	TRA	LIGHT LHS				
RP23	975QWX	68115	06/10/2024	TRA	0	LABOUR	MECH 4	Labour - Internal	
RP23	975QWX	68115	06/10/2024	TRA	16	CON		YAT	Consumables
RP23	975QWX	68115	06/10/2024	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva

RP23	975QWX	68282	06/14/2024	WEICAL	AIR GAUGE: 14000 ADJUSTED : 14750 WEIGHBRIDGE: 14380					
RP23	975QWX	68282	06/14/2024	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP23	975QWX	69001	07/08/2024	DEFECT		1	LABOUR	MECH	Labour	
RP23	975QWX	69001	07/08/2024	DEFECT						
RP23	975QWX	69001	07/08/2024	DEFECT	DEFECT CLEARED.					
RP23	975QWX	69001	07/08/2024	GEN		39	LABOUR	MECH 4	Labour	
RP23	975QWX	69001	07/08/2024	GEN	REPAIR COMPLETED BY WORKSHOP 08/07/2024					
RP23	975QWX	69001	07/08/2024	GEN	REMOVED AND REPLACED 1M OF TRCK INSIDE TRAILER					
RP23	975QWX	69001	07/08/2024	GEN		16	CON	YAT	Consumables	
RP23	975QWX	69001	07/08/2024	GEN		16	STEEL	YAT	STEEL MATERIALS	

RP23	975QWX	71355	07/08/2024	WASH	TRAILER WASH COMPLETED ON 08/07/2024 AT LOCATION : YATALA				
RP23	975QWX	71569	07/22/2024	SANI	TRAILER SANITISATION COMPLETED ON 22/07/2024 AT LOCATION : TULLY				
RP23	975QWX	71570	07/22/2024	WASH	TRAILER WASH COMPLETED ON 22/07/2024 AT LOCATION : TULLY				
RP23	975QWX	69476	07/26/2024	DEFECT		1	LABOUR	MECH	Labour
RP23	975QWX	69476	07/26/2024	DEFECT					
RP23	975QWX	69476	07/26/2024	DEFECT	DEFECT CLEARED.				

RP23	975QWX	69476	07/26/2024	DEFECT	Defect :- Defect Code : 00011377 Defect Reference : RP23 Date : 02/05/2024 Description of Defect : NOT TRACKING. PLEASE CHECK TRACKER OPERATION. DEFECT CLEARED ON 24/07/2024 TRAILER IS				
RP23	975QWX	69476	07/26/2024	TRA		1	LABOUR	MECH 1	Labour

RP23	975QWX	69476	07/26/2024	TRA	'A' SERVICE COMPLETED BY NICK, JOSEPH, JOSH & BEN (WORKSHOP) ON 24/07/2024. TRAILER IS TRACKING REPLACED FRONT AXLE SPRING EYE BUSHES BOTH LEFT AND RIGHT SIDE							
RP23	975QWX	69476	07/26/2024	TRA	0	LABOUR	APPRENJ	Labour - Internal				
RP23	975QWX	69476	07/26/2024	TRA	0	LABOUR	APPRENJC	Labour - Internal				
RP23	975QWX	69476	07/26/2024	TRA	0	LABOUR	MECH 5	Labour - Internal				
RP23	975QWX	69476	07/26/2024	TRA	16	CON		YAT	Consumables			
RP23	975QWX	69459	07/26/2024	TYRES	15	11002821		BRIAUS01		EX00035448	11R22.5 148/145L BS R119 ECO,	
RP23	975QWX	69459	07/26/2024	TYRES	15	77000232		BRIAUS01		EX00035448	CASE STOCK 11R22.5 ECOPIA,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000084		BRIAUS01		EX00035448	FIT TBR TYRE,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33001507		BRIAUS01		EX00035448	CUSTOMER SCRAPPED OWN TYRE,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000517		BRIAUS01		EX00035448	REMOVAL: CUSTOMER PULL POINT,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000522		BRIAUS01		EX00035448	REMOVAL: PUNCTURED,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000085		BRIAUS01		EX00035448	ROTATE TBR TYRE,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000118		BRIAUS01		EX00035448	SCHEDULED DEPOT SERVICE 15MIN,	
RP23	975QWX	69459	07/26/2024	TYRES	15	11002821		BRIAUS01		1.89E+08	11R22.5 148/145L BS R119 ECO,	
RP23	975QWX	69459	07/26/2024	TYRES	15	77000232		BRIAUS01		1.89E+08	CASE STOCK 11R22.5 ECOPIA,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000084		BRIAUS01		1.89E+08	FIT TBR TYRE,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33001507		BRIAUS01		1.89E+08	CUSTOMER SCRAPPED OWN TYRE,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000517		BRIAUS01		1.89E+08	REMOVAL: CUSTOMER PULL POINT,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000522		BRIAUS01		1.89E+08	REMOVAL: PUNCTURED,	
RP23	975QWX	69459	07/26/2024	TYRES	15	33000085		BRIAUS01		1.89E+08	ROTATE TBR TYRE,	

RP23	975QWX	69459	07/26/2024	TYRES	15	33000118		BRIAUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,	
RP23	975QWX	69553	07/31/2024	FRIVANB	0	LABOUR	MECH	Labour			
				VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL							
RP23	975QWX	69553	07/31/2024	FRIVANB	R+R						

									Consumab les
RP23	975QWX	69553	07/31/2024	FRIVANB	39	CON	BRIVAL01	EX00035504	,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	CC	BRIVAL01	EX00035504	CALIBRATION CETIFICATE,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	100417	BRIVAL01	EX00035504	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	91-8972	BRIVAL01	EX00035504	ISOLATOR SNUBBER,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	42-0100	BRIVAL01	EX00035504	STOP FUEL SOLENOID, FRIDGE MOTORS,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	33-2230	BRIVAL01	EX00035504	SOLENOID O-RING FRIDGE MOTORS,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	78-1968	BRIVAL01	EX00035504	GEN Water Pump Belt,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	1/4" Fuel Line	BRIVAL01	EX00035504	1/4" Fuel Line,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	Comp Fuel Fitting	BRIVAL01	EX00035504	1/4" Compressio Fuel Fitting,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	LAB	BRIVAL01	EX00035504	Labour,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	40	3413005	YAT	OIL 15W-40, CK 4/E9	
RP23	975QWX	69553	07/31/2024	FRIVANB	Service completed by BVR 24/07/2024 - Carry out B Service as per BVR Specifications - Remove and replace leaking fuel solenoid - Found engine had a lot of mov				

									Consumab les
RP23	975QWX	69553	07/31/2024	FRIVANB	39	CON	BRIVAL01	INV-00022106	,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	CC	BRIVAL01	INV-00022106	CALIBRATION CETIFICATE,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	100417	BRIVAL01	INV-00022106	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	91-8972	BRIVAL01	INV-00022106	ISOLATOR SNUBBER,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	42-0100	BRIVAL01	INV-00022106	STOP FUEL SOLENOID, FRIDGE MOTORS,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	33-2230	BRIVAL01	INV-00022106	SOLENOID O-RING FRIDGE MOTORS,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	78-1968	BRIVAL01	INV-00022106	GEN Water Pump Belt,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	1/4" Fuel Line	BRIVAL01	INV-00022106	1/4" Fuel Line,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	Comp Fuel Fitting	BRIVAL01	INV-00022106	1/4" Compressio Fuel Fitting,RP23
RP23	975QWX	69553	07/31/2024	FRIVANB	39	LAB	BRIVAL01	INV-00022106	Labour,RP23
RP23	975QWX	69553	07/31/2024	FRIVCAL	1	LABOUR MECH	Labour		
									Consumab les
RP23	975QWX	70422	08/22/2024	FVGEN	39	CON	BRIVAL01	EX00035938	,RP23
RP23	975QWX	70422	08/22/2024	FVGEN	39	78-1945	BRIVAL01	EX00035938	SLX TOP BELT,RP23
RP23	975QWX	70422	08/22/2024	FVGEN	39	LAB	BRIVAL01	EX00035938	Labour,RP23
RP23	975QWX	70422	08/22/2024	FVGEN	Service completed by BVR 22/08/2024 - Travel to site and inspect unit for reported noisy belt - Traced to worn fan belt - Remove centre panel - Remove and repl				

											Consumab les
RP23	975QWX	70422	08/22/2024	FVGEN	39	CON		BRIVAL01		INV-00022538	,RP23
RP23	975QWX	70422	08/22/2024	FVGEN	39	78-1945		BRIVAL01		INV-00022538	SLX TOP BELT,RP23
RP23	975QWX	70422	08/22/2024	FVGEN	39	LAB		BRIVAL01		INV-00022538	Labour,RP23
RP23	975QWX	70365	08/27/2024	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	70365	08/27/2024	DEFECT							
RP23	975QWX	70365	08/27/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	70365	08/27/2024	TRA	1	LABOUR	MECH 5	Labour			
RP23	975QWX	70365	08/27/2024	TRA	'A' SERVICE COMPLETED BY BEN & TYLER (WORKSHOP) ON 27/08/2024.						
RP23	975QWX	70365	08/27/2024	TRA	0	LABOUR	APPREN	Labour - Internal			
RP23	975QWX	70365	08/27/2024	TRA	16	CON		YAT	Consumables		
RP23	975QWX	72425	09/09/2024	WASH	TRAILER WASH COMPLET ED ON 09.09.202 4 AT LOCATION : YATALA						
RP23	975QWX	71439	09/19/2024	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	71440	09/19/2024	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	71439	09/19/2024	DEFECT							
RP23	975QWX	71440	09/19/2024	DEFECT							
RP23	975QWX	71439	09/19/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	71440	09/19/2024	DEFECT	DEFECT CLEARED.						

RP23	975QWX	71440	09/19/2024	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES QLD ON 19/09/2024 INVOICE NO. 00029781 NO DEFECTS IDENTIFIED						
RP23	975QWX	71440	09/19/2024	EXOINS		1	LABEXT		DIESER01	EX00036373	CARRY OUT C & D SERVICE WITH BEARINGS AND GREASE,
RP23	975QWX	71440	09/19/2024	EXOINS		16	DEGREASER		DIESER01	EX00036373	DEGREASER,
RP23	975QWX	71440	09/19/2024	EXOINS		16	CON		DIESER01	EX00036373	Consumables,
RP23	975QWX	71440	09/19/2024	EXOINS		1	LABEXT		DIESER01	29781	CARRY OUT C & D SERVICE WITH BEARINGS AND GREASE,
RP23	975QWX	71440	09/19/2024	EXOINS		16	DEGREASER		DIESER01	29781	DEGREASER,
RP23	975QWX	71440	09/19/2024	EXOINS		16	CON		DIESER01	29781	Consumables,
RP23	975QWX	71439	09/19/2024	TRA		1	LABOUR	MECH	Labour		

RP23	975QWX	71439	09/19/2024	TRA	SERVICE COMPLETED.					
RP23	975QWX	71439	09/19/2024	TRB		1	LABOUR	MECH	Labour	
RP23	975QWX	71439	09/19/2024	TRB	SERVICE COMPLETED.					
					SERVICE COMPLETED BY DIESEL SERVICES QLD ON 19/09/2024 INVOICE NO. 00029781					
					C and D service with bearings and grease. Remove, replace all bearings and seals, clean and repack all hubs.					
RP23	975QWX	71439	09/19/2024	TRC	Retention					
RP23	975QWX	71439	09/19/2024	TRC		11	0980107040TSSC		YAT	KIT W/BRG & SEAL 10T ECO
RP23	975QWX	71439	09/19/2024	TRC		11	2.57E+08		YAT	Hub Seal Grease, BPW, Eco Plus
RP23	975QWX	71439	09/19/2024	TRC		11	210404900-20		YAT	GREASE ECO-LI-PLUS 19KG
RP23	975QWX	71439	09/19/2024	TRC		16	84010		YAT	White Reflector 60mm Dia
RP23	975QWX	73427	11/14/2024	DEFECT		1	LABOUR	MECH	Labour	
RP23	975QWX	73427	11/14/2024	DEFECT						
RP23	975QWX	73427	11/14/2024	DEFECT	DEFECT CLEARED.					
RP23	975QWX	73427	11/14/2024	TRA		1	LABOUR	MECH 5	Labour	

					"A" SERVICE COMPLETED BY WORKSHOP 14/11/2024						
RP23	975QWX	73427	11/14/2024	TRA	REPAIRED LHS MARKER LIGHT						
RP23	975QWX	73427	11/14/2024	TRA		16	CON		YAT	Consumables	
RP23	975QWX	73781	11/27/2024	GEN		39	LABEXT		RCCLOW01	EX00037436	CHECK CODES ALL INDICATING LOW BATTERY. CHECK BATTERY, FOUND UNSERV
RP23	975QWX	73781	11/27/2024	GEN		14	BATTERY		RCCLOW01	EX00037436	BATTERY, Consumables
RP23	975QWX	73781	11/27/2024	GEN		16	CON		RCCLOW01	EX00037436	,
RP23	975QWX	73781	11/27/2024	GEN		16	ENVLEV		RCCLOW01	EX00037436	ENVIRONMENTAL LEVY,
RP23	975QWX	73781	11/27/2024	GEN		39	LABEXT		RCCLOW01	39145	CHECK CODES ALL INDICATING LOW BATTERY. CHECK BATTERY, FOUND UNSERV
RP23	975QWX	73781	11/27/2024	GEN		14	BATTERY		RCCLOW01	39145	BATTERY, Consumables
RP23	975QWX	73781	11/27/2024	GEN		16	CON		RCCLOW01	39145	,
RP23	975QWX	73781	11/27/2024	GEN		16	ENVLEV		RCCLOW01	39145	ENVIRONMENTAL LEVY,
RP23	975QWX	74045	12/06/2024	TYRES		15	33000118		BRIAUS01	EX00037616	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	74045	12/06/2024	TYRES		15	33000188		BRIAUS01	EX00037616	B FLEET PRESSURE CHECK,
RP23	975QWX	74045	12/06/2024	TYRES		15	33000118		BRIAUS01	1.9E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	74045	12/06/2024	TYRES		15	33000188		BRIAUS01	1.9E+08	B FLEET PRESSURE CHECK,
RP23	975QWX	74294	12/20/2024	DEFECT		1	LABOUR	MECH	Labour		
RP23	975QWX	74294	12/20/2024	DEFECT							
RP23	975QWX	74294	12/20/2024	DEFECT	DEFECT CLEARED.						
RP23	975QWX	74294	12/20/2024	TRA		1	LABOUR	MECH 5	Labour		

					SERVICE COMPLETED BY BEN & JOSH (WORKSHOP) ON 20/12/2024. REPLACED LH SIDE MIDDLE PARK LIGHT REPLACE LH REAR RED GUARD USED 2ND HAND GUARD INSTALLED 2ND HAND MUDFLAP					
RP23	975QWX	74294	12/20/2024	TRA	F/E EXP :					
RP23	975QWX	74294	12/20/2024	TRA		0	LABOUR	APPRENJC	Labour - Internal	
RP23	975QWX	74294	12/20/2024	TRA		16	CON		YAT	Consumables
RP23	975QWX	74294	12/20/2024	TRA		14	91700BL		YAT	Clearance Light, LED Amber, Narva
RP23	975QWX	75395	01/29/2025	FVGEN		39	CON		ICEGRO01	EX00038366	Consumables,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	R404A		ICEGRO01	EX00038366	GAS R404A,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	33-0230-10		ICEGRO01	EX00038366	SUCTION SERVICE O-RING,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	NITRO		ICEGRO01	EX00038366	NITROGEN HIGH PURITY,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	LAB		ICEGRO01	EX00038366	Labour,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	42-2284-10		ICEGRO01	EX00038366	SUCTION TRANSDUCER,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	33-1221-10		ICEGRO01	EX00038366	SUCTION SCREEN O RING,RP23
RP23	975QWX	75395	01/29/2025	FVGEN	Service completed by Iceman 29/01/2025 - Attached gauges - Found leaking suction o-rings and suction transducer reading incorrectly - Carried out compressor					

RP23	975QWX	75395	01/29/2025	FVGEN		39	33-1221-10		ICEGRO01	895938	SUCTION SCREEN O RING,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	42-2284-10		ICEGRO01	895938	SUCTION TRANSDUCER,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	LAB		ICEGRO01	895938	Labour,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	NITRO		ICEGRO01	895938	NITROGEN HIGH PURITY,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	33-0230-10		ICEGRO01	895938	SUCTION SERVICE O-RING,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	R404A		ICEGRO01	895938	GAS R404A,RP23
RP23	975QWX	75395	01/29/2025	FVGEN		39	CON		ICEGRO01	895938	Consumables ,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL	0	LABOUR	MECH	Labour		
RP23	975QWX	75571	02/12/2025	FRIVANB	R+R						

RP23	975QWX	75571	02/12/2025	FRIVANB	39	CON		ICEGRO01	EX00038475	Consumables,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39	CC		ICEGRO01	EX00038475	CALIBRATION CETIFICATE,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39		100417	ICEGRO01	EX00038475	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39	LAB		ICEGRO01	EX00038475	Labour,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	40		3413005	YAT	OIL 15W-40, CK 4/E9	
RP23	975QWX	75571	02/12/2025	FRIVANB	Service completed by Iceman 10/02/2025 - Carried out B Service as per Iceman Specifications					
RP23	975QWX	75571	02/12/2025	FRIVANB	39	CON		ICEGRO01	896669	Consumables,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39	CC		ICEGRO01	896669	CALIBRATION CETIFICATE,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39		100417	ICEGRO01	896669	Filter Service Kit, Fridge Motor, SLX-400,RP23
RP23	975QWX	75571	02/12/2025	FRIVANB	39	LAB		ICEGRO01	896669	Labour,RP23
RP23	975QWX	75571	02/12/2025	FRIVCAL	1	LABOUR	MECH	Labour		
RP23	975QWX	75571	02/12/2025	FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED					
RP23	975QWX	76106	02/25/2025	DEFECT	1	LABOUR	MECH	Labour		
RP23	975QWX	76106	02/25/2025	DEFECT	DEFECT CLEARED.					

RP23	975QWX	76106	02/25/2025	TRA	A SERVICE COMPLETED BY RCC LOWTH (NQFM) ON 25/02/2025. CARRIED OUT A-SERVICE AS PER SERVICE SHEET REPLACED UNSERVICABLE FRONT-RIGHT AMBER LED LIGHT FIRE EXT EXP: MARCH 2025				
RP23	975QWX	76106	02/25/2025	TRA	1	LABEXT	RCCLOW01	EX00038721	CARRIED OUT A-SERVICE AS PER SERVICE SHEET,
RP23	975QWX	76106	02/25/2025	TRA	39	LABEXT	RCCLOW01	EX00038721	REPLACED UNSERVICEABLE FRONT-RIGHT AMBER LIGHT,
RP23	975QWX	76106	02/25/2025	TRA	14	PART	RCCLOW01	EX00038721	SIDE MARKER,
RP23	975QWX	76106	02/25/2025	TRA	16	GREASE	RCCLOW01	EX00038721	GREASE,
RP23	975QWX	76106	02/25/2025	TRA	16	CON	RCCLOW01	EX00038721	Consumables,
RP23	975QWX	76106	02/25/2025	TRA	16	ENVLEV	RCCLOW01	EX00038721	ENVIRONMENTAL LEVY,
RP23	975QWX	76106	02/25/2025	TRA	1	LABEXT	RCCLOW01	39872	CARRIED OUT A-SERVICE AS PER SERVICE SHEET,
RP23	975QWX	76106	02/25/2025	TRA	39	LABEXT	RCCLOW01	39872	REPLACED UNSERVICEABLE FRONT-RIGHT AMBER LIGHT,
RP23	975QWX	76106	02/25/2025	TRA	14	PART	RCCLOW01	39872	SIDE MARKER,

RP23	975QWX	76106	02/25/2025	TRA	16	GREASE	RCCLOW01	39872	GREASE, Consumables
RP23	975QWX	76106	02/25/2025	TRA	16	CON	RCCLOW01	39872	,
RP23	975QWX	76106	02/25/2025	TRA	16	ENVLEV	RCCLOW01	39872	ENVIRONMENTAL LEVY, Consumables
RP23	975QWX	76657	03/26/2025	FVGEN	39	CON	ICEGRO01	EX00039133	,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	91-8972-10	ICEGRO01	EX00039133	SLX ISOLATOR SNUBBER,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	41-1566-10	ICEGRO01	EX00039133	SOLENOID - COMPLETE,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	77-3218-10	ICEGRO01	EX00039133	SMOOTH IDLER PULLEY,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	77-3219-10	ICEGRO01	EX00039133	GROOVED IDLER PULLEY,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	LAB	ICEGRO01	EX00039133	Labour,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	Service completed by Iceman 26/03/2025 - Inspected noist unit - Traced to compressor idlers - Removed belt guard and comp belt - Replaced u/s idlers and worr				
RP23	975QWX	76657	03/26/2025	FVGEN	39	CON	ICEGRO01	899862	Consumables ,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	91-8972-10	ICEGRO01	899862	SLX ISOLATOR SNUBBER,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	41-1566-10	ICEGRO01	899862	SOLENOID - COMPLETE,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	77-3218-10	ICEGRO01	899862	SMOOTH IDLER PULLEY,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	77-3219-10	ICEGRO01	899862	GROOVED IDLER PULLEY,RP23
RP23	975QWX	76657	03/26/2025	FVGEN	39	LAB	ICEGRO01	899862	Labour,RP23
RP23	975QWX	77116	04/15/2025	DEFECT	1	LABOUR MECH	Labour		
RP23	975QWX	77116	04/15/2025	DEFECT	DEFECT CLEARED.				

RP23	975QWX	77116	04/15/2025	DEFECT	Reported Defect :- Defect Code : 00007929 Defect Reference : WO 50141 Date : 24/08/2022 Description of Defect : NEEDS TO GO TO TRAILER SALES FOR INTERNAL REPAIRS				
RP23	975QWX	77116	04/15/2025	TRA		1	LABOUR	MECH	Labour - Internal
RP23	975QWX	77116	04/15/2025	TRA	A SERVICE COMPLETED. FIRE EXT EXP:				
RP23	975QWX	77116	04/15/2025	TRA		16	CON	YAT	Consumables
RP23	975QWX	77116	04/15/2025	TRB		1	LABOUR	MECH 1	Labour - Internal

RP23	975QWX	77116	04/15/2025	TRB	B SERVICE COMPLETED BY WORKSHOP 15/04/2025 FIRE EXT EXP: NOV 25 CHANGE FIRE EXTINGUISHER REPLACED LHS O RINGS DEFECT #7929 ALL OKAY - CHECKED WITH MICK

RP23	975QWX	77116	04/15/2025	TRB	16	CON		YAT	Consumables		
RP23	975QWX	77116	04/15/2025	TRB	0	LABOUR	APPRENJC	1.5	105	157.5	
RP23	975QWX	77116	04/15/2025	TRB	16	4.5KGEXT		YAT	4.5KG Fire Extinguisher		
RP23	975QWX	77173	04/16/2025	TYRES	15	99015526		BRIAUS01		EX00039495	RUNOUT TYRE,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000084		BRIAUS01		EX00039495	FIT TBR TYRE,
RP23	975QWX	77173	04/16/2025	TYRES	15	33001507		BRIAUS01		EX00039495	CUSTOMER SCRAPPED OWN TYRE,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000522		BRIAUS01		EX00039495	REMOVAL: PUNCTURED,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000118		BRIAUS01		EX00039495	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000118		BRIAUS01		1.9E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000522		BRIAUS01		1.9E+08	REMOVAL: PUNCTURED,
RP23	975QWX	77173	04/16/2025	TYRES	15	33001507		BRIAUS01		1.9E+08	CUSTOMER SCRAPPED OWN TYRE,
RP23	975QWX	77173	04/16/2025	TYRES	15	33000084		BRIAUS01		1.9E+08	FIT TBR TYRE,
RP23	975QWX	77173	04/16/2025	TYRES	15	99015526		BRIAUS01		1.9E+08	RUNOUT TYRE,

										Consumab les
RP23	975QWX	77905	05/16/2025	FVGEN	39	CON		ICEGRO01	EX00039982	,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	772856		ICEGRO01	EX00039982	DRIVE PLATE BUSHES 30S FRIDGE,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	78-1831-OP		ICEGRO01	EX00039982	SLX COMPRESSOR BELT,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	33-2805-10		ICEGRO01	EX00039982	DISCHARGE GASKET,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	91-8972-10		ICEGRO01	EX00039982	SLX ISOLATOR SNUBBER,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	R404A		ICEGRO01	EX00039982	GAS R404A,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	NITRO		ICEGRO01	EX00039982	NITROGEN HIGH PURITY,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	LAB		ICEGRO01	EX00039982	Labour,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	Service completed by Iceman 16/05/2025 - Inspected unit - Carried out compressor pump down - Removed belt guard and brace - Removed battery and compre					

										Consumab les
RP23	975QWX	77905	05/16/2025	FVGEN	39	CON		ICEGRO01	903262	,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	772856		ICEGRO01	903262	DRIVE PLATE BUSHES 30S FRIDGE,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	78-1831-OP		ICEGRO01	903262	SLX COMPRESSOR BELT,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	33-2805-10		ICEGRO01	903262	DISCHARGE GASKET,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	91-8972-10		ICEGRO01	903262	SLX ISOLATOR SNUBBER,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	R404A		ICEGRO01	903262	GAS R404A,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	NITRO		ICEGRO01	903262	NITROGEN HIGH PURITY,RP23
RP23	975QWX	77905	05/16/2025	FVGEN	39	LAB		ICEGRO01	903262	Labour,RP23
RP23	975QWX	77906	05/21/2025	TRA	1	LABOUR	MECH 1	Labour - Internal		

RP23	975QWX	77906	05/21/2025	TRA	A SERVICE COMPLETED BY WORKSHOP 21.05.2025 FIRE EXT EXP: NOVEMBER 2025 REPAIR LADDER RECURING LATCH FIT X2 REAR REFLECTORS REFIT TOP L/H CLEARANCE LIGHT					
RP23	975QWX	77906	05/21/2025	TRA		16	CON		YAT	Consumables
RP23	975QWX	77906	05/21/2025	TRA		0	LABOUR	APPRENJ	Labour - Internal	
RP23	975QWX	77906	05/21/2025	TRA		16	22558WCRK-V		YAT	4" ROUND GLO TRAC LED TAIL LAMP CLEAR/RED

RP23	975QWX	81682	06/25/2025	WEICAL	WEIGHBRIDGE: 10880 AIR GAUGE:11500 ADJUSTED: 11250 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP23	975QWX	79106	07/01/2025	FVGEN	39	CON		ICEGRO01	EX00040778	Consumables,RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39		417852	ICEGRO01	EX00040778	DAMPER MOTOR (SLX),RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39	LAB		ICEGRO01	EX00040778	Labour,RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39		990214	ICEGRO01	EX00040778	MOUNTING BOLT,RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	Service completed by Iceman 01/07/2025 - Inspected unit - Removed rear wall - Replaced u/s damper motor - Removed panels - Replaced upper mounting bolts						
RP23	975QWX	79106	07/01/2025	FVGEN	39	CON		ICEGRO01	906323	Consumables,RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39		417852	ICEGRO01	906323	DAMPER MOTOR (SLX),RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39	LAB		ICEGRO01	906323	Labour,RP23	
RP23	975QWX	79106	07/01/2025	FVGEN	39		990214	ICEGRO01	906323	MOUNTING BOLT,RP23	
RP23	975QWX	78990	07/02/2025	DEFECT	1	LABOUR	MECH	Labour			
RP23	975QWX	78990	07/02/2025	DEFECT	DEFECT CLEARED.						
RP23	975QWX	78990	07/02/2025	TRA	1	LABOUR	MECH 1	Labour - Internal			

RP23	975QWX	78990	07/02/2025	TRA	A SERVICE COMPLETED BY WORKSHOP 02/07/2025 FIRE EXT EXP: NOVEMBER 2025 REPLACE REVERSE BEEPER TOGGLE SWITCH

RP23	975QWX	78990	07/02/2025	TRA	16	CON		YAT	Consumables	
RP23	975QWX	78990	07/02/2025	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	78990	07/02/2025	TRA	16	60056BL		YAT	TOGGLE SWITCH	
RP23	975QWX	79128	07/04/2025	TYRES	15	11002821		BRIAUS01	EX00040800	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	79128	07/04/2025	TYRES	15	99015526		BRIAUS01	EX00040800	RUNOUT TYRE,
RP23	975QWX	79128	07/04/2025	TYRES	15	77000232		BRIAUS01	EX00040800	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000084		BRIAUS01	EX00040800	FIT TBR TYRE,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000517		BRIAUS01	EX00040800	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000118		BRIAUS01	EX00040800	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	79128	07/04/2025	TYRES	15	11002821		BRIAUS01	1.91E+08	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	79128	07/04/2025	TYRES	15	99015526		BRIAUS01	1.91E+08	RUNOUT TYRE,
RP23	975QWX	79128	07/04/2025	TYRES	15	77000232		BRIAUS01	1.91E+08	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000084		BRIAUS01	1.91E+08	FIT TBR TYRE,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000517		BRIAUS01	1.91E+08	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	79128	07/04/2025	TYRES	15	33000118		BRIAUS01	1.91E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	79805	07/25/2025	TYRES	15	11002821		BRIAUS01	EX00041293	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	79805	07/25/2025	TYRES	15	77000232		BRIAUS01	EX00041293	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000084		BRIAUS01	EX00041293	FIT TBR TYRE,
RP23	975QWX	79805	07/25/2025	TYRES	15	33001507		BRIAUS01	EX00041293	CUSTOMER SCRAPPED OWN TYRE,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000517		BRIAUS01	EX00041293	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000531		BRIAUS01	EX00041293	REMOVAL: FLAT OR UNDER INFLATED,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000118		BRIAUS01	EX00041293	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	79805	07/25/2025	TYRES	15	11002821		BRIAUS01	1.91E+08	11R22.5 148/145L BS R119 ECO,
RP23	975QWX	79805	07/25/2025	TYRES	15	77000232		BRIAUS01	1.91E+08	CASE STOCK 11R22.5 ECOPIA,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000084		BRIAUS01	1.91E+08	FIT TBR TYRE,

RP23	975QWX	79805	07/25/2025	TYRES	15	33001507	BRIAUS01	1.91E+08	CUSTOMER SCRAPPED OWN TYRE,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000517	BRIAUS01	1.91E+08	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000531	BRIAUS01	1.91E+08	REMOVAL: FLAT OR UNDER INFLATED,
RP23	975QWX	79805	07/25/2025	TYRES	15	33000118	BRIAUS01	1.91E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	80213	08/20/2025	TYRES	15	11004118	BRIAUS01	EX00041586	11R22.5 148/145L BS R1668II,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000084	BRIAUS01	EX00041586	FIT TBR TYRE,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000241	BRIAUS01	EX00041586	SCRAP TYRES TBR,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000237	BRIAUS01	EX00041586	FTSD-096431 FLEET#-RP23 REGO-975QWX DATE-19/08/25 POS - 17/18,
RP23	975QWX	80213	08/20/2025	TYRES	15	11004118	BRIAUS01	1.91E+08	11R22.5 148/145L BS R1668II,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000084	BRIAUS01	1.91E+08	FIT TBR TYRE,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000241	BRIAUS01	1.91E+08	SCRAP TYRES TBR,
RP23	975QWX	80213	08/20/2025	TYRES	15	33000237	BRIAUS01	1.91E+08	FTSD-096431 FLEET#-RP23 REGO-975QWX DATE-19/08/25 POS - 17/18,
RP23	975QWX	80431	08/30/2025	DEFECT	1	LABOUR	MECH	Labour	
RP23	975QWX	80431	08/30/2025	DEFECT	DEFECT CLEARED.				
RP23	975QWX	80431	08/30/2025	TRA	1	LABOUR	MECH 1	Labour - Internal	
RP23	975QWX	80431	08/30/2025	TRA	COMPLETED BY WORKSHOP 30/8/2025 FIRE EXT EXP: NOVEMBER 2025 STRAIGHTEN AND REPAIR MOUNTING BRACKETS AND REPLACE FRONT LEFT MUDGUARD REPLACE SHOCK ABSORBE					

RP23	975QWX	80431	08/30/2025	TRA	16	CON		YAT	Consumables	
RP23	975QWX	80431	08/30/2025	TRA	0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	80431	08/30/2025	TRA	0	LABOUR	APPRENJC	Labour - Internal		
RP23	975QWX	80431	08/30/2025	TRA	0	LABOUR	APPREND	Labour - Internal		
RP23	975QWX	80431	08/30/2025	TRA	16	F5480		YAT	SHOCK ABSORBER MAGNUM MOI	
RP23	975QWX	80431	08/30/2025	TRA	16	MG630-R		YAT	MUDGUARD RED	
RP23	975QWX	80889	09/12/2025	FVGEN	39	CON		ICEGRO01	EX00042048	Consumables,RP23
RP23	975QWX	80889	09/12/2025	FVGEN	39	LAB		ICEGRO01	EX00042048	Labour,RP23
RP23	975QWX	80889	09/12/2025	FVGEN	39	98-7912-10		ICEGRO01	EX00042048	SLX PANEL LOWER LEFT,RP23
RP23	975QWX	80889	09/12/2025	FVGEN		SERVICE COMPLETED BY ICEMAN 12/09/2025 - INSPECTED UNIT - REPLACED U/S BATTERY DOOR - STRAIGHTENED BRACKETS - CHECKED OPERATION...UNIT RAN ON TEST				
RP23	975QWX	80889	09/12/2025	FVGEN	39	CON		ICEGRO01	910894	Consumables,RP23
RP23	975QWX	80889	09/12/2025	FVGEN	39	LAB		ICEGRO01	910894	Labour,RP23
RP23	975QWX	80889	09/12/2025	FVGEN	39	98-7912-10		ICEGRO01	910894	SLX PANEL LOWER LEFT,RP23
RP23	975QWX	80782	09/13/2025	GEN	39	LABOUR	MECH 1	Labour		

RP23	975QWX	80782	09/13/2025	GEN	COMPLETED BY WORKSHOP 13/09/2025 FIRE EXT EXP: FABRICATE AND WELD NEW MOUNT ONTO RH FRONT HANGER, FIT NEW BRACKET AND RED MUDGUARD (MUDGUARD AND BRACKET W/SHOP						
RP23	975QWX	80782	09/13/2025	GEN		16	CON		YAT	Consumables	
RP23	975QWX	80782	09/13/2025	GEN		0	LABOUR	APPREN	Labour - Internal		
RP23	975QWX	81539	10/13/2025	FVGEN		39	CON		ICEGRO01	EX00042463	Consumables,RP23
RP23	975QWX	81539	10/13/2025	FVGEN		39	LAB		ICEGRO01	EX00042463	Labour,RP23
RP23	975QWX	81539	10/13/2025	FVGEN	SERVICE COMPLETED BY ICEMAN 13/10/2025 - REPLACED U/S DOOR HINGE (CUSTOMER SUPPLIED - FROM SCRAP UNIT)						
RP23	975QWX	81539	10/13/2025	FVGEN		39	CON		ICEGRO01	912703	Consumables,RP23
RP23	975QWX	81539	10/13/2025	FVGEN		39	LAB		ICEGRO01	912703	Labour,RP23
RP23	975QWX	81457	10/14/2025	DEFECT		1	LABOUR	MECH	Labour		

RP23	975QWX	81457	10/14/2025	DEFECT	DEFECT CLEARED.				
RP23	975QWX	81457	10/14/2025	DEFECT	Reported Defect :- Defect Code : 00015009 Defect Reference : RP23 Date : 30/08/2025 Description of Defect : NEED TO ORDER NHVR LABEL - MISSING				
RP23	975QWX	81456	10/14/2025	EXOINS		1	LABOUR	MECH	Labour

					VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT #1 INSPECTION COMPLETED BY WORKSHOP 14/10/2025 FIRE EXT EXP - NOVEMBER 2025 DEFECTS IDENTIFIED - NONE				
RP23	975QWX	81456	10/14/2025	EXOINS					
RP23	975QWX	81457	10/14/2025	TRA	1	LABOUR	MECH	Labour - Internal	
					A SERVICE COMPLETED.				
RP23	975QWX	81457	10/14/2025	TRA	FIRE EXT EXP:				
RP23	975QWX	81457	10/14/2025	TRA	16	CON		YAT	Consumables
RP23	975QWX	81457	10/14/2025	TRB	1	LABOUR	MECH	Labour - Internal	

					B SERVICE COMPLETED.						
RP23	975QWX	81457	10/14/2025	TRB	FIRE EXT EXP:						
RP23	975QWX	81457	10/14/2025	TRB		16	CON		YAT	Consumables	
RP23	975QWX	81457	10/14/2025	TRC	COMPLETED BY WORKSHOP 14/10/2025	1	LABOUR	MECH 1	Labour		
					FIRE EXT EXP: NOVEMBER 2025						
					REPAIR LOAD LOCK TRACK AND REPLACE ENTIRE WHICH WAS DAMAGED						
RP23	975QWX	81457	10/14/2025	TRC	DEFECT 15009 - FIT NHVR						
RP23	975QWX	81457	10/14/2025	TRC		16	CON		YAT	Consumables	
RP23	975QWX	81457	10/14/2025	TRC		0	LABOUR	APPREND	Labour - Internal		
RP23	975QWX	81602	10/14/2025	TYRES		15	11004117		BRIAUS01	EX00042519	11R22.5 148/145L FS FT469,
RP23	975QWX	81602	10/14/2025	TYRES		15	33000084		BRIAUS01	EX00042519	FIT TBR TYRE,

RP23	975QWX	81602	10/14/2025	TYRES	15	33000371	BRIAUS01	EX00042519	TYRE SENT FIR CAPPING,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000517	BRIAUS01	EX00042519	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000118	BRIAUS01	EX00042519	SCHEDULED DEPOT SERVICE 15MIN,
RP23	975QWX	81602	10/14/2025	TYRES	15	11004117	BRIAUS01	1.92E+08	11R22.5 148/145L FS FT469,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000084	BRIAUS01	1.92E+08	FIT TBR TYRE,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000371	BRIAUS01	1.92E+08	TYRE SENT FIR CAPPING,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000517	BRIAUS01	1.92E+08	REMOVAL: CUSTOMER PULL POINT,
RP23	975QWX	81602	10/14/2025	TYRES	15	33000118	BRIAUS01	1.92E+08	SCHEDULED DEPOT SERVICE 15MIN,

Total for Asset	81,291.40
Total for Report	81,291.40

Report Options:
Sort By - AssetCode
Starting Asset Code - RP23
To - RP23
Starting Registration - To -
Starting Operations No - To -
From: Work Order Location - To -
From:

as required - Wash engine and compressor - Unit run on t

'LACED & RETESTED, ALL OK

'LACED & RETESTED, ALL OK

damper operation. all ok - Unit run on test, pretrip p

ıovement - Remove and replace worn snubber mount - 1/4" fuel lines rubbed through - Remove and replace u/s fuel lines and secured - Remove and replace cracked water pump belt - Unit run on t

eplace u/s fan belt - Unit run on t

:RVICEABLE. REMOVE & REPLACE WITH NEW BATTERY. TEST. ALL (

:RVICEABLE. REMOVE & REPLACE WITH NEW BATTERY. TEST. ALL (

;or pump down - Replaced leaking o-rings - Replaced suction transducer - Pressure tested system with nitrogen - Vac out unit and regassed system - Checked operation - Unit ran on t

rorn snubber mount - Refitted and tensioned belt - Refitted belt guard and secured hoses - Removed fan panel - Replaced missing rivnuts - Refitted panel - Checked operation - Unit ran on t

pressor - Removed and rebuilt drive plate with new bushes - Refitted all components - Replaced u/s snubber mount - Pressure tested compressor with nitrogen - Vac out unit and regassed system - Checked operation - Unit ran on t

olts and washers - Refitted all panels - Checked operation - Unit ran on t