Exodas Pty Ltd

11/17/2025 14:36:03 User: HELENT

 Comp: EXO

Work Order History

Asset	Registration	Work	Work Order	Service	RM	Task	Employee	Product	W/H	Supplier
RPS22	750QWU	2821	07/04/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2822	07/18/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2823	08/04/2016	TRA	1	LABOUR	MECH1	Labour		
RPS22	750QWU	2824	08/30/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2825	09/30/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2825	09/30/2016	TRB	1	LABOUR	MECH	Labour		
RPS22	750QWU	2826	10/11/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2827	11/04/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2828	11/28/2016	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2829	01/20/2017	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	2829	01/20/2017	TRB	1	LABOUR	MECH	Labour		
RPS22	750QWU	2830	01/30/2017	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	3158	03/07/2017	GEN	DEFECT 5500 614377 HAS BEEN CLEARED.					
RPS22	750QWU	3143	03/07/2017	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	3143	03/07/2017	TRA	16	CON		YAT Consumables		
RPS22	750QWU	3143	03/07/2017	TRA	CHECKED ALL WHEEL BEARINGS					
RPS22	750QWU	3574	03/21/2017	GEN	3	917709		QTKGRO05	EX00001123	Eng Mount Fridge SB310,750QWU, RP22
RPS22	750QWU	3574	03/21/2017	GEN	16	CON		QTKGRO05	EX00001123	Consumables ,750QWU, RP22
RPS22	750QWU	3574	03/21/2017	GEN	0	LABEXT		QTKGRO05	EX00001123	Labour External,750QWU, RP22
RPS22	750QWU	3574	03/21/2017	GEN	0	LABEXT		QTKGRO05	SI-094957	Labour External,750QWU, RP22
RPS22	750QWU	3574	03/21/2017	GEN	16	CON		QTKGRO05	SI-094957	Consumables ,750QWU, RP22
RPS22	750QWU	3574	03/21/2017	GEN	3	917709		QTKGRO05	SI-094957	Eng Mount Fridge SB310,750QWU, RP22
RPS22	750QWU	3943	05/08/2017	TYRES	15	STRFIT		TYRMOR01	EX00001467	Strip & Fit,
RPS22	750QWU	3943	05/08/2017	TYRES	15	TYRDIS		TYRMOR01	EX00001467	Tyre Disposal,
RPS22	750QWU	3943	05/08/2017	TYRES	FITTED 4 NEW & 2 RUNOUTS					
RPS22	750QWU	3943	05/08/2017	TYRES	15	TYRDIS		TYRMOR01	12705	Tyre Disposal,
RPS22	750QWU	3943	05/08/2017	TYRES	15	STRFIT		TYRMOR01	12705	Strip & Fit,
RPS22	750QWU	4907	05/15/2017	FRIVANA	1	LABOUR	MECH	Labour		

RPS22	750QWU	4955	05/15/2017	FRIVANA	3	QTKPAR		QTKGRO01	EX00002087	QTK PARTS, SEALING RING,RP22	
RPS22	750QWU	4907	05/15/2017	FRIVANA	QTK PERFORMED A SERVICE - INV SI-098026						
RPS22	750QWU	4955	05/15/2017	FRIVANA	16	CON		QTKGRO01	EX00002087	Consumables,RP22	
RPS22	750QWU	4955	05/15/2017	FRIVANA	0	LABEXT		QTKGRO01	EX00002087	Labour External,RP22	
RPS22	750QWU	4955	05/15/2017	FRIVANA	QTK SERVICED THIS AT ROCKLEA						
RPS22	750QWU	4955	05/15/2017	FRIVANA	3	QTKPAR		QTKGRO01	SI-098026	QTK PARTS, SEALING RING,RP22	
RPS22	750QWU	4955	05/15/2017	FRIVANA	16	CON		QTKGRO01	SI-098026	Consumables,RP22	
RPS22	750QWU	4955	05/15/2017	FRIVANA	0	LABEXT		QTKGRO01	SI-098026	Labour External,RP22	
RPS22	750QWU	5010	05/31/2017	FRIVANA	1	LABOUR	Labour			0	
RPS22	750QWU	5010	05/31/2017	FRIVANA	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RPS22	750QWU	5011	05/31/2017	FRIVCAL	1	LABOUR	Labour			0	
RPS22	750QWU	5011	05/31/2017	FRIVCAL	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RPS22	750QWU	4904	06/08/2017	FRIVANA	1	LABOUR	MECH	Labour			
RPS22	750QWU	4904	06/08/2017	FRIVANSE	1	LABOUR	MECH	Labour			
RPS22	750QWU	4904	06/08/2017	FRIVANSE	QTK - PERFORMED B SERVICE - INV SI-099697						
RPS22	750QWU	4633	06/08/2017	GEN	35	129		QTKGRO01	EX00001883	B SERVICE DONE,	
RPS22	750QWU	4633	06/08/2017	GEN	35	129		QTKGRO01	SI-099697	B SERVICE DONE,	
RPS22	750QWU	5165	07/11/2017	FRIVANA	16	128		QTKGRO01	EX00002181	A SERVICE LABOUR + ENGINE OIL + CONSUMABLES,	
RPS22	750QWU	5165	07/11/2017	FRIVANA	16	128		QTKGRO01	SI-101762	A SERVICE LABOUR + ENGINE OIL + CONSUMABLES,	
RPS22	750QWU	5346	07/22/2017	GEN	39	LABEXT		VISMEC01	EX00002288	Labour External,RP22	
RPS22	750QWU	5346	07/22/2017	GEN	TIM WARREN A/C AND ELECTRICAL REPAIRED FUEL BREAKER.						
RPS22	750QWU	5346	07/22/2017	GEN	39	LABEXT		VISMEC01	74826	Labour External,RP22	
RPS22	750QWU	5361	07/31/2017	GEN	39	LABEXT		QTKGRO01	EX00002296	Labour External,RP22	
RPS22	750QWU	5361	07/31/2017	GEN	AFTER BUSINESS CALL OUT HOURS. 14/07/2017. UNIT WILL NOT START. DIAGNOSED LIGHTS LEFT ON, BATTERY FLAT, JUMP STARTED, CHECKED SYSTEM, ALL OK						
RPS22	750QWU	5361	07/31/2017	GEN	39	LABEXT		QTKGRO01	SI-103051	Labour External,RP22	
RPS22	750QWU	5727	08/23/2017	GEN	39	CON		QTKGRO01	EX00002541	Consumables,RP22	
RPS22	750QWU	5727	08/23/2017	GEN	39	LABEXT		QTKGRO01	EX00002541	Labour External,RP22	
RPS22	750QWU	5727	08/23/2017	GEN	QTK COMPLETED A FULL SERVICE AND REPAIR LEAKING FUEL LINE.						
RPS22	750QWU	5727	08/23/2017	GEN	39	CON		QTKGRO01	SI-104371	Consumables,RP22	
RPS22	750QWU	5727	08/23/2017	GEN	39	LABEXT		QTKGRO01	SI-104371	Labour External,RP22	
RPS22	750QWU	5991	09/13/2017	FRIVANA	1	LABOUR	MECH1	Labour			

RPS22	750QWU	5991	09/13/2017	FRIVANA	6	LF9030		YAT	Lube Filter	
RPS22	750QWU	5991	09/13/2017	FRIVANA	40	3380369		YAT	ENGINE OIL, VECTON 15W/40 CJ-4/E9 BULK	
RPS22	750QWU	5991	09/13/2017	FRIVANA	6	FS19580A		YAT	Fuel Water Seperator Filter	
RPS22	750QWU	5991	09/13/2017	FRIVANA	6	119300		YAT	QTK Fridge A/Filter EMI 3000	
RPS22	750QWU	5991	09/13/2017	FRIVANA	14	NSB-AGM35		YAT	Battery, Roll Back Fridge, Deep Cycle	
RPS22	750QWU	5991	09/13/2017	FRIVANA	16	CON		YAT	Consumables	
RPS22	750QWU	5991	09/13/2017	FRIVANA	SERVICE COMPLETED. FIT UP NEW BATTERY.					
RPS22	750QWU	5991	09/13/2017	FRIVANSE	1	LABOUR	MECH1	Labour		
RPS22	750QWU	5990	09/13/2017	TRA	1	LABOUR	APPREN	Labour		
RPS22	750QWU	5990	09/13/2017	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	5990	09/13/2017	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	5990	09/13/2017	TRA	FIT MASS MANAGEMENT LABEL. FIT REGO LABEL. FIT FLEET NUMBER. FIT FUEL TAG. REPAIRED LHS GUARD BRACKET. REPAIRED PLATE INSIDE THE VAN.					
RPS22	750QWU	6440	10/16/2017	EXOINS	1	LABOUR	Labour			0
RPS22	750QWU	6440	10/16/2017	EXOINS	0	LABOUR	MECH	Labour - Internal		
RPS22	750QWU	6440	10/16/2017	EXOINS	PASSED					
RPS22	750QWU	6439	10/16/2017	TRA	1	LABOUR	Labour			0

RPS22	750QWU	6439	10/16/2017	TRB	1	LABOUR	Labour				0
RPS22	750QWU	6439	10/16/2017	TRC	1	LABOUR	Labour				0
RPS22	750QWU	6439	10/16/2017	TRC	0	LABOUR	TRADEA	Labour - Internal			
RPS22	750QWU	6439	10/16/2017	TRC	14	82062		YAT	7 Pin Female Trailer Plug		
RPS22	750QWU	6439	10/16/2017	TRC	16	CON		YAT	Consumables		
RPS22	750QWU	6439	10/16/2017	TRC	SERVICE COMPLETED. WHEEL BEARINGS CHECKED. REPLACED FEMALE ELECTRIC PLUG. CRACK IN LEFT FRONT VERTICAL STRIP.						
RPS22	750QWU	6576	10/18/2017	GEN	39	CON		QTKGRO01		EX00003060	Consumables,RP22
RPS22	750QWU	6576	10/18/2017	GEN	39	LABEXT		QTKGRO01		EX00003060	Labour External,RP22
RPS22	750QWU	6576	10/18/2017	GEN	QTK DIAGNOSED FUEL NOT RUNNING FAULT. IT HAD RUN OUT OF FUEL. QTK PRIMED THE FUEL PUMP AND RAN IT.						
RPS22	750QWU	6576	10/18/2017	GEN	39	LABEXT		QTKGRO01		SI-108064	Labour External,RP22
RPS22	750QWU	6576	10/18/2017	GEN	39	CON		QTKGRO01		SI-108064	Consumables,RP22
RPS22	750QWU	6577	10/20/2017	FRIVANA	QTK FOUND FAILED PRIMING PUMP. REPLACED PUMP AND SERVICED MOTOR.						
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	118680		QTKGRO01		EX00003061	PRIMING PUMP, FRIDGE MOTOR,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	PART		QTKGRO01		EX00003061	GENERAL PART CODE,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	PART		QTKGRO01		EX00003061	GENERAL PART CODE,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	CON		QTKGRO01		EX00003061	Consumables,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	LABEXT		QTKGRO01		EX00003061	Labour External,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	QTK DIAGNOSED FUEL DELIVERY CONCERN, THEY SUPPLIED AND FITTED A NEW PRIMING PUMP.						

RPS22	750QWU	6585	10/20/2017	FRIVANA	1	LABEXT		QTKGRO01		SI-108341	Labour External,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	CON		QTKGRO01		SI-108341	Consumables,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	PART		QTKGRO01		SI-108341	GENERAL PART CODE,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	PART		QTKGRO01		SI-108341	GENERAL PART CODE,RP22
RPS22	750QWU	6585	10/20/2017	FRIVANA	1	118680		QTKGRO01		SI-108341	PRIMING PUMP, FRIDGE MOTOR,RP22
RPS22	750QWU	6530	10/23/2017	TYRES	15	77000180		BRIAUS01		EX00003046	CASE STOCK 11-22.5,RP22
RPS22	750QWU	6530	10/23/2017	TYRES	15	33000084		YAT	FIT TBR TYRE		
RPS22	750QWU	6530	10/23/2017	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS22	750QWU	6530	10/23/2017	TYRES	15	77000180		BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP22
RPS22	750QWU	7358	12/18/2017	TRA	1	LABOUR	Labour				0
RPS22	750QWU	7358	12/18/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	7358	12/18/2017	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	7358	12/18/2017	TRA	SERVICE COMPLETED.						
RPS22	750QWU	7990	01/29/2018	TRA	1	LABOUR	Labour				0
RPS22	750QWU	7990	01/29/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	7990	01/29/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	7990	01/29/2018	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	7990	01/29/2018	TRA	SERVICE COMPLETED.						
RPS22	750QWU	8077	01/30/2018	GEN	39	15W40		JC&SL01		EX00004043	ENGINE OIL,RP22
RPS22	750QWU	8077	01/30/2018	GEN	39	COO		JC&SL01		EX00004043	Coolant Allcool K/worth,
RPS22	750QWU	8077	01/30/2018	GEN	39	CON		JC&SL01		EX00004043	Consumables,
RPS22	750QWU	8077	01/30/2018	GEN	39	LABEXT		JC&SL01		EX00004043	Labour External,
RPS22	750QWU	8077	01/30/2018	GEN	JC & SL REFRIGERATION COMPLETED SERVICE AND/OR REPAIRS.						
RPS22	750QWU	8077	01/30/2018	GEN	39	LABEXT		JC&SL01		8137	Labour External,
RPS22	750QWU	8077	01/30/2018	GEN	39	CON		JC&SL01		8137	Consumables,
RPS22	750QWU	8077	01/30/2018	GEN	39	COO		JC&SL01		8137	Coolant Allcool K/worth,
RPS22	750QWU	8077	01/30/2018	GEN	39	15W40		JC&SL01		8137	ENGINE OIL,RP22
RPS22	750QWU	8137	02/01/2018	TYRES	15	77000180		BRIAUS01		EX00004063	CASE STOCK 11-22.5,RP22
RPS22	750QWU	8137	02/01/2018	TYRES	15	77000180		BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP22
RPS22	750QWU	8137	02/01/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RPS22	750QWU	8137	02/01/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		

RPS22	750QWU	8559	02/28/2018	GEN	39	LABOUR	Labour			0
RPS22	750QWU	8559	02/28/2018	GEN	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	8559	02/28/2018	GEN	LUKE COMPLETED THE REPAIR FOR DEFECT 10296. RHS AIRBAG STRAP WAS BROKEN. LHS STRAP WAS DAMAGED.					
RPS22	750QWU	8742	03/02/2018	GEN	39	61-0600		JC&SL01	EX00004462	RECIEVER DRIER, FRIDGE MOTOR,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	2030740		JC&SL01	EX00004462	R404A REFRIGERANT GAS,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	NITRO		JC&SL01	EX00004462	NITROGEN HIGH PURITY,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	CON		JC&SL01	EX00004462	Consumables,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	CON		JC&SL01	EX00004462	Consumables,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	SUND		JC&SL01	EX00004462	SUNDRIES,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	LABEXT		JC&SL01	EX00004462	Labour External,RP22
RPS22	750QWU	8742	03/02/2018	GEN	JC & SL REFRIGERATION REPAIRED FRIDGE MOTOR UNIT.					
RPS22	750QWU	8742	03/02/2018	GEN	39	LABEXT		JC&SL01	8278	Labour External,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	SUND		JC&SL01	8278	SUNDRIES,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	CON		JC&SL01	8278	Consumables,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	CON		JC&SL01	8278	Consumables,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	NITRO		JC&SL01	8278	NITROGEN HIGH PURITY,RP22
RPS22	750QWU	8742	03/02/2018	GEN	39	2030740		JC&SL01	8278	R404A REFRIGERANT GAS,RP22

RPS22	750QWU	8742	03/02/2018	GEN	39	61-0600		JC&SL01	8278	RECIEVER DRIER, FRIDGE MOTOR,RP22
RPS22	750QWU	8671	03/07/2018	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	8671	03/07/2018	DEFECT	Reported Defect :- Defect Code : 00001029 Defect Reference : 10295 Date : 28/02/2018 Description of Defect : CODES 26-32, WILL NOT COOL. REPAIRED AND CLEARED.					

RPS22	750QWU	8671	03/07/2018	DEFECT	Reported Defect :- Defect Code : 00000589 Defect Reference : W/O 6439 Date : 16/10/2017 Description of Defect : CRACK IN LEFT FRONT VERTICAL STRIP. REPAIRED							
RPS22	750QWU	8671	03/07/2018	TRA		1	LABOUR	Labour				0
RPS22	750QWU	8671	03/07/2018	TRA		0	LABOUR	MECH	Labour - Internal			
RPS22	750QWU	8671	03/07/2018	TRA		0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	8671	03/07/2018	TRA		16	CON		YAT	Consumables		
RPS22	750QWU	8671	03/07/2018	TRA	SERVICE COMPLETED. REPAIRED WIRING. TIGHTENED THE GAURD.							
RPS22	750QWU	9210	04/10/2018	FRIVANSE		1	15W40		JC&SL01		EX00004758	ENGINE OIL,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE		1	119300		JC&SL01		EX00004758	QTK Fridge A/Filter EMI 3000,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE		1	Nov-82		JC&SL01		EX00004758	OIL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE		1	Nov-42		JC&SL01		EX00004758	FUEL FILTER, FRIDGE MOTOR,RP22

RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	COIL		JC&SL01		EX00004758	COIL CLEAN, EVAPORATOR/CONDENSOR,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	SUND		JC&SL01		EX00004758	SUNDRIES,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	LABEXT		JC&SL01		EX00004758	Labour External,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	CC		JC&SL01		EX00004758	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	JC & SL REFRIGERATION COMPLETED THE 'B' SERVICE AND CALIBRATED THIS UNIT.						
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	CC		JC&SL01		8414	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	LABEXT		JC&SL01		8414	Labour External,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	SUND		JC&SL01		8414	SUNDRIES,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	COIL		JC&SL01		8414	COIL CLEAN, EVAPORATOR/CONDENSOR,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	Nov-42		JC&SL01		8414	FUEL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	Nov-82		JC&SL01		8414	OIL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	119300		JC&SL01		8414	QTK Fridge A/Filter EMI 3000,RP22
RPS22	750QWU	9210	04/10/2018	FRIVANSE	1	15W40		JC&SL01		8414	ENGINE OIL,RP22
RPS22	750QWU	9242	04/12/2018	TYRES	15	77000232		BRIAUS01		EX00004767	CASE STOCK 11R22.5 ECOPIA,RP22
RPS22	750QWU	9242	04/12/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RPS22	750QWU	9242	04/12/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS22	750QWU	9242	04/12/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RPS22	750QWU	9242	04/12/2018	TYRES	15	77000232		BRIAUS01		4.42E+09	CASE STOCK 11R22.5 ECOPIA,RP22
RPS22	750QWU	9463	04/27/2018	TRA	1	LABOUR	Labour				0
RPS22	750QWU	9463	04/27/2018	TRB	1	LABOUR	Labour				0
RPS22	750QWU	9463	04/27/2018	TRB	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	9463	04/27/2018	TRB	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	9463	04/27/2018	TRB	16	CON		YAT	Consumables		
RPS22	750QWU	9463	04/27/2018	TRB	SERVICE COMPLETED.						
RPS22	750QWU	9571	05/03/2018	TYRES	15	77000180		BRIAUS01		EX00005013	CASE STOCK 11-22.5,RP22
RPS22	750QWU	9571	05/03/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RPS22	750QWU	9571	05/03/2018	TYRES	15	33000085		YAT	ROTATE TBR TYRE		
RPS22	750QWU	9571	05/03/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RPS22	750QWU	9571	05/03/2018	TYRES	15	77000180		BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP22
RPS22	750QWU	9896	05/24/2018	TRA	1	LABOUR	Labour				0
RPS22	750QWU	9896	05/24/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	9896	05/24/2018	TRA	0	LABOUR	TRADEA	Labour - Internal			
RPS22	750QWU	9896	05/24/2018	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	9896	05/24/2018	TRA	SERVICE COMPLETED. FIT UP 460MM OF 'F' TRACK FOR POGO RAIL						
RPS22	750QWU	10386	06/18/2018	TRA	1	LABOUR	MECH	Labour			
RPS22	750QWU	10386	06/18/2018	TRA	0	LABOUR	MECH1	Labour - Internal			

RPS22	750QWU	10386	06/18/2018	TRA	0	LABOUR	TRADEA	Labour - Internal				
RPS22	750QWU	10386	06/18/2018	TRA	8	B310-30KG-PP		YAT	WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH			
RPS22	750QWU	10386	06/18/2018	TRA	16	CON		YAT	Consumables			
RPS22	750QWU	10386	06/18/2018	TRA	SERVICE COMPLETED. FITTED WEIGH GAUGE. REPAIRED POGO RAIL SECTION.							
RPS22	750QWU	10557	06/26/2018	TYRES								
RPS22	750QWU	10557	06/26/2018	TYRES	15	LABOUR	Labour					0
RPS22	750QWU	10557	06/26/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK			
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	COO		JC&SL01		EX00005843	Coolant Allcool K/worth ,RP22	
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	SUND		JC&SL01		EX00005843	SUNDRIES,RP22	
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	LABEXT		JC&SL01		EX00005843	Labour External,RP22	
RPS22	750QWU	11021	07/09/2018	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	LABEXT		JC&SL01		8744	Labour External,RP22	
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	SUND		JC&SL01		8744	SUNDRIES,RP22	
RPS22	750QWU	11021	07/09/2018	FRIVANA	1	COO		JC&SL01		8744	Coolant Allcool K/worth ,RP22	
RPS22	750QWU	11035	07/25/2018	TRA	1	LABOUR	Labour					0
RPS22	750QWU	11035	07/25/2018	TRA	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	11035	07/25/2018	TRA	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	11035	07/25/2018	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva			
RPS22	750QWU	11035	07/25/2018	TRA	16	CON		YAT	Consumables			

RPS22	750QWU	11035	07/25/2018	TRA	SERVICE COMPLETED RH TOP COVER/DOOR MISSING OFF FRIDGE REPLACED 2ND LIGHT FROM BACK OF RIGHT SIDE (CLEARANCE LIGHT) REPLACED REGO LABEL					
RPS22	750QWU	11334	08/10/2018	TYRES		15	33000241	BRIAUS01	EX00006054	SCRAP TYRES TBR,RP22
RPS22	750QWU	11334	08/10/2018	TYRES		15	11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS22	750QWU	11334	08/10/2018	TYRES	R&R TYRES - BRIDGESTONE					
RPS22	750QWU	11334	08/10/2018	TYRES		15	TYRRUN	YAT	Tyre Runouts	
RPS22	750QWU	11334	08/10/2018	TYRES		15	33000241	BRIAUS01	95990856	SCRAP TYRES TBR,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	15W40	JC&SL01	EX00006219	ENGINE OIL,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	COO	JC&SL01	EX00006219	Coolant Allcool K/worth ,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	78-0603	JC&SL01	EX00006219	SB Series Fridge motor fanbelt,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	78-0629	JC&SL01	EX00006219	SB series fridge motor fanbelt,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	Nov-42	JC&SL01	EX00006219	FUEL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	Nov-82	JC&SL01	EX00006219	OIL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	COIL	JC&SL01	EX00006219	COIL CLEAN, EVAPORATOR/CONDENSOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	SUND	JC&SL01	EX00006219	SUNDRIES,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	LABEXT	JC&SL01	EX00006219	Labour External,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	119300	JC&SL01	EX00006219	QTK Fridge A/Filter EMI 3000,RP22
RPS22	750QWU	11583	08/20/2018	GEN	B SERVICE COMPLETED - JC & SL					
RPS22	750QWU	11583	08/20/2018	GEN		39	119300	JC&SL01	8869	QTK Fridge A/Filter EMI 3000,RP22
RPS22	750QWU	11583	08/20/2018	GEN		39	LABEXT	JC&SL01	8869	Labour External,RP22

RPS22	750QWU	11583	08/20/2018	GEN	39	SUND		JC&SL01		8869	SUNDRIES,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	COIL		JC&SL01		8869	COIL CLEAN, EVAPORATOR/CONDENSOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	Nov-82		JC&SL01		8869	OIL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	Nov-42		JC&SL01		8869	FUEL FILTER, FRIDGE MOTOR,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	78-0629		JC&SL01		8869	SB series fridge motor fanbelt,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	78-0603		JC&SL01		8869	SB Series Fridge motor fanbelt,RP22
											Coolant
											Allcool
											K/worth
RPS22	750QWU	11583	08/20/2018	GEN	39	COO		JC&SL01		8869	,RP22
RPS22	750QWU	11583	08/20/2018	GEN	39	15W40		JC&SL01		8869	ENGINE OIL,RP22
RPS22	750QWU	11551	08/27/2018	GEN	39	LABOUR	Labour				0
RPS22	750QWU	11551	08/27/2018	GEN	0	LABOUR	TRADEA	Labour - Internal			
RPS22	750QWU	11551	08/27/2018	GEN	14	82062		YAT	7 Pin Female Trailer Plug		
RPS22	750QWU	11551	08/27/2018	GEN	16	CON		YAT	Consumables		
					REPLACED						
					FEMALE						
					LIGHT						
					PLUG						
					CHECKED						
					ALL						
RPS22	750QWU	11551	08/27/2018	GEN	LIGHTS						
RPS22	750QWU	11994	09/24/2018	TRA	1	LABOUR	Labour				0
RPS22	750QWU	11994	09/24/2018	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	11994	09/24/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	11994	09/24/2018	TRA	13	91700BL		YAT	Clearance Light, LED Amber, Narva		
RPS22	750QWU	11994	09/24/2018	TRA	16	CON		YAT	Consumables		
					SERVICE						
					COMPLET						
					ED						
					REPLACED						
					MARKER						
RPS22	750QWU	11994	09/24/2018	TRA	LIGHT RHS						
RPS22	750QWU	12624	10/29/2018	FRIVANA	1	LABEXT		RIXREF01		EX00006866	Labour External,RP22
RPS22	750QWU	12624	10/29/2018	FRIVANA	1	SUND		RIXREF01		EX00006866	SUNDRIES,RP22
RPS22	750QWU	12624	10/29/2018	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	12624	10/29/2018	FRIVANA	1	SUND		RIXREF01		18392	SUNDRIES,RP22
RPS22	750QWU	12624	10/29/2018	FRIVANA	1	LABEXT		RIXREF01		18392	Labour External,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	PART		RIXREF01		EX00006918	ALTERNATOR BELT,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABEXT		RIXREF01		EX00006918	Labour External,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	SUND		RIXREF01		EX00006918	SUNDRIES,RP22

RPS22	750QWU	12730	11/01/2018	FRIVANA	1	PART		RIXREF01	18411	ALTERNATOR BELT,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABEXT		RIXREF01	18411	Labour External,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	SUND		RIXREF01	18411	SUNDRIES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	EX00010377	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	EX00010473	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	EX00010475	LABOUR & CONSUMABLES,RP22, 27871.0
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	721	LABOUR & CONSUMABLES,RP22, 27871.0
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	710	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	EX00010591	LABOUR & CONSUMABLES,RP22, 27871.0
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	EX00010593	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	743	LABOUR & CONSUMABLES,RP22, 27871.0
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	753	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12730	11/01/2018	FRIVANA	1	LABCON		BRIVAL01	692	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	12843	11/08/2018	FRIVANA	1	LABEXT		RIXREF01	EX00006984	Labour External,RP22
RPS22	750QWU	12843	11/08/2018	FRIVANA	1	SUND		RIXREF01	EX00006984	SUNDRIES,RP22
RPS22	750QWU	12843	11/08/2018	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	12843	11/08/2018	FRIVANA	1	LABEXT		RIXREF01	18479	Labour External,RP22
RPS22	750QWU	12843	11/08/2018	FRIVANA	1	SUND		RIXREF01	18479	SUNDRIES,RP22
RPS22	750QWU	13433	12/13/2018	TRA	1	LABOUR	Labour			0
RPS22	750QWU	13433	12/13/2018	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	13433	12/13/2018	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	13433	12/13/2018	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	13433	12/13/2018	TRA	SERVICE COMPLETED RE POPRIVETED METAL SHEET INSIDE VAN THAT COVERS TOP CORNER FROM FRONT TO BACK					
RPS22	750QWU	13417	12/14/2018	TYRES	15	77000180		BRIAUS01	EX00007311	CASE STOCK 11-22.5,RP22
RPS22	750QWU	13417	12/14/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187	
RPS22	750QWU	13417	12/14/2018	TYRES	R&R TYRES					
RPS22	750QWU	13417	12/14/2018	TYRES	15	77000180		BRIAUS01	96404595	CASE STOCK 11-22.5,RP22

RPS22	750QWU	13687	12/19/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007420	Labour External,RP22
RPS22	750QWU	13687	12/19/2018	FRIVANA	1	SUND	RIXREF01		EX00007420	SUNDRIES,RP22
RPS22	750QWU	13687	12/19/2018	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	13687	12/19/2018	FRIVANA	1	SUND	RIXREF01		18800	SUNDRIES,RP22
RPS22	750QWU	13687	12/19/2018	FRIVANA	1	LABEXT	RIXREF01		18800	Labour External,RP22
RPS22	750QWU	13926	12/21/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007572	Labour External,RP22
RPS22	750QWU	13926	12/21/2018	FRIVANA	1	SUND	RIXREF01		EX00007572	SUNDRIES,RP22
RPS22	750QWU	13926	12/21/2018	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	13926	12/21/2018	FRIVANA	1	SUND	RIXREF01		18805	SUNDRIES,RP22
RPS22	750QWU	13926	12/21/2018	FRIVANA	1	LABEXT	RIXREF01		18805	Labour External,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	FILKIT	BRIVAL01		EX00007794	FILTER KIT FRIDGE,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	CON	BRIVAL01		EX00007794	Consumab les ,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	PART	BRIVAL01		EX00007794	ALTERNATOR,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	LABEXT	BRIVAL01		EX00007794	Labour External,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	40	3413005	YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	14362	12/24/2018	FRIVANSE	13	GRILL	YAT	SB HONEYCOMB GRILL		
RPS22	750QWU	14362	12/24/2018	FRIVANSE	SERVICE COMPLETED R&R U/S ALTERNATOR FITTED HONEYCOMB GRILL CALIBRATED UNIT					
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	LABEXT	BRIVAL01		21	Labour External,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	PART	BRIVAL01		21	ALTERNATOR,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	CON	BRIVAL01		21	Consumab les ,RP22
RPS22	750QWU	14362	12/24/2018	FRIVANSE	1	FILKIT	BRIVAL01		21	FILTER KIT FRIDGE,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	60-298	BRIVAL01		EX00007631	THROTTLE VALVE KIT,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	66-1116	BRIVAL01		EX00007631	THROTTLE VALVE SPRING,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	R404A	BRIVAL01		EX00007631	GAS R404A,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	LABEXT	BRIVAL01		EX00007631	Labour External,RP22

RPS22	750QWU	14027	12/28/2018	GEN	UNIT LOW ON GAS - TRACED TO LEAKING THROTTLE VALVE REPLACED THROTTLE ASSEMBLY REGASED					
RPS22	750QWU	14027	12/28/2018	GEN	39	LABEXT	BRIVAL01	27	Labour External,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	R404A	BRIVAL01	27	GAS R404A,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	66-1116	BRIVAL01	27	THROTTLE VALVE SPRING,RP22
RPS22	750QWU	14027	12/28/2018	GEN	39	60-298	BRIVAL01	27	THROTTLE VALVE KIT,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	119342	QTKGRO01	EX00007656	FUEL FILTER ASSEMBLY, EMI 3000,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	119300	QTKGRO01	EX00007656	QTK Fridge A/Filter EMI 3000,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	39	914159	QTKGRO01	EX00007656	VIBRATION ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	917709	QTKGRO01	EX00007656	ISOLATOR ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	PART	QTKGRO01	EX00007656	HOSE 1-1/8ID X 6.00 WATER,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	914043	QTKGRO01	EX00007656	SNUBBER ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	CON	QTKGRO01	EX00007656	Consumables ,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	ENVLEV	QTKGRO01	EX00007656	ENVIRONMENTAL LEVY,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	CC	QTKGRO01	EX00007656	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	LABEXT	QTKGRO01	EX00007656	Labour External,RP22

RPS22	750QWU	14108	01/15/2019	FRIVANSE	COMPLETED REPLACED OIL & FILTERS R&R WORN ENGINE MOUNTS REPLACED DAMAGED HOSE FROM TUBE TUBE TO ENGINE CALIBRATED UNIT WARRANTY HEAD GASKET FAILED - R&R ENGINE AS REQUIRED

RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	LABEXT	QTKGRO01	SI-139263	Labour External,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	CC	QTKGRO01	SI-139263	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	ENVLEV	QTKGRO01	SI-139263	ENVIRONMENTAL LEVY,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	CON	QTKGRO01	SI-139263	Consumables ,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	914043	QTKGRO01	SI-139263	SNUBBER ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	PART	QTKGRO01	SI-139263	HOSE 1-1/8ID X 6.00 WATER,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	917709	QTKGRO01	SI-139263	ISOLATOR ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	39	914159	QTKGRO01	SI-139263	VIBRATION ENGINE MOUNT FRIDGE SB310,RP22
RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	119300	QTKGRO01	SI-139263	QTK Fridge A/Filter EMI 3000,RP22

RPS22	750QWU	14108	01/15/2019	FRIVANSE	1	119342	QTKGRO01	SI-139263	FUEL FILTER ASSEMBLY, EMI 3000,RP22
RPS22	750QWU	14276	01/18/2019	FRIVANA	1	LABEXT	BRIVAL01	EX00007734	Labour External,RP22
RPS22	750QWU	14276	01/18/2019	FRIVANA	1	CON	BRIVAL01	EX00007734	Consumab les ,RP22
RPS22	750QWU	14276	01/18/2019	FRIVANA	SERVICE COMPLETED				
RPS22	750QWU	14276	01/18/2019	FRIVANA	1	CON	BRIVAL01	47	Consumab les ,RP22
RPS22	750QWU	14276	01/18/2019	FRIVANA	1	LABEXT	BRIVAL01	47	Labour External,RP22
RPS22	750QWU	14274	01/18/2019	GEN	39	LABEXT	BRIVAL01	EX00007732	Labour External,RP22
RPS22	750QWU	14274	01/18/2019	GEN	39	91-0373	BRIVAL01	EX00007732	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	14274	01/18/2019	GEN	REPLACED U/S DISCHARGE CLAMPS FOUND UNIT LOW COOLANT CODE 37 - TRACED FAULT TO U/S HEAD GASKET - SENT TO THERMO KING FOR WARRANTY ENGINE REPLACEMENT				
RPS22	750QWU	14274	01/18/2019	GEN	39	91-0373	BRIVAL01	48	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	14274	01/18/2019	GEN	39	LABEXT	BRIVAL01	48	Labour External,RP22
RPS22	750QWU	14367	01/23/2019	FRIVANA	1	LABEXT	BRIVAL01	EX00007803	Labour External,RP22
RPS22	750QWU	14500	01/23/2019	FRIVANA	1	FLECHE	BRIVAL01	EX00007880	FLEET CHECK LABOUR/CONS,RP22
RPS22	750QWU	14556	01/23/2019	FRIVANA	1	LABCON	BRIVAL01	EX00007908	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	14367	01/23/2019	FRIVANA	40	3413005	YAT	OIL 15W-40, CK 4/E9	

RPS22	750QWU	14500	01/23/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	14556	01/23/2019	FRIVANA	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	14367	01/23/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	14500	01/23/2019	FRIVANA	1	FLECHE		BRIVAL01		75	FLEET CHECK LABOUR/CONS,RP22
RPS22	750QWU	14556	01/23/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	14367	01/23/2019	FRIVANA	1	LABEXT		BRIVAL01		69	Labour External,RP22
RPS22	750QWU	14556	01/23/2019	FRIVANA	1	LABCON		BRIVAL01		77	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	14227	01/24/2019	TRA	1	LABOUR	Labour				0
RPS22	750QWU	14227	01/24/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	14227	01/24/2019	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	14227	01/24/2019	TRA	SERVICE COMPLETED						
RPS22	750QWU	14349	01/30/2019	FRIVANA	1	LABEXT		BRIVAL01		EX00007785	Labour External,RP22
RPS22	750QWU	14632	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		EX00007925	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	14349	01/30/2019	FRIVANA	1	CON		BRIVAL01		EX00007785	Consumables,RP22
RPS22	750QWU	14632	01/30/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	14349	01/30/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	14632	01/30/2019	FRIVANA	1	LABCON		BRIVAL01		96	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	14349	01/30/2019	FRIVANA	1	CON		BRIVAL01		56	Consumables,RP22
RPS22	750QWU	14349	01/30/2019	FRIVANA	1	LABEXT		BRIVAL01		56	Labour External,RP22
RPS22	750QWU	14273	01/30/2019	GEN	39	8452372		QTKGRO01		EX00007730	HMI 3 & GASKET WEST NEWX,RP22
RPS22	750QWU	14273	01/30/2019	GEN	PARTS ONLY						
RPS22	750QWU	14273	01/30/2019	GEN	39	8452372		QTKGRO01		SI-140307	HMI 3 & GASKET WEST NEWX,RP22
RPS22	750QWU	15563	02/08/2019	FRIVANA	1	LABCON		BRIVAL01		EX00008490	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15563	02/08/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	15563	02/08/2019	FRIVANA	1	LABCON		BRIVAL01		102	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	14729	02/08/2019	GEN	39	CON		BRIVAL01		EX00008001	Consumables,RP22
RPS22	750QWU	14729	02/08/2019	GEN	39	LABEXT		BRIVAL01		EX00008001	Labour External,RP22
RPS22	750QWU	14729	02/08/2019	GEN	UNIT NOT STARTING - REPLACED U/S HMI CONTROLLER (EXODAS SUPPLIED)						
RPS22	750QWU	14729	02/08/2019	GEN	13	8452372		YAT	HMI 3 & GASKET WEST NEWX		
RPS22	750QWU	14729	02/08/2019	GEN	39	LABEXT		BRIVAL01		113	Labour External,RP22
RPS22	750QWU	14729	02/08/2019	GEN	39	CON		BRIVAL01		113	Consumables,RP22
RPS22	750QWU	14868	02/20/2019	GEN	39	LABEXT		BRIVAL01		EX00008112	Labour External,RP22

RPS22	750QWU	14868	02/20/2019	GEN	CARRIED OUT DIAGNOSTIC DOWNLOAD FORWARDED TO WARREN FOUND UNIT WITH U/S BATTERY REPLACED BATTERY							
RPS22	750QWU	14868	02/20/2019	GEN	13	NX120-7		YAT	BATTERY			
RPS22	750QWU	14868	02/20/2019	GEN	39	LABEXT		BRIVAL01		126	Labour External,RP22	
RPS22	750QWU	15042	02/28/2019	FRIVANA	1	LABCON		BRIVAL01		EX00008215	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15042	02/28/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	15042	02/28/2019	FRIVANA	1	LABCON		BRIVAL01		157	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15781	03/01/2019	FRIVANA	1	LABCON		BRIVAL01		EX00008586	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15781	03/01/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	15781	03/01/2019	FRIVANA	1	LABCON		BRIVAL01		242	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15140	03/04/2019	BEARPK	0	LABOUR	MECH	Labour - Internal				
RPS22	750QWU	14993	03/04/2019	EXOINS	1	LABOUR	Labour					0
RPS22	750QWU	14993	03/04/2019	EXOINS	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	14993	03/04/2019	EXOINS	PASSED 1ST INSPECTION							
RPS22	750QWU	14992	03/04/2019	TRA	1	LABOUR	Labour					0
RPS22	750QWU	14992	03/04/2019	TRB	1	LABOUR	Labour					0
RPS22	750QWU	14992	03/04/2019	TRC	1	LABOUR	Labour					0
RPS22	750QWU	14992	03/04/2019	TRC	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	14992	03/04/2019	TRC	0	LABOUR	APPREN	Labour - Internal				
RPS22	750QWU	14992	03/04/2019	TRC	0	LABOUR	TRADEA	Labour - Internal				
RPS22	750QWU	14992	03/04/2019	TRC	10	FQ7750A		YAT	Air Bag Bellow, Type 36, BPW			
RPS22	750QWU	14992	03/04/2019	TRC	11	2.57E+08		YAT	Hub Seal Grease, BPW, Eco Plus			
RPS22	750QWU	14992	03/04/2019	TRC	2	106834		YAT	SPRING BRAKE VALVE, SR3, TRAILER			
RPS22	750QWU	14992	03/04/2019	TRC	13	91622		YAT	LED Marker light. Amber. Narva			
RPS22	750QWU	14992	03/04/2019	TRC	16	CON		YAT	Consumables			

RPS22	750QWU	14992	03/04/2019	TRC	COMPLETED TENSIONED ALL UBOLTS, SPRING EYE BOLTS & SHOCK BOLTS REPLACED LHS MIDDLE AIRBAG CLEANED ALL BEARINGS & REPLACED ALL GREASE & SEALS (BEARINGS WASHED BY AUSTIN) REPLACED					
RPS22	750QWU	15900	03/05/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00008384	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	169	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00008634	LABOUR & CONSUMABLES,RP22, HOURS 26137	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	244	LABOUR & CONSUMABLES,RP22, HOURS 26137	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00008689	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00008807	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00008808	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	285	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	286	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	257	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	EX00009293	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON	BRIVAL01	417	LABOUR & CONSUMABLES,RP22	

RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009446	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009475	LABOUR & CONSUMABLES,RP22, 26967.0
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009473	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009474	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	309	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	436	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	437	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	431	LABOUR & CONSUMABLES,RP22, 26967.0
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009583	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009584	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009585	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	479	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	478	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	480	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009721	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009720	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009751	LABOUR & CONSUMABLES,RP22, 27342.0
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	537	LABOUR & CONSUMABLES,RP22, 27342.0
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	509	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	508	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009964	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	15399	03/08/2019	FRIVANA	1	LABCON		BRIVAL01	581	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	16025	03/27/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	15828	03/27/2019	GEN	39	LABEXT		BRIVAL01	EX00008603	Labour External,RP22
RPS22	750QWU	15828	03/27/2019	GEN	CARRIED OUT DIAGNOSTIC DOWNLOAD OF SELECTED PERIOD - 01/03/19 TO 15/3/19 FORWARDED TO WARREN					
RPS22	750QWU	15828	03/27/2019	GEN	39	LABEXT		BRIVAL01	227	Labour External,RP22
RPS22	750QWU	16249	04/02/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	16254	04/03/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	16074	04/08/2019	TRA	1	LABOUR	Labour			0

RPS22	750QWU	16074	04/08/2019	TRB	1	LABOUR	Labour			0
RPS22	750QWU	16074	04/08/2019	TRB	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	16074	04/08/2019	TRB	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	16074	04/08/2019	TRB	0	LABOUR	TRADEA	Labour - Internal		
RPS22	750QWU	16074	04/08/2019	TRB	16	CON		YAT	Consumables	
RPS22	750QWU	16074	04/08/2019	TRB	SERVICE COMPLETED AUSTIN POLISHED THE SIDES					
RPS22	750QWU	17374	04/09/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	16817	05/18/2019	GEN	39	LABOUR	Labour			0
RPS22	750QWU	16817	05/18/2019	GEN	0	LABOUR	MECH	Labour - Internal		
RPS22	750QWU	16817	05/18/2019	GEN	16	CON		YAT	Consumables	
RPS22	750QWU	16817	05/18/2019	GEN	FITTED NEW BATTERY TO FRIDGE TENSIONED/REPAIRED ALTERNATOR					
RPS22	750QWU	16817	05/18/2019	GEN	14	SS70ZZM		YAT	Battery 12v	
RPS22	750QWU	17128	05/27/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	17433	05/29/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	17077	05/29/2019	TRA	1	LABOUR	Labour			0
RPS22	750QWU	17077	05/29/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	17077	05/29/2019	TRA	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	17077	05/29/2019	TRA	16	CON		YAT	Consumables	

RPS22	750QWU	17077	05/29/2019	TRA	SERVICE COMPLETED REPAIRED F TRACK RHS REPLACED LHS FRONT AIRBAG RHS FRONT & RHS REAR AIRBAGS HAVE SLIGHT LEAKS NO MORE BAGS IN STOCK					
RPS22	750QWU	17077	05/29/2019	TRA		10	SP0022ASPM	YAT	AIRBAG ASSBLY D36 PLASTIC PISTON	
RPS22	750QWU	17449	05/30/2019	FRIVANA	SERVICE COMPLETED					
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	FILKIT	BRIVAL01	EX00009292	FILTER KIT FRIDGE,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	41-7063	BRIVAL01	EX00009292	SWITCH PRESS OIL,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	119299	BRIVAL01	EX00009292	AIR FILTER, EMI 3000,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	CON	BRIVAL01	EX00009292	Consumables,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	CON	BRIVAL01	EX00009292	Consumables,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	LABEXT	BRIVAL01	EX00009292	Labour External,RP22

RPS22	750QWU	17121	05/30/2019	FRIVANSE	BVR - SERVICE COMPLETED CALIBRATED UNIT R&R OIL PRESSURE SWITCH, AIR FILTER HOUSING						
RPS22	750QWU	17121	05/30/2019	FRIVANSE		40	3413005	YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	LABEXT	BRIVAL01		423	Labour External,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	CON	BRIVAL01		423	Consumables,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	CON	BRIVAL01		423	Consumables,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	119299	BRIVAL01		423	AIR FILTER, EMI 3000,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	41-7063	BRIVAL01		423	SWITCH PRESS OIL,RP22
RPS22	750QWU	17121	05/30/2019	FRIVANSE		1	FILKIT	BRIVAL01		423	FILTER KIT FRIDGE,RP22
RPS22	750QWU	17464	05/31/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	17117	05/31/2019	TYRES		15	77000180	BRIAUS01		EX00009280	CASE STOCK 11-22.5,RP22
RPS22	750QWU	17117	05/31/2019	TYRES		15	11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS22	750QWU	17117	05/31/2019	TYRES	R&R TYRES PLUS ROTATION						
RPS22	750QWU	17117	05/31/2019	TYRES		15	77000180	BRIAUS01		96922004	CASE STOCK 11-22.5,RP22
RPS22	750QWU	17733	06/10/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	17761	06/11/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	17775	06/14/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18059	06/20/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18072	06/21/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	17930	06/25/2019	GEN		39	78-603	BRIVAL01		EX00009693	SB Fridge Fan belt,RP22
RPS22	750QWU	17930	06/25/2019	GEN		39	78-629	BRIVAL01		EX00009693	BELT,RP22
RPS22	750QWU	17930	06/25/2019	GEN		39	CON	BRIVAL01		EX00009693	Consumables,RP22
RPS22	750QWU	17930	06/25/2019	GEN		39	LABEXT	BRIVAL01		EX00009693	Labour External,RP22
RPS22	750QWU	17930	06/25/2019	GEN	BVR - REPLACED U/S DRIVE BELTS						
RPS22	750QWU	17930	06/25/2019	GEN		39	78-603	BRIVAL01		490	SB Fridge Fan belt,RP22

RPS22	750QWU	17930	06/25/2019	GEN	39	78-629		BRIVAL01		490	BELT,RP22
RPS22	750QWU	17930	06/25/2019	GEN	39	CON		BRIVAL01		490	Consumables,RP22
RPS22	750QWU	17930	06/25/2019	GEN	39	LABEXT		BRIVAL01		490	Labour External,RP22
RPS22	750QWU	18201	06/28/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18615	07/05/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18683	07/11/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18708	07/15/2019	FRIVANA	1	LABCON		BRIVAL01		EX00009958	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	18708	07/15/2019	FRIVANA	1	LABCON		BRIVAL01		EX00009962	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	18708	07/15/2019	FRIVANA	SERVICE COMPLETED						
RPS22	750QWU	18708	07/15/2019	FRIVANA	1	LABCON		BRIVAL01		580	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	18708	07/15/2019	FRIVANA	1	LABCON		BRIVAL01		568	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	18551	07/22/2019	DEFECT	1	LABOUR	MECH	Labour			
RPS22	750QWU	18551	07/22/2019	DEFECT	Reported Defect :- Defect Code : 00002583 Defect Reference : WO17077 Date : 29/05/2019 Description of Defect : RHS FRONT & RHS REAR AIRBAGS HAVE SLIGHT LEAKS NO MORE BAGS IN STOCK VERY MINOR						

RPS22	750QWU	18551	07/22/2019	TRA	1	LABOUR	Labour					0
RPS22	750QWU	18551	07/22/2019	TRA	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	18551	07/22/2019	TRA	16	CON		YAT	Consumables			
RPS22	750QWU	18551	07/22/2019	TRA	SERVICE COMPLETED							
RPS22	750QWU	19560	08/15/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	19759	08/22/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	19682	08/26/2019	DEFECT	1	LABOUR	MECH	Labour				
RPS22	750QWU	19682	08/26/2019	DEFECT	Reported Defect :- Defect Code : 00002833 Defect Reference : 07328 Date : 05/08/2019 Description of Defect : TRAILER PLUG HAS MULTIPLE BROKEN PINS							
RPS22	750QWU	19780	08/26/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	19682	08/26/2019	TRA	1	LABOUR	Labour					0
RPS22	750QWU	19682	08/26/2019	TRA	0	LABOUR	MECH1	Labour - Internal				
RPS22	750QWU	19682	08/26/2019	TRA	16	CON		YAT	Consumables			
RPS22	750QWU	19682	08/26/2019	TRA	SERVICE COMPLETED							
RPS22	750QWU	19993	08/27/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	20005	08/29/2019	FRIVANA	SERVICE COMPLETED							
RPS22	750QWU	20215	09/09/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010733	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	20215	09/09/2019	FRIVANA	Service Completed							
RPS22	750QWU	20215	09/09/2019	FRIVANA	1	LABCON		BRIVAL01		827	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	20110	09/09/2019	TYRES	15	77000180		BRIAUS01		EX00010643	CASE STOCK 11-22.5,RP22	
RPS22	750QWU	20110	09/09/2019	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187			
RPS22	750QWU	20110	09/09/2019	TYRES	R&R TYRES POS 21/22							
RPS22	750QWU	20110	09/09/2019	TYRES	15	77000180		BRIAUS01		97252844	CASE STOCK 11-22.5,RP22	

RPS22	750QWU	20334	09/18/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010753	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20334	09/18/2019	FRIVANA	Service Completed BVR 17.09.2019					
RPS22	750QWU	20334	09/18/2019	FRIVANA	1	LABCON		BRIVAL01	868	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20389	09/19/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010774	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20389	09/19/2019	FRIVANA	SERVICE COMPLETED BVR 16.09.2019					
RPS22	750QWU	20389	09/19/2019	FRIVANA	1	LABCON		BRIVAL01	867	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20411	09/23/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010775	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20411	09/23/2019	FRIVANA	SERVICE COMPLETED BVR 19.09.2019					
RPS22	750QWU	20411	09/23/2019	FRIVANA	1	LABCON		BRIVAL01	890	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20962	09/30/2019	FRIVANA	1	LABCON		BRIVAL01	EX00011120	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20962	09/30/2019	FRIVANA	SERVICE COMPLETED BVR 30.09.2019					
RPS22	750QWU	20962	09/30/2019	FRIVANA	1	LABCON		BRIVAL01	938	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20632	10/01/2019	TRA	1	LABOUR	Labour			0
RPS22	750QWU	20632	10/01/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	20632	10/01/2019	TRA	10	MONF5002		YAT	SHOCK ABSORBER TO SUIT BPW LONG	
RPS22	750QWU	20632	10/01/2019	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	20632	10/01/2019	TRA	SERVICE COMPLETED R&R ST AXLE SHOCKS x2 ATTACHED ACUFF BAND BACK TO WALL INSIDE TRAILER TIGHTENED MUD GUARDS RIVETED CARGO RAIL BACK TO WALL INSIDE TRAILER					
RPS22	750QWU	20632	10/01/2019	TRB	1	LABOUR	Labour			0
RPS22	750QWU	20813	10/03/2019	FRIVANA	1	LABCON		BRIVAL01	EX00011043	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20829	10/03/2019	FRIVANA	1	LABCON		BRIVAL01	EX00011044	LABOUR & CONSUMABLES,RP22

RPS22	750QWU	20813	10/03/2019	FRIVANA	SERVICE COMPLETED BVR 02.10.2019					
RPS22	750QWU	20829	10/03/2019	FRIVANA	SERVICE COMPLETED BVR 01.10.2019					
RPS22	750QWU	20813	10/03/2019	FRIVANA	1	LABCON	BRIVAL01		953	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20829	10/03/2019	FRIVANA	1	LABCON	BRIVAL01		948	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	LABEXT	BRIVAL01		EX00011112	Labour External,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	CON	BRIVAL01		EX00011112	Consumables,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	FILKIT	BRIVAL01		EX00011112	FILTER KIT FRIDGE,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	Nov-80	BRIVAL01		EX00011112	HAND PRIMER,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	SERVICE COMPLETED CALIBRATED UNIT R&R HAND PRIMER					
RPS22	750QWU	20936	10/04/2019	FRIVANSE	40	3413005	YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	Nov-80	BRIVAL01		962	HAND PRIMER,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	FILKIT	BRIVAL01		962	FILTER KIT FRIDGE,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	CON	BRIVAL01		962	Consumables,RP22
RPS22	750QWU	20936	10/04/2019	FRIVANSE	1	LABEXT	BRIVAL01		962	Labour External,RP22
RPS22	750QWU	21034	10/09/2019	FRIVANA	1	LABCON	BRIVAL01		EX00011142	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	21034	10/09/2019	FRIVANA	SERVICE COMPLETED 09.10.2019					
RPS22	750QWU	21034	10/09/2019	FRIVANA	1	LABCON	BRIVAL01		973	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20985	10/15/2019	FRIVANA	1	LABCON	BRIVAL01		EX00011121	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	20985	10/15/2019	FRIVANA	SERVICE COMPLETED BVR 10.10.2019					
RPS22	750QWU	20985	10/15/2019	FRIVANA	1	LABCON	BRIVAL01		995	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	21188	10/16/2019	TYRES	15	33000241	BRIAUS01		EX00011225	SCRAP TYRES TBR,RP22
RPS22	750QWU	21188	10/16/2019	TYRES	15	11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RPS22	750QWU	21188	10/16/2019	TYRES	15	33000370	YAT	TYRE HELD FOR RUNOUT		
RPS22	750QWU	21188	10/16/2019	TYRES	R&R TYRES 31,32					
RPS22	750QWU	21188	10/16/2019	TYRES	15	33000241	BRIAUS01		97448412	SCRAP TYRES TBR,RP22
RPS22	750QWU	21481	10/17/2019	GEN	39	LABEXT	BRIVAL01		EX00011277	Labour External,RP22
RPS22	750QWU	21481	10/17/2019	GEN	39	CON	BRIVAL01		EX00011277	Consumables,RP22
RPS22	750QWU	21481	10/17/2019	GEN	39	78-1360	BRIVAL01		EX00011277	ALTERNATOR BELT FRIDGE,RP22
RPS22	750QWU	21481	10/17/2019	GEN	BVR - REPLACED ALTERNATOR BELT DUE TO CRACKING, CLEANED COILS, PASSED PRETRIP					
RPS22	750QWU	21481	10/17/2019	GEN	39	78-1360	BRIVAL01		1025	ALTERNATOR BELT FRIDGE,RP22

RPS22	750QWU	21481	10/17/2019	GEN	39	CON		BRIVAL01		1025	Consumables,RP22
RPS22	750QWU	21481	10/17/2019	GEN	39	LABEXT		BRIVAL01		1025	Labour External,RP22
RPS22	750QWU	21076	10/18/2019	FRIVANA	1	LABCON		BRIVAL01		EX00011157	LABOUR & CONSUMABLES,RP22, 28347
RPS22	750QWU	21076	10/18/2019	FRIVANA	SERVICE COMPLETED BVR 16.10.2019						
RPS22	750QWU	21076	10/18/2019	FRIVANA	1	LABCON		BRIVAL01		1031	LABOUR & CONSUMABLES,RP22, 28347
RPS22	750QWU	21828	11/04/2019	TRA	1	LABOUR	Labour				0
RPS22	750QWU	21828	11/04/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	21828	11/04/2019	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	21828	11/04/2019	TRA	13	91700BL		YAT	Clearance Light, LED Amber, Narva		
RPS22	750QWU	21828	11/04/2019	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	21828	11/04/2019	TRA	SERVICE COMPLETED REPALCED RHS MIDDLE SIDE MARKER LIGHT REPLACED LHS FRONT AXLE MUDFLAP & ANTI SAIL BRACKET (BOTH 2ND HAND)						
RPS22	750QWU	22251	11/05/2019	FRIVANA	1	LABCON		BRIVAL01		EX00011553	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	22251	11/05/2019	FRIVANA	SERVICE COMPLETED BVR 05.11.2019						
RPS22	750QWU	22251	11/05/2019	FRIVANA	1	LABCON		BRIVAL01		1122	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	23008	12/12/2019	TRA	1	LABOUR	Labour				0

RPS22	750QWU	23008	12/12/2019	TRA	SERVICE COMPLETED BY BEN 12.12.19 CARRIED OUT A SERVICE REPLACED AIR BAGS REAR AXLE X 2							
RPS22	750QWU	23008	12/12/2019	TRA		0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	23008	12/12/2019	TRA		13	TRP8066		YAT	AIR SPRING TRP BPW D36		
RPS22	750QWU	23008	12/12/2019	TRA		16	CON		YAT	Consumables		
RPS22	750QWU	23744	01/08/2020	WEICAL		0	LABOUR	Labour				0
RPS22	750QWU	23744	01/08/2020	WEICAL	AIR GAUGE: 16.5 ADJUSTED: 17.75 WEIGHBRIDGE: 17.4 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.							
RPS22	750QWU	23814	01/10/2020	FVGEN		13	CON		BRIVAL01	EX00012389	RP22,	
RPS22	750QWU	23814	01/10/2020	FVGEN		13	LABEXT		BRIVAL01	EX00012389	RP22,	

RPS22	750QWU	23814	01/10/2020	FVGEN	ED BY BVR 10.01.2020 INVOICE # 00001438 UNIT FOUND WITH WATER LEAK IN ZONE 2 TRACED TO CRACKED DRAIN HOSE RECONNECTED FITTING AND RESEALED PIPING UNIT RUN ON TEST PRETRIP PASSED					
RPS22	750QWU	23814	01/10/2020	FVGEN		13	LABEXT	BRIVAL01	1438	RP22,
RPS22	750QWU	23814	01/10/2020	FVGEN		13	CON	BRIVAL01	1438	RP22,
RPS22	750QWU	24096	01/23/2020	GEN		15	33000517	BRIAUS01	EX00012591	RP22,REMOVAL: CUSTOMER PULL POINT
RPS22	750QWU	24096	01/23/2020	GEN		15	77000180	BRIAUS01	EX00012591	RP22,CASE STOCK 11-22.5
RPS22	750QWU	24096	01/23/2020	GEN		15	11001464	BRIAUS01	EX00012591	RP22,TYRE 11R22.5 148/145L 16 BS R187
RPS22	750QWU	24096	01/23/2020	GEN		15	33000084	BRIAUS01	EX00012591	RP22,FIT TBR TYRE

RPS22	750QWU	24096	01/23/2020	GEN	COMPLETED BY BRIDGESTONE 23.01.2020 INVOICE # 97963479					
RPS22	750QWU	24096	01/23/2020	GEN		15	33000084	BRIAUS01	97963479	RP22,FIT TBR TYRE
RPS22	750QWU	24096	01/23/2020	GEN		15	11001464	BRIAUS01	97963479	RP22,TYRE 11R22.5 148/145L 16 BS R187
RPS22	750QWU	24096	01/23/2020	GEN		15	77000180	BRIAUS01	97963479	RP22,CASE STOCK 11-22.5
RPS22	750QWU	24096	01/23/2020	GEN		15	33000517	BRIAUS01	97963479	RP22,REMOVAL: CUSTOMER PULL POINT
RPS22	750QWU	24212	01/24/2020	FVGEN		13	CON	BRIVAL01	EX00012651	RP22,
RPS22	750QWU	24212	01/24/2020	FVGEN		13	LABEXT	BRIVAL01	EX00012651	RP22,
RPS22	750QWU	24212	01/24/2020	FVGEN	COMPLETED BY BVR 24.01.2020 INVOICE # 00001516 UNIT HAD CODES FOR ZONE / COIL SENSOR FAULT TRACED TO FAULTY CONTROLLER CLEANED PINS ON BOARD UNIT RUN ON TEST PRE TRIP PASSED					

RPS22	750QWU	24212	01/24/2020	FVGEN	13	LABEXT		BRIVAL01		1516	RP22,
RPS22	750QWU	24212	01/24/2020	FVGEN	13	CON		BRIVAL01		1516	RP22,
RPS22	750QWU	24261	02/04/2020	TRA	1	LABOUR	Labour				0
RPS22	750QWU	24261	02/04/2020	TRA	SERVICE COMPLETED BY SEAN / MICK 04.02.2020						
RPS22	750QWU	24261	02/04/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	24261	02/04/2020	TRA	0	LABOUR	MECH	Labour - Internal			
RPS22	750QWU	24261	02/04/2020	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	24446	02/11/2020	FVGEN	13	78-1362		BRIVAL01		EX00012807	RP22,EVAPORTAOR FAN
RPS22	750QWU	24446	02/11/2020	FVGEN	16	CON		BRIVAL01		EX00012807	RP22,
RPS22	750QWU	24446	02/11/2020	FVGEN	13	LABEXT		BRIVAL01		EX00012807	RP22,
RPS22	750QWU	24446	02/11/2020	FVGEN	COMPLETED BY BVR 11.02.2020 INVOICE # 00001583 UNIT FOUND WITH CODE 112 - CHECK FANS TRACED TO FAULTY EVAPORATOR FAN IN ZONE 2 REPLACED UNSERVICABLE FAN UNIT RUN ON TEST PRETRIP PASSED						

RPS22	750QWU	24446	02/11/2020	FVGEN	13	LABEXT	BRIVAL01	1583	RP22,
RPS22	750QWU	24446	02/11/2020	FVGEN	16	CON	BRIVAL01	1583	RP22,
RPS22	750QWU	24446	02/11/2020	FVGEN	13	78-1362	BRIVAL01	1583	RP22,EVAPORTAOR FAN
RPS22	750QWU	25434	02/11/2020	FVPRE	1	LABCON	BRIVAL01	EX00013288	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	25470	02/11/2020	FVPRE	1	LABCON	BRIVAL01	EX00013289	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	25434	02/11/2020	FVPRE	1	LABCON	BRIVAL01	1575	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	25470	02/11/2020	FVPRE	SERVICE COMPLETED BY BVR 06.02.2020				
RPS22	750QWU	25470	02/11/2020	FVPRE	1	LABCON	BRIVAL01	1576	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	24518	02/12/2020	FVGEN	13	40-0974	BRIVAL01	EX00012834	RP22,GRADED SENSOR
RPS22	750QWU	24518	02/12/2020	FVGEN	16	CON	BRIVAL01	EX00012834	RP22,
RPS22	750QWU	24518	02/12/2020	FVGEN	13	LABEXT	BRIVAL01	EX00012834	RP22,
RPS22	750QWU	24518	02/12/2020	FVGEN	COMPLETED BY BVR 12.02.2020 INVOICE # 00001611 UNIT FOUND WITH EVAPORATOR COIL SENSOR CODES ON ZONE 1 TRACED TO FAULTY SENSOR REMOVED AND REPLACED UNIT RUN ON TEST PRETRIP PASSED				
RPS22	750QWU	24518	02/12/2020	FVGEN	13	LABEXT	BRIVAL01	1611	RP22,
RPS22	750QWU	24518	02/12/2020	FVGEN	16	CON	BRIVAL01	1611	RP22,
RPS22	750QWU	24518	02/12/2020	FVGEN	13	40-0974	BRIVAL01	1611	RP22,GRADED SENSOR

RPS22	750QWU	25158	02/13/2020	FVPRE	1	LABCON		BRIVAL01	EX00013196	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	25549	02/13/2020	FVPRE	1	LABCON		BRIVAL01	EX00013331	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	25158	02/13/2020	FVPRE	SERVICE COMPLETED BY BVR 10.02.2020						
RPS22	750QWU	25549	02/13/2020	FVPRE	SERVICE COMPLETED BY BVR 10.02.2020						
RPS22	750QWU	25158	02/13/2020	FVPRE	1	LABCON		BRIVAL01	1624	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	24931	02/14/2020	WEICAL	0	LABOUR	Labour			0	
RPS22	750QWU	24931	02/14/2020	WEICAL	AIR GAUGE: 14.5 ADJUSTED: 14.75 WEIGHBRIDGE: 14.45						
RPS22	750QWU	24931	02/14/2020	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RPS22	750QWU	25574	02/18/2020	FVPRE	1	LABCON		BRIVAL01	EX00013332	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	25574	02/18/2020	FVPRE	SERVICE COMPLETED BY BVR 14.02.2020						
RPS22	750QWU	25574	02/18/2020	FVPRE	1	LABCON		BRIVAL01	1651	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	24732	02/24/2020	FVGEN	13	78-603		BRIVAL01	EX00012954	RP22,SB Fridge Fan belt	
RPS22	750QWU	24732	02/24/2020	FVGEN	13	78-629		BRIVAL01	EX00012954	RP22,BELT	
RPS22	750QWU	24732	02/24/2020	FVGEN	16	CON		BRIVAL01	EX00012954	RP22,	
RPS22	750QWU	24732	02/24/2020	FVGEN	13	LABEXT		BRIVAL01	EX00012954	RP22,	

					COMPLETED BY BVR 24.02.2020 INVOICE # 00001674						
RPS22	750QWU	24732	02/24/2020	FVGEN	REPLACED UNSERVICEABLE DRIVE BELTS ADJUSTED ALL BELTS UNIT RUN ON TEST PRETRIP PASSED						
RPS22	750QWU	24732	02/24/2020	FVGEN		13	LABEXT		BRIVAL01	1674	RP22,
RPS22	750QWU	24732	02/24/2020	FVGEN		16	CON		BRIVAL01	1674	RP22,
RPS22	750QWU	24732	02/24/2020	FVGEN		13	78-629		BRIVAL01	1674	RP22,BELT
RPS22	750QWU	24732	02/24/2020	FVGEN		13	78-603		BRIVAL01	1674	RP22,SB Fridge Fan belt
RPS22	750QWU	24762	02/25/2020	EXOINS		1	LABOUR	Labour			0

RPS22	750QWU	24762	02/25/2020	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY BILLY 25.02.2020				
RPS22	750QWU	24761	02/25/2020	TRA		1	LABOUR	Labour	0
RPS22	750QWU	24761	02/25/2020	TRA	SERVICE COMPLETED.				
RPS22	750QWU	24761	02/25/2020	TRB		1	LABOUR	Labour	0
RPS22	750QWU	24761	02/25/2020	TRB	SERVICE COMPLETED.				
RPS22	750QWU	24761	02/25/2020	TRC		1	LABOUR	Labour	0

RPS22	750QWU	24761	02/25/2020	TRC	COMPLETED BY BILLY / KEIRAN 25.02.2020 REPLACED LATCH ON FRIDGE DOORS ADJUSTED WHEEL BEARINGS NEED TO CHANGE OUT KINGPIN WHEN STOCK IS AVAILABLE - STILL WITH IN SPECS - JUST HAS A LOT OF						
RPS22	750QWU	24761	02/25/2020	TRC	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	24761	02/25/2020	TRC	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	24761	02/25/2020	TRC	16	CON		YAT	Consumables		
RPS22	750QWU	26093	04/07/2020	FVPRE	1	LABCON		BRIVAL01		EX00013585	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	26093	04/07/2020	FVPRE	SERVICE COMPLETED BY BVR 01.04.2020						
RPS22	750QWU	26093	04/07/2020	FVPRE	1	LABCON		BRIVAL01		1940	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	1	10-417		BRIVAL01		EX00013731	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	1	45-2258		BRIVAL01		EX00013731	120 AMP ALTERNATOR,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	16	CON		BRIVAL01		EX00013731	Consumables,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	1	LABEXT		BRIVAL01		EX00013731	Labour External,RP22

RPS22	750QWU	26385	04/20/2020	FRIVANB	ED BY BVR 20.04.2020 INVOICE # 00002051 UNIT FOUND WITH ALTERNATOR NOT CHARGING REMOVE AND REPLACE UNSERVICEABLE ALTERNATOR B SERVICE OIL 14L (CUSTOMER SUPPLIED) CALIBRATI

RPS22	750QWU	26385	04/20/2020	FRIVANB	1	LABEXT		BRIVAL01		2051	Labour External,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	16	CON		BRIVAL01		2051	Consumables ,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	1	45-2258		BRIVAL01		2051	120 AMP ALTERNATOR,RP22
RPS22	750QWU	26385	04/20/2020	FRIVANB	1	10-417		BRIVAL01		2051	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	26650	05/01/2020	TRA	1	LABOUR	Labour				0
RPS22	750QWU	26650	05/01/2020	TRA		SERVICE COMPLETED BY SEAN / BEN 01.05.2020 REPLACED FIRE EXTINGUISHER REPLACED KINGPIN CHECK AND ADJUSTED ALL WHEEL BEARINGS AN TENSIONED CAPS					
RPS22	750QWU	26650	05/01/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	26650	05/01/2020	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	26650	05/01/2020	TRA	13	KZC1012/01BO		YAT	KING PIN 2" JOST WITH BOLTS		
RPS22	750QWU	26650	05/01/2020	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	26703	05/04/2020	GEN	15	33000517		BRIAUS01		EX00013898	REMOVAL: CUSTOMER PULL POINT,RP22
RPS22	750QWU	26703	05/04/2020	GEN	15	77000180		BRIAUS01		EX00013898	CASE STOCK 11-22.5,RP22
RPS22	750QWU	26703	05/04/2020	GEN	15	99015526		BRIAUS01		EX00013898	RUNOUT TYRE,RP22
RPS22	750QWU	26703	05/04/2020	GEN	15	33000084		BRIAUS01		EX00013898	FIT TBR TYRE,RP22

RPS22	750QWU	26703	05/04/2020	GEN	COMPLETED BY BRIDGESTONE 04.05.2020 INVOICE # 98433229					
RPS22	750QWU	26703	05/04/2020	GEN	15	33000084	BRIAUS01	98433229	FIT TBR TYRE,RP22	
RPS22	750QWU	26703	05/04/2020	GEN	15	99015526	BRIAUS01	98433229	RUNOUT TYRE,RP22	
RPS22	750QWU	26703	05/04/2020	GEN	15	77000180	BRIAUS01	98433229	CASE STOCK 11-22.5,RP22	
RPS22	750QWU	26703	05/04/2020	GEN	15	33000517	BRIAUS01	98433229	REMOVAL: CUSTOMER PULL POINT,RP22	
RPS22	750QWU	27001	05/08/2020	FVPRE	1	LABCON	BRIVAL01	EX00014011	LABOUR & CONSUMABLES,RP22	HOURS = 39738
RPS22	750QWU	27001	05/08/2020	FVPRE	SERVICE COMPLETED BY BVR 01.05.2020					
RPS22	750QWU	27001	05/08/2020	FVPRE	1	LABCON	BRIVAL01	2181	LABOUR & CONSUMABLES,RP22	HOURS = 39738
RPS22	750QWU	27089	05/13/2020	FVPRE	1	LABCON	BRIVAL01	EX00014059	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	27089	05/13/2020	FVPRE	SERVICE COMPLETED BY BVR 07.05.2020					
RPS22	750QWU	27089	05/13/2020	FVPRE	1	LABCON	BRIVAL01	2251	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	27201	05/15/2020	FVPRE	1	LABCON	BRIVAL01	EX00014101	LABOUR & CONSUMABLES,RP22	HOURS = 29929
RPS22	750QWU	27201	05/15/2020	FVPRE	SERVICE COMPLETED BY BVR 11.05.2020					
RPS22	750QWU	27201	05/15/2020	FVPRE	1	LABCON	BRIVAL01	2283	LABOUR & CONSUMABLES,RP22	HOURS = 29929
RPS22	750QWU	28156	06/24/2020	FRIVANA	SERVICE COMPLETED BVR 17/06/2020					
RPS22	750QWU	28164	06/24/2020	FRIVANA	SERVICE COMPLETED BVR 16/06/2020					
RPS22	750QWU	28452	06/24/2020	FRIVANA	1	LABCON	BRIVAL01	EX00014519	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	28452	06/24/2020	FRIVANA	1	LABCON	BRIVAL01	EX00014517	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	28452	06/24/2020	FRIVANA	1	LABCON	BRIVAL01	2574	LABOUR & CONSUMABLES,RP22	
RPS22	750QWU	28452	06/24/2020	FRIVANA	1	LABCON	BRIVAL01	2567	LABOUR & CONSUMABLES,RP22	

RPS22	750QWU	28222	06/26/2020	TRA	service complete d by duane + keiran26/ 06/20 weld both lift legs becuase they both had cracks in them replace rhs mud guard and mud flap						
RPS22	750QWU	28222	06/26/2020	TRA	0	LABOUR	mech1	Labour - Internal			
RPS22	750QWU	28222	06/26/2020	TRA	0	LABOUR	appren	Labour - Internal			
RPS22	750QWU	28222	06/26/2020	TRA	16	con		YAT	Consumables		
RPS22	750QWU	28222	06/26/2020	TRA	13	P/N K127-1116-08A		YAT	Red mudguard Spraysafe		
RPS22	750QWU	28222	06/26/2020	TRA	16	K213-2766		yat	Mudflap		
RPS22	750QWU	28752	07/07/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014799	LABOUR & CONSUMABLES,RP22, HOURS 30325
RPS22	750QWU	28752	07/07/2020	FRIVANA	1	LABCON		BRIVAL01		2677	LABOUR & CONSUMABLES,RP22, HOURS 30325
RPS22	750QWU	28752	07/07/2020	FRIVANA	SERVICE COMPLETED BVR						
RPS22	750QWU	28541	07/10/2020	GEN	1	LABCON		BRIVAL01		EX00014664	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	28541	07/10/2020	GEN	13	PART		BRIVAL01		EX00014664	GRADED AIR SENSOR,RP22

RPS22	750QWU	28541	07/10/2020	GEN	COMPLETED BY BVR 26.06.2020. INV: 00002605. UNIT WAS FOUND WITH MULTIPLE CODES AND NOT COOLING. TRACE FAULT TO RETURN AIR SENSOR. R+R UNSERVICEABLE RETURN AIR SENSOR.				
RPS22	750QWU	28541	07/10/2020	GEN	13	PART	BRIVAL01	2605	GRADED AIR SENSOR,RP22
RPS22	750QWU	28541	07/10/2020	GEN	1	LABCON	BRIVAL01	2605	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	29566	07/27/2020	GEN	1	LABCON	BRIVAL01	EX00015178	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	29566	07/27/2020	GEN	FLEET CHECK COMPLETED BY BVR 27.07.2020				
RPS22	750QWU	29566	07/27/2020	GEN	1	LABCON	BRIVAL01	2862	LABOUR & CONSUMABLES,RP22

RPS22	750QWU	29877	08/24/2020	DEFECT	DEFECT CLEARED BY SEAN 24.08.2020 Defect: 12714 Reported by: Craig B Replace light plug as flap to hold in truck plug RHS.					
RPS22	750QWU	29877	08/24/2020	TRA		1	LABOUR	Labour		0
RPS22	750QWU	29877	08/24/2020	TRA	SERVICE COMPLETED.					
RPS22	750QWU	29877	08/24/2020	TRB		1	LABOUR	MECH1	Labour	

RPS22	750QWU	29877	08/24/2020	TRB	SERVICE COMPLETED BY SEAN AND BEN 24.08.2020 REPLACED FRIDGE BATTERY ADJSUTED ALL WHEEL BEARINGS, TENSIONED HUBCAPS REPALCED FEMALE LIGHT PLUG.

RPS22	750QWU	29877	08/24/2020	TRB	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	29877	08/24/2020	TRB	16	CON		YAT	Consumables	
RPS22	750QWU	29877	08/24/2020	TRB	14	MF70ZZDT		YAT	BATTERY DEEP CYCLE & TRUCK	
RPS22	750QWU	30164	09/02/2020	FVGEN	39	LABCON		BRIVAL01	EX00015425	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	PART		BRIVAL01	EX00015425	DISCHARGE CLAMP,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	PART		BRIVAL01	EX00015425	BROWN TIP SOLDER,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	R404A		BRIVAL01	EX00015425	GAS R404A,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	LABCON		BRIVAL01	3188	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	PART		BRIVAL01	3188	DISCHARGE CLAMP,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	PART		BRIVAL01	3188	BROWN TIP SOLDER,RP22
RPS22	750QWU	30164	09/02/2020	FVGEN	39	R404A		BRIVAL01	3188	GAS R404A,RP22
RPS22	750QWU	30188	09/02/2020	FVPRE	39	LABCON		BRIVAL01	EX00015432	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30208	09/02/2020	FVPRE	39	LABCON		BRIVAL01	EX00015433	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30188	09/02/2020	FVPRE	39	LABCON		BRIVAL01	3185	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30208	09/02/2020	FVPRE	39	LABCON		BRIVAL01	3174	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30090	09/02/2020	TRA	1	LABOUR	MECH1	Labour		
RPS22	750QWU	30090	09/02/2020	TRA	SERVICE COMPLETED BY BEN AND SEAN 02.09.2020					
RPS22	750QWU	30090	09/02/2020	TRA	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	30090	09/02/2020	TRA	16	CON		YAT	Consumables	

RPS22	750QWU	30851	09/10/2020	FRIVANA	1	LABCON	BRIVAL01	EX00015794	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30851	09/10/2020	FRIVANA	1	LABCON	BRIVAL01	3264	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30294	09/10/2020	FRIVANB	39	LABCON	BRIVAL01	EX00015496	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30294	09/10/2020	FRIVANB	39	10-417	BRIVAL01	EX00015496	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	30294	09/10/2020	FRIVANB		VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R				

RPS22	750QWU	30294	09/10/2020	FRIVANB	39	LABCON		BRIVAL01	3266	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30294	09/10/2020	FRIVANB	39	10-417		BRIVAL01	3266	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	30458	09/17/2020	FVPRE	39	LABCON		BRIVAL01	EX00015571	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30458	09/17/2020	FVPRE		FRIDGE VAN PRE-CHECK COMPLETED PRE-CHECK COMPLETED BY BVR.				
RPS22	750QWU	30458	09/17/2020	FVPRE	39	LABCON		BRIVAL01	3346	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30805	09/24/2020	FRIVANA	1	LABCON		BRIVAL01	EX00015759	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	30805	09/24/2020	FRIVANA	1	LABCON		BRIVAL01	3395	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000517		BRIAUS01	EX00016032	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000085		BRIAUS01	EX00016032	ROTATE TBR TYRE,
RPS22	750QWU	31338	10/13/2020	TYRES	15	77000180		BRIAUS01	EX00016032	CASE STOCK 11-22.5,
RPS22	750QWU	31338	10/13/2020	TYRES	15	11001573		BRIAUS01	EX00016032	TYRE 11R22.5 148/145L 16 FS T559,
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000084		BRIAUS01	EX00016032	FIT TBR TYRE,
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000084		BRIAUS01	9928305	FIT TBR TYRE,
RPS22	750QWU	31338	10/13/2020	TYRES	15	11001573		BRIAUS01	9928305	TYRE 11R22.5 148/145L 16 FS T559,
RPS22	750QWU	31338	10/13/2020	TYRES	15	77000180		BRIAUS01	9928305	CASE STOCK 11-22.5,
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000085		BRIAUS01	9928305	ROTATE TBR TYRE,
RPS22	750QWU	31338	10/13/2020	TYRES	15	33000517		BRIAUS01	9928305	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	31759	10/23/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016164	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	31759	10/23/2020	FRIVANA	1	LABCON		BRIVAL01	3705	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	31913	10/29/2020	TRA	1	LABOUR	MECH1	Labour		

RPS22	750QWU	31913	10/29/2020	TRA	SERVICE COMPLETED BY SEAN/MICK 29/10/20 REPLACED REAR REFLECTIVE SIGNS CANNOT CHECK INSIDE AS LOADED REPLACED RHS TOP REAR INDICTATOR

RPS22	750QWU	31913	10/29/2020	TRA	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	31913	10/29/2020	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	31913	10/29/2020	TRA	14	91642		YAT	Side Indicator Lamp, LED	
RPS22	750QWU	32009	10/30/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016303	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32009	10/30/2020	FRIVANA	1	LABCON		BRIVAL01	3796	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32300	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016496	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32310	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016497	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32300	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	3905	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32310	11/11/2020	FRIVANA	1	LABCON		BRIVAL01	3906	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32439	11/17/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016583	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32439	11/17/2020	FRIVANA	1	LABCON		BRIVAL01	3972	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32619	11/24/2020	FRIVANA	1	LABCON		BRIVAL01	EX00016689	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32619	11/24/2020	FRIVANA	1	LABCON		BRIVAL01	4038	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32638	11/24/2020	FVGEN	35	PART		BRIVAL01	EX00016694	GENERAL PART CODE,100W 12V SOLAR PANEL
RPS22	750QWU	32638	11/24/2020	FVGEN	35	LABCON		BRIVAL01	EX00016694	LABOUR & CONSUMABLES,
RPS22	750QWU	32638	11/24/2020	FVGEN	35	PART		BRIVAL01	4046	GENERAL PART CODE,100W 12V SOLAR PANEL
RPS22	750QWU	32638	11/24/2020	FVGEN	35	LABCON		BRIVAL01	4046	LABOUR & CONSUMABLES,
RPS22	750QWU	32705	11/26/2020	TYRES	15	33000517		BRIAUS01	EX00016719	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	32705	11/26/2020	TYRES	15	77000180		BRIAUS01	EX00016719	CASE STOCK 11-22.5,
RPS22	750QWU	32705	11/26/2020	TYRES	15	11001464		BRIAUS01	EX00016719	TYRE 11R22.5 148/145L 16 BS R187,OWN STOCK

RPS22	750QWU	32705	11/26/2020	TYRES	15	33000084	BRIAUS01	EX00016719	FIT TBR TYRE,
RPS22	750QWU	32705	11/26/2020	TYRES	15	33000084	BRIAUS01	99527562	FIT TBR TYRE,
RPS22	750QWU	32705	11/26/2020	TYRES	15	11001464	BRIAUS01	99527562	TYRE 11R22.5 148/145L 16 BS R187,OWN STOCK
RPS22	750QWU	32705	11/26/2020	TYRES	15	77000180	BRIAUS01	99527562	CASE STOCK 11-22.5,
RPS22	750QWU	32705	11/26/2020	TYRES	15	33000517	BRIAUS01	99527562	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	32784	11/30/2020	FRIVANA	1	LABCON	BRIVAL01	EX00016762	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	32784	11/30/2020	FRIVANA	1	LABCON	BRIVAL01	4081	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33419	12/24/2020	FRIVANA	1	LABCON	brival01	EX00017095	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33419	12/24/2020	FRIVANA	SERVICE COMPLETED BY BVR 18/12/2020.				
RPS22	750QWU	33419	12/24/2020	FRIVANA	1	LABCON	brival01	4375	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33398	12/24/2020	FVGEN	39	CON	BRIVAL01	EX00017082	Consumables,RP22
RPS22	750QWU	33549	12/24/2020	FVGEN	39	CON	BRIVAL01	EX00017149	Consumables,RP22
RPS22	750QWU	33685	12/24/2020	FVGEN	39	CON	BRIVAL01	EX00017266	Consumables,RP22
RPS22	750QWU	33398	12/24/2020	FVGEN	39	LAB	BRIVAL01	EX00017082	Labour,RP22
RPS22	750QWU	33549	12/24/2020	FVGEN	39	LAB	BRIVAL01	EX00017149	Labour,RP22
RPS22	750QWU	33685	12/24/2020	FVGEN	39	LAB	BRIVAL01	EX00017266	Labour,RP22
RPS22	750QWU	33398	12/24/2020	FVGEN	SERVICE COMPLETED BY BVR 19/12/2020.				
RPS22	750QWU	33549	12/24/2020	FVGEN	SERVICE COMPLETED BY BVR 19/12/2020.				
RPS22	750QWU	33685	12/24/2020	FVGEN	39	LAB	BRIVAL01	00004339REV	Labour,RP22
RPS22	750QWU	33398	12/24/2020	FVGEN	39	LAB	BRIVAL01	00004339A	Labour,RP22
RPS22	750QWU	33549	12/24/2020	FVGEN	39	LAB	BRIVAL01	4339	Labour,RP22
RPS22	750QWU	33685	12/24/2020	FVGEN	39	CON	BRIVAL01	00004339REV	Consumables,RP22
RPS22	750QWU	33398	12/24/2020	FVGEN	39	CON	BRIVAL01	00004339A	Consumables,RP22
RPS22	750QWU	33549	12/24/2020	FVGEN	39	CON	BRIVAL01	4339	Consumables,RP22

RPS22	750QWU	33380	01/04/2021	DEFECT	Reported Defect :- Defect Code : 00005682 Defect Reference : 08179 Date : 01/01/2021 Description of Defect : NEEDS LIGHT PLUG REPLACED DEFECT CLEARED BY SEAN 0401021				
RPS22	750QWU	33380	01/04/2021	TRA		0	LABOUR	MECH1	Labour

RPS22	750QWU	33380	01/04/2021	TRA	SERVICE COMPLETED BY SEAN AND BEN FITTED BREAKDOWN KIT REPLACED 4.5KG FIRE EXTINGUISHER FITTED FEMALE LIGHT PLUG AT FRONT						
RPS22	750QWU	33380	01/04/2021	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	33380	01/04/2021	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	33380	01/04/2021	TRA	14	82062		YAT	7 Pin Female Trailer Plug		
RPS22	750QWU	34305	01/08/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017545	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	34305	01/08/2021	FRIVANA	SERVICE COMPLETED BY BVR 05/01/2021.						
RPS22	750QWU	34305	01/08/2021	FRIVANA	1	LABCON		BRIVAL01		4438	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	10-417		BRIVAL01		EX00017167	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	CON		BRIVAL01		EX00017167	Consumables,RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	LAB		BRIVAL01		EX00017167	Labour,RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	SERVICE COMPLETED BY BVR 04/01/2021.						
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	LAB		BRIVAL01		4423	Labour,RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	CON		BRIVAL01		4423	Consumables,RP22
RPS22	750QWU	33598	01/08/2021	FRIVANB	39	10-417		BRIVAL01		4423	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	33579	01/08/2021	GEN	1	LABCON		BRIVAL01		EX00017163	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33579	01/08/2021	GEN	SERVICE COMPLETED BY BVR 04/01/2021.						
RPS22	750QWU	33579	01/08/2021	GEN	1	LABCON		BRIVAL01		4437	LABOUR & CONSUMABLES,RP22

					AIR GAUGE: 11,450 ADJUSTED : WEIGHBRIDGE: 11,200						
RPS22	750QWU	33863	01/13/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RPS22	750QWU	33982	01/18/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017422	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	33982	01/18/2021	FRIVANA	SERVICE COMPLETED BY BVR 13/01/2021.						
RPS22	750QWU	33982	01/18/2021	FRIVANA	1	LABCON		BRIVAL01		4588	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	34605	02/12/2021	TRA	0	LABOUR	APPREN	Labour			
RPS22	750QWU	34605	02/12/2021	TRA	SERVICE COMPLETED BY BEN AND SEAN 11//2021.						
RPS22	750QWU	34605	02/12/2021	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	34605	02/12/2021	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	34666	02/12/2021	TYRES	15	77000180		BRIAUS01		EX00017692	CASE STOCK 11-22.5,RP22
RPS22	750QWU	34666	02/12/2021	TYRES	15	77000180		BRIAUS01		85380082	CASE STOCK 11-22.5,RP22
RPS22	750QWU	35308	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017976	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	35308	02/16/2021	FRIVANA	SERVICE COMPLETED BY BVR 11/02/2021.						
RPS22	750QWU	35308	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		4901	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	39	40-0974		BRIVAL01		EX00017779	GRADED SENSOR,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	39	CON		BRIVAL01		EX00017779	Consumables,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	39	LAB		BRIVAL01		EX00017779	Labour,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	SERVICE COMPLETED BY BVR 11/02/2021.						
RPS22	750QWU	34801	02/16/2021	FVGEN	39	LAB		BRIVAL01		4905	Labour,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	39	CON		BRIVAL01		4905	Consumables,RP22
RPS22	750QWU	34801	02/16/2021	FVGEN	39	40-0974		BRIVAL01		4905	GRADED SENSOR,RP22

RPS22	750QWU	35051	02/24/2021	EXOINS	0	LABOUR	MECH1	Labour		
				VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1						
				INSPECTION COMPLETED BY						
RPS22	750QWU	35051	02/24/2021	EXOINS SEAN						
RPS22	750QWU	35051	02/24/2021	TRA	1	LABOUR	Labour			0
RPS22	750QWU	35051	02/24/2021	TRA	SERVICE COMPLETED.					
RPS22	750QWU	35051	02/24/2021	TRB	1	LABOUR	Labour			0
RPS22	750QWU	35051	02/24/2021	TRB	SERVICE COMPLETED.					
RPS22	750QWU	35051	02/24/2021	TRC	0	LABOUR	MECH1	Labour		
				SERVICE COMPLETED BY SEAN						
				ADJUSTED ALL WHEEL BEARINGS REPLACED FEMALE SEALS REPLACED LHS FRONT MARKER LIGHT GREASE DUE TO BE REPLACED						
RPS22	750QWU	35051	02/24/2021	TRC 2022						

RPS22	750QWU	35051	02/24/2021	TRC	16	CON		YAT	Consumables			
RPS22	750QWU	35051	02/24/2021	TRC	14	91700BL		YAT	Clearance Light, LED Amber, Narva			
RPS22	750QWU	35407	02/25/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017983		LABOUR & CONSUMABLES,RP22
RPS22	750QWU	35407	02/25/2021	FRIVANA	SERVICE COMPLETED BY BVR 23/02/2021.							
RPS22	750QWU	35407	02/25/2021	FRIVANA	1	LABCON		BRIVAL01			5021	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	37416	05/07/2021	TRA	0	LABOUR	MECH1	Labour				
RPS22	750QWU	37416	05/07/2021	TRA	SERVICE COMPLETED BY RYAN AND MICK REPLACED WORN BOLT AND NUT FROM MUDGAURD ASSEMBLED A FEW RIVETS TO THE CABLE DUCT CORE REPAIRED STICKY RING FEEDER							
RPS22	750QWU	37416	05/07/2021	TRA	0	LABOUR	MECH	1.5	85	127.5		
RPS22	750QWU	37416	05/07/2021	TRA	16	CON		YAT	Consumables			
RPS22	750QWU	37468	05/10/2021	TYRES	15	33000096		BRIAUS01		EX00018890		PUNCTURE REPAIR TBR,RP22
RPS22	750QWU	37468	05/10/2021	TYRES	15	33000096		BRIAUS01		85841145		PUNCTURE REPAIR TBR,RP22
RPS22	750QWU	38084	05/31/2021	FRIVANA	1	LABCON		BRIVAL01		EX00019120		LABOUR & CONSUMABLES,RP22
RPS22	750QWU	38084	05/31/2021	FRIVANA	SERVICE COMPLETED BY BVR 27/05/2021							
RPS22	750QWU	38084	05/31/2021	FRIVANA	1	LABCON		BRIVAL01			6137	LABOUR & CONSUMABLES,RP22

RPS22	750QWU	38086	05/31/2021	FVGEN	39	78-1886		BRIVAL01		EX00019121	FAN BLOWER MOTOR 14V,RP22
RPS22	750QWU	38086	05/31/2021	FVGEN	39	CON		BRIVAL01		EX00019121	Consumables,RP22
RPS22	750QWU	38086	05/31/2021	FVGEN	39	LAB		BRIVAL01		EX00019121	Labour,RP22
RPS22	750QWU	38086	05/31/2021	FVGEN	SERVICE COMPLETED BY BVR 27/05/2021						
RPS22	750QWU	38086	05/31/2021	FVGEN	39	LAB		BRIVAL01		6131	Labour,RP22
RPS22	750QWU	38086	05/31/2021	FVGEN	39	CON		BRIVAL01		6131	Consumables,RP22
RPS22	750QWU	38086	05/31/2021	FVGEN	39	78-1886		BRIVAL01		6131	FAN BLOWER MOTOR 14V,RP22
RPS22	750QWU	39568	07/13/2021	TRA	0	LABOUR	MECH1	Labour			
RPS22	750QWU	39568	07/13/2021	TRA	SERVICE COMPLETED BY SEAN AND BEN R&R FIRE EXTINGUISHER FITTED TRACKER						
RPS22	750QWU	39568	07/13/2021	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	39568	07/13/2021	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	39647	07/15/2021	FRIVANA	1	LABCON		BRIVAL01		EX00019796	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	39647	07/15/2021	FRIVANA	SERVICE COMPLETED BY BVR 13/07/2021						
RPS22	750QWU	39647	07/15/2021	FRIVANA	1	LABCON		BRIVAL01		6671	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	39	R404A		BRIVAL01		EX00019790	GAS R404A,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	39	CON		BRIVAL01		EX00019790	Consumables,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	39	LAB		BRIVAL01		EX00019790	Labour,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	SERVICE COMPLETED BY BVR 13/07/2021						
RPS22	750QWU	39634	07/15/2021	FVGEN	39	R404A		BRIVAL01		6661	GAS R404A,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	39	CON		BRIVAL01		6661	Consumables,RP22
RPS22	750QWU	39634	07/15/2021	FVGEN	39	LAB		BRIVAL01		6661	Labour,RP22
RPS22	750QWU	40220	07/30/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020054	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40411	07/30/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020056	LABOUR & CONSUMABLES,RP22

RPS22	750QWU	40448	07/30/2021	FRIVANA	1	LABCON	BRIVAL01	EX00020057	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40220	07/30/2021	FRIVANA	SERVICE COMPLETED BY BVR 22.07.2021				
RPS22	750QWU	40411	07/30/2021	FRIVANA	SERVICE COMPLETED BY BVR 26/07/2021				
RPS22	750QWU	40448	07/30/2021	FRIVANA	SERVICE COMPLETED BY BVR 28/07/2021				
RPS22	750QWU	40220	07/30/2021	FRIVANA	1	LABCON	BRIVAL01	6820	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40411	07/30/2021	FRIVANA	1	LABCON	BRIVAL01	6854	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40448	07/30/2021	FRIVANA	1	LABCON	BRIVAL01	6879	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	10-417	BRIVAL01	EX00020052	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	45-2256	BRIVAL01	EX00020052	ALTERNATOR 65 AMP,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	CON	BRIVAL01	EX00020052	Consumables,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	LAB	BRIVAL01	EX00020052	Labour,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	SERVICE COMPLETED BY BVR 27.07.2021				
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	LAB	BRIVAL01	6877	Labour,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	CON	BRIVAL01	6877	Consumables,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	45-2256	BRIVAL01	6877	ALTERNATOR 65 AMP,RP22
RPS22	750QWU	40217	07/30/2021	FRIVANB	39	10-417	BRIVAL01	6877	FILTER KIT (FRIDGE MOTOR),RP22
RPS22	750QWU	40272	08/03/2021	FRIVANA	1	LABCON	BRIVAL01	EX00020072	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40272	08/03/2021	FRIVANA	SERVICE COMPLETED BY BVR 29/07/2021				
RPS22	750QWU	40272	08/03/2021	FRIVANA	1	LABCON	BRIVAL01	6916	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40779	08/09/2021	FRIVANA	1	LABCON	BRIVAL01	EX00020198	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40779	08/09/2021	FRIVANA	SERVICE COMPLETED BY BVR 09/08/2021				
RPS22	750QWU	40779	08/09/2021	FRIVANA	1	LABCON	BRIVAL01	7052	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	40572	08/09/2021	WEICAL	AIR GAUGE: 18000 ADJUSTED: 19000 WEIGHBRIDGE: 18610				
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				

RPS22	750QWU	40930	08/12/2021	FVGEN	39	CON		BRIVAL01		EX00020270	Consumables,RP22
RPS22	750QWU	40930	08/12/2021	FVGEN	39	LAB		BRIVAL01		EX00020270	Labour,RP22
RPS22	750QWU	40930	08/12/2021	FVGEN	SERVICE COMPLETED BY BVR 12/08/2021						
RPS22	750QWU	40930	08/12/2021	FVGEN	39	LAB		BRIVAL01		7089	Labour,RP22
RPS22	750QWU	40930	08/12/2021	FVGEN	39	CON		BRIVAL01		7089	Consumables,RP22
RPS22	750QWU	41680	09/02/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020478	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	41680	09/02/2021	FRIVANA	SERVICE COMPLTED BY BVR 02/09/2021						
RPS22	750QWU	41680	09/02/2021	FRIVANA	1	LABCON		BRIVAL01		7339	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	41462	09/02/2021	TRA	0	LABOUR	APPREN	Labour			
RPS22	750QWU	41462	09/02/2021	TRA	SERVICE COMPLETED BY KEIRAN						
RPS22	750QWU	41462	09/02/2021	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	41695	09/03/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020479	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	41695	09/03/2021	FRIVANA	SERVICE COMPLETED BY BVR 03/09/2021						
RPS22	750QWU	41695	09/03/2021	FRIVANA	1	LABCON		BRIVAL01		7364	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	42283	09/20/2021	FRIVANA	1	LABCON		BRIVAL01		EX00020664	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	42283	09/20/2021	FRIVANA	SERVICE COMPLETED BY BVR 20/09/2021						
RPS22	750QWU	42283	09/20/2021	FRIVANA	1	LABCON		BRIVAL01		7669	LABOUR & CONSUMABLES,RP22

RPS22	750QWU	42690	10/11/2021	DEFECT	Reported Defect :- Defect Code : 00006729 Defect Reference : 09069 Date : 13/07/2021 Description of Defect : 3 X FAULTS APPEARING ON FRIDGE MOTOR SCREEN OK'D TO GO BY AIGARS /BRETT							
RPS22	750QWU	42887	10/11/2021	FRIVANA		1	LABCON		BRIVAL01		EX00020930	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	42887	10/11/2021	FRIVANA	SERVICE COMPLTED BY BVR 11/10/2021							
RPS22	750QWU	42887	10/11/2021	FRIVANA		1	LABCON		BRIVAL01		7896	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	42690	10/11/2021	TRA		0	LABOUR	MECH1	Labour			
RPS22	750QWU	42690	10/11/2021	TRA	SERVICE COMPLETED BY SEAN							
RPS22	750QWU	42690	10/11/2021	TRA		16	CON		YAT	Consumables		
RPS22	750QWU	43092	10/21/2021	FRIVANA		1	LABCON		BRIVAL01		EX00021004	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43092	10/21/2021	FRIVANA	SERVICE COMPLETED BY BVR 21/10/2021							
RPS22	750QWU	43092	10/21/2021	FRIVANA		1	LABCON		BRIVAL01		8015	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43521	11/01/2021	FRIVANA		1	LABCON		BRIVAL01		EX00021213	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43521	11/01/2021	FRIVANA	SERVICE COMPLETED BY BVR 01/11/2021							
RPS22	750QWU	43521	11/01/2021	FRIVANA		1	LABCON		BRIVAL01		8107	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43423	11/02/2021	FRIVANA		1	LABCON		BRIVAL01		EX00021177	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43423	11/02/2021	FRIVANA	SERVICE COMPLTED BY BVR 02/11/2021							

RPS22	750QWU	43423	11/02/2021	FRIVANA	1	LABCON		BRIVAL01		8124	LABOUR & CONSUMABLES,RP22
RPS22	750QWU	43647	11/15/2021	FVGEN	39	CON		BRIVAL01		EX00021293	Consumables,RP22
RPS22	750QWU	43647	11/15/2021	FVGEN	39	LAB		BRIVAL01		EX00021293	Labour,RP22
RPS22	750QWU	43647	11/15/2021	FVGEN	SERVICE COMPLETED BY BVR 15/11/2021						
RPS22	750QWU	43647	11/15/2021	FVGEN	39	LAB		BRIVAL01		8255	Labour,RP22
RPS22	750QWU	43647	11/15/2021	FVGEN	39	CON		BRIVAL01		8255	Consumables,RP22
RPS22	750QWU	43854	11/26/2021	TYRES	15	77000180		BRIAUS01		EX00021419	CASE STOCK 11-22.5,RP22
RPS22	750QWU	43854	11/26/2021	TYRES	15	77000180		BRIAUS01		86868338	CASE STOCK 11-22.5,RP22
RPS22	750QWU	44574	01/09/2022	WEICAL	AIR GAUGE:19500 ADJUSTED:19500 WEIGHBRIDGE:19070						
RPS22	750QWU	44626	01/13/2022	TRA	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RPS22	750QWU	44626	01/13/2022	TRA	0	LABOUR	MECH1	Labour			
RPS22	750QWU	44626	01/13/2022	TRA	SERVICE COMPLETED.						
RPS22	750QWU	44626	01/13/2022	TRA	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	44626	01/13/2022	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	44626	01/13/2022	TRB	1	LABOUR	Labour				0
RPS22	750QWU	44626	01/13/2022	TRB	SERVICE COMPLETED.						
RPS22	750QWU	44641	01/14/2022	TYRES	15	77000180		BRIAUS01		EX00021984	CASE STOCK 11-22.5,RP22
RPS22	750QWU	44641	01/14/2022	TYRES	15	77000180		BRIAUS01		87105661	CASE STOCK 11-22.5,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	100417		BRIVAL01		EX00022174	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	400974		BRIVAL01		EX00022174	Sensor, Return Air, QTK Fridge,RP22

												Consumables
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	CON		BRIVAL01		EX00022174		,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	LAB		BRIVAL01		EX00022174		Labour,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9			
RPS22	750QWU	44903	01/18/2022	FRIVANSE	SERVICE COMPLETED BY BVR 18.01.22							
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	LAB		BRIVAL01		8956		Labour,RP22
												Consumables
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	CON		BRIVAL01		8956		,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	400974		BRIVAL01		8956		Sensor, Return Air, QTK Fridge,RP22
RPS22	750QWU	44903	01/18/2022	FRIVANSE	39	100417		BRIVAL01		8956		Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	45258	02/11/2022	TYRES	15	33000096		BRIAUS01		EX00022441		PUNCTURE REPAIR TBR,RP22
RPS22	750QWU	45258	02/11/2022	TYRES	15	33000096		BRIAUS01		87251687		PUNCTURE REPAIR TBR,RP22
RPS22	750QWU	45786	02/25/2022	TRA	0	LABOUR	APPRENB	Labour				
RPS22	750QWU	45786	02/25/2022	TRA	SERVICE COMPLETED BY BEN, BRENDAN AND TYLER REPLACED 4.5KG F/E AND BAG							
RPS22	750QWU	45786	02/25/2022	TRA	0	LABOUR	SUBMEC	Labour - Internal				
RPS22	750QWU	45786	02/25/2022	TRA	0	LABOUR	TRADEA	0.5	85	42.5		
RPS22	750QWU	45786	02/25/2022	TRA	16	CON		YAT	Consumables			
RPS22	750QWU	45848	03/03/2022	EXOINS	1	LABOUR	MECH	Labour				

RPS22	750QWU	45848	03/03/2022	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES						
RPS22	750QWU	45848	03/03/2022	GEN		39	PART		DIESER01	EX00022860	GENERAL PART CODE,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	EX00022860	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	EX00022860	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	EX00022860	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	EX00022860	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	CON		DIESER01	EX00022860	Consumables,RP22
RPS22	750QWU	45848	03/03/2022	GEN		11	0980106890TSSC		YAT	Wheel Bearing Kit BPW	
RPS22	750QWU	45848	03/03/2022	GEN		11	BP1802.BAG		YAT	Air Bag BPW	
RPS22	750QWU	45848	03/03/2022	GEN		11	M1862-08		YAT	JOINER 8MM PUSH	
RPS22	750QWU	45848	03/03/2022	GEN		39	CON		DIESER01	27301	Consumables,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	27301	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	27301	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	27301	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	LAB		DIESER01	27301	Labour,RP22
RPS22	750QWU	45848	03/03/2022	GEN		39	PART		DIESER01	27301	GENERAL PART CODE,RP22
RPS22	750QWU	45848	03/03/2022	TRA		1	LABOUR	Labour			0
RPS22	750QWU	45848	03/03/2022	TRA	SERVICE COMPLETED.						
RPS22	750QWU	45848	03/03/2022	TRB		1	LABOUR	Labour			0
RPS22	750QWU	45848	03/03/2022	TRB	SERVICE COMPLETED.						
RPS22	750QWU	45848	03/03/2022	TRC		1	LABOUR	Labour			0

RPS22	750QWU	45848	03/03/2022	TRC	COMPLETED BY DIESEL SERVICES INV# 00027301 C&D SERVICE WITH BEARINGS REPLACE ALL BEARINGS PACK AND SET ALL BEARINGS REPALCE RH FIRST AND SECOND AXLE AIRBAGS REPLACE LEAKING AIR JOINER				
RPS22	750QWU	45868	03/04/2022	GEN	39	PART	GIBBS01	EX00022759	GENERAL PART CODE,RP22
RPS22	750QWU	45868	03/04/2022	GEN	39	PART	GIBBS01	1622504	GENERAL PART CODE,RP22
RPS22	750QWU	46026	03/09/2022	GEN	39	PART	BRIVAL01	EX00022879	GENERAL PART CODE,RP22
RPS22	750QWU	46036	03/09/2022	GEN	39	PART	BRIVAL01	EX00022889	GENERAL PART CODE,RP22
RPS22	750QWU	46026	03/09/2022	GEN	39	CON	BRIVAL01	EX00022879	Consumables,RP22
RPS22	750QWU	46036	03/09/2022	GEN	39	CON	BRIVAL01	EX00022889	Consumables,RP22

RPS22	750QWU	46026	03/09/2022	GEN	39	LAB		BRIVAL01	EX00022879	Labour,RP22
RPS22	750QWU	46036	03/09/2022	GEN	39	LAB		BRIVAL01	EX00022889	Labour,RP22
RPS22	750QWU	46026	03/09/2022	GEN	SERVICE COMPLETED BY 09.03.2022					
RPS22	750QWU	46036	03/09/2022	GEN	SERVICE COMPLETED BY 09.03.2022					
RPS22	750QWU	46026	03/09/2022	GEN	39	LAB		BRIVAL01	9582	Labour,RP22
RPS22	750QWU	46026	03/09/2022	GEN	39	CON		BRIVAL01	9582	Consumables,RP22
RPS22	750QWU	46026	03/09/2022	GEN	39	PART		BRIVAL01	9582	GENERAL PART CODE,RP22
RPS22	750QWU	46597	03/30/2022	GEN	39	PART		BRIVAL01	EX00023180	GENERAL PART CODE,RP22
RPS22	750QWU	46597	03/30/2022	GEN	39	CON		BRIVAL01	EX00023180	Consumables,RP22
RPS22	750QWU	46597	03/30/2022	GEN	39	LAB		BRIVAL01	EX00023180	Labour,RP22
RPS22	750QWU	46597	03/30/2022	GEN	SERVICE COMPLETED BY BVR 29.03.2022					
RPS22	750QWU	46597	03/30/2022	GEN	39	LAB		BRIVAL01	9935	Labour,RP22
RPS22	750QWU	46597	03/30/2022	GEN	39	CON		BRIVAL01	9935	Consumables,RP22
RPS22	750QWU	46597	03/30/2022	GEN	39	PART		BRIVAL01	9935	GENERAL PART CODE,RP22
RPS22	750QWU	47239	04/28/2022	GEN	0	LABOUR	SUBMEC	Labour		
RPS22	750QWU	47239	04/28/2022	GEN	REPAIR COMPLETED BY BRENDAN, IAN AND BEN R&R WORN SPRING EYE BUSH 1ST RHS					
RPS22	750QWU	47239	04/28/2022	GEN	0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	47239	04/28/2022	GEN	0	LABOUR	APPRENB	Labour - Internal		
RPS22	750QWU	47239	04/28/2022	GEN	16	CON		YAT	Consumables	
RPS22	750QWU	47219	04/28/2022	TRA	0	LABOUR	APPRENB	Labour		

RPS22	750QWU	47219	04/28/2022	TRA	SERVICE COMPLETED BY BEN, BRENDAN, TYLER AND IAN REMOVE STRAIGHTEN AND REPAIR REAR LADDER ASSEMBLY						
RPS22	750QWU	47219	04/28/2022	TRA	0	LABOUR	SUBMEC	Labour - Internal			
RPS22	750QWU	47219	04/28/2022	TRA	0	LABOUR	TRADEA	Labour - Internal			
RPS22	750QWU	47219	04/28/2022	TRA	0	LABOUR	MECH1	Labour - Internal			
RPS22	750QWU	47219	04/28/2022	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	47735	05/17/2022	GEN	39	PART		BRIVAL01		EX00023674	GENERAL PART CODE,RP22
RPS22	750QWU	47741	05/17/2022	GEN	39	42-2320		BRIVAL01		EX00023680	MODULE EXPANSION MT SR2/3. FRIDGE VAN,RP22
RPS22	750QWU	47735	05/17/2022	GEN	39	CON		BRIVAL01		EX00023674	Consumables ,RP22
RPS22	750QWU	47741	05/17/2022	GEN	39	CON		BRIVAL01		EX00023680	Consumables ,RP22
RPS22	750QWU	47735	05/17/2022	GEN	39	LAB		BRIVAL01		EX00023674	Labour,RP22
RPS22	750QWU	47741	05/17/2022	GEN	39	LAB		BRIVAL01		EX00023680	Labour,RP22
RPS22	750QWU	47735	05/17/2022	GEN	39	LAB		BRIVAL01		10708	Labour,RP22
RPS22	750QWU	47741	05/17/2022	GEN	SERVICE COMPLETED BY BVR 17.05.2022						
RPS22	750QWU	47735	05/17/2022	GEN	39	CON		BRIVAL01		10708	Consumables ,RP22
RPS22	750QWU	47735	05/17/2022	GEN	39	PART		BRIVAL01		10708	GENERAL PART CODE,RP22
RPS22	750QWU	48173	06/07/2022	TRA	0	LABOUR	APPREN	Labour			
RPS22	750QWU	48173	06/07/2022	TRA	SERVICE COMPLETED BY TYLER AND MICK						
RPS22	750QWU	48173	06/07/2022	TRA	0	LABOUR	MECH	Labour - Internal			
RPS22	750QWU	48173	06/07/2022	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	48499	06/23/2022	GEN	39	400974		BRIVAL01		EX00024135	Sensor, Return Air, QTK Fridge,RP22

RPS22	750QWU	48499	06/23/2022	GEN		39	CON	BRIVAL01	EX00024135	Consumables ,RP22
RPS22	750QWU	48499	06/23/2022	GEN		39	LAB	BRIVAL01	EX00024135	Labour,RP22
RPS22	750QWU	48499	06/23/2022	GEN	COMPLETED BY BVR 23.06.2022 TRAVEL TO SITE AND INSPECT FOUND UNIT FAULTING ON REMOTE FANS REMOVE PLUGS IN WIRING HARNESS REJOIN WIRING HARNESS AS REQUIRED remove and replace					
RPS22	750QWU	48499	06/23/2022	GEN		39	LAB	BRIVAL01	11247	Labour,RP22
RPS22	750QWU	48499	06/23/2022	GEN		39	CON	BRIVAL01	11247	Consumables ,RP22
RPS22	750QWU	48499	06/23/2022	GEN		39	400974	BRIVAL01	11247	Sensor, Return Air, QTK Fridge,RP22

					AIR GAUGE: 13500 ADJUSTED : 13750 WEIGHBRIDGE: 12380						
RPS22	750QWU	49091	07/06/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RPS22	750QWU	49588	07/27/2022	GEN		0	LABOUR	APPRENK	Labour		
					REPAIR COMPLETED BY KEIRAN						
RPS22	750QWU	49588	07/27/2022	GEN	REPLACED FRIDGE BATTERY						
RPS22	750QWU	49588	07/27/2022	GEN		16	CON		YAT	Consumables	
RPS22	750QWU	49588	07/27/2022	GEN		14	MF70ZZDT		YAT	BATTERY DEEP CYCLE & TRUCK	
RPS22	750QWU	49493	07/28/2022	GEN		39	LAB		BRIVAL01	EX00024564	Labour,RP22
RPS22	750QWU	49601	07/28/2022	GEN		39	449298		BRIVAL01	EX00024631	SENSOR RPM,RP22

RPS22	750QWU	49493	07/28/2022	GEN	SERVICE COMPLETED BY BVR 28.07.2022 NIGHT CALLOUT CHARGES FOR JUMP STARTING THE REFRIGERATOR						
RPS22	750QWU	49601	07/28/2022	GEN		39	CON		BRIVAL01	EX00024631	Consumables,RP22
RPS22	750QWU	49493	07/28/2022	GEN		39	LAB		BRIVAL01	9835	Labour,RP22
RPS22	750QWU	49601	07/28/2022	GEN		39	LAB		BRIVAL01	EX00024631	Labour,
RPS22	750QWU	49601	07/28/2022	GEN		39	LAB		BRIVAL01	10067	Labour,
RPS22	750QWU	49601	07/28/2022	GEN		39	CON		BRIVAL01	10067	Consumables,RP22
RPS22	750QWU	49601	07/28/2022	GEN		39		449298	BRIVAL01	10067	SENSOR RPM,RP22
RPS22	750QWU	49804	08/08/2022	WEICAL	AIR GAUGE: 20000 ADJUSTED: 20500 WEIGHBRIDGE: 20120 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						

RPS22	750QWU	50333	09/02/2022	DEFECT	Reported Defect :- Defect Code : 00007880 Defect Reference : 37352 Date : 29/07/2022 Description of Defect : POSSIBLE BATTERY OR ALT, NEEDS TO BE JUMP STARTED					
RPS22	750QWU	50333	09/02/2022	TRA	1	LABOUR	Labour			0
RPS22	750QWU	50333	09/02/2022	TRA	SERVICE COMPLETED.					
RPS22	750QWU	50333	09/02/2022	TRB	0	LABOUR	APPREN	Labour		

RPS22	750QWU	50333	09/02/2022	TRB	SERVICE COMPLETED BY TYLER AND KEIRAN REPLACED FRONT LH PARK LIGHT CHECKED FRIDGE - CHARGING AT 14.2V						
RPS22	750QWU	50333	09/02/2022	TRB		0	LABOUR	MECH1	Labour - Internal		
RPS22	750QWU	50333	09/02/2022	TRB		16	CON		YAT	Consumables	
RPS22	750QWU	50489	09/07/2022	FRIVANSE		39	100417		BRIAUS01	EX00025070	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE		39	449181		BRIAUS01	EX00025070	Solenoid, QTK Fridge, SB310 plus,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE		39	CON		BRIAUS01	EX00025070	Consumables,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE		39	LAB		BRIAUS01	EX00025070	Labour,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE	SERVICE COMPLETED BY BVR 7.9.2022 TRAVEL TO SITE AND INSPECT UNIT REMOVE AND REPLACE U/S HIGH SPEED SOLENOID						

RPS22	750QWU	50489	09/07/2022	FRIVANSE	39	LAB	BRIVAL01	12118	Labour,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE	39	CON	BRIVAL01	12118	Consumables,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE	39	449181	BRIVAL01	12118	Solenoid, QTK Fridge, SB310 plus,RP22
RPS22	750QWU	50489	09/07/2022	FRIVANSE	39	100417	BRIVAL01	12118	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	781360	BRIVAL01	EX00025305	FAN BELT, QTK FRIDGE MOTOR,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	PART	BRIVAL01	EX00025305	78629,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	78-0603	BRIVAL01	EX00025305	SB Series Fridge motor fanbelt,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-4159	BRIVAL01	EX00025305	VIBRATION MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-4043	BRIVAL01	EX00025305	SNUBBER MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-7709	BRIVAL01	EX00025305	VIBRATION MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	CON	BRIVAL01	EX00025305	Consumables,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	LAB	BRIVAL01	EX00025305	Labour,RP22
RPS22	750QWU	50880	09/15/2022	GEN	SERVICE COMPLETED BY BVR 15.09.2022				
RPS22	750QWU	50880	09/15/2022	GEN	39	LAB	BRIVAL01	12259	Labour,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	CON	BRIVAL01	12259	Consumables,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-7709	BRIVAL01	12259	VIBRATION MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-4043	BRIVAL01	12259	SNUBBER MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	91-4159	BRIVAL01	12259	VIBRATION MOUNT,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	78-0603	BRIVAL01	12259	SB Series Fridge motor fanbelt,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	PART	BRIVAL01	12259	78629,RP22
RPS22	750QWU	50880	09/15/2022	GEN	39	781360	BRIVAL01	12259	FAN BELT, QTK FRIDGE MOTOR,RP22

					AIR GAUGE: 20.01 ADJUSTED: 20.01 WEIGHBRIDGE: 19.74					
RPS22	750QWU	50746	09/21/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RPS22	750QWU	51187	09/29/2022	FVGEN		39	R404A	BRIVAL01	EX00025436	GAS R404A,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	PART	BRIVAL01	EX00025436	BROWN TIP SOLDER,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	910372	BRIVAL01	EX00025436	CLAMP TUBE - FRIDGE MOTOR,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	91-0373	BRIVAL01	EX00025436	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	33-2805	BRIVAL01	EX00025436	MANIFOLD GASKET FRIDGE,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	LAB	BRIVAL01	EX00025436	Labour,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN		39	LAB	BRIVAL01	EX00025436	Labour,RP22

RPS22	750QWU	51187	09/29/2022	FVGEN	COMPLETED BY BVR 29.09.2022 TRAVEL TO SITE-UNIT REPORTED NOT PULLING HIGH SPEED DIAGNOSED AS HIGH SPEED BAD EARTH FIX EARTHING PROBLEM DIAGNOSE GAS LEAK ON DISCHARGE PIPE

RPS22	750QWU	51187	09/29/2022	FVGEN	39	LAB		BRIVAL01	12414	Labour,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	LAB		BRIVAL01	12414	Labour,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	33-2805		BRIVAL01	12414	MANIFOLD GASKET FRIDGE,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	91-0373		BRIVAL01	12414	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	910372		BRIVAL01	12414	CLAMP TUBE - FRIDGE MOTOR,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	PART		BRIVAL01	12414	BROWN TIP SOLDER,RP22
RPS22	750QWU	51187	09/29/2022	FVGEN	39	R404A		BRIVAL01	12414	GAS R404A,RP22
RPS22	750QWU	51528	10/21/2022	TRA	0	LABOUR	APPREN	Labour		
RPS22	750QWU	51528	10/21/2022	TRA	SERVICE COMPLETED BY TYLER AND FLYNN					
RPS22	750QWU	51528	10/21/2022	TRA	0	LABOUR	APPREN	Labour - Internal		
RPS22	750QWU	51528	10/21/2022	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	52521	12/01/2022	TYRES	15	77000180		BRIAUS01	EX00026171	CASE STOCK 11-22.5,RP22
RPS22	750QWU	52521	12/01/2022	TYRES	15	77000180		BRIAUS01	88792736	CASE STOCK 11-22.5,RP22
RPS22	750QWU	52898	12/20/2022	TRA	1	LABOUR	APPRENK	Labour		

RPS22	750QWU	52898	12/20/2022	TRA	SERVICE COMPLETED BY TYLER AND KEIRAN 20.12.2022 REPLACED INTERIOR LIGHT SWITCH PART# WS226 - MICK ADV. TO CODE TO CONSUMABLES AS IS A NEW PART # AND WON'T BE IN SYSTEM.					
RPS22	750QWU	52898	12/20/2022	TRA		0	LABOUR	APPREN	Labour - Internal	
RPS22	750QWU	52898	12/20/2022	TRA		16	CON		YAT	Consumables
RPS22	750QWU	53629	01/27/2023	FRIVANB		0	LABOUR	MECH	Labour	

RPS22	750QWU	53629	01/27/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

RPS22	750QWU	53629	01/27/2023	FRIVANB	39	CON		BRIVAL01		EX00026845	Consumables ,RP22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	100417		BRIVAL01		EX00026845	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	COOLANT		BRIVAL01		EX00026845	COOLANT,RP22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	LAB		BRIVAL01		EX00026845	Labour,PR22
RPS22	750QWU	53629	01/27/2023	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	53629	01/27/2023	FRIVANB	Completed Service by BVR 16/01/2023. Carry out B Service as per BVR specifications.						
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	LAB		BRIVAL01		14045	Labour,PR22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	COOLANT		BRIVAL01		14045	COOLANT,RP22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	100417		BRIVAL01		14045	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	53629	01/27/2023	FRIVANB	39	CON		BRIVAL01		14045	Consumables ,RP22
RPS22	750QWU	53629	01/27/2023	FRIVCAL	1	LABOUR	MECH	Labour			
RPS22	750QWU	53629	01/27/2023	FRIVCAL	39	CC		BRIVAL01		EX00026845	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	53629	01/27/2023	FRIVCAL	39	CC		BRIVAL01		14045	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	53909	02/07/2023	GEN	0	LABOUR	APPRENF	Labour			
RPS22	750QWU	53909	02/07/2023	GEN	REPAIR COMPLETED. REPLACED TRAILER PLUG ON FRONT OF TRAILER						
RPS22	750QWU	53909	02/07/2023	GEN	16	CON		YAT	Consumables		
RPS22	750QWU	54464	02/23/2023	TYRES	15	11002822		BRIAUS01		EX00027380	11R2.5 148L 16 BS R168,
RPS22	750QWU	54464	02/23/2023	TYRES	15	77000180		BRIAUS01		EX00027380	CASE STOCK 11-22.5,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000084		BRIAUS01		EX00027380	FIT TBR TYRE,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000517		BRIAUS01		EX00027380	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000085		BRIAUS01		EX00027380	ROTATE TBR TYRE,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000085		BRIAUS01		89219807	ROTATE TBR TYRE,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000517		BRIAUS01		89219807	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	54464	02/23/2023	TYRES	15	33000084		BRIAUS01		89219807	FIT TBR TYRE,
RPS22	750QWU	54464	02/23/2023	TYRES	15	77000180		BRIAUS01		89219807	CASE STOCK 11-22.5,
RPS22	750QWU	54464	02/23/2023	TYRES	15	11002822		BRIAUS01		89219807	11R2.5 148L 16 BS R168,
RPS22	750QWU	55026	03/23/2023	EXOINS	1	LABOUR	MECH	Labour			

RPS22	750QWU	55026	03/23/2023	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES					
RPS22	750QWU	55027	03/23/2023	GEN	39	2.57E+08		DIESER01	EX00027695	O-RING Exodas Stock,
RPS22	750QWU	55027	03/23/2023	GEN	39	82161BL		DIESER01	EX00027695	7 PIN PLUG TRAILER (Exodas Stock,
RPS22	750QWU	55027	03/23/2023	GEN	39	PART		DIESER01	EX00027695	GENERAL PART CODE 90862BL Narva LED Number Plate Lights (Exodas Stock),
RPS22	750QWU	55027	03/23/2023	GEN	39	CRC-5073		DIESER01	EX00027695	DEGREASER CAN,
RPS22	750QWU	55027	03/23/2023	GEN	39	LABEXT		DIESER01	EX00027695	Labour External C & D No grease,
RPS22	750QWU	55027	03/23/2023	GEN	39	LABEXT		DIESER01	EX00027695	Labour External Replace 7 pin trailer plug and rear number plate lamps,
RPS22	750QWU	55027	03/23/2023	GEN	39	DEL		DIESER01	EX00027695	DELIVERY - Pick up and return trailer,
RPS22	750QWU	55027	03/23/2023	GEN	39	SUND		DIESER01	EX00027695	SUNDRIES - MATERIALS,
RPS22	750QWU	55027	03/23/2023	GEN	39	SUND		DIESER01	28369	SUNDRIES - MATERIALS,
RPS22	750QWU	55027	03/23/2023	GEN	39	DEL		DIESER01	28369	DELIVERY - Pick up and return trailer,
RPS22	750QWU	55027	03/23/2023	GEN	39	LABEXT		DIESER01	28369	Labour External Replace 7 pin trailer plug and rear number plate lamps,
RPS22	750QWU	55027	03/23/2023	GEN	39	LABEXT		DIESER01	28369	Labour External C & D No grease,
RPS22	750QWU	55027	03/23/2023	GEN	39	CRC-5073		DIESER01	28369	DEGREASER CAN,
RPS22	750QWU	55027	03/23/2023	GEN	39	PART		DIESER01	28369	GENERAL PART CODE 90862BL Narva LED Number Plate Lights (Exodas Stock),
RPS22	750QWU	55027	03/23/2023	GEN	39	82161BL		DIESER01	28369	7 PIN PLUG TRAILER (Exodas Stock,
RPS22	750QWU	55027	03/23/2023	GEN	39	2.57E+08		DIESER01	28369	O-RING Exodas Stock,
RPS22	750QWU	55027	03/23/2023	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	55027	03/23/2023	TRA	SERVICE COMPLETED.					
RPS22	750QWU	55027	03/23/2023	TRB	1	LABOUR	MECH	Labour		
RPS22	750QWU	55027	03/23/2023	TRB	SERVICE COMPLETED.					
RPS22	750QWU	55027	03/23/2023	TRC	1	LABOUR	MECH	Labour		

RPS22	750QWU	55027	03/23/2023	TRC	COMPLETED. COMPLETE C&D SERVICE NO GREASE, ADJUST ALL WHEEL BEARINGS, ADJUST BRAKES, TENSION SUSPENSION POINTS, REPLACE TRAILER PLUG, REPLACE BOTH NUMBER PLATE LIGHT, REPLACE HUBCAP					
RPS22	750QWU	55027	03/23/2023	TRC		16	2.57E+08		YAT	O-RING
RPS22	750QWU	55027	03/23/2023	TRC		16	82161BL		YAT	7 PIN PLUG TRAILER
RPS22	750QWU	55027	03/23/2023	TRC		16	PART		YAT	GENERAL PART CODE - 90862BL NUMBER PLATE LIGHT
RPS22	750QWU	55543	04/13/2023	GEN		0	LABOUR	MECH 3	Labour	
RPS22	750QWU	55543	04/13/2023	GEN	REPAIR COMPLETED. REMOVE DAMEGED GUARD & REPLACE WITH NEW ITEM					
RPS22	750QWU	55543	04/13/2023	GEN		0	LABOUR	MECH 1	Labour - Internal	

RPS22	750QWU	55543	04/13/2023	GEN	16	PART		YAT	GENERAL PART CODE - RED HARD MUDGUARD
RPS22	750QWU	55543	04/13/2023	GEN	16	CON		YAT	Consumables
RPS22	750QWU	55885	04/27/2023	TRA	0	LABOUR	APPRENB	Labour	
RPS22	750QWU	55885	04/27/2023	TRA	SERVICE COMPLETED. REPLACED 9KG WITH 4.5 KG FIRE EXTINGUISHER				
RPS22	750QWU	55885	04/27/2023	TRA	0	LABOUR	APPRENF	Labour - Internal	
RPS22	750QWU	55885	04/27/2023	TRA	0	LABOUR	MECH 1	Labour - Internal	
RPS22	750QWU	55885	04/27/2023	TRA	19	FIREEXT4.5KG		YAT	4.5KG FIRE EXTINGUISHER
RPS22	750QWU	55885	04/27/2023	TRA	16	CON		YAT	Consumables
RPS22	750QWU	56807	05/26/2023	WEICAL	AIR GAUGE: 17500 ADJUSTED: 18000 WEIGHBRIDGE: 17620 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RPS22	750QWU	56722	05/30/2023	TRA	0	LABOUR	MECH 1	Labour	
RPS22	750QWU	56722	05/30/2023	TRA	SERVICE COMPLETED.				
RPS22	750QWU	56722	05/30/2023	TRA	0	LABOUR	MECH 3	Labour - Internal	
RPS22	750QWU	56722	05/30/2023	TRA	16	CON		YAT	Consumables

					AIR GAUGE: 14460 ADJUSTED : 17000 WEIGHBRIDGE: 16750					
RPS22	750QWU	57157	06/10/2023	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RPS22	750QWU	57345	06/21/2023	TRA		0	LABOUR	APPREN	Labour	
RPS22	750QWU	57345	06/21/2023	TRA	SERVICE COMPLETED. INOX & BLEW OUT RING FEEDER DUE TO BEING HARD TO OPERATE					
RPS22	750QWU	57345	06/21/2023	TRA		16	CON		YAT	Consumables
RPS22	750QWU	57435	06/22/2023	FRIVANB		0	LABOUR	MECH	Labour	

RPS22	750QWU	57435	06/22/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

RPS22	750QWU	57435	06/22/2023	FRIVANB	39	CON		BRIVAL01	EX00029242	Consumables ,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	CC		BRIVAL01	EX00029242	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	100417		BRIVAL01	EX00029242	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	91-0373		BRIVAL01	EX00029242	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	42-0100		BRIVAL01	EX00029242	STOP FUEL SOLENOID, FRIDGE MOTORS,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	33-2230		BRIVAL01	EX00029242	SOLENOID O-RING FRIDGE MOTORS,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	92-0374		BRIVAL01	EX00029242	SLAM LATCH FRIDGE,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	LAB		BRIVAL01	EX00029242	Labour,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9	
RPS22	750QWU	57435	06/22/2023	FRIVANB	Service completed by BVR 20/06/23 - Carry out B Service as per BVR Specifications - Remove and replace leaking fuel solenoid - Remove and replace worn door s					
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	CON		BRIVAL01	16646	Consumables ,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	CC		BRIVAL01	16646	CALIBRATION CETIFICATE,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	100417		BRIVAL01	16646	Filter Service Kit, Fridge Motor, SLX-400,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	91-0373		BRIVAL01	16646	CLAMP TUBE FRIDGE MOTOR,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	42-0100		BRIVAL01	16646	STOP FUEL SOLENOID, FRIDGE MOTORS,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	33-2230		BRIVAL01	16646	SOLENOID O-RING FRIDGE MOTORS,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	92-0374		BRIVAL01	16646	SLAM LATCH FRIDGE,RP22
RPS22	750QWU	57435	06/22/2023	FRIVANB	39	LAB		BRIVAL01	16646	Labour,RP22
RPS22	750QWU	57435	06/22/2023	FRIVCAL	1	LABOUR	MECH	Labour		
RPS22	750QWU	57456	06/23/2023	TYRES	15	11004117		BRIAUS01	EX00029178	11R22.5 148/145L FS FT469,
RPS22	750QWU	57478	06/23/2023	TYRES	15	33000188		BRIAUS01	EX00029190	B FLEET PRESSURE CHECK,
RPS22	750QWU	57456	06/23/2023	TYRES	15	77000180		BRIAUS01	EX00029178	CASE STOCK 11-22.5,
RPS22	750QWU	57478	06/23/2023	TYRES	15	33000188		BRIAUS01	89868716	B FLEET PRESSURE CHECK,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000084		BRIAUS01	EX00029178	FIT TBR TYRE,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000517		BRIAUS01	EX00029178	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000118		BRIAUS01	EX00029178	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	57456	06/23/2023	TYRES	15	11004117		BRIAUS01	89865560	11R22.5 148/145L FS FT469,
RPS22	750QWU	57456	06/23/2023	TYRES	15	77000180		BRIAUS01	89865560	CASE STOCK 11-22.5,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000084		BRIAUS01	89865560	FIT TBR TYRE,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000517		BRIAUS01	89865560	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	57456	06/23/2023	TYRES	15	33000118		BRIAUS01	89865560	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	57683	07/04/2023	GEN	39	LABEXT		REDTRU01	EX00029334	Labour External,

RPS22	750QWU	57683	07/04/2023	GEN	39	CON		REDTRU01		EX00029334	Consumables ,7 PIN PLUG
RPS22	750QWU	57683	07/04/2023	GEN	39	LABEXT		REDTRU01		29312	Labour External,
RPS22	750QWU	57683	07/04/2023	GEN	39	CON		REDTRU01		29312	Consumables ,7 PIN PLUG
RPS22	750QWU	58405	07/28/2023	TRA	0	LABOUR	APPREN	Labour			
RPS22	750QWU	58405	07/28/2023	TRA	SERVICE COMPLETED.						
RPS22	750QWU	58405	07/28/2023	TRA	0	LABOUR	APPRENF	Labour - Internal			
RPS22	750QWU	58405	07/28/2023	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	58498	07/31/2023	TYRES	15	11002821		BRIAUS01		EX00029748	11R22.5 148/145L BS R119 ECO,
RPS22	750QWU	58498	07/31/2023	TYRES	15	77000232		BRIAUS01		EX00029748	CASE STOCK 11R22.5 ECOPIA,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000084		BRIAUS01		EX00029748	FIT TBR TYRE,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000517		BRIAUS01		EX00029748	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000118		BRIAUS01		EX00029748	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	58498	07/31/2023	TYRES	15	11002821		BRIAUS01		1.87E+08	11R22.5 148/145L BS R119 ECO,
RPS22	750QWU	58498	07/31/2023	TYRES	15	77000232		BRIAUS01		1.87E+08	CASE STOCK 11R22.5 ECOPIA,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000084		BRIAUS01		1.87E+08	FIT TBR TYRE,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000517		BRIAUS01		1.87E+08	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	58498	07/31/2023	TYRES	15	33000118		BRIAUS01		1.87E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	60295	09/28/2023	TRA	1	LABOUR	MECH	Labour			
RPS22	750QWU	60295	09/28/2023	TRA	SERVICE COMPLETED.						
RPS22	750QWU	60295	09/28/2023	TRB	1	LABOUR	MECH 3	Labour			
RPS22	750QWU	60295	09/28/2023	TRB	SERVICE COMPLETED BY MATT & FLYNN ON 28/09/2023. REPLACED DAMAGED HUB CAP RH REAR						
RPS22	750QWU	60295	09/28/2023	TRB	0	LABOUR	APPRENF	Labour - Internal			
RPS22	750QWU	60295	09/28/2023	TRB	16	CON		YAT	CONSUMABLES		
RPS22	750QWU	60295	09/28/2023	TRB	15	BPW0321225310		YAT	BPW ECO PLUS M136 x 2.5 HUB CAP		

										Consumab les
RPS22	750QWU	60835	10/17/2023	FVGEN	39	CON		BRIVAL01	EX00030962	,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	61-0600		BRIVAL01	EX00030962	RECIEVER DRIER, FRIDGE MOTOR,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	Drive Plate		BRIVAL01	EX00030962	Drive Plate,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	77-2856		BRIVAL01	EX00030962	Bush Drive Coupling,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	22-1160		BRIVAL01	EX00030962	OIL PUMP ASSEMBLY FRIDGE,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	Solest Oil		BRIVAL01	EX00030962	Solest Compressor Oil,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	LAB		BRIVAL01	EX00030962	Labour,
										Consumab les
RPS22	750QWU	60835	10/17/2023	FVGEN	39	CON		BRIVAL01	INV-00018156	,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	61-0600		BRIVAL01	INV-00018156	RECIEVER DRIER, FRIDGE MOTOR,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	Drive Plate		BRIVAL01	INV-00018156	Drive Plate,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	77-2856		BRIVAL01	INV-00018156	Bush Drive Coupling,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	22-1160		BRIVAL01	INV-00018156	OIL PUMP ASSEMBLY FRIDGE,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	Solest Oil		BRIVAL01	INV-00018156	Solest Compressor Oil,
RPS22	750QWU	60835	10/17/2023	FVGEN	39	LAB		BRIVAL01	INV-00018156	Labour,
RPS22	750QWU	61147	10/25/2023	TRA	1	LABOUR	APPREN	Labour		
RPS22	750QWU	61147	10/25/2023	TRA	SERVICE COMPLETED BY TYLER ON 24/10/2023.					
RPS22	750QWU	61147	10/25/2023	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	61293	10/27/2023	GEN	15	99015526		BRIAUS01	EX00031129	RUNOUT TYRE,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000084		BRIAUS01	EX00031129	FIT TBR TYRE,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000522		BRIAUS01	EX00031129	REMOVAL: PUNCTURED,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000118		BRIAUS01	EX00031129	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	61293	10/27/2023	GEN	15	99015526		BRIAUS01	1.88E+08	RUNOUT TYRE,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000084		BRIAUS01	1.88E+08	FIT TBR TYRE,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000522		BRIAUS01	1.88E+08	REMOVAL: PUNCTURED,
RPS22	750QWU	61293	10/27/2023	GEN	15	33000118		BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	61865	11/14/2023	GEN	15	11004117		BRIAUS01	EX00031395	11R22.5 148/145L FS FT469,

RPS22	750QWU	61867	11/14/2023	GEN	COMPLETED BY BDS MECHANICAL ON 14/11/2023 INVOICE NO. MK-RIN08126 Airbag Leaking - Inspect and replace Replace leaking shocks Inspect and test trailer suspension, connect air supply. Found					
RPS22	750QWU	61865	11/14/2023	GEN		15	33000084	BRIAUS01	EX00031395	FIT TBR TYRE,
RPS22	750QWU	61867	11/14/2023	GEN		39	LABEXT	BDSMEC01	EX00031399	AIRBAG LEAKING - INSPECT AND REPLACE. REPLACE LEAKING SHOCKS,
RPS22	750QWU	61865	11/14/2023	GEN		15	33000241	BRIAUS01	EX00031395	SCRAP TYRES TBR,
RPS22	750QWU	61867	11/14/2023	GEN		39	PART	BDSMEC01	EX00031399	AIR SPRING ASSEMBLY TYPE 36,
RPS22	750QWU	61865	11/14/2023	GEN		15	33000237	BRIAUS01	EX00031395	TENSION WHEEL NUT - TWN#442478,

RPS22	750QWU	61867	11/14/2023	GEN	39	PART		BDSMEC01	EX00031399	SHOCK ABSORBER BPW,
RPS22	750QWU	61865	11/14/2023	GEN	15	33000237		BRIAUS01	EX00031395	POS 39, 40,
RPS22	750QWU	61867	11/14/2023	GEN	16	CON		BDSMEC01	EX00031399	WYNN'S ULTRA HIGH TEMP,
RPS22	750QWU	61865	11/14/2023	GEN	15	11004117		BRIAUS01	1.88E+08	11R22.5 148/145L FS FT469,
										Consumab
										les
RPS22	750QWU	61867	11/14/2023	GEN	16	CON		BDSMEC01	EX00031399	,
RPS22	750QWU	61865	11/14/2023	GEN	15	33000084		BRIAUS01	1.88E+08	FIT TBR TYRE,
RPS22	750QWU	61867	11/14/2023	GEN	16	ENVLEV		BDSMEC01	EX00031399	ENVIRONMENTAL LEVY,
RPS22	750QWU	61865	11/14/2023	GEN	15	33000241		BRIAUS01	1.88E+08	SCRAP TYRES TBR,
RPS22	750QWU	61867	11/14/2023	GEN	39	LABEXT		BDSMEC01	MK-RIN08126	AIRBAG LEAKING - INSPECT AND REPLACE. REPLACE LEAKING SHOCKS,
RPS22	750QWU	61865	11/14/2023	GEN	15	33000237		BRIAUS01	1.88E+08	TENSION WHEEL NUT - TWN#442478,
RPS22	750QWU	61867	11/14/2023	GEN	39	PART		BDSMEC01	MK-RIN08126	AIR SPRING ASSEMBLY TYPE 36,
RPS22	750QWU	61865	11/14/2023	GEN	15	33000237		BRIAUS01	1.88E+08	POS 39, 40,
RPS22	750QWU	61867	11/14/2023	GEN	39	PART		BDSMEC01	MK-RIN08126	SHOCK ABSORBER BPW,
RPS22	750QWU	61867	11/14/2023	GEN	16	CON		BDSMEC01	MK-RIN08126	WYNN'S ULTRA HIGH TEMP,
										Consumab
										les
RPS22	750QWU	61867	11/14/2023	GEN	16	CON		BDSMEC01	MK-RIN08126	,
RPS22	750QWU	61867	11/14/2023	GEN	16	ENVLEV		BDSMEC01	MK-RIN08126	ENVIRONMENTAL LEVY,
RPS22	750QWU	62110	11/21/2023	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	62110	11/21/2023	TRA	A SERVICE COMPLETED BY NQFM 21/11/2023 INV # 36151					
RPS22	750QWU	62110	11/21/2023	TRA	39	LAB		RCCLOW01	EX00031510	Labour,
RPS22	750QWU	62110	11/21/2023	TRA	39	CON		RCCLOW01	EX00031510	GREASE,
										Consumab
										les
RPS22	750QWU	62110	11/21/2023	TRA	39	CON		RCCLOW01	EX00031510	,
RPS22	750QWU	62110	11/21/2023	TRA	39	ENVLEV		RCCLOW01	EX00031510	ENVIRONMENTAL LEVY,
RPS22	750QWU	62110	11/21/2023	TRA	39	ENVLEV		RCCLOW01	36151	ENVIRONMENTAL LEVY,
										Consumab
										les
RPS22	750QWU	62110	11/21/2023	TRA	39	CON		RCCLOW01	36151	,
RPS22	750QWU	62110	11/21/2023	TRA	39	CON		RCCLOW01	36151	GREASE,
RPS22	750QWU	62110	11/21/2023	TRA	39	LAB		RCCLOW01	36151	Labour,
RPS22	750QWU	63209	12/22/2023	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	63209	12/22/2023	DEFECT						
RPS22	750QWU	63209	12/22/2023	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	63209	12/22/2023	FRIVANB	0	LABOUR	MECH	Labour		

RPS22	750QWU	63209	12/22/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

RPS22	750QWU	63209	12/22/2023	FRIVANB	OUT B SERVICE AS PER BVR SPECIFICATIONS 22/12/2023 UNIT FAULTING ON ALARM CODE 106 - REMOVE AND REPLACE U/S COIL PRETRIP UNIT FAILED ON RUN RELAY - REMOVE AND REPLACE U/S FUEL SOLENOID						
RPS22	750QWU	63209	12/22/2023	FRIVANB		40	3413005	YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	CON	BRIVAL01		EX00032093	Consumables,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	CC	BRIVAL01		EX00032093	CALIBRATION CETIFICATE,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	100417	BRIVAL01		EX00032093	Filter Service Kit, Fridge Motor, SLX-400,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	42-0100	BRIVAL01		EX00032093	STOP FUEL SOLENOID, FRIDGE MOTORS,WARRANRY ZERO COST
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	61-8939	BRIVAL01		EX00032093	SOLENOID VALVE,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	LAB	BRIVAL01		EX00032093	Labour,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	CON	BRIVAL01		INV-00019188	Consumables,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	CC	BRIVAL01		INV-00019188	CALIBRATION CETIFICATE,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	100417	BRIVAL01		INV-00019188	Filter Service Kit, Fridge Motor, SLX-400,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	42-0100	BRIVAL01		INV-00019188	STOP FUEL SOLENOID, FRIDGE MOTORS,WARRANRY ZERO COST

RPS22	750QWU	63209	12/22/2023	FRIVANB		39	61-8939		BRIVAL01	INV-00019188	SOLENOID VALVE,
RPS22	750QWU	63209	12/22/2023	FRIVANB		39	LAB		BRIVAL01	INV-00019188	Labour,
RPS22	750QWU	63209	12/22/2023	FRIVCAL		1	LABOUR	MECH	Labour		
RPS22	750QWU	63135	12/28/2023	DEFECT		1	LABOUR	MECH	Labour		
RPS22	750QWU	63135	12/28/2023	DEFECT							
RPS22	750QWU	63135	12/28/2023	DEFECT	DEFECT CLEARED.						
RPS22	750QWU	63135	12/28/2023	TRA		1	LABOUR	APPREN	Labour		
RPS22	750QWU	63135	12/28/2023	TRA	SERVICE COMPLETED BY TYLER ON 28/12/2023. REPLACED FIRE EXTINGUISHER - NEW EXPIRY DATE - JULY 2024						
RPS22	750QWU	63135	12/28/2023	TRA		16	CON		YAT	Consumables	
RPS22	750QWU	63135	12/28/2023	TRA		19	FIREEXT4.5KG		YAT	4.5KG FIRE EXTINGUISHER	
RPS22	750QWU	63326	12/28/2023	WEICAL	AIR GAUGE: 20750 ADJUSTED: 20750 WEIGHBRIDGE: 20500						
RPS22	750QWU	63326	12/28/2023	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						

RPS22	750QWU	63620	01/15/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	63621	01/15/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	63620	01/15/2024	DEFECT						
RPS22	750QWU	63621	01/15/2024	DEFECT						
RPS22	750QWU	63620	01/15/2024	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	63621	01/15/2024	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	63621	01/15/2024	EXOINS	1	LABOUR	MECH	Labour		
					PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 2 MISSING REFLECTOR NOTED DURING FIRST INSPECTION. RECTIFIED 15/01/2024. NO DEFECTS APPARENT INSPECTION					
RPS22	750QWU	63621	01/15/2024	EXOINS	1	LABEXT	DIESER01	EX00032259	CARRY OUT C & D SERVICE WITHOUT BEARINGS,	
RPS22	750QWU	63621	01/15/2024	EXOINS	16	CON	DIESER01	EX00032259	DEGREASER,	
RPS22	750QWU	63621	01/15/2024	EXOINS	16	CON	DIESER01	EX00032259	MATERIALS,	

RPS22	750QWU	63621	01/15/2024	EXOINS	1	LABEXT		DIESER01		29185	CARRY OUT C & D SERVICE WITHOUT BEARINGS,
RPS22	750QWU	63621	01/15/2024	EXOINS	16	CON		DIESER01		29185	DEGREASER,
RPS22	750QWU	63621	01/15/2024	EXOINS	16	CON		DIESER01		29185	MATERIALS,
RPS22	750QWU	63620	01/15/2024	TRA	1	LABOUR	MECH	Labour			
RPS22	750QWU	63620	01/15/2024	TRA	SERVICE COMPLETED.						
RPS22	750QWU	63620	01/15/2024	TRB	1	LABOUR	MECH	Labour			
RPS22	750QWU	63620	01/15/2024	TRB	SERVICE COMPLETED.						
RPS22	750QWU	63620	01/15/2024	TRC	1	LABOUR	MECH	Labour			
RPS22	750QWU	63620	01/15/2024	TRC	SERVICE COMPLETED BY DIESEL SERVICES QLD ON 15/01/2024. INVOICE NO. 00029185 Service as per C and D service sheet without bearings. Retention all fasteners to factory torque settings and grease all points, adjust all						
RPS22	750QWU	63620	01/15/2024	TRC	31	84035		YAT	84035 White Reflector 70x28		
RPS22	750QWU	64243	01/31/2024	FVGEN	39	CON		BRIVAL01		EX00032609	Consumables ,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	45-2258		BRIVAL01		EX00032609	120 AMP ALTERNATOR,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	78-0629		BRIVAL01		EX00032609	SB series fridge motor fanbelt,RP22

RPS22	750QWU	64243	01/31/2024	FVGEN	39	78-1360	BRIVAL01	EX00032609	ALTERNATOR BELT FRIDGE,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	LAB	BRIVAL01	EX00032609	Labour,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	Service completed by BVR 31/01/2024 - Travel to site and inspect unit - Remove and replace u/s alternator - Replace worn water pump belt and lower fan belt -				
RPS22	750QWU	64243	01/31/2024	FVGEN	39	CON	BRIVAL01	INV-00019669	Consumables,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	45-2258	BRIVAL01	INV-00019669	120 AMP ALTERNATOR,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	78-0629	BRIVAL01	INV-00019669	SB series fridge motor fanbelt,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	78-1360	BRIVAL01	INV-00019669	ALTERNATOR BELT FRIDGE,RP22
RPS22	750QWU	64243	01/31/2024	FVGEN	39	LAB	BRIVAL01	INV-00019669	Labour,RP22
RPS22	750QWU	64584	02/08/2024	WEICAL	AIR GAUGE: 17250 ADJUSTED: 16750 WEIGHBRIDGE: 16380 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RPS22	750QWU	64859	02/21/2024	DEFECT	1	LABOUR	MECH	Labour	
RPS22	750QWU	64859	02/21/2024	DEFECT					
RPS22	750QWU	64859	02/21/2024	DEFECT	DEFECT CLEARED.				
RPS22	750QWU	64859	02/21/2024	GEN	39	LABOUR	APPRENJ	Labour	

RPS22	750QWU	64859	02/21/2024	GEN	REPAIR COMPLETED BY JOSPEH ON 21.02.24 REPLACED FEMALE LIGHT PLUG ON FRONT OF TRAILER WITH A BACKING ON IT						
RPS22	750QWU	64859	02/21/2024	GEN		16	CON		YAT	Consumables	
RPS22	750QWU	64859	02/21/2024	GEN		31	700-102		YAT	RETAINER PLUG DIN	
RPS22	750QWU	64859	02/21/2024	GEN		14	82161BL		YAT	7 PIN PLUG TRAILER	
RPS22	750QWU	64916	02/23/2024	DEFECT		1	LABOUR	MECH	Labour		
RPS22	750QWU	64916	02/23/2024	DEFECT							
RPS22	750QWU	64916	02/23/2024	DEFECT	DEFECT CLEARED.						
RPS22	750QWU	64916	02/23/2024	TRA		1	LABOUR	APPREN	Labour		
RPS22	750QWU	64916	02/23/2024	TRA	SERVICE COMPLETED BY TYLER ON 23/02/2024. REPLACED BOOSTER HOSE ON LHF DUE TO THEM RUBBING.						
RPS22	750QWU	64916	02/23/2024	TRA		16	CON		YAT	Consumables	
RPS22	750QWU	65495	03/14/2024	GEN		39	LABEXT		REDTRU01	EX00033290	FRIDGE UNIT - ALTERNATOR FAULT CODE. CHECKED CHARGING - ALL GOOD. CHE

RPS22	750QWU	65495	03/14/2024	GEN		39	LABEXT		REDTRU01	INV-0168	FRIDGE UNIT - ALTERNATOR FAULT CODE. CHECKED CHARGING - ALL GOOD. CHE
RPS22	750QWU	65814	03/19/2024	GEN		39	LABOUR	Labour			0
RPS22	750QWU	65814	03/19/2024	GEN	COMPLETED BY BROWN & HURLEY ON 19/03/2024. INVOICE NO. 3155486 B-Trailer has dull lights and not all lights are working as normal. Tested electrical suzi lead, and found to be faulty, replaced, lead and socket for						
RPS22	750QWU	65814	03/19/2024	GEN		39	LABEXT		BROHUR01	EX00033492	TRAILER LIGHTS DULL, INSPECT & REPAIR,
RPS22	750QWU	65814	03/19/2024	GEN		31	82506		BROHUR01	EX00033492	Eurocoil-7 Core Suzi Coil Long Tail,
RPS22	750QWU	65814	03/19/2024	GEN		31	82062/1		BROHUR01	EX00033492	7 PIN LGE ROUND METAL SKT,

RPS22	750QWU	65814	03/19/2024	GEN	16	CON		BROHUR01	EX00033492		Consumables,
RPS22	750QWU	65814	03/19/2024	GEN	16	ENVLEV		BROHUR01	EX00033492		ENVIRONMENTAL LEVY,
RPS22	750QWU	65814	03/19/2024	GEN	39	LABEXT		BROHUR01	3155486		TRAILER LIGHTS DULL, INSPECT & REPAIR,
RPS22	750QWU	65814	03/19/2024	GEN	31	82506		BROHUR01	3155486		Eurocoil-7 Core Suzi Coil Long Tail,
RPS22	750QWU	65814	03/19/2024	GEN	31	82062/1		BROHUR01	3155486		7 PIN LGE ROUND METAL SKT,
RPS22	750QWU	65814	03/19/2024	GEN	16	CON		BROHUR01	3155486		Consumables,
RPS22	750QWU	65814	03/19/2024	GEN	16	ENVLEV		BROHUR01	3155486		ENVIRONMENTAL LEVY,
RPS22	750QWU	65802	03/25/2024	DEFECT	1	LABOUR	MECH	Labour			
RPS22	750QWU	65802	03/25/2024	DEFECT							
RPS22	750QWU	65802	03/25/2024	DEFECT	DEFECT CLEARED. Defect :- Defect Code : 00010535 Defect Reference : 10707 Date : 21/12/2023 Description of Defect : ALARM CODE 106 - PURGE VALVE CIRCUIT. CAN CLEAR IT BUT KEEPS COMING BACK. (BOTH FRIDGE						
RPS22	750QWU	65802	03/25/2024	DEFECT	UNITS						

RPS22	750QWU	65802	03/25/2024	TRA		1	LABOUR	APPRENB	Labour	
RPS22	750QWU	65802	03/25/2024	TRA	SERVICE COMPLETED BY BEN & ETHAN ON 25/03/2024. BVR HAS REPAIRED CODE. REPAIRED LHS MARKER LIGHT WIRING					
RPS22	750QWU	65802	03/25/2024	TRA		0	LABOUR	MECH 4	Labour - Internal	
RPS22	750QWU	65802	03/25/2024	TRA		16	CON		YAT	Consumables
RPS22	750QWU	66291	04/05/2024	WEICAL	AIR GAUGE: 18500 ADJUSTED: 19820 WEIGHBRIDGE: 19520 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					

RPS22	750QWU	66517	04/11/2024	FVGEN	39	CON	BRIVAL01	EX00033877		Consumables,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	BROWN TIP SOLDER	BRIVAL01	EX00033877		BROWN TIP SOLDER,rp22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	NITRO	BRIVAL01	EX00033877		NITROGEN HIGH PURITY,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	R404A	BRIVAL01	EX00033877		GAS R404A,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	LAB	BRIVAL01	EX00033877		Labour,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	Service completed by BVR 11/04/2024 - Travel to site and inspect unit for reported low on gas - Pressure test with nitrogen and check for leaks - Located split ho					
RPS22	750QWU	66517	04/11/2024	FVGEN	39	CON	BRIVAL01	INV-00020659		Consumables,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	BROWN TIP SOLDER	BRIVAL01	INV-00020659		BROWN TIP SOLDER,rp22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	NITRO	BRIVAL01	INV-00020659		NITROGEN HIGH PURITY,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	R404A	BRIVAL01	INV-00020659		GAS R404A,RP22
RPS22	750QWU	66517	04/11/2024	FVGEN	39	LAB	BRIVAL01	INV-00020659		Labour,RP22
					AIR GAUGE: 16000 ADJUSTED: 15250 WEIGHBRIDGE: 14840					
RPS22	750QWU	67336	05/09/2024	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RPS22	750QWU	67111	05/15/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	67111	05/15/2024	DEFECT						
RPS22	750QWU	67111	05/15/2024	DEFECT	DEFECT CLEARED.					

RPS22	750QWU	67111	05/15/2024	DEFECT	Defect :- Defect Code : 00011146 Defect Reference : RP22 Date : 19/03/2024 Description of Defect : WIRING FAULT. SEE BELOW AS NOTED BY BROWN & HURLEY Tested electrical suzi lead, and found to be faulty, replaced,				
RPS22	750QWU	67111	05/15/2024	TRA		1	LABOUR	MECH 1	Labour

RPS22	750QWU	67111	05/15/2024	TRA	'A' SERVICE COMPLETED BY NICK & BEN ON 15/05/2024. COULDN'T FAULT LIGHTS, ALL OK					
RPS22	750QWU	67111	05/15/2024	TRA		0	LABOUR	MECH 5	Labour - Internal	
RPS22	750QWU	67111	05/15/2024	TRA		16	CON		YAT	Consumables
RPS22	750QWU	71242	06/07/2024	SANI	TRAILER SANITISATION COMPLETED ON 07/06/2024 AT LOCATION : YATALA					
RPS22	750QWU	68150	06/11/2024	DEFECT		1	LABOUR	MECH	Labour	
RPS22	750QWU	68150	06/11/2024	DEFECT						
RPS22	750QWU	68150	06/11/2024	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	68150	06/11/2024	FRIVANB		0	LABOUR	MECH	Labour	

RPS22	750QWU	68150	06/11/2024	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR 06/06/2024. FOUND ALL ENGINE MOUNTS WORN AND UNIT STUGGLING TO START, FOUND

RPS22	750QWU	68150	06/11/2024	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	CON		BRIVAL01		EX00034751	Consumables,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	CC		BRIVAL01		EX00034751	CALIBRATION CETIFICATE,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	10-417		BRIVAL01		EX00034751	FILTER KIT (FRIDGE MOTOR),
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-4043		BRIVAL01		EX00034751	SNUBBER MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-7709		BRIVAL01		EX00034751	VIBRATION MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-4159		BRIVAL01		EX00034751	VIBRATION MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	41-4470		BRIVAL01		EX00034751	Oil Level Switch,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	45-2753		BRIVAL01		EX00034751	Yanmar Starter Motor,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	LAB		BRIVAL01		EX00034751	Labour,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	CON		BRIVAL01		INV-00021446	Consumables,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	CC		BRIVAL01		INV-00021446	CALIBRATION CETIFICATE,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	10-417		BRIVAL01		INV-00021446	FILTER KIT (FRIDGE MOTOR),
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-4043		BRIVAL01		INV-00021446	SNUBBER MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-7709		BRIVAL01		INV-00021446	VIBRATION MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	91-4159		BRIVAL01		INV-00021446	VIBRATION MOUNT,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	41-4470		BRIVAL01		INV-00021446	Oil Level Switch,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	45-2753		BRIVAL01		INV-00021446	Yanmar Starter Motor,
RPS22	750QWU	68150	06/11/2024	FRIVANB	39	LAB		BRIVAL01		INV-00021446	Labour,
RPS22	750QWU	68150	06/11/2024	FRIVCAL	1	LABOUR	MECH	Labour			
RPS22	750QWU	71256	06/18/2024	SANI	TRAILER SANITISATION COMPLETED ON 18/06/2024 AT LOCATION : TULLY						

RPS22	750QWU	68501	06/24/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	68501	06/24/2024	DEFECT						
RPS22	750QWU	68501	06/24/2024	DEFECT	DEFECT CLEARED. Defect :- Defect Code : 00011790 Defect Reference : RPS22 Date : 18/06/2024 Description of Defect : BACK LEFT HAND DOOR HINGE SEEMS TO BE BENT AND NEEDS STRAIGHTENING AS CAN'T CLOSE TOP LATCH.					
RPS22	750QWU	68501	06/24/2024	DEFECT						
RPS22	750QWU	68528	06/24/2024	GEN	15	11002821	BRIAUS01	EX00034905	11R22.5 148/145L BS R119 ECO,	
RPS22	750QWU	68639	06/24/2024	GEN	39	LAB	DLLAS01	EX00034962	ALIGNMENT OF TRAILER,	
RPS22	750QWU	68528	06/24/2024	GEN	15	77000232	BRIAUS01	EX00034905	CASE STOCK 11R22.5 ECOPIA,	
RPS22	750QWU	68639	06/24/2024	GEN	39	LAB	DLLAS01	Q623511	ALIGNMENT OF TRAILER,	
RPS22	750QWU	68528	06/24/2024	GEN	15	33000084	BRIAUS01	EX00034905	FIT TBR TYRE,	
RPS22	750QWU	68528	06/24/2024	GEN	15	33000517	BRIAUS01	EX00034905	REMOVAL: CUSTOMER PULL POINT,	
RPS22	750QWU	68528	06/24/2024	GEN	15	33000118	BRIAUS01	EX00034905	SCHEDULED DEPOT SERVICE 15MIN,	
RPS22	750QWU	68528	06/24/2024	GEN	15	11002821	BRIAUS01	1.89E+08	11R22.5 148/145L BS R119 ECO,	

RPS22	750QWU	68528	06/24/2024	GEN	15	77000232		BRIAUS01		1.89E+08	CASE STOCK 11R22.5 ECOPIA,
RPS22	750QWU	68528	06/24/2024	GEN	15	33000084		BRIAUS01		1.89E+08	FIT TBR TYRE,
RPS22	750QWU	68528	06/24/2024	GEN	15	33000517		BRIAUS01		1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	68528	06/24/2024	GEN	15	33000118		BRIAUS01		1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	68501	06/24/2024	TRA	1	LABOUR	APPREN	Labour			
RPS22	750QWU	68501	06/24/2024	TRA		SERVICE COMPLETED BY TYLER, JOSEPH & MICK ON 22/06/2024. SENT TO D & L FOR WHEEL ALIGNMENT ON 24/06/2024 FRONT LHS SPRING EYE WAS SEIZED SO WE HAD TO MELT IT OUT. REPLACED THE HEIGHT CONTROL					
RPS22	750QWU	68501	06/24/2024	TRA	0	LABOUR	APPRENJ	Labour - Internal			
RPS22	750QWU	68501	06/24/2024	TRA	0	LABOUR	MECH	Labour - Internal			
RPS22	750QWU	68501	06/24/2024	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	68654	06/25/2024	FVGEN	39	CON		BRIVAL01		EX00034970	Consumables ,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	13-2929		BRIVAL01		EX00034970	Pulley Pump Set,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-1836		BRIVAL01		EX00034970	PULLEY IDLER COMPL,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-1835		BRIVAL01		EX00034970	IDLER PULLEY - CONDENSER SIDE,RPS22

RPS22	750QWU	68654	06/25/2024	FVGEN	39	78-1360		BRIVAL01	EX00034970	ALTERNATOR BELT FRIDGE,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	LAB		BRIVAL01	EX00034970	Labour,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-2359		BRIVAL01	EX00034970	ALTERNATOR PULLEY SB,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	Service completed by BVR 25/06/2024 - Travel to site and inspect unit as unit requires pulleys - Remove belts - Remove and replace worn water pump pulley, wc					
RPS22	750QWU	68654	06/25/2024	FVGEN	39	CON		BRIVAL01	INV-00021675	Consumables,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	13-2929		BRIVAL01	INV-00021675	Pulley Pump Set,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-1836		BRIVAL01	INV-00021675	PULLEY IDLER COMPL,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-1835		BRIVAL01	INV-00021675	IDLER PULLEY - CONDENSER SIDE,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	78-1360		BRIVAL01	INV-00021675	ALTERNATOR BELT FRIDGE,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	LAB		BRIVAL01	INV-00021675	Labour,RPS22
RPS22	750QWU	68654	06/25/2024	FVGEN	39	77-2359		BRIVAL01	INV-00021675	ALTERNATOR PULLEY SB,RPS22
RPS22	750QWU	71306	07/03/2024	SANI	TRAILER SANITISATION COMPLETED ON 03/07/2024 AT LOCATION: TULLY					
RPS22	750QWU	69148	07/12/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	69148	07/12/2024	DEFECT						
RPS22	750QWU	69148	07/12/2024	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	69148	07/12/2024	TRA	1	LABOUR	MECH	Labour		
RPS22	750QWU	69148	07/12/2024	TRA	SERVICE COMPLETED.					
RPS22	750QWU	69148	07/12/2024	TRB	1	LABOUR	MECH 6	Labour		

RPS22	750QWU	69148	07/12/2024	TRB	SERVICE COMPLETED BY COREY, TYLER AND JOSEPH ON 12/07/2024. REPLACED A PIECE OF LOAD LOCK RAIL AND FIXED A HEAP OF BROKEN BITS WITH POP RIVETS AND REPLACED ALL 3 REAR LIGHTS AT						
RPS22	750QWU	69148	07/12/2024	TRB	0	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	69148	07/12/2024	TRB	0	LABOUR	APPRENJ	Labour - Internal			
RPS22	750QWU	69148	07/12/2024	TRB	16	CON		YAT	Consumables		
RPS22	750QWU	69148	07/12/2024	TRB	19	FIREEXT4.5KG		YAT	4.5KG FIRE EXTINGUISHER		
RPS22	750QWU	69148	07/12/2024	TRB	14	91632		YAT	LED Marker Light, Red. Narva		
RPS22	750QWU	69148	07/12/2024	TRB	14	91622		YAT	LED Marker light. Amber. Narva		
RPS22	750QWU	69284	07/15/2024	FVGEN	39	CON		BRIVAL01		EX00035338	Consumables,RPS22
RPS22	750QWU	69284	07/15/2024	FVGEN	39	41-9181		BRIVAL01		EX00035338	Engine Speed Solinoid,RPS22
RPS22	750QWU	69284	07/15/2024	FVGEN	39	LAB		BRIVAL01		EX00035338	Labour,RPS22
RPS22	750QWU	69284	07/15/2024	FVGEN	Service completed by BVR 15/07/2024 - Travel to site and inspect unit for reported not going into high speed - Check for power at speed solenoid, all ok - Remov						
RPS22	750QWU	69284	07/15/2024	FVGEN	39	CON		BRIVAL01		INV-00021986	Consumables,RPS22

RPS22	750QWU	69284	07/15/2024	FVGEN	39	41-9181		BRIVAL01	INV-00021986	Engine Speed Solinoid,RPS22
RPS22	750QWU	69284	07/15/2024	FVGEN	39	LAB		BRIVAL01	INV-00021986	Labour,RPS22
RPS22	750QWU	69165	07/15/2024	GEN	15	99015526		BRIAUS01	EX00035276	RUNOUT TYRE,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000084		BRIAUS01	EX00035276	FIT TBR TYRE,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000517		BRIAUS01	EX00035276	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000118		BRIAUS01	EX00035276	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	69165	07/15/2024	GEN	15	99015526		BRIAUS01	1.89E+08	RUNOUT TYRE,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000084		BRIAUS01	1.89E+08	FIT TBR TYRE,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000517		BRIAUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	69165	07/15/2024	GEN	15	33000118		BRIAUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	69985	08/14/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	69985	08/14/2024	DEFECT						
RPS22	750QWU	69985	08/14/2024	DEFECT	DEFECT CLEARED. Defect :- Defect Code : 00011669 Defect Reference : 59751 Date : 01/05/2024 Description of Defect : VERY SLOW TO BUILD UP AIR DEFECT CLEARED ON 14/08/2024 COULDN'T FIND LEAK, HOWEVER						
RPS22	750QWU	69985	08/14/2024	DEFECT						

RPS22	750QWU	69985	08/14/2024	TRA	1	LABOUR	MECH 5	Labour			
RPS22	750QWU	69985	08/14/2024	TRA	'A' SERVICE COMPLETED BY BEN (WORKSHOP) ON 14/08/2024. REPLACED INTERIOR LIGHT SWITCH COULDN'T FIND LEAK, HOWEVER IT HAS NEW AIRBAGS & RIDE HEIGHT VALVE						
RPS22	750QWU	69985	08/14/2024	TRA	16	CON	YAT	Consumables			
RPS22	750QWU	70583	08/27/2024	FVGEN	39	CON	BRIVAL01		EX00036017	Consumables ,RPS22	
RPS22	750QWU	70583	08/27/2024	FVGEN	39	LAB	BRIVAL01		EX00036017	Labour,RPS22	
RPS22	750QWU	70583	08/27/2024	FVGEN	39	77-2613	BRIVAL01		EX00036017	SB IDLER REBUILD KIT,rps22	
RPS22	750QWU	70583	08/27/2024	FVGEN	Service completed by BVR 27/08/2024 - Travel to site and inspect unit for reported unit is very loud - Remove belts - Check all pulleys and bearings - Found noisy						
RPS22	750QWU	70583	08/27/2024	FVGEN	39	CON	BRIVAL01		INV-00022644	Consumables ,RPS22	
RPS22	750QWU	70583	08/27/2024	FVGEN	39	LAB	BRIVAL01		INV-00022644	Labour,RPS22	
RPS22	750QWU	70583	08/27/2024	FVGEN	39	77-2613	BRIVAL01		INV-00022644	SB IDLER REBUILD KIT,rps22	
RPS22	750QWU	70370	08/27/2024	TYRES	15	11002821	BRIAUS01		EX00035913	11R22.5 148/145L BS R119 ECO,	
RPS22	750QWU	70370	08/27/2024	TYRES	15	77000232	BRIAUS01		EX00035913	CASE STOCK 11R22.5 ECOPIA,	
RPS22	750QWU	70370	08/27/2024	TYRES	15	33000084	BRIAUS01		EX00035913	FIT TBR TYRE,	
RPS22	750QWU	70370	08/27/2024	TYRES	15	33000517	BRIAUS01		EX00035913	REMOVAL: CUSTOMER PULL POINT,	

RPS22	750QWU	70370	08/27/2024	TYRES	15	33000118		BRIAUS01	EX00035913	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	70370	08/27/2024	TYRES	15	11002821		BRIAUS01	1.89E+08	11R22.5 148/145L BS R119 ECO,
RPS22	750QWU	70370	08/27/2024	TYRES	15	77000232		BRIAUS01	1.89E+08	CASE STOCK 11R22.5 ECOPIA,
RPS22	750QWU	70370	08/27/2024	TYRES	15	33000084		BRIAUS01	1.89E+08	FIT TBR TYRE,
RPS22	750QWU	70370	08/27/2024	TYRES	15	33000517		BRIAUS01	1.89E+08	REMOVAL: CUSTOMER PULL POINT,
RPS22	750QWU	70370	08/27/2024	TYRES	15	33000118		BRIAUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	70565	08/30/2024	DEFECT	1	LABOUR	MECH	Labour		
RPS22	750QWU	70565	08/30/2024	DEFECT						
RPS22	750QWU	70565	08/30/2024	DEFECT	DEFECT CLEARED.					
RPS22	750QWU	70565	08/30/2024	DEFECT	Reported Defect :- Defect Code : 00012319 Defect Reference : 40027 Date : 21/08/2024 Description of Defect : ROAD TRAIN SIGN MISSING OFF REAR LH SIDE (ROAD). TRAIN SIGN STILL THERE.					
RPS22	750QWU	70565	08/30/2024	GEN	39	LABOUR	APPRENJC	Labour		

RPS22	750QWU	70565	08/30/2024	GEN	REPAIR COMPLETED BY JOSH ON 30/08/2024. REPLACE LONG VEHICLE SIGNS					
RPS22	750QWU	70565	08/30/2024	GEN		16	CON		YAT	Consumables
RPS22	750QWU	70565	08/30/2024	GEN		31	MSRTLVCOMBO		YAT	2 PCE LONG VEHICLE & ROAD TRAIN SIGN
RPS22	750QWU	70957	09/16/2024	TRA		1	LABOUR	APPRENJC	Labour	
RPS22	750QWU	70957	09/16/2024	TRA	'A' SERVICE COMPLETED BY JOSH, BEN & NICK (WORKSHOP) ON 16/09/2024. TIGHTENED AIR TANK BOLTS					
RPS22	750QWU	70957	09/16/2024	TRA		0	LABOUR	MECH 5	Labour - Internal	
RPS22	750QWU	70957	09/16/2024	TRA		0	LABOUR	MECH 1	Labour - Internal	
RPS22	750QWU	70957	09/16/2024	TRA		16	CON		YAT	Consumables

					FRIDGE MOTOR CONDENSOR CLEAN COMPLETED ON 19.09.2024					
RPS22	750QWU	72551	09/19/2024	CONCLE	AT LOCATION: YATALA					
RPS22	750QWU	71528	09/19/2024	FVGEN		39	CON	BRIVAL01	EX00036397	Consumables,RPS22
RPS22	750QWU	71528	09/19/2024	FVGEN		39	LAB	BRIVAL01	EX00036397	Labour,RPS22
RPS22	750QWU	71528	09/19/2024	FVGEN	Service completed by BVR 19/09/2024 - Travel to site and inspect unit for reported remote fans alarm code (trailer is loaded and at temp) - Download data and c					
RPS22	750QWU	71528	09/19/2024	FVGEN		39	CON	BRIVAL01	INV-00022959	Consumables,RPS22
RPS22	750QWU	71528	09/19/2024	FVGEN		39	LAB	BRIVAL01	INV-00022959	Labour,RPS22
					TRAILER SANITISATION COMPLETED ON 19.09.2024					
RPS22	750QWU	72551	09/19/2024	SANI	AT LOCATION: YATALA					

RPS22	750QWU	71684	09/24/2024	FVGEN	39	CON	BRIVAL01	EX00036431	Consumables,RPS22
RPS22	750QWU	71684	09/24/2024	FVGEN	39	78-1886	BRIVAL01	EX00036431	FAN BLOWER MOTOR 14V,RPS22
RPS22	750QWU	71684	09/24/2024	FVGEN	39	LAB	BRIVAL01	EX00036431	Labour,RPS22
RPS22	750QWU	71684	09/24/2024	FVGEN	Service completed by BVR 24/09/2024 - Travel to site and inspect unit for reported faulty remote fan - Check remote fan operations - Traced to u/s FM1 - Remov				
RPS22	750QWU	71684	09/24/2024	FVGEN	39	LAB	BRIVAL01	INV-00023020	Labour,RPS22
RPS22	750QWU	71684	09/24/2024	FVGEN	39	78-1886	BRIVAL01	INV-00023020	FAN BLOWER MOTOR 14V,RPS22
RPS22	750QWU	71684	09/24/2024	FVGEN	39	CON	BRIVAL01	INV-00023020	Consumables,RPS22
RPS22	750QWU	72597	09/24/2024	SANI	TRAILER SANITISATION COMPLETED ON 24.09.2024 AT LOCATION : YATALA				
RPS22	750QWU	71847	09/27/2024	FVGEN	39	CON	BRIVAL01	EX00036482	Consumables,RPS22
RPS22	750QWU	71847	09/27/2024	FVGEN	39	LAB	BRIVAL01	EX00036482	Labour,RPS22
RPS22	750QWU	71847	09/27/2024	FVGEN	Service completed by BVR 27/09/2024 - Travel to site and inspect unit for reported not going into high speed - Tighten all belts - Tidy wiring - Test operation of s				
RPS22	750QWU	71847	09/27/2024	FVGEN	39	LAB	BRIVAL01	INV-00023081	Labour,RPS22
RPS22	750QWU	71847	09/27/2024	FVGEN	39	CON	BRIVAL01	INV-00023081	Consumables,RPS22

					AIR GAUGE: 11.30 ADJUSTED: 11.38 WEIGHBRIDGE: 11.08						
RPS22	750QWU	72794	10/16/2024	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RPS22	750QWU	72989	10/18/2024	FVGEN		39	CON		ICEGRO01	EX00036908	Consumables,RPS22
RPS22	750QWU	72989	10/18/2024	FVGEN		39	LAB		ICEGRO01	EX00036908	Labour,RPS22
RPS22	750QWU	72989	10/18/2024	FVGEN	Service completed by Iceman 18/10/2024 - Travel to site and inspect unit for reported not pulling into high speed - Traced to damaged wiring to high speed sole						
RPS22	750QWU	72989	10/18/2024	FVGEN		39	CON		ICEGRO01	INV-00023339	Consumables,RPS22
RPS22	750QWU	72989	10/18/2024	FVGEN		39	LAB		ICEGRO01	INV-00023339	Labour,RPS22
RPS22	750QWU	72691	10/18/2024	TRA		1	LABOUR	MECH 1	Labour		

RPS22	750QWU	72691	10/18/2024	TRA	'A' SERVICE COMPLETED BY NICK & JOSH (W/SHOP) ON 18/10/2024. SPLIT SYSTEM PROTECTIVE PANEL RE-RIVETED BACK ON					
RPS22	750QWU	72691	10/18/2024	TRA		0	LABOUR	APPRENJC	Labour - Internal	
RPS22	750QWU	72691	10/18/2024	TRA		16	CON		YAT	Consumables
RPS22	750QWU	75043	11/03/2024	WEICAL	AIR GAUGE: 19640 ADJUSTED: 19640 WEIGHBRIDGE: 20000 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					

RPS22	750QWU	73299	11/05/2024	FVGEN	39	CON		ICEGRO01	EX00037104	Consumables,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	NITRO		ICEGRO01	EX00037104	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	BROWN TIP SOLDER		ICEGRO01	EX00037104	BROWN TIP SOLDER,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	R404A		ICEGRO01	EX00037104	GAS R404A,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	LAB		ICEGRO01	EX00037104	Labour,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	44-2823		ICEGRO01	EX00037104	TRUCK DAMPER SOLENOID,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	Service completed by Iceman 05/11/2024 - Travel to site and inspect unit for reported not cooling (had gas topped up) - Attach gauges - Pressure test system wit					
RPS22	750QWU	73299	11/05/2024	FVGEN	39	CON		ICEGRO01	INV-00023530	Consumables,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	NITRO		ICEGRO01	INV-00023530	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	BROWN TIP SOLDER		ICEGRO01	INV-00023530	BROWN TIP SOLDER,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	R404A		ICEGRO01	INV-00023530	GAS R404A,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	LAB		ICEGRO01	INV-00023530	Labour,RPS22
RPS22	750QWU	73299	11/05/2024	FVGEN	39	44-2823		ICEGRO01	INV-00023530	TRUCK DAMPER SOLENOID,RPS22
RPS22	750QWU	73629	11/22/2024	TRA	1	LABOUR	APPRENJ	Labour		
RPS22	750QWU	73629	11/22/2024	TRA	'A' SERVICE COMPLETED BY JOSH & COREY (WORKSHOP) ON 22/11/2024. REPAIRED AIR LEAKS					
RPS22	750QWU	73629	11/22/2024	TRA	0	LABOUR	MECH 6	Labour - Internal		
RPS22	750QWU	73629	11/22/2024	TRA	16	CON		YAT	Consumables	

										PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES QLD ON 16/01/2025 INVOICE NO. 00030035 NO DEFECTS IDENTIFIED
RPS22	750QWU	74965	01/16/2025	EXOINS						
RPS22	750QWU	74965	01/16/2025	EXOINS	1	LABEXT	DIESER01	EX00038144		C & D SERVICE WITH BEARINGS AND GREASE,
RPS22	750QWU	74965	01/16/2025	EXOINS	39	LABEXT	DIESER01	EX00038144		REPLACE BRAKE KIT BPW,
RPS22	750QWU	74965	01/16/2025	EXOINS	16	DEGREASER	DIESER01	EX00038144		DEGREASER,
RPS22	750QWU	74965	01/16/2025	EXOINS	16	CON	DIESER01	EX00038144		Consumables,
RPS22	750QWU	74965	01/16/2025	EXOINS	1	LABEXT	DIESER01	30035		C & D SERVICE WITH BEARINGS AND GREASE,
RPS22	750QWU	74965	01/16/2025	EXOINS	39	LABEXT	DIESER01	30035		REPLACE BRAKE KIT BPW,
RPS22	750QWU	74965	01/16/2025	EXOINS	16	DEGREASER	DIESER01	30035		DEGREASER,

RPS22	750QWU	74965	01/16/2025	EXOINS	16	CON		DIESER01		30035	Consumables,
RPS22	750QWU	74964	01/16/2025	TRA	1	LABOUR	MECH	Labour			
RPS22	750QWU	74964	01/16/2025	TRA	SERVICE COMPLETED.						
RPS22	750QWU	74964	01/16/2025	TRB	1	LABOUR	MECH	Labour			
RPS22	750QWU	74964	01/16/2025	TRB	SERVICE COMPLETED.						
RPS22	750QWU	74964	01/16/2025	TRC	SERVICE COMPLETED BY DIESEL SERVICES QLD ON 16/01/2025. INVOICE NO. 30035 C and D service with bearings and grease. Remove, replace all bearings and seals, clean and repack all hubs. Retention						
RPS22	750QWU	74964	01/16/2025	TRC	11	0980107040TSSC		YAT	KIT W/BRG & SEAL 10T ECO		
RPS22	750QWU	74964	01/16/2025	TRC	2	MKSMG2ABC36/95		YAT	Shoe Kit BPW 36 B95		
RPS22	750QWU	74964	01/16/2025	TRC	11	2.57E+08		YAT	Hub Seal Grease, BPW, Eco Plus		
RPS22	750QWU	75560	02/01/2025	FVGEN	39	CON		ICEGRO01		EX00038457	Consumables,RPS22

RPS22	750QWU	75560	02/01/2025	FVGEN	[illegible] complete d by Iceman 01/02/20 25 - REFRIGER ANT LEAK...A/ HOURS...C ALLOUT... CHARGEB ACK FROM PARKHUR ST. NSW After hours callout - Travelled to site - Installed gauges, checked refrigeran t level and pressures -	39	LAB	ICEGRO01	EX00038457	Labour - SUBCONTRACTOR,RPS22
RPS22	750QWU	75560	02/01/2025	FVGEN	Ran unit					
RPS22	750QWU	75560	02/01/2025	FVGEN		39	CON	ICEGRO01	896621	Consumab les ,RPS22
RPS22	750QWU	75560	02/01/2025	FVGEN		39	LAB	ICEGRO01	896621	Labour - SUBCONTRACTOR,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN		39	CON	ICEGRO01	EX00038462	Consumab les ,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN		39	R404A	ICEGRO01	EX00038462	GAS R404A,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN		39	NITRO	ICEGRO01	EX00038462	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN		39	CON	ICEGRO01	EX00038462	WELDING & MATERIALS,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN		39	LAB	ICEGRO01	EX00038462	Labour,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN	Service completed by Iceman 05/02/2025 - Inspected unit - Found cracked pipe on suction pipe - Attached gauges - Carried out low side pump down - Heated an					

RPS22	750QWU	75564	02/05/2025	FVGEN	39	CON	ICEGRO01	896532	Consumables ,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN	39	R404A	ICEGRO01	896532	GAS R404A,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN	39	NITRO	ICEGRO01	896532	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN	39	CON	ICEGRO01	896532	WELDING & MATERIALS,RPS22
RPS22	750QWU	75564	02/05/2025	FVGEN	39	LAB	ICEGRO01	896532	Labour,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	780603	ICEGRO01	EX00038488	BELT- MAIN DRIVE UPPER SB-II/III/300,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	781360	ICEGRO01	EX00038488	FAN BELT, QTK FRIDGE MOTOR,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	33-2805-10	ICEGRO01	EX00038488	DISCHARGE GASKET,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	OIL-CE-35	ICEGRO01	EX00038488	ESTER OIL SOLEST 35 A/C,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	R404A	ICEGRO01	EX00038488	GAS R404A,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	NITRO	ICEGRO01	EX00038488	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	PART	ICEGRO01	EX00038488	WELDING & MATERIALS,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	VAC OUT	ICEGRO01	EX00038488	Vac Out and Reclaim System,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	LAB	ICEGRO01	EX00038488	Labour,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	Service completed by Iceman 12/02/2025 - Travelled to site - Checked over unit reported cooling fault - Installed gauges - Checked refrigerant level and pressure				
RPS22	750QWU	75630	02/12/2025	FVGEN	39	780603	ICEGRO01	896810	BELT- MAIN DRIVE UPPER SB-II/III/300,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	781360	ICEGRO01	896810	FAN BELT, QTK FRIDGE MOTOR,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	33-2805-10	ICEGRO01	896810	DISCHARGE GASKET,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	OIL-CE-35	ICEGRO01	896810	ESTER OIL SOLEST 35 A/C,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	R404A	ICEGRO01	896810	GAS R404A,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	NITRO	ICEGRO01	896810	NITROGEN HIGH PURITY,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	PART	ICEGRO01	896810	WELDING & MATERIALS,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	VAC OUT	ICEGRO01	896810	Vac Out and Reclaim System,RPS22
RPS22	750QWU	75630	02/12/2025	FVGEN	39	LAB	ICEGRO01	896810	Labour,RPS22

					AIR GAUGE: 29.02 ADJUSTED: 29.50 WEIGHBRIDGE: 29.00				
RPS22	750QWU	75770	02/14/2025	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RPS22	750QWU	75840	02/20/2025	FRIVANB		0	LABOUR	MECH	Labour

RPS22	750QWU	75840	02/20/2025	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

											Consumab les
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	CON		ICEGRO01		EX00038574	,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	CC		ICEGRO01		EX00038574	CALIBRATION CETIFICATE,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	100417		ICEGRO01		EX00038574	Filter Service Kit, Fridge Motor, SLX-400,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	LAB		ICEGRO01		EX00038574	Labour,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RPS22	750QWU	75840	02/20/2025	FRIVANB	6	COOLANT		YAT	COOLANT		
RPS22	750QWU	75840	02/20/2025	FRIVANB	Service completed by Iceman 19/02/2025 - Carried out B Service as per Iceman specifications - Topped up 1L coolant (customer supplied)						
											Consumab les
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	CON		ICEGRO01		897399	,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	CC		ICEGRO01		897399	CALIBRATION CETIFICATE,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	100417		ICEGRO01		897399	Filter Service Kit, Fridge Motor, SLX-400,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVANB	39	LAB		ICEGRO01		897399	Labour,RPS22
RPS22	750QWU	75840	02/20/2025	FRIVCAL	1	LABOUR	MECH	Labour			
RPS22	750QWU	75840	02/20/2025	FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED						
RPS22	750QWU	75980	02/26/2025	TRA	1	LABOUR	APPRENJ	Labour - Internal			

RPS22	750QWU	75980	02/26/2025	TRA	COMPLETED BY JOSEPH & BEN (WORKSHOP) ON 26/02/2025. REPLACED 4.5KG FIRE EXTINGUISHER FIRE EXT EXP: SEPTEMBER 2025 REPLACED LHS MARKER LIGHT REPLACED FEMALE LIGHT PLUG AT

RPS22	750QWU	75980	02/26/2025	TRA	16	CON		YAT	Consumables	
RPS22	750QWU	75980	02/26/2025	TRA	0	LABOUR	MECH 5	Labour - Internal		
RPS22	750QWU	75980	02/26/2025	TRA	19	FIREEXT4.5KG		YAT	4.5KG FIRE EXTINGUISHER	
RPS22	750QWU	75980	02/26/2025	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva	
RPS22	750QWU	75980	02/26/2025	TRA	31	82062/1		YAT	7 PIN LGE ROUND METAL SKT	
RPS22	750QWU	76349	03/10/2025	FVGEN	39	CON		ICEGRO01	EX00038910	Consumables,RPS22
RPS22	750QWU	76349	03/10/2025	FVGEN	39	LAB		ICEGRO01	EX00038910	Labour,RPS22
RPS22	750QWU	76349	03/10/2025	FVGEN	Service completed by Iceman 10/03/2025 - Inspected unit - Unit lost prime - Primed fuel system - Checked operation - Unit ran on test					
RPS22	750QWU	76349	03/10/2025	FVGEN	39	CON		ICEGRO01	898786	Consumables,RPS22

RPS22	750QWU	76349	03/10/2025	FVGEN	39	LAB		ICEGRO01	898786	Labour,RPS22
RPS22	750QWU	76578	03/24/2025	FVGEN	39	CON		ICEGRO01	EX00039046	Consumables,RPS22
RPS22	750QWU	76578	03/24/2025	FVGEN	39	LAB		ICEGRO01	EX00039046	Labour,RPS22
RPS22	750QWU	76578	03/24/2025	FVGEN	35	SS66TI		YAT	BATTERY, STOP/START AGM	
RPS22	750QWU	76578	03/24/2025	FVGEN	Service completed by Iceman 24/03/2025 - Inspected unit for reported not starting - Replaced u/s battery (customer supplied) - Checked operation - Unit ran on					
RPS22	750QWU	76578	03/24/2025	FVGEN	39	CON		ICEGRO01	899680	Consumables,RPS22
RPS22	750QWU	76578	03/24/2025	FVGEN	39	LAB		ICEGRO01	899680	Labour,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	39	CON		ICEGRO01	EX00039401	Consumables,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	39	45-2258-10		ICEGRO01	EX00039401	120 AMP ALTERNATOR,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	39	LAB		ICEGRO01	EX00039401	Labour,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	Service completed by Iceman 07/04/2025 - Inspected unit for reported not starting - Replaced u/s battery (customer supplied) - Checked charging - Alternator ha					
RPS22	750QWU	77035	04/07/2025	FVGEN	35	SS66TI		YAT	BATTERY, STOP/START AGM	
RPS22	750QWU	77035	04/07/2025	FVGEN	39	LAB		ICEGRO01	900688	Labour,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	39	45-2258-10		ICEGRO01	900688	120 AMP ALTERNATOR,RPS22
RPS22	750QWU	77035	04/07/2025	FVGEN	39	CON		ICEGRO01	900688	Consumables,RPS22
RPS22	750QWU	77169	04/16/2025	TYRES	15	11004117		BRIAUS01	EX00039493	11R22.5 148/145L FS FT469,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000084		BRIAUS01	EX00039493	FIT TBR TYRE,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000370		BRIAUS01	EX00039493	TYRE HELD FOR RUNOUT,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33001507		BRIAUS01	EX00039493	CUSTOMER SCRAPPED OWN TYRE,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000527		BRIAUS01	EX00039493	REMOVAL: SIDEWALL CUT OR STAKED,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000536		BRIAUS01	EX00039493	REMOVAL: MATCH OTD OR PATTERN,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000118		BRIAUS01	EX00039493	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000118		BRIAUS01	1.9E+08	SCHEDULED DEPOT SERVICE 15MIN,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000536		BRIAUS01	1.9E+08	REMOVAL: MATCH OTD OR PATTERN,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000527		BRIAUS01	1.9E+08	REMOVAL: SIDEWALL CUT OR STAKED,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33001507		BRIAUS01	1.9E+08	CUSTOMER SCRAPPED OWN TYRE,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000370		BRIAUS01	1.9E+08	TYRE HELD FOR RUNOUT,
RPS22	750QWU	77169	04/16/2025	TYRES	15	33000084		BRIAUS01	1.9E+08	FIT TBR TYRE,
RPS22	750QWU	77169	04/16/2025	TYRES	15	11004117		BRIAUS01	1.9E+08	11R22.5 148/145L FS FT469,
RPS22	750QWU	77559	05/08/2025	TRA	1	LABOUR	MECH 5	Labour - Internal		

RPS22	750QWU	77559	05/08/2025	TRA	COMPLETED.BY WORKSHOP FIRE EXT EXP: SEPTEMBER 2025 REPAIRD EARTH ISSUE FOR INTERIOR LIGHTS REPLACED MALE FITTING ON FRONT REPLACED FEMALE FITTING ON FRONT REPLACED AMBER

RPS22	750QWU	77559	05/08/2025	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	77559	05/08/2025	TRA	0	LABOUR	APPRENJ	Labour - Internal			
RPS22	750QWU	77559	05/08/2025	TRA	16	91632		YAT	LED Marker Light, Red. Narva		
RPS22	750QWU	77559	05/08/2025	TRA	16	91622		YAT	LED Marker light. Amber. Narva		
RPS22	750QWU	77775	05/08/2025	TYRES	39	CON		ICEGRO01		EX00039891	Consumables,RPS22
RPS22	750QWU	77775	05/08/2025	TYRES	39	LAB		ICEGRO01		EX00039891	Labour,RPS22
RPS22	750QWU	77775	05/08/2025	TYRES	Service completed by Iceman 08/05/2025 - Inspected unit for reported no high speed - Found damaged wire to high speed - Repaired, tidied and secured wiring						

RPS22	750QWU	77775	05/08/2025	TYRES	39	CON	ICEGRO01	902758	Consumables,RPS22
RPS22	750QWU	77775	05/08/2025	TYRES	39	LAB	ICEGRO01	902758	Labour,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	39	CON	ICEGRO01	EX00040198	Consumables,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	39	41-1566-10	ICEGRO01	EX00040198	SOLENOID - COMPLETE,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	39	LAB	ICEGRO01	EX00040198	Labour,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	Service completed by Iceman 26/05/2025 - Inspected unit for reported no high speed - Checked power at solenoid, ok - Replaced u/s high speed solenoid as requ				
RPS22	750QWU	78229	05/26/2025	FVGEN	39	CON	ICEGRO01	903811	Consumables,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	39	41-1566-10	ICEGRO01	903811	SOLENOID - COMPLETE,RPS22
RPS22	750QWU	78229	05/26/2025	FVGEN	39	LAB	ICEGRO01	903811	Labour,RPS22
RPS22	750QWU	78697	06/21/2025	FVGEN	39	CON	ICEGRO01	EX00040509	Consumables,RPS22
RPS22	750QWU	78697	06/21/2025	FVGEN	39	LABEXT	ICEGRO01	EX00040509	Labour External,RPS22

RPS22	750QWU	78697	06/21/2025	FVGEN	completed by Iceman 21/06/2025 - Travelled to sit and inspected unit - Reported zone 2 fans not working - Carried out defrost in zone 2 x2 - Informed yard hand to carry out defrost every hour FURTHER REPAIRS REQUIRED						
RPS22	750QWU	78697	06/21/2025	FVGEN		39	CON		ICEGRO01	905598	Consumables ,RPS22
RPS22	750QWU	78697	06/21/2025	FVGEN		39	LABEXT		ICEGRO01	905598	Labour External,RPS22
RPS22	750QWU	78779	06/23/2025	DEFECT		1	LABOUR	MECH	Labour		
RPS22	750QWU	78779	06/23/2025	DEFECT	DEFECT CLEARED.						

RPS22	750QWU	78779	06/23/2025	DEFECT	Reported Defect :- Defect Code : 00014525 Defect Reference : 17456 Date : 14/06/2025 Description of Defect : LEAKING AIR DROPS AIR WHEN APPLYING FOOT PEDAL				
RPS22	750QWU	78779	06/23/2025	TRA		1	LABOUR	MECH 1	Labour - Internal

RPS22	750QWU	78779	06/23/2025	TRA	COMPLETED BY WORKSHOP 23.06.2025 FIRE EXT EXP BY SEPTEMBER 2025 REPLACE AIR BAG OF POSITION 10. DEFECT # 17456 - DONE REPAIR LADDER & LATCH REPAIR & REFIT TREAD GRIP ON

RPS22	750QWU	78779	06/23/2025	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	78779	06/23/2025	TRA	0	LABOUR	APPRENJ		2	105	210
RPS22	750QWU	78779	06/23/2025	TRA	19	1K8967		YAT	AIR BAG BPW TYPE 36 WITH PISTON		
RPS22	750QWU	78722	06/25/2025	FRIVANB	0	LABOUR	MECH	Labour			

RPS22	750QWU	78722	06/25/2025	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY ICEMAN OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

RPS22	750QWU	78722	06/25/2025	FRIVANB	39	CON	ICEGRO01	EX00040536		Consumables,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	CC	ICEGRO01	EX00040536		CALIBRATION CETIFICATE,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	100417	ICEGRO01	EX00040536		Filter Service Kit, Fridge Motor, SLX-400,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	LAB	ICEGRO01	EX00040536		Labour,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	77-2613-10KIT	ICEGRO01	EX00040536		SB JACKSHAFT REBUILD KIT,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	40	3413005	YAT		OIL 15W-40, CK 4/E9	
RPS22	750QWU	78722	06/25/2025	FRIVANB	Service completed by Iceman 23/06/2025 - Carried out B Service as per Iceman Specifications - Repaired wiring to remote fans - Reran harness for high speed sol					
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	77-2613-10KIT	ICEGRO01	905704		SB JACKSHAFT REBUILD KIT,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	LAB	ICEGRO01	905704		Labour,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	100417	ICEGRO01	905704		Filter Service Kit, Fridge Motor, SLX-400,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	CC	ICEGRO01	905704		CALIBRATION CETIFICATE,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVANB	39	CON	ICEGRO01	905704		Consumables,RPS22
RPS22	750QWU	78722	06/25/2025	FRIVCAL	1	LABOUR	MECH	Labour		
RPS22	750QWU	78722	06/25/2025	FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED WEIGHBRIDGE:12520 AIR GAUGE:13500 ADJUSTED: 13000					
RPS22	750QWU	81697	06/26/2025	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					

RPS22	750QWU	79337	07/16/2025	FVGEN	39	CON	ICEGRO01	EX00040948	Consumables ,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	400974	ICEGRO01	EX00040948	Sensor, Return Air, QTK Fridge,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	780603	ICEGRO01	EX00040948	BELT- MAIN DRIVE UPPER SB-II/III/300,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	LAB	ICEGRO01	EX00040948	Labour,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	780706	ICEGRO01	EX00040948	FANSHAFT ASSEMBLY,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	40-0985-10	ICEGRO01	EX00040948	PILOT LIGHT KIT,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN		complete d by Iceman 11/07/20 25 - Inspected unit - Removed rear wall - Replaced u/s return air sensor - Replaced u/s coil sensor - Checked operation - Unit ran on test FURTHER REPAIRS REQUIRED - Fanshaft 15/07/20 25 - Inspected unit -			

RPS22	750QWU	79337	07/16/2025	FVGEN	39	CON	ICEGRO01	907228	Consumables ,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	400974	ICEGRO01	907228	Sensor, Return Air, QTK Fridge,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	780603	ICEGRO01	907228	BELT- MAIN DRIVE UPPER SB-II/III/300,RPS22

RPS22	750QWU	79337	07/16/2025	FVGEN	39	LAB		ICEGRO01		907228	Labour,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	780706		ICEGRO01		907228	FANSHAFT ASSEMBLY,RPS22
RPS22	750QWU	79337	07/16/2025	FVGEN	39	40-0985-10		ICEGRO01		907228	PILOT LIGHT KIT,RPS22
RPS22	750QWU	79593	07/29/2025	TRA	1	LABOUR	MECH	Labour - Internal			
RPS22	750QWU	79593	07/29/2025	TRA	A SERVICE COMPLETED. FIRE EXT EXP:						
RPS22	750QWU	79593	07/29/2025	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	79593	07/29/2025	TRB	1	LABOUR	APPREN	Labour - Internal			
RPS22	750QWU	79593	07/29/2025	TRB	B SERVICE COMPLETED BY WORKSHOP 29/7/2025 FIRE EXT EXP: SEPTEMBER 2025 FITTED "DUMMY" EBS PLUG REPLACED CLEARANCE LIGHT						
RPS22	750QWU	79593	07/29/2025	TRB	16	CON		YAT	Consumables		
RPS22	750QWU	79593	07/29/2025	TRB	0	LABOUR	MECH 5	Labour - Internal			
RPS22	750QWU	79593	07/29/2025	TRB	14	91700BL		YAT	Clearance Light, LED Amber, Narva		
RPS22	750QWU	80502	09/03/2025	TRA	1	LABOUR	APPRENJ	Labour - Internal			

					A SERVICE COMPLETED BY WORKSHOP 03/09/2025						
RPS22	750QWU	80502	09/03/2025	TRA	FIRE EXT EXP: FEBRUARY 2026						
RPS22	750QWU	80502	09/03/2025	TRA	16	CON		YAT	Consumables		
RPS22	750QWU	80502	09/03/2025	TRA	0	LABOUR	APPREND	Labour - Internal			
RPS22	750QWU	80502	09/03/2025	TRA	0	LABOUR	MECH 1	Labour - Internal			
RPS22	750QWU	81387	10/02/2025	FVGEN	39	CON		ICEGRO01		EX00042371	Consumables,RPS22
RPS22	750QWU	81387	10/02/2025	FVGEN	39	41-6538-10		ICEGRO01		EX00042371	COOLANT TEMP SENSOR,RPS22
RPS22	750QWU	81387	10/02/2025	FVGEN	39	LAB		ICEGRO01		EX00042371	Labour,RPS22
RPS22	750QWU	81387	10/02/2025	FVGEN	SERVICE COMPLETED BY ICEMAN 02/10/2025 - INSPECTED UNIT FOR REPORTED COOLANT TEMP -SENSOR FAULT -DRAINED COOLAT FROM SYSTEM - REPLACED						
RPS22	750QWU	81387	10/02/2025	FVGEN	39	CON		ICEGRO01		912173	Consumables,RPS22
RPS22	750QWU	81387	10/02/2025	FVGEN	39	41-6538-10		ICEGRO01		912173	COOLANT TEMP SENSOR,RPS22
RPS22	750QWU	81387	10/02/2025	FVGEN	39	LAB		ICEGRO01		912173	Labour,RPS22
			Total for Asset		########						
			Total for Report		########						

Options:
Sort By
-
Registrati
on
Starting
Asset
Code -
RPS22
To
- RPS22
Starting
Registrati
on -
To
-
Starting
Operation
s No -
To
-
From:
Work
Order
Location -
To
-

(

or slam latches - Tighten all belts - Remove and replace broken discharge clamp - Unit run on t

lt - Top up 2L coolant - Check operation - Unit run on t

CHECKED BELT, IT WAS LOOSE. TIGHTENED BE

CHECKED BELT, IT WAS LOOSE. TIGHTENED BE

hot gas pipe feeding into distributor block - Pump down system and repair leak as requred - Pressure test system, ok - Tighten all belts - Vac out unit and regas system - Run to 0c and check gas level - Unit run on t

worn alternator pulley and worn alt belt - Remove Jack shaft - Remove and replace jack shaft pulleys - Refit jack shaft - Tighten all belts - Unit run on t

nove and replace u/s speed solenoid - Unit run on t

oisy jack shaft - Remove jack shaft and refurbish - Refit jack shaft - Refit belts - Unit run on t

ıd check operation - Unit is still cooling well and holding temp - Open doors and inspect fan operations - Found left fan to be faulty - Wait for host unit to finish timed defrost - Ensure unit is still cooling well, all ok - Will need remote fan trailer is emp

nove rear zone cover - Remove and replace u/s remote fan - Refit rear zone cover - Unit run on t

of speed solenoid operation, failed - Test for power at solenoid, no power - Traced to blown fuse - Remove and replace u/s fuse and test speed solenoid operation, ok - Check over harness for damage or wear, ok - Fit extra earth to speed solenoid - Unit r

olenoid - Repair wiring as required - Remove and replace blown fuse - Unit run on t

with nitrogen - Remove rear wall and check for leaks - Found small leak at TX valve - Remove nitrogen - Repair leak as required - Change with nirtogen and check, ok - Vac out unit and regas system - Remove and replace worn damper solenoid - Refit rea

and repaired pipe as required - Pressure tested with nitrogen - Vac out unit and regassed system - Checked operation - Unit ran on t

ures - Reclaimed refrigerant from system - Repaired and soldered refrigerant leak on discharge piping - Refit discharge flange and replaced compressor discharge gasket - Topped up compressor oil level - Charged system with refrigerant - Rechecked pres

on t

r has low output - Replaced u/s alternator - Checked operation - Unit ran on t

ing as required - Checked operation - Unit ran on t

equired - Checked operation - Unit ran on t

solenoid - Removed and rebuilt jackshaft - Retensioned all belts - Checked operation - Unit ran on t

ED U/S COOLANT TEMP SENSOR - REFILLED COOLANT - CHECKED OPERATION...UNIT RAN ON TE

·un on te

r wall - Ran both zones down to 0c and check gas level, ok - Unit run on te

ssures - Checked all wiring and connections - Replaced damaged fan drive belt and alternator belt - Adjusted all belts - Checked pulleys and bearings - Ran unit and rechecked operatio