Exodas Pty Ltd

11/17/2025 14:14:52 User: HELENT

 Comp: EXO

Work Order History

Asset	Registration	Work	Work Order	Service	RM	Task	Employee	Product	W/H	Supplier
RP20	434QWL	2802	07/04/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2803	07/18/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2804	07/29/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2805	08/15/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2806	09/19/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2807	10/13/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2808	11/07/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2808	11/07/2016	TRB	1	LABOUR	MECH	Labour		
RP20	434QWL	2809	11/18/2016	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2810	01/20/2017	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2811	02/03/2017	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	2811	02/03/2017	TRB	1	LABOUR	MECH	Labour		
RP20	434QWL	3199	03/15/2017	TRA	0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	3199	03/15/2017	TRA	0	LABOUR	MECH	Labour - Internal		
RP20	434QWL	3199	03/15/2017	TRA	16	CON		YAT Consumables		
RP20	434QWL	3199	03/15/2017	TRA	KING PIN TO BE MONITORED.					
RP20	434QWL	3472	03/17/2017	TYRES	FITTED 2X RUN OUTS					
RP20	434QWL	3569	03/27/2017	TYRES	15	TYR11R22.5BRI		BRIAUS05	EX00001118	TYR11R.22.5 Bridgestone,434QWL RP20
RP20	434QWL	3569	03/27/2017	TYRES	15	TYRFIT		BRIAUS05	EX00001118	Tyre Fitting,
RP20	434QWL	3569	03/27/2017	TYRES	15	CON		BRIAUS05	EX00001118	Consumables,
RP20	434QWL	3569	03/27/2017	TYRES	15	CON		BRIAUS05	4.42E+09	Consumables,
RP20	434QWL	3569	03/27/2017	TYRES	15	TYRFIT		BRIAUS05	4.42E+09	Tyre Fitting,
RP20	434QWL	3569	03/27/2017	TYRES	15	TYR11R22.5BRI		BRIAUS05	4.42E+09	TYR11R.22.5 Bridgestone,434QWL RP20
RP20	434QWL	4914	03/31/2017	FRIVANA	1	LABOUR	MECH	Labour		
RP20	434QWL	5061	03/31/2017	FRIVANA	16	CON		QTKGRO01	EX00002119	Consumables,RP20
RP20	434QWL	4914	03/31/2017	FRIVANA	QTK PERFORMED A SERVICE - INV SI-095549					
RP20	434QWL	5061	03/31/2017	FRIVANA	0	LABEXT		QTKGRO01	EX00002119	Labour External,RP20

RP20	434QWL	5061	03/31/2017	FRIVANA	QTK SERVICED AT ROCKLEA DEPOT						
RP20	434QWL	5061	03/31/2017	FRIVANA	16	CON		QTKGRO01	SI-095549		Consumables,RP20
RP20	434QWL	5061	03/31/2017	FRIVANA	0	LABEXT		QTKGRO01	SI-095549		Labour External,RP20
RP20	434QWL	3793	04/26/2017	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	3793	04/26/2017	TRA	16	CON		YAT	Consumables		
RP20	434QWL	4021	05/11/2017	TYRES	15	CON		BRIAUS01	EX00001510		Consumables,
RP20	434QWL	4021	05/11/2017	TYRES	15	CON		BRIAUS01	4.42E+09		Consumables,
RP20	434QWL	5006	06/01/2017	FRIVANA	1	LABOUR	Labour				0
RP20	434QWL	5006	06/01/2017	FRIVANA	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RP20	434QWL	5007	06/01/2017	FRIVCAL	1	LABOUR	Labour				0
RP20	434QWL	5007	06/01/2017	FRIVCAL	ZERO DOLLAR WORK ORDER CREATED TO BRING SERVICING INTO LINE WITH QTK RECORDS 12/07/2017						
RP20	434QWL	4337	06/01/2017	TYRES	15	33000084		BRIAUS01	EX00001704		FIT TBR TYRE,NO CHARGE
RP20	434QWL	4337	06/01/2017	TYRES	15	77000180		BRIAUS01	EX00001704		CASE STOCK 11-22.5,CREDIT
RP20	434QWL	4337	06/01/2017	TYRES	15	33000096		BRIAUS01	EX00001704		PUNCTURE REPAIR TBR,
RP20	434QWL	4337	06/01/2017	TYRES	15	33000096		BRIAUS01	4.42E+09		PUNCTURE REPAIR TBR,
RP20	434QWL	4337	06/01/2017	TYRES	15	77000180		BRIAUS01	4.42E+09		CASE STOCK 11-22.5,CREDIT
RP20	434QWL	4337	06/01/2017	TYRES	15	33000084		BRIAUS01	4.42E+09		FIT TBR TYRE,NO CHARGE
RP20	434QWL	4906	06/08/2017	FRIVANA	1	LABOUR	MECH	Labour			
RP20	434QWL	4906	06/08/2017	FRIVANSE	1	LABOUR	Labour				0
RP20	434QWL	4906	06/08/2017	FRIVANSE	QTK PERFORMED B SERVICE - INV SI-099683						
RP20	434QWL	4636	06/08/2017	GEN	35	129		QTKGRO01	EX00001886		B SERVICE,
RP20	434QWL	4636	06/08/2017	GEN	35	129		QTKGRO01	SI-099683		B SERVICE,
RP20	434QWL	4488	06/09/2017	TYRES	15	33000084		BRIAUS01	EX00001787		FIT TBR TYRE,NO CHARGE
RP20	434QWL	4488	06/09/2017	TYRES	15	77000180		BRIAUS01	EX00001787		CASE STOCK 11-22.5,
RP20	434QWL	4488	06/09/2017	TYRES	15	33000084		BRIAUS01	4.42E+09		FIT TBR TYRE,NO CHARGE
RP20	434QWL	4488	06/09/2017	TYRES	15	77000180		BRIAUS01	4.42E+09		CASE STOCK 11-22.5,
RP20	434QWL	5360	07/31/2017	GEN	39	LABOUR	Labour				0
RP20	434QWL	5360	07/31/2017	GEN	39	N0440002		QTKGRO01	EX00002295		BATTERY LARGE ED5,RP20
RP20	434QWL	5360	07/31/2017	GEN	39	CON		QTKGRO01	EX00002295		Consumables,RP20
RP20	434QWL	5360	07/31/2017	GEN	39	LABEXT		QTKGRO01	EX00002295		Labour External,RP20
RP20	434QWL	5360	07/31/2017	GEN	INSPECTED UNIT 24/07/2017. BATTERY DEAD. R/R BATTERY. CHECKED SYSTEM, ALL OK.						
RP20	434QWL	5360	07/31/2017	GEN	39	LABEXT		QTKGRO01	si-103026		Labour External,RP20

RP20	434QWL	5360	07/31/2017	GEN	39	CON		QTKGRO01		si-103026	Consumables,RP20
RP20	434QWL	5360	07/31/2017	GEN	39	N0440002		QTKGRO01		si-103026	BATTERY LARGE ED5,RP20
RP20	434QWL	15138	08/18/2017	BEARPK	0	LABOUR	MECH	Labour - Internal			
RP20	434QWL	5564	08/18/2017	EXOINS	1	LABOUR	Labour				0
RP20	434QWL	5564	08/18/2017	EXOINS	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	5564	08/18/2017	EXOINS	PASSED						
RP20	434QWL	5564	08/18/2017	EXOINS	0	LABOUR	MECH	Labour - Internal			
RP20	434QWL	5604	08/18/2017	GEN	39	2.57E+08		BROHUR01		EX00002451	Hub Seal Grease, BPW, Eco Plus,RP20
RP20	434QWL	5563	08/18/2017	TRA	1	LABOUR	Labour				0
RP20	434QWL	5563	08/18/2017	TRA	0	LABOUR	MECH	Labour - Internal			
RP20	434QWL	5563	08/18/2017	TRB	1	LABOUR	Labour				0
RP20	434QWL	5563	08/18/2017	TRC	1	LABOUR	Labour				0
RP20	434QWL	5563	08/18/2017	TRC	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	5563	08/18/2017	TRC	0	LABOUR	TRADEA	Labour - Internal			
RP20	434QWL	5563	08/18/2017	TRC	13	ASA93-109		YAT	AirFitting Bulkhead (Male)1/2"		
RP20	434QWL	5563	08/18/2017	TRC	16	CON		YAT	Consumables		
RP20	434QWL	5563	08/18/2017	TRC	13	1800T/S		YAT	DO NOT OVERTAKE DECAL		
RP20	434QWL	5563	08/18/2017	TRC	'C' SERVICE COMPLETED. FITTED NEW BPW HUB CAP ORING SEALS. FITTED BPW HUB SEALS.						
RP20	434QWL	5621	08/22/2017	TYRES	15	33000084		BRIAUS01		EX00002470	FIT TBR TYRE,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000370		BRIAUS01		EX00002470	TYRE HELD FOR RUNOUT,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000241		BRIAUS01		EX00002470	SCRAP TYRES TBR,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000356		BRIAUS01		EX00002470	NWR R CASE - WORN TOO FAR,RP20
RP20	434QWL	5621	08/22/2017	TYRES	FIT UP 2X 11R22.5						
RP20	434QWL	5621	08/22/2017	TYRES	15	33000084		BRIAUS01		4.42E+09	FIT TBR TYRE,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000370		BRIAUS01		4.42E+09	TYRE HELD FOR RUNOUT,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000241		BRIAUS01		4.42E+09	SCRAP TYRES TBR,RP20
RP20	434QWL	5621	08/22/2017	TYRES	15	33000356		BRIAUS01		4.42E+09	NWR R CASE - WORN TOO FAR,RP20
RP20	434QWL	5805	08/31/2017	GEN	39	CON		QTKGRO01		EX00002584	Consumables,RP20

RP20	434QWL	5805	08/31/2017	GEN	39	LABEXT		QTKGRO01		EX00002584	Labour External,RP20	
RP20	434QWL	5805	08/31/2017	GEN	DIAGNOSED NOT HEATING, AND REPAIRED UNIT.							
RP20	434QWL	5805	08/31/2017	GEN	39	CON		QTKGRO01		SI-104972	Consumables,RP20	
RP20	434QWL	5805	08/31/2017	GEN	39	LABEXT		QTKGRO01		SI-104972	Labour External,RP20	
RP20	434QWL	5812	09/04/2017	GEN	39	LABEXT		QTKGRO01		EX00002591	Labour External,RP20	
RP20	434QWL	5812	09/04/2017	GEN	0	LABOUR	MECH	0	85	0		
RP20	434QWL	5812	09/04/2017	GEN	TRAVELLED TO DIRECT IN TOWNSVILLE. DIAGNOSED POSSIBLE FAULTY RELAY BOARD. VEHICLE SENT TO BRISBANE FOR REPAIR.							
RP20	434QWL	5812	09/04/2017	GEN	0	LABOUR	MECH	Labour - Internal				
RP20	434QWL	5812	09/04/2017	GEN	39	LABEXT		QTKGRO01		SI-104870	Labour External,RP20	
RP20	434QWL	5951	09/08/2017	FRIVANSE	1	CON		QTKGRO01		EX00002661	Consumables,RP20	
RP20	434QWL	5951	09/08/2017	FRIVANSE	1	LABEXT		QTKGRO01		EX00002661	Labour External,RP20	
RP20	434QWL	5951	09/08/2017	FRIVANSE	QTK COMPLETED THE SERVICE.							
RP20	434QWL	5951	09/08/2017	FRIVANSE	1	CON		QTKGRO01		S1-105475	Consumables,RP20	
RP20	434QWL	5951	09/08/2017	FRIVANSE	1	LABEXT		QTKGRO01		S1-105475	Labour External,RP20	
RP20	434QWL	6476	10/18/2017	TYRES	REPLACED ONTO RIM							
RP20	434QWL	6476	10/18/2017	TYRES	15	LABOUR	Labour					0
RP20	434QWL	6476	10/18/2017	TYRES	15	33000084		YAT	FIT TBR TYRE			
RP20	434QWL	6662	10/30/2017	TRA	1	LABOUR	Labour					0
RP20	434QWL	6662	10/30/2017	TRA	0	LABOUR	MECH1	Labour - Internal				
RP20	434QWL	6662	10/30/2017	TRA	16	CON		YAT	Consumables			
RP20	434QWL	6662	10/30/2017	TRA	SERVICE COMPLETED.							
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	100417		QTKGRO01		EX00003322	Filter Service Kit, Fridge Motor, SLX-400,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON		QTKGRO01		EX00003322	552208 SEALING RING,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	15W40		QTKGRO01		EX00003322	ENGINE OIL,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON		QTKGRO01		EX00003322	Consumables,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON		QTKGRO01		EX00003322	Consumables,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CC		QTKGRO01		EX00003322	CALIBRATION CETIFICATE,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	LABEXT		QTKGRO01		EX00003322	Labour External,RP20	
RP20	434QWL	6979	11/17/2017	FRIVANSE	QTK COMPLETED 'B' SERVICE.							
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	LABEXT		QTKGRO01		SI-110178	Labour External,RP20	

RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CC			QTKGRO01		SI-110178	CALIBRATION CETIFICATE,RP20
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON			QTKGRO01		SI-110178	Consumables,RP20
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON			QTKGRO01		SI-110178	Consumables,RP20
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	15W40			QTKGRO01		SI-110178	ENGINE OIL,RP20
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	CON			QTKGRO01		SI-110178	552208 SEALING RING,RP20
RP20	434QWL	6979	11/17/2017	FRIVANSE	1	100417			QTKGRO01		SI-110178	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	7066	11/20/2017	GEN	39	CON			QTKGRO01		EX00003371	Consumables,RP20
RP20	434QWL	7066	11/20/2017	GEN	39	LABEXT			QTKGRO01		EX00003371	Labour External,RP20
RP20	434QWL	7066	11/20/2017	GEN		QTK CALLED TO BREAKDOWN. DIAGNOSED WIRING AND EARTHPLATE LOOSE. TENSIONED AND RE TESTED. ALL OK.						
RP20	434QWL	7066	11/20/2017	GEN	39	LABEXT			QTKGRO01		SI-110260	Labour External,RP20
RP20	434QWL	7066	11/20/2017	GEN	39	CON			QTKGRO01		SI-110260	Consumables,RP20
RP20	434QWL	7413	12/19/2017	TRA	1	LABOUR	Labour					0
RP20	434QWL	7413	12/19/2017	TRA	0	LABOUR	MECH1		Labour - Internal			
RP20	434QWL	7413	12/19/2017	TRA	16	CON			YAT	Consumables		

RP20	434QWL	7413	12/19/2017	TRA	SERVICE COMPLETED. REPAIRED LANDING LEG CROSSBAR. REPAIRED MULTIPLE AIR LEAKS.						
RP20	434QWL	7498	12/27/2017	TYRES		15	77000180	BRIAUS01		EX00003694	CASE STOCK 11-22.5,RP20
RP20	434QWL	7498	12/27/2017	TYRES		15	33000084	YAT	FIT TBR TYRE		
RP20	434QWL	7498	12/27/2017	TYRES		15	11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP20	434QWL	7498	12/27/2017	TYRES		15	77000180	BRIAUS01		4.42E+09	CASE STOCK 11-22.5,RP20
RP20	434QWL	7591	12/28/2017	FRIVANA		1	CON	QTKGRO01		EX00003739	Consumables,RP20
RP20	434QWL	7591	12/28/2017	FRIVANA		1	LABEXT	QTKGRO01		EX00003739	Labour External,RP20
RP20	434QWL	7591	12/28/2017	FRIVANA	QTK COMPLETED THE SERVICE.						
RP20	434QWL	7591	12/28/2017	FRIVANA		1	CON	QTKGRO01		SI-112956	Consumables,RP20
RP20	434QWL	7591	12/28/2017	FRIVANA		1	LABEXT	QTKGRO01		SI-112956	Labour External,RP20
RP20	434QWL	7921	01/05/2018	FRIVANA		1	78-1341	QTKGRO01		EX00003921	SB fridge motor fanbelt,RP20
RP20	434QWL	7921	01/05/2018	FRIVANA		1	CON	QTKGRO01		EX00003921	Consumables,
RP20	434QWL	7921	01/05/2018	FRIVANA		1	LABEXT	QTKGRO01		EX00003921	Labour External,
RP20	434QWL	7921	01/05/2018	FRIVANA	QTK COMPLETED THE SERVICE AND/OR REPAIRS.						
RP20	434QWL	7921	01/05/2018	FRIVANA		1	LABEXT	QTKGRO01		SI-113789	Labour External,
RP20	434QWL	7921	01/05/2018	FRIVANA		1	CON	QTKGRO01		SI-113789	Consumables,
RP20	434QWL	7921	01/05/2018	FRIVANA		1	78-1341	QTKGRO01		SI-113789	SB fridge motor fanbelt,RP20
RP20	434QWL	8105	02/05/2018	DEFECT		1	LABOUR MECH	Labour			

RP20	434QWL	8105	02/05/2018	DEFECT	Reported Defect :- Defect Code : 00000918 Defect Reference : 10970 Date : 08/01/2018 Description of Defect : ALTERNATOR CODE PRESENT THERMO KING REPAIRED FAULT 08/01/2018						
RP20	434QWL	8180	02/05/2018	FRIVANA	1	15W40		JC&SL01		EX00004109	ENGINE OIL,RP20
RP20	434QWL	8180	02/05/2018	FRIVANA	1	CON		JC&SL01		EX00004109	Consumables ,RP20
RP20	434QWL	8180	02/05/2018	FRIVANA	1	LABEXT		JC&SL01		EX00004109	Labour External,
RP20	434QWL	8180	02/05/2018	FRIVANA	JC & SL REFRIGERATION COMPLETED THE SERVICE/REPAIR.						
RP20	434QWL	8180	02/05/2018	FRIVANA	1	LABEXT		JC&SL01		8164	Labour External,
RP20	434QWL	8180	02/05/2018	FRIVANA	1	CON		JC&SL01		8164	Consumables ,RP20
RP20	434QWL	8180	02/05/2018	FRIVANA	1	15W40		JC&SL01		8164	ENGINE OIL,RP20
RP20	434QWL	8105	02/05/2018	TRA	1	LABOUR	Labour				0
RP20	434QWL	8105	02/05/2018	TRB	1	LABOUR	Labour				0
RP20	434QWL	8105	02/05/2018	TRB	0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	8105	02/05/2018	TRB	16	CON		YAT	Consumables		

RP20	434QWL	8105	02/05/2018	TRB	SERVICE COMPLETED.WHEEL BEARINGS TENSIONED. SHOCKY BOLTS TENSIONED.						
RP20	434QWL	8816	03/17/2018	GEN	39	LABOUR	Labour				0
RP20	434QWL	8816	03/17/2018	GEN	0	LABOUR	MECH	Labour - Internal			
RP20	434QWL	8816	03/17/2018	GEN	16	CON		YAT	Consumables		
RP20	434QWL	8816	03/17/2018	GEN	REPAIRED/MODIFIED PIN FOR LANDING LEG.						
RP20	434QWL	9347	04/20/2018	GEN	39	LABOUR	Labour				0
RP20	434QWL	9347	04/20/2018	GEN	0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	9347	04/20/2018	GEN	0	LABOUR	MECH	Labour - Internal			
RP20	434QWL	9347	04/20/2018	GEN	0	LABOUR	TRADEA	Labour - Internal			
RP20	434QWL	9347	04/20/2018	GEN	13	JSD01		YAT	Landing Leg Curved Foot		
RP20	434QWL	9347	04/20/2018	GEN	16	CON		YAT	Consumables		
RP20	434QWL	9347	04/20/2018	GEN	REMOVED FAILED LANDING LEG SYSTEM. FITTED NEW RHS LEG.						
RP20	434QWL	9402	04/24/2018	TRA	1	LABOUR	Labour				0
RP20	434QWL	9402	04/24/2018	TRA	0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	9402	04/24/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	9402	04/24/2018	TRA	14	82062		YAT	7 Pin Female Trailer Plug		
RP20	434QWL	9402	04/24/2018	TRA	16	CON		YAT	Consumables		
RP20	434QWL	9402	04/24/2018	TRA	SERVICE COMPLETED. FITTED NEW TRAILER PLUG.						
RP20	434QWL	9417	04/24/2018	TYRES	15	77000232		BRIAUS01		EX00004904	CASE STOCK 11R22.5 ECOPIA,RP20
RP20	434QWL	9417	04/24/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RP20	434QWL	9417	04/24/2018	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		

RP20	434QWL	9417	04/24/2018	TYRES	15	33000084		YAT	FIT TBR TYRE		
RP20	434QWL	9417	04/24/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RP20	434QWL	9417	04/24/2018	TYRES	15	77000232		BRIAUS01		4.42E+09	CASE STOCK 11R22.5 ECOPIA,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	15W40		jc&sl01		EX00005203	ENGINE OIL,RP20
											Coolant
											Allcool
											K/worth
RP20	434QWL	9884	05/18/2018	CUMBE5	1	COO		jc&sl01		EX00005203	,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	119300		jc&sl01		EX00005203	QTK Fridge A/Filter EMI 3000,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	Nov-42		jc&sl01		EX00005203	FUEL FILTER, FRIDGE MOTOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	Nov-82		jc&sl01		EX00005203	OIL FILTER, FRIDGE MOTOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	COIL		jc&sl01		EX00005203	COIL CLEAN, EVAPORATOR/CONDENSOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	SUND		jc&sl01		EX00005203	SUNDRIES,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	LABEXT		jc&sl01		EX00005203	Labour External,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	SERVICE/REPAIRS COMPLETED BY JC&SL REFRIGERATION.						
RP20	434QWL	9884	05/18/2018	CUMBE5	1	LABEXT		jc&sl01		8528	Labour External,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	SUND		jc&sl01		8528	SUNDRIES,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	COIL		jc&sl01		8528	COIL CLEAN, EVAPORATOR/CONDENSOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	Nov-82		jc&sl01		8528	OIL FILTER, FRIDGE MOTOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	Nov-42		jc&sl01		8528	FUEL FILTER, FRIDGE MOTOR,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	119300		jc&sl01		8528	QTK Fridge A/Filter EMI 3000,RP20
											Coolant
											Allcool
											K/worth
RP20	434QWL	9884	05/18/2018	CUMBE5	1	COO		jc&sl01		8528	,RP20
RP20	434QWL	9884	05/18/2018	CUMBE5	1	15W40		jc&sl01		8528	ENGINE OIL,RP20
RP20	434QWL	9963	05/28/2018	TYRES							
RP20	434QWL	9963	05/28/2018	TYRES	15	LABOUR	Labour				0
RP20	434QWL	9963	05/28/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RP20	434QWL	10423	06/19/2018	TRA	1	LABOUR	Labour				0
RP20	434QWL	10423	06/19/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	10423	06/19/2018	TRA	16	CON		YAT	Consumables		

RP20	434QWL	10423	06/19/2018	TRA	SERVICE COMPLETED. F TRACK SECTION FITTED TO TRAILER. NEW REGO LABEL FITTED. WEIGH GAUGE NEEDS TO BE FITTED, NIL STOCK.				
RP20	434QWL	10459	06/21/2018	GEN	39	LABEXT	VISMEC01	EX00005531	Labour External,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	CON	VISMEC01	EX00005531	6x AIR FITTINGS,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	CON	VISMEC01	EX00005531	DRAIN TAP,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	CON	VISMEC01	EX00005531	Consumables,RP20

RP20	434QWL	10459	06/21/2018	GEN	DIESEL TRAVELLED TO PUMA SERVICE STATION AT CALLIOPE. FOUND TRAILER AIR TANK OM THE GROUND WITH BROKEN AIR LINE AND FITTINGS. AIR TANK WAS FITTED BACK INTO THE TRAILER WITH NEW FITTINGS						
RP20	434QWL	10459	06/21/2018	GEN	39	CON		VISMEC01		4653	Consumables,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	CON		VISMEC01		4653	DRAIN TAP,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	CON		VISMEC01		4653	6x AIR FITTINGS,RP20
RP20	434QWL	10459	06/21/2018	GEN	39	LABEXT		VISMEC01		4653	Labour External,RP20
RP20	434QWL	10571	06/26/2018	TYRES							
RP20	434QWL	10571	06/26/2018	TYRES	15	LABOUR	Labour				0
RP20	434QWL	10571	06/26/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RP20	434QWL	10571	06/26/2018	TYRES	15	33000188		YAT	B FLEET PRESSURE CHECK		
RP20	434QWL	11076	07/23/2018	GEN	39	LABEXT		FLEWRI01		EX00005865	Labour External,RP20
RP20	434QWL	11076	07/23/2018	GEN	SIGN WRITING COMPLETED.						
RP20	434QWL	11076	07/23/2018	GEN	39	LABEXT		FLEWRI01		INV-5260	Labour External,RP20
RP20	434QWL	11169	08/01/2018	tra	1	LABOUR	Labour				0
RP20	434QWL	11169	08/01/2018	tra	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	11169	08/01/2018	tra	16	CON		YAT	Consumables		

RP20	434QWL	11169	08/01/2018	tra	SERVICE COMPLETED UNABLE TO CHECK INSIDE AS IT WAS LOADED WITH EMPTY CRATES				
RP20	434QWL	11476	08/21/2018	DEFECT		1	LABOUR	MECH	Labour
RP20	434QWL	11476	08/21/2018	DEFECT	Reported Defect :- Defect Code : 00001423 Defect Reference : 10423 Date : 19/06/2018 Description of Defect : WEIGH GAUGE NEEDS TO BE FITTED, NIL STOCK. FITTED - SEAN				
RP20	434QWL	11477	08/21/2018	EXOINS		1	LABOUR	Labour	0
RP20	434QWL	11477	08/21/2018	EXOINS		0	LABOUR	MECH1	Labour - Internal
RP20	434QWL	11477	08/21/2018	EXOINS	PASSED 1ST INSPECTION - SEAN				

RP20	434QWL	11471	08/21/2018	GEN	39	CON		PIRTEK01	EX00006153	PF5C 3/8 X 1/4 MALE ELBOW,RP20
RP20	434QWL	11471	08/21/2018	GEN	PARTS ONLY					
RP20	434QWL	11471	08/21/2018	GEN	39	CON		PIRTEK01	YA-T00021995	PF5C 3/8 X 1/4 MALE ELBOW,RP20
RP20	434QWL	11476	08/21/2018	TRA	1	LABOUR	Labour			0
RP20	434QWL	11476	08/21/2018	TRB	1	LABOUR	Labour			0
RP20	434QWL	11476	08/21/2018	TRC	1	LABOUR	Labour			0
RP20	434QWL	11476	08/21/2018	TRC	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	11476	08/21/2018	TRC	0	LABOUR	TRADEA	Labour - Internal		
RP20	434QWL	11476	08/21/2018	TRC	13	B310-30KG-PP		YAT	WEIGH GAUGE,TRI AXLE,W/LGE AIR BAG. PUSH/PULL SWITCH	
RP20	434QWL	11476	08/21/2018	TRC	13	91632		YAT	LED Marker Light, Red. Narva	
RP20	434QWL	11476	08/21/2018	TRC	16	CON		YAT	Consumables	
RP20	434QWL	11476	08/21/2018	TRC	COMPLETED FITTED WEIGHT GUAGE ADJUSTED ALL WHEEL BEARING & RETIGHTENED CAPS REPAIRED RHS REAR GUARD REPAIRED AIR LINES ON FRONT AXLE FITTED BRAKE DOWN KIT REPLACED TOP RHS REAR MARKET					
RP20	434QWL	11507	08/23/2018	TYRES	15	CON		BRIAUS01	EX00006184	FLIP TRUCK TYRE OR RETREAD,RP20
RP20	434QWL	11507	08/23/2018	TYRES	FLIP TRUCK TYRE OR RETREAD - BRIDGESTONE					
RP20	434QWL	11507	08/23/2018	TYRES	15	CON		BRIAUS01	96030022	FLIP TRUCK TYRE OR RETREAD,RP20

RP20	434QWL	11671	08/27/2018	FRIVANA	1	SUND		JC&SL01		EX00006270	SUNDRIES,RP20
RP20	434QWL	11671	08/27/2018	FRIVANA	1	LABEXT		JC&SL01		EX00006270	Labour External,RP20
RP20	434QWL	11671	08/27/2018	FRIVANA	A SERVICE COMPLETED						
RP20	434QWL	11671	08/27/2018	FRIVANA	1	LABEXT		JC&SL01		8895	Labour External,RP20
RP20	434QWL	11671	08/27/2018	FRIVANA	1	SUND		JC&SL01		8895	SUNDRIES,RP20
RP20	434QWL	13035	10/06/2018	GEN	39	LABEXT		DJTRAN01		EX00007075	Labour External,RP20
RP20	434QWL	13035	10/06/2018	GEN	39	PART		DJTRAN01		EX00007075	LEG HANDLE,RP20
RP20	434QWL	13035	10/06/2018	GEN	39	CON		DJTRAN01		EX00007075	Consumables,RP20
RP20	434QWL	13035	10/06/2018	GEN	FITTED NEW LANDING LEG HANDLE						
RP20	434QWL	13035	10/06/2018	GEN	39	CON		DJTRAN01		11617	Consumables,RP20
RP20	434QWL	13035	10/06/2018	GEN	39	PART		DJTRAN01		11617	LEG HANDLE,RP20
RP20	434QWL	13035	10/06/2018	GEN	39	LABEXT		DJTRAN01		11617	Labour External,RP20
RP20	434QWL	12521	10/24/2018	FRIVANA	1	LABEXT		RIXREF01		EX00006823	Labour External,RP20
RP20	434QWL	12521	10/24/2018	FRIVANA	1	SUND		RIXREF01		EX00006823	SUNDRIES,RP20
RP20	434QWL	12521	10/24/2018	FRIVANA	SERVICE COMPLETED R&R BELTS, DISCHARGE CLAMP, OIL SWITCH						
RP20	434QWL	12521	10/24/2018	FRIVANA	1	LABEXT		RIXREF01		18337	Labour External,RP20
RP20	434QWL	12521	10/24/2018	FRIVANA	1	SUND		RIXREF01		18337	SUNDRIES,RP20
RP20	434QWL	12652	10/24/2018	GEN	39	LABOUR	Labour				0
RP20	434QWL	12652	10/24/2018	GEN	11	78-0629		YAT	SB series fridge motor fanbelt		
RP20	434QWL	12652	10/24/2018	GEN	11	78-0603		YAT	SB Series Fridge motor fanbelt		
RP20	434QWL	12652	10/24/2018	GEN	11	78-1341		YAT	SB fridge motor fanbelt		
RP20	434QWL	12652	10/24/2018	GEN	3	91-0372		YAT	CLAMP TUBE, FRIDGE MOTOR		
RP20	434QWL	12652	10/24/2018	GEN	3	ED0067450810-S		YAT	Oil Pressure Switch		
RP20	434QWL	12652	10/24/2018	GEN	PARTS SUPPLIED BY EXODAS FOR SERVICING BY RIXON						
RP20	434QWL	12604	11/02/2018	TRA	1	LABOUR	Labour				0
RP20	434QWL	12604	11/02/2018	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	12604	11/02/2018	TRA	16	CON		YAT	Consumables		
RP20	434QWL	12604	11/02/2018	TRA	SERVICE COMPLETED						
RP20	434QWL	12837	11/06/2018	FRIVANA	1	LABEXT		RIXREF01		EX00006980	Labour External,RP20
RP20	434QWL	12837	11/06/2018	FRIVANA	1	SUND		RIXREF01		EX00006980	SUNDRIES,RP20
RP20	434QWL	12837	11/06/2018	FRIVANA	SERVICE COMPLETED						
RP20	434QWL	12837	11/06/2018	FRIVANA	1	LABEXT		RIXREF01		18472	Labour External,RP20

RP20	434QWL	12837	11/06/2018	FRIVANA	1	SUND	RIXREF01		18472	SUNDRIES,RP20
RP20	434QWL	12951	11/12/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007034	Labour External,RP20
RP20	434QWL	12951	11/12/2018	FRIVANA	1	SUND	RIXREF01		EX00007034	SUNDRIES,RP20
RP20	434QWL	12951	11/12/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	12951	11/12/2018	FRIVANA	1	SUND	RIXREF01		18515	SUNDRIES,RP20
RP20	434QWL	12951	11/12/2018	FRIVANA	1	LABEXT	RIXREF01		18515	Labour External,RP20
RP20	434QWL	12798	11/13/2018	TYRES	15	77000180	BRIAUS01		EX00006963	CASE STOCK 11-22.5,RP20
RP20	434QWL	12798	11/13/2018	TYRES	15	11001464	YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP20	434QWL	12798	11/13/2018	TYRES	R&R TYRES					
RP20	434QWL	12798	11/13/2018	TYRES	15	77000180	BRIAUS01		96292255	CASE STOCK 11-22.5,RP20
RP20	434QWL	13108	11/21/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007119	Labour External,RP20
RP20	434QWL	13108	11/21/2018	FRIVANA	1	SUND	RIXREF01		EX00007119	SUNDRIES,RP20
RP20	434QWL	13108	11/21/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13108	11/21/2018	FRIVANA	1	SUND	RIXREF01		18562	SUNDRIES,RP20
RP20	434QWL	13108	11/21/2018	FRIVANA	1	LABEXT	RIXREF01		18562	Labour External,RP20
RP20	434QWL	13331	11/28/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007255	Labour External,RP20
RP20	434QWL	13331	11/28/2018	FRIVANA	1	SUND	RIXREF01		EX00007255	SUNDRIES,RP20
RP20	434QWL	13331	11/28/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13331	11/28/2018	FRIVANA	1	SUND	RIXREF01		18630	SUNDRIES,RP20
RP20	434QWL	13331	11/28/2018	FRIVANA	1	LABEXT	RIXREF01		18630	Labour External,RP20
RP20	434QWL	13468	12/05/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007338	Labour External,RP20
RP20	434QWL	13468	12/05/2018	FRIVANA	1	SUND	RIXREF01		EX00007338	SUNDRIES,RP20
RP20	434QWL	13468	12/05/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13468	12/05/2018	FRIVANA	1	SUND	RIXREF01		18712	SUNDRIES,RP20
RP20	434QWL	13468	12/05/2018	FRIVANA	1	LABEXT	RIXREF01		18712	Labour External,RP20
RP20	434QWL	14143	12/07/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007679	Labour External,RP20
RP20	434QWL	14143	12/07/2018	FRIVANA	1	SUND	RIXREF01		EX00007679	SUNDRIES,RP20
RP20	434QWL	14143	12/07/2018	FRIVANA	SERVICE COMPLETED ELOACTED COIL SENSOR - CALIBRATED DEFROST SENSOR					
RP20	434QWL	14143	12/07/2018	FRIVANA	1	SUND	RIXREF01		18723	SUNDRIES,RP20
RP20	434QWL	14143	12/07/2018	FRIVANA	1	LABEXT	RIXREF01		18723	Labour External,RP20
RP20	434QWL	13633	12/11/2018	FRIVANA	1	LABEXT	RIXREF01		EX00007406	Labour External,RP20
RP20	434QWL	13633	12/11/2018	FRIVANA	1	SUND	RIXREF01		EX00007406	SUNDRIES,RP20
RP20	434QWL	13633	12/11/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13633	12/11/2018	FRIVANA	1	SUND	RIXREF01		18729	SUNDRIES,RP20
RP20	434QWL	13633	12/11/2018	FRIVANA	1	LABEXT	RIXREF01		18729	Labour External,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	FILKIT	BRIVAL01		EX00007354	FILTER KIT FRIDGE,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	CC	BRIVAL01		EX00007354	CALIBRATION CETIFICATE,RP20

RP20	434QWL	13514	12/18/2018	FRIVANSE	1	CON	BRIVAL01	EX00007354		Consumables,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	LABEXT	BRIVAL01	EX00007354		Labour External,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	40	3413005	YAT	OIL 15W-40, CK 4/E9		
RP20	434QWL	13514	12/18/2018	FRIVANSE	SERVICE COMPLETED R&R ENGINE OIL, FILTERS TOPPED UP OIL CALIBRATED UNIT					
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	FILKIT	BRIVAL01	19		FILTER KIT FRIDGE,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	CC	BRIVAL01	19		CALIBRATION CETIFICATE,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	CON	BRIVAL01	19		Consumables,RP20
RP20	434QWL	13514	12/18/2018	FRIVANSE	1	LABEXT	BRIVAL01	19		Labour External,RP20
RP20	434QWL	13942	12/24/2018	FRIVANA	1	LABEXT	RIXREF01	EX00007574		Labour External,RP20
RP20	434QWL	13942	12/24/2018	FRIVANA	1	SUND	RIXREF01	EX00007574		SUNDRIES,RP20
RP20	434QWL	13942	12/24/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13942	12/24/2018	FRIVANA	1	SUND	RIXREF01	18806		SUNDRIES,RP20
RP20	434QWL	13942	12/24/2018	FRIVANA	1	LABEXT	RIXREF01	18806		Labour External,RP20
RP20	434QWL	14041	12/28/2018	FRIVANA	1	LABEXT	BRIVAL01	EX00007633		Labour External,RP20
RP20	434QWL	14041	12/28/2018	FRIVANA	1	CON	BRIVAL01	EX00007633		Consumables,RP20
RP20	434QWL	14041	12/28/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	14041	12/28/2018	FRIVANA	1	CON	BRIVAL01	29		Consumables,RP20
RP20	434QWL	14041	12/28/2018	FRIVANA	1	LABEXT	BRIVAL01	29		Labour External,RP20
RP20	434QWL	13986	12/31/2018	FRIVANA	1	LABEXT	RIXREF01	EX00007587		Labour External,RP20
RP20	434QWL	13986	12/31/2018	FRIVANA	1	SUND	RIXREF01	EX00007587		SUNDRIES,RP20
RP20	434QWL	13986	12/31/2018	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	13986	12/31/2018	FRIVANA	1	SUND	RIXREF01	18851		SUNDRIES,RP20
RP20	434QWL	13986	12/31/2018	FRIVANA	1	LABEXT	RIXREF01	18851		Labour External,RP20

RP20	434QWL	13813	01/04/2019	WEICAL	0	LABOUR	Labour				0
RP20	434QWL	13813	01/04/2019	WEICAL	AIR GAUGE - 16.75 ADJUSTED - 18.75 WEIGHBRIDGE - 18.42						
RP20	434QWL	14098	01/06/2019	FRIVANA	1	LABEXT		BRIVAL01		EX00007647	Labour External,RP20
RP20	434QWL	14098	01/06/2019	FRIVANA	1	CON		BRIVAL01		EX00007647	Consumables,RP20
RP20	434QWL	14098	01/06/2019	FRIVANA	SERVICE COMPLETED						
RP20	434QWL	14098	01/06/2019	FRIVANA	1	CON		BRIVAL01		43	Consumables,RP20
RP20	434QWL	14098	01/06/2019	FRIVANA	1	LABEXT		BRIVAL01		43	Labour External,RP20
RP20	434QWL	13749	01/07/2019	TRA	1	LABOUR	Labour				0
RP20	434QWL	13749	01/07/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	13749	01/07/2019	TRA	13	91622		YAT	LED Marker light. Amber. Narva		
RP20	434QWL	13749	01/07/2019	TRA	16	CON		YAT	Consumables		

RP20	434QWL	13749	01/07/2019	TRA	SERVICE COMPLETED REPLACED TOP RIGHT CLEARANCE LIGHT AS REQUIRED MIDDLE AXLE TYRES WORN UNEVEN, SHOWED DAVE & WILL LET THEM RUN FOR A BIT LONGER					
RP20	434QWL	14286	01/18/2019	FRIVANA		1	LABEXT	BRIVAL01	EX00007735	Labour External,RP20
RP20	434QWL	14303	01/18/2019	FRIVANA		1	LABEXT	BRIVAL01	EX00007740	Labour External,RP20
RP20	434QWL	14286	01/18/2019	FRIVANA		1	CON	BRIVAL01	EX00007735	Consumables,RP20
RP20	434QWL	14303	01/18/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	14286	01/18/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	14303	01/18/2019	FRIVANA		1	LABEXT	BRIVAL01	46	Labour External,RP20
RP20	434QWL	14286	01/18/2019	FRIVANA		1	CON	BRIVAL01	45	Consumables,RP20
RP20	434QWL	14286	01/18/2019	FRIVANA		1	LABEXT	BRIVAL01	45	Labour External,RP20
RP20	434QWL	14605	01/30/2019	FRIVANA		1	LABCON	BRIVAL01	EX00007920	LABOUR & CONSUMABLES,RP20
RP20	434QWL	14619	01/30/2019	FRIVANA		1	LABCON	BRIVAL01	EX00007923	LABOUR & CONSUMABLES,RP20
RP20	434QWL	14605	01/30/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	14619	01/30/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	14605	01/30/2019	FRIVANA		1	LABCON	BRIVAL01	91	LABOUR & CONSUMABLES,RP20
RP20	434QWL	14619	01/30/2019	FRIVANA		1	LABCON	BRIVAL01	94	LABOUR & CONSUMABLES,RP20
RP20	434QWL	14601	01/30/2019	GEN		39	LABEXT	BRIVAL01	EX00007919	Labour External,RP20
RP20	434QWL	14601	01/30/2019	GEN	CARRY OUT DIAGNOSTIC DOWNLOAD OF SELECTED PERIOD, CONVERT TO HARD COPY FORWARDED TO WARREN					

RP20	434QWL	14601	01/30/2019	GEN	39	LABEXT		BRIVAL01		90	Labour External,RP20
RP20	434QWL	14407	02/05/2019	TRA	1	LABOUR	Labour				0
RP20	434QWL	14407	02/05/2019	TRB	1	LABOUR	Labour				0
RP20	434QWL	14407	02/05/2019	TRB	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	14407	02/05/2019	TRB	16	CON		YAT	Consumables		
RP20	434QWL	14407	02/05/2019	TRB	SERVICE COMPLETED ADJUSTED WHEEL BEARINGS AS REQUIRED						
RP20	434QWL	14485	02/06/2019	TYRES	15	77000180		BRIAUS01		EX00007863	CASE STOCK 11-22.5,RP20
RP20	434QWL	14485	02/06/2019	TYRES	15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP20	434QWL	14485	02/06/2019	TYRES	R&R TYRES PLUS ROTATION						
RP20	434QWL	14485	02/06/2019	TYRES	15	77000180		BRIAUS01		96555925	CASE STOCK 11-22.5,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	55-2208		BRIVAL01		EX00008208	COPPER WASHER,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	FILKIT		BRIVAL01		EX00008208	FILTER KIT FRIDGE,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	CON		BRIVAL01		EX00008208	Consumables,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	LABEXT		BRIVAL01		EX00008208	Labour External,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	SERVICE COMPLETED R&r ENGINE OIL & FILTERS. CALIBRATED UNIT						
RP20	434QWL	15027	02/28/2019	FRIVANSE	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	LABEXT		BRIVAL01		149	Labour External,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	CON		BRIVAL01		149	Consumables,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	FILKIT		BRIVAL01		149	FILTER KIT FRIDGE,RP20
RP20	434QWL	15027	02/28/2019	FRIVANSE	1	55-2208		BRIVAL01		149	COPPER WASHER,RP20
RP20	434QWL	15994	03/08/2019	FRIVANA	SERVICE COMPLETED						
RP20	434QWL	15448	03/13/2019	TYRES	15	11001464		BRIAUS01		EX00008432	TYRE 11R22.5 148/145L 16 BS R187,RP20
RP20	434QWL	15448	03/13/2019	TYRES	15	33000241		BRIAUS01		EX00008432	SCRAP TYRES TBR,RP20

RP20	434QWL	15448	03/13/2019	TYRES	PUNCTURE REPAIR					
RP20	434QWL	15448	03/13/2019	TYRES	15	11001464		BRIAUS01	2.46E+09	TYRE 11R22.5 148/145L 16 BS R187,RP20
RP20	434QWL	15448	03/13/2019	TYRES	15	33000241		BRIAUS01	2.46E+09	SCRAP TYRES TBR,RP20
RP20	434QWL	16053	03/14/2019	FRIVANA	1	LABCON		BRIVAL01	EX00008692	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16053	03/14/2019	FRIVANA	SERVICE COMPLETED - 21,872 HOURS					
RP20	434QWL	16053	03/14/2019	FRIVANA	1	LABCON		BRIVAL01	251	LABOUR & CONSUMABLES,RP20
RP20	434QWL	15370	03/14/2019	TRA	1	LABOUR	Labour			0
RP20	434QWL	15370	03/14/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	15370	03/14/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	15370	03/14/2019	TRA	16	CON		YAT	Consumables	
RP20	434QWL	15370	03/14/2019	TRA	SERVICE COMPLETED					
RP20	434QWL	15700	03/20/2019	FRIVANA	1	LABCON		BRIVAL01	EX00008555	LABOUR & CONSUMABLES,RP20
RP20	434QWL	15700	03/20/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	15700	03/20/2019	FRIVANA	1	LABCON		BRIVAL01	203	LABOUR & CONSUMABLES,RP20
RP20	434QWL	15659	03/20/2019	GEN	39	CON		BRIVAL01	EX00008529	Consumables,RP20
RP20	434QWL	15659	03/20/2019	GEN	39	LABEXT		BRIVAL01	EX00008529	Labour External,RP20
RP20	434QWL	15659	03/20/2019	GEN	ACID CLEAN EVAP & COND COILS					
RP20	434QWL	15659	03/20/2019	GEN	39	LABEXT		BRIVAL01	198	Labour External,RP20
RP20	434QWL	15659	03/20/2019	GEN	39	CON		BRIVAL01	198	Consumables,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00008686	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	247	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009084	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	367	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009143	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	382	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009479	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	463	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009560	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009562	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	403	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	332	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009584	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009585	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	479	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	480	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009722	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009721	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	EX00009752	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	536	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	511	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01	509	LABOUR & CONSUMABLES,RP20

RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00009959	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		577	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010116	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		625	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010208	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		644	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010238	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		662	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010378	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010591	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		EX00010592	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		743	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		752	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16001	03/27/2019	FRIVANA	1	LABCON		BRIVAL01		691	LABOUR & CONSUMABLES,RP20
RP20	434QWL	16213	04/15/2019	TRA	1	LABOUR	Labour				0
RP20	434QWL	16213	04/15/2019	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	16213	04/15/2019	TRA	0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	16213	04/15/2019	TRA	0	LABOUR	TRADEA	Labour - Internal			
RP20	434QWL	16213	04/15/2019	TRA	10	FQ7750A		YAT	Air Bag Bellow, Type 36, BPW		
RP20	434QWL	16213	04/15/2019	TRA	16	CON		YAT	Consumables		
RP20	434QWL	16213	04/15/2019	TRA		COMPLETED REPLACED FEMALE LIGHT PLUG - KEIRAN REPLACED RHS FRONT & RHS REAR AIRBAGS - SEAN REPLACED RHS FRONT MUDGUARD & STRAIGHTENED BRACKETS - KEIRAN & AUSTIN REMOVED ALL HORSE HAIR					

RP20	434QWL	17666	04/24/2019	FRIVANA	SERVICED COMPLETED					
RP20	434QWL	16743	05/15/2019	FRIVANA	Service Completed					
RP20	434QWL	16839	05/20/2019	DEFECT		1	LABOUR	MECH	Labour	
RP20	434QWL	16839	05/20/2019	DEFECT	Reported Defect :- Defect Code : 00002442 Defect Reference : 02008 Date : 03/04/2019 Description of Defect : AIR LEAK WHEN BRAKES ARE ON RP20 - PM68					
RP20	434QWL	16894	05/20/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	16839	05/20/2019	TRA		1	LABOUR	Labour		0
RP20	434QWL	16839	05/20/2019	TRA		0	LABOUR	MECH1	Labour - Internal	
RP20	434QWL	16839	05/20/2019	TRA		16	CON		YAT Consumables	
RP20	434QWL	16839	05/20/2019	TRA	SERVICE COMPLETED REPARED INTERIOR LIGHTS COULDN'T FIND ANY AIR LEAKS					

RP20	434QWL	17694	05/21/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	16919	05/21/2019	TYRES		15	77000180		BRIAUS01		EX00009165	CASE STOCK 11-22.5,RP20
RP20	434QWL	16919	05/21/2019	TYRES		15	11001464		YAT	TYRE 11R22.5 148/145L 16 BS R187		
RP20	434QWL	16919	05/21/2019	TYRES	R&R TYRES POS 29,30,31,32							
RP20	434QWL	16919	05/21/2019	TYRES		15	77000180		BRIAUS01		96884152	CASE STOCK 11-22.5,RP20
RP20	434QWL	17525	06/06/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	17760	06/11/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	17780	06/14/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	18002	06/18/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	18060	06/20/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	18235	07/01/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	18631	07/08/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	18351	07/10/2019	TRA		1	LABOUR	Labour				0
RP20	434QWL	18351	07/10/2019	TRA		0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	18351	07/10/2019	TRA		0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	18351	07/10/2019	TRA		13	91700BL		YAT	Clearance Light, LED Amber, Narva		
RP20	434QWL	18351	07/10/2019	TRA		16	CON		YAT	Consumables		
RP20	434QWL	18351	07/10/2019	TRA	SERVICE COMPLETED FITTED FIRE EXTINGUISHER AS REQUIRED FITTED 1M OF POGO TRACK RAIL AS REQUIRED FITTED NEW IDE MARKER AS REQUIRED							
RP20	434QWL	18973	07/26/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	19198	08/02/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	19267	08/07/2019	FRIVANA	SERVICE COMPLETED							
RP20	434QWL	19313	08/07/2019	GEN		39	LABEXT		BRIVAL01		EX00010244	Labour External,RP20
RP20	434QWL	19313	08/07/2019	GEN		39	78-1341		BRIVAL01		EX00010244	SB fridge motor fanbelt,RP20

RP20	434QWL	19313	08/07/2019	GEN	39	CON		BRIVAL01	EX00010244	Consumables,RP20
RP20	434QWL	19313	08/07/2019	GEN	BVR - R&R U/S ALTERNATOR BELT & CLEANED EVAP & COND COILS					
RP20	434QWL	19313	08/07/2019	GEN	39	CON		BRIVAL01	648	Consumables,RP20
RP20	434QWL	19313	08/07/2019	GEN	39	78-1341		BRIVAL01	648	SB fridge motor fanbelt,RP20
RP20	434QWL	19313	08/07/2019	GEN	39	LABEXT		BRIVAL01	648	Labour External,RP20
RP20	434QWL	19562	08/16/2019	FRIVANA	SERVICE COMPLETED					
RP20	434QWL	20204	08/16/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010877	LABOUR & CONSUMABLES,RP20
RP20	434QWL	20204	08/16/2019	FRIVANA	SERVICE COMPLETED 16/8/19 BVR					
RP20	434QWL	20204	08/16/2019	FRIVANA	1	LABCON		BRIVAL01	0000691A	LABOUR & CONSUMABLES,RP20
RP20	434QWL	19572	08/21/2019	TRA	1	LABOUR	Labour			0
RP20	434QWL	19572	08/21/2019	TRA	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	19572	08/21/2019	TRA	0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	19572	08/21/2019	TRA	13	91700BL		YAT	Clearance Light, LED Amber, Narva	
RP20	434QWL	19572	08/21/2019	TRA	10	F5002		YAT	SHOCK ABSORBER, BPW LONG	
RP20	434QWL	19572	08/21/2019	TRA	16	CON		YAT	Consumables	
RP20	434QWL	19572	08/21/2019	TRA	SERVICE COMPLETED REFITTED REAR RHS MARKER LIGHT REPLACED MIDDLE RHS MARKER LIGHT PUT NEW BOLTS IN FRONT RHS GUARD (MISSING) FITTED NEW SHOCK ABSORBER TO FRONT LHS					

RP20	434QWL	19992	08/27/2019	FRIVANA	SERVICE COMPLETED						
RP20	434QWL	20002	08/28/2019	FRIVANA	SERVICE COMPLETED						
RP20	434QWL	19859	09/02/2019	TYRES		15	33000241	BRIAUS01		EX00010544	SCRAP TYRES TBR,RP20
RP20	434QWL	20069	09/02/2019	TYRES		15	33000241	BRIAUS01		EX00010609	SCRAP TYRES TBR,RP20
RP20	434QWL	19859	09/02/2019	TYRES	R&R TYRES POS 24,28						
RP20	434QWL	20069	09/02/2019	TYRES	R&R TYRES POS 24/28						
RP20	434QWL	19859	09/02/2019	TYRES		15	33000241	BRIAUS01		4.42E+09	SCRAP TYRES TBR,RP20
RP20	434QWL	20108	09/09/2019	TYRES		15	77000180	BRIAUS01		EX00010641	CASE STOCK 11-22.5,RP20
RP20	434QWL	20108	09/09/2019	TYRES		15	TYRRUN	YAT	Tyre Runouts		
RP20	434QWL	20108	09/09/2019	TYRES	R&R TYRES POS 26						
RP20	434QWL	20108	09/09/2019	TYRES		15	77000180	BRIAUS01		97252842	CASE STOCK 11-22.5,RP20
RP20	434QWL	20230	09/10/2019	FRIVANA		1	LABCON	BRIVAL01		EX00010734	LABOUR & CONSUMABLES,RP20
RP20	434QWL	20230	09/10/2019	FRIVANA	Service Completed BVR						
RP20	434QWL	20230	09/10/2019	FRIVANA		1	LABCON	BRIVAL01		834	LABOUR & CONSUMABLES,RP20
RP20	434QWL	20096	09/12/2019	BEARPK		1	LABOUR	Labour - Internal			0
RP20	434QWL	20096	09/12/2019	BEARPK	NEW BEARINGS & FRESH GREASE BY DIESEL SERVICES						
RP20	434QWL	20095	09/12/2019	EXOINS		1	LABOUR	Labour			0
					2ND INSPECTION BY DIESEL SERVICES FAILED 1ST INSPECTION * SUSPENSION & AIRBAGS - REPLACED AIR BAGS x 4, SHOCKS x 6 * BRAKES - REPLACED SHOES, DRUMS * REFLECTOR - REPLACED						
RP20	434QWL	20095	09/12/2019	EXOINS	* WHEEL						

RP20	434QWL	20312	09/12/2019	FRIVANSE	1	LABEXT		BRIVAL01		EX00010749	Labour External,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	CON		BRIVAL01		EX00010749	Consumables,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	FILKIT		BRIVAL01		EX00010749	FILTER KIT FRIDGE,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	452589		BRIVAL01		EX00010749	Alternator, QTK Fridge,,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	Nov-80		BRIVAL01		EX00010749	HAND PRIMER,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	SERVICE COMPLETED BVR CALIBRATED UNIT R&R U/S ALTERNATOR HAND PRIMER & OIL PRESSURE SWITCH						
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	Nov-80		BRIVAL01		842	HAND PRIMER,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	452589		BRIVAL01		842	Alternator, QTK Fridge,,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	FILKIT		BRIVAL01		842	FILTER KIT FRIDGE,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	CON		BRIVAL01		842	Consumables,RP20
RP20	434QWL	20312	09/12/2019	FRIVANSE	1	LABEXT		BRIVAL01		842	Labour External,RP20
RP20	434QWL	20094	09/12/2019	TRA	1	LABOUR	Labour				0
RP20	434QWL	20094	09/12/2019	TRB	1	LABOUR	Labour				0
RP20	434QWL	20094	09/12/2019	TRC	1	LABOUR	Labour				0

RP20	434QWL	20094	09/12/2019	TRC	COMPLETED BY DIESEL SERVICES R&R WHEEL BEARINGS, SHOES, RUMS, S-CAMS & BUSHES REPLACED 1ST AXLE LH AIRBAG, BOTH MIDDLE AXLE AIR BAGS, 3RD AXLE LH AIRBAG REPLACED ALL SHOCKS R&R KING PIN				
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (C&D),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (REPLACED BRAKE KITS),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (REPLACED BRAKE DRUM),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (SLACK ADJ NEW SCAM),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (AIR BAG REPLACEMENT),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (SHOCK ABSORBER),RP20
RP20	434QWL	20094	09/12/2019	TRC		1	LABEXT	DIESER01	EX00010880	Labour External (REPLACE LEAKING AIR TANK, KING PINS, 7 PIN PLUG),RP20

RP20	434QWL	20094	09/12/2019	TRC	1	CON	DIESER01		EX00010880	Consumables,RP20
RP20	434QWL	20094	09/12/2019	TRC	1	CON	DIESER01		EX00010880	DEGREASER,RP20
RP20	434QWL	20094	09/12/2019	TRC	2	LH121	YAT	285 Brake Drum 10 Stud Suit BPW		
RP20	434QWL	20094	09/12/2019	TRC	2	MSKMG1ABC36.95	YAT	BRAKE SHOE & HARDWARE KIT BPW		
RP20	434QWL	20094	09/12/2019	TRC	10	BP1802.BAG	YAT	Air Bag BPW		
RP20	434QWL	20094	09/12/2019	TRC	8	KZ1012.01	YAT	50MM BOLT IN KING PIN		
RP20	434QWL	20094	09/12/2019	TRC	10	F5002	YAT	SHOCK ABSORBER, BPW LONG		
RP20	434QWL	20094	09/12/2019	TRC	8	17.6655A	YAT	CAMSHAFT LH BPW NEW GEN		
RP20	434QWL	20094	09/12/2019	TRC	8	17.6656A	YAT	CAMSHAFT RH BPW NEW GEN		
RP20	434QWL	20094	09/12/2019	TRC	8	0980107040TSSC	YAT	KIT W/BRG & SEAL 10T ECO		
RP20	434QWL	20094	09/12/2019	TRC	8	5.1E+08	YAT	CAM SHAFT LH TRAILER		
RP20	434QWL	20094	09/12/2019	TRC	8	5.1E+08	YAT	CAM SHAFT RH TRAILER		
RP20	434QWL	20094	09/12/2019	TRC	2	TRPAT02	YAT	AIR TANK 48LT TRAILER		
RP20	434QWL	20094	09/12/2019	TRC	8	FQ4020-S	YAT	Hub Cap Screw on (K-Hitch)		
RP20	434QWL	20094	09/12/2019	TRC	8	E-1318AHD	YAT	CAM SHAFT BUSH ASSY		
RP20	434QWL	20094	09/12/2019	TRC	8	453879	YAT	SEAL		
RP20	434QWL	20094	09/12/2019	TRC	1	CON	DIESER01		24618	DEGREASER,RP20
RP20	434QWL	20094	09/12/2019	TRC	1	CON	DIESER01		24618	Consumables,RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (REPLACE LEAKING AIR TANK, KING PINS, 7 PIN PLUG),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (SHOCK ABSORBER),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (AIR BAG REPLACEMENT),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (SLACK ADJ NEW SCAM),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (REPLACED BRAKE DRUM),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (REPLACED BRAKE KITS),RP20
RP20	434QWL	20094	09/12/2019	TRC	1	LABEXT	DIESER01		24618	Labour External (C&D),RP20
RP20	434QWL	20715	09/14/2019	WEICAL	0	LABOUR	Labour			0
RP20	434QWL	20715	09/14/2019	WEICAL	AIR GAUGE: 21.000 ADJUSTED: 21.250 WEIGHBRIDGE: 20.800					

RP20	434QWL	20408	09/23/2019	FRIVANA	1	LABCON		BRIVAL01	EX00010775	LABOUR & CONSUMABLES,RP20
RP20	434QWL	20408	09/23/2019	FRIVANA	SERVICE COMPLETED BVR 19.09.2019					
RP20	434QWL	20408	09/23/2019	FRIVANA	1	LABCON		BRIVAL01	890	LABOUR & CONSUMABLES,RP20
RP20	434QWL	21180	10/17/2019	WEICAL	0	LABOUR	Labour			0
RP20	434QWL	21180	10/17/2019	WEICAL	AIR GAUGE - 11.70 ADJUSTED - NA WEIGHBRIDGE - 11.70					
RP20	434QWL	22221	10/29/2019	FRIVANA	1	LABCON		BRIVAL01	EX00011551	LABOUR & CONSUMABLES,RP20
RP20	434QWL	22221	10/29/2019	FRIVANA	SERVICE COMPLETED BVR 28.10.2019					
RP20	434QWL	22221	10/29/2019	FRIVANA	1	LABCON		BRIVAL01	1083	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23082	11/07/2019	FVPRE	1	LABCON		BRIVAL01	EX00011987	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23082	11/07/2019	FVPRE	SERVICE COMPLETED BY BVR 05.11.2019					
RP20	434QWL	23082	11/07/2019	FVPRE	1	LABCON		BRIVAL01	1144	LABOUR & CONSUMABLES,RP20
RP20	434QWL	22406	11/14/2019	GEN	39	LAB		BRIVAL01	EX00011662	Labour,RP20
RP20	434QWL	22406	11/14/2019	GEN	39	CON		BRIVAL01	EX00011662	Consumables,RP20
RP20	434QWL	22406	11/14/2019	GEN	39	78-603		BRIVAL01	EX00011662	SB Fridge Fan belt,RP20
RP20	434QWL	22406	11/14/2019	GEN	39	78-629		BRIVAL01	EX00011662	BELT,RP20
RP20	434QWL	22406	11/14/2019	GEN	REMOVED AND REPLACED DRIVE BELTS DUE TO CRACKING CLEANED FILTER SCREEN UNIT RUN ON TEST PRETRIP PASSED					

RP20	434QWL	22406	11/14/2019	GEN		39	LAB		BRIVAL01	1179	Labour,RP20
RP20	434QWL	22406	11/14/2019	GEN		39	CON		BRIVAL01	1179	Consumables,RP20
RP20	434QWL	22406	11/14/2019	GEN		39	78-603		BRIVAL01	1179	SB Fridge Fan belt,RP20
RP20	434QWL	22406	11/14/2019	GEN		39	78-629		BRIVAL01	1179	BELT,RP20
RP20	434QWL	22665	11/27/2019	TRA		1	LABOUR	Labour			0
RP20	434QWL	22665	11/27/2019	TRA		0	LABOUR	MECH	Labour - Internal		
RP20	434QWL	22665	11/27/2019	TRA		0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	22665	11/27/2019	TRA		16	CON		YAT Consumables		
RP20	434QWL	22665	11/27/2019	TRA	SERVICE COMPLETED. ADJUSTED LHS FRONT GUARD. FITTED 1 metre OF F-TRACK ON RHS.						
RP20	434QWL	23910	12/03/2019	FRIVANA		1	LABCON		BRIVAL01	EX00012457	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23910	12/03/2019	FRIVANA	SERVICE COMPLETED BY BVR 02.12.2019						
RP20	434QWL	23910	12/03/2019	FRIVANA		1	LABCON		BRIVAL01	1257	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23097	12/15/2019	GEN		13	LABEXT		NABQAN01	EX00012000	RP20,AFTER HOURS LABOUR RATE
RP20	434QWL	23097	12/15/2019	GEN		13	CALL OUT FEE		NABQAN01	EX00012000	RP20,AFTER HOURS CALL OUT FEE
RP20	434QWL	23097	12/15/2019	GEN		13	PART		NABQAN01	EX00012000	RP20,TEE PIECE
RP20	434QWL	23097	12/15/2019	GEN		13	TRAVEL FEE		NABQAN01	EX00012000	RP20,TRAVEL CHARGE
RP20	434QWL	23097	12/15/2019	GEN	COMPLETED BY ROLENZ (ENZED) 15.12.19 INVOICE # 19-00008749 PAID VIA CREDIT CARD.						

RP20	434QWL	23097	12/15/2019	GEN	13	TRAVEL FEE		NABQAN01	19-00008749	RP20,TRAVEL CHARGE
RP20	434QWL	23097	12/15/2019	GEN	13	PART		NABQAN01	19-00008749	RP20,TEE PIECE
RP20	434QWL	23097	12/15/2019	GEN	13	CALL OUT FEE		NABQAN01	19-00008749	RP20,AFTER HOURS CALL OUT FEE
RP20	434QWL	23097	12/15/2019	GEN	13	LABEXT		NABQAN01	19-00008749	RP20,AFTER HOURS LABOUR RATE
RP20	434QWL	23354	12/17/2019	FVPRE	1	LABCON		BRIVAL01	EX00012083	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23354	12/17/2019	FVPRE	SERVICE COMPLETED BY BVR 16.12.2019					
RP20	434QWL	23354	12/17/2019	FVPRE	1	LABCON		BRIVAL01	1339	LABOUR & CONSUMABLES,RP20
RP20	434QWL	23693	01/02/2020	WEICAL	0	LABOUR	Labour			0
RP20	434QWL	23693	01/02/2020	WEICAL	AIR GAUGE: 7 ADJUSTED : 7.5 WEIGHBRIDGE: 7 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	23726	01/10/2020	TRA	1	LABOUR	Labour			0

RP20	434QWL	23726	01/10/2020	TRA	SERVICE COMPLETED SEAN / BEN 10.01.2020 REPLACED MALE FITTING AT FRONT OF TRAILER REPAIRED IN SECTION OF F TRACK TIGHTENED GUARD BOLTS RHS REAR.						
RP20	434QWL	23726	01/10/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	23726	01/10/2020	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	23726	01/10/2020	TRA	16	CON		YAT	Consumables		
RP20	434QWL	23865	01/15/2020	FVGEN	13	78-1341		BRIVAL01		EX00012442	RP20,SB fridge motor fanbelt
RP20	434QWL	23865	01/15/2020	FVGEN	16	CON		BRIVAL01		EX00012442	RP20,
RP20	434QWL	23865	01/15/2020	FVGEN	13	LABEXT		BRIVAL01		EX00012442	RP20,

RP20	434QWL	23865	01/15/2020	FVGEN	COMPLETED BY BRIDGESTONE 15.01.2020 INVOICE # 00001468 REPLACED UNSERVICEABLE ALTERNATOR BELT PRESSURE WASH EVAPORATE AND CONDENSER COILS UNIT RUN ON TEST PRETRIP PASSED.

RP20	434QWL	23865	01/15/2020	FVGEN	13	LABEXT	BRIVAL01	1468	RP20,
RP20	434QWL	23865	01/15/2020	FVGEN	16	CON	BRIVAL01	1468	RP20,
RP20	434QWL	23865	01/15/2020	FVGEN	13	78-1341	BRIVAL01	1468	RP20,SB fridge motor fanbelt
RP20	434QWL	23999	01/21/2020	GEN	15	33000517	BRIAUS01	EX00012498	RP20,REMOVAL: CUSTOMER PULL POINT
RP20	434QWL	23999	01/21/2020	GEN	15	33000085	BRIAUS01	EX00012498	RP20,ROTATE TBR TYRE
RP20	434QWL	23999	01/21/2020	GEN	15	77000180	BRIAUS01	EX00012498	RP20,CASE STOCK 11-22.5
RP20	434QWL	23999	01/21/2020	GEN	15	11001464	BRIAUS01	EX00012498	RP20,TYRE 11R22.5 148/145L 16 BS R187
RP20	434QWL	23999	01/21/2020	GEN	15	33000084	BRIAUS01	EX00012498	RP20,FIT TBR TYRE

RP20	434QWL	23999	01/21/2020	GEN	COMPLETED BY BRIDGESTONE 21.01.2020 INVOICE # 97944466					
RP20	434QWL	23999	01/21/2020	GEN	15	33000084	BRIAUS01	97944466	RP20,FIT TBR TYRE
RP20	434QWL	23999	01/21/2020	GEN	15	11001464	BRIAUS01	97944466	RP20,TYRE 11R22.5 148/145L 16 BS R187
RP20	434QWL	23999	01/21/2020	GEN	15	77000180	BRIAUS01	97944466	RP20,CASE STOCK 11-22.5
RP20	434QWL	23999	01/21/2020	GEN	15	33000085	BRIAUS01	97944466	RP20,ROTATE TBR TYRE
RP20	434QWL	23999	01/21/2020	GEN	15	33000517	BRIAUS01	97944466	RP20,REMOVAL: CUSTOMER PULL POINT
RP20	434QWL	24215	01/23/2020	FRIVANB	1	10-417	BRIVAL01	EX00012654	RP20,
RP20	434QWL	24215	01/23/2020	FRIVANB	1	917709	BRIVAL01	EX00012654	RP20,ISOLATOR ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	914043	BRIVAL01	EX00012654	RP20,SNUBBER ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	914159	BRIVAL01	EX00012654	RP20,VIBRATION ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	CON	BRIVAL01	EX00012654	RP20,
RP20	434QWL	24215	01/23/2020	FRIVANB	1	LABEXT	BRIVAL01	EX00012654	RP20,

RP20	434QWL	24215	01/23/2020	FRIVANB	ED BY BVR 23.01.2020 INVOICE # 00001504 REPLACED UNSERVICEABLE ENGINE MOUNTS MOUNTS HAD TO BE OXY CUT AS DUE TO SEIZING B SERVICE OIL 14L (CUSTOMER SUPPLIED) CALIBRATION CERTIFICATE

RP20	434QWL	24215	01/23/2020	FRIVANB	1	LABEXT		BRIVAL01	1504	RP20,
RP20	434QWL	24215	01/23/2020	FRIVANB	1	CON		BRIVAL01	1504	RP20,
RP20	434QWL	24215	01/23/2020	FRIVANB	1	914159		BRIVAL01	1504	RP20,VIBRATION ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	914043		BRIVAL01	1504	RP20,SNUBBER ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	917709		BRIVAL01	1504	RP20,ISOLATOR ENGINE MOUNT FRIDGE SB310
RP20	434QWL	24215	01/23/2020	FRIVANB	1	10-417		BRIVAL01	1504	RP20,
RP20	434QWL	24207	01/28/2020	GEN	15	33000096		BRIAUS01	EX00012645	RP20,PUNCTURE REPAIR TBR
RP20	434QWL	24207	01/28/2020	GEN	COMPLETED BY BRIDGESTONE 28.01.2020 INVOICE # 97976628					
RP20	434QWL	24207	01/28/2020	GEN	15	33000096		BRIAUS01	97976628	RP20,PUNCTURE REPAIR TBR
RP20	434QWL	25267	02/05/2020	FVPRE	1	LABCON		BRIVAL01	EX00013225	LABOUR & CONSUMABLES,RP20
RP20	434QWL	25267	02/05/2020	FVPRE	SERVICE COMPLETED BY BVR 29.01.2020					
RP20	434QWL	25267	02/05/2020	FVPRE	1	LABCON		BRIVAL01	1563	LABOUR & CONSUMABLES,RP20
RP20	434QWL	24413	02/11/2020	TRA	1	LABOUR	Labour			0

RP20	434QWL	24413	02/11/2020	TRA	COMPLETED BILLY 11.02.2020 REPLACED MISSING RIVETS INSIDE VAN TOP CORNER/ ANGLE AS REQUIRED MOVED AND RE TIGHTENED BACK AIR TANK AS IT MOVED AND CHECKED TENSION ON THE AIR TANK BOLTS RE

RP20	434QWL	24413	02/11/2020	TRA	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	24413	02/11/2020	TRA	16	CON		YAT	Consumables	
RP20	434QWL	24508	02/13/2020	GEN	15	33000517		BRIAUS01	EX00012822	RP20,REMOVAL: CUSTOMER PULL POINT
RP20	434QWL	24508	02/13/2020	GEN	15	77000180		BRIAUS01	EX00012822	RP20,CASE STOCK 11-22.5
RP20	434QWL	24508	02/13/2020	GEN	15	11001464		BRIAUS01	EX00012822	RP20,TYRE 11R22.5 148/145L 16 BS R187
RP20	434QWL	24508	02/13/2020	GEN	15	33000084		BRIAUS01	EX00012822	RP20,FIT TBR TYRE

					COMPLETED BY BRIDGESTONE 13.02.2020 INVOICE #						
RP20	434QWL	24508	02/13/2020	GEN	98066528						
RP20	434QWL	24508	02/13/2020	GEN		15	33000084		BRIAUS01	98066528	RP20,FIT TBR TYRE
RP20	434QWL	24508	02/13/2020	GEN		15	11001464		BRIAUS01	98066528	RP20,TYRE 11R22.5 148/145L 16 BS R187
RP20	434QWL	24508	02/13/2020	GEN		15	77000180		BRIAUS01	98066528	RP20,CASE STOCK 11-22.5
RP20	434QWL	24508	02/13/2020	GEN		15	33000517		BRIAUS01	98066528	RP20,REMOVAL: CUSTOMER PULL POINT
RP20	434QWL	25608	03/27/2020	TRA		1	LABOUR	Labour			0
RP20	434QWL	25608	03/27/2020	TRA	SERVICE COMPLETED.						
RP20	434QWL	25608	03/27/2020	TRB		1	LABOUR	Labour			0
					SERVICE COMPLETED BY SEAN / KEIRAN 27.03.2020						
RP20	434QWL	25608	03/27/2020	TRB	ADJUST ALL WHEEL BEARINGS AND TENSIONED CAPS TENSIONED ALL PIVOT BOLTS AND SHOCKS						
RP20	434QWL	25608	03/27/2020	TRB		0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	25608	03/27/2020	TRB		0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	25608	03/27/2020	TRB		16	CON		YAT	Consumables	
RP20	434QWL	25902	03/30/2020	FVPRE		1	LABCON		BRIVAL01	EX00013486	LABOUR & CONSUMABLES,RP20
RP20	434QWL	25902	03/30/2020	FVPRE	SERVICE COMPLETED BY BVR 23.03.2020						

RP20	434QWL	25902	03/30/2020	FVPRE	1	LABCON	BRIVAL01	1901	LABOUR & CONSUMABLES,RP20
RP20	434QWL	26052	04/07/2020	FVPRE	1	LABCON	BRIVAL01	EX00013571	LABOUR & CONSUMABLES,RP20
RP20	434QWL	26052	04/07/2020	FVPRE	SERVICE COMPLETED BY BVR 03.04.2020				
RP20	434QWL	26052	04/07/2020	FVPRE	1	LABCON	BRIVAL01	1975	LABOUR & CONSUMABLES,RP20
RP20	434QWL	26209	04/16/2020	FVGEN	16	CON	BRIVAL01	EX00013649	Consumables,RP20
RP20	434QWL	26209	04/16/2020	FVGEN	13	LABEXT	BRIVAL01	EX00013649	Labour External,RP20
RP20	434QWL	26209	04/16/2020	FVGEN	COMPLETED BY BVR 16.04.2020 INVOICE # 00002010 CALL OUT TO UNIT UNIT FOUND WITH CODE 61 TRACED FAULT TO BROKEN EARTH BOLT ON BLOCK REPAIRED UNIT RUN ON TEST PRETRIP PASSED				
RP20	434QWL	26209	04/16/2020	FVGEN	13	LABEXT	BRIVAL01	2010	Labour External,RP20
RP20	434QWL	26209	04/16/2020	FVGEN	16	CON	BRIVAL01	2010	Consumables,RP20

RP20	434QWL	26253	04/16/2020	FVPRE	1	LABCON	BRIVAL01	EX00013660	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	26253	04/16/2020	FVPRE	SERVICE COMPLETED BY BVR 07.04.2020					
RP20	434QWL	26253	04/16/2020	FVPRE	1	LABCON	BRIVAL01	2031	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	26429	04/20/2020	FVPRE	1	LABCON	BRIVAL01	EX00013776	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	27515	04/20/2020	FVPRE	1	LABCON	BRIVAL01	EX00014263	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	26429	04/20/2020	FVPRE	SERVICE COMPLETED BY BVR 15.04.2020					
RP20	434QWL	27515	04/20/2020	FVPRE	SERVICE COMPLETED BY BVR 15.04.2020					
RP20	434QWL	26429	04/20/2020	FVPRE	1	LABCON	BRIVAL01	2071	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	26477	04/21/2020	WEICAL	0	LABOUR	Labour			0
					AIR GAUGE: 19 ADJUSTED : 18.75 WEIGHBRIDGE: 18.35					
RP20	434QWL	26477	04/21/2020	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	26580	04/28/2020	WEICAL	0	LABOUR	Labour			0

					AIR GAUGE: 16.75 ADJUSTED: 0 WEIGHBRIDGE: 16.25						
RP20	434QWL	26580	04/28/2020	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	26763	05/01/2020	FVPRE		1	LABCON		BRIVAL01	EX00013908	LABOUR & CONSUMABLES,RP20
RP20	434QWL	26763	05/01/2020	FVPRE	SERVICE COMPLETED BY BVR 21.04.2020						
RP20	434QWL	26763	05/01/2020	FVPRE		1	LABCON		BRIVAL01	2136	LABOUR & CONSUMABLES,RP20
RP20	434QWL	27112	05/13/2020	FVPRE		1	LABCON		BRIVAL01	EX00014061	LABOUR & CONSUMABLES,RP20
RP20	434QWL	27112	05/13/2020	FVPRE	SERVICE COMPLETED BY BVR 08.05.2020						
RP20	434QWL	27112	05/13/2020	FVPRE		1	LABCON		BRIVAL01	2250	LABOUR & CONSUMABLES,RP20
RP20	434QWL	27310	05/21/2020	FVPRE		1	LABCON		BRIVAL01	EX00014155	LABOUR & CONSUMABLES,RP20
RP20	434QWL	27310	05/21/2020	FVPRE	SERVICE COMPLETED BY BVR 15.05.2020						
RP20	434QWL	27310	05/21/2020	FVPRE		1	LABCON		BRIVAL01	2335	LABOUR & CONSUMABLES,RP20
RP20	434QWL	27434	05/29/2020	TRA		1	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	27434	05/29/2020	TRA	SERVICE COMPLETED.						
RP20	434QWL	27434	05/29/2020	TRA		16	CON		YAT	Consumables	
RP20	434QWL	27463	05/30/2020	GEN		15	33000517		BRIAUS01	EX00014213	REMOVAL: CUSTOMER PULL POINT,RP20
RP20	434QWL	27463	05/30/2020	GEN		15	77000180		BRIAUS01	EX00014213	CASE STOCK 11-22.5,RP20
RP20	434QWL	27463	05/30/2020	GEN		15	99015526		BRIAUS01	EX00014213	RUNOUT TYRE,RP20
RP20	434QWL	27463	05/30/2020	GEN		15	33000084		BRIAUS01	EX00014213	FIT TBR TYRE,RP20
RP20	434QWL	27463	05/30/2020	GEN		15	11001464		BRIAUS01	EX00014213	TYRE 11R22.5 148/145L 16 BS R187,RP20

RP20	434QWL	27463	05/30/2020	GEN	COMPLETED BY BRIDGESTONE 30.05.2020 INVOICE # 98580341						
RP20	434QWL	27463	05/30/2020	GEN	15	11001464		BRIAUS01		98580341	TYRE 11R22.5 148/145L 16 BS R187,RP20
RP20	434QWL	27463	05/30/2020	GEN	15	33000084		BRIAUS01		98580341	FIT TBR TYRE,RP20
RP20	434QWL	27463	05/30/2020	GEN	15	99015526		BRIAUS01		98580341	RUNOUT TYRE,RP20
RP20	434QWL	27463	05/30/2020	GEN	15	77000180		BRIAUS01		98580341	CASE STOCK 11-22.5,RP20
RP20	434QWL	27463	05/30/2020	GEN	15	33000517		BRIAUS01		98580341	REMOVAL: CUSTOMER PULL POINT,RP20
RP20	434QWL	28154	06/24/2020	FRIVANA	SERVICE COMPLETED BVR 17/06/2020						
RP20	434QWL	28157	06/24/2020	FRIVANA	SERVICE COMPLETED BVR 15/06/2020						
RP20	434QWL	28470	06/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014518	LABOUR & CONSUMABLES,RP20
RP20	434QWL	28470	06/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014517	LABOUR & CONSUMABLES,RP20
RP20	434QWL	28470	06/24/2020	FRIVANA	1	LABCON		BRIVAL01		2573	LABOUR & CONSUMABLES,RP20
RP20	434QWL	28470	06/24/2020	FRIVANA	1	LABCON		BRIVAL01		2567	LABOUR & CONSUMABLES,RP20
RP20	434QWL	28284	06/30/2020	GEN	39	LABOUR	MECH	Labour			
RP20	434QWL	28284	06/30/2020	GEN	REPAIR COMPLETED.						
RP20	434QWL	28284	06/30/2020	TRA	1	LABOUR	Labour				0
RP20	434QWL	28284	06/30/2020	TRA	SERVICE COMPLETED.						
RP20	434QWL	28284	06/30/2020	TRA	service completed by duane + keiran 29/6/20						
RP20	434QWL	28284	06/30/2020	TRA	0	LABOUR	mech1	Labour - Internal			
RP20	434QWL	28284	06/30/2020	TRA	0	LABOUR	appren	Labour - Internal			
RP20	434QWL	28284	06/30/2020	TRA	0	LABOUR	appren	Labour - Internal			
RP20	434QWL	28284	06/30/2020	TRA	16	con		YAT	Consumables		
RP20	434QWL	28531	07/10/2020	FRIVANA	1	LABCON		BRIVAL01		EX00014663	LABOUR & CONSUMABLES,RP20
RP20	434QWL	28531	07/10/2020	FRIVANA	13	PART		BRIVAL01		EX00014663	OIL PRESSURE SWITCH,RP20

RP20	434QWL	28531	07/10/2020	FRIVANA	COMPLETED BY BVR 30.06.2020 INV: 00002638 A SERVICE CHECK COOLANT CHECK + ADJUST BELTS CHECK DEFROST DAMPER OPERATION CHECK REFRIGERANT LEVEL PERFORM COMPRESSOR EFFICIENC					
RP20	434QWL	28531	07/10/2020	FRIVANA		13	PART	BRIVAL01	2638	OIL PRESSURE SWITCH,RP20
RP20	434QWL	28531	07/10/2020	FRIVANA		1	LABCON	BRIVAL01	2638	LABOUR & CONSUMABLES,RP20

RP20	434QWL	29681	08/19/2020	TRA	COMPLETED. BY SEAN MICK 19/08/2020 REPLACED 2.5KG FIRE EXTINGUISHER REPLACED 3M OF F-TRACK RHS TOP ROW REPLACED LHS FRONT MARKER LIGHT LOWER REPLACED RHS TOP MIDDLE MARKER

RP20	434QWL	29681	08/19/2020	TRA	0	LABOUR	MECH1	Labour - Internal				
RP20	434QWL	29681	08/19/2020	TRA	0	LABOUR	MECH	1.5	85	127.5		
RP20	434QWL	29681	08/19/2020	TRA	16	CON		YAT	Consumables			
RP20	434QWL	29681	08/19/2020	TRA	14	91700BL		YAT	Clearance Light, LED Amber, Narva			
RP20	434QWL	29784	08/24/2020	FRIVANA	SERVICE COMPLETED BVR							
RP20	434QWL	29966	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00015309	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	29966	08/24/2020	FRIVANA	1	LABCON		BRIVAL01		3095	LABOUR & CONSUMABLES,RP20	

RP20	434QWL	30063	09/02/2020	DEFECT	DEFECT CLEARED BY SEAN 02/09/2020. L/H SIDE REAR AIR BAG HAS A HOLE IN IT!!!						
RP20	434QWL	30170	09/02/2020	FRIVANB		39	LABCON		BRIVAL01	EX00015431	LABOUR & CONSUMABLES,RP20
RP20	434QWL	30170	09/02/2020	FRIVANB		39	PART		BRIVAL01	EX00015431	FILTER KIT,RP20
RP20	434QWL	30170	09/02/2020	FRIVANB		39	PART		BRIVAL01	EX00015431	SB SLAM LATCH,RP20
RP20	434QWL	30170	09/02/2020	FRIVANB		39	LABCON		BRIVAL01	3199	LABOUR & CONSUMABLES,RP20
RP20	434QWL	30170	09/02/2020	FRIVANB		39	PART		BRIVAL01	3199	FILTER KIT,RP20
RP20	434QWL	30170	09/02/2020	FRIVANB		39	PART		BRIVAL01	3199	SB SLAM LATCH,RP20
RP20	434QWL	30177	09/02/2020	FVPRE		39	LABCON		BRIVAL01	EX00015436	LABOUR & CONSUMABLES,RP20
RP20	434QWL	30177	09/02/2020	FVPRE		39	ROUNDING		BRIVAL01	EX00015436	ROUNDING,ROUNDING
RP20	434QWL	30177	09/02/2020	FVPRE		39	LABCON		BRIVAL01	3200	LABOUR & CONSUMABLES,RP20
RP20	434QWL	30177	09/02/2020	FVPRE		39	ROUNDING		BRIVAL01	3200	ROUNDING,ROUNDING
RP20	434QWL	30063	09/02/2020	TRA		1	LABOUR	MECH1	Labour		
RP20	434QWL	30063	09/02/2020	TRA	SERVICE COMPLETED BY SEAN & BEN 02/09/2020. REPLACED LHS REAR AXLE AIRBAG.						
RP20	434QWL	30063	09/02/2020	TRA		0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	30063	09/02/2020	TRA		16	CON		YAT	Consumables	
RP20	434QWL	30063	09/02/2020	TRA		10	FQ7750A		YAT	Air Bag Bellow, Type 36, BPW	
RP20	434QWL	30543	09/19/2020	GEN		39	LABOUR	MECH1	Labour		

RP20	434QWL	30543	09/19/2020	GEN	REPAIR COMPLETED BY SEAN 19.09.2020 REMOVED FEMALE LIGHT PLUG. REPAIRED FRONT OF TRAILER. FITTED NEW LIGHT PLUG. FITTED FALSE EBS SOCKET.							
RP20	434QWL	30543	09/19/2020	GEN		16	CON		YAT	Consumables		
RP20	434QWL	30543	09/19/2020	GEN		14	82062		YAT	7 Pin Female Trailer Plug		
RP20	434QWL	30543	09/19/2020	GEN		14	600-3.01		YAT	FALSE EBS SOCKET		
RP20	434QWL	30998	09/30/2020	FRIVANA		1	LABCON		BRIVAL01		EX00015842	LABOUR & CONSUMABLES,RP20
RP20	434QWL	30998	09/30/2020	FRIVANA		1	LABCON		BRIVAL01		3472	LABOUR & CONSUMABLES,RP20
RP20	434QWL	31426	10/16/2020	FRIVANA		1	LABCON		BRIVAL01		EX00016093	LABOUR & CONSUMABLES,RP20
RP20	434QWL	31426	10/16/2020	FRIVANA		1	LABCON		BRIVAL01		3643	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32188	11/09/2020	EXOINS		1	LABOUR	MECH	Labour			

RP20	434QWL	32188	11/09/2020	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT #1 INSPECTION COMPLETED BY DIESEL SERVICES					
RP20	434QWL	32251	11/09/2020	GEN		39	F5002	BROHUR01	EX00016447	SHOCK ABSORBER, BPW LONG,RP20
RP20	434QWL	32279	11/09/2020	GEN		39	PART	DIESER01	EX00016484	GENERAL PART CODE,RP20
RP20	434QWL	32177	11/09/2020	GEN		0	LABOUR MECH1	Labour		
RP20	434QWL	32251	11/09/2020	GEN	SERVICE COMPLETED BY BROWN AND HURLEY					
RP20	434QWL	32279	11/09/2020	GEN		39	LAB	DIESER01	EX00016484	Labour,RP20
RP20	434QWL	32177	11/09/2020	GEN	REPAIR COMPLETED. REMOVED LHS FRONT AIRBAG AND REPLACED					
RP20	434QWL	32251	11/09/2020	GEN		39	F5002	BROHUR01	2046225	SHOCK ABSORBER, BPW LONG,RP20
RP20	434QWL	32279	11/09/2020	GEN		39	LAB	DIESER01	EX00016484	Labour,RP20
RP20	434QWL	32177	11/09/2020	GEN		16	CON	YAT	Consumables	
RP20	434QWL	32279	11/09/2020	GEN		39	CON	DIESER01	EX00016484	Consumables,RP20
RP20	434QWL	32177	11/09/2020	GEN		14	SP0022M	YAT	AIRBAG BELLOWS BPW D36 AFTERMARKET	
RP20	434QWL	32279	11/09/2020	GEN	SERVICE COMPLETED BY DIESEL SERVICES 09/11/20					

RP20	434QWL	32279	11/09/2020	GEN	39	CON		DIESER01	25838	Consumables,RP20	
RP20	434QWL	32279	11/09/2020	GEN	39	LAB		DIESER01	25838	Labour,RP20	
RP20	434QWL	32279	11/09/2020	GEN	39	LAB		DIESER01	25838	Labour,RP20	
RP20	434QWL	32279	11/09/2020	GEN	39	PART		DIESER01	25838	GENERAL PART CODE,RP20	
RP20	434QWL	32188	11/09/2020	TRA	1	LABOUR	Labour			0	
RP20	434QWL	32188	11/09/2020	TRA	SERVICE COMPLETED.						
RP20	434QWL	32188	11/09/2020	TRB	1	LABOUR	Labour			0	
RP20	434QWL	32188	11/09/2020	TRB	SERVICE COMPLETED.						
RP20	434QWL	32188	11/09/2020	TRC	1	LABOUR	MECH	Labour			
RP20	434QWL	32188	11/09/2020	TRC	SERVICE COMPLETED. C AND D SERVICE NO GREASE REPLACE BOTH REAAR AXLE SHOCKS ADJUST ALL WHEEL BEARINGS TIGHTEN SERVICE AIR FITTING ON BULK HEAD DEGREASE, WASH AND DROP BACK TO						
RP20	434QWL	32188	11/09/2020	TRC	16	CON		YAT	DEGREASER, GREASE CARTRIDGE, ZIP TIES		
RP20	434QWL	32188	11/09/2020	TRC	10	F5002		YAT	SHOCK ABSORBER, BPW LONG		

RP20	434QWL	32449	11/17/2020	FRIVANA	1	LABCON		BRIVAL01		EX00016583	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32449	11/17/2020	FRIVANA	1	LABCON		BRIVAL01		3972	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32626	11/24/2020	FRIVANA	1	LABCON		BRIVAL01		EX00016689	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32626	11/24/2020	FRIVANA	1	LABCON		BRIVAL01		4038	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32637	11/24/2020	FVGEN	35	PART		BRIVAL01		EX00016693	GENERAL PART CODE,100W 12V SOLAR PANEL
RP20	434QWL	32637	11/24/2020	FVGEN	35	LABCON		BRIVAL01		EX00016693	LABOUR & CONSUMABLES,
RP20	434QWL	32637	11/24/2020	FVGEN	35	LABCON		BRIVAL01		4045	LABOUR & CONSUMABLES,
RP20	434QWL	32637	11/24/2020	FVGEN	35	PART		BRIVAL01		4045	GENERAL PART CODE,100W 12V SOLAR PANEL
RP20	434QWL	32901	12/07/2020	FRIVANA	1	LABCON		BRIVAL01		EX00016835	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32901	12/07/2020	FRIVANA	1	LABCON		BRIVAL01		4055	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32999	12/09/2020	FRIVANA	1	LABCON		BRIVAL01		EX00016903	LABOUR & CONSUMABLES,RP20
RP20	434QWL	32999	12/09/2020	FRIVANA	1	LABCON		BRIVAL01		4191	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33130	12/15/2020	FRIVANA	1	LABCON		BRIVAL01		EX00016961	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33130	12/15/2020	FRIVANA	1	LABCON		BRIVAL01		4250	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33563	01/07/2021	TRA	0	LABOUR	APPREN	Labour			
RP20	434QWL	33563	01/07/2021	TRA	SERVICE COMPLETED BY BEN AND SEAN RE RIVETTED F-TRACK MIDWAY RHS						
RP20	434QWL	33563	01/07/2021	TRA	0	LABOUR	MECH1	Labour - Internal			
RP20	434QWL	33563	01/07/2021	TRA	16	CON		YAT	Consumables		
RP20	434QWL	33666	01/11/2021	TYRES	15	77000180		BRIAUS01		EX00017229	CASE STOCK 11-22.5,RP20
RP20	434QWL	33666	01/11/2021	TYRES	15	77000180		BRIAUS01		85203259	CASE STOCK 11-22.5,RP20
RP20	434QWL	33764	01/12/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017307	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33788	01/12/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017309	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33764	01/12/2021	FRIVANA	SERVICE COMPLETED BY BVR ON 08/01/2021.						
RP20	434QWL	33788	01/12/2021	FRIVANA	SERVICE COMPLETED BY BVR ON 07/01/2021.						
RP20	434QWL	33764	01/12/2021	FRIVANA	1	LABCON		BRIVAL01		4491	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33788	01/12/2021	FRIVANA	1	LABCON		BRIVAL01		4493	LABOUR & CONSUMABLES,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	39	91-0373		BRIVAL01		EX00017298	CLAMP TUBE FRIDGE MOTOR,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	39	CON		BRIVAL01		EX00017298	Consumables,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	39	LAB		BRIVAL01		EX00017298	Labour,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	SERVICE COMPLETED BY BVR ON 08/01/2021.						

RP20	434QWL	33744	01/12/2021	FVGEN	39	LAB		BRIVAL01	4489	Labour,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	39	CON		BRIVAL01	4489	Consumables,RP20
RP20	434QWL	33744	01/12/2021	FVGEN	39	91-0373		BRIVAL01	4489	CLAMP TUBE FRIDGE MOTOR,RP20
RP20	434QWL	34320	01/13/2021	FRIVANA	1	LABCON		BRIVAL01	EX00017546	LABOUR & CONSUMABLES,RP20
RP20	434QWL	34320	01/13/2021	FRIVANA	SERVICE COMPLETED BY BVR 11/01/2021.					
RP20	434QWL	34320	01/13/2021	FRIVANA	1	LABCON		BRIVAL01	4547	LABOUR & CONSUMABLES,RP20
RP20	434QWL	34644	02/09/2021	TYRES	15	77000180		BRIAUS01	EX00017661	CASE STOCK 11-22.5,RP20
RP20	434QWL	34644	02/09/2021	TYRES	15	77000180		BRIAUS01	85356925	CASE STOCK 11-22.5,RP20
RP20	434QWL	34563	02/09/2021	WEICAL	AIR GAUGE: 7000 ADJUSTED: 7000 WEIGHBRIDGE: 6750					
RP20	434QWL	34586	02/11/2021	TRA	0	LABOUR	MECH	Labour		
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					

RP20	434QWL	34586	02/11/2021	TRA	SERVICE COMPLETED BY MICK AND BEN REPAIRED BROKEN FIBRE GLASS AT REAR INTERIOR LIGHTS DONT WORK RHS STOP/TAIL PANEL LOOSE AT REAR						
RP20	434QWL	34586	02/11/2021	TRA	0	LABOUR	APPREN	Labour - Internal			
RP20	434QWL	34586	02/11/2021	TRA	16	CON		YAT	Consumables		
RP20	434QWL	34884	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017792	LABOUR & CONSUMABLES,RP20
RP20	434QWL	35321	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		EX00017977	LABOUR & CONSUMABLES,RP20
RP20	434QWL	34884	02/16/2021	FRIVANA	SERVICE COMPLETED BY BVR 10/02/2021						
RP20	434QWL	35321	02/16/2021	FRIVANA	SERVICE COMPLETED BY BVR 12/02/2021.						
RP20	434QWL	34884	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		4900	LABOUR & CONSUMABLES,RP20
RP20	434QWL	35321	02/16/2021	FRIVANA	1	LABCON		BRIVAL01		4925	LABOUR & CONSUMABLES,RP20
RP20	434QWL	34799	02/16/2021	FVGEN	39	CON		BRIVAL01		EX00017778	Consumables,RP20
RP20	434QWL	34811	02/16/2021	FVGEN	39	41-6538		BRIVAL01		EX00017782	COOLANT TEMP SENSOR,RP20
RP20	434QWL	34799	02/16/2021	FVGEN	39	LAB		BRIVAL01		EX00017778	Labour,RP20
RP20	434QWL	34811	02/16/2021	FVGEN	39	CON		BRIVAL01		EX00017782	Consumables,RP20
RP20	434QWL	34799	02/16/2021	FVGEN	SERVICE COMPLETED BY BVR 10/02/2021.						
RP20	434QWL	34811	02/16/2021	FVGEN	39	LAB		BRIVAL01		EX00017782	Labour,RP20
RP20	434QWL	34799	02/16/2021	FVGEN	39	LAB		BRIVAL01		4904	Labour,RP20

RP20	434QWL	34811	02/16/2021	FVGEN	SERVICE COMPLETED BY BVR 12/02/2021.					
RP20	434QWL	34799	02/16/2021	FVGEN		39	CON	BRIVAL01	4904	Consumables,RP20
RP20	434QWL	34811	02/16/2021	FVGEN		39	LAB	BRIVAL01	4929	Labour,RP20
RP20	434QWL	34811	02/16/2021	FVGEN		39	CON	BRIVAL01	4929	Consumables,RP20
RP20	434QWL	34811	02/16/2021	FVGEN		39	41-6538	BRIVAL01	4929	COOLANT TEMP SENSOR,RP20
RP20	434QWL	35889	03/17/2021	DEFECT	Reported Defect :- Defect Code : 00005900 Defect Reference : WO34586 Date : 11/02/2021 Description of Defect : INTERIOR LIGHTS DONT WORK DEFECT CLEARED BY MICK 17.03.21					

RP20	434QWL	35889	03/17/2021	DEFECT	Reported Defect :- Defect Code : 00005901 Defect Reference : WO34586 Date : 11/02/2021 Description of Defect : RHS STOP/TAIL PANEL LOOSE AT REAR DEFECT CLEARED BY MICK 17.03.21						
RP20	434QWL	35915	03/17/2021	FRIVANA		1	LABCON		BRIVAL01	EX00018196	LABOUR & CONSUMABLES,RP20
RP20	434QWL	35915	03/17/2021	FRIVANA	SERVICE COMPLETED BY BVR 15/03/2021						
RP20	434QWL	35915	03/17/2021	FRIVANA		1	LABCON		BRIVAL01	5284	LABOUR & CONSUMABLES,RP20
RP20	434QWL	35889	03/17/2021	TRA		0	LABOUR	APPREN	Labour		

RP20	434QWL	35889	03/17/2021	TRA	SERVICE COMPLETED BY BEN AND MICK RE-RIVETTED RH PANEL TO CHASIS REPLACED 2.5KG FIRE EXTINGUISHER					
RP20	434QWL	35889	03/17/2021	TRA	0	LABOUR	MECH	Labour - Internal		
RP20	434QWL	35889	03/17/2021	TRA	16	CON		YAT	Consumables	
RP20	434QWL	36183	03/18/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018300	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36183	03/18/2021	FRIVANA	SERVICE COMPLETED BY BVR 16/03/2021					
RP20	434QWL	36183	03/18/2021	FRIVANA	1	LABCON		BRIVAL01	5328	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36219	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018302	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36233	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018303	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36558	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018452	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36972	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018588	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36219	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 18/03/2021					
RP20	434QWL	36233	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 19/03/2021					
RP20	434QWL	36558	03/22/2021	FRIVANA	SERVICE COMPLETED BY BVR 18/03/2021					
RP20	434QWL	36233	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	5376	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36558	03/22/2021	FRIVANA	1	LABCON		BRIVAL01	5351	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36338	03/29/2021	FRIVANA	1	LABCON		BRIVAL01	EX00018317	LABOUR & CONSUMABLES,RP20
RP20	434QWL	36338	03/29/2021	FRIVANA	SERVICE COMPLETED BY BVR 25/03/2021.					
RP20	434QWL	36338	03/29/2021	FRIVANA	1	LABCON		BRIVAL01	5432	LABOUR & CONSUMABLES,RP20
RP20	434QWL	37242	04/28/2021	GEN	39	LAB		RCCLOW01	EX00018749	Labour,434QWL
RP20	434QWL	37242	04/28/2021	GEN	39	PART		RCCLOW01	EX00018749	GENERAL PART CODE,RP20
RP20	434QWL	37242	04/28/2021	GEN	39	PART		RCCLOW01	26852	GENERAL PART CODE,RP20
RP20	434QWL	37242	04/28/2021	GEN	39	LAB		RCCLOW01	26852	Labour,434QWL
RP20	434QWL	37593	05/14/2021	TRA	0	LABOUR	APPREN	Labour		
RP20	434QWL	37593	05/14/2021	TRA	SERVICE COMPLETED BY KEIRAN AND SEAN					
RP20	434QWL	37593	05/14/2021	TRA	0	LABOUR	MECH1	Labour - Internal		
RP20	434QWL	37593	05/14/2021	TRA	16	CON		YAT	Consumables	

RP20	434QWL	38352	05/18/2021	WEICAL	AIR GAUGE: 21000 ADJUSTED: 21250 WEIGHBRIDGE: 20980 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	37744	05/19/2021	FRIVANA	1	LABCON		BRIVAL01		EX00019011	LABOUR & CONSUMABLES,RP20
RP20	434QWL	37744	05/19/2021	FRIVANA	SERVICE COMPLETED BY BVR 12/05/2021						
RP20	434QWL	37744	05/19/2021	FRIVANA	1	LABCON		BRIVAL01		5965	LABOUR & CONSUMABLES,RP20
RP20	434QWL	37892	05/21/2021	FRIVANA	1	LABCON		BRIVAL01		EX00019077	LABOUR & CONSUMABLES,RP20
RP20	434QWL	37892	05/21/2021	FRIVANA	SERVICE COMPLETED BY BVR 18/05/2021						
RP20	434QWL	37892	05/21/2021	FRIVANA	1	LABCON		BRIVAL01		5998	LABOUR & CONSUMABLES,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	39	R404A		BRIVAL01		EX00019073	GAS R404A,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	39	CON		BRIVAL01		EX00019073	Consumables,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	39	LAB		BRIVAL01		EX00019073	Labour,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	SERVICE COMPLETED BY BVR 18/05/2021						
RP20	434QWL	37863	05/21/2021	FVGEN	39	LAB		BRIVAL01		6007	Labour,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	39	CON		BRIVAL01		6007	Consumables,RP20
RP20	434QWL	37863	05/21/2021	FVGEN	39	R404A		BRIVAL01		6007	GAS R404A,RP20
RP20	434QWL	38337	06/09/2021	TRA	1	LABOUR	Labour				0
RP20	434QWL	38337	06/09/2021	TRA	SERVICE COMPLETED.						
RP20	434QWL	38337	06/09/2021	TRB	0	LABOUR	MECH1	Labour			
RP20	434QWL	38337	06/09/2021	TRB	SERVICE COMPLETED BY SEAN						
RP20	434QWL	38337	06/09/2021	TRB	16	CON		YAT	Consumables		
RP20	434QWL	38427	06/10/2021	FRIVANA	1	LABCON		BRIVAL01		EX00019287	LABOUR & CONSUMABLES,RP20
RP20	434QWL	38427	06/10/2021	FRIVANA	SERVICE COMPLETED BY BVR 08/06/2021						
RP20	434QWL	38427	06/10/2021	FRIVANA	1	LABCON		BRIVAL01		6263	LABOUR & CONSUMABLES,RP20

RP20	434QWL	38414	06/10/2021	FRIVANB	39	10-417	BRIVAL01	EX00019286	FILTER KIT (FRIDGE MOTOR),RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	45-2256	BRIVAL01	EX00019286	ALTERNATOR 65 AMP,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	CON	BRIVAL01	EX00019286	Consumables,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	LAB	BRIVAL01	EX00019286	Labour,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	SERVICE COMPLETED BY BVR 08/06/2021				
RP20	434QWL	38414	06/10/2021	FRIVANB	39	LAB	BRIVAL01	6241	Labour,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	CON	BRIVAL01	6241	Consumables,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	45-2256	BRIVAL01	6241	ALTERNATOR 65 AMP,RP20
RP20	434QWL	38414	06/10/2021	FRIVANB	39	10-417	BRIVAL01	6241	FILTER KIT (FRIDGE MOTOR),RP20
RP20	434QWL	38761	06/17/2021	FRIVANA	1	LABCON	BRIVAL01	EX00019392	LABOUR & CONSUMABLES,RP20
RP20	434QWL	38761	06/17/2021	FRIVANA	SERVICE COMPLETDED BY BVR 16/06/2021				
RP20	434QWL	38761	06/17/2021	FRIVANA	1	LABCON	BRIVAL01	6347	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39103	06/24/2021	FRIVANA	1	LABCON	BRIVAL01	EX00019579	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39103	06/24/2021	FRIVANA	SERVICE COMPLETED BY BVR 21.06.2021				
RP20	434QWL	39103	06/24/2021	FRIVANA	1	LABCON	BRIVAL01	6409	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39138	06/28/2021	FRIVANA	1	LABCON	BRIVAL01	EX00019580	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39138	06/28/2021	FRIVANA	SERVICE COMPLETED BY BVR 23.06.2021				
RP20	434QWL	39138	06/28/2021	FRIVANA	1	LABCON	BRIVAL01	6429	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39745	07/13/2021	FRIVANA	1	LABCON	BRIVAL01	EX00019829	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39745	07/13/2021	FRIVANA	SERVICE COMPLETED BVR 08/07/2021				
RP20	434QWL	39745	07/13/2021	FRIVANA	SERVICE COMPLETED BVR 08/07/2021				
RP20	434QWL	39745	07/13/2021	FRIVANA	1	LABCON	BRIVAL01	6608	LABOUR & CONSUMABLES,RP20
RP20	434QWL	39881	07/13/2021	WEICAL	AIR GAUGE: 18,250 ADJUSTED: 18,500 WEIGHBRIDGE: 18,060				
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				

					AIR GAUGE: 16500 ADJUSTED: 16500 WEIGHBRIDGE: 16170						
RP20	434QWL	39933	07/21/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	40084	07/27/2021	GEN		39	LABOUR	Labour			0
					REPAIR COMPLETED.						
RP20	434QWL	40084	07/27/2021	GEN	TRACKER FITTED - 865284045593179						
RP20	434QWL	40083	07/27/2021	TRA		0	LABOUR	MECH1	Labour		

RP20	434QWL	40083	07/27/2021	TRA	SERVICE COMPLETED BY SEAN AND KEIRAN R&R SWITCH AT FRONT OF TRAILER FOR INTERIOR LIGHTS REPAIRED 2M OF F-TRACK FITTED SOLAR TRACKER

RP20	434QWL	40083	07/27/2021	TRA	0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	40083	07/27/2021	TRA	16	CON		YAT	Consumables	
RP20	434QWL	40482	07/30/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020058	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40482	07/30/2021	FRIVANA	SERVICE COMPLETED BY BVR 27/07/2021					
RP20	434QWL	40482	07/30/2021	FRIVANA	1	LABCON		BRIVAL01	6883	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40629	08/02/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020153	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40629	08/02/2021	FRIVANA	SERVICE COMPLETED BY BVR 02/08/2021					
RP20	434QWL	40629	08/02/2021	FRIVANA	1	LABCON		BRIVAL01	6962	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40582	08/03/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020146	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40582	08/03/2021	FRIVANA	SERVICE COMPLETED BY BVR 03/08/2021					
RP20	434QWL	40582	08/03/2021	FRIVANA	1	LABCON		BRIVAL01	6961	LABOUR & CONSUMABLES,RP20
RP20	434QWL	41646	08/04/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020474	LABOUR & CONSUMABLES,RP20
RP20	434QWL	41646	08/04/2021	FRIVANA	SERVICE COMPLTED BY BVR 04/08/2021					
RP20	434QWL	41646	08/04/2021	FRIVANA	1	LABCON		BRIVAL01	6988	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40667	08/05/2021	FRIVANA	1	LABCON		BRIVAL01	EX00020157	LABOUR & CONSUMABLES,RP20
RP20	434QWL	40667	08/05/2021	FRIVANA	SERVICE COMPLETED BY BVR 05/08/2021					
RP20	434QWL	40667	08/05/2021	FRIVANA	1	LABCON		BRIVAL01	6987	LABOUR & CONSUMABLES,RP20

					AIR GAUGE: 20 500 ADJUSTED : 20 600 WEIGHBRIDGE: 20 350							
RP20	434QWL	40807	08/12/2021	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.							
RP20	434QWL	40899	08/17/2021	GEN		0	LABOUR	APPREN	Labour			
					REPAIR COMPLETED BY KEIRAN REPLACED LH REAR INDICATOR LH REAR INDICATOR WILL NEED CORRECT LIGHT							
RP20	434QWL	40899	08/17/2021	GEN	FITTED							
RP20	434QWL	40899	08/17/2021	GEN		16	CON		YAT	Consumables		
RP20	434QWL	42153	09/13/2021	FRIVANA		1	LABCON		BRIVAL01		EX00020647	LABOUR & CONSUMABLES,RP20

RP20	434QWL	42153	09/13/2021	FRIVANA	SERVICE COMPLETED BY BVR 13/09/2021					
RP20	434QWL	42153	09/13/2021	FRIVANA	1	LABCON		BRIVAL01	7499	LABOUR & CONSUMABLES,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	910372		BRIVAL01	EX00020703	CLAMP TUBE - FRIDGE MOTOR,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	91-0373		BRIVAL01	EX00020703	CLAMP TUBE FRIDGE MOTOR,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	CON		BRIVAL01	EX00020703	Consumables,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	LAB		BRIVAL01	EX00020703	Labour,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	SERVICE COMPLETED BY BVR 23/09/2021					
RP20	434QWL	42360	09/23/2021	FVGEN	39	LAB		BRIVAL01	7698	Labour,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	CON		BRIVAL01	7698	Consumables,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	91-0373		BRIVAL01	7698	CLAMP TUBE FRIDGE MOTOR,RP20
RP20	434QWL	42360	09/23/2021	FVGEN	39	910372		BRIVAL01	7698	CLAMP TUBE - FRIDGE MOTOR,RP20
RP20	434QWL	42768	10/12/2021	DEFECT	1	LABOUR	MECH	Labour		
RP20	434QWL	42768	10/12/2021	DEFECT						
RP20	434QWL	42768	10/12/2021	DEFECT	DEFECT CLEARED.					
RP20	434QWL	42768	10/12/2021	DEFECT	Reported Defect :- Defect Code : 00006838 Defect Reference : WO40899 Date : 17/08/2021 Description of Defect : LH REAR INDICATOR WILL NEED CORRECT LIGHT FITTED					

RP20	434QWL	42768	10/12/2021	TRA	0	LABOUR	MECH1	Labour					
RP20	434QWL	42768	10/12/2021	TRA	COMPLETED BY SEAN AND BEN. RNR RHS SIDE MARKER LIGHT RNR FIRE EXTINGUISHER RNR LHS REAR INDICATOR FITTED BOLT TO RHS MIDDLE AIR BAG. MONITOR MOVEMENT FRONT RHS PIVOT BUSH.								
RP20	434QWL	42768	10/12/2021	TRA	0	LABOUR	APPREN	1.5	85	127.5			
RP20	434QWL	42768	10/12/2021	TRA	16	CON		YAT	Consumables				
RP20	434QWL	42768	10/12/2021	TRA	16	94800		YAT	Indicator Light LED				
RP20	434QWL	42768	10/12/2021	TRA	16	91700BL		YAT	Clearance Light, LED Amber, Narva				
RP20	434QWL	43174	10/22/2021	FRIVANA	1	LABCON		BRIVAL01			EX00021055	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	43174	10/22/2021	FRIVANA	SERVICE COMPLTED BY BVR 22/10/2021								
RP20	434QWL	43174	10/22/2021	FRIVANA	1	LABCON		BRIVAL01			8035	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	43499	11/01/2021	FRIVANA	1	LABCON		BRIVAL01			EX00021213	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	43499	11/01/2021	FRIVANA	SERVICE COMPLETED BY BVR 01/11/2021								
RP20	434QWL	43499	11/01/2021	FRIVANA	1	LABCON		BRIVAL01			8107	LABOUR & CONSUMABLES,RP20	
RP20	434QWL	43429	11/02/2021	FRIVANA	1	LABCON		BRIVAL01			EX00021177	LABOUR & CONSUMABLES,RP20	

RP20	434QWL	43429	11/02/2021	FRIVANA	SERVICE COMPLTED BY BVR 02/11/2021					
RP20	434QWL	43429	11/02/2021	FRIVANA	1	LABCON		BRIVAL01	8124	LABOUR & CONSUMABLES,RP20
RP20	434QWL	43375	11/02/2021	tyres	15	77000180		BRIAUS01	EX00021133	CASE STOCK 11-22.5,RP20
RP20	434QWL	43375	11/02/2021	tyres	15	77000180		BRIAUS01	86734546	CASE STOCK 11-22.5,RP20
RP20	434QWL	43987	12/03/2021	DEFECT	Reported Defect :- Defect Code : 00007036 Defect Reference : WO42768 Date : 12/10/2021 Description of Defect : SEVERAL RIVETS MISSING FROM BOTH TOP CORNERS INSIDE					
RP20	434QWL	43987	12/03/2021	EXOINS	0	LABOUR	APPREN	Labour		

RP20	434QWL	43987	12/03/2021	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY KEIRAN					
RP20	434QWL	43987	12/03/2021	TRA		1	LABOUR	Labour		0
RP20	434QWL	43987	12/03/2021	TRA	SERVICE COMPLETED.					
RP20	434QWL	43987	12/03/2021	TRB		1	LABOUR	Labour		0
RP20	434QWL	43987	12/03/2021	TRB	SERVICE COMPLETED.					
RP20	434QWL	43987	12/03/2021	TRC		0	LABOUR	APPREN	Labour	

RP20	434QWL	43987	12/03/2021	TRC	COMPLETED BY KEIRAN AND IAN REPLACED BOTTOM HINGE ON LH DOOR AND MADE NEW PIN FOR IT REPLACED FEMALE LIGHT PLUG AS PER DEFECT, CHECKED INTERIOR OF TRAILER, ONLY A HAND FUL OF RIVETS MISSING,							
RP20	434QWL	43987	12/03/2021	TRC	0	LABOUR	MECH1	Labour - Internal				
RP20	434QWL	43987	12/03/2021	TRC	16	CON		YAT	Consumables			
RP20	434QWL	43987	12/03/2021	TRC	11	50339		YAT	Hinge, Trailer door (Maxicube)			
RP20	434QWL	44596	01/11/2022	TRA	1	LABOUR	Labour					0
RP20	434QWL	44596	01/11/2022	TRA	SERVICE COMPLETED BEN							
RP20	434QWL	44596	01/11/2022	TRA	0	LABOUR	APPREN	Labour - Internal				
RP20	434QWL	44596	01/11/2022	TRA	16	CON		YAT	Consumables			
RP20	434QWL	44689	01/13/2022	TYRES	15	77000180		BRIAUS01		EX00022021	CASE STOCK 11-22.5,RP20	
RP20	434QWL	44689	01/13/2022	TYRES	15	77000180		BRIAUS01		87098993	CASE STOCK 11-22.5,RP20	
RP20	434QWL	44775	01/19/2022	GEN	39	R404A		BRIVAL01		EX00022068	GAS R404A,RP20	
RP20	434QWL	44775	01/19/2022	GEN	39	33-0230		BRIVAL01		EX00022068	SUCTION SERVICE VALVE ORING,RP20	
RP20	434QWL	44775	01/19/2022	GEN	39	CON		BRIVAL01		EX00022068	Consumables,RP20	

RP20	434QWL	44775	01/19/2022	GEN	39	LAB		BRIVAL01	EX00022068	Labour,RP20
RP20	434QWL	44775	01/19/2022	GEN	39	LAB		BRIVAL01	8977	Labour,RP20
RP20	434QWL	44775	01/19/2022	GEN	39	CON		BRIVAL01	8977	Consumables,RP20
RP20	434QWL	44775	01/19/2022	GEN	39	33-0230		BRIVAL01	8977	SUCTION SERVICE VALVE ORING,RP20
RP20	434QWL	44775	01/19/2022	GEN	39	R404A		BRIVAL01	8977	GAS R404A,RP20
RP20	434QWL	45159	02/08/2022	TRA	0	LABOUR	apprenk	Labour		
RP20	434QWL	45159	02/08/2022	TRA	SERVICE COMPLETED BY KIERAN AND MICK					
RP20	434QWL	45159	02/08/2022	TRA	0	LABOUR	MECH	Labour - Internal		
RP20	434QWL	45159	02/08/2022	TRA	16	CON		YAT	Consumables	
RP20	434QWL	45770	02/25/2022	TRA	0	LABOUR	APPREN	Labour		
RP20	434QWL	45770	02/25/2022	TRA	SERVICE COMPLETED BY BEN, BRENDAN AND TYLER					
RP20	434QWL	45770	02/25/2022	TRA	0	LABOUR	SUBMEC	Labour - Internal		
RP20	434QWL	45770	02/25/2022	TRA	0	LABOUR	TRADEA	Labour - Internal		
RP20	434QWL	45770	02/25/2022	TRA	16	CON		YAT	Consumables	
RP20	434QWL	46806	04/12/2022	TRA	0	LABOUR	MECH1	Labour		
RP20	434QWL	46806	04/12/2022	TRA	SERVICE COMPLETED BY IAN AND BEN NO EBS FITTED REPLACED FRIDGE BATTERY - SECOND HAND					
RP20	434QWL	46806	04/12/2022	TRA	0	LABOUR	APPRENB	Labour - Internal		
RP20	434QWL	46806	04/12/2022	TRA	16	CON		YAT	Consumables	

RP20	434QWL	46989	04/13/2022	WEICAL	AIR GAUGE: 9.5 ADJUSTED: 11.25 WEIGHBRIDGE: 11.32						
RP20	434QWL	46989	04/13/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	47215	04/27/2022	GEN		39	100417	BRIVAL01	EX00023454	Filter Service Kit, Fridge Motor, SLX-400,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	41-7063	BRIVAL01	EX00023454	SWITCH PRESS OIL,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	CON	BRIVAL01	EX00023454	Consumables,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	LAB	BRIVAL01	EX00023454	Labour,RP20	
RP20	434QWL	47215	04/27/2022	GEN	SERVICE COMPLETED BY BVR 27.04.2022						
RP20	434QWL	47215	04/27/2022	GEN		39	LAB	BRIVAL01	10401	Labour,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	CON	BRIVAL01	10401	Consumables,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	41-7063	BRIVAL01	10401	SWITCH PRESS OIL,RP20	
RP20	434QWL	47215	04/27/2022	GEN		39	100417	BRIVAL01	10401	Filter Service Kit, Fridge Motor, SLX-400,RP20	
RP20	434QWL	47722	05/18/2022	TYRES		15	11004117	BRIAUS01	EX00023655	11R22.5 148/145L FS FT469,RP20	
RP20	434QWL	47722	05/18/2022	TYRES		15	77000180	BRIAUS01	EX00023655	CASE STOCK 11-22.5,RP20	
RP20	434QWL	47722	05/18/2022	TYRES		15	77000180	BRIAUS01	87748126	CASE STOCK 11-22.5,RP20	
RP20	434QWL	47722	05/18/2022	TYRES		15	11004117	BRIAUS01	87748126	11R22.5 148/145L FS FT469,RP20	
RP20	434QWL	48465	06/21/2022	TRA		1	LABOUR	Labour			0
RP20	434QWL	48465	06/21/2022	TRA	SERVICE COMPLETED.						
RP20	434QWL	48465	06/21/2022	TRB		1	LABOUR	Labour			0
RP20	434QWL	48465	06/21/2022	TRB	SERVICE COMPLETED BRENDAN AND BEN						

RP20	434QWL	48465	06/21/2022	TRB	0	LABOUR	SUBMEC	Labour - Internal			
RP20	434QWL	48465	06/21/2022	TRB	0	LABOUR	APPRENB	Labour - Internal			
RP20	434QWL	48465	06/21/2022	TRB	16	CON		YAT	Consumables		
RP20	434QWL	48495	06/23/2022	GEN	39	CON		BRIVAL01		EX00024131	Consumables,RP20
RP20	434QWL	48495	06/23/2022	GEN	39	LAB		BRIVAL01		EX00024131	Labour,RP20
RP20	434QWL	48495	06/23/2022	GEN	COMPLETED BY BVR 23.06.2022 TRAVEL TO SITE AND INSPECT UNIT UNIT WOULD NOT START DUE TO BOX LIGHT LEFT ON REMOVE AND REPLACE U/S BATTERY (BATTERY SUPPLIED BY CUSTOME						
RP20	434QWL	48495	06/23/2022	GEN	39	LAB		BRIVAL01		11284	Labour,RP20
RP20	434QWL	48495	06/23/2022	GEN	39	CON		BRIVAL01		11284	Consumables,RP20
RP20	434QWL	49361	07/25/2022	TRA	0	LABOUR	APPRENK	Labour			
RP20	434QWL	49361	07/25/2022	TRA	SERVICE COMPLETED BY KEIRAN AND BEN						

RP20	434QWL	49361	07/25/2022	TRA	0	LABOUR	APPRENB	Labour - Internal			
RP20	434QWL	49361	07/25/2022	TRA	16	CON		YAT	Consumables		
				AIR GAUGE: 16.250 ADJUSTED: 16.750 WEIGHBRIDGE: 16.460							
RP20	434QWL	49515	07/26/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	49599	07/27/2022	GEN	39	CON		BRIVAL01		EX00024629	Consumables,RP20
RP20	434QWL	49599	07/27/2022	GEN	39	LAB		BRIVAL01		EX00024629	Labour,RP20
RP20	434QWL	49599	07/27/2022	GEN	39	LAB		BRIVAL01		9095	Labour,RP20
RP20	434QWL	49599	07/27/2022	GEN	39	CON		BRIVAL01		9095	Consumables,RP20

					AIR GAUGE: 19.9 ADJUSTED: 20.4 WEIGHBRIDGE:20.7
RP20	434QWL	50086	08/21/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.
					AIR GAUGE: 21.00 ADJUSTED: 21.00 WEIGHBRIDGE: 20.68
RP20	434QWL	50179	08/21/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.

					AIR GAUGE: 19750 ADJUSTED : 19750 WEIGHBRIDGE: 19380							
RP20	434QWL	50627	09/05/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.							
RP20	434QWL	50457	09/07/2022	TRA	1	LABOUR	Labour					0
RP20	434QWL	50457	09/07/2022	TRA	SERVICE COMPLETED BENNY							
RP20	434QWL	50457	09/07/2022	TRA	0	LABOUR	APPRENB	Labour - Internal				
RP20	434QWL	50457	09/07/2022	TRA	16	CON		YAT	Consumables			
RP20	434QWL	50858	09/16/2022	GEN	39	LAB		ALLTIM01		EX00025279	Labour,434QWL	
RP20	434QWL	50858	09/16/2022	GEN	39	2.51E+08		ALLTIM01		EX00025279	BOLT - AIRBAG M16 X 65,RP20	
RP20	434QWL	50858	09/16/2022	GEN	39	PART		ALLTIM01		EX00025279	GENERAL PART CODE,RP20	
RP20	434QWL	50858	09/16/2022	GEN	39	PART		ALLTIM01		9594	GENERAL PART CODE,RP20	
RP20	434QWL	50858	09/16/2022	GEN	39	2.51E+08		ALLTIM01		9594	BOLT - AIRBAG M16 X 65,RP20	
RP20	434QWL	50858	09/16/2022	GEN	39	LAB		ALLTIM01		9594	Labour,434QWL	

					AIR GAUGE: 20000 ADJUSTED: 20500 WEIGHBRIDGE: 20180				
RP20	434QWL	50764	09/21/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
					AIR GAUGE: 20000 ADJUSTED: 21000 WEIGHBRIDGE: 20600				
RP20	434QWL	50963	09/29/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.				
RP20	434QWL	51118	10/06/2022	GEN		39 LAB	BROHUR01	EX00025398	Labour,434QWL
RP20	434QWL	51118	10/06/2022	GEN		39 PART	BROHUR01	EX00025398	GENERAL PART CODE,RP20

RP20	434QWL	51118	10/06/2022	GEN	39	CON	BROHUR01	EX00025398	Consumables,RP20
RP20	434QWL	51118	10/06/2022	GEN	39	ENVLEV	BROHUR01	EX00025398	ENVIRONMENTAL LEVY,RP20
RP20	434QWL	51118	10/06/2022	GEN	39	COMPLETED BY BROWN & HURLEY INV# 2648653 TESTED POWER AT THE PLUG AT THE REAR OF THE TRAILER, IT WAS GOOD HERE. REMOVED THE LIGHT FROM THE HOUSING AND TESTED POWER, THERE IS GOOD			
RP20	434QWL	51118	10/06/2022	GEN	39	LAB	BROHUR01	2648653	Labour,434QWL
RP20	434QWL	51118	10/06/2022	GEN	39	PART	BROHUR01	2648653	GENERAL PART CODE,RP20
RP20	434QWL	51118	10/06/2022	GEN	39	CON	BROHUR01	2648653	Consumables,RP20
RP20	434QWL	51118	10/06/2022	GEN	39	ENVLEV	BROHUR01	2648653	ENVIRONMENTAL LEVY,RP20
RP20	434QWL	51323	10/12/2022	FVGEN	39	PART	BRIVAL01	EX00025506	99-6565,RP20

RP20	434QWL	51323	10/12/2022	FVGEN		39	449181		BRIVAL01	EX00025506	Solenoid, QTK Fridge, SB310 plus,RP20
RP20	434QWL	51323	10/12/2022	FVGEN		39	CON		BRIVAL01	EX00025506	Consumables,RP20
RP20	434QWL	51323	10/12/2022	FVGEN		39	LAB		BRIVAL01	EX00025506	Labour,RP20
RP20	434QWL	51323	10/12/2022	FVGEN	COMPLETED BY BVR 12.10.2022 TRAVEL TO SITE AND INSPECT UNIT - FOUND DAMPER FLAP STUCK OPEN - SHAFT WAS RUSTED IN BUSHES- - REPLACE BUSHES - REMOVE AND REPLACE ENGINE SPEED						
RP20	434QWL	51323	10/12/2022	FVGEN		39	LAB		BRIVAL01	12561	Labour,RP20
RP20	434QWL	51323	10/12/2022	FVGEN		39	CON		BRIVAL01	12561	Consumables,RP20
RP20	434QWL	51323	10/12/2022	FVGEN		39	449181		BRIVAL01	12561	Solenoid, QTK Fridge, SB310 plus,RP20
RP20	434QWL	51323	10/12/2022	FVGEN		39	PART		BRIVAL01	12561	99-6565,RP20
RP20	434QWL	51864	11/04/2022	TRA		0	LABOUR	APPREN	Labour		

					SERVICE COMPLETED BY TYLER AND FLYNN					
RP20	434QWL	51864	11/04/2022	TRA	REPAIR LEFT HAND BRAKE LIGHT					
RP20	434QWL	51864	11/04/2022	TRA		0	LABOUR	APPRENF	Labour - Internal	
RP20	434QWL	51864	11/04/2022	TRA		16	CON		YAT	Consumables
					AIR GAUGE: 16.00 ADJUSTED: 16.500 WEIGHBRIDGE: 16.000					
RP20	434QWL	51978	11/05/2022	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	51899	11/07/2022	TYRES		15	77000180		BRIAUS01	EX00025811	CASE STOCK 11-22.5,RP20
RP20	434QWL	51899	11/07/2022	TYRES		15	77000180		BRIAUS01	88652840	CASE STOCK 11-22.5,RP20
RP20	434QWL	52926	12/15/2022	FVGEN		39	CON		BRIVAL01	EX00026441	Consumables,RP20
RP20	434QWL	52926	12/15/2022	FVGEN		39	LAB		BRIVAL01	EX00026441	Labour,RP20

					SERVICE COMPLETED BY BVR - 15.12.2022					
RP20	434QWL	52926	12/15/2022	FVGEN	diagnosed defrost flap not working - remove a spring from the defrost flap and adjust defrost solenoid - test operation ok					
RP20	434QWL	52926	12/15/2022	FVGEN		39	CON	BRIVAL01	13639	Consumables,RP20
RP20	434QWL	52926	12/15/2022	FVGEN		39	LAB	BRIVAL01	13639	Labour,RP20

RP20	434QWL	52963	12/23/2022	DEFECT	Reported Defect :- Defect Code : 00007841 Defect Reference : 7388 Date : 14/07/2022 Description of Defect : RH SIDE RED MUD GAURD - DAMAGE TORN					
RP20	434QWL	52963	12/23/2022	TRA		1	LABOUR	MECH	Labour	
RP20	434QWL	52963	12/23/2022	TRA	SERVICE COMPLETED BENNY AND FLYNN - REPLACED RHS FRONT BOTTOM MARKER LIGHT					
RP20	434QWL	52963	12/23/2022	TRA		14	91700BL		YAT	Clearance Light, LED Amber, Narva
RP20	434QWL	52963	12/23/2022	TRA		0	LABOUR	APPRENB	Labour - Internal	
RP20	434QWL	52963	12/23/2022	TRA		0	LABOUR	APPRENF	Labour - Internal	
RP20	434QWL	52963	12/23/2022	TRA		16	CON		YAT	Consumables

					AIR GAUGE: 20750 ADJUSTED :20500 WEIGHBRIDGE:20100						
RP20	434QWL	53525	01/11/2023	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	53389	01/17/2023	TRA		1	LABOUR	APPREN	Labour		
RP20	434QWL	53389	01/17/2023	TRA	SERVICE COMPLETED. FRIDGE IS OUT OF SERVIE, GETTING SORTED BY BVR						
RP20	434QWL	53389	01/17/2023	TRA		16	CON		YAT	Consumables	
RP20	434QWL	53465	01/18/2023	FVGEN		39	CON		BRIVAL01	EX00026743	Consumables,RP20
RP20	434QWL	53465	01/18/2023	FVGEN		39	R404A		BRIVAL01	EX00026743	GAS R404A,RP20
RP20	434QWL	53465	01/18/2023	FVGEN		39	LAB		BRIVAL01	EX00026743	Labour,RP20

RP20	434QWL	53465	01/18/2023	FVGEN						complete d by BVR 13/01/20 23 - Travel to site and attempt to download unit - unable to download unit. CALL OUT- Travel to site and inspect unit - fully loaded with freezer - found condenser leaking and possible shaft seal leaking -
RP20	434QWL	53465	01/18/2023	FVGEN	39	CON	BRIVAL01	14018		Consuma bles ,RP20
RP20	434QWL	53465	01/18/2023	FVGEN	39	R404A	BRIVAL01	14018		GAS R404A,RP20
RP20	434QWL	53465	01/18/2023	FVGEN	39	LAB	BRIVAL01	14018		Labour,RP20
RP20	434QWL	53741	01/18/2023	GEN	39	2.57E+08	DIESER01	EX00026912		O-RING - EXODAS STOCK,
RP20	434QWL	53741	01/18/2023	GEN	39	0980107040TSSC	DIESER01	EX00026912		KIT W/BRG & SEAL 10T ECO (EXODAS STOCK),
RP20	434QWL	53741	01/18/2023	GEN	39	82161BL	DIESER01	EX00026912		7 PIN PLUG TRAILER - EXODAS STOCK,
RP20	434QWL	53741	01/18/2023	GEN	39	CRC-5073	DIESER01	EX00026912		DEGREASER CAN,
RP20	434QWL	53741	01/18/2023	GEN	39	0210404900-20	DIESER01	EX00026912		GREASE EXODAS STOCK,
RP20	434QWL	53741	01/18/2023	GEN	39	LABEXT	DIESER01	EX00026912		Labour External EXODAS C&D SERVICE,
RP20	434QWL	53741	01/18/2023	GEN	39	LABEXT	DIESER01	EX00026912		Labour External - GENERAL REPAIR,
RP20	434QWL	53741	01/18/2023	GEN	39	PART	DIESER01	EX00026912		GENERAL PART CODE - MATERIALS,

RP20	434QWL	53741	01/18/2023	GEN	39	PART		DIESER01	28199	GENERAL PART CODE - MATERIALS,
RP20	434QWL	53741	01/18/2023	GEN	39	LABEXT		DIESER01	28199	Labour External - GENERAL REPAIR,
RP20	434QWL	53741	01/18/2023	GEN	39	LABEXT		DIESER01	28199	Labour External EXODAS C&D SERVICE,
RP20	434QWL	53741	01/18/2023	GEN	39	0210404900-20		DIESER01	28199	GREASE EXODAS STOCK,
RP20	434QWL	53741	01/18/2023	GEN	39	CRC-5073		DIESER01	28199	DEGREASER CAN,
RP20	434QWL	53741	01/18/2023	GEN	39	82161BL		DIESER01	28199	7 PIN PLUG TRAILER - EXODAS STOCK,
RP20	434QWL	53741	01/18/2023	GEN	39	0980107040TSSC		DIESER01	28199	KIT W/BRG & SEAL 10T ECO (EXODAS STOCK),
RP20	434QWL	53741	01/18/2023	GEN	39	2.57E+08		DIESER01	28199	O-RING - EXODAS STOCK,
RP20	434QWL	53491	01/19/2023	EXOINS	1	LABOUR	MECH	Labour		
RP20	434QWL	53491	01/19/2023	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES					
RP20	434QWL	53492	01/19/2023	TRA	1	LABOUR	MECH	Labour		
RP20	434QWL	53492	01/19/2023	TRA	SERVICE COMPLETED.					
RP20	434QWL	53492	01/19/2023	TRB	1	LABOUR	MECH	Labour		
RP20	434QWL	53492	01/19/2023	TRB	SERVICE COMPLETED.					
RP20	434QWL	53492	01/19/2023	TRC	1	LABOUR	MECH	Labour		

RP20	434QWL	53492	01/19/2023	TRC	COMPLETED. BY DIESEL SERVICES COMPLETE C SERVICE REPLACE PACK AND SET ALL BEARINGS ADJUST BRAKES CHECK SUSPENSION POINTS REPLACE TRAILER PLUG REPLACE HUBCAP ORING TENSION HUBCAP DEGREASE					
RP20	434QWL	53798	01/31/2023	FVGEN		39	22-1101	BRIVAL01	EX00026935	SEALED COMPRESSOR, LGE SHAFT, A/C,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	R404A	BRIVAL01	EX00026935	GAS R404A,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	CON	BRIVAL01	EX00026935	Consumables ,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	LAB	BRIVAL01	EX00026935	Labour,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	Drive Plate	BRIVAL01	EX00026935	Drive Plate,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	67-2766	BRIVAL01	EX00026935	Con/Rad Oil Assembly,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	FLY WHEEL	BRIVAL01	EX00026935	Fly Wheel,RP20
RP20	434QWL	53798	01/31/2023	FVGEN		39	77-2856	BRIVAL01	EX00026935	Bush Drive Coupling,RP20

RP20	434QWL	53798	01/31/2023	FVGEN	39	Anti-Freeze Coolant		BRIVAL01	EX00026935	Anti-Freeze Coolant,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	Service Completed by BVR 17/01/2023 - Travel to site and inspect unit - Remove gas and drain coolant - Rermove all panels - Remove and replace leaking conde					
RP20	434QWL	53798	01/31/2023	FVGEN	39	22-1101		BRIVAL01	14087	SEALED COMPRESSOR, LGE SHAFT, A/C,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	R404A		BRIVAL01	14087	GAS R404A,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	CON		BRIVAL01	14087	Consumables,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	LAB		BRIVAL01	14087	Labour,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	Drive Plate		BRIVAL01	14087	Drive Plate,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	67-2766		BRIVAL01	14087	Con/Rad Oil Assembly,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	FLY WHEEL		BRIVAL01	14087	Fly Wheel,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	77-2856		BRIVAL01	14087	Bush Drive Coupling,RP20
RP20	434QWL	53798	01/31/2023	FVGEN	39	Anti-Freeze Coolant		BRIVAL01	14087	Anti-Freeze Coolant,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	0	LABOUR	MECH	Labour		
RP20	434QWL	54062	02/13/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R					

RP20	434QWL	54062	02/13/2023	FRIVANB	39	100417		BRIVAL01	EX00027100	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-1360		BRIVAL01	EX00027100	ALTERNATOR BELT FRIDGE,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-0603		BRIVAL01	EX00027100	SB Series Fridge motor fanbelt,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-0629		BRIVAL01	EX00027100	SB series fridge motor fanbelt,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	41-7063		BRIVAL01	EX00027100	SWITCH PRESS OIL,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	CC		BRIVAL01	EX00027100	CALIBRATION CETIFICATE,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	CON		BRIVAL01	EX00027100	Consuma bles ,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	LAB		BRIVAL01	EX00027100	Labour,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9	
RP20	434QWL	54062	02/13/2023	FRIVANB	Service completed by BVR 06/02/2023 - Carry out B Service as per BVR Specifications - Remove and replace all worn belts - Remove and replace u/s oil pressure					
RP20	434QWL	54062	02/13/2023	FRIVANB	39	100417		BRIVAL01	14423	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-1360		BRIVAL01	14423	ALTERNATOR BELT FRIDGE,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-0603		BRIVAL01	14423	SB Series Fridge motor fanbelt,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	78-0629		BRIVAL01	14423	SB series fridge motor fanbelt,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	41-7063		BRIVAL01	14423	SWITCH PRESS OIL,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	CC		BRIVAL01	14423	CALIBRATION CETIFICATE,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	CON		BRIVAL01	14423	Consuma bles ,RP20
RP20	434QWL	54062	02/13/2023	FRIVANB	39	LAB		BRIVAL01	14423	Labour,RP20
RP20	434QWL	54062	02/13/2023	FRIVCAL	1	LABOUR	MECH	Labour		

RP20	434QWL	54504	02/24/2023	FVGEN	39	CON	BRIVAL01	EX00027284	Consumables,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	61-0600	BRIVAL01	EX00027284	RECIEVER DRIER, FRIDGE MOTOR,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	BROWN TIP SOLDER	BRIVAL01	EX00027284	BROWN TIP SOLDER,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	NITRO	BRIVAL01	EX00027284	NITROGEN HIGH PURITY,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	R404A	BRIVAL01	EX00027284	GAS R404A,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	8452739	BRIVAL01	EX00027284	CONTROLLER SR3 NEWX SLXI,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	LAB	BRIVAL01	EX00027284	Labour,RP20
RP20	434QWL	54504	02/24/2023	FVGEN		completed by BVR 20/02/2023 - Travel to site and inspect unit - Install unit - Drill new holes and fit mounting bolts - Connect fuel lines and wiring - Remove and replace damaged section of pipe - Replace drier - Pressure test - Vac out unit			
RP20	434QWL	54504	02/24/2023	FVGEN	39	LAB	BRIVAL01	14707	Labour,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	8452739	BRIVAL01	14707	CONTROLLER SR3 NEWX SLXI,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	R404A	BRIVAL01	14707	GAS R404A,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	NITRO	BRIVAL01	14707	NITROGEN HIGH PURITY,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	BROWN TIP SOLDER	BRIVAL01	14707	BROWN TIP SOLDER,RP20

RP20	434QWL	54504	02/24/2023	FVGEN	39	61-0600	BRIVAL01	14707	RECIEVER DRIER, FRIDGE MOTOR,RP20
RP20	434QWL	54504	02/24/2023	FVGEN	39	CON	BRIVAL01	14707	Consumables,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	39	CON	BRIVAL01	EX00027327	Consumables,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	39	61-0600	BRIVAL01	EX00027327	RECIEVER DRIER, FRIDGE MOTOR,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	39	LAB	BRIVAL01	EX00027327	Labour,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	Service completed by BVR 21/02/2023 - Travel to site and inspect unit - reset optiset, download unit - fit all panels - tidy fuel lines and wiring - replace drier - wash condenser coil - unit run on test * Note - needs light switch				
RP20	434QWL	54506	02/28/2023	FVGEN	39	LAB	BRIVAL01	14733	Labour,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	39	61-0600	BRIVAL01	14733	RECIEVER DRIER, FRIDGE MOTOR,RP20
RP20	434QWL	54506	02/28/2023	FVGEN	39	CON	BRIVAL01	14733	Consumables,RP20

RP20	434QWL	54536	03/07/2023	TRA	0	LABOUR	MECH1	Labour		
RP20	434QWL	54536	03/07/2023	TRA	SERVICE COMPLETED.					
RP20	434QWL	54536	03/07/2023	TRA	0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	54536	03/07/2023	TRA	0	LABOUR	APPRENF	Labour - Internal		
RP20	434QWL	54536	03/07/2023	TRA	16	CON		YAT	Consumables	
RP20	434QWL	55660	04/14/2023	FVGEN	39	CON		BRIVAL01	EX00028099	Consumables,RP20
RP20	434QWL	55660	04/14/2023	FVGEN	39	41-3669		BRIVAL01	EX00028099	SWITCH HPCO,RP20
RP20	434QWL	55660	04/14/2023	FVGEN	39	LAB		BRIVAL01	EX00028099	Labour,RP20
RP20	434QWL	55660	04/14/2023	FVGEN	Service completed by BVR 11/04/2023 - Travel to site and inspect unit for reported cutting out on High Pressure - Pump down compressor - Remove and replace					
RP20	434QWL	55660	04/14/2023	FVGEN	39	LAB		BRIVAL01	15510	Labour,RP20
RP20	434QWL	55660	04/14/2023	FVGEN	39	41-3669		BRIVAL01	15510	SWITCH HPCO,RP20
RP20	434QWL	55660	04/14/2023	FVGEN	39	CON		BRIVAL01	15510	Consumables,RP20
RP20	434QWL	55802	04/24/2023	TYRES	15	98000120		BRIAUS01	EX00028214	ISS AFTER HOURS CALL OUT,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	CALL OUT TO MAREEBA QLD 6/4/23,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	CALLER WALLY AMORY,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	DRIVER RUSSELL 0419948564,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	4 X 11R22.5 MARATHON LHT,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	3 X SCRAP,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	POS 5-8,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	EX00028214	R141022,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	R141022,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	POS 5-8,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	3 X SCRAP,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	4 X 11R22.5 MARATHON LHT,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	DRIVER RUSSELL 0419948564,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	CALLER WALLY AMORY,
RP20	434QWL	55802	04/24/2023	TYRES	15	33000237		BRIAUS01	89539305	CALL OUT TO MAREEBA QLD 6/4/23,
RP20	434QWL	55802	04/24/2023	TYRES	15	98000120		BRIAUS01	89539305	ISS AFTER HOURS CALL OUT,
RP20	434QWL	56304	05/16/2023	FVGEN	39	CON		BRIVAL01	EX00028568	Consumables,RP20
RP20	434QWL	56304	05/16/2023	FVGEN	39	LAB		BRIVAL01	EX00028568	Labour,RP20

RP20	434QWL	56304	05/16/2023	FVGEN	completed by BVR 11/05/2023 - Traverl to site and inspect unit for defrost damper circuit alarm code (*trailer was loaded) - Check operation of fuse - Unit cooling well, set at 2c, 5c return and -1c supply - Unit run					
RP20	434QWL	56304	05/16/2023	FVGEN	39	LAB		BRIVAL01	16022	Labour,RP20
RP20	434QWL	56304	05/16/2023	FVGEN	39	CON		BRIVAL01	16022	Consumables,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	0	LABOUR	MECH	Labour		

RP20	434QWL	56359	05/19/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

											Consuma bles
RP20	434QWL	56359	05/19/2023	FRIVANB	39	CON		BRIVAL01		EX00028616	,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	CC		BRIVAL01		EX00028616	CALIBRATION CETIFICATE,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	100417		BRIVAL01		EX00028616	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	55-2208		BRIVAL01		EX00028616	COPPER WASHER,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	LAB		BRIVAL01		EX00028616	Labour,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	41-7852		BRIVAL01		EX00028616	41-7852 SLX Defrost Blade,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP20	434QWL	56359	05/19/2023	FRIVANB	Service completed by BVR 17/05/2023 - Carry out B Service as per BVR Specifications - Remove and replace flat bettery (customer supplied) - Clean fuel screen a						
RP20	434QWL	56359	05/19/2023	FRIVANB	39	41-7852		BRIVAL01		16106	41-7852 SLX Defrost Blade,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	LAB		BRIVAL01		16106	Labour,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	55-2208		BRIVAL01		16106	COPPER WASHER,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	100417		BRIVAL01		16106	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	56359	05/19/2023	FRIVANB	39	CC		BRIVAL01		16106	CALIBRATION CETIFICATE,RP20
											Consuma bles
RP20	434QWL	56359	05/19/2023	FRIVANB	39	CON		BRIVAL01		16106	,RP20
RP20	434QWL	56359	05/19/2023	FRIVCAL	1	LABOUR	MECH	Labour			
RP20	434QWL	56920	06/06/2023	TRA	0	LABOUR	MECH 3	Labour			
RP20	434QWL	56920	06/06/2023	TRA	SERVICE COMPLET ED. REPAIR INDICATO R WIRING LH SIDE						
RP20	434QWL	56920	06/06/2023	TRA	0	LABOUR	APPRENF	Labour - Internal			
RP20	434QWL	56920	06/06/2023	TRA	16	CON		YAT	Consumables		

RP20	434QWL	57586	06/27/2023	WEICAL	AIR GAUGE: 20850 ADJUSTED : 20050 WEIGHBRIDGE: 19780					
RP20	434QWL	57655	06/30/2023	TRA	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.	0	LABOUR	APPRENF	Labour	
RP20	434QWL	57655	06/30/2023	TRA	SERVICE COMPLETED. REPLACED 2.5KG FIRE EXTINGUISHER					
RP20	434QWL	57655	06/30/2023	TRA		0	LABOUR	APPREN	Labour - Internal	
RP20	434QWL	57655	06/30/2023	TRA		0	LABOUR	MECH 3	Labour - Internal	
RP20	434QWL	57655	06/30/2023	TRA		19	FIREEXT2.5KG		YAT	2.5KG FIRE EXTINGUISHER
RP20	434QWL	57655	06/30/2023	TRA		16	CON		YAT	Consumables
RP20	434QWL	57972	07/13/2023	TRA		0	LABOUR	MECH 3	Labour	

RP20	434QWL	57972	07/13/2023	TRA	SERVICE COMPLETED. REPLACED SPRING EYE BUSH FRONT RHS AXLE. REPLACED SPRING EYE CENTRE BOLT				
RP20	434QWL	57972	07/13/2023	TRA		0	LABOUR	APPRENF	Labour - Internal
RP20	434QWL	57972	07/13/2023	TRA		16	CON	YAT	Consumables
RP20	434QWL	57972	07/13/2023	TRA		8	0203142K1T-1ALP	YAT	KIT BUSH AL2 ALIGN PARALLEL
RP20	434QWL	58063	07/19/2023	TRA		1	LABOUR	MECH	Labour
RP20	434QWL	58063	07/19/2023	TRA	SERVICE COMPLETED.				
RP20	434QWL	58063	07/19/2023	TRB		0	LABOUR	MECH 3	Labour
RP20	434QWL	58063	07/19/2023	TRB	SERVICE COMPLETED. REPLACED SPRINGAGE BUSH FRONT RHS AXLE. REPLACED SPRINGAGE CENTRE BOLT				
RP20	434QWL	58063	07/19/2023	TRB		0	LABOUR	APPRENF	Labour - Internal
RP20	434QWL	58063	07/19/2023	TRB		16	CON	YAT	Consumables
RP20	434QWL	58063	07/19/2023	TRB		16	0203142K1T-1ALP	YAT	KIT BUSH AL2 ALIGN PARALLEL

RP20	434QWL	58985	08/08/2023	FVGEN	39	CON		BRIVAL01	EX00029983	Consumables,RP20
RP20	434QWL	58985	08/08/2023	FVGEN	39	LAB		BRIVAL01	EX00029983	Labour,RP20
RP20	434QWL	58985	08/08/2023	FVGEN	Service completed by BVR 09/08/2023 - Travel to site and inspect unit - Carried out engine, condenser and compressor clean.					
RP20	434QWL	58985	08/08/2023	FVGEN	39	CON		BRIVAL01	INV-00017137	Consumables,RP20
RP20	434QWL	58985	08/08/2023	FVGEN	39	LAB		BRIVAL01	INV-00017137	Labour,RP20
RP20	434QWL	59030	08/18/2023	TRA	1	LABOUR	MECH 3	Labour		
RP20	434QWL	59030	08/18/2023	TRA	SERVICE COMPLETED BY MATT, FLYNN & JOSEPH ON 17/08/2023.					
RP20	434QWL	59030	08/18/2023	TRA	0	LABOUR	APPRENF	Labour - Internal		
RP20	434QWL	59030	08/18/2023	TRA	0	LABOUR	APPRENJ	Labour - Internal		
RP20	434QWL	59030	08/18/2023	TRA	16	CON		YAT	Consumables	
RP20	434QWL	59355	08/23/2023	WEICAL	AIR GAUGE: 15500 ADJUSTED: 15750 WEIGHBRIDGE: 15480 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	59635	08/31/2023	FVGEN	39	CON		BRIVAL01	EX00030350	Consumables,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	45-2258		BRIVAL01	EX00030350	120 AMP ALTERNATOR,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	78-1945		BRIVAL01	EX00030350	SLX TOP BELT,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	77-3124		BRIVAL01	EX00030350	IDLER BEARING,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	77-3125		BRIVAL01	EX00030350	CROSS SHAFT BEARING,RP20

RP20	434QWL	59635	08/31/2023	FVGEN	39	LAB		BRIVAL01	EX00030350	Labour,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	Service completed by BVR 31/08/2023 - Travel to site and inspect unit - Remove and replace flat battery (customer supplied) - Found alternator is overcharging					
RP20	434QWL	59635	08/31/2023	FVGEN	39	LAB		BRIVAL01	INV-00017507	Labour,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	77-3125		BRIVAL01	INV-00017507	CROSS SHAFT BEARING,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	77-3124		BRIVAL01	INV-00017507	IDLER BEARING,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	78-1945		BRIVAL01	INV-00017507	SLX TOP BELT,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	45-2258		BRIVAL01	INV-00017507	120 AMP ALTERNATOR,RP20
RP20	434QWL	59635	08/31/2023	FVGEN	39	CON		BRIVAL01	INV-00017507	Consumables,RP20
RP20	434QWL	59518	09/04/2023	GEN	15	11002822		BRIAUS01	EX00030294	11R2.5 148L 16 BS R168,
RP20	434QWL	59518	09/04/2023	GEN	15	77000180		BRIAUS01	EX00030294	CASE STOCK 11-22.5,
RP20	434QWL	59518	09/04/2023	GEN	15	33000084		BRIAUS01	EX00030294	FIT TBR TYRE,
RP20	434QWL	59518	09/04/2023	GEN	15	33000517		BRIAUS01	EX00030294	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	59518	09/04/2023	GEN	15	33000096		BRIAUS01	EX00030294	PUNCTURE REPAIR TBR,
RP20	434QWL	59518	09/04/2023	GEN	15	33000118		BRIAUS01	EX00030294	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	59518	09/04/2023	GEN	15	11002822		BRIAUS01	1.87E+08	11R2.5 148L 16 BS R168,
RP20	434QWL	59518	09/04/2023	GEN	15	77000180		BRIAUS01	1.87E+08	CASE STOCK 11-22.5,
RP20	434QWL	59518	09/04/2023	GEN	15	33000084		BRIAUS01	1.87E+08	FIT TBR TYRE,
RP20	434QWL	59518	09/04/2023	GEN	15	33000517		BRIAUS01	1.87E+08	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	59518	09/04/2023	GEN	15	33000096		BRIAUS01	1.87E+08	PUNCTURE REPAIR TBR,
RP20	434QWL	59518	09/04/2023	GEN	15	33000118		BRIAUS01	1.87E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	59844	09/13/2023	TRA	1	LABOUR	APPRENB	Labour		
RP20	434QWL	59844	09/13/2023	TRA	SERVICE COMPLETED BY BEN & JOE ON 13/09/2023.					
RP20	434QWL	59844	09/13/2023	TRA	0	LABOUR	APPRENJ	Labour - Internal		
RP20	434QWL	59844	09/13/2023	TRA	16	CON		YAT	Consumables	
RP20	434QWL	60851	10/16/2023	TRA	1	LABOUR	MECH 3	Labour		
RP20	434QWL	60851	10/16/2023	TRA	SERVICE COMPLETED BY MATT & NICK ON 16/10/2023.					
RP20	434QWL	60851	10/16/2023	TRA	0	LABOUR	MECH 1	Labour - Internal		
RP20	434QWL	60851	10/16/2023	TRA	16	CON		YAT	Consumables	
RP20	434QWL	60834	10/17/2023	FVGEN	39	CON		BRIVAL01	EX00030961	Consumables,
RP20	434QWL	60834	10/17/2023	FVGEN	39	40-0985		BRIVAL01	EX00030961	LED Status Light,
RP20	434QWL	60834	10/17/2023	FVGEN	39	LAB		BRIVAL01	EX00030961	Labour,
RP20	434QWL	60834	10/17/2023	FVGEN	39	CON		BRIVAL01	INV-00018194	Consumables,
RP20	434QWL	60834	10/17/2023	FVGEN	39	40-0985		BRIVAL01	INV-00018194	LED Status Light,
RP20	434QWL	60834	10/17/2023	FVGEN	39	LAB		BRIVAL01	INV-00018194	Labour,

RP20	434QWL	61360	10/26/2023	FVGEN	39	CON	BRIVAL01	EX00031188	Consumables,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	41-7063	BRIVAL01	EX00031188	SWITCH PRESS OIL,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	44-9298	BRIVAL01	EX00031188	RPM SENSOR, FRIDGE MOTOR,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	CON	BRIVAL01	EX00031188	RIVNUT,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	LAB	BRIVAL01	EX00031188	Labour,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	COMPLETED BY BVR ON 26.10.2023 TRAVEL TO SITE AND INSPECT UNIT - REMOVE AND REPLACE LEAKING OIL PRESSURE SWITCH - REMOVE AND REPLACE US RPM SENSOR - REPLACE MISSING BOLTS ON FAN BELT - UNIT RAN				
RP20	434QWL	61360	10/26/2023	FVGEN	39	CON	BRIVAL01	INV-00018362	Consumables,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	41-7063	BRIVAL01	INV-00018362	SWITCH PRESS OIL,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	44-9298	BRIVAL01	INV-00018362	RPM SENSOR, FRIDGE MOTOR,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	CON	BRIVAL01	INV-00018362	RIVNUT,RP20
RP20	434QWL	61360	10/26/2023	FVGEN	39	LAB	BRIVAL01	INV-00018362	Labour,RP20
RP20	434QWL	61619	11/07/2023	GEN	15	11004117	BRIAUS01	EX00031273	11R22.5 148/145L FS FT469,FITTED FROM CUSTOMER'S OWN STOCK

RP20	434QWL	61619	11/07/2023	GEN	15	77000180		BRIAUS01		EX00031273	CASE STOCK 11-22.5,
RP20	434QWL	61619	11/07/2023	GEN	15	33000084		BRIAUS01		EX00031273	FIT TBR TYRE,
RP20	434QWL	61619	11/07/2023	GEN	15	33000517		BRIAUS01		EX00031273	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	61619	11/07/2023	GEN	15	11004117		BRIAUS01		1.88E+08	11R22.5 148/145L FS FT469,FITTED FROM CUSTOMER'S OWN STOCK
RP20	434QWL	61619	11/07/2023	GEN	15	77000180		BRIAUS01		1.88E+08	CASE STOCK 11-22.5,
RP20	434QWL	61619	11/07/2023	GEN	15	33000084		BRIAUS01		1.88E+08	FIT TBR TYRE,
RP20	434QWL	61619	11/07/2023	GEN	15	33000517		BRIAUS01		1.88E+08	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	61902	11/15/2023	TRA	1	LABOUR	MECH 3	Labour			
RP20	434QWL	61902	11/15/2023	TRA	SERVICE COMPLETED BY MATT & FLYNN ON 15/11/2023. REPAIRED INTERIOR LIGHT CIRCUIT AND REPLACED RED INDICATOR LAMP AT FRONT SWITCH AREA						
RP20	434QWL	61902	11/15/2023	TRA	0	LABOUR	APPRENF	Labour - Internal			
RP20	434QWL	61902	11/15/2023	TRA	16	CON		YAT	Consumables		
RP20	434QWL	61902	11/15/2023	TRA	14	91632		YAT	LED Marker Light, Red. Narva		
RP20	434QWL	62093	11/17/2023	FVGEN	39	CON		BRIVAL01		EX00031491	Consumables,RP20
RP20	434QWL	62093	11/17/2023	FVGEN	39	40-0974		BRIVAL01		EX00031491	GRADED SENSOR,RP20
RP20	434QWL	62093	11/17/2023	FVGEN	39	LAB		BRIVAL01		EX00031491	Labour,RP20
RP20	434QWL	62093	11/17/2023	FVGEN	Service completed by BVR 16/11/2023 - Travel to site and inspect unit for reported sensor alarm codes - Remove and replace u/s return air sensor and control s						
RP20	434QWL	62093	11/17/2023	FVGEN	39	LAB		BRIVAL01		INV-00018679	Labour,RP20
RP20	434QWL	62093	11/17/2023	FVGEN	39	40-0974		BRIVAL01		INV-00018679	GRADED SENSOR,RP20

RP20	434QWL	62093	11/17/2023	FVGEN		39	CON		BRIVAL01	INV-00018679	Consumables ,RP20
RP20	434QWL	62868	12/14/2023	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES QLD ON 14/12/2023 INVOICE NO. 00029135 NO FAULTS APPARENT	1	LABOUR	MECH	Labour		
RP20	434QWL	62868	12/14/2023	EXOINS		1	LABEXT		DIESER01	EX00031946	C & D SERVICE WITHOUT BEARINGS,
RP20	434QWL	62868	12/14/2023	EXOINS		16	CON		DIESER01	EX00031946	MATERIALS,
RP20	434QWL	62868	12/14/2023	EXOINS		16	CON		DIESER01	EX00031946	DEGREASER,
RP20	434QWL	62868	12/14/2023	EXOINS		1	LABEXT		DIESER01	29135	C & D SERVICE WITHOUT BEARINGS,
RP20	434QWL	62868	12/14/2023	EXOINS		16	CON		DIESER01	29135	MATERIALS,
RP20	434QWL	62868	12/14/2023	EXOINS		16	CON		DIESER01	29135	DEGREASER,
RP20	434QWL	62867	12/14/2023	TRA		1	LABOUR	MECH	Labour		
RP20	434QWL	62867	12/14/2023	TRA	SERVICE COMPLETED.						
RP20	434QWL	62867	12/14/2023	TRB		1	LABOUR	MECH	Labour		
RP20	434QWL	62867	12/14/2023	TRB	SERVICE COMPLETED.						

RP20	434QWL	62867	12/14/2023	TRC	COMPLETED BY DIESEL SERVICES QLD ON 13/12/2023. INVOICE NO. 00029135 Service as per C and D service sheet without bearings. Retention all fasteners to factory torque settings and grease all points, adjust all	1	LABOUR	MECH	Labour	
RP20	434QWL	62867	12/14/2023	TRC		8	2.57E+08		YAT	O-RING
RP20	434QWL	63207	12/27/2023	FRIVANB		0	LABOUR	MECH	Labour	

RP20	434QWL	63207	12/27/2023	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL R+R

RP20	434QWL	63207	12/27/2023	FRIVANB	CARRY OUT B SERVICE AS PER BVR SPECIFICATIONS 27/12/2023						
RP20	434QWL	63207	12/27/2023	FRIVANB		40	3413005		YAT	OIL 15W-40, CK 4/E9	
RP20	434QWL	63207	12/27/2023	FRIVANB		39	CON		BRIVAL01	EX00032091	Consumables,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	CC		BRIVAL01	EX00032091	CALIBRATION CETIFICATE,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	100417		BRIVAL01	EX00032091	Filter Service Kit, Fridge Motor, SLX-400,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	LAB		BRIVAL01	EX00032091	Labour,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	CON		BRIVAL01	INV-00019193	Consumables,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	CC		BRIVAL01	INV-00019193	CALIBRATION CETIFICATE,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	100417		BRIVAL01	INV-00019193	Filter Service Kit, Fridge Motor, SLX-400,
RP20	434QWL	63207	12/27/2023	FRIVANB		39	LAB		BRIVAL01	INV-00019193	Labour,
RP20	434QWL	63207	12/27/2023	FRIVCAL		1	LABOUR	MECH	Labour		
RP20	434QWL	63371	01/02/2024	WEICAL	AIR GAUGE: 19.16 ADJUSTED: 19.16 WEIGHBRIDGE: 19.46 AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						
RP20	434QWL	64438	02/12/2024	TRA		1	LABOUR	APPREN	Labour		

RP20	434QWL	64438	02/12/2024	TRA	SERVICE COMPLETED BY TYLER ON 12/02/2024. REPLACED MALE AIR FITTING NOTED: TINY BIT OF MOVEMENT IN THE LHF SPRING EYE. WILL NEED DOING NEXT SERVICE. DEFECT NO. 00010892 CREATED.						
RP20	434QWL	64438	02/12/2024	TRA		16	CON		YAT	Consumables	
RP20	434QWL	65432	03/14/2024	DEFECT		1	LABOUR	MECH	Labour		
RP20	434QWL	65432	03/14/2024	DEFECT							
RP20	434QWL	65432	03/14/2024	DEFECT	DEFECT CLEARED.						
RP20	434QWL	65686	03/14/2024	GEN		15	33000096		BRIAUS01	EX00033399	PUNCTURE REPAIR TBR,
RP20	434QWL	65686	03/14/2024	GEN		15	33000118		BRIAUS01	EX00033399	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	65686	03/14/2024	GEN		15	33000096		BRIAUS01	1.88E+08	PUNCTURE REPAIR TBR,
RP20	434QWL	65686	03/14/2024	GEN		15	33000118		BRIAUS01	1.88E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	65432	03/14/2024	TRA		1	LABOUR	MECH 1	Labour		
RP20	434QWL	65432	03/14/2024	TRA	SERVICE COMPLETED BY NICK ON 14/03/2024.						
RP20	434QWL	65432	03/14/2024	TRA		16	CON		YAT	Consumables	
RP20	434QWL	66512	04/22/2024	DEFECT		1	LABOUR	MECH	Labour		
RP20	434QWL	66512	04/22/2024	DEFECT							
RP20	434QWL	66512	04/22/2024	DEFECT	DEFECT CLEARED.						

					Defect :- Defect Code : 00010892 Defect Reference : RP20 Date : 12/02/2024 Description of Defect : TINY BIT OF MOVEMENT IN THE LHF SPRING EYE. WILL NEED DOING NEXT SERVICE				
RP20	434QWL	66512	04/22/2024	DEFECT	DEFECT CLEARED				
RP20	434QWL	66512	04/22/2024	TRA		1	LABOUR	APPRENB	Labour

					SERVICE COMPLETED BY BEN & TYLER ON 22/04/2024. LHF SPRING EYE IS DONE, BELIEVE IT WAS DONE IN PRIOR SERVICE. TOPPED UP FRIDGE WITH COOLANT. NOTED: * NEEDS NEW						
RP20	434QWL	66512	04/22/2024	TRA	NHVR					
RP20	434QWL	66512	04/22/2024	TRA		0	LABOUR	APPREN	Labour - Internal	
RP20	434QWL	66512	04/22/2024	TRA		16	CON		YAT	Consumables

					AIR GAUGE: 19250 ADJUSTED: 19750 WEIGHBRIDGE: 19440					
RP20	434QWL	66993	04/30/2024	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	67257	05/17/2024	GEN	15	11004117		BRIAUS01	EX00034317	11R22.5 148/145L FS FT469,OWN STOCK
RP20	434QWL	67257	05/17/2024	GEN	15	77000180		BRIAUS01	EX00034317	CASE STOCK 11-22.5,
RP20	434QWL	67257	05/17/2024	GEN	15	33000084		BRIAUS01	EX00034317	FIT TBR TYRE,
RP20	434QWL	67257	05/17/2024	GEN	16	33000518		BRIAUS01	EX00034317	REMOVAL: CUSTOMER REQUEST,
RP20	434QWL	67257	05/17/2024	GEN	15	33000118		BRIAUS01	EX00034317	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	67257	05/17/2024	GEN	15	33000118		BRIAUS01	1.89E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	67257	05/17/2024	GEN	16	33000518		BRIAUS01	1.89E+08	REMOVAL: CUSTOMER REQUEST,
RP20	434QWL	67257	05/17/2024	GEN	15	33000084		BRIAUS01	1.89E+08	FIT TBR TYRE,
RP20	434QWL	67257	05/17/2024	GEN	15	77000180		BRIAUS01	1.89E+08	CASE STOCK 11-22.5,
RP20	434QWL	67257	05/17/2024	GEN	15	11004117		BRIAUS01	1.89E+08	11R22.5 148/145L FS FT469,OWN STOCK
RP20	434QWL	67363	05/22/2024	DEFECT	1	LABOUR	MECH	Labour		
RP20	434QWL	67363	05/22/2024	DEFECT						
RP20	434QWL	67363	05/22/2024	DEFECT	DEFECT CLEARED.					

RP20	434QWL	67363	05/22/2024	DEFECT	Defect :- Defect Code : 00011307 Defect Reference : RP20 Date : 22/04/2024 Description of Defect : NEEDS NEW NHVR STICKER DEFECT CLEARED ON 22/05/2024 FITTED NEW NHVR STICKER				
RP20	434QWL	67363	05/22/2024	TRA		1	LABOUR	MECH 5	Labour

RP20	434QWL	67363	05/22/2024	TRA	'A' SERVICE COMPLETED BY BEN & ETHAN ON 22/05/2024. FITTED NEW NHVR STICKER.						
RP20	434QWL	67363	05/22/2024	TRA		0	LABOUR	MECH 4	Labour - Internal		
RP20	434QWL	67363	05/22/2024	TRA		16	CON		YAT	Consumables	
RP20	434QWL	70700	06/12/2024	WASH	TRAILER WASH COMPLETED ON 12/06/2024 AT LOCATION : YATALA						
RP20	434QWL	68339	06/13/2024	FVGEN		39	CON		BRIVAL01	EX00034826	Consumables,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	22-1160		BRIVAL01	EX00034826	OIL PUMP ASSEMBLY FRIDGE,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	78-1968		BRIVAL01	EX00034826	GEN Water Pump Belt,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	91-4159		BRIVAL01	EX00034826	VIBRATION MOUNT,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	91-8972		BRIVAL01	EX00034826	ISOLATOR SNUBBER,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	42-2284		BRIVAL01	EX00034826	PRESSURE TRANSDUCER, FRIDGE MOTOR,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	77-2856		BRIVAL01	EX00034826	Bush Drive Coupling,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	R404A		BRIVAL01	EX00034826	GAS R404A,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	Engine Oil		BRIVAL01	EX00034826	Engine Oil 15w40 Gulf Western,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	LAB		BRIVAL01	EX00034826	Labour,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	30-0243		BRIVAL01	EX00034826	COMPRESSOR GASKET KIT,rp20

RP20	434QWL	68339	06/13/2024	FVGEN	complete d by BVR 13/6/202 4 - Travel to site and inspect unit for reported leaking oil from compress or and short on gas - Check over unit - Found compress or needs overhaul, ran unit and pumped down compress or - Remove

RP20	434QWL	68339	06/13/2024	FVGEN		39	CON	BRIVAL01	INV-00021525	Consumables,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	22-1160	BRIVAL01	INV-00021525	OIL PUMP ASSEMBLY FRIDGE,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	78-1968	BRIVAL01	INV-00021525	GEN Water Pump Belt,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	91-4159	BRIVAL01	INV-00021525	VIBRATION MOUNT,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	91-8972	BRIVAL01	INV-00021525	ISOLATOR SNUBBER,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	42-2284	BRIVAL01	INV-00021525	PRESSURE TRANSDUCER, FRIDGE MOTOR,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	77-2856	BRIVAL01	INV-00021525	Bush Drive Coupling,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	R404A	BRIVAL01	INV-00021525	GAS R404A,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	Engine Oil	BRIVAL01	INV-00021525	Engine Oil 15w40 Gulf Western,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	LAB	BRIVAL01	INV-00021525	Labour,RP20
RP20	434QWL	68339	06/13/2024	FVGEN		39	30-0243	BRIVAL01	INV-00021525	COMPRESSOR GASKET KIT,rp20
RP20	434QWL	68235	06/14/2024	WEICAL	AIR GAUGE: 13750 ADJUSTED: 13250 WEIGHBRIDGE: 12760					
RP20	434QWL	68235	06/14/2024	WEICAL	AIR GAUGE CALIBRATION COMPLETED CORRECTLY.					
RP20	434QWL	68847	07/04/2024	DEFECT		1	LABOUR	MECH	Labour	
RP20	434QWL	68847	07/04/2024	DEFECT						
RP20	434QWL	68847	07/04/2024	DEFECT	DEFECT CLEARED.					

RP20	434QWL	68847	07/04/2024	DEFECT	Reported Defect :- Defect Code : 00011477 Defect Reference : RP20 Date : 17/05/2024 Description of Defect : NOT TRACKING . PLEASE CHECK TRACKER				
RP20	434QWL	68847	07/04/2024	TRA		1	LABOUR	MECH	Labour
RP20	434QWL	68847	07/04/2024	TRA	SERVICE COMPLETED.				
RP20	434QWL	68847	07/04/2024	TRB		1	LABOUR	APPRENA	Labour

RP20	434QWL	68847	07/04/2024	TRB	SERVICE COMPLETED BY WORKSHOP 02/07/2024 FITTED NEW FIRE EXTINGUISER FITTED NEW HOSES AND CLAMPS TO VALUES DUE TO LEAKS FITTED NEW TRACKER TO ROOF

RP20	434QWL	68847	07/04/2024	TRB	0	LABOUR	MECH 6	Labour - Internal	
RP20	434QWL	68847	07/04/2024	TRB	16	CON		YAT	Consumables
RP20	434QWL	68847	07/04/2024	TRB	16	FIREEXT4.5KG		YAT	4.5KG FIRE EXTINGUISHER
RP20	434QWL	69650	08/01/2024	GEN	39	LABOUR	MECH 5	Labour	

RP20	434QWL	69650	08/01/2024	GEN	REPAIR COMPLETED BY BEN, JOSEPH & MICK ON 01/08/2024. REPLACED FRONT LEFT AND RIGHT SPRING EYES AND REPLACED WEAR PLATES. WHEEL ALIGNED THE AXLE					
RP20	434QWL	69650	08/01/2024	GEN		0	LABOUR	APPRENJ	Labour - Internal	
RP20	434QWL	69650	08/01/2024	GEN		0	LABOUR	MECH	Labour - Internal	
RP20	434QWL	69650	08/01/2024	GEN		16	con		YAT	Consumables
RP20	434QWL	69628	08/01/2024	TRA		1	LABOUR	MECH 1	Labour	

RP20	434QWL	69628	08/01/2024	TRA	'A' SERVICE COMPLETED BY NICK (WORKSHOP) ON 01/08/2024. REPLACED ALL BRAKES THAT HAD JOINERS IN THEM. REPLACED LEAKING FITTING ON BRAKE VALVE. REPLACED DRAIN TANK VALVE.					
RP20	434QWL	69628	08/01/2024	TRA		16	CON		YAT	Consumables
RP20	434QWL	70050	08/12/2024	SANI	TRAILER SANITISATION COMPLETED ON 12/08/2024. AT LOCATION : TULLY.					
RP20	434QWL	70636	09/02/2024	FRIVANB		0	LABOUR	MECH	Labour	

RP20	434QWL	70636	09/02/2024	FRIVANB	VAN "B" SERVICE COMPLETED BY BVR 02/09/2024 INV # INV-00022691 FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY BVR. CARRY OUT B SERVICE AS PER BVR SPECIFICATIONS

RP20	434QWL	70636	09/02/2024	FRIVANB	39	CON		BRIVAL01		EX00036056	Consumables,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	LAB		BRIVAL01		EX00036056	Labour,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	CC		BRIVAL01		EX00036056	CALIBRATION CETIFICATE,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	100417		BRIVAL01		EX00036056	Filter Service Kit, Fridge Motor, SLX-400,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	781626		BRIVAL01		EX00036056	Belt, Engine, Fridge Motor,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	45-2753		BRIVAL01		EX00036056	Yanmar Starter Motor,
RP20	434QWL	70636	09/02/2024	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9		
RP20	434QWL	70636	09/02/2024	FRIVANB	39	CON		BRIVAL01		INV-00022691	Consumables,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	LAB		BRIVAL01		INV-00022691	Labour,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	CC		BRIVAL01		INV-00022691	CALIBRATION CETIFICATE,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	100417		BRIVAL01		INV-00022691	Filter Service Kit, Fridge Motor, SLX-400,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	781626		BRIVAL01		INV-00022691	Belt, Engine, Fridge Motor,
RP20	434QWL	70636	09/02/2024	FRIVANB	39	45-2753		BRIVAL01		INV-00022691	Yanmar Starter Motor,
RP20	434QWL	70636	09/02/2024	FRIVCAL	1	LABOUR	MECH	Labour			
RP20	434QWL	72184	09/04/2024	WEICAL	AIR GAUGE: 19.100 ADJUSTED: 19.500 WEIGHBRIDGE: 19.200						
					AIR GAUGE CALIBRATION COMPLETED CORRECTLY.						

RP20	434QWL	70804	09/09/2024	TRA	1	LABOUR	APPREN	Labour			
RP20	434QWL	70804	09/09/2024	TRA		'A' SERVICE COMPLETED BY TYLER (WORKSHOP) ON 09/09/2024. FIXED A BREAK IN WIRING WHICH WAS CAUSING RHT ROOF LIGHTS TO BE OUT					
RP20	434QWL	70804	09/09/2024	TRA	16	CON		YAT	Consumables		
RP20	434QWL	72446	09/11/2024	WASH		TRAILER WASH COMPLETED ON 11.09.2024 AT LOCATION : YATALA					
RP20	434QWL	71820	09/26/2024	FVGEN	39	42-0100		BRIVAL01		EX00036468	STOP FUEL SOLENOID, FRIDGE MOTORS,RP20
RP20	434QWL	71820	09/26/2024	FVGEN	39	LAB		BRIVAL01		EX00036468	Labour,RP20

RP20	434QWL	71820	09/26/2024	FVGEN	Service completed by BVR 26/09/2024 - **PARTS DELIVERY. ...@ MT. SAINT JOHN Delivered fuel solenoid to customer as per requested					
RP20	434QWL	71820	09/26/2024	FVGEN	39	LAB		BRIVAL01	INV-00023069	Labour,RP20
RP20	434QWL	71820	09/26/2024	FVGEN	39	42-0100		BRIVAL01	INV-00023069	STOP FUEL SOLENOID, FRIDGE MOTORS,RP20
RP20	434QWL	71655	09/27/2024	GEN	39	LABEXT		BNTAUT01	EX00036424	CHECK RUNNING ISSUE AND FOUND SHUT OFF SOLENOID FAULTY. REMOVED S(
RP20	434QWL	71655	09/27/2024	GEN	16	CON		BNTAUT01	EX00036424	Consumables,
RP20	434QWL	71655	09/27/2024	GEN	16	CON		BNTAUT01	29463	Consumables,
RP20	434QWL	71655	09/27/2024	GEN	39	LABEXT		BNTAUT01	29463	CHECK RUNNING ISSUE AND FOUND SHUT OFF SOLENOID FAULTY. REMOVED S(
RP20	434QWL	72733	10/18/2024	TRA	1	LABOUR	MECH 1	Labour		
RP20	434QWL	72733	10/18/2024	TRA	'A' SERVICE COMPLETED BY NICK & TYLER (W/SHOP) ON 18/10/2024.					
RP20	434QWL	72733	10/18/2024	TRA	0	LABOUR	APPREN	Labour - Internal		
RP20	434QWL	72733	10/18/2024	TRA	16	CON		YAT	Consumables	
RP20	434QWL	73340	11/07/2024	TYRES	15	11002821		BRIAUS01	EX00037139	11R22.5 148/145L BS R119 ECO,

RP20	434QWL	73340	11/07/2024	TYRES	15	77000232		BRIAUS01	EX00037139	CASE STOCK 11R22.5 ECOPIA,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000084		BRIAUS01	EX00037139	FIT TBR TYRE,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000517		BRIAUS01	EX00037139	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000085		BRIAUS01	EX00037139	ROTATE TBR TYRE,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000118		BRIAUS01	EX00037139	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	73340	11/07/2024	TYRES	15	11002821		BRIAUS01	1.9E+08	11R22.5 148/145L BS R119 ECO,
RP20	434QWL	73340	11/07/2024	TYRES	15	77000232		BRIAUS01	1.9E+08	CASE STOCK 11R22.5 ECOPIA,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000084		BRIAUS01	1.9E+08	FIT TBR TYRE,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000517		BRIAUS01	1.9E+08	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000085		BRIAUS01	1.9E+08	ROTATE TBR TYRE,
RP20	434QWL	73340	11/07/2024	TYRES	15	33000118		BRIAUS01	1.9E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	73942	12/05/2024	DEFECT	1	LABOUR	MECH	Labour		
RP20	434QWL	73942	12/05/2024	DEFECT						
RP20	434QWL	73942	12/05/2024	DEFECT	DEFECT CLEARED.					
RP20	434QWL	73942	12/05/2024	DEFECT	Defect :- Defect Code : 00012910 Defect Reference : 35714 Date : 02/11/2024 Description of Defect : LEG WINDER HANDLE ABOUT TO BREAK @ BOLT/SWIVEL SECTION DEFECT CLEARED ON 05/12/2024					

RP20	434QWL	73942	12/05/2024	DEFECT	Reported Defect :- Defect Code : 00013069 Defect Reference : RP20 Date : 05/12/2024 Description of Defect : TRACKER NOT WORKING - LAST TRACKED 02 NOV 2024 DEFECT CLEARED ON 05/12/2024				
RP20	434QWL	73942	12/05/2024	TRA		1	LABOUR	MECH 5	Labour

RP20	434QWL	73942	12/05/2024	TRA	SERVICE COMPLETED BY BEN, JOSH & COREY (WORKSHOP) ON 05/12/2024. LEG HANDLE HAS BEEN REPAIRED AND IS OKAY. REPLACED RIDE HEIGHT VALVE. F/E EXP : JAN 2025 TRACKER REPLACED. IMEI:					
RP20	434QWL	73942	12/05/2024	TRA		0	LABOUR	APPRENJC	Labour - Internal	
RP20	434QWL	73942	12/05/2024	TRA		0	LABOUR	MECH 6	Labour - Internal	
RP20	434QWL	73942	12/05/2024	TRA		16	CON		YAT	Consumables
RP20	434QWL	73942	12/05/2024	TRA		10	KN27000		YAT	Level valve (Haldex) Trailer

RP20	434QWL	74169	12/17/2024	EXOINS	VEHICLE PASSED ANNUAL ROADWORTHY INSPECTION. ATTEMPT # 1 INSPECTION COMPLETED BY DIESEL SERVICES QLD ON 17/12/202 INVOICE NO. 00029991 NO DEFECTS IDENTIFIED					
RP20	434QWL	74169	12/17/2024	EXOINS		1	LABEXT	DIESER01	EX00037715	C & D SERVICE WITHOUT BEARINGS,
RP20	434QWL	74169	12/17/2024	EXOINS		16	DEGREASER	DIESER01	EX00037715	DEGREASER,
RP20	434QWL	74169	12/17/2024	EXOINS		16	CON	DIESER01	EX00037715	Consumables,
RP20	434QWL	74169	12/17/2024	EXOINS		1	LABEXT	DIESER01	29991	C & D SERVICE WITHOUT BEARINGS,
RP20	434QWL	74169	12/17/2024	EXOINS		16	DEGREASER	DIESER01	29991	DEGREASER,
RP20	434QWL	74169	12/17/2024	EXOINS		16	CON	DIESER01	29991	Consumables,
RP20	434QWL	74168	12/17/2024	TRA		1	LABOUR MECH	Labour		
RP20	434QWL	74168	12/17/2024	TRA	SERVICE COMPLETED.					
RP20	434QWL	74168	12/17/2024	TRB		1	LABOUR MECH	Labour		

RP20	434QWL	74168	12/17/2024	TRB	SERVICE COMPLETED.
RP20	434QWL	74168	12/17/2024	TRC	SERVICE COMPLETED BY DIESEL SERVICES QLD ON 17/12/2024. INVOICE NO. 00029991 Service as per C and D service sheet without bearings. Retention all fasteners to factory torque settings and grease all points,

RP20	434QWL	75559	01/30/2025	FVGEN	39	LAB	FNQTRA01	EX00038425	Labour INC TRAVELLING,RP20
RP20	434QWL	75559	01/30/2025	FVGEN	39	NITRO	FNQTRA01	EX00038425	NITROGEN HIGH PURITY,RP20
RP20	434QWL	75559	01/30/2025	FVGEN	39	CON	FNQTRA01	EX00038425	Consumables,RP20
RP20	434QWL	75559	01/30/2025	FVGEN	Service completed by FNQ Transport Refrigeration Repairs 30/01/2025 - Job. No. D195 - Travelled to trailer to check fault code and unit cutting out - Fitted gaug				
RP20	434QWL	75559	01/30/2025	FVGEN	39	LAB	FNQTRA01	IV00000010022	Labour INC TRAVELLING,RP20
RP20	434QWL	75559	01/30/2025	FVGEN	39	NITRO	FNQTRA01	IV00000010022	NITROGEN HIGH PURITY,RP20
RP20	434QWL	75559	01/30/2025	FVGEN	39	CON	FNQTRA01	IV00000010022	Consumables,RP20

RP20	434QWL	75690	02/11/2025	FVGEN		39	610600	ICEGRO01	EX00038509	FILTER DRIER,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	OIL-CE-35	ICEGRO01	EX00038509	ESTER OIL SOLEST 35 A/C,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	363636-005	ICEGRO01	EX00038509	LONGLIFE COOLANT PREMI,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	CON	ICEGRO01	EX00038509	Consumables,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	NITRO	ICEGRO01	EX00038509	NITROGEN HIGH PURITY,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	LAB	ICEGRO01	EX00038509	Labour,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	VAC OUT	ICEGRO01	EX00038509	Vac Out and Reclaim System,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	LAB	ICEGRO01	EX00038509	TRAINING,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	6307DDU	ICEGRO01	EX00038509	BEARING (NSK),RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	6304DDUNR	ICEGRO01	EX00038509	BEARING (W/CIRCLIP) (NSK),RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	559960	ICEGRO01	EX00038509	SNAP RING SL/SLX IDLERS,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	559959	ICEGRO01	EX00038509	LOCKWASHER - STAR,RP20
RP20	434QWL	75690	02/11/2025	FVGEN		39	78-1282-8	ICEGRO01	EX00038509	TENSIONER - RECON,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	completed by Iceman 10/02/2025 - Inspected unit - Installed guages - checked refrigerant level and pressures - Pressure tested system with nitrogen - Removed rear wall and panels - Traced and rubbed through u-joints on					

RP20	434QWL	75690	02/11/2025	FVGEN	39	78-1282-8		ICEGRO01	896960	TENSIONER - RECON,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	559959		ICEGRO01	896960	LOCKWASHER - STAR,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	559960		ICEGRO01	896960	SNAP RING SL/SLX IDLERS,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	6304DDUNR		ICEGRO01	896960	BEARING (W/CIRCLIP) (NSK),RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	6307DDU		ICEGRO01	896960	BEARING (NSK),RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	LAB		ICEGRO01	896960	TRAINING,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	VAC OUT		ICEGRO01	896960	Vac Out and Reclaim System,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	LAB		ICEGRO01	896960	Labour,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	NITRO		ICEGRO01	896960	NITROGEN HIGH PURITY,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	CON		ICEGRO01	896960	Consumables,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	363636-005		ICEGRO01	896960	LONGLIFE COOLANT PREMI,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	OIL-CE-35		ICEGRO01	896960	ESTER OIL SOLEST 35 A/C,RP20
RP20	434QWL	75690	02/11/2025	FVGEN	39	610600		ICEGRO01	896960	FILTER DRIER,RP20
RP20	434QWL	75674	02/13/2025	TRA	1	LABOUR	MECH 1	Labour - Internal		

RP20	434QWL	75674	02/13/2025	TRA	A SERVICE COMPLETED BY NICK & JOSH (WORKSHOP) ON 13/02/2025. REPLACED FEMALE LIGHT PLUG REPLACED HOSE CLAMPS AS REQUIRED FIRE EXT EXP: AUGUST 2025					
RP20	434QWL	75674	02/13/2025	TRA		16	CON		YAT	Consumables
RP20	434QWL	75674	02/13/2025	TRA		0	LABOUR	APPRENJC	Labour - Internal	
RP20	434QWL	76337	03/17/2025	GEN	REPAIR COMPLETED.BY WORKSHOP 17/03/2024 REPLACED LHS FRONT GAURDE	39	LABOUR	APPRENJ	Labour	

RP20	434QWL	76337	03/17/2025	GEN	16	CON		YAT	Consumables			
RP20	434QWL	76337	03/17/2025	GEN	0	LABOUR	MECH 1		0.5	105	52.5	
RP20	434QWL	76337	03/17/2025	GEN	16	k127-1116-08a		YAT	Mudguard Red			
RP20	434QWL	76753	04/01/2025	DEFECT	1	LABOUR	MECH	Labour				
RP20	434QWL	76753	04/01/2025	DEFECT	DEFECT CLEARED.							
RP20	434QWL	76753	04/01/2025	DEFECT	Reported Defect :- Defect Code : 00013914 Defect Reference : RP20 Date : 01/04/2025 Description of Defect : BRAKE LIGHT NOT WORKING							
RP20	434QWL	76753	04/01/2025	TRA	1	LABOUR	APPREN	Labour - Internal				

RP20	434QWL	76753	04/01/2025	TRA	A SERVICE COMPLETED BY WORKSHOP 01/04/2025 FIRE EXT EXP: AUG 25 REPLACED LHS REAR PARK BRAKE LIGHT SECOND HAND STOCK USED AT NO COST						
RP20	434QWL	76753	04/01/2025	TRA		16	CON		YAT	Consumables	
RP20	434QWL	76753	04/01/2025	TRA		0	LABOUR	APPRENJC	Labour - Internal		
RP20	434QWL	77212	04/15/2025	FVGEN		39	CON		ICEGRO01	EX00039524	Consumables,RP20
RP20	434QWL	77212	04/15/2025	FVGEN		39	LAB		ICEGRO01	EX00039524	Labour,RP20
RP20	434QWL	77212	04/15/2025	FVGEN		35	SS66TI		YAT	BATTERY, STOP/START AGM	
RP20	434QWL	77212	04/15/2025	FVGEN	Service completed by Iceman 15/04/2025 - Inspected unit for reported not starting - Attempted jump start, failed - Replaced u/s battery (customers supplied) - (						
RP20	434QWL	77212	04/15/2025	FVGEN		39	CON		ICEGRO01	901315	Consumables,RP20
RP20	434QWL	77212	04/15/2025	FVGEN		39	LAB		ICEGRO01	901315	Labour,RP20
RP20	434QWL	77857	05/13/2025	DEFECT		1	LABOUR	MECH	Labour		

RP20	434QWL	77857	05/13/2025	DEFECT	DEFECT CLEARED.						
RP20	434QWL	77857	05/13/2025	TRA		1	LABOUR	MECH	Labour - Internal		
					A SERVICE COMPLETED BY NQFM 13.05.2025 INV # 40427 FIRE EXT EXP: AUGUST 2025 CAIIRED OUT A-SERVICE AS PER SERVICE SHEET PROVIDED REPLACED FRONT LHS BOTTOM REFLECTOR						
RP20	434QWL	77857	05/13/2025	TRA							
RP20	434QWL	77857	05/13/2025	TRA		16	CON		YAT	Consumables	
RP20	434QWL	77860	05/21/2025	TRA		39	LAB		RCCLOW01	EX00039959	Labour,
RP20	434QWL	77860	05/21/2025	TRA		39	GREASE		RCCLOW01	EX00039959	GREASE,
RP20	434QWL	77860	05/21/2025	TRA		39	PART		RCCLOW01	EX00039959	RECTANGLE REFLECTOR,
RP20	434QWL	77860	05/21/2025	TRA		39	CON		RCCLOW01	EX00039959	Consumables,
RP20	434QWL	77860	05/21/2025	TRA		39	ENVLEV		RCCLOW01	EX00039959	ENVIRONMENTAL LEVY,
RP20	434QWL	77860	05/21/2025	TRA		39	LAB		RCCLOW01	40427	Labour,
RP20	434QWL	77860	05/21/2025	TRA		39	GREASE		RCCLOW01	40427	GREASE,
RP20	434QWL	77860	05/21/2025	TRA		39	PART		RCCLOW01	40427	RECTANGLE REFLECTOR,

RP20	434QWL	77860	05/21/2025	TRA		39	CON		RCCLOW01	40427	Consumables,
RP20	434QWL	77860	05/21/2025	TRA		39	ENVLEV		RCCLOW01	40427	ENVIRONMENTAL LEVY,
RP20	434QWL	78424	06/12/2025	FRIVANB	VAN "B" SERVICE COMPLETED. FRIDGE VAN UNIT CALIBRATED @ SERVICE. SERVICE COMPLETED BY ICEMAN OIL 14L (Customer Supplied) CALIBRATION CERTIFICATE R+R ENGINE OIL	0	LABOUR	MECH	Labour		
RP20	434QWL	78424	06/12/2025	FRIVANB	R+R						

										Consumables
RP20	434QWL	78424	06/12/2025	FRIVANB	39	CON		ICEGRO01	EX00040319	,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	CC		ICEGRO01	EX00040319	CALIBRATION CETIFICATE,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	100417		ICEGRO01	EX00040319	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	LAB		ICEGRO01	EX00040319	Labour,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	40	3413005		YAT	OIL 15W-40, CK 4/E9	
RP20	434QWL	78424	06/12/2025	FRIVANB	Service completed by Iceman 02/06/2025 - Carried out B Service as per Iceman Specifications					
										Consumables
RP20	434QWL	78424	06/12/2025	FRIVANB	39	CON		ICEGRO01	904402	,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	CC		ICEGRO01	904402	CALIBRATION CETIFICATE,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	100417		ICEGRO01	904402	Filter Service Kit, Fridge Motor, SLX-400,RP20
RP20	434QWL	78424	06/12/2025	FRIVANB	39	LAB		ICEGRO01	904402	Labour,RP20
RP20	434QWL	78424	06/12/2025	FRIVCAL	1	LABOUR	MECH	Labour		
RP20	434QWL	78424	06/12/2025	FRIVCAL	FRIDGE VAN CALIBRATION COMPLETED					
RP20	434QWL	78556	06/17/2025	TYRES	15	11002821		BRIAUS01	EX00040406	11R22.5 148/145L BS R119 ECO,
RP20	434QWL	78556	06/17/2025	TYRES	15	77000232		BRIAUS01	EX00040406	CASE STOCK 11R22.5 ECOPIA,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000084		BRIAUS01	EX00040406	FIT TBR TYRE,
RP20	434QWL	78556	06/17/2025	TYRES	15	33001507		BRIAUS01	EX00040406	CUSTOMER SCRAPPED OWN TYRE,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000517		BRIAUS01	EX00040406	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000522		BRIAUS01	EX00040406	REMOVAL: PUNCTURED,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000118		BRIAUS01	EX00040406	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000118		BRIAUS01	1.91E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000522		BRIAUS01	1.91E+08	REMOVAL: PUNCTURED,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000517		BRIAUS01	1.91E+08	REMOVAL: CUSTOMER PULL POINT,
RP20	434QWL	78556	06/17/2025	TYRES	15	33001507		BRIAUS01	1.91E+08	CUSTOMER SCRAPPED OWN TYRE,
RP20	434QWL	78556	06/17/2025	TYRES	15	33000084		BRIAUS01	1.91E+08	FIT TBR TYRE,
RP20	434QWL	78556	06/17/2025	TYRES	15	77000232		BRIAUS01	1.91E+08	CASE STOCK 11R22.5 ECOPIA,
RP20	434QWL	78556	06/17/2025	TYRES	15	11002821		BRIAUS01	1.91E+08	11R22.5 148/145L BS R119 ECO,
RP20	434QWL	79476	07/23/2025	TRA	1	LABOUR	MECH	Labour - Internal		
					A SERVICE COMPLETED.					
RP20	434QWL	79476	07/23/2025	TRA	FIRE EXT EXP:					

RP20	434QWL	79476	07/23/2025	TRA	16	CON		YAT	Consumables
RP20	434QWL	79476	07/23/2025	TRB	1	LABOUR	APPRENJC	Labour - Internal	
				B SERVICE COMPLETED BY WORKSHOP 23/7/2025 FIRE EXT EXP: AUGUST 2025 REPLACED FRONT LHS SHOCKIE REPLACED REAR LHS REVERSE LIGHT ADJUSTED RIDE HEIGHT TO 375MM					
RP20	434QWL	79476	07/23/2025	TRB	16	CON		YAT	Consumables
RP20	434QWL	79476	07/23/2025	TRB	16	F5002		YAT	SHOCK ABSORBER, BPW LONG
RP20	434QWL	79476	07/23/2025	TRB	16	91700BL		YAT	Clearance Light, LED Amber, Narva
RP20	434QWL	80407	08/26/2025	DEFECT	1	LABOUR	MECH	Labour	
RP20	434QWL	80407	08/26/2025	DEFECT	DEFECT CLEARED.				
RP20	434QWL	80407	08/26/2025	TRA	1	LABOUR	MECH	Labour - Internal	

					A SERVICE COMPLETED BY NQFM 26/8/2025 FIRE EXT EXP: FEBRUARY 2026						
RP20	434QWL	80407	08/26/2025	TRA	INVOICE #41240						
RP20	434QWL	80407	08/26/2025	TRA	16	CON		YAT	Consumables		
RP20	434QWL	80407	08/26/2025	TRA	1	LABEXT		RCCLOW01		EX00041717	Labour External,
RP20	434QWL	80407	08/26/2025	TRA	1	GREASE		RCCLOW01		EX00041717	GREASE, Consumables
RP20	434QWL	80407	08/26/2025	TRA	1	CON		RCCLOW01		EX00041717	,
RP20	434QWL	80407	08/26/2025	TRA	1	ENVLEV		RCCLOW01		EX00041717	ENVIRONMENTAL LEVY,
RP20	434QWL	80407	08/26/2025	TRA	1	BAG		RCCLOW01		EX00041717	BAG FIRE,
RP20	434QWL	80407	08/26/2025	TRA	1	TEST		RCCLOW01		EX00041717	TEST AND TAG FIRE EXTINGUISHER,
RP20	434QWL	80407	08/26/2025	TRA	1	LABEXT		RCCLOW01		41240	Labour External,
RP20	434QWL	80407	08/26/2025	TRA	1	GREASE		RCCLOW01		41240	GREASE, Consumables
RP20	434QWL	80407	08/26/2025	TRA	1	CON		RCCLOW01		41240	,
RP20	434QWL	80407	08/26/2025	TRA	1	ENVLEV		RCCLOW01		41240	ENVIRONMENTAL LEVY,
RP20	434QWL	80407	08/26/2025	TRA	1	BAG		RCCLOW01		41240	BAG FIRE,
RP20	434QWL	80407	08/26/2025	TRA	1	TEST		RCCLOW01		41240	TEST AND TAG FIRE EXTINGUISHER,
RP20	434QWL	81386	10/10/2025	DEFECT	1	LABOUR	MECH	Labour			
RP20	434QWL	81386	10/10/2025	DEFECT	DEFECT CLEARED.						

RP20	434QWL	81386	10/10/2025	DEFECT	Reported Defect :- Defect Code : 00014979 Defect Reference : RP20 Date : 26/08/2025 Description of Defect : NO TELEMETRY DATA FOR TEMPS					
RP20	434QWL	81386	10/10/2025	TRA		1	LABOUR	MECH 1	Labour - Internal	
RP20	434QWL	81386	10/10/2025	TRA	A SERVICE COMPLETED BY WORKSHOP 10/10/2025 FIRE EXT EXP: MARCH 2026 SUPPLY BREAKDOWN KIT					
RP20	434QWL	81386	10/10/2025	TRA		16	CON		YAT	Consumables

RP20	434QWL	81386	10/10/2025	TRA	0	LABOUR	APPRENJ	Labour - Internal			
RP20	434QWL	81386	10/10/2025	TRA	0	LABOUR	MECH 5	Labour - Internal			
RP20	434QWL	81610	10/10/2025	TYRES	15	99015526		BRIAUS01	EX00042527	RUNOUT TYRE,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000084		BRIAUS01	EX00042527	FIT TBR TYRE,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000517		BRIAUS01	EX00042527	REMOVAL: CUSTOMER PULL POINT,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000118		BRIAUS01	EX00042527	SCHEDULED DEPOT SERVICE 15MIN,	
RP20	434QWL	81610	10/10/2025	TYRES	15	99015526		BRIAUS01	1.92E+08	RUNOUT TYRE,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000084		BRIAUS01	1.92E+08	FIT TBR TYRE,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000517		BRIAUS01	1.92E+08	REMOVAL: CUSTOMER PULL POINT,	
RP20	434QWL	81610	10/10/2025	TYRES	15	33000118		BRIAUS01	1.92E+08	SCHEDULED DEPOT SERVICE 15MIN,	
RP20	434QWL	81489	10/15/2025	GEN	39	LABOUR	MECH 1	Labour			
RP20	434QWL	81489	10/15/2025	GEN	REPAIR COMPLETED BY WORKSHOP 15/10/2025 REPLACE SPRING EYE BUSHES AT 3RD AXLE BOTH SIDES AND ADJUST AXLE ALIGNMENT						
RP20	434QWL	81489	10/15/2025	GEN	16	CON		YAT	Consumables		
RP20	434QWL	81489	10/15/2025	GEN	0	LABOUR	APPRENJ	Labour - Internal			
RP20	434QWL	81489	10/15/2025	GEN	16	2.03E+08		YAT	SPRING EYE BUSH SRS AL2		
RP20	434QWL	81600	10/15/2025	TYRES	15	11004117		BRIAUS01	EX00042518	11R22.5 148/145L FS FT469,	
RP20	434QWL	81600	10/15/2025	TYRES	15	77000180		BRIAUS01	EX00042518	CASE STOCK 11-22.5,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000084		BRIAUS01	EX00042518	FIT TBR TYRE,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000370		BRIAUS01	EX00042518	TYRE HELD FOR RUNOUT,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000518		BRIAUS01	EX00042518	REMOVAL: CUSTOMER REQUEST,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000521		BRIAUS01	EX00042518	REMOVAL: MECHANICAL FLAT SPOT,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000118		BRIAUS01	EX00042518	SCHEDULED DEPOT SERVICE 15MIN,	
RP20	434QWL	81600	10/15/2025	TYRES	15	11004117		BRIAUS01	1.92E+08	11R22.5 148/145L FS FT469,	
RP20	434QWL	81600	10/15/2025	TYRES	15	77000180		BRIAUS01	1.92E+08	CASE STOCK 11-22.5,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000084		BRIAUS01	1.92E+08	FIT TBR TYRE,	
RP20	434QWL	81600	10/15/2025	TYRES	15	33000370		BRIAUS01	1.92E+08	TYRE HELD FOR RUNOUT,	

RP20	434QWL	81600	10/15/2025	TYRES	15	33000518		BRIAUS01		1.92E+08	REMOVAL: CUSTOMER REQUEST,
RP20	434QWL	81600	10/15/2025	TYRES	15	33000521		BRIAUS01		1.92E+08	REMOVAL: MECHANICAL FLAT SPOT,
RP20	434QWL	81600	10/15/2025	TYRES	15	33000118		BRIAUS01		1.92E+08	SCHEDULED DEPOT SERVICE 15MIN,
RP20	434QWL	81570	10/20/2025	GEN	39	LABOUR	MECH 1	Labour			
						REPAIR COMPLETED BY WORKSHOP 20/10/2025					
RP20	434QWL	81570	10/20/2025	GEN		REPLACE 2 AIRBAGS AT FIRST AXLE CHECK ALL OTHER AIR BAGS FOR LEAKS AND SERVICEABILITY - ALL OK					
RP20	434QWL	81570	10/20/2025	GEN	16	CON		YAT	Consumables		
RP20	434QWL	81570	10/20/2025	GEN	0	LABOUR	APPRENJ	Labour - Internal			
RP20	434QWL	81570	10/20/2025	GEN	16	70.0059		YAT	AIR SPRING TYPE 36		
RP20	434QWL	82025	11/03/2025	GEN	39	LABOUR	APPREN	Labour			

RP20	434QWL	82025	11/03/2025	GEN	REPAIR COMPLETED BY WORKSHOP 03/11/2025 FIRE EXT EXP: REPLACE LHR TAIL LIGHT REPLACED LHR (DO NOT OVERTAKE SIGN)				
RP20	434QWL	82025	11/03/2025	GEN		16	CON	YAT	Consumables
RP20	434QWL	82025	11/03/2025	GEN		16	TRP34A-A	YAT	DO NOT OVERTAKE 34A SIGN
RP20	434QWL	82025	11/03/2025	GEN		16	2361	YAT	JUMBO-S LED RED STOP/REAR
			Total for Asset		99,929.82				
			Total for Report		99,929.82				

Options:
Sort By
-
AssetCode
Starting
Asset
Code -
RP20
To
- RP20
Starting
Registrati
on -
To
-
Starting
Operation
s No -
To
-
From:
Work
Order
Location -
To
-
From:

ıdenser - Fill with new coolant -Remove compresser - Remove and replace leaking shaft seal - Remove and replace damaged fly wheel and drive plate - Fit new drive bushes - Re-install comp and evacuate - Fill with new gas - Run and check unit - Run dow

ure swit

lace u/s HP switch - Vac out comp - Tighten leaking coolant hose clamp - Reset water pump pulley - Run down to 0c - Unit run on t

en and replace copper washers - Remove and replace faulty damper motor, test operation - Connect van lights, test operation - Unit run on t

ng - Remove and replace u/s alternator as required - Replace worn fan belt - Check charging rate - Replace all noisy idler and cross shaft bearings - Unit run on t

ɔl sensor - Calibrated sensors - Unit run on t

D SOLENOID FROM TRAILER UNIT RP73A AND FITTED TO TRAILER. WHEN NEW SOLENOID ARRIVED, FITTED IT TO TRAILER RP7:

D SOLENOID FROM TRAILER UNIT RP73A AND FITTED TO TRAILER. WHEN NEW SOLENOID ARRIVED, FITTED IT TO TRAILER RP7:

auges and found had no gas filled nitrogen and found leak at evaporator - Customer decided not to go ahead with rep

l) - Checked alternator, ok - Checked operation - Unit ran on t

n to 5 degrees with -7 degrees supply air - Unit run on test - Pretrip pass