SERVICE & REPAIR RECORDS

Plant / Equipment Service & Repair Records			
Make:	Freightliner	**Type:**	Truck
Model:	Columbia CL112 ISL		
Rego / Serial #:	VIN 1FVSF0CYXLLKX4287	**Year of Manufacture:**	2021

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
27.06.24		Maint / Svce Check	Rep RH Brake Light,Complete Inside & Out,Full Brake Adj & Test	Clearance Lights,FL Brake Booster,Rollers For Hook Bin & Hook,Battery For Remote Tarp
01.07.24		Maint	Fault Find Electrics & Rep Mud Guards	WO 1672
04.07.24		Maint	Rep to Hook Rollers & Svce,Adj Brakes,& Grease	WO 1672
05.07.24		Maint	Service	WO 1672
11.07.24		Maint	Fix Boxes & Underneath Doors of Track & Put Rollers On	WO 1672
18.07.24		Maint	Fit Window Actuator,Door Trim,& Switches	WO 1672
22.07.24		Maint	Remove Compliance Plate & Refit QLD Plate,Remove Rego Plates & Fit Cabin Filter	WO 1672
08.08.24		Maint	Fit Trims,Hook & Paint,Remove Stickers	WO 1672
08.08.24		Maint	Freightliner Fridge Mount	WO 1672
09.08.24		Maint	Fit Fridge Cradle & Fridge	WO 1672
28.08.24		Maint	Fit Mud Flap	WO 1806
06.09.24		Maint	Unjammed ride height valve & grease & adj brakes	WO 1830
10.09.24		Maint	Replace Height Level Valve,Wash & prep for Crack Repairs	WO 1830
10.09.24		Maint	Fix Cross Member of Track	WO 1830

SERVICE & REPAIR RECORDS

11.09.24		Maint	Fix Cracks	WO 1830
02.10.24		Maint	Repair to Hook Grind Off Burrs ,Fabricate & Refit Safety Stop	WO 1893
23.10.24		Maint	Remove broken mud flap,Mount fab & fit new mud flap & mount brackets. Fab new mud flaps to fit	WO 1907
05.02.2025	136,289km	Service	Repair to sump leak, repair to PTO leak, missing bolt on stub axel lefthand side 2nd steer tyre, no fault report in the vehicle.	WO 2165 Next Service due: 236,289 Kms
16.07.2025	1955393kms	Service	Windscreen wipers replaced, number plate light replaced, coolant level topped up, grease added to steering joints, grease added to suspension pins and bushes	WO 060039 Next service due: 265000kms
16.11.2025	235680kms	Service	Carried out service as per Schedule	Next service due: 265000kms
05.02.2026		Maint	Replaced air tank valve blocked, replaced missing PTO plug & topped up trans oil	1161
24.04.2026		Maint	Replaced leaking air bag	1255
06.05.2026	266231kms	Service & repairs	Carried out service as req,Trans changing Erratic got Trans specs to recal trans reset shift patterns	Next service 295000kms
10.08.2026		Maint	Carry out pre coi inspection	1366
15.10.2026		Maint	Replaced main air line for hook controls	1452

SERVICE & REPAIR RECORDS
