SERVICE & REPAIR RECORDS

Plant / Equipment QUICK HITCH Service & Repair Records			
Make:	Volvo 48T Excavator	**Type:**	Plant
Model:	EC480DL		
Rego / Serial #:	VCEC480DC00281832	**Year of Manufacture:**	2018

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
October 2018	0			
06/02/2019	427	General service		
20/02/2020	715		Ram Replacement	Supplied by CJD Equipment
26/06/2019	997	General service	Replaced CH attachment hose	
17/09/2019	1355	General Service		
18/02/2020	1466	General Service		
31/07/2020	2514	General Service		
18/05/2021	3477	General Service		
11/12/2021	4164	General Service		
18/03/2022	4320	Inspection	Replaced bulb on RHS boom	
09/05/2022	4396	Inspection		
17/12/2022	4500	Inspection		
19/04/2023	5250	General Service		

SERVICE & REPAIR RECORDS

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
20/04/2023	5328	Inspection		
13/09/2023	5690	General Service		
20/09/2023	5748	Inspection	Bucket Cylinder Resealed,Wiper Motor Replaced,both Dve Motor Oil badly burnt & blk changed both oils	Next Service Due - 6248
14/12/2023	5758	Inspection	Rep Fire Ext	Next Svce - 6248
12/04/2024	5985	General Service	Window Washer doesn't work. The front right light doesn't work. Oils topped up.	
28/05/2024		Maint Insp	Loadrite Sensor Fit Dve Motor Leak Check & Fit Plates	WO 1587 & 1588
30/05/2024	6040	Maint Insp		Next Service Due – 6500hrs
12.08.24	6539	General Service	500 Hr Service	Next Service 7000 Hrs
08.10.24		Maint	Cutting out hitch point plates	WO 1906
09.10.24		Maint	Machining up pin – Cut plates – Fabricate & Weld Stiff arm boom mount plate	WO 1906
10.10.24 -11.10.24		Maint	Drill Pin & Machine Bosses, Cut Parts Fabricate/Modify stiff arm ready for welding together	WO 1906
15.10.24		Maint	Onsite finish welding on Hitch Point,Weld Fit & Test new Strong arm & Mount bracket	WO 1906
14.10.24		Maint	Line boar still arm,Load little tipper	WO 1906
25.10.24		Maint	Remove Dipper Arm Ram for purpose of re-seal	WO 1936
29.10.24		Maint	Strip Cylinder	WO 1906
30.10.24		Maint	Re-seal dipper ram & Re-assemble Hyd Ram	WO 1936

SERVICE & REPAIR RECORDS

Date of Service / Repaired	Km / Hours	Service Type	Repairs Conducted	Comments
16/01/2025	6997	Maint	1000hr service	WO 2107
16.04.2025	7206	Maint Inspection	Steel boom on hose taken off flexi put on, Load rite screen broken off, Door glass broken, grouser plate bent, hand rail broken,	Next service due: 7600 hrs
11.06.2025	7608	Maint & repairs	500hrs service, repairs to batteries, replacement of fire ext	Next svc 8100 hrs
22.01.2026	7807	Maint & repairs	Carry Inspection for start up	Next svc 8600 hrs
04.05.2026	8143	Maint & repairs	2000hrs service, replacement batteries/FE	Next svc 8600 hrs
10.09.2026	8627	Maint & repairs	500hrs service repairs to quitch cyl	Next svc 9050