**SERVICE & REPAIR RECORDS**

| Plant / Equipment Service & Repair Records | | | |
|---|---|---|---|
| **Make:** | Manitou | **Type:** | Plant |
| **Model:** | MT1030S | | |
| **Rego / Serial #:** | | **Year of Manufacture:** | |

| Date of Service / Repaired | Km / Hours | Service Type | Repairs Conducted | Comments |
|---|---|---|---|---|
| 08/08/2022 | 8556 | Inspection | Replace alternator belt, tighten fan belts, replace door strap, adjust door so it closes right, repair hand break missing mount bolts, adjust hand break, fit 2way radio | |
| 27/03/2024 | 8818 | Major Maintenance | See maintenance record | |
| 27/03/2024 | 8818 | General Maintenance | | Next Service Due - 9300 |
| 02.08.24 | | Maint | Switch On Transmission leaking – Replacement required | WO 1751 |
| 26.08.24 | | Maint | Drive Belt Issue – Replaced | WO 1782 |
| 29.08.24 | | Maint | Re-Install Belt & Pulley & adjust | WO 1782 |
| 11.09.24 | | Maint | Remove & Replace Top & Bottom Rad Hoses – Replace Coolant | WO 1825 |
| 17.01.2025 | | Maint | Bleed brakes air in system | WO 2219 |
| 19.03.2025 | | Maint | Replace brake master cyl & bleed | WO 2294 |
| 21.05.205 | | Annual service & repairs | Replaced engine oil, filter & rekitted front stabalizer cyl | WO2467 |
| 25.11.2025 | | Maint | Repairs to leaking hoses on bool ext | 0003 |
| 19.03.2025 | | Maint | Coolant leaking replaced heater hose on engine | 0109 |
| 04.10.2026 | | Maint | Non start replaced S/motor | 1329 |

## SERVICE & REPAIR RECORDS

| Date of Service / Repaired | Km / Hours | Service Type | Repairs Conducted | Comments |
|---|---|---|---|---|
| | | | | |