



E02-9

DONE JUN 16, 2025

April 23, 2025

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the U.S. Clean Air Act, California Health & Safety Code, and Canadian Environmental Protection Act, 1999, as applicable.

Our records indicate that you possibly own a product that requires an emissions recall. Please refer to the attached table for engines that may be affected by this issue.

Cummins Inc. has launched a campaign that may affect your Model Year 2024 X15 engine. Your engine may have a calibration where your engine may not comply with current emissions regulations. This campaign will provide an updated engine software calibration that will bring your engine into compliance. The parts and labor for this repair will be provided to you at no cost.

California residents: The State of California may require the completion of emission campaign repairs prior to vehicle registration renewal. Your Authorized Cummins Repair location will provide you with an Emission Campaign Proof of Correction Form after the campaign is performed. **Be sure to save this form since the California Department of Motor Vehicles may require that you supply it as proof that the campaign has been performed.** In order to ensure your full protection under the emission warranty provision, it is recommended that you have your engine serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your engine. Please help update our records if you have sold the engine to another owner with the included product registration card or by visiting <https://prodreg.cummins.com>.

This action is set to expire on March 27th, 2030. To learn more, confirm your eligibility and schedule a service appointment, please call your local Cummins certified service location or Cummins Care by visiting us on the web at <https://care.cummins.com> or you are welcome to contact us at 1-800-CUMMINS. If you have already had this recall performed, no further action is required. Please disregard this notification.

Sincerely,

Cummins Campaign Administration




April 23, 2025

HIRT'S VACUUM TRUCK SERVICES
BOX 775
HIGH LEVEL AB T0H 1Z0
CANADA

Engines eligible for the campaigns: CZ099

Engine Serial Number	Vehicle Model or OEM	Vehicle Identification Number
80624802		

Cummins Inc.
Box 3005
Columbus, IN 47202-3005 USA
Mail Code: 40911
Phone: 1 800 CUMMINS
care.cummins.com



WESTERN STAR & FREIGHTLINER TRUCKS of GRANDE PRAIRIE

Address: 7802 - 110 Street | Grande Prairie, AB T8W 1M3
Phone: 780-513-2236 | Toll Free: 1-866-388-7827 | Fax: 780-513-2846

Visit us online at www.wsnorth.com

Remit To: 24210 - 114 Avenue | Acheson, AB T7X 6B9

GST: R92297052

Invoice: 0020319659
Date / Hour: 6/17/2025 10:30:43AM
Repair Order: 19659
Customer: 4939
Branch: GRP
Total Invoice: \$0.00
Cash

Page 1 of 2

Bill To: HIRT'S VACUUM TRUCK SERVICES
BOX 775
HIGH LEVEL, AB T0H 1Z0

Ship To: HIRT'S VACUUM TRUCK SERVICES
BOX 775
HIGH LEVEL, AB T0H 1Z0
Email: beth_b12@yahoo.com

Customer P/O:

Add User: RAROBINSON

Open Date: 06/16/2025

Completion Date: 06/16/2025

Salesperson:

Unit Number: 21477

Model Year: 2025

Make/Model: WST 49X

Type: VACUUM UNIT

VIN: 5KKPBWFG5SPVP9866

Meter: 12068 Kilometers

In-Service Date: 09/18/2024

ECM Reading: 644

COLOUR: WHITE

FRONT AXLE: MFS-20-133A

REAR AXLE: RZ-166

SUSPENSION: AIR-69 - 55

Task: 1 60-100005.03 CUMMINS RECALL CAMPAIGN

600003

Department: SERVICE

Complaint: ENGINE SERIAL #
80624802

OPEN RECALL 7099

X15 CM2450 X142B ON-BOARD DIAGNOSTICS EMISSIONS CALIBRATION CAMPAIGN

Correction: RECALL

BROUGHT TRUCK INSIDE. HOOKED UP LAPTOP. FOUND SOFTWARE UPDATES AVAILABLE. PROGRAMMED TO LATEST.
NN10082.05 ORIGINAL. NN10082.08 CURRENT. RECALL COMPLETED

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SS SVC	SHOP SUPPLIES		1.0	\$9.07	\$9.07

Detail Tax Info:

Total Parts:	\$0.00
Total Labor:	\$0.00
Invoice Subtotal:	\$0.00
Total Tax:	\$0.00
Total Invoice:	\$0.00

Payment Method

Terms

Due Date

Cash

ON RECEIPT

6/17/2025

Remit To:

WESTERN STAR & FREIGHTLINER TRUCKS OF GRP
24210 - 114 AVENUE


ACHESON, AB T7X 6B9

Paid With: Cash

Amount Due: \$0.00

Amount Received: \$0.00

Chg Due: \$0.00



**WESTERN STAR & FREIGHTLINER TRUCKS
of GRANDE PRAIRIE**

Address: 7802 - 110 Street | Grande Prairie, AB T8W 1M3
Phone: 780-513-2236 | **Toll Free:** 1-866-388-7827 | **Fax:** 780-513-2846

Visit us online at www.wsnorth.com

Remit To: 24210 - 114 Avenue | Acheson, AB T7X 6B9

GST: 892297052

Invoice: 0020319659
Date / Hour: 6/17/2025 10:30:43AM
Repair Order: 19659
Customer: 4939
Branch: GRP
Total Invoice: \$0.00
Cash

Page 2 of 2

Bill To: HIRT'S VACUUM TRUCK SERVICES
BOX 775
HIGH LEVEL, AB T0H 1Z0

Ship To: HIRT'S VACUUM TRUCK SERVICES
BOX 775
HIGH LEVEL, AB T0H 1Z0
Email: beth_b12@yahoo.com

Customer P/O:

Add User: RAROBINSON

Open Date: 06/16/2025

Completion Date: 06/16/2025

Salesperson:

HAVING AUTHORIZED REPAIRS TO MY (OUR) MOTOR VEHICLE, AND(OR) AUTHORIZED PART(S) PURCHASES, I (WE) HEREBY ACKNOWLEDGE MY (OUR) INDEBTEDNESS TO: WESTERN STAR TRUCKS (NORTH) LTD.

IN THE SUM OF \$ 0.00 BEING ALL OR THE BALANCE OF THE ACCOUNT FOR SAID WORK.

DATE: _____ X _____ ERRORS AND OMISSIONS EXCEPTED

***** EMAIL IN NOW AVAILABLE * NO RETURNS ON ELECTRICAL * CORES MUST BE RETURNED IN 90 DAYS FOR CREDIT *****

***** EACH REPAIR TASK HAS BEEN INSPECTED FOR QUALITY AND FUNCTION VERIFIED - IF YOU ARE NOT COMPLETELY SATISFIED, PLEASE CONTACT DEPARTMENT MANAGER *****

IMPORTANT RECALL NOTICE

CAMPAIGN: F1020-A



SUBJECT: Positive Junction Post

This notice applies to your vehicle.

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act

If you no longer own this vehicle or need to inform us of other changes, please note them below then sign and return this form in the enclosed business reply envelope.

SAFETY RECALL / RAPPEL SÉCURITÉ

1830
105398



HIRT'S VACUUM TRUCK SERVICES
PO BOX 775
HIGH LEVEL, AB T0H 1Z0
CANADA

UNIT 34
COMBO UNIT
DONE 1/20/2025

Reason
for Change

Vehicle
Identification Number

5KKPBWFG5SPVP9866

Current Owner



Address

Signature

Date

IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s), see enclosed VIN list.

June 2025

F1020

Transport Canada #2025-269

Subject: Positive Junction Post

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Daimler Truck North America LLC (DTNA), on behalf of its wholly owned subsidiary, Western Star Truck Sales, Inc., has decided that a defect, which relates to motor vehicle safety, exists in certain model years 2020-2026 Western Star 47X, and 49X vehicles. See below for additional details:

Make	Model	Model Yr. Start	Model Yr. End	Prod. Start Date	Prod. End Date
Western Star	47X	2022	2026	September 14, 2021	May 14, 2025
Western Star	49X	2020	2026	August 12, 2019	May 8, 2025

A stud connecting the battery to the starter at the frame rail may have been installed incorrectly. This may result in a short circuit, increasing the risk of a vehicle fire.

A Daimler Truck North America authorized service facility will inspect and replace damaged cables, tighten loose hardware and, install dielectric paint. The Recall will take approximately one hour and will be **performed free of charge**.

Please contact an authorized Daimler Truck North America dealer to arrange to have the Recall performed and to ensure that parts are available.

To locate an authorized dealer, go to <https://northamerica.daimlertruck.com/brands/support>. At the bottom of the page click on the appropriate brand (shown as an icon), and at the top of each brand's page is an option to 'Find a Dealer'.

You may also confirm your vehicle's involvement in this recall at the following URL:
<https://dtna-dlrinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, ~~please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist~~ us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within ten days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7 a.m. to 4 p.m. Pacific Time, Monday through Friday, e-mail address dtna-war-campaigns@daimlertruck.com. For other concerns, you may contact the Customer Assistance Center at (800) 385-4357. If you have a safety concern relating to this Recall, you may wish to contact Transport Canada – Motor Vehicle Safety at, 80 rue Noel, Gatineau, Quebec J8Z 0A1 or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure

RAPPEL DE SÉCURITÉ IMPORTANT

Le présent avis s'applique à votre (vos) véhicule (s), voir la liste des NIV ci-jointe.

juin 2025

F1020

Transports Canada #2025-269

Objet : Poteau de jonction positif

Le présent avis vous est envoyé conformément aux exigences de la Loi sur la sécurité automobile. La présente vise à vous informer que votre véhicule peut contenir un défaut qui pourrait nuire à la sécurité d'une personne.

Daimler Truck North America LLC (DTNA), au nom de sa filiale à part entière, Western Star Truck Sales, Inc., a décidé qu'il existe un défaut relatif à la sécurité des véhicules automobiles dans certains véhicules des années de modèle 2020-2026 Western Star 47X et 49X. Voir ci-dessous pour plus de détails :

Faire	Modèle	Début de l'année de modèle	Fin de l'année modèle	Date de début de la production	Date de fin de production
Western Star	47X	2022	2026	14 septembre 2021	14 mai 2025
Western Star	49X	2020	2026	Le 12 août 2019	8 mai 2025

Il se peut qu'un goujon reliant la batterie au démarreur situé sur le rail du cadre ait été mal installé. Cela peut entraîner un court-circuit, ce qui augmente le risque d'incendie d'un véhicule.

Une installation de service autorisée par Daimler Truck North America inspectera et remplacera les câbles endommagés, serrera la quincaillerie desserrée et installera de la peinture diélectrique. Le rappel prendra environ une heure et sera **effectué gratuitement**.

Veuillez communiquer avec un concessionnaire autorisé de Daimler Truck North America afin de faire effectuer le rappel et de vous assurer que les pièces sont disponibles.

Pour trouver un concessionnaire autorisé, rendez-vous à l'adresse <https://northamerica.daimlertruck.com/brands/support>. Au bas de la page, cliquez sur la marque appropriée (illustrée sous forme d'icône) et, en haut de la page de chaque marque, vous trouverez l'option « Trouver un concessionnaire ».

Vous pouvez également confirmer la participation de votre véhicule à ce rappel à l'adresse suivante : <https://dtna-dlrinfo.prn.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

Vous pourriez être responsable de tout dommage progressif résultant de votre omission de terminer le rappel dans un délai raisonnable après avoir reçu l'avis.

~~Si vous n'êtes pas propriétaire du véhicule correspondant au (x) numéro (s) d'identification figurant sur l'avis de rappel,~~ veuillez retourner l'avis au Service des campagnes de garantie avec tous les renseignements que vous pouvez fournir pour nous aider à localiser le propriétaire actuel. Si vous avez loué ce véhicule, la loi fédérale exige que vous transmettiez cet avis au locataire dans les dix jours. Si vous êtes un fabricant subséquent, la loi fédérale exige que vous transmettiez cet avis à vos distributeurs et points de vente au détail dans un délai de cinq jours ouvrables.

Si vous avez des questions au sujet de ce rappel, veuillez communiquer avec le Service des campagnes de garantie au (800) 547-0712, de 7 h à 16 h, heure du Pacifique, du lundi au vendredi, à l'adresse courriel dtna-war-campaigns@daimlertruck.com. Pour toute autre question, vous pouvez communiquer avec le Centre d'assistance à la clientèle au (800) 385-4357. Si vous avez des préoccupations en matière de sécurité relativement à ce rappel, vous pouvez communiquer avec Transports Canada — Sécurité des véhicules automobiles au 80, rue Noel, Gatineau (Québec) J8Z 0A1 ou téléphoner au (800) 333-0510.

Nous regrettons tout inconfort que cette mesure pourrait causer, mais nous sommes certains que vous comprenez notre intérêt pour la sécurité des véhicules automobiles.

IMPORTANT RECALL NOTICE

CAMPAIGN: F1029-G



SUBJECT: Western Star Positive Junction Post

This notice applies to your vehicle.

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act

If you no longer own this vehicle or need to inform us of other changes, please note them below then sign and return this form in the enclosed business reply envelope.

SAFETY RECALL / RAPPEL SÉCURITÉ

376
117424



HIRTS VACUUM TRUCK SERVICES
PO BOX 775
HIGH LEVEL, AB T0H 1Z0
CANADA

RECEIVED JUN 03 2026

*DONE
SPT. 03, 2026*

Reason
for Change

Vehicle
Identification Number

5KKPBWFG5SPVP9866

*COMBID STEAM JAC
UNIT 54*

Current Owner



Address

Signature

Date

IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s), see enclosed VIN list.

May 2026

Campaign #F1029

Transport Canada #2026-054

Subject: Western Star Positive Junction Post

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Daimler Truck North America LLC (DTNA), on behalf of its wholly owned subsidiary, Western Star Truck Sales, Inc., has decided that a defect, which relates to motor vehicle safety, exists in certain model years 2020-2027 Western Star 47X, and 49X vehicles. See below for additional details:

Make	Model	Model Year Start	Model Year End	Production Start Date	Production End Date
Western Star	47X	2022	2027	September 14, 2021	February 3, 2026
	49X	2021	2027	June 29, 2020	January 30, 2026

In the affected vehicles, the stud connecting the battery to the frame rail may fail due to incorrect installation or corrosion. If the stud fails, there is an increased risk of a short circuit and vehicle fire. Drivers may experience a slow or no crank when starting their vehicle.

A Daimler Truck North America authorized service facility will remove the positive junction post and the jump start provision will be moved to an alternate location. The Recall will take approximately two hours and will be **performed free of charge**.

Please contact an authorized Daimler Truck North America dealer to arrange to have the Recall performed and to ensure that parts are available.

To locate an authorized dealer, go to <https://northamerica.daimlertruck.com/brands/support>. At the bottom of the page click on the appropriate brand (shown as an icon), and at the top of each brand's page is an option to 'Find a Dealer'.

You may also confirm your vehicle's involvement in this recall at the following URL:

<https://dtna-dlrinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within ten days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7 a.m. to 4 p.m. Pacific Time, Monday through Friday, e-mail address dtna-war-campaigns@daimlertruck.com. For other concerns, you may contact the Customer Assistance Center at (800) 385-4357. If you have a safety concern relating to this Recall, you may wish to contact Transport Canada – Motor Vehicle Safety at, 80 rue Noel, Gatineau, Quebec J8Z 0A1 or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

Rappel de sécurité important

Le présent avis s'applique à votre (vos) véhicule (s), voir la liste des NIV ci-jointe.

Mai 2026

Campagne #F1029

Transports Canada #2026-054

Objet : Poteau de jonction positif Western Star

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*. La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

Daimler Truck North America LLC (DTNA), au nom de sa filiale à part entière, Western Star Truck Sales, Inc., a décidé qu'il existe un défaut relatif à la sécurité des véhicules automobiles dans certains véhicules des années de modèle 2020-2027 Western Star 47X et 49X. Voir ci-dessous pour plus de détails :

Faire	Modèle	Début de l'année de modèle	Fin de l'année modèle	Date de début de la production	Date de fin de production
Western Star	47X	2022	2027	14 septembre 2021	3 février 2026
	49X	2021	2027	29 juin 2020	30 janvier 2026

Dans les véhicules touchés, le goujon reliant la batterie au rail du châssis peut se rompre en raison d'une installation incorrecte ou d'une corrosion. Si le goujon tombe en panne, il y a un risque accru de court-circuit et d'incendie du véhicule. Les conducteurs peuvent faire face à une manivelle lente ou à l'absence de manivelle lorsqu'ils démarrent leur véhicule.

Une installation de service autorisée par Daimler Truck North America retirera le poteau de jonction positif et la disposition de démarrage rapide sera déplacée vers un autre endroit. Le rappel prendra environ deux heures et sera **effectué gratuitement**.

Veuillez communiquer avec un concessionnaire autorisé de Daimler Truck North America afin de faire effectuer le rappel et de vous assurer que les pièces sont disponibles.

Pour trouver un concessionnaire autorisé, rendez-vous à l'adresse <https://northamerica.daimlertruck.com/brands/support>. Au bas de la page, cliquez sur la marque appropriée (illustrée sous forme d'icône) et, en haut de la page de chaque marque, vous trouverez l'option « Trouver un concessionnaire ».

Vous pouvez également confirmer la participation de votre véhicule à ce rappel à l'adresse suivante : <https://dtna-dlrinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>.

Vous pourriez être responsable de tout dommage progressif résultant de votre omission de terminer le rappel dans un délai raisonnable après avoir reçu l'avis.

Si vous n'êtes pas propriétaire du véhicule correspondant au (x) numéro (s) d'identification figurant sur l'avis de rappel, veuillez retourner l'avis à la garantie Campagnes Department avec tous les renseignements que vous pouvez fournir qui nous aideront à localiser le propriétaire actuel. Si vous avez loué ce véhicule, la loi fédérale exige que vous transmettiez cet avis au locataire dans les dix jours. Si vous êtes un fabricant subséquent, la loi fédérale exige que vous transmettiez cet avis à vos distributeurs et points de vente au détail dans un délai de cinq jours ouvrables.

Si vous avez des questions au sujet de ce rappel, veuillez communiquer avec le Service des campagnes de garantie au (800) 547-0712, de 7 h à 16 h, heure du Pacifique, du lundi au vendredi, à l'adresse courriel dtna-war-campaigns@daimlertruck.com. Pour toute autre question, vous pouvez communiquer avec le Centre d'assistance à la clientèle au (800) 385-4357. Si vous avez des préoccupations en matière de sécurité relativement à ce rappel, vous pouvez

**Daimler Truck
North America LLC**

Daimler Truck North America LLC
Service des campagnes de garantie
C.P. 4090
Portland, OR 97208-4090
800.547.0712 Téléphone

communiquer avec Transports Canada — Sécurité des véhicules automobiles au 80, rue Noel, Gatineau (Québec) J8Z 0A1
ou téléphoner au (800) 333-0510.

Nous regrettons tout inconvénient que cette mesure pourrait causer, mais nous sommes certains que vous comprenez
notre intérêt pour la sécurité des véhicules automobiles.

SERVICE DES CAMPAGNES DE GARANTIE

Enceinte



Invoice

Specializing in Truck, Trailer & Heavy Equip A/C & Repair Service.
 Box 90 La Crete, AB T0H 2H0
 Phone 780-928-3406 Fax 780-928-4141
 Email Mike@schellhe.ca
 Your One STOP Inspection Shop



Date	Invoice #
2026-08-24	204507

Invoice To: Hirts Vacuum Truck Service Box 775 High Level, AB T0H 1Z0
--

Rep

JF

Make: Westernstar Yr: 2024 Unit: 54 Km: 23256 Hr: 796 Vin: 5KKPBWFG5SPVP9866 Esn: 80624802	voice
P.O. No.	S/O 01980285

Item	Qty	Description	Rate	Amount	Tax
Labour	15	Recharge dead batteries. Diagnose no start. Connect laptop to check fault codes, - 2468, - 4484, - 6255 and 559 active. Reset tripped positive air shut off, - still no start, - not getting fuel rail pressure. Go through no start troubleshooting steps in Guidanz, - found fuel rail relief valve leaking which was not in Guidanz troubleshooting steps. Replace relief valve and sealing washer, - start engine while monitoring fuel rail pressure in insight, - fuel rail pressure way higher then commanded, - blew the pump to rail line off at the rear fuel pump head, - fault code 553 now active. Troubleshoot fault code - 553. Replace damaged fuel line and fuel pump actuator. Start engine and monitor fuel rail pressure, - commanded and measured pressures now in spec. Fault codes all inactive. Clear inactive fault codes. GST On Sales	120.00	1,800.00	G
			5.00%	167.12	

Thank You For Your Business	Subtotal	\$3,342.47
	Total	\$3,509.59

GST/HST No. 846514974 Please Sign

A service charge of 2% per month will be added on accounts 30 days or more past due. These items remain the property of Schellenberg Heavy Equipment until fully paid. All returns must be made within 7 days along with a copy of the invoice. A restocking fee may apply as per return policy.

DAIMLER TRUCK

North America

N.V.I.S / D.V.N.

New Vehicle Information Statement
Description du véhicule neuf

Vehicle / Véhicule

* Vehicle Identification Number / Numéro d'identification du véhicule					Plate or Registration N° / N° de plaque d'immatriculation		
5KKPBWFG5SPVP9866							
* Make / Marque		* Model / Modèle		Series / Série	* Model Year / Année du modèle	* Color / Couleur	* Body Type / Type de carrosserie
WESTERN STAR		WJ121086S			2025	WHI/BLA	TRACTOR
No. of Cyl / Nombre de cyl		* Motive Power / Force motrice	* Shipping Weight (kg) Masse nette	* G.V.W.R (kg) P.N.B.V.	* Wheelbase (mm) Empattement	OFFICE USE ONLY / À L'USAGE DU BUREAU	
6		DIESEL	11585	39916	7779		
Engine Serial No. (if applicable) / N° de série du moteur (si applicable)					Displacement / Cylindrée	* Off Road Vehicle / Véhicule Hors- Route	
80624802						yes/oui ☐ no/non ☒	
Manufacturer's Comments / Commentaires du fabricant							

Manufacturer or Importer / Fabricant ou importeur

Name and Location / Nom et adresse Daimler Truck Canada Ltd, Mississauga, Ontario.	N.S.M. / M.N.S. No.
Final Stage Manufacturer - Name and Location / Dernier fabricant - Nom et adresse	

Dealer / Commerçant

I, the undersigned, authorized representative of the company, firm or corporation named below, hereby certify that the new vehicle herein described is assigned on this date for registration and certify that the vehicle is new and has not been registered previously.

Je soussigné, représentant autorisé de la compagnie, firme ou corporation désignée ci-dessous, déclare par la présente que le véhicule neuf ci-décrit est cédé à cette date, afin d'être immatriculé, et je certifie que ce véhicule est neuf et qu'il n'a pas été immatriculé précédemment.

* Name / Nom		Province / Terr.	Dealer's N° / N° du commerçant
WESTERN STAR TRUCKS NORTH LTD.		ALBERTA	41C3
Authorized Signature Signature autorisée	Print First Name and Surname Nom et prénom en lettres moulés	Date of Sale / Date du vente Yr./ An. M/ M. D/ J	Odometer Reading Kilomètres au compteur
	COREY BILYK		

Purchaser or Lessor (if applicable) / Acheteur ou Locateur (si applicable)

Name (Surname, First Name) / Nom (nom de famille, prénom)			
Address (No., Street, Apt.) / Adresse (No, Rue, App.)			
City - Municipality / Ville - Municipalité	Province / Terr.	Postal code / Code postal	Phone Number / Numéro de tél.

Lessee (if applicable) / Locataire (si applicable)

Name (Surname, First Name) / Nom (nom de famille, prénom)			
Address (No., Street, Apt.) / Adresse (No, Rue, App.)			
City - Municipality / Ville - Municipalité	Province / Terr.	Postal code / Code postal	Phone Number / Numéro de tél.

This is not a titling document / Ce document ne constitue pas un titre de propriété

Personal information must be used in accordance with applicable privacy laws / Renseignements personnels qui ne doivent être utilisés qu'en conformité avec les lois sur la confidentialité.



HIRT'S VACUUM TRUCK SERVICE LTD. —

Founded in 1995 by Gerhard Hirt

P.O. Box 775 High Level Alberta TOH 1Z0

Tel. #: (780) 926 - 4568; Cell #: (780) 926 - 0835; Fax #: (780) 926 - 5643

E-mail: beth_b12@yahoo.com; admin@hirtsvac.com

Webmail: <https://www.hirtsvac.com>

2025 WESTERN STAR COMBO (STEAMER & VAC) VIN # 5KKPBWFG5SPVP9866

1. UNIT 54 REGISTRATION COPY OF ORIGINAL
2. UNIT 54 INSURANCE - PINK CARD 2026-01-13
TO 2027-01-13
3. UNIT 54 CVIP October 2026
4. UNIT 54 SAFETY RECALL Combo Unit Engine #
80624802_Emissions Recall DONE JUNE 16, 2025
5. UNIT 54 SAFETY RECALL DONE JULY 30, 2025
6. UNIT 54 SAFETY RECALL DONE SEPT. 03, 2026
7. UNIT 54 SCHELLENBERG HEAVY EQUIPMENT
INV # 204507 AUG. 24, 2026 DEAD BATTERY
8. UNIT 54 PURGE TICKET # 38417
9. UNIT 54 VEHICLE INFORMATION STATEMENT
10. UNIT 54 TRUCK MANUAL
11. DEPLICATE KEY IN THE BLACK BINDER (2)

RECEIVED BY:

DATE: