KINETIC TRANSPORT LTD.

Work Order

Work Order #: 7335
Date: Aug/28/2025
Unit #: 332

KM's: 391937
Hr's: 6431

Description of Defect	Description of Repair	Mechanic	HRS
CEL ON	Found # 6 Injector fault - Replaced all 6 Injectors with new. Updated software. All completed under warranty on Invoice # PR69152	Stahl Peterbilt	

Follow Up Notes:

KINETIC TRANSPORT LTD.

Work Order

Work Order #: 8803
Date: Jul/29/2026
Unit #: 332

KM's: 443,534 km
Hr's: 7,614

E11-1

Description of Defect	Description of Repair	Mechanic	HRS
Inspect Clutch	Remove/Replaced clutch w/New	Kaya	16
Windshield Damaged	Replaced with new on Invoice # 8844-7225181	Standard Auto Glass	
Replace master cyclinder	Replaced w/New	Kaya	0.5
Replace servo	Replaced w/New	Kaya	1
Replace driveline bolts	Replaced w/New	Kaya	1
Replace hyd. line for clutch	Replaced w/New	Kaya	1
P/S rear mudflap missing	Replaced flaps and brackets	Kaya	0.5

Follow Up Notes: