# RITCHIE BROS. Auctioneers Diagnostic Report

## 2008 International DuraStar 4400

### Test Information

| | |
|---|---|
| **Engine** | International DT466/Maxxforce DT (7.6) |
| **Engine Serial** | INT *466224240711696M07*5005251853-- |
| **VIN** | 1HTMSAARX8H676390 |
| **Driveline** | Class 8 6x4 |
| **Body** | Truck |
| **Test Time** | Nov. 19, 2026, 11:08 a.m. |
| **File Length** | 33.968 s |

### Usage

| Label | Value | Units |
|---|---|---|
| Engine Odometer | 191,892 | mi |
| Engine Total Hours of Operation | 18,290.8 | h |

### Engine On/Off

Engine running

### Check Engine Light

No check engine lights on

### Emissions Deleted/Tampered

No

### Faults

| DM | Controller Name | SPN Name | FMI Name | Count |
|---|---|---|---|---|
| Previous | Brakes - System Controller | J1939 Network #1. Primary Vehicle Network | Failure | 1 |
| Previous | Instrument Cluster #1 | Source Address 33 | Abnormal Update Rate | 115 |
| Previous | Body Controller | Wiper Motor | Current Above Normal | 2 |
| Previous | Body Controller | Operator Input device for Cab Climate Control | Erratic, Intermittent, or Incorrect | 5 |
| Previous | Body Controller | Disengage Differential Lock Request - Central Rear | Erratic, Intermittent, or Incorrect | 12 |
| Previous | Body Controller | Source Address 0 | Data Error | 8 |
| Previous | Body Controller | Headlamp Low Beam Left #1 | Current Below Normal | 1 |
| Previous | Body Controller | Headlamp 1 High Beam | Current Below Normal | 12 |
| Previous | Body Controller | Source Address 23 | Abnormal Update Rate | 1 |
| Previous | Body Controller | Cab Dome Light 1 | Current Above Normal | 126 |
| Previous | Body Controller | Brake Switch | Erratic, Intermittent, or Incorrect | 8 |
| Previous | Body Controller | Manufacturer Assignable SPN | Current Above Normal | 7 |
| Previous | Body Controller | Cab HVAC System Controller | Abnormal Update Rate | 2 |
| Previous | Body Controller | Manufacturer Assignable SPN | Erratic, Intermittent, or Incorrect | 1 |
| Previous | Body Controller | Cab HVAC Mode Control Actuator | Erratic, Intermittent, or Incorrect | 1 |
| Previous | Body Controller | Headlamp Low Beam Right #1 | Current Below Normal | 126 |