



Spark N Wrenches

650 Sunrise Road

Box 309

Nampa, AB T0H2R0

780-624-5551

integratirepr@outlook.com

GST Tax ID# 760902882RT0001

Invoice

Bill To [REDACTED]

AB

Canada

Home [REDACTED]

Email [REDACTED]

Invoice # 10428

Work Order # 10480

Service Advisor [REDACTED]

Technician [REDACTED]

Vehicle 2007 Toyota Tundra

VIN 5T8BV581975484836

License # [REDACTED]

Engine 5.7 Litre

Kilometres 309963

Invoice Date 9/28/2026 8:26 AM

H11-1

Service

Disc Brake Pads, Rotors & Calipers (Front)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Replaced Front Rotors and pads	2.0 5Hour	\$165.00 / Hour	\$338.25 *G
Replaced Front calipers as they were seized			
Bleed brakes front end			
Disc Brake Pad	1 Unit	\$125.52 / Unit	\$125.52 G
Disc Brake Rotor	2 Unit	\$223.72 / Unit	\$447.44 G
Disc Brake Caliper	1 Unit	\$279.59 / Unit	\$279.59 G
Brake fluid Dot 3 4L jug	0.4 Litre	\$14.07 / Litre	\$5.63 G
		Sub	\$1,196.43

Disc Brake Pads, Rotors & Calipers (Rear)

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Replaced Rear Rotors and Pads	1.8 Hour	\$165.00 / Hour	\$297.00 *G
Lubricated calipers			
Disc Brake Pad	1 Unit	\$106.03 / Unit	\$106.03 G
Disc Brake Rotor	2 Unit	\$174.61 / Unit	\$349.22 G
Disc Brake Caliper	1 Unit	\$279.59 / Unit	\$279.59 G
		Sub	\$1,031.84

Total Parts		\$1,593.02
Total Labor		\$717.75
Total Before Taxes & Miscellaneous Charges		\$2,310.77
(*) Shop Supplies		\$14.36 G
(G) Canadian Goods and Services Tax (GST)	5 %	\$116.26
Grand Total		\$2,441.39