Mid-Valley Drivetrain & Truck Repair Ltd.
#5-32860 Mission Way
Mission, B.C. V2V 5X9
(604) 826-4031

INVOICE

Invoice No.: 11478
Date: 03/09/26

Sold to:

[redacted]

KENWORTH
UNIT #HT-01 VIN #960656
KM 423667

Business No.: 852994268 RT0001

Item No.	Quantity	Description	Tax	Unit Price	Amount
4410309102	1	ABS Sensor	GP	105.35	105.35
6382093RX	1	Turbo Actuator Kit	GP	3,020.95	3,020.95
Labour	4	Troubleshoot ABS codes, found faulty sensor axle #3 left. Remove wheels & drum, replace sensor, reinstall wheels & drum . Troubleshoot derate codes. Many codes for failed turbo actuator. Drain coolant, replace actuator & run program for installation. Refill coolant & road test truck. All codes went inactive .	GP	155.00	620.00
Shop	1	Shop Supplies	GP	120.00	120.00
		Subtotal:			3,866.30
		GP - GST @ 5%; PST @ 7%			
		GST			193.32
		PST			270.64

Terms: Net 30. Due 04/08/26.
Comment:

Total Amount	4,330.26
Amount Paid	0.00
Amount Owing	**4,330.26**