SERVICE SUMMARY HISTORY – HX226
2020 Volvo ECR145EL

Date	Job #	Hrs.	Service Description
14/08/2021		500	500hr service (CJD)
06/09/2022		1086	Carried out 100hr service
31/01/2023		1250	Replace belt on A/C Compressor (2 belts snapped previously. A/C Compressor was locking up and recording high pressures 300PSI on the high and 80PSI on the low.
08/02/2023		1281	Carried out 1250hr Service
17/07/2023		1560	Carried out 1500Hr Service
10/11/2023		1782	Carried out 1750hr service
23/04/2024		2013	Carried out 2000hr Service IMU AND GPS Repairs carried out by CJD (29/04/2024)
27/08/24		2394hrs	250 hr service
24/10/24		2577	500hr service
02/12/24		2793	750hr service
24/12/2024		2839	Carried out 250Hr Service
14/05/2025		3005	Carried out 1000 Hour Service
03/07/2025		3141	Communication Fault - Repairs completed by CJD
22/08/2025		3337	Carried out 250 Hour Service

SERVICE SUMMARY HISTORY – HX226
2020 Volvo ECR145EL