

L26-1
Nov

	9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Report UPPER COUPLER INSPECTION				QF-058	
	Tank S/N 10951		WO No SV-24647		Rev: 2		PAGE 1 OF 1	
Owner Rick's Oilfield Hauling 4606-51 Avenue Red Water, AB T0A 2W0 Phone No (780) 942-2025		Tank Mfr TREM CAR		Tank Spec TC 407 AL		Mr Date Nov 2012		Test Date APR 11-2024
		Assembler TREM CAR		Min Thickness Heads (in) 6.39 MM		Min Thickness Shell (in) 5.49 MM		Retest Required On APR. 2029
		Tank Type SUPER B LEAD		Certification Date Nov 2012		Special Services NO		Original Test Date Nov 2012
Tank is Linked		Tank is Insulated		Both		Inspection Location WESTLOCK		VIN 2TLBL4038DB005313
Owner's Serial No T168L		TCRN / MDIN / CRN 9246		Unit No T168L		MAWP 172 KPA		Material 5454-H32
Trailer Mfr TREM CAR		Trailer Material STEEL		Trailer Mfr Date Nov 2012				# Compartments ONE
PREPARATION	Complies	Concerns	Fails	Re-test after repair	VISUAL OF HIDDEN AREA	Complies	Concerns	Fails
1 Trailer Blocked	X				1 Corrosion	X		
2 Kingpin Gauge on Hand	X				2 Abrasion	X		
UPPER COUPLER	Complies	Concerns	Fails	Re-test after repair	3 Cracks	X		
1 Kingpin 90° ± 1° for 19"	X				4 Dents	X		
2 Upper Plate Not Down 1/3" at 10"	X				5 Distortions	X		
3 Upper Plate Not Down 1/4" at 19"	X				6 Weld Defects	X		
4 Upper Plate Not 0.65" within 19"	X				7 Other Weakness	X		
5 Loose or Missing Bolts	X				8 Repaired as Necessary	X		
6 Remove Upper Coupler	X				COMPLETION	Complies	Concerns	Fails
7 Replace Upper Coupler	N/A				1 Original Wabash File	X		
					2 Copies to Owner	X		

Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)

NO DEFECTS FOUND

Current Disposition of Trailer Coupler Tested:

Returned to Service ☒


Repair Required ☐

CERTIFICATE OF INSPECTION COMPLIANCE

We certify that the statements in this report are correct and the said unit has been inspected in accordance with
D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.

Wabash Mfg Inc - TC TDG Certificate of Registration #25-93

Inspector Signature



Name: MAURY LITKE

Title: INSPECTOR

Date: APR. 11-2024

L26-2
NOV

1361514 A.B. Ltd / Smithbuilt Ent.

Facility Registration Number 25-1019

EXTERNAL INSPECTION REPORT

Per B620-20 Section 7.2.1, and Smithbuilt Ent. QC Manual Section A4

Job No.:				Date:	September 14, 2026
Owner/Customer:	223786 Alberta Ltd			Phone No.:	780-942-2025
Address:	Box 979 Redwater A.B. T0A 2W0				
Tank Insp. Name:	Ryan Smith	Name of Helper:			
Make:	Tremcar	Model:	Super B Pup	V.I.N.	2TLBL312XDB005314
Unit No.:	T168P	KM:		Lic. Pl. No.:	5ZD5-87
Tank Manufacturer:	Tremcar	Tank Ser. No.	10952		
Tank Specification:	DOT 407 AL	TCRN/MDIN/CERT	11/2012		

COMMENTS	DESCRIPTION	PASS	FAIL	DEFECTS: Nature & Location
1	Certificate Plate Legible, Certificate Plate Properly Attached	X		
2	Tank Welds-undercut, leaks, cracks, etc., Tank Rollover Protection, Ring Stiffeners, Tank Stiffeners, Tank Damage, Dent 10% Deeper than length or 0.5" deep	X		
3	Tank Piping, Tank Piping, Mounting Flange & Hardware, Tank Piping, Mounting Brackets, Tank Safety Post	X		
4	Rear Door, Rear Door Hinge, Rear Door Pin-Wheels and Brackets, Rear Door Cylinder Brackets, Rear Door Valves	N/A		
5	Front Head Valves, Belly Valves	X		
	Hoist	N/A		
6	Manway Seals, Spillway Valves	X		
7	Hoist Brackets and Cradle, Cyclone, Cyclone Mounting Brackets, Moisture Trap	N/A		
8	Shut-off Valve & Mounting Hardware, Shut-off Valve Operates Properly / Emergency shut-Off (ect.)	X		
9	Tipping Hinge, Outriggers, Decking, Attaching Hardware	X		
10	Hoses and hose assemblies, Defects/markings	N/A		
11	Hydraulic Tank, Hydraulic Tank Frame	N/A		
12	Blower Frame / Pump Frame, Silencers, Silencer Attaching Hardware	N/A		
13	Tank Pressure Relief Valves	X		
14	Bumper	X		
15	Float Bowl Bushing	X		
16	Front Pedestals, Rear Pedestals, Full Length Pedestals	X		
	Visual Inspection "V"	X		
	Tank Removed from Service			
	Tank Returned to Service	X		

Comments: If inspection fails, give details regarding what failed and actions taken to ensure pass on re-inspection.

Tank Inspector: Ryan Smith
Name (Print)

Signature: 

Date: September 14, 2026

1361514 A.B. Ltd / Smithbuilt Ent.

Facility # 25-1019

LEAKAGE ☒ / PRESSURE ☐ / Upper Coupler ☐

Per B620-20 Section 7.2.5, and Smithbuilt Ent. QC Manual Section A4

Owner/Customer:	223786 Alberta Ltd			Date:	September 14, 2026
Address:	Box 979 Redwater A.B. T0A 2W0			Phone No.:	780-942-2025
Tank Insp. Name:	Ryan Smith	Name of Helper:			
Make:	Tremcar	Model:	Super B Pup	V.I.N.	2TLBL312XDB005314
Unit No.:	T168P	KM:			
Tank Manufacturer:	Tremcar	Tank Ser. No.	10952	Lic. Pl. No.:	5ZD5-87
Tank Specification:	DOT 407 AL	TCRN/MDIN/CERT	11/2012	Test Pressure:	20 Psi
				Test Medium:	Hydro

TEST PERSONNEL

Name:			
Name:			
Gauge	Serial No.:	1A02AQ5F522	


Prior to tank being filled with water:

1. Tank is sitting secure to floor.
2. Door Seal installed properly
3. Rear Door Blanking Flanges installed and torqued properly
4. Front Head Blanking Flanges installed and torqued properly
5. Top Blanking Flanges (Shell) installed and torqued properly
6. Pin Wheels installed and secured
7. Record Gauge Numbers, Make, and Model
8. Record Heat Numbers of Blanking Flanges
9. Gauges installed Shell area
10. Gauges installed Head area
11. Fill Tank with water
12. Prior to tank pressurization ensure that work area is secured and all non-essential personnel are removed from test area
13. Flag Hydro-test with signs and time for Start-up and Bleed-down
14. When Tank is at Full Pressure, remove Fill Line
15. Tank passed Hydro-test

CATAGOR Y	DESCRIPTION	PASS	FAIL	DEFECTS: Name & Location
1	Certificate Plate Legible, Certificate Plate Properly Attached	X		
2	Tank Piping, Mounting Flange	X		
3	Rear Door, Rear Door Seal, Rear Door Valves, Front Head Valves, Belly Valves, Manway Seals	X		
4	Shut-off Valve Operates Properly / and Emergency Shut-off	X		
5	Deck Piping	N/A		
6	Tank Pressure Relief Valves Door Seal	X		
7	Float Bowl Bushing	X		
8	Test Valves, Caps or Flanges	X		
9	Compartments 1, 2, 3, 4, & 5	X		
10	Upper coupler area / Upper coupler removed Y__N__	N/A		
	Pressure Test "P" / Leakage Test "K"	X		
	Tank Removed from Service			
	Tank Returned to Service	X		

Comments: If inspection fails, give details regarding what failed and action taken to ensure pass on re-inspection.

Tank Inspector: Ryan Smith
Name (Print)

Signature: 

Date: September 14, 2026

1361514 AB LTD./Smithbuilt Ent.

Facility # 25-1019

INTERNAL INSPECTION REPORT



Per B620-20 Section 7.2.2, and Smithbuilt QC Manual Section A4


Job No.:		Date:	September 14, 2026
Owner/Customer:	223786 Alberta Ltd		
Address:	Box 979 Redwater A.B. T0A 2W0	Phone No.	780-942-2025
Tank Insp. Name:	Ryan Smith	Name of Helper:	
Make:	Tremcar	Model:	Super B Pup
Unit No.:	T168P	V.I.N.	2TLBL312XDB005314
Tank Manufacturer:	Tremcar	KM:	
Tank Specification:	DOT 407 AL	Tank Ser. No.	10952
		TCRN/MDIN/CERT	11/2012
		Lic. Pl. No.:	5ZD5-87

COMMENTS	DESCRIPTION	PASS	FAIL
	Certificate Plate Legible	X	
	Certificate Plate Properly Attached	X	
	Tank Damage:	N/A	
	Dent 10% Deeper than length or 0.5" Deep	N/A	
	Internal Valves	X	
	Tank Corrosion According to Certificate Plate	X	
	Tank Baffles Properly Secured	X	
	Shut-off Ball Seat	N/A	
	Internal Repads on Valves	X	
	Internal Tank Shut-off Repads	X	
	Internal Weld Seams Long L1-L2-L3	X	
	Internal Tank Shell Circular C1-C2-C3	X	
	Tank Lining Line 1	N/A	
	Tank Lining Line 2	N/A	
	Tank Lining Line 3	N/A	
	Multi-Tank Divider Head(s) & Weld Seam(s)	N/A	
	Divider Head Valve(s)	N/A	
	Internal Ladder(s) & Repads	N/A	
	Internal Inspection "I"	X	
	Tank Scrapped		
	Tank Removed from Service		
	Tank Returned to Service	X	

Comments: If inspection fails, give details regarding what failed and action taken to ensure pass on re-inspection.

Tank Inspector: Ryan Smith
Name (Print)Signature: Date: September 14, 2026

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record PRESSURE TEST REPORT				QF-044 Rev: 6 Page 1 of 1			
				Tank S/N 10952		WO No SV-24063		Test Date OCT. 3- 2023			
Owner Rick's Oilfield Hauling 4606-51 Avenue Red Water, AB T0A 2W0		Mfr TREMCAR		Tank Spec TC 407 AL		Mfr Date Nov 2012		Retest Required On OCT. 2028			
		Assembler TREMCAR		Min Thickness, Heads (in) 5.97 mm		Min Thickness, Shell (in) 5.49 mm		Special Services NO			
Phone No (780) 942-2025		Tank Type SUPER B TAIL				Certification Date Nov 2012		Original Test Date Nov 2012			
Tank is Lined NO	Tank is Insulated YES	Both	Inspection Location WESTLOCK		VIN 2TLBL312XDB005314		Material SB209 A95454-H32				
Owners's Serial No. T168P		TCRN / MDIN / CRN 9240		Unit No T168P		MAWP 172 KPA		# Compartments ONE			
Test Pressure 40 PSI		Test Medium WATER									
PREPARATION		Complies N/A	Concerns	Fails	Re-test after repair	PIPING & ACCESSORIES		Complies N/A	Concerns	Fails	Re-test after repair
1. External & Internal visual (& thickness if required) done		X				1. Assemble hose and piping on unit		X			
2. Select proper gauges and SRV		X				2. Mount test head at top of piping		X			
3. Inspect reclosing vents, inert & red flag		X				3. Press to 80% MAWP & disconnect		X			
COMPARTMENT HYDRO TEST		Complies N/A	Concerns	Fails	Re-test after repair	4. Check for leaks & 10 min retention		X			
1. Mount test head at top. Visible from safe distance		X				5. Bleed off pressure & drain		X			
2. Fill test compartment		X				COMPLETION		Complies N/A	Concerns	Fails	Re-test after repair
3. Pressure up to Test pressure & disconnect hose		X				1. Flush per 300WP		X			
4. Check for leaks &/or 10min retention/Bleed of pressure to MAWP/10min retention		X				2. Tag valve & placard if required		X			
5. Apply soap water, check for leak and/or Bleed off pressure		N/A				3. Sticker as appropriate		X			
6. Activate vent to confirm set pressure. Bleed off pressure & drain		X				4. Original Wabash file. Copies to owner		X			
PRV	Compartment 1	Compartment 2		PRV Test Report QF 046	MC330/331 / TC331/341/11/51/60 tanks only						
Make	FORT VALE			Completed and Attached? Y	1. Is tank QT or NQT		N/A				
Serial Number	1307964				2. Stress relieved after manufacture? (New Tanks)		N/A				
Set Pressure	30 PSI 12" HG				3. If applicable: Stress relief after repair?		N/A				
Compartment 3	Compartment 4	Compartment 5			Location:		N/A				
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)					4. Off-truck remote emergency shutdown?		N/A				
					TANK VOLUME (LITERS)		32,659				
Current Disposition of Tank Tested											
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☒ Condemned (removed from service) ☐											
CERTIFICATE OF INSPECTION COMPLIANCE											
We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.											
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93											
Inspector Signature 					Tester Signature 						
Name: MAURY LITKE					Name: MAURY LITKE						
Title: INSPECTOR					Title: INSPECTOR						
Date: OCT. 3- 2023					Date: OCT. 3- 2023						

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Report UPPER COUPLER INSPECTION				QF-058	
				Rev: 2		PAGE 1 OF 1			
Owner Rick's Oilfield Hauling 4606-51 Avenue Red Water, AB T0A 2W0 Phone No (780) 942-2025		Tank S/N 10952		WO No SV-24063		Test Date: OCT. 3- 2023			
		Tank Mfr TREMCAR		Tank Spec TC 407 AL		Mfr Date Nov 2012		Retest Required On OCT. 2028	
Assembler TREMCAR		Min Thickness, Heads (in) 5.97 mm		Min Thickness, Shell (in) 5.49 mm		Special Services NO			
		Tank Type SUPER B TAIL		Certification Date Nov 2012		Original Test Date Nov 2012			
Tank is Lined NO		Tank is Insulated YES		Both		Inspection Location WESTLOCK		VIN 2TLBL312XDB005314	
Material SB209 A95454-H32		Owners's Serial No. T168P		TCRN / MDIN / CRN 9240		Unit No T168P		MAWP 172 KPA	
# Compartments ONE		Trailer Mfr TREMCAR		Trailer Material STEEL		Trailer Mfr Date Nov 2012			
PREPARATION		Complies	Concerns	Fails	Re-test after repair	VISUAL OF HIDDEN AREA		Complies	Concerns
1. Trailer Blocked		X				1. Corrosion		X	
2. Kingpin Gauge on Hand		X				2. Abrasion		X	
UPPER COUPLER		Complies	Concerns	Fails	Re-test after repair	3. Cracks		X	
1. Kingpin 90° ± 1° for 19"		X				4. Dents		X	
2. Upper Plate Not Down 1/8" at 10"		X				5. Distortions		X	
3. Upper Plate Not Down 1/4" at 19"		X				6. Weld Defects		X	
4. Upper Plate Not 0.65" within 19"		X				7. Other Weakness		X	
5. Loose or Missing Bolts		X				8. Repaired as Necessary		X	
6. Remove Upper Coupler		X				COMPLETION		Complies	Concerns
7. Replace Upper Coupler		N/A				1. Original Wabash File		X	
						2. Copies to Owner		X	
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)									
Current Disposition of Trailer Coupler Tested:									
Returned to Service ☒					Repair Required ☐				
CERTIFICATE OF INSPECTION COMPLIANCE									
We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 									
Name: MAURY LITKE									
Title: INSPECTOR									
Date: OCT. 3- 2023									