



SLICK
INSPECTION LTD.
403-581-9887
Medicine Hat, AB

GSY OILFIELD TECHNOLOGIES INC.
226 VISTA CLOSE S.E.
MEDICINE HAT, AB, T1B 0C4
PH: 403-866-6888
SLICK INSPECTION LTD.
2038 12th AV, N.W
MEDICINE HAT, AB, T1C 2A7
PH: 403-581-9887

EQUIPMENT INSPECTION REPORT

Report: **26-755**

CLIENT: Brothers HDD		DATE: Sept 15 2026	
EQUIPMENT IDENTIFICATION: Picker Unit		UNIT #: 803	
MAKE: Hiab	MODEL: 211 EP-5 HIDUO	S/N: BL211HD00121	
CODES: OHSA, CSA Z150-98 & W59-18		LOCATION: Ritchie Bros, Nisku	

MAGNITIZATION		PARTICAL		PROCEDURE	
Method:	Yoke S.N 4483	Medium:	Magnaflux	Technique:	MT-3
Current:	Alternating (AC)	Type:	Grey Powder	Surface Cond:	Sand Blasted
Field:	Continuous	Application:	Bottle Puffer	Demagnification:	ASME V Art. 7
				Post cleaning:	Ardrox Cleaner

A full length inspection was conducted on the picker and outriggers. No indications were found at time of inspection. A certification sticker was placed on the unit after inspection.



INSPECTOR: Brent Ahrens

SIGNATURE: 

Inspector's Stamp

Brent Ahrens
CGSB Level II RT MT
ASNT Level II RT MT REG. # 5607



SLICK
INSPECTION LTD.
403-581-9887
Medicine Hat, AB

GSY OILFIELD TECHNOLOGIES INC.

226 VISTA CLOSE S.E.
MEDICINE HAT, AB, T1B 0C4
PH: 403-866-6888
SLICK INSPECTION LTD.
2038 12th AV, N.W
MEDICINE HAT, AB, T1C 2A7
PH: 403-581-9887

EQUIPMENT INSPECTION CHECKLIST

COMPONENTS	DEFECTS	OK	DEFECT IDENTIFICATIONS
Picker Model, S/N on Structure		✓	
Load Rating Chart		✓	
Load Indicator Device (LID)		✓	
Boom Angle Indicator		✓	
Boom Length Indicator		✓	
Outrigger Vertical Rams		✓	
Outrigger Boxes		✓	
Outrigger Extensions		✓	
Outrigger Pads		✓	
Outrigger Welds		✓	
Main Boom		✓	
1st Extension		✓	
2nd Extension		✓	
3rd Extension		✓	
4th Extension		✓	
Boom Rest Hook		✓	
Boom Section Wear Pads		✓	
Boom Head Sheaves		✓	
Rotating Frame Welds		✓	
Structure Members between outrigger box's		✓	
Deck		✓	
Holding Nuts and Bolts		✓	
Visual Control Elements		✓	
Other:			
Other:			

COMMENTS:

--