

| Date            | Maintenance Item       | Hours | Description                                                                                                                                                                                                                                                                                                                                                            |
|-----------------|------------------------|-------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| August 9 2025   | Work Lights            |       | Wire in 3 work lights, test                                                                                                                                                                                                                                                                                                                                            |
| August 14 2025  | Strainer, Air Filters  |       | Install fuel fill strainer, install new inner/outer air filters                                                                                                                                                                                                                                                                                                        |
| October 24 2025 | Brake Complaint        |       | Disassemble steering and brake valve, clean and reassemble brake valve, remove LH brake mechanism, remove lubrication tubes, buff and clean mating surfaces, silicone mating surfaces, install lube tubes, buff and clean LH brake mechanism, silicone surfaces and install brakes, adjust LH brake 15 clicks, disassemble RH brake mechanism, clean and install seals |
| October 25 2025 | Transmission Complaint |       | Disassemble shuttle valve in brake housing, install new valve, assemble brake housing, install brake housing, test run and check pressures, remove filter base and priority valve, disassemble priority valve, install priority valve and filter base                                                                                                                  |
| October 28 2025 | Reassembly, Wiring     |       | Remove fuel tank and seat frame, repair seat frame mount, modify brake plumbing to clear seat frame                                                                                                                                                                                                                                                                    |
| October 29 2025 | Transmission Service   |       | Drain transmission fluid, exchange transmission filter, clean mag strainer and mag plugs                                                                                                                                                                                                                                                                               |
| October 30 2025 | Reassembly             |       | Install floor panels with all new hardware, disassemble boom for mob                                                                                                                                                                                                                                                                                                   |
| November 4 2025 | Brake Complaint        |       | Diagnose park brake stuck on, adjust brakes, repair park brake linkage, diagnose no shift at idle, inspect brake booster leaks, verify oil level and quality                                                                                                                                                                                                           |
| November 8 2025 | Shift Complaint        |       | Exchange transmission pump, check transmission pressure, test hot & cold                                                                                                                                                                                                                                                                                               |

|                  |                             |      |                                                                                                                                                                                                                                                                                                                                                                |
|------------------|-----------------------------|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| November 27 2025 | DEMOB                       |      | Diagnose rough operation and loose hydraulic tank, inspect under carriage, adjust both tracks, repair broken track adjuster cover bolts, remove seat and repair cracked seat frame, repair seat back, repair work light harness at rear of machine, inspect and test unit, adjust brakes, repair leak at draw works control, repair coolant leak at water pump |
| December 4 2025  | Ether Injection             |      | Replace ether cannister and test                                                                                                                                                                                                                                                                                                                               |
| December 5 2025  | Exhaust, fuel fill strainer |      | Install fuel fill strainer, build and mock up exhaust system                                                                                                                                                                                                                                                                                                   |
| December 8 2025  | Shift Complaint             |      | Connect pressure gauges to test ports and check pressures, confirm shims required for modulating valve                                                                                                                                                                                                                                                         |
| December 12 2025 | Transmission Complaint      |      | Remove ROPS, disconnect electrical, remove fuel tank, remove gaurds, remove battery box and seat platform, remove RH brake actuator, disassemble brake, order parts, remove diff cover, buff and clean surfaces, silicone/paint cover, replace washers                                                                                                         |
| December 19 2025 | Priority Valve              |      | Remove transmission filter housing and priority valve from transmission, disassemble and inspect priority valve, remove excess shims and assemble, repair seat frame mount, install transmission top plate and linkages, install clutch linkages                                                                                                               |
| December 20 2025 | Transmission Complaint      |      | Tranny oil level low, hook up hauge to transmission filter housing, trans shifted normally, check brake adjustment, confirm trans pressures                                                                                                                                                                                                                    |
| December 31 2025 | Brake Adjustment/Leaks      |      | Adjust left brake and test, assemble remaining panels, repair exhaust leak at muffler, repair oil pan drain plug leak, repair hoses rubbing under seat frame                                                                                                                                                                                                   |
| January 21 2026  | PM#1                        |      | Completed PM#1                                                                                                                                                                                                                                                                                                                                                 |
| January 24 2026  | Leaks                       |      | Remove leaking fuel line, pressure test, clean up mating surfaces, install and test, remove leaking fuel tank drain valve and replace with new valve                                                                                                                                                                                                           |
| February 16 2026 | Ether Injection             | 3518 | Repaired ether aid button, notice engine has noticeable mis fire. Transmission slow to shift in cold, transmission suction screen plugged with clutch material.                                                                                                                                                                                                |

|                  |                 |      |                                                                             |
|------------------|-----------------|------|-----------------------------------------------------------------------------|
| February 18 2026 | Ether Injection | 3520 | Fix ether aid system, install right side up, need to wire switch seperately |
| March 23 2026    | PM#2            |      | Preformed PM#2                                                              |