

| Date             | Maintenance Item           | Hours | Description                                                                                                                                                                   |
|------------------|----------------------------|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| March 20 2025    | Initial Inspection         | 4038  | Deactivate melted shocker pass harness<br>Top up hydraulic oil<br>Diagnose joystick rocker fault                                                                              |
| April 11 2025    | Trunnion ball replacement  | 4181  | Pulled tilt cylinder had welders weld in trunnion ball. Left side tilt. Photo in equipment folder                                                                             |
| April 11 2025    | Right joystick replacement | 4181  | Exchange right joystick handle and test, Clear codes for joystick switch, Raise cab clean out and inspect under cab, Remove melted shocker pass harness                       |
| May 30 2025      | PM#2                       | 4263  | Engine oil, final drive oil, oil filter, fuel filters, cabin air, primary air, secondary air                                                                                  |
| June 9 2025      | Seat Slide                 | 4278  | Secure cab filter cover, Inspect undercarriage<br>Repair seat slide                                                                                                           |
| June 11 2025     | Cabin Air                  | 4300  | Install cabin fresh air filter and cage                                                                                                                                       |
| June 14 2025     | Derate                     |       | Diagnose and repair L04 codes and de-rate<br>Disassemble right blade angle cylinder rod end bushing, clear out grease grooves and passages. Assemble and grease bearing       |
| August 2 2025    | Undercarriage Disassembly  | 4324  | Remove all worn parts, tracks, rails, idlers, carrier rollers etc.                                                                                                            |
| August 5 2025    | Undercarriage Reassembly   | 4324  | Buff all mating surfaces, install carrier rollers, install bottom rollers                                                                                                     |
| August 6 2025    | Undercarriage Reassembly   | 4324  | Install final bottom rollers, install sprocket segments, torque all hardware to spec, torch old tracks for scrap                                                              |
| August 12 2025   | Undercarriage Reassembly   | 4324  | Assemble idlers and install, wrap new tracks, adjust tracks                                                                                                                   |
| December 4 2025  | Inspection                 |       | Assemble blade, inspect and test unit                                                                                                                                         |
| December 11 2025 | Horse cock keeper plate    |       | Install horse cock keeper plate and push arm keeper pins                                                                                                                      |
| January 5 2026   | Start Up                   | 4386  | Espar fired after I had block heater and charger on it a while. Started, installed blade. Pin plate needs modifications, pins in arms need modification and cotter pins.      |
| January 26 2026  | Tilt hose                  | 4458  | Tilt cylinder hose bleeding, replace hose with proper angle/butterfly fitting                                                                                                 |
| January 29 2026  | Tilt function              | 4472  | Blade pins iteself RH side, checked joystick/harness, found valveis stuck, oulled spool pilot valve stuck, cleaned and reinstalled                                            |
| February 27 2026 | Coolant Leak               | 4719  | Fill coolant system several jugs, run up to temp and leak check, raise cab and pressure up cooling system, repair rubbed thru hose on espar, top up coolant                   |
| March 10 2026    | RH Hyd. Motor Hose         | 4903  | Leak drained entire hyd. System, RH front final hose found to have, leak in flange fitting, parts ordered                                                                     |
| March 12 2026    | Hyd. Static Motor Hose     | 4905  | Installed flange fitting hose to hydrostatic motor, reinstall pans, covers, drop cab                                                                                          |
| March 12 2026    | PM#1                       | 4905  | Preformed PM#1                                                                                                                                                                |
| March 18 2026    | Cabin Air                  | 4970  | Replace cabin air and all associated hardware                                                                                                                                 |
| August 15 2026   | Once over                  | 5242  | Check all fluids, run and test for leaks, check all functions, repair a/c vent in cab, repair looses panels on right side of engine bay, repair ripper keeper pin backing out |