

Date	Maintenance Item	Hours	Description
April 30 2025	Inspection		Did a general inspection of the unit.
May 3 2025	General Maintainece	13393	Change final drive oils, change swing drive oils, change service intervals in monitor, pull hydraulic suction screen, inspect and clean, pull hydraulic return filter and inspect, variety PM#2 filters up to date and all fluids have life, repair seat slide mechanism, preform cycle time tests, preform hydraulic pump performance tests, verify relief pressures, repair bushings not taking grease, preform undercarriage inspection, drain bottom of fuel tank and water separator
May 5 2025	Coolant Leak	13393	Repaired a coolant leak at lower rad hose and topped up all fluids
May 7 2025	Multiple belt replacements		Replaced alternator belt, Replaced AC belt, Replaced Seat belt
May 10 2025	Roller Replacement	13,393	Replace two bottom rollers and adjust track
May 13 2025	Install GPS	13,397	Wire gps and test
May 15 2025	Final PDI		Clean out tool box, line up teeth and keepers for digging bucket Replace travel alarm and test Remove belly pans inspect and clean out Repair coolant leak at lower rad hose
August 26 2025	Inspection		Preform undercarriage inspection, preform hydraulic flow/pressure checks, test thermostat and fan function, adjust A/C belt tension, shim bucket pins
October 30 2025	Pressure Test		Remove panels around control valve, look up pressure procedure and relief locations
November 10 2025	Harness		Remove harness from pumps, inspect and re-loom harness, inspect all plugs, repair rubbed wire
November 11 2025	Pressure Adjustment		Dial up main relief and di relief pressures, set all line relief and motor relief pressures
November 12 2025	Pump House Wash		Assemble panels after wash, change small hose in pump house
January 11 2026	Initial Inspection		Pull panels and leak check unit following 2 days operation, small leak on right swing drain plumbing, inspect previous leak repairs
February 8 2026	Hyd. Leak		Investigate hydraulic oil under rear pans, repair leaking engine drain valve, repair hydraulic return lines leaking
February 13 2026	PM#1	13,836	Preform PM#1
February 17 2026	Main Hyd. Cooler Line	13,854	Main hydraulic cooler line blown off, replace all seals and install two new clamps. Checked fan, not loose, not damaged.
February 18 2026	Main Hyd. Cooler Line	13,861	Blew cooler line again, different spot, possible hood frame contact with cooler line, welded frame, re rigged line holders, add more clamps

March 1 2026	Swing Drive	13,944	Top up swing drive, seal pushing grease, potentially contaminated with oil
March 2 2026	Cooler Bypass Valve		Install new cooler bypass valve
August 22 2026	Undercarriage		Split both tracks, repair mushroomed links and install new master pins. Replace left idler. Replace RH bottom roller. Replace 2 pads and hardware.