SCANIA

CREDIT
MV: Cash

Invoice To: 103603

Date: 11/02/2026

Invoice number: 21912750

Reference: CREDIT FOR INVOICE 21129380
Contract Number:
Your Order No:
Work completed: 11/02/2026
Workorder number: 21163309

Vehicle make: SCANIA TRUCK R 620 A6X4NB
Vehicle model: R 620 A6X4NB
Chassis No: 9259216
Engine No: 1160401

Registration No:
Mileage: 971939
Delivery Date: 8/07/2020
Fleet Number

Product	Description	Price/unit	%	Total *

TAKE 5
Complete Take 5 Safety Report ******** DO NOT STAMP TO LINE **********

0.00

Vehicle, Check
Group GENERAL ----------
00005095 Vehicle status, check before planned work.

0.00

0.00

FAULT: CHECK AND REPORT - CUSTOMER ADVISES - ALL DASH LIGHTS ON ASWELL AS NOISE

CAUSE: Overheated brakes on steer axle and exhaust gas pressure sensor T125 faulty
FAULT CODES- EMS 5141, BMS 2114103

Remedy: Inspected vehicle and found fault codes for exhaust gas pressure sensor and brake related fault codes. Inspected exhaust system and found t125 pressure sensor not displaying correct values. Removed sensor and pipe to sensor and cleaned carbon out of both and found sensor started displaying correct values and fault code went inactive. Found on front axle the brakes have overheated. Removed wheel speed sensors and found grease has cooked on hard to the sensors causing them not to read correctly, once cleaned they started reading correctly and fault codes went inactive. Road tested and no fault codes returned. Also carried out brake test which passed. Suspect fault codes may return as no physical parts have been replaced.
[1, 1, 18] Customer complaint,Engine,Fault codes/warning lamp comes on because of ,
Group ENGINE ----------
00005004 Implement secondary diagnosis.
01005121 Troubleshoot individual product. Incl. starting or test driving in order to note fault symptoms.
01005261 *** troubleshooting.
10005032 Roller brake test brakes.
10005052 Clear fault codes using Scania Diagnos.
16455078 Renew exhaust gas pressure sensor, 1

Page Total: -1,477.40

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.
Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney
Lic No: MVRL 449 / MD 615
16-18 Lyn Parade. Prestons. 2170
Telephone: 02 9825 7900
Facsimile: 02 9825 7998

Banking Details
BSB: 013226
Account: 8361-52653
Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333
Web: www.scania.com.au

Invoice To: 103603

... continued from previous pa

Date: 11/02/2026

Invoice number: 21912750

Product	Description		Price/unit	%	Total *
				Previous page carried forward:	-1,477.40
	off, for the emission system. Including clearing fault codes with Scania Diagnos, operational testing with Scania Diagnos.				

					-1,477.40
1911032	SENSOR EXHAUST GAS PRESSURE	-1.00	621.00		-621.00 1
					-2,098.40

FAULT: DETECTED DURING REPAIRS - BRAKES ON STEER AXLE LOW

Cause - Found piston boots and slides on callipers to be damaged

Remedy - Applied chocks to vehicle wheels, jacked up vehicle and supported on stands, removed front wheels, disconnected brake boosters, disconnected components to brake callipers, removed callipers, received new callipers, built callipers and torqued all bolts to spec, installed new callipers onto vehicle and torqued all bolts to spec, installed new brake pads and adjusted to spec, reinstalled brake boosters and torqued to spec, reconnected components to brake callipers, reinstalled wheels, torqued wheel nuts to spec, completed a brake test and road test. On return retorqued wheel nuts, found brakes to be working correctly.

[1, 10, 9] Customer complaint,Brakes,Poor braking effect
because of ,
Group BRAKES ----------

00005004	Implement secondary diagnosis.				
10015300	Renew brake calipers, 2 off, on one axle. Incl. renew brake pads, check brake discs.				
10005032	Roller brake test brakes.				
01005117	Test drive vehicle.				

					-1,173.00
2475272	BRAKE CALIPER	-1.00	1,341.00		-1,341.00 1
2475273	BRAKE CALIPER	-1.00	1,341.00		-1,341.00 1
2325212	BR.PAD SET	-1.00	296.00		-296.00 1
2048972	BOLT	-8.00	58.24		-465.92 1
					-4,616.92
	SUNDRY ITEMS				-132.52 1
	Rounding				0.02 0

* 1 GST 10% *	**Sub Total (Excl. of GST) :**	**-6,847.82**
	GST :	**-684.78**
	TOTAL AMOUNT PAYABLE:	**-7,532.60**

Customer Survey Reminder

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.
Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney
Lic No: MVRL 449 / MD 615
16-18 Lyn Parade. Prestons. 2170
Telephone: 02 9825 7900
Facsimile: 02 9825 7998

Banking Details
BSB: 013226
Account: 8361-52653
Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333
Web: www.scania.com.au

Invoice To: 103603

... continued from previous pa

Date: 11/02/2026

Invoice number: 21912750

Product	Description	Price/unit	%	Total *

After your visit to our workshop, you may receive a survey from Scania Australia to share your feedback.
Survey ratings are as follows:
9-10: Positive
7-8: Neutral
1-6: Negative
If you feel unable to provide a positive rating, we encourage you to contact the Branch Manager to discuss how we can enhance your experience during your next visit. We truly appreciate your feedback.

***** Scania RTA Licence AU067978 expires 24.12.2028 *****

For queries on this invoice, please contact: Rebecca George on

Terms and conditions applicable to this invoice are displayed in the Scania Customer centre, a copy of which is available on request.
Payment Terms Trading Accounts: Strictly 30 days from date of invoice. Payment Terms Cash Sales: Payment on delivery of goods.

Scania Australia - Sydney
Lic No: MVRL 449 / MD 615
16-18 Lyn Parade. Prestons. 2170
Telephone: 02 9825 7900
Facsimile: 02 9825 7998

Banking Details
BSB: 013226
Account: 8361-52653
Account Name Scania Australia Pty Ltd - NSW Account

A.B.N. 44000537333
Web: www.scania.com.au