

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontractor Cost	Other Cost	Total Cost
93677		07/06/2026	1HM103HBG	ID - EARTHMOVING	121G		Tracks	1ME507	34466.0000	0	TRACK INSPECTION DONE BY WILLIAM ADAMS		0	0	0	0	
90978	109968	05/22/2026	1HM103HBG	ID - EARTHMOVING	184G	INT-S	Service EarthmovingA	1ME507	34893.0000	0	A TYPE SERVICE	TRAVELLED TO BRIDGEWATER CARRIED OUT SERVICE & INSPECTION. - GREASE RAN UP & TESTED ALL FUNCTIONS - ALL OK ON TEST	400	482.67	0	220	1072.67
90902	109774	05/21/2026	1HM103HBG	ID - EARTHMOVING	182G	R	Sundries	1ME507	0.0000	0	Make spigotted disk as per drg		96	15	0	15	111
86769	104860	03/11/2026	1HM103HBG	ID - EARTHMOVING	121G	R	Sundries	1ME507	0.0000	0	Supply 2x pins		0	1090.02	0	0	1090.02
77565		09/09/2025	1HM103HBG	ID - EARTHMOVING	121G	R	Sundries	1ME507	34952.0000	0	CHARGE MISSING OIL TO JOB 75275		0	1673.04	0	0	1673.04
75275	92338	07/30/2025	1HM103HBG	ID - EARTHMOVING	184G	R	Transmission	1ME507	34864.0000	0	DRAIN, FLUSH AND REPLACE TRANSMISSION FLUID		600	326.06	0	280	1186.06
72138	86961	06/02/2025	1HM103HBG	ID - EARTHMOVING	184G	R	Drive Line	1ME507	0.0000	34808	Trans filter and seat	REPALCE TRANSMISSION FITLER AND TIGHEN SEAT BOLTS	250	0	0	240	490
68969	85800	03/31/2025	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	34952.0000	0	Battreys and check over	DIAGNOSE AN DREPLACE BATTERIES CHECK CHARGE RATE ALL OK	636.56	907.11	0	400	1943.67
62267	76470	12/02/2024	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	34952.0000	0	Fit Savannah Plow	FIT UP SAVANNAH PLOW AT HBMI	1310.96	0	0	360	1670.96
											GREASE UNIT AND CHECK HYDRAULIC PRESSURES AND ADJUST TEST OPERATION ALL OK						
61477	73841	11/18/2024	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	34952.0000	0	Jump start Dozer		155.03	0	0	0	155.03
55405	67246	07/22/2024	1HM103HBG	ID - EARTHMOVING	186G	R	Hydraulic	1ME507	34952.0000	0	Change out Trans oil (bad oil sample)	DRAIN TRANS OIL AND REPLACE CHANGE TRANS FILTER RUN MACHINE AND TAKE NEW OIL SAMPLE	792.88	615.01	0	235	1642.89
52564	64183	05/27/2024	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	34952.0000	0	Inspect oil leak @ Onetrak	IDENTIFY SOURCE OF OIL LEAK AT ONETRAK AS REQUESTED DYLAN	93.28	0	0	0	93.28
41510	49960	10/20/2023	1HM103HBG	ID - EARTHMOVING	186G	R	Electrical	1ME507	34952.0000	0	Jumpstart	TAKE JUMP STARTER TO WAHS BAY, JUMP START MACHINE FOR TRANSPORT	118	0	0	0	118
40022	46881	09/21/2023	1HM103HBG	ID - EARTHMOVING	121G	R	Sundries	1ME507	0.0000	0	DOZER CABLES - SITECH INVOICE	DOZER CABLES - SITECH INVOICE	0	1352	0	580	1932
39260	46021	09/06/2023	1HM103HBG	ID - EARTHMOVING	186G	R	Electrical	1ME507	0.0000	0	CHECK /REPAIR LIGHTS ECT	PER KEVIN KARSSON REMOVED TRACKER. TESTED LIGHTS, SEVERAL NOT WORKING. REPLACED BLOWN GLOBES IN ALL 4 HALOGEN WORK LIGHTS. REPLACED PLUG AND REPAIRED WIRING FOR LED WORKLIGHTS AT FRONT OF CAGE. TRACED AND RECONNECTED SWITCH SUPPLY WIRE TO BATTERY FOR LED'S ON FRONT OF CAB. REPLACED LED BEACON LIGHT FULL OF WATER. RE-TESTED LIGHTS, ALL OKAY. CHECKED OIL LEVELS. REMOVED STICKER AND LOG BOOK. REMOVED GROUSER BOLTS AND PLATE. REMOVED PIN FROM RIPPER, ALIGNED CYLINDER AND REFITTED PIN, GROUSER AND BOLTS. FITTED SHIMS TO PUSH ARM CAP	1657.5	316.05	0	80	2053.55
38554	45643	08/22/2023	1HM103HBG	ID - EARTHMOVING	182G	INT-R	Lathe	1ME507	0.0000	0	REPAIR 1 BLADE CYLINDER ROD & REPLACE OTHER ROD	REPAIR 1 BLADE CYLINDER ROD & REPLACE OTHER ROD WELD UP MARKS ON 1 ROD & POLISH, MACHINE 2ND ROD FROM 3" 4140 CHROME ROD AND WELD ROD EYE BACK ON	1105	739.23	0	200	2044.23
38310	46706	08/17/2023	1HM103HBG	ID - EARTHMOVING	182G	R	Sundries	1ME507	34952.0000	0	REPAIRS TO DOZER	REPAIRS TO DOZER - UNBOLT SIDE PROTECTION COVERS, GRIND OUT CRACKS & GRIND FLUS, GOUGE OUT CRACKS UNDER CAB & REWELD. REMOVE CAB BUSHES, MACHINE NEW NYLON CAB MOUNT BUSHES & FIT.	4928.5	43.1	0	200	5171.6
37497	43488	08/01/2023	1HM103HBG	ID - EARTHMOVING	186G	S	Service EarthmovingB	1ME507	34952.0000	0	V-Belt - Missed off service Job 25027		0	285.75	0	0	285.75
36592	46695	07/17/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	34782	hydraulic issue	REMOVE COVERS, BLANK OFF HYDRAULIC HOSES CARRY OUT BYPASS TEST REMOVE LHS AND DISMANTLE, TAKE CYLINDER TO WILLIAM ADAMS TO REMOVE GLANDS. PICK UP CYLINDERS AND MAKE TOOL TO REMOVE PISTON. CHECK BONNET FOR DAMAGE. REASEAL CYLINDERS AND REFIT BOTH. RECONNECT HOSES AND CHECK OPERATION AND FOR LEAKS. REFILL HYDRALUIC OILS AND REFIT COVERS.	5838	1236.05	357	200	7631.05
											INSPECT FOR REPORTED FAULT, INSPECT VALVE BANK. DIASSEMBLE AND INSPECT FOUND NO FUALTS. REASSEMBLED ALL OK.						
											CARRY OUT PREPERATIONS FOR TRANSPORT. CHECK COVERS, CHAIN UP BLADE AND CLEAN UP MCHINE. REMOVED, WASHED AND REFIT BELLY PLATE.						
36426	42136	07/12/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Tracks	1ME507	0.0000	0	LABOUR MISSING FROM JOB 31316 - WILLIAM ADAMS	LABOUR MISSING FROM JOB 31316 - WILLIAM ADAMS	0	2654.38	0	0	2654.38
35405	42853	06/25/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Transmission	1ME507	34952.0000	0	TRANS FAULT	INVESTIGATED BLADE NOT WORKING. CHECKED CONTROL VALVE, LINKAGES ETC - ALL OK REMOVED SEAT FOR ACCESS CHECKED HYDRAULIC OIL LEVEL - ALL OK HYDRAULIC PUMP FUNCTION - ALL OK CHECKED COMPENSATOR VALVE (QUICK DROP) CHANGED TRANSMISSION OIL & FILTER RAN MACHINE, CHECKED FOR LEAKS & TESTED OPERATION - ALL OK PACKED UP & RETURNED TO SERVICE	3068.78	1164.28	0	100	4333.06

35072	39868	06/19/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	34701.0000	0	CHECK FOR BATTERY SHORT	CHECK FOR BATTERY SHORT. COVERED UP LINK CABLE. BATTERY BOX NEEDS REPLACING	171.26	194.04	0	75	440.3
34432	39312	06/05/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Transmission	1ME507	34702.0000	0	CHECK TRANSMISSION FAULT	FILL TRANS WITH HD30 MOVE TO WORKSHOP AFTER TEST DRIVE PULL FLOOR PAN OUT AND CHECK FOR LEAKS FOUND MULTIPLE HOSES TO BE LEAKING CLEAN AND TEST DRIVE TO INSPECT FOR LEAKS. REQUIRES HOSE SPECIALIST	895.91	341.7	0	30	1267.61
32203	39885	05/12/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	34701.0000	0	Replace batteries	TRAVEL TO LKW AND INSPECT BATTERIES, REMOVE TO REPAIR TEMP TRAVEL BACK TO LA. REPAIRED TERMINALS AND TRAVEL TO LKW. REMOVED OLD TERMINALS FROM WIRING CRIMP EYES ON LEADS AND HEAT SHRINK. REMOVE AND REPLACED BATTERIES NOTES: BASE OF BATTERY BOX HOLDER NEEDS REPAIRING SO THAT THE BATTERIES SIT EVEN.	1664.22	1469.36	0	120	3253.58
31315	37241	04/24/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	0.0000	0	INSPECT HEATER BLOWER FAN INOP	REMOVE DASH TO CHECK FAN OPERATION FOUND FAN BLOWER TO REQUIRE REPLACING REFIT DASH AND ORDER PARTS TRAVEL TO SITE AND REMOVE DASH AND FIT BLOWER FAN FOUND RH BLOWER FAN TO BE DAMAGED. REASSEMBLE AND FIT NEW VENTS REMOVE RH BLOWER AND FIT NEW BLADES REASSEMBLE AND TEST. ALL OK	795.49	781.48	0	40	1616.97
31316	38035	04/24/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Tracks	1ME507	0.0000	0	TRACK REPAIRS	REMOVE BROKEN TRACK AND FIT SPARE TRAVEL TO LKW TAKE TRACK TO WILLIAM ADAMS FOR REPAIRS PICK TRACK UP AND TRAVEL TO LKW REFIT REPAIRED ORIGINAL TRACK TRAVEL FROM LKW	2206.28	3043.08	0	1360	6609.36
30915	36792	04/14/2023	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingB	1ME507	0.0000	0	CARRY OUT B SERVICE	CARRY OUT B SERVICE REPLACE OIL AND FILTER REPLACE FUEL AND AIR FILTER REPLACE TRANS AND HYDRAULIC FILTERS	588.31	831.41	0	30	1449.72
30851	36796	04/13/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	0	HYDRAULIC PUMP NOISE	INSPECT HYDRAULIC PUMP NOISE FOUND HYDRAULIC LEVEL TO BE LOW TOP UP OIL AND TEST MACHINE FOUND HYDRAULIC LEAK TO BE PRESENT REMOVE FLOORING AND BELLY PLATE FOR ACCESS FOUND BLOWN O'RING TO BE CAUSE OF LEAK REPLACE O'RING AND TOP UP LEVEL TEST FOR LEAKS AND OPERATION NO HYDRAULIC PUMP NOISE HEARD ALL TESTS OK REPLACE FLOORING AND BELLY PLATE	1082.8	0	0	200	1282.8
30701	35819	04/11/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	0.0000	0	UHF/RADIO ANTENNAS	TRAVEL TO LAKE KING WILLIAM REPLACE AM/FM ANTENNA REPLACE UHF RADIO ANTENNA TRAVEL BACK FROM LAKE KING WILLIAM	428.15	171.64	0	395	994.79
30653	35688	04/06/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	0	HYDRAULIC LEAK	TRAVEL TO LKW REMOVED SEAT BASE AND FLOOR. RESEALED LEAKING SPOOL VALVE. REPLACE AND REPLACED LEAKING HYDRAULIC HOSE. TEST OPERATION AND TOP UP HYD AND TRANS OILS	556.6	16.11	0	450	1022.71
30475	36726	04/04/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	0.0000	0	SEAT PARTS MISSING FROM JOB # 28539		0	2395.01	0	0	2395.01
28625	37887	03/17/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Chassis	1ME507	0.0000	0	REMOVE FORESTRY GUARDING FOR REPAIRS	TRAVEL TO LAKE KING WILLIAM ASSESS MACHINE FOR REPAIRS REPAIR THREADS IN SIDE DOORS AND REPLACE BOLTS TRAVEL FROM LAKE KING WILLIAM TRAVEL TO LAKE KING WILLIAM REMOVE FORESTRY GUARDING AS PER REQUEST FIT NEW LIGHTS TO MACHINE REFIT ROTATING BEACON TO MACHINE TRAVEL FROM LAKE KING WILLIAM	4532.27	1094.17	0	1050	6676.44
28539	34334	03/16/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	0.0000	0	REPLACE SEAT		1008.24	2733.28	0	298	4039.52
28541	34307	03/16/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	0.0000	0	REPLACE LH DOOR GLASS		691.08	527.4	0	330	1548.48
28406	33659	03/14/2023	1HM103HBG	ID - EARTHMOVING	184G	R	Tracks	1ME507	34321.0000	0	REPLACE EAGLE CLAW BOLTS	TRAVEL TO LAKE KING WILLIAM CHECK SEAT FAULT, BROKEN WINDOW AND PULL APART R/H SIDE DOOR LOCK TO GET WORKING. CLEAN UP EQUIPMENT, MOVE RIPPERS DOWN TO NEXT HOLE INSPECT OIL LEAK	1378.15	42	0	265	1685.15
25647	29954	02/06/2023	1HM103HBG	ID - EARTHMOVING	192G	INT-R	Engine	1ME507	34136.0000	0	Repair Grease System	HRS: 24327 CLEAN OUT REMOVE REPLACE GREASE NIPPLES GREASE NIPPLE UNIT RE FIT CAPS WHERE POSSIBLE	128.45	0	0	10	138.45

25027	29657	01/20/2023	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingD	1ME507	0.0000	0	A TYPE SERVICE	HRS: 34313 CARRIED OUT SERVICE	774.11	505.13	0	360.75	1639.99
24899	35754	01/18/2023	1HM103HBG	ID - EARTHMOVING	186G	INT-R	Air Con	1ME507	0.0000	0	A/C ISSUES	FOLLOW UP REPLACE GREASE NIPPLE LHS OF BAR INSPECT AND REPAIR AC FAULT	206.93	0	0	0	206.93
24009	33849	12/16/2022	1HM103HBG	ID - EARTHMOVING	184G	INT-R	Engine	1ME507	0.0000	0	Repair belt tensioner	TRAVEL TO SITE, INSPECT AND REPOSITION OVER CENTERED BELT TENSIONER	165.68	0	0	95	260.68
22899	27724	11/22/2022	1HM103HBG	ID - EARTHMOVING	184G	INT-R	Hydraulic	1ME507	34136.0000	0	REPLACE LEAKING HYDRAULIC HOSES	REMOVED SEAT REMOVED LEAKING PUMP HOSES AND REPLACED AND REFITTED THE SEAT REPLACED FLASHING LIGHT	685.04	375.55	0	150	1210.59
21667	27742	10/26/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Engine	1ME507	0.0000	0	INSPECT ISSUE WITH AIR CON AND FAN BELT TENSIONER	REPLACED A/C COMPRESSOR AND HOSE TO CONDENSOR REGASSED AND CHECKED OPERATION ALL OK REMOVED LEAKING HYDRLOIC HOSE REPLACED HOSE	1027.57	561.53	0	110	1699.1
19466	23081	09/07/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	0.0000	53915	CHECK ALTERNATOR LIGHT ON DISPLAY	INSPECT ALTERNATOR LIGHT ON DISPLAY, BLOW DUST OUT OF ALTERNATOR AND UNIT TESTED OK TRAVEL CAMBRIDGE AND RETURN	128.45	0	0	60	188.45
19500	25028	09/07/2022	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingD	1ME507	0.0000	0	CARRY OUT S1 D SERVICE	IME507 34015HRS	740.27	1669.98	0	140	2550.25
19005	24006	08/29/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	33861.0000	0	REPAIR TOP COM WIRING	CARRY OUT S1 D SERVICE AS PER SERVICE SHEET INSPECT AIR CON ISSUES TRAVEL CLARENDON VALE AND RETURN INSPECT TRIMBLE SYSTEM ISSUE, FOUND SEVERAL DAMAGED WIRES RUBBED THROUGH. REMOVE HARNESS AND CARRY OUT REPAIRS, PERFORM CONTINUITY TEST ON HARNESS ONCE REPAIRED , REFIT HARNESS AND RECHECK OPERATION, CARRY OUT FINAL INSPECTION TRAVEL CAMBRIDGE AND RETURN	470.97	0	0	83	553.97
18348	23258	08/15/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	0.0000	33818	REPAIR/REPLACE REVOLVING LIGHT	INSPECT REVOLVING LIGHT ISSUE, FOUND TO BE FAULTY. REMOVE AND REPLACE REVOLVING LIGHT TRAVEL CAMBRIDGE AND RETURN	171.26	215.02	0	60	446.28
17350	21599	07/25/2022	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingA	1ME507	33781.0000	0	S1 A SERVICE	CARRY OUT S1 A SERVICE AS PER SERVICE SHEET TRAVEL HBMI	223.16	255.66	0	60	538.82
17086	21574	07/18/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Engine	1ME507	33738.0000	0	INSPECT ENGINE OVERHEATING ISSUE	INSPECT REPORTED OVER HEATING ISUE REALIGN BELT TENSIONER TO KEEP TENSION ON FAN BELTS TRAVEL HOBART TIP AND RETURN	85.63	0	0	65	150.63
16826	19912	07/13/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Engine	1ME507	33713.0000	0	INSPECT ENGINE OIL LEAK	INSPECT ENGINE OIL LEAK, CLEAN OFF AROUND FUEL PUMP MOUNTING POINT AND RESEALED TRAVEL HOBART TIP AND RETURN	214.08	25.76	0	70	309.84
16692	19266	07/11/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	34634.0000	0	REMOVE AND REPLACE RIPPER BOOT	REMOVE AND REPLACE WORN RIPPER BOOT HAD TROUBLE REMOVING BOOT FROM ADAPTOR TRAVEL HBMI	85.63	0	0	20	105.63
16330	25174	07/01/2022	1HM591HBG	CAPEX	121G	INT-R	Transmission	1ME507	0.0000	0	STEERING CLUTCH AND TRANS. REBUILT BY WILLIAM ADAMS		0	0	78489.9	0	78489.9
16086	18496	06/27/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Engine	1ME507	33507.0000	0	REFIT EXHAUST STACK	REFIT EXHAUST STACK TO MACHINE TRAVEL DYSART	170.84	0	0	97	267.84
15988	18702	06/24/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	33507.0000	0	REPAIR CONTROL LINKAGES AND RESEAL CONTROL VALVE, REPAIR ENGINE OIL LEAKS	REMOVE CONTROL VALVE , STRIP CLEAN AND RESEAL REPLACE WORN LINKAGE PARTS REPAIR ENGINE OIL LEAKS REPAIR ENGINE DOORS AND SIDE COVERS REPAIRS CARRIED OUT BY WILLIAM ADAMS	0	0	4238.63	0	4238.63
15489	18137	06/14/2022	1HM103HBG	ID - EARTHMOVING	184G	INT-R	Bodywork	1ME507	0.0000	0	REWELD GUARDING AFTER MECHANICAL REPAIRS	WELD IN FORESTRY GUARDING AND PLATE UNDER TRANSMISSION AFTER REPAIRS CARRIED OUT BY WILLIAM ADAMS TRAVEL TO MACHINE AND RETURN	402.29	0	0	49	451.29
15558	18021	06/14/2022	1HM103HBG	ID - EARTHMOVING	184G	INT-R	Hydraulic	1ME507	33590.0000	0	REPAIR HYD LEAK AT RIPPER	REMOVE GUARD FROM REAR OF MACHINE, REPLACE BLOWN O RINGS ON RIPPER CONTROL VALVE AND OPERATE MACHINE TO CHECK FOR FURTHER LEAKS. TRAVEL ELDERSLIE AND RETURN	341.68	79.4	0	252	673.08
14410	17146	05/19/2022	1HM103HBG	ID - EARTHMOVING	186G	INT-R	Transmission	1ME507	0.0000	0	CONTROL VALVE transmission repairs	ASSIST WILLIAM ADAMS IN REBUILDING D8 TRAINSMISSION	4256.56	0	0	0	4256.56
13310	15877	04/22/2022	1HM103HBG	ID - EARTHMOVING	182G	R	Sundries	1ME507	33665.0000	0	REPAIR RIPPER	REPAIR RIPPER - SUPPLY NEW RIPPER NOSE & BOOT, CLEANUP RIPPER PREHEAT & WELD ON NEW NOSE, FIT NEW TOOTH ETC & CLEANUP AREA	1460.4	462	0	150	2072.4
12843	19903	04/11/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Differential-FD	1ME507	0.0000	0	INSPECT RIGHT HAND DRIVE ISSUE	INSPECT DRIVE ISSUE ON RIGHT HAND TRACK REMOVE FINAL DRIVE COVER AND INSPECT AXLE AND DRIVE GEARS , REFIT COVER ASSIST WILLIAM ADAMS REMOVE AND REFIT FINAL DRIVE FINAL DRIVE RECONDITIONED BY WILLIAM ADAMS	2256.2	91	15858.11	100	18305.31
12555	14171	04/04/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Trays/Buckets	1ME507	33665.0000	0	WELD TRUNION CAP BACK ONTO PUSH ARM	WELD TRUNION CAP BACK ONTO PUSH ARM AND REFIT ONTO MOUNTING BALL TRAVEL DYSART AND RETURN	298.97	0	0	171.6	470.57

12384	15509	03/30/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Sundries	1ME507	0.0000	0	REPLACE DAMAGED FLOOR MAT	REPLACE DAMAGED FLOOR MAT AS REQUESTED' OPERATOR TO FIT	0	577.06	0	0	577.06
12306	14162	03/29/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	33558	REPAIR OIL LEAK UNDER FLOOR PLATE	REMOVE FLOOR PLATE AND TRANSMISSION COVER AND CLEAN AREA REPAIR OIL LEAKS AT BACK OF TRANSMISSION, REFIT STEERING MOTOR AND REFIT FLOOR PLATE AND COVERS REMOVE ENGINE BAY DOORS AND REPAIR HINGES, REPLACE MISSING BOLTS IN BONNET REMOVE AND REPLACE RIPPER BOOTS	683.36	79.4	0	35	797.76
11920	14516	03/21/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Tracks	1ME507	33627.0000	0	REPLACE BROKEN EAGLE CLAW BOLTS	REMOVE AND REPLACE BROKEN EAGLE CLAW BOLTS IN RIGHT HAND TRACK. REPLACE BOLTS IN LEFY HAND TRACK JOINT REPLACE MISSING TRACK GUIDES TRAVEL MURDUNNA AND RETURN TWICE	2260.26	32.36	0	510	2802.62
11491	12957	03/09/2022	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingB	1ME507	33507.0000	0	CARRY OUT S1 B SERVICE	CARRY OUT S1 B SERVICE AS PER SERVICE SHEET TRAVEL MURDUNNA AND RETURN	506.54	528.83	0	315	1350.37
11193	12943	03/02/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Suspension/UC	1ME507	0.0000	0	REPLACE BROKEN ROLLER CAP BOLTS	NOTE: BROKEN BOLT IN TRACK JOINING LINK REMOVE BROKEN ROLLER CAP BOLTS CLEAN UP THREADS AND FIT NEW CAP AND MISSING BOLTS TRAVEL MURDUNNA AND RETURN	899.7	67.54	0	284.25	1251.49
10943	12592	02/25/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Trays/Buckets	1ME507	0.0000	33446	REPLACE CORNER TIPS AND TURN EDGES	TURN CUTTING EDGES AND FIT NEW CORNER TIPS REMOVE AND REPLACE BROKEN SIDE PANEL BOLT TRAVE CAMBRIDGE AND RETURN	1381.95	0	0	100.75	1482.7
10411	11830	02/15/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Engine	1ME507	33390.0000	0	REPLACE DAMAGED FAN BELTS AND TENSIONER ASSEMBLY	REMOVE AND REPLACE DAMAGED FAN BELTS AND TENSIONER ASSEMBLY. WORK CARRIED OUT BY WILLIAM ADAMS AT CAMBRIDGE SITE	0	0	3746.23	0	3746.23
9246	10641	01/19/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Bodywork	1ME507	33272.0000	0	REPLACE BROKEN REAR CAB WINDOW	REPLACE REAR CAB WINDOW TRAVEL CAMBRIDGE	170.84	375.84	0	53.5	600.18
9094	10144	01/17/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	33234	REPAIR HYDRAULIC LEAK UNDER FLOOR PLATE	REMOVE FLOOR PLATE, REMOVE AND REPLACE BLOWN O RING ON STEERING PUMP. TOP UP HYDRAULIC OIL AND TEST OPERATION. REFIT FLOOR PLATES TRAVEL HBMI	132.05	45.6	0	39	216.65
9025	13377	01/14/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Trays/Buckets	1ME507	0.0000	0	REPLACE CORNER TIPS, TURN CUTTINGEDGES	SUPPLY SPARE PARTS ONLY, OPERATOR TO GET MORE WEAR OUT OF EXISTING PARTS	0	1577.16	0	0	1577.16
8981	10158	01/13/2022	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingA	1ME507	0.0000	23245	S1 A SERVICE	CARRY OUT S1 A SERVICE AS PER SERVICE SHEET TRAVEL HBMI 33245 HRS	330.08	259.42	0	73	662.5
8879	11534	01/11/2022	1HM103HBG	ID - EARTHMOVING	184G	R	Transmission	1ME507	0.0000	33406	INSPECT TRANSMISSION TEMP LIGHT ISSUE	INSPECT TRANSMISSION FILTER LIGHT ISSUE, REMOVE AND REPLACE DAMAGED SENSOR TRAVEL HBMI 33406 HRS AT REPAIR	198.8	405.58	0	60.75	665.13
8429	11754	12/20/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Differential-FD	1ME507	0.0000	33191	RESEAL BOTH AXLES BETWEEN FINAL DRIVE AND TRANSMISSION	REMOVE PLANETARY COVERS AND AXLES , REPLACE SEALS BETWEEN FINAL DRIVES AND TRANSMISSION ON BOTH SIDES. REFIT PLANITARY COVERS AND FILL WITH OIL . RUN MACHINE AND TESTED OK TRAVEL HBMI AND RETURN TWICE 33191 HRS	780.54	1032.09	0	160.5	1973.13
8016	9394	12/13/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	33107.0000	0	CHANGE HYDRAULIC OIL , CHECK CYCLE TIMES	DRAIN HYDRAULIC OIL AND CHANGE FILTERS AFTER BAD SAMPLE AS REQUESTED BY CAPPO FILL TANK WITH NEW OIL AND CHECK CYCLE TIMES TRAVEL HBMI AND RETURN	264.1	372.03	0	102	738.13
6729	7274	11/11/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	33041.0000	0	REPAIR OIL LEAK UNDER FLOOR PLATE	REMV E FLOOR PLATE, REMOVE AND REPLACE LEAKING HYDRAULIC HOSES. TOP UP HYDRAULIC OIL AND TEST FOR LEAKS, REFIT FLOOR PLATE TRAVEL SORELL AND RETURN	683.36	372.73	0	145.96	1202.05
6269	9749	10/29/2021	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingC	1ME507	0.0000	33071	S1 C SERVICE	CARRYOUT S1 C SERVICE AS PER SERVICE SHEET ADJUST ALL BELTS TRAVEL SORELL AND RETURN 33071 HRS AT SERVICE	683.36	1522.15	0	122	2327.51
5654	7005	10/13/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	32911.0000	0	REPAIR OIL LEAK UNDER FLOOR PLATE	REMOVE FLOOR PLATE AND SEAT BASE, REMOVE BELLY PLATES. REMOVE AND REPLACE BLOWN HYDRAULIC HOSE. REASSEMBLE MACHINE , TOP UP HYDRAULIC OIL AND TEST OPERATION GRIND DOWN RIPPER SHANK TO SUIT NEW TOOTH AND FIT RIPPER INTO TOOL BAR TRAVEL SORELL AND RETURN	512.52	265.45	0	97.5	875.47
5565	9535	10/11/2021	1HM103HBG	ID - EARTHMOVING	182G	R	Ground Engaging	1ME507	32859.0000	0	BUILD UP RIPPER ADAPTER	BUILD UP RIPPER ADAPTER	836.12	0	0	50	886.12
5243	5609	10/04/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Bodywork	1ME507	32859.0000	0	REPAIR BROKEN BRACKET	REMOVE , REPAIR AND REFIT LIGHT BRACKET ON TOP OF BLADE CYLINDER TRAVEL SORELL	256.26	0	0	56.5	312.76
5032	7040	09/27/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	0.0000	0	REPAIR BROKEN FITTING ON REAR FRAME	REPLACE DAMAGED FITTING ON REAR FRAME, WORK CARRIED OUT BY PIRTEK AT SORELL	0	123.43	0	0	123.43
4955	6067	09/24/2021	1HM103HBG	ID - EARTHMOVING	182G	FAB	Sundries	1ME507	32790.0000	0	MODIFY FIRE EXTINGUISHER BRAKET	MODIFY FIRE EXTINGUISHER BRAKET & MODIFY NEW BRACKET, WELD BRACKETS TOGETHER	114.02	0	0	5	119.02
4162	4007	09/07/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Electrical	1ME507	32790.0000	0	Replace batteries	REMOVE AND REPLACE OLD BATTERIES TRAVEL SORELL AND RETURN	229.23	1001.92	0	87	1318.15
3885	4118	08/31/2021	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingA	1ME507	0.0000	32765	S1 A SERVICE	S1A SERVICE AS PER SERVICE SHEET ADJUST FAN BELTS TRAVEL SORELL AND RETURN	186.52	253.41	0	72.5	512.43
2876	2635	08/05/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	32534.0000	0	REPLACE BLOWN HOSE	REMOVE FLOOR PLATE, REMOVE AND REPLACE BLOWN HYDRAULIC HOSE. TOP UP HYDRAULIC OIL AND TEST OPERATE MACHINE. REFIT FLOOR PLATE. SUPPLY 20LTS SPARE HYD OIL TRAVEL SORELL	298.97	170.56	0	58	527.53

2672	4895	08/02/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Tracks	1ME507	0.0000	0	INSPECT REPORTED TRACK BOLT	INSPECT BROKEN TRACK BOLT, BREAK LEFT TRACK AND REMOVE BROKEN EAGLE CLAW BOLT. CLEAN UP BOTH TRACK LINKS AND RETAP THREADS, LINE UP TRACK LINKS AND FIT NEW BOLTS, TENSION BOLTS TO SPECS AND ADJUST TRACK.	683.36	28.84	0	87	799.2
2124	1668	07/19/2021	1HM103HBG	ID - EARTHMOVING	184G	S	Service EarthmovingB	1ME507	32534.0000	0	S1 B SERVICE	TRAVEL SORELL AND RETURN s1 b service as per service sheet travel sorell and return	512.52	454.29	0	0	966.81
1963	4866	07/15/2021	1HM103HBG	ID - EARTHMOVING	184G	R	Hydraulic	1ME507	32486.0000	0	REPLACE BLOWN RIPPER HOSE	REMOVE AND REPLACE DAMAGED RIPPER HOSE SUPPLY SPARE HOSE TO SUIT SUPPLY ENGINE AND HYDRAULIC OIL TRAVEL SORELL	170.84	357.81	0	43.5	572.15
210422-0035	SVC00263110	06/21/2021	1H0103	ID - EARTHMOVING	184_INT	R	Suspension/UC	1ME507	32051HR		REPLACE COLLAPSED EQUALIZER BE	REMOVE BELLY PLATE REMOVE DAMAGED EQUALIZER BAR, GOUGE OUT AND REWELD CRACKS IN SIDE MOUNTINGS ON TRACK FRAME. FIT NEW EQUALIZER BAR AND REFIT BELLY PLATE TRAVEL HBMI AND RETURN X3	4880.8	10872.28	0	325	16078.08
210513-0028	SVC00264229	06/21/2021	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	32,140 HRS		REPAIR TRIMBLE FAULT	REPAIR DAMAGED THREADS IN TRIMBLE POLE MOUNTS REMOVE AND REPLACE DAMAGED HOSE TRAVEL TO THE AIRPORT	163.4	0	0	212.5	375.9
210315-0041	SVC00261264	06/18/2021	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	32035HRS		WELD UP CRACKS IN BLADE	GOUGE OUT AND REWELD CRACKS IN BLADE AND RIPPER BOX TRAVEL CAMPANIA AND RETURN	698.2	0	0	225	923.2
210526-0055	SVC00265023	06/03/2021	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	32,226 HR		S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET TRAVEL TO SORELL	263.93	326.75	0	80	670.68
210513-0053	SVC00264251	05/24/2021	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507			SUPPLY 2 X 25MM TRIMBLE BASES	SUPPLY 2 X 25MM TRIMBLE BASES FOR WELDING TO MACHINE	406.05	135.42	0	20	561.47
210426-0003	SVC00263220	05/19/2021	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507			MACHINE SPACERS AS REQUESTED	MACHINE SPACERS AS REQUESTED & PULLER PLATES	225.25	158.69	0	0	383.94
210427-0060	SVC00263309	05/05/2021	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	32,052 HRS		REPAIR WORK LIGHT WIRING	REPAIR WORK LIGHT WIRING, REPLACE WIRING PLUG ASSIST CHRIS REMOVE DAMAGED HOSES TRAVEL HBMI	163.4	12.36	0	37.5	213.26
210421-0050	SVC00261784	04/29/2021	1H0103	ID - EARTHMOVING	184_INT	R	Steering	1ME507	32,050HRS		REPLACE BLOWN STEERING HOSES	REMOVE FLOOR PLATE, REMOVE AND REPLACE TWO BLOWN STEERING HOSES. TEST OPERATION AND TOP UP HYDRAULIC OIL , REFIT FLOOR PLATE TIGHTEN TRUNION BOLTS TRAVEL HBMI AND RETURN	571.9	425.1	0	75	1072
210406-0004	SVC00262518	04/22/2021	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	32,089HRS		REPAIR OIL LEAKS	REMOVE COVERS AND INSPECT OIL LEAK, FOUND HYDRAULIC TANK CRACKED. REMOVE DAMAGED SIDE COMBING, REMOVE HYDRAULIC TANK AND CUT OUT FLOORING UNDER TANK, CLEAN AND PREP FOR REPAIRS, CUT OUT NEW FLOOR PLATE AND CLEAN ALL PARTS . WELD UP CRACKS IN HYDRAULIC TANK AND WELD ON STRENGTHENER PLATES. WELD IN NEW FLOOR PLATE AND SUPPORT, REFIT HYDRAULIC TANK AND PLUMB TO MACHINE, FILL TANK WITH OIL AND TEST OPERATE MACHINE TO CHECK FOR LEAKS. REFIT SIDE GUARDING AND WELD CAB GUARD BACK IN PLACE . OPERATE MACHINE TO RECHECK FOR LEAKS TRAVEL RICHMOND AND RETURN TWICE	3785.55	414.14	0	200	4399.69
210222-0037	SVC00260208	04/09/2021	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	31,198 HRS		S1 D SERVICE	S1 D SERVICE AS PER SERVICE SHEET TRAVEL RICHMOND AREA AND RETURN REMOVE AND REPLACE DAMAGED AIR CON BELT TRAVEL RICHMOND AREA AND RETURN	876.6	1456.6	0	250	2583.2
190815-0080	SVC00231253	03/30/2021	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507	30107hr		OIL COOLERS AND SEALS	TRAVEL TO RAEBURN, REMOVED SIDE COVERS TO ENGINE, DRAINED COOLANT OUT OF MACHINE, DRAINED OIL OUT OF MOTOR AS PER OIL DRAIN BLOCK HAD CRACKED, REPLACED DRAIN BLOCK, REMOVED PARTS OF ENGINE TO GAIN ACCESS TO ENGINE AND TRANSMISSION COOLER, REMOVED ENGINE AND TRANSMISSION COOLER, DROP BELLY PLATE TO GAIN ACCESS TO BOLT ON BOTTOM OF COOLER, HAD COOLERS TESTED, FITTED NEW COOLERS WITH NEW SEALS AND GASKETS, FITTED OTHER PARTS REMOVED FROM ENGINE WITH NEW GASKETS AND SEALS, FILLED ENGINE WITH OIL AND WATER, FITTED SIDE COVERS.	1379.98	6704.78	0	50	8134.76
190815-0080	SVC00259167	03/30/2021	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507	30107hr		OIL COOLERS AND SEALS	CORE RETURN MISSED OF PREVIOUS INVOICE	0	-1070.54	0	0	-1070.54
210219-0016	SVC00260136	02/23/2021	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	31,942 HRS		REPLACE BROKEN EAGLE CLAW	DRILL OUT AND REPLACE BROKEN EAGLE CLAW BOLT ON TRACK LINK TIGHTEN AIR CON BELT AND CHECK OVER MACHINE TRAVEL RICHMOND AND RETURN	290.8	19.46	0	75	385.26
210111-0012	SVC00258148	01/28/2021	1H0103	ID - EARTHMOVING	184_INT	R	Air Con	1ME507			REPAIR AIRCON	INSPECT A/C SYSTEM AND FOUND CONDENSER LEAKING, FREE UP QUICK RELEASE FITTINGS AND REPLACE CONDENSER AND RECIEVER DRYER. CHARGE SYSTEM AND FOUND BLOWN SUCTION HOSE, REPLACE SUCTION HOSE AND RECHARGE SYSTEM. TEST OPERATION AND FOUND OK TRAVEL RAEBURN QUARRY AND RETURN	1171.5	1783.48	90.9	450	3495.88
210113-0040	SVC00258350	01/20/2021	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	31,757 HRS		A TYPE SERVICE	A TYPE SERVICE AS PER SERVICE SHEET TRAVEL HBMI AND RETURN	145.4	252.64	0	75	473.04
201106-0037	SVC00255211	01/07/2021	1H0103	ID - EARTHMOVING	192_INT	S	Service	1ME507	31510HR		S1B SERVICE	TRAVELTO TUNBRIDGE, CARRY OUT S1B SERVICE AS PER SCHEDULE, CHANGE HYD OIL AND FILTER, REPLACED HYD FILTERS, BLEW OUT OUTER AIR FILTER, TOP UP RH FINAL DRIVE OIL	966.63	894.03	0	250	2110.66
201208-0013	SVC00256891	12/18/2020	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	31,629 hrs		REPAIR OIL LEAK	TRAVEL HBMI AND RETURN, REMOVE CAB FLOOR PLATE AND SMALL BELLY PLATE, DEGREASE AREA AROUND OIL LEAK. RUN MACHINE AND LOCATE OIL LEAK, REMOVE AND REPLACE BLOWN HYDRAULIC HOSE. RUN MACHINE AND CHECK FOR OTHER LEAKS, TESTED OK. REFIT BELLY AND FLOOR PLATES. DRILL OUT AND REPLACE BROKEN ROLLER END CAP BOLTS	694.45	121.6	149.6	30	995.65
201116-0005	SVC00255606	12/09/2020	1H0103	ID - EARTHMOVING	192_INT	R	Ground Engaging	1ME507	31510 HRS		CORNER TIPS FOR TRANSPORT	TRAVEL TO CAMPBELL TOWN, REMOVED CORNER TIPS FOR TRANSPORT OF DOZER, TRAVEL TO NORTH SCOTTSDALE AND FIT CORNER TIPS BACK TO MACHINE.	624.46	0	0	425	1049.46
201123-0024	SVC00256007	11/24/2020	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	31,548 HRS		REFIT CORNER TIPS	TRAVEL TO HBMI, REFIT CORNER TIPS ON DOZER DLADE AND TENSION BOLT WITH HI TORQUE	89.2	0	0	37.5	126.7
201023-0021	SVC00254429	11/20/2020	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	31,319 HRS		REPLACE LEAKING TRANS HOSE	TRAVEL TO CAMPBELL TOWN REPLACE LEAKING TRANS HOSE REMOVE FLOOR PLATE AND COVERS REMOVE AND REPLACE LEAKING TRANSMISSION HOSE REFIT FLOOR PLATES AND COVERS AND TEST OPERATION	408.5	180.02	0	162.9	751.42

201109-0066	SVC00255258	11/19/2020	1H0103	ID - EARTHMOVING	192_INT	R	Tyres	1ME507	31472	TIGHTEN GROUSER PLATES	TRAVEL TO CAMPBELL TOWN, TIGHTEN GROUSER PLATES	411.9	0	0	56.25	468.15
200928-0023	SVC00253127	11/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	31,247 HRS	REPLACE CUTTING EDGES	TRAVEL TO BOTHWELL, REMOVE WORN CUTTING EDGES AND CLEAN UP BLADE SURFACES, CLEAN PAINT FROM BACK OF NEW CUTTING EDGES AND BOLT EGES ONTO BLADE. TENSION BOLTS.	1071.13	3598.48	0	225	4894.61
200929-0057	SVC00253263	11/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	31,319 HRS	RESEAL RADIATOR SEGMENTS	TRAVEL TO CAMPBELL TOWN, DRAIN COOLANT AND REMOVE RADIATOR SEGMENTS , CLEAN UP SURFACES AND REPLACE SEALING RUBBERS. REFIT SEGMENTS AND REFILL WITH COOLANT, RUN MACHINE AND CHECK FOR LEAKS.	1077.1	1363.64	0	175	2615.74
200618-0065	SVC00247797	10/21/2020	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		REPLACE ROD IN BLADE LIFT CYL	REPLACE ROD IN BLADE LIFT CYL	1544.88	0	0	50	1594.88
200925-0025	SVC00253058	09/30/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	31,247 HRS	S1 A SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET. TRAVEL TO BOTHWELL AND RETURN	488.03	261.96	0	149	898.99
200610-0032	SVC00247341	09/17/2020	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	31817 hrs	REPLACE TRACKS AND SEGMENTS	BREAK RIGHT HAND TRACK, REMOVE AND REPLACE WORN FRONT AND REAR IDLERS. REMOVE AND REPLACE WORN DRIVE SEGMENTS. FIT NEW TRACK AND ADJUST TO SUIT BREAK LEFT HAND TRACK, REMOVE AND REPLACE WORN FRONT IDLER. REMOVE AND REPLACE WORN DRIVE SEGMENTS, FIT NEW TRACK AND ADJUST TO SUIT TRAVEL TO HBMI AND RETURN THREE TIMES	4061.2	8579.91	25728.4	275	38644.51
200812-0030	SVC00251472	09/09/2020	1H0103	ID - EARTHMOVING	183_INT	R	Lathe	1ME507		MACHINE BROKEN CANNON & WELD	Repair of failed cannon. Disassembled and cleaned all parts. Set the cannon up and marked as needed (two repair areas) Machined back the damaged area on both sections. skimmed a lead inside the tube .5mm and polished the end of the machined cut. Machined the ends as explained in the repair proceeedure machined hollow bar end and machined back to length that was required Set up and tack Once correct, fully weld out keepng and eye on the temperature as per the spec sheet. Cleaned the bores and cleane dout all threaded holes. Set up pressing equipment and pulled in the new Major boggie pins fitted the retainers. Set up the tooling to press the spring in place as per the manual. Clenaed up and packaged on a pallet.	7384.8	702.02	0	250	8336.82
200812-0030	SVC00252212	09/09/2020	1H0103	ID - EARTHMOVING	183_INT	R	Lathe	1ME507		MACHINE BROKEN CANNON & WELD	CREDIT FOR HOLLOW BAR	0	-485	0	0	-485
200803-0067	SVC00250348	08/31/2020	1H0103	ID - EARTHMOVING	184_INT	R	Suspension/UC	1ME507	31,819 HRS	REPAIR CANNON	TRAVEL TO HBMI, REMOVE CANNON FROM DOZER AND TRANSPORT BACK TO WORKSHOP REMOVE IDLER AND FRONT BOGIE FROM CONNON AND CLEAN UP PARTS READY FOR WELDING REPAIRS, LOAD REPAIRED CANNON ON TRUCK AND TRANSPORT TO HBMI	2907.85	2918.2	0	225	6051.05
200713-0009	SVC00249045	08/12/2020	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	30974 HRS	REPAIR CRACK IN BLADE AND RIPP	FIT NEW SEALS AND BUSH INTO FRAME AND REFIT CANNON REPAIR CRACK IN BLADE AND RIPPER BOX	612.75	152.7	0	107.5	872.95
191114-0064	SVC00236164	08/11/2020	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	30390	REPLACE BLOWN HEAD GASKET	GOUGE OUT AND REPAIR CRACKS IN BLADE CORNERS AND RIPPER BOX TRAVEL HBMI AND RETURN SOS KITS ADDED FROM CLOSED S/C 200722-0010 REPLACE BLOWN HEAD GASKET. Pressurizing the cooling system, removed cover and panels that are required. Removed the cylinder head. Found number 5 cylinder to be water damaged. removed the belly guards and the sump. Removed the piston and liner group. replaced with reman and rebuilt the engine. Tested the engine and reassembled as needed. REPAIR AND RECOVER SEAT CARRIED OUT BY PAUL BAKER CHRIS COWEN REQ RECEIVED 25/11 MCORF-19-12 X 2 MCORF451912 X 2 G2XH12 X 10M1ME507 - 30390 S1 C SERVICE AS PER SERVICE SHEET	11264.55	4250.44	610	0	16124.99
200722-0010	SVC00249555	07/28/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	31016 hrs	S1 C SERVICE		653.6	971.66	0	95	1720.26
200716-0025	SVC00249301	07/24/2020	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	NA	SUPPLY SPARE HOSE AS REQUESTED	REPAIR WORK LIGHT WIRING TRAVEL MORNINGTON AND RETURN SUPPLY SPARE HOSE AS REQUESTED FOR TILT CYLINDER	40.85	94.15	0	5	140
200717-0017	SVC00249329	07/21/2020	1H0103	ID - EARTHMOVING	184_INT	R	Differential-FD	1ME507	30972 HRS	CHECK OIL LEAK AT FINAL DRIVE	TRAVEL TO MORNINGTON, CHECK OIL LEAK AT FINAL DRIVE, CLEAN AROUND DUO SEAL AND TOP UP OIL	163.4	4.59	0	25	192.99
200602-0024	SVC00246949	07/10/2020	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	30870 hrs	REPAIR BROKEN TRACK	REPAIR BROKEN TRACK REMOVE BROKEN TRACK FROM MACHINE AND FIT SECONDHAND TRACK ONTO MACHINE TO ALLOW UNIT TO CONTINUE WORKING WHILE TRACK IS REPAIRED. DELIVER BROKEN TRACK TO WILLIAM ADAMS TRAVEL GROVE AND RETURN TWICE	939.55	1237.56	2070.61	0	4247.72

200605-0036	SVC00247829	07/10/2020	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	30936 HRS	REPLACE SIDE ARM TRUNION BALLS	REPLACE SIDE ARM TRUNION BALLS AND CAPS ADJUST SIDE TRUNION CAPS TO ALLOW UNIT TO KEEP WORKING UNTIL NEW PARTS ARRIVE TRAVEL JUDBURY AND RETURN REMOVE SIDE TRUNIONS AND BLADE LIFT CYLINDER FOR REPAIRS TRAVEL JUDBURY REMOVE OLD TRUNIONS FROM MOUNTING BRACKETS AND WELD IN NEW ONES REFIT TRUNION BALLS AND LIFT CYLINDER TO MACHINE, REMOVE WORN TRUNION CAPS FROM PUSH ARMS AND WELD ON NEW ONES . REFIT PUSH ARMS ONTO MACHINE AND SHIM UP TO SUIT TRAVEL JUDBURY AND RETURN	3331.35	2813.03	0	387.5	6531.88
200626-0042	SVC00248255	07/10/2020	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	30870 hrs	ASSESS TRACK DUE TO DRY PINS	ASSESS TRACK DUE TO DRY PINS, REMOVE TRACK PLATES START TO WET TURN PINS. FOUND TO MANY DRY PINS TO CONTINUE REPAIRS. WORK CARRIED OUT BY WILLIAM ADAMS	0	0	1872.76	0	1872.76
200602-0038	SVC00246978	07/09/2020	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	30870 hrs	REPLACE BROKEN DOOR GLASS	REPLACE BROKEN DOOR GLASS RIGHT HAND DOOR REPLACE MISSING TRACK WEAR GUIDES TRAVEL GROVE	245.1	410.58	0	0	655.68
200601-0035	SVC00246902	06/09/2020	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	30844 HRS	TIGHTEN CUTTING EDGE BOLTS	TIGHTEN CUTTING EDGE BOLTS REMOVE CORNER TIP AND CLEAN UP SURFACES, REFIT CORNER TIP AND TIGHTEN ALL CUTTING EDGES BOLTS WITH HI TORQUE TOOL TRAVEL GROVE	285.95	0	0	51.5	337.45
200529-0080	SVC00246770	06/05/2020	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	30, 844 HRS	REPLACE FAULTY REVOLVING LIGH	REPLACE FAULTY REVOLVING LIGHT AND REPAIR WIRING WHILE ON SITE AT GROVE	81.7	189	0	0	270.7
191128-0017	SVC00237136	04/23/2020	1H0103	ID - EARTHMOVING	182_INT	R	Milling	1ME507		MACHINE PUSH BAR CAP FACES	MACHINE PUSH BAR CAP FACES	283.1	0	0	14	297.1
200326-0066	SVC00243254	04/19/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	30706 HRS	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET TRAVEL TO CHWF	456.85	658.4	0	150	1265.25
191113-0033	SVC00236075	04/15/2020	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	30387 HR	S1 A SERVICE		245.1	244.49	0	12	501.59
200221-0063	SVC00241934	03/04/2020	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	NOT SUPPLIED	REPAIR EXHAUST	CLEAN UP EXHAUST STACK AND WELD NEW MOUNTING FLANGE ON BOTTOM PART DROPPED OF AT WORKSHOP BY OPERATOR	178.4	40	0	8	226.4
200130-0031	SVC00240030	02/18/2020	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	30507 HR	REBOLT CUTTING EDGES AND	REBOLT CUTTING EDGES AND CORNER TIPS, TORQUE BOLTS TO SPECS FIT NEW UHF AERIAL AND REVOLVING LIGHT	538.55	305.21	0	0	843.76
200203-0061	SVC00240190	02/18/2020	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	30507 HRS	REPAIR CRACK IN HYDRAULIC TANK	REPAIR CRACK IN HYDRAULIC TANK REMOVE SIDE PANELS AND PART OF ROPS SCREEN, DRAIN AND REMOVE HYDRAULIC TANK. CUT OUT BENT UP SECTION OF SIDE COMB AND WELD IN NEW PLATE. REPAIR CRACK IN HYDRAULIC TANK AND REFIT TO MACHINE, FILL WITH OIL AND TEST FOR LEAKS. REFIT SIDE PANELS AND WELD IN ROPS SCREEN TRAVEL HBMI AND RETURN TWICE	2250.18	334.46	0	200	2784.64
191017-0008	SVC00237601	01/16/2020	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	30387hr	INSPECT AND REPAIR TRANS	REPLACED TORQUE CONVERTER AND TRANSMISSION PUMP DUE TO FAILURE OF RECONDITIONED UNIT	3774.85	5973.62	0	0	9748.47
191211-0031	SVC00238467	01/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	30389 HRS	CHANGE TRANSMISSION FILTERS	CHANGE TRANSMISSION FILTERS AND CHECK TRANSMISSION PRESSURE INSPECT WIRING AND RECHECK FILTER REMOVE AND REPLACE OIL TEMPERATURE SWITCH, RAN UNIT FOR PERIOD OF TIME AND COULD NOT FAULT TRAVEL HBMI AND RETURN	1155.05	59.1	0	100	1314.15
191218-0046	SVC00238147	01/06/2020	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	30389 HR	REPLACE COOLANT	REPLACE COOLANT DRAIN WATER FROM UNIT AND FILL WITH COOLANT, RUN UNIT AND CHECK FOR LEAKS. TESTED OK TRAVEL BRIGHTON AND RETURN	204.25	614.64	0	50	868.89
191127-0050	SVC00236851	11/27/2019	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		TROUBLE SHOOT MACHINE	Trouble shoot machine, Remove belly plates and test machine as needed for oil leak.s and coolant leak.	1017.8	0	0	20	1037.8
190913-0024	SVC00232873	10/22/2019	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	NOT SUPPLIED	SUPPLY CUTTING EDGES	SUPPLY CUTTING EDGES AS REQUESTED TO BE STORED AT LA	0	3319.78	0	0	3319.78
191008-0030	SVC00234153	10/22/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507		INSPECT TRANS LEAK	INSPECT DOZER FOR OIL LEAKS, REMOVED SEAT AND FLOOR PANELS INSIDE CAB TO INSPECT FOR LEAKS, FOUND HYDRAULIC LEAKS AND TRANSMISSION LEAKS, CHECKED ENGINE FOUND OIL LEAKS COMING FROM AROUND MOTOR, REMVOED TRANSMISSION FILTER TO FIND IT FULL OF METAL, TAG OUT DOZER AND TO BE SENT TO HOBART WSHOP FAULTS AS LISTED: TRANSMISSION OIL LEAKS, HYDRAULIC OIL LEAKS, ENGINE OIL LEAKS, ENGINE PRESSURIZING CODING SYSTEM AND BLOWING BUBBLES INTO OVERFLOW BOTTLE	297.2	0	0	0	297.2
190930-0053	10061	10/08/2019	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507		RADIATOR LEAK - JOB CANCELLED		0	0	0	0	0
191002-0022	SVC00233917	10/08/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507	30360 HRS	TRANS BUZZER GOING OFF	TRAVELLED TO BEAUTY POINT, FIT NEW TRANS FILTER, START UP MACHINE AND BUZZER STILL ON, REMOVE AND CLEAN TRANS PRESSURE SWITCH, START UP AND BUZZER STILL GOING, REMOVE FILTER HOUSING AND FOUND BROKEN TEMP SWITCH, REFIT HOUSING, TEST ALL OK.	479.33	228.1	0	174	881.43
190904-0075	SVC00232434	09/30/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507	30193	OIL LEAK ON TRANSMISSION HOSE	TRAVEL TO RAEBURN, CHECK OIL LEAK AND REMOVE FLOOR COVER PLATE AND INSPECT, CLEAN HOSE FITTINGS AND TIGHTEN CLAMPS, TOP UP HYD OIL, REFIT FLOOR PLATE AND OPERATE MACHINE TO RECHECK FOR LEAK ALL OK	245.1	90.2	0	67	402.3
190917-0031	SVC00233032	09/27/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507		TRANS SENSORS	TRAVEL TO BEAUTY POINT. INVESTIGATE REPORTED TRANS SENDER FAULT. FOUND DAMAGED HARNESS. OBTAIN PORT, DROP BELLY PLATES AND FIT. REFIT BELLY PLATES	363.15	200.4	0	168	731.55
190920-0028	SVC00233231	09/27/2019	1H0103	ID - EARTHMOVING	192_INT	R	Ground Engaging	1ME507		TURN CUTTING EDGES AND FIT NEW	TRAVELLED TO BEAUTY POINT TURN CUTTING EDGES AND FIT NEW CORNERS	713.35	418.39	0	73.5	1205.24
190911-0034	SVC00233432	09/24/2019	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507		REPLACE CORNER TIPS	SUPPLY CORNER TIPS PARTS ONLY TO BE FITTED AT BEAUTY POINT BY CROSS ROADS	0	975.62	0	0	975.62

190829-0089	SVC00232048	08/29/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	30106	INSPECT NO DRIVE FAULT	1ME507-30106 HRS	0	0	1622.75	0	1622.75
											INSPECT NO DRIVE FAULT FROM TRANSMISSION, TESTED PUMP PRESSURE, ALL OK, TESTED TORQUE CONVERTOR PRESSURES AND LOCK UP, ALL OK, REMOVE VALVE BLOCK ON TOP OF TRANS, FOUND TO BE FULL OF SLUDGE THAT WAS BLOCKING SOME PORTS, TESTED CLUTCH PRESSURES AND FOUND TO BE EXTREMELY LOW FROM SPEC, CHECKED INSIDE TRANS AND IS FULL OF SLUDGE, TRANS NEEDS TO BE REMOVED AND REBUILT,					
190806-0051	SVC00230779	08/27/2019	1H0103	ID - EARTHMOVING	192_INT	S	Service	1ME507		2000HR SERVICE	TRANS REMOVED AND REBUILT ON S/C 190725-0045 TRAVEL TO RAEURN QUARRY, CARRIED OUT 2000 HR SERVICE AS PER SHEET	1106.15	2520.41	0	110	3736.56
190716-0005	SVC00229509	08/26/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507	30107hr	NO DRIVE IN TRANSMISSION	1ME507 30104hours.	10291.53	1028.11	0	1022	12341.64
											Assisted with the testing and removal of all componants. Spent many hours cleaning the entire transmission system internally. Traveled to hobart to contince with the repair of the transmission.					
190725-0045	SVC00230079	08/26/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	30107hr	REMOVE TRANSMISSION FOR REPAIR	1ME507 TRANSMISSION REPAIR POST CONTAMINATION IN THE TRANS OIL.	13435.58	22720.34	600	1114	37869.92
											The transmission lost drive, tested the machine and found the modulation spool in the transmission was stuck. The transmission filter was 4 hours oil and full of dirt type material. Disassmbled the transmission system on location, returned to Hobart with the removed items. All parts were cleaned and repaired as needed, full set of clutch plates, front housing due to wear in the seal area. all seals and gaskets were replaced, the bevel gear group was disassembled cleaned and reused. The transmission and convertor were reassembled as per the manual. returned to site and reinstalled into the cleaned out machine, refer to the Launceston job.					
190813-0036	SVC00231109	08/20/2019	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507		DRAIN AND REFILL RADIATOR	TRAVEL TO RAEURN, CHECK OIL IN COOLANT AND DRAIN, CHECK FOR OIL LEAK, DRAIN ENGINE OIL, REMOVE DRAIN PLUG ASSY,	1418.9	353.31	0	105	1877.21
190801-0036	SVC00230558	08/13/2019	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		REPAIR TRANSMISSION REMOVAL	REMOVE SIDE GUARDS AND COVERS, REMOVE ENGINE AND TRANSMISSION COOLERS, RETURN TO WSHOP. REPAIR TRANSMISSION REMOVAL ROLLERS, FABRICATESUPPORT JIG FOR REINSTALLING TRANSMISSION & CLEANUP DAMAGE TO INTERNAL SPLINE	654.3	0	0	33	687.3
190708-0090	SVC00229146	07/29/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507	30085	CHANGE TRANS OIL AND SCREEN	TRAVELLED TO RAEURN, GET OIL SAMPLE, DRAIN TRANS OIL, REMOVE MAIN FILTER SCREEN, CLEAN & REFIT, REMOVE BELLY PLATE, REMOVE MAIN SUCTION HOSE, REMOVE CLEANAND REFIT FILTER SCREEN, REFIT HOSE, MAKE UP LIFTING SYSTEM AND REFIT BELLY PLATE, REPLACE MAIN FILTER, FILL TRANSMISSION START AND OPERATE MACHINE, RECHECK OIL LEVEL, CLEAN WORK AREA, DECANT AND DISPOSE OF WASTE OIL, RETURN TO WSHOP.	581.6	1147.05	37.5	84	1850.15
190617-0024	SVC00228014	07/23/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507		REPAIR OIL AND COOLANT LEAKS	LOAD PARTS AND TOOLING AND TRAVEL TO LAUNCESTON. REMOVE COVERS AND BELLY PLATES. REMOVE RADIATOR CORES. REMOVE ENGINE FAN AND STRIP OUT FRONT OF ENGINE. REMOVE AND REPLACE TIMING COVER SEAL AND GASKETS. REPLACE SUMP GASKET. REFIT RADIATOR CORES. FILL WITH OIL AND WATER AND RUN ENGINE TO CHECK FOR LEAKS. REFIT ALL COVERS AND BELLY PLATES. OPERATE UNIT FOR PERIOD OF TIME AND DRAIN WATER FROM RADIATOR. REFILL WITH COOLANT. TRAVEL BACK TO LAMPTON AVENUE.	9852.61	3462.65	200	350	13865.26
190612-0009	SVC00227688	07/15/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507		SUPPLY TRANS FILTERS	SUPPLY TRANS FILTERS.	72.7	126.6	0	3.64	202.94
190702-0082	SVC00228907	07/10/2019	1H0103	ID - EARTHMOVING	192_INT	R	Transmission	1ME507		SUPPLY TRANS FILTER AND HOSE	PICK UP PARTS FROM SUPPLIER AND SUPPLY PARTS ONLY. PICK UP HYDRAULIC HOSE & FILTER, DROP OFF TO OPERATOR.	36.35	20.57	0	0	56.92
190624-0092	SVC00228256	07/04/2019	1H0103	ID - EARTHMOVING	192_INT	R	Electrical	1ME507		STARTER REPAIRS	1ME507 sub let and supply of starter motor	36.35	900	622.73	0	1559.08
190524-0021	SVC00226507	06/28/2019	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507		INSPECT OIL LEAKS @ RAEURN	INSPECT OIL LEAKS @ RAEURN.	230.5	213.93	0	62.5	506.93
											TRAVEL TO RAEURN SITE. LOOK AT OIL LEAKS. EMAIL INFORMATION TO RICKI DODGE. SUPPLY ENGINE OIL 20LTR GREASE AND USED INSPECTED FIRE EXTINGUISHER - CRAIG PAILTHORPE 10269					
190624-0105	SVC00228264	06/27/2019	1H0103	ID - EARTHMOVING	192_INT	R	Engine	1ME507	29999hr	DRAIN AND REFILL COOLANT	Drain the water and replace with coolant, Checked the dozer for cooant leaks prior to draining and once filled.	257.3	377.36	0	0	634.66
190517-0033	SVC00226040	06/12/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507		REPAIR RIPPER BOX	Replaced the bush guarding rubbers 1ME507-29834 HRS	703.53	115.2	0	68.75	887.48
190401-0102	SVC00224889	06/07/2019	1H0103	ID - EARTHMOVING	184_INT	R	Differential-FD	1ME507		CHANGE OIL IN BOTH FINAL DRIVE	PREP AND WELD IN NEW WEAR PLATES TO RIPPER BOX AT CATTLE HILL CHANGE THE OIL IN BOTH FINAL DRIVE AND SUPPLY 20LTR OF ENGINE OIL AS REQUESTED REPLACED RADIATOR CAP	122.55	289.49	0	0	412.04
190507-0080	SVC00225309	05/24/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507		S1 A SERVICE	S1 A SERVICE AS PER SERVICE SHEET BLOW OUT RADIATOR AND COOLER CORES CHANGE TRANSMISSION FILTER TRAVEL ON SITE CATTLE HILL	642.75	319.38	0	25	987.13
190517-0046	SVC00226046	05/24/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507		Repair UHF fault	REPAIR UHF FAULT CHECK UHF NOT TRANSMITTING CLEAR, TEST ANTENNA AND FOUND TO BE OK. REPLACE UHF AND FOUND TO BE OK REPLACED FAULTY WORK LIGHT TRAVEL CATTLE HILL TO LA	338.05	360.5	0	201	899.55
190511-0001	SVC00225496	05/15/2019	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	29960	REMOUNT TRIMBLE POLE	TRAVEL ONSITE AT CATTLE HILL, REMOVE TRIMBLE POLE, DRILL AND RETAP HOLES. REFIT POLE AND LOCTITE BOLTS IN TO STOP COMING LOOSE.	297.2	28.87	0	27.5	353.57
190410-0067	SVC00224895	04/29/2019	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	29704 HR	REPLACE DAMAGED LIFT CYLINDER	REPLACE DAMAGED LIFT CYLINDER TUBE REMOVE DAMAGED LIFT CYLINDER TUBE AND TEMPORARY REPAIR TO KEEP MACHINE WORKING TRAVEL TO BASHEN RD QUARRY REMOVE DAMAGED TUBE AND REPAIR AGAIN UNTIL NEW PART ARRIVES REMOVE AND REPLACE DAMAGED HYDRAULIC TUBE ON LIFT CYLINDER, TEST OPERATE AND CHECK FOR LEAKS, REFIT TOP COVER AND TOP UP HYDRAULIC OIL TRAVEL BASHAM QUARRY AND RETURN	1143.8	759.73	0	200	2103.53

190328-0042	SVC00223189	04/06/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507		REPLACE FAULTY ALTERNATOR	CHECK ENGINE LIGHT ON DISPLAY, BLOW DUST OUT OF ALTERNATOR AND TIGHTEN BELT. FOUND ALTERNATOR TO BE FAULTY. REMOVE AND REPLACE ALTERNATOR . TESTED OK REPLACE DAMAGED WORK LIGHTS TRAVEL ON SITE CATTLE HILL	408.5	688.46	0	57.5	1154.46
190312-0065	SVC00222139	03/27/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	29402	CHANGE TRANS FILTER & REPAIR S1 B SERVICE	CHANGE TRANS FILTER & REPAIR ENGINE OIL LEAK AT TIMING COVER	326.08	0	0	34.75	360.83
190318-0102	SVC00222498	03/27/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507		S1 B SERVICE	S1 B SERVICE AS PER SERVICE SHEET TRAVEL ON SITE CATTLE HILL	376.05	465.8	0	30.5	872.35
190301-0008	SVC00221602	03/16/2019	1H0103	ID - EARTHMOVING	184_INT	R	Air Con	1ME507	29405	REPAIR AIR CON SYSTEM, HOSE	Traveled to Ashdown, collected hose and fittings. Fabricate new hose as required to replace U/S hose.	581.65	309.02	0	155	1045.67
190304-0020	SVC00221761	03/16/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	29387	REPAIR GPS CABLE FAULT	REPAIR GPS CABLE FAULT, REPLACED PLUGS ON GPS CABLE, LOCATE AND REPAIRED SHORT IN WIRING	326.8	0	0	28.5	355.3
181112-0072	SVC00215329	03/14/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	28844 HRS	REPLACE LEAKING RADIATOR SEALS	TRAVELLED ONSITE CATTLE HILL REPLACE LEAKING RADIATOR SEALS REMOVE RADIATOR SEGMENTS AND REPLACE SEALING RUBBERS	612.2	0	0	43	655.2
181112-0072	SVC00215666	03/14/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	28844 HRS	REPLACE LEAKING RADIATOR SEALS	REPLACE LEAKING RADIATOR SEALS REMOVE RADIATOR SEGMENTS AND REPLACE SEALING RUBBERS TRAVEL ON SITE CATTLE HILL	1905.75	2422.33	0	75	4403.08
190201-0061	SVC00219914	03/14/2019	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507		S1 A SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET	704.93	353.64	0	47.5	1106.07
190225-0051	SVC00221064	02/27/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	29349	REMOVE TRANS FILTER & CHECK	REMOVE TRANS FILTER & CHECK FOR BLOCKAGES DUE TO LIGHT COMING ON, REFIT FILTER AS THIS IS A LOWER MICRON THAN STANDARD TO BE USED FOR CLEANING OUT PAINT CONTAMINATION.	81.7	28.16	0	12.5	122.36
190212-0045	SVC00220301	02/23/2019	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507		REPLACE HYD HOSE ON TOOL BAR	REPLACE HYD HOSE ON TOOL BAR REMOVE AND REPLACE DAMAGED HOSE ON TOOL BAR, TOP UP WITH HYDRAULIC OIL AND TEST OPERATE TRAVEL TO CATTLE HILL	204.25	410.63	0	125	739.88
190206-0038	SVC00220919	02/22/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507		CHANGE TRANSMISSION OIL AND	CHANGE TRANSMISSION OIL AND FILTER AS REQUESTED BY CAPPO CHANGE TRANSMISSION OIL AND FILTER AFTER BAD SAMPLE REMOVE AND REPLACE LEAKING RUBBER SEALS ON RADIATOR SEGMENTS, FILL WITH COOLANT AND TEST OPERATE TO CHECK FOR LEAKS. TESTED OK TRAVEL ON SITE CATTLE HIL	801.45	1004.57	0	65	1871.02
190213-0040	SVC00220390	02/22/2019	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507		REPLACE AM/FM RADIO & REFIT TR	REPLACE AM/FM RADIO & REFIT TRIMBLE POST REMOVE AND REPLACE AM/FM RADIO CHECK GPS FAULT TIGHTEN HOSE CLAMPS ON RADIATOR TRAVEL TO CATTLE HILL	621.15	176.2	0	145	942.35
190131-0037	SVC00219678	02/19/2019	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	29249	REPLACE DAMAGED AIR INTAKE PRE	REPLACE DAMAGED AIR INTAKE PRE CLEANER, CLEAN OUT COOLERS AND FILTERS, SUPPLY SPARES CHWF	408.5	587.2	0	187.5	1183.2
181218-0062	SVC00218123	02/08/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	29174	REPLACE EXHAUST CLAMP	REPLACE EXHAUST CLAMP. TOP UP ENGINE OIL	538.55	94.05	0	38.5	671.1
190118-0040	SVC00218893	01/31/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	29191 HRS	CHANGE TRANS FILTER, FIT SWITC	REMOVE AND REPLACE FILTER SENSOR SWITCH ON FILTER HOUSING REPLACE TRANSMISSION FILTER AND SAMPLE TRANSMISSION OIL TRAVEL ON SITE CATTLE HILL	378.9	18.84	0	31.5	429.24
181121-0011	SVC00215976	01/25/2019	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507		REPAIR, REPLACE COOLANT TUBE	CLEAN OUT RADIATOR REMOVE COOLANT TUBE AND HAVE REPAIRED , REFIT TO MACHINE AND CHECK FOR LEAKS. ORDER NEW TUBE REPLACE LEAKING RADIATOR SEALING RUBBERS AND REPLACE COOLANT TUBE. TEST OPERATE AND CHECK FOR LEAKS TRAVEL ON SITE CATTLE HILL	970.05	636.91	0	82.5	1689.46
181214-0036	SVC00217355	01/25/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507		RESAMPLE TRANS AS PER CAPPO	RESAMPLE TRANS AS PER CAPPO, AND CHANGE FILTER AFTER BAD SAMPLE FILTER FITTED WAS CLEAN UP FILTER TRAVEL ON SITE CATTLE HILL	109.05	165.71	0	25	299.76
190107-0031	SVC00218453	01/10/2019	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507		CHANGE TRANS FILTER AND TAKE	CHANGE TRANS FILTER AND TAKE SAMPLE OF OIL TRAVEL CATTLE HILL	133.8	0	0	62.5	196.3
181214-0044	SVC00217361	12/19/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	29062	REPLACE BROKEN BOLTS IN TRIMBL	TRAVEL ONSITE CATTLE HILL, REPLACE BROKEN BOLTS IN TRIMBLE POSTS	326.8	0	0	58.5	385.3
181010-0023	SVC00214804	12/13/2018	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507		REPLACE DOOR SEAL AND GLASS	REMOVE AND REPLACE DAMAGED DOOR GLASS. REPLACE DAMAGED DOOR SEALS TRAVEL ON SITE CATTLE HILL	232.63	626.79	0	12.5	871.92
181109-0052	SVC00215677	12/13/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	28996 HRS	REAR IDLER LEAKING	REAR IDLER LEAKING CHECK LEFT REAR IDLER AND FIT GREASE NIPPLE TO KEEP IDLER LUBRICATED UNTIL NEW PART ARRIVES PUMP GREASE INTO IDLER DAILY UNTIL REPLACED BREAK TRACK AND REMOVE IDLER, REMOVE BROKEN RETAINING BOLT AND FIT NEW IDLER. FIT AND TENSION RETAINING CAPS AND BOLTS. REFIT TRACK AND ADJUST TO SUIT TRAVEL ON SITE CATTLE HILL	876.6	1951.88	0	40	2868.48
181122-0039	SVC00215954	12/13/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	28998	S1 B SERVICE AS PER SERVICE SH	TRAVEL ON SITE TO CATTLE HILL CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET	650.71	559.99	0	50	1260.7
181213-0001	SVC00217249	12/13/2018	1H0103	ID - EARTHMOVING	121_INT	R	Ground Engaging	1ME507		SUPPLY SPARE BOOTS PINS & RET	SUPPLY SPARE BOOTS PINS & RETAINERS	0	990	0	0	990
181128-0071	SVC00216640	12/12/2018	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	28925 HR	REPLACE MISSING NOSE CONE PIN	TRAVEL TO CATTLE HILL. CHECK REPORTED NOSE CONE LOOSE AND ORGANISE REPAIR REMOVE BELLY PLATE, REPLACE LEFT HAND BOTTOM NOSE CONE PIN AND REFIT BELLY PLATE.	367.65	537.6	0	168	1073.25
181126-0078	SVC00216145	11/30/2018	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507		INSPECT TRANS LIGHT FAULT	TRAVELLED TO CATTLE HILL, CHECKED FOR TRANSMISSION SCREENS UNDER FLOOR AND AROUND TRANSMISSION, REMOVED FLOOR ETC AND HAS ONE AT BACK THAT REQUIRES DRAINING TO CHANGE, FOUND FAULT WITH FILTER SENSOR, CLEAN OUT AND REFIT, TESTED OK.	449.35	0	0	85	534.35

181005-0066	SVC00213336	11/19/2018	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	28630 HRS	REPAIR OIL IN COOLANT FAULT	TRAVEL CATTLE HILL AND RETURN TWICE CHECK OIL IN COOLANT, FOUND TO BE TRANSMISSION OIL. FLUSH RADIATOR WITH SOAPY WATER THREE TIMES TO REMOVE OIL FROM SYSTEM. DRAIN RADIATOR AND REMOVE ENGINE SIDE COVERS. REMOVE BELLY PLATE TO GAIN ACCESS TO TRANSMISSION COOLER. REMOVE AND REPLACE TRANSMISSION COOLER WITH EXCHANGE UNIT, REFIT ENGINE COOLER AND FILL UNIT WITH WATER. REMOVE IDLER PULLEY , STRIP AND RECONDITION WITH NEW BEARINGS , SEALS AND SHAFT. REFIT IDLER ASSEMBLY AND FIT NEW FAN BELTS. RUN UNIT AND FLUSH RADIATOR WITH SOAPY WATER UNTIL OIL RESIDUE GONE FROM SYSTEM OVER THREE OR FOUR DAYS AND FILL WITH COOLANT	4184.33	4816.23	0	665	9665.56
181105-0140	SVC00215398	11/13/2018	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	28800 HRS	CHANGE TRANSMISSION FILTER	DRAIN TRANSMISSION AND FILL WITH NEW OIL AFTER WATER DETECTED IN OIL , CHANGE TRANSMISSION FILTER TRAVELLED ONSITE CATTLE HILL, CHECK OVER HEATING FAULT, FOUND TRANSMISSION FILTER BLOCKED. CHANGED FILTER AND OPERATED OK.	163.4	55.84	0	20.5	239.74
181105-0043	SVC00215033	11/05/2018	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	28734hr	CHECK TRANSMISSION O/HEAT FAUL	1me704 trouble shoot transmission over heat, Removed covers and checked the oil cooler temps 101c in and 85c out. Checked the transmission pressure 456PSI at low idle Removed the cab floor plate and checked the brake pressures. 440PSI at low idle and 12PSI with brake applied. Spec is 10PSI. Drained 30lt from the transmission as it was slightly over full. Changed the transmission oil filter	765.8	0	0	38	803.8
181001-0049	SVC00212941	10/30/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	28608	REPLACE LEAKING RADIATOR SEALS	REPLACE LEAKING RADIATOR SEALS REMOVE RADIATOR CORE AND REPLACE RUBBER SEALS, REFIT CORE AND FILL WITH COOLANT. TEST FOR LEAKS AND TESTED OK	717.65	925.47	0	60	1703.12
181017-0134	SVC00213836	10/26/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	28724 hr	S1 A SERVICE	COOLANT SUPPLIED TO OPERATOR S1 A SERVICE AS PER SERVICE SHEET REPLACE MISSING LIFT CYLINDER GUARD BOLTS REPLACE MISSING SIDE PANEL BOLTS TRAVEL CATTLE HILL	484.5	277.1	0	86.5	848.1
181011-0031	SVC00210590	10/18/2018	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE NEW PIN FOR JOCKEY	MACHINE NEW PIN FOR JOCKEY PULLEY	145.4	12.74	0	7	165.14
180917-0042	SVC00211907	09/20/2018	1H0103	ID - EARTHMOVING	182_INT	A	Sundries	1ME507		REPAIR RIPPER NOSE	Build up ripper nose used with out boot.	581.6	165	0	20	766.6
180903-0049	SVC00211228	09/11/2018	1H0103	ID - EARTHMOVING	184_INT	R	Service	1ME507	28468 HRS	S1 B SERVICE	TRAVELLED TO CATTLE HILL. CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET.	650.7	500.97	0	225	1376.67
180828-0082	SVC00210828	08/31/2018	1H0103	ID - EARTHMOVING	121_INT	R	Engine	1ME507		Engine oil	ENGINE OIL SHIN GUARDS RETAINER PINS	0	418.8	0	0	418.8
180828-0063	SVC00210803	08/28/2018	1H0103	ID - EARTHMOVING	121_INT	R	Ground Engaging	1ME507		RIPPER BOOT PIN & RETAINER	RIPPER BOOT, PIN & RETAINER	0	165	0	0	165
180806-0042	SVC00209523	08/27/2018	1H0103	ID - EARTHMOVING	182_INT	B	Sundries	1ME507		BUILD UP RIPPER NOSE	Build up worn ripper nose as to suit new adaptor.	167.85	0	0	8	175.85
180807-0026	SVC00209577	08/09/2018	1H0103	ID - EARTHMOVING	121_INT	R	Sundries	1ME507		SUPPLY 1 X 20LTR HYD OIL	7/08/18 REQ 103-9912 KEVIN CORDWELL 1 X 20 LTR HYD OIL	0	0	0	0	0
180807-0026	SVC00209813	08/09/2018	1H0103	ID - EARTHMOVING	121_INT	R	Sundries	1ME507		SUPPLY 1 X 20LTR HYD OIL	SUPPLY HYDRAULIC OIL AND MIXED RAGS	0	105.7	0	0	105.7
180809-0079	SVC00209799	08/09/2018	1H0103	ID - EARTHMOVING	121_INT	R	Trays/Buckets	1ME507		4T5452. RIPPER BOOTS X 4	4T5452. RIPPER BOOTS X 4 PINS X 4 + RETAINERS X 4	0	660	0	0	660
180703-0052	SVC00208000	07/18/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	NA	SUPPLY SPARE FAN BELTS	PARTS ONLY -- SUPPLY SPARE FAN BELTS	0	239.12	0	0	239.12
180625-0055	SVC00207137	07/04/2018	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	28215 HRS	S1 A SERVICE	TRAVELLED TO WADDAMANA, CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET, TIGHTEN ALT BELT	484.5	276.72	0	254	1015.22
180625-0028	SVC00207117	06/26/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	28171 HRS	CHECK OIL LEAK	CHECK OIL LEAK ON FRONT OF ENGINE NEAR TIMING COVERS, CHECK UNIT OVER WHILE ON SITE TRAVEL CATTLE HILL	81.7	0	0	50	131.7
180621-0064	SVC00207061	06/22/2018	1H0103	ID - EARTHMOVING	121_INT	R	Engine	1ME507		SUPPLY ENGINE OIL	SUPPLY ENGINE OIL	0	89.8	0	0	89.8
180409-0036	SVC00202875	06/14/2018	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		WELD REPAIR CRACKS	Repair various cracks in and around cab and rop mounts. Repair splits down both sides of cab entry platform. Grind and repair belly plate hinges. Repair cracks around ripper box frame. Prep draft arm for reskin RHS. Cut and fabricate plates for draft arm reskin. Gouge and repair cracks in and around draft arm pre-reskin. Fabricate skin plates to draft arms. Weld out new skin plates. Straighten belly plates. Cut and fabricate new top plates to top of blade horns.	1935.37	371.03	0	50	2356.4
180608-0060	SVC00206299	06/12/2018	1H0103	ID - EARTHMOVING	121_INT	R	Engine	1ME507		SUPPLY COOLANT 20 LTR	SUPPLY COOLANT 20 LTR CRAIG PAILTHORPE PICKED UP BY KEVIN CORDWELL	0	96.98	0	0	96.98
180601-0058	SVC00206020	06/04/2018	1H0103	ID - EARTHMOVING	121_INT	R	Hydraulic	1ME507		SUPPLY HYD OIL, GREASE & BLUE GREASE	SUPPLY HYD OIL, GREASE & BLUE GREASE ISSUED TO KEVIN CORDWELL	0	150.3	0	0	150.3
180227-0022	SVC00201043	05/22/2018	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507	27957 HRS	REPAIR TRACKS	FABRICATE BOGIE STRAPS AND SECURE IN PLACE, JACK UP MACHINE AND SPLIT TRACKS. REMOVE TRACKS AND ROLL UP FOR DELIVERY TO WILLIAM ADAMS. WILLIAM ADAMS WET TURN TRACK PIN AND BUSH. REMOVE AND REPLACE SPROCKET SEGMENTS, REFIT TRACKS AND ADJUST TO SPECS. REPLACE MISSING TRACK GUIDE.	3825.26	2778.2	23667.86	290.1	30561.42
180308-0041	SVC00201690	05/22/2018	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	27957 HRS	REPAIR RIPPER BOX	REMOVE RIPPER CYLINDERS, RIPPER BOX AND H FRAME. REMOVE RIPPER BOX MOUNTING BRACKETS,RESEAL LEFT LOWER CYLINDER FIT NEW BUSHES AND SEALS IN RIPPER BOX FRAME, REFIT RIPPER BOX MOUNTING BRACKETS, H FRAME AND RIPPER BOX. REMOVE LEFT AND RIGHT DRAFT ARMS, HAVE PLATED ON SIDE AND BOTTOM AND REFIT. REMOVE SECOND BELLY PLATE AND PRESS DENT OUT IN BOTTOM, FOUND FRONT ENGINE SUMP LEAKING, REMOVE SUMP , HAVE CRACKS WELDED AND REFIT. REFIT BELLY PLATE, REPLACED DRAFT ARM TRUNION BOLTS.	7527.43	3264.64	0	50	10842.07

180416-0052	SVC00204172	05/21/2018	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	27957 HRS	S1 D SERVICE	CARRIED OUT S1 D SERVICE AS PER SERVICE SHEET, REPLACE WIPER BLADES, REPLACE PIVOT SHAFT PLUGS	856.2	1280.09	0	48	2184.29
180504-0002	SVC00204297	05/15/2018	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	28003 HRS	CHECK OIL LEAK	TRAVELLED TO TUNBRIDGE, REMOVE AND REPLACE LEAKING O RINGS ON RIPPER CYLINDER HOSE FITTING, SUPPLY OPERATOR WITH 20 LITRES OF COOLANT	80.35	92.57	0	37.5	210.42
180316-0017	SVC00201699	04/27/2018	1H0103	ID - EARTHMOVING	182_INT	R	Line Boring	1ME507		LINE BORE RIPPER BOX & MOUNTS	LINE BORE RIPPER BOX & MOUNTS, WELD UP CRACKS, HONE RIPPER LIFT CYLINDER & RECHROME ROD	6335.08	170.4	480	50	7035.48
180122-0017	SVC00198896	02/26/2018	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		REPAIR CRACKS IN SIDE ARMS	Strip down and prep LHSarm for repairs and reskin. Gouge and repair cracking in mid section of arm. Grind and prep arm for welding. Cut and fabricate skin to side arm. Weld out skin. Fabricate and reweld side step back to side arm. Sand and tidy up all welds.	1610.21	174.28	0	75	1859.49
180207-0021	SVC00199871	02/20/2018	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	27,899 HRS	SUPPLY RIPPER INSTALL RIPPER B	SUPPLY RIPPER INSTALL RIPPER BOOT.	376.58	578.96	0	106.33	1061.87
180209-0012	SVC00199947	02/20/2018	1H0103	ID - EARTHMOVING	187_INT	R	Transmission	1ME507	27,899 HRS	Transmission Repair	TRAVEL TO LONG HILL QUARRY. FIT NEW RIPPER BOOTS AND PINS. FIT 2ND RIPPER TO RIPPER BOX. TRANSMISSION REPAIR.	204.63	31.49	0	97.73	333.85
180110-0045	SVC00198435	01/31/2018	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	27820	REPLACE LEAKING SUMP GASKET	TRAVEL TO LONG HILL QUARRY. DIAGNOSE TRANS LIGHT FAULT. CHECKED OIL LEVEL & FILTER. FOUND FILTER TO BE BLOCKED. REMOVED AND REPLACED. REMOVED BELLY PLATES TO GAIN ACCESS TO SUMP, REMOVE SUMP AND CLEAN ALL SURFACES,REPLACE SUMP GASKET AND REFIT SUMP, FILLED WITH OIL AND TEST RUN, FOUND LEAK AT FRONT SECTION, REMOVED FRONT SECTION OF SUMP AND RESEAL, REFIT SUMP AND FILL WITH OIL AND TEST RUN, TESTED OK, REPAIRED OIL LEAK AT FRONT TIMING COVER, CHANGE OIL FILTER AND REFIT BELLY PLATES	3920.68	472.38	0	50	4443.06
180110-0046	SVC00199419	01/31/2018	1H0103	ID - EARTHMOVING	186_INT	R	Suspension/UC	1ME507	27820 HRS	REPAIR SIDE ARMS	REMOVED R/HAND SIDE PUSH ARM AND TILT CYLINDER TO ALLOW REPAIRS TO ARM, REFIT ARM AND CYLINDER AFTER WELDING REPAIRS FINISHED, REMOVED RADIATOR DOORS TO ALLOW REPAIRS TO FRONT BELLY PLATE, RESHIM RIPPER BOX PINS, REFIT RADIATOR DOORS AFTER REPAIRS	2102.58	0	0	50	2152.58
171206-0061	SVC00195306	12/28/2017	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507		REPLACE REACTION ARM ON TORQU	REPLACE REACTION ARM ON TORQUE MULTIPLIER	0	0	0	784	784
171122-0030	SVC00196135	12/19/2017	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	27557 HRS	REPLACE CANOPY RUBBERS	CHECKED AND REPLACED CANOPY RUBBERS	80.35	123.44	0	0	203.79
171211-0001	SVC00197579	12/19/2017	1H0103	ID - EARTHMOVING	184_INT	R	Differential-FD	1ME507	27756 HRS	CHECK FINAL DRIVE OIL	TRAVELLED TO TUNBRIDGE, REMOVED ENGINE SIDE COVERS AND REMOVE SEALANT ON TIMING COVER CLEANED SURFACES AND RESEAL, REFIT COVERS REPLACE FAULTY TOP COVER ON HYDRAULIC TANK, REPLACE MISSING BOLTS TO SECURE GRILL, REPLACE RUBBER MOUNTS ON ROPS FRAME, CHECKED FINAL DRIVE AND TRANSMISSION OIL LEVELS, DRAIN AND FILL TO CORRECT LEVELS.	686.73	145.03	0	334	1165.76
171123-0100	SVC00196308	12/13/2017	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	27600 HRS	REPAIR OIL LEAKS	TRAVELLED TO HBMI, REMOVED PANELS AROUND HYDRAULIC TANK, REPLACE LOOSE AND MISSING BOLTS. TIGHTEN LOOSE TANK FLANGE BOLTS, REFIT PANELS AROUND HYDRAULIC TANK, REMOVE AND REPLACE BROKEN PANEL BOLTS ***SUPPLIED OIL 20 LTR TO KEVIN CORDWELL AS REQUESTED BY CRAIG	1439.89	409.74	0	87.5	1937.13
171205-0037	SVC00196921	12/13/2017	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	27757HRS	S1 A SERVICE	TRAVELLED TO TUNBRIDGE, CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET, WELD UP CRACKS IN PUSH ARMS	749.7	281.21	0	292.5	1323.41
171128-0030	SVC00196770	12/06/2017	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507		SUPPLY RIPPER BOOTS	SUPPLY RIPPER BOOTS PARTS ONLY	0	479.72	0	0	479.72
171127-0118	SVC00196768	12/04/2017	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	27689 HRS	REPLACE CUTTING EDGES	TRAVELLED TO HBMI, SET UP BLADE ON BLOCKS AND REMOVE OLD CUTTING EDGES, CLEAN UP BLADE AND NEW EDGES. BOLT EDGES TO BLADE AND TENSION ALL BOLTS.	482.1	339.24	0	61.5	882.84
171010-0045	SVC00193985	12/01/2017	1H0103	ID - EARTHMOVING	180HARDOX	H	Cut Plate Sale	1ME507		HARDOX 40MM CUTTING EDGE	HARDOX 40MM CUTTING EDGE	2222.4	814.59	0	0	3036.99
171106-0035	SVC00195302	11/27/2017	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE SHIMS FOR TOOLBAR	HARDOX450 - 2 @ 825mm x 330mm x 40mm HARDOX450 - 2 @ 910mm x 330mm x 40mm MACHINE SHIMS FOR TOOLBAR	439.53	80.11	0	24.5	544.14
171106-0004	SVC00195324	11/06/2017	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	27584 HRS	REPAIR CRACKS IN TOOL BAR	TRAVELLED TO HBMI, GOUGE OUT CRACKS IN BRAW BAR AND REWELD, REMOVE DAMAGED BOLTS FROM SIDE COMBING AND RETAP HOLES TO 5/8 IN TO ALLOW NEW BOLTS TO BE FITTED GOUGE OUT CRACKS UNDER FUEL TANK AND REWELD	638.4	0	0	107	745.4
171010-0028	SVC00194569	10/24/2017	1H0103	ID - EARTHMOVING	186_INT	R	Ground Engaging	1ME507	NA	SUPPLY RIPPER BOOTS	SUPPLY RIPPER BOOTS AND CORNER TIPS	0	1756.88	0	0	1756.88
171016-0092	SVC00194192	10/24/2017	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	27522 HRS	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET CHECK FOR HYDRAULIC OIL LEAK AND TOPP UP HYDRAULIC OIL REPLACED SIDE PANEL BOLT AND WASHER NOTE RIPPER PINS NEED REPLACING, CRACKS IN GRILL BRACKETS, HYDRAULIC TANK IS MOVING AROUND, ALL PANELS ARE LOOSE, CANOPY BOLTS ARE MISSING, ENGINE OIL LEAK FRONT TIMING COVER UNDER FUEL PUMP	401.75	509.05	0	125	1035.8
170815-0002	SVC00190953	10/10/2017	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	27125	REPAIR TRIMBLE POST MOUNT	REPAIR TRIMBLE POST MOUNT, REMOVE AND REPLACE BROKEN BOLTS, CLEAN UP MOUNTING SURFACE, REPLACE WIPER BLADES	120.53	8.4	0	0	128.93
171002-0006	SVC00193515	10/03/2017	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	27413	REPAIR WORN BLADE CORNERS	TRAVELLED TO HBMI X 2, REPAIRED OUTSIDE EDGES OF BLADE WHERE IT HAD WORN PAST WEAR PLATES	1256.68	0	0	237.5	1494.18
170919-0050	SVC00192800	09/27/2017	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	27304	REPLACE CAB GUARDING BOLTS	TIGHTEN LOOSE CAB GUARDING BOLTS AND REPLACED MISSING BOLTS.	80.35	0	0	0	80.35
170905-0021	SVC00192080	09/12/2017	1H0103	ID - EARTHMOVING	187_INT	R	Engine	1ME507		top up coolant	TOPPED UP COOLANT AND INSPECT FOR LEAKS	40.18	46.26	0	0	86.44

170630-0060	SVC00188585	08/30/2017	1H0103	ID - EARTHMOVING	187_INT	R	Exhaust	1ME507	26939 HRS	REPAIR MUFFLER	REPAIR MUFFLER. TRAVELLED TO UNIT AT FLOWERDALE. REMOVED MUFFLER FROM UNIT AND RETURNED TO W/SHOP. WELD UP BROKEN MUFFLER. RETURNED TO FLOWERDALE AND REINSTALLED MUFFLER TO UNIT. TEST FOR LEAKS ALL OK. RETURNED TO W/SHOP. NEW GUENUINE MUFFLER ORDERED. AS PER REQUEST.	648.55	1267.94	0	132.43	2048.92
170803-0024	SVC00190345	08/28/2017	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	27236	S1 C SERVICE	CARRIED OUT S1 C SERVICE AS PER SCHEDULE. REPLACED LEAKING ORING ON FUEL RETURN HOSE FITTING ON FUEL PUMP	822.26	914.48	0	46	1782.74
170803-0032	SVC00190350	08/22/2017	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	27110	REPLACE BLOWN LIFT CYL HOSE	2/8/17 CHECKED HYDRAULIC LEAK AT RH LIFT CYLINDER, FOUND HOSE U/S, ENZED CALLED IN TO REPAIR HOSE, REFIT HOSE AND COVERS, 3/8/17 RECHECK HYD HOSE AS REPORTED LEAKING, CALLED ENZED BACK TO FAB NEW HOSE.	212.13	79.22	505.96	10.5	807.81
170629-0066	SVC00187739	07/11/2017	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	26,965hr	REPLACE CORNER TIPS, TURN CENT	REPLACE CORNER TIPS. CHANGE OUT CORNER TIPS AND NUTS & BOLTS. TURN CENTRE EDGES. TORQUE BOLTS & NUTS TO SPEC.	937.3	1332.76	0	79.69	2349.75
170628-0046	SVC00188480	07/06/2017	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	26,929 hrs	REPAIR ALTERNATOR LUME	REPAIR ALTERNATOR LUME. REPAIR WIRE LUME CONNECTED TO THE BACK OF THE ALTERNATOR.	80.35	0	0	41.52	121.87
170703-0109	SVC00188723	07/06/2017	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	N/A	Supply Box Of Grease	SUPPLY BOX (10) OF GREASE. PARTS ONLY.	0	34.8	0	0	34.8
170602-0022	SVC00187309	06/19/2017	1H0103	ID - EARTHMOVING	187_INT	R	Radiator	1ME507	26858	REPAIR RADIATOR CORE	REPAIR RADIATOR CORE, REMOVE LEAKING LHS CORE NUMBERS 1, 2 & 3, REPLACE NO 1 WITH NEW CORE, REPLACE SEALS ON NUMBERS 2 & 3, FILL UP WITH COOLANT AND CHECK FOR LEAKS.	321.4	1457.94	0	16	1795.34
170609-0034	SVC00187576	06/19/2017	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	26858	S1 A SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPCTIONS AS PER SERVICE SCHEDULE FOUND AN OIL LEAK AT ENGINE DRAIN, REMOVED AND REPLACED FAULTY O-RING REMOVED THE BELLY PLATE UNDER THE SUMP AND STRAIGHTENED AND REFITTED NOTE TRACK GUIDE SHOES ARE GETTING LOW AND WILL REQUIRE REPLACING SOON	334.78	500.91	0	17	852.69
170324-0007	SVC00183657	05/30/2017	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	26853	REPLACE CANOPY RUBBERS & STEPS	CUT OFF BROKEN PUSH ARM STEP AND WLED ON NEW ONE, WELD UP CRACKS IN RH PUSH ARM AND WELD ON NEW STEP, WELD CRACKS UNDER LH WALKWAY, REFIT LEFT REAR NOSE CONE PIN AND RETAINER.	723.15	325.13	0	36	1084.28
170518-0029	SVC00186305	05/23/2017	1H0103	ID - EARTHMOVING	187_INT	R	Tyres	1ME507	26740	RETENSION LHS TRACK LINK	INSPECT MACHINE WHEN RETURNED TO SITE AND FOUND LHS TRACK MASTER LINK LOOSE, REMOVED MASTER LINK BOLTS, CLEANED UP THREADS, REFIT BOLTS AND TENSION TO SPEC.	160.7	0	0	0	160.7
170321-0010	SVC00183448	04/18/2017	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	26583	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SCHEDULE	330.03	507	0	21.5	858.53
170410-0008	SVC00184595	04/18/2017	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	26583	REPLACE CUTTING EDGES	REPLACE CUTTING EDGES, PARTS SUPPLIED BY MMG PROJECT	370.2	0	0	18.5	388.7
170303-0018	SVC00182625	03/15/2017	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507		REPLACE RIPPER BOOT & SHIN GUA	REPLACE RIPPER BOOT & SHIN GUARD, PARTS SUPPLIED BY MMG PROJECT	80.35	0	0	0	80.35
170203-0044	SVC00181187	02/28/2017	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	26282	REPLACE BLADE CYLINDER HOSE	REPLACE LEAKING BLADE CYLINDER HOSE WITH SPARE HOSE	120.53	52.9	0	6	179.43
170210-0012	SVC00181420	02/28/2017	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	26310	REPLACE FAULTY BATTERY ISOLATO	CHECKED SLOW CRANKING FOUND EARTH LEAD FROM ALTERNATOR HOUSING TO ENGINE LOOSE, REPLACED EYE FITTING AND RECHECKED CHARGE RATE	241.05	104.3	0	12	357.35
170222-0068	SVC00182050	02/28/2017	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	26345	REPLACE PUSH ARM STEPS	CHECKED AND RESECURE PUSH ARM STEP, CHECKED CRACKS IN PUSH ARMS, MEASURE FOR PUSHING	80.35	0	0	0	80.35
170206-0002	SVC00181203	02/08/2017	1H0103	ID - EARTHMOVING	187_INT	R	Exhaust	1ME507	26287	WELD UP BROKEN MUFFLER	REMOVED MUFFLER ASSY FROM MACHINE AND WELD UP INLET PIPE, REFIT TO MACHINE	200.88	0	0	10	210.88
170201-0016	SVC00181077	02/07/2017	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507		REPLACE RIPPER BOOT, PARTS SUP	REPLACE RIPPER BOOT, PARTS SUPPLIED BY MMG PROJECT, CHANGE OUT RIPPER SHANK	80.36	0	0	0	80.36
170202-0016	SVC00167538	02/07/2017	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	26275	S1 A SERVICE	CARRIED OUT S1 A 250 HR SERVICE, DRAINED AND REFILLED ENGINE OIL AND REPLACED OIL FILTER, CHECKED ALL OIL LEVELS, CLEANED FUEL SEDIMENT BOWL, REPAIRED BROKEN WIRE ON LEFT FRONT WORK LIGHT	160.7	245.14	0	5	410.84
170113-0020	SVC00180226	01/23/2017	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	26213	FIT NEW CORNERS & ROTATE EDGES	REMOVED CORNER TIPS AND CENTRE EDGES, FIT NEW CORNER TIPS AND ROTATE CENTRE CUTTING EDGES, TIGHTEN CUTTING EDGE BOLTS TO SPEC, REPLACED 2 MISSING TRACK SHOE BOLTS.	450.56	0	0	22.5	473.06
161125-0032	SVC00178051	01/11/2017	1H0103	ID - EARTHMOVING	187_INT	R	Differential-FD	1ME507	26127	REPLACE U/S LHS FINAL DRIVE	REPLACE U/S LHS FINAL DRIVE RECONDITION AFTER FAILURE FINAL DRIVE & BRAKE WHEEL. DISASSEMBLE FAILED FINAL DRIVE, CLEAN AND INSPECT ALL PARTS FOR REUSABILITY, CUSTOMER SOURCED SECOND HAND SPINDLE, OTHER PARTS ORDERED. FINAL DRIVE ASSEMBLED WITH NEW SEAL, BEARINGS, ETC AND ALL REQUIRED NEW GEARS AND HOUSINGS/CARRIERS TO CAT SPEC. SUPPLIED MOUNTING ORING SEAL AND TRACK MASTER BOLTS AS REQUESTED. CARRIED OUT BY WILLIAM ADAMS.	1099.1	6850	21884.37	50	29883.47
161209-0053	SVC00179286	12/19/2016	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	26127	WELD UP CRACKS IN STEPS	WELD UP CRACKS UNDER LHS CAB LANDING	241.05	0	0	12	253.05
161104-0010	SVC00177040	12/06/2016	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	26025	S1 D SERVICE	CARRIED OUT S1 D SERVICE AS PER SCHEDULE, DRAINED AND REFILLED ENGINE OIL AND FUEL FILTER, CLEANED PRE FILTER SCREEN, DRAINED AND REFILLED FINAL DRIVES, CHANGE TRANS OIL AND FILTERS	361.58	2051.31	0	23	2435.89
161103-0031	SVC00176978	11/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	26007	REPLACE BATTERY TERMINALS	REPLACE BATTERY TERMINALS	43.05	40	0	0	83.05
161110-0048	SVC00177310	11/14/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	26060	REPLACE RIPPER BOOT	REPLACED RIPPER BOOT, PARTS SUPPLIED BY MMG PROJECT	80.35	0	0	0	80.35
160721-0063	9831	11/09/2016	1H0103	ID - EARTHMOVING	187_INT	R	Exhaust	1ME507	25575	REPAIR EXHAUST LEAK		0	-540.46	0	0	-540.46
160721-0063	SVC00171470	11/09/2016	1H0103	ID - EARTHMOVING	187_INT	R	Exhaust	1ME507	25575	REPAIR EXHAUST LEAK	TRAVELLED TO WORK SITE, CHECKED EXHAUST LEAK AT MUFFLER, FOUND ELBOW FROM TURBO WORN OUT, REMOVED MUFFLER ASSEMBLY, FIT NEW MUFFLER, MODIFIED STACK TO FIT UNTIL NEW PART ARRIVES, FIT NEW EXHAUST STACK.	356.79	2168.83	0	18	2543.62
161031-0025	SVC00176845	11/08/2016	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507		FABRICATE LIFT CYLINDER HOSES	FABRICATE LIFT CYLINDER HOSES AS PER SAMPLE FOR SPARES AT MMG	80.35	303.99	0	0	384.34

161018-0052	SVC00176121	10/31/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507		REPLACE ALTERNATOR & BATTERIES	JUMP START AND CHECK CHARGE RATE, ALL OK, JUMP START THE NEXT DAY AND CHECK CHARGE RATE AGAIN, CHARGE RATE OK, LOOK FOR POSSIBLE CAUSE OF BATTERY DRAIN, NONOE FOUND, JUMP START FOR THIRD DAY IN A ROW, CHECK CHARGE RATE AGAIN,FOUND ALTERNATOR INTERMINTANTLY CHARGING, ARRANGE FOR REPLACEMENT ALTERNATOR AND BATTERIES, REPLACE ALTERNATOR & BATTERIES, CHECK CHARGE RATE, ALL OK.	611.26	1164.14	0	30.5	1805.9
161027-0039	SVC00176479	10/31/2016	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	25967	RETAP THREADS IN TRIMBLE POST	RETAP THREADS IN TRIMBLE POST MOUNTS AND REFIT TRIMBLE POLE	86.1	0	0	0	86.1
161004-0030	SVC00175369	10/10/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25896	REPLACE TILT CYLINDER HOSE	REPLACE TILT CYLINDER HOSE, REMOVED COVER FROM BLADE STRABILIZER BAR, REPLACED SUPPLIED HOSE FROM BAR TO TILT CYLINDER, REASSEMBLED AND CHECKED OPERATION	160.7	0	0	8	168.7
160714-0076	SVC00171099	09/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Tyres	1ME507	25805	REPLACE MISSING TRACK GUIDES	REPLACE MISSING TRACK GUIDES	277.23	476.4	152	13	918.63
160915-0038	SVC00174346	09/30/2016	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	25829	STRIP DOWN & REBUILD LHR IDLER	STRIP DOWN & REBUILD LHR IDLER WITH ALL NEW SEALS AND BEARINGS, FILL WITH OIL.	763.89	558.82	0	38	1360.71
160915-0038	SVC00175153	09/30/2016	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	25829	STRIP DOWN & REBUILD LHR IDLER	SEAL RETURNED FOR CREDIT	0	-123.64	0	0	-123.64
160928-0027	SVC00175010	09/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25880	TIGHTEN LIGHTS	CHECK OPERATION AND TIGHTEN ALL WORK LIGHTS AS REQUIRED	83.23	0	0	0	83.23
160914-0014	SVC00174261	09/29/2016	1H0103	ID - EARTHMOVING	187_INT	R	Tyres	1ME507	25829	REMOVE LHR IDLER FOR REPAIR	SET UP MACHINE AND SPLIT LEFT HAND TRACK, REMOVED REAR IDLER, MPICK UP IDLER FROM LA WORKSHOP AND REFIT IDLER ASSEMBLY, RETENSION BOLTS TO SPEC, REJOIN THE TRACK AT MASTER LINK AND TENSION BOLTS TO SPEC.	1002.46	0	0	50	1052.46
160909-0019	SVC00174016	09/20/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25810	REPLACE BLADE CYLINDER HOSE	TRAVEL TO QUARRY, REMOVED RH BLADE LIFT CYLINDER HOSE FOR ENZED TO REPAIR, REFIT NEW HOSE AND REFILLED HYD OIL	200.88	108.3	336.68	0	645.86
160818-0019	SVC00172879	09/13/2016	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	25775	S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SCHEDULE	207.9	215.68	0	15.5	439.08
160825-0065	SVC00173187	08/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	25765	REPAIR TRIMBLE POST ON BLADE	REFIT RH TRIMBLE POLE BACK ON TOP OF BLADE, CLEANED OUT THREADS AND LOCK TIGHT BOLTS	157.5	0	0	8	165.5
160811-0078	SVC00172566	08/17/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25689	REPLACE CUTTING EDGES	REPLACE CUTTING EDGES, CUTTING EDGES SUPPLIED BY MMG PROJECT	544.95	0	0	22	566.95
160722-0064	SVC00171551	08/09/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25588	REPAIR TRIMBLE/GPS WIRING	REPAIRED TRIMBLE/GPS WIRING ON MUSHROOM PLUG ON BLADE	78.75	0	0	0	78.75
160804-0013	SVC00172243	08/09/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	25655	LOOSE TRIMBLE POSTS & WIRING	TIGHTENED TRIMBLE POST BOLTS ON TOPE OF BLADE, CHECKED TRIMBLE SYSTEM FUSE BLOWING, CHECKED WIRING AND FOUND CHAFFED AND SHORTING OUT, REPAIRED SHORT AND INSULATE WIRING HARNESS.	247.28	0	0	12	259.28
160707-0010	SVC00171756	07/27/2016	1H0103	ID - EARTHMOVING	184_INT	PW	Tyres	1ME507	25531	REPLACE DAMAGED RHS MASTER LIN	REPLACE DAMAGED RHS TRACK MASTER LINK AT MMG ROSEBERY, TRACK JOINING LINK BOLTS WERE LOOSE AND BROKE DAMAGING THE THREADS IN THE LINK ASSY, WORK CARRIED OUT BY HB FITTERS, JACK UP MACHINE WITH BLADE AND RIPPERS, ROTATE TRACK TO GAIN ACCESS TO LINK ASSY, DRILL OUT AND REMOVE BROKEN BOLTS, RETAP TREADS, ONE HOLE NOT RECOVERABLE, REJOIN LINK WITH 3 BOLTS TO MOVE MACHINE OF ROCK PILE IN QUARRY AND UP TO WORKSHOP, WORK CARRIED OUT BY WILLIAM ADAMS, REPORTED MASTER LINK BOLTS HAD BROKEN CAUSING LINK TO COME APART DAMAGING TEETH LINK ON RHS TRACK, REMOVED AND INSTALLED TRACK PLATES AND MASTER LINK, SET UP GROUSER PLATES, TENSIONED BOLTS TO THE CORRECT TENSION, REMOVE BOLTS FROM THE LHS MASTER LINK AND INSTALLED NEW BOLTS, TENSIONED BOLTS TO SPECIFICATION, MOVED MACHINE BACKWARDS AND FORWARDS, SET TRACK TENSION. WORK CARRIED OUT AS POLICY AFTER RECENT TRACK REPLACEMENT AND LINKS NOT TIGHTENED TO SPEC AT BURNIE WORKSHOP BY A CC186 EMPLOYEE	1285.73	99.76	3783.7	0	5169.19
160713-0004	SVC00170953	07/26/2016	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	25402	REPAIR BROKEN TRACK ON 24/5/16	WORKS COMPLETED BY WILLIAM ADAMS REPORTED TRACK LINK HAD A BROKEN PIN. REMOVED 3 TRACK PINS. REMOVED LINKS. REPLACED 2 LINKS, 3 PINS AND BUSHES. REFITTED GROUSER PLATES. TENSIONED BOLTS AND TRACKS TO SPEC. REQUESTED TO TENSION FULL REAR EDGE BOLTS. FOUND TRACKS ARE HEAVILY WORN. INFORMED CUSTOMER ON THE CONDITION OF THE TRACKS. NB: WHEN SERVICEMAN ARRIVED ONSITE IT TOOK 4 HOURS TO SORT OUT PAPERWORK AND MMG REQUIREMENTS.	0	0	2969.14	0	2969.14
160701-0077	SVC00171375	07/25/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25471	REPAIR HYD OIL LEAK & RIPPER B	REPAIR HYDRAULIC OIL LEAK & CHANGE RIPPER BOOT, RIPPER BOOT SUPPLIED BY MMG PROJECT	78.75	426.05	0	0	504.8
160701-0081	SVC00171374	07/25/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	25479	RETENSION CORNER TIP BOLTS	BOLTS FROM NUTS & BOLTS (MISSED OFF SC160603-0006 - BLADE REPAIRS) ONSITE AT MMG, CLEANED SURROUNDING AREA, RETENSION CORNER TIP BOLTS	86.1	0	0	0	86.1
160704-0078	SVC00170654	07/25/2016	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	25530	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET, CLEANED PRE FILTER, REPLACED FUEL AND OIL FILTER, REPLACED TRANS FILTER, FITTED WORK LIGHTS TO TOP OF BLADE LIFT CLY	866.26	469.23	0	48	1383.49
160707-0052	SVC00170775	07/12/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25530	Fit up work lights	FIT UP EXTRA WORK LIGHTS, AS REQUESTED BY OPERATOR AND JASON HAZELL	118.13	105	0	0	223.13
160707-0073	SVC00170789	07/12/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25513	REPLACE RIPPER BOOT	REPLACE RIPPER BOOT, PARTS SUPPLIED BY MMG PROJECT	86.1	0	0	0	86.1
160603-0006	SVC00169626	06/30/2016	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507		REMOVE BLADE RIPPERS AND IDLER	REMOVE BLADE RIPPERS AND IDLER FOR REPAIRS, WELD IN UPPER SUPPORT BAR FOR CORNER TIPS	2827.15	256.56	757.27	0	3840.98
160421-0023	SVC00166763	06/22/2016	1H0103	ID - EARTHMOVING	187_INT	F	Electrical	1ME507		FIT LED WORK LIGHTS TO LIFT CY	PARTS ONLY -- FIT LED WORK LIGHTS TO LIFT CYLINDERS	0	70.5	0	0	70.5
160523-0051	SVC00168408	06/22/2016	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507		REPLACE TRACKS AND SEGMENTS	1ME507 Track replacement job. Brake the tracks and remove the rear idlers. These were sent to Hobart for repair. Removed the brkoen cap bolts and ran a tap through all the threaded holes, Arranged new bolts and washers. Installed the rear idlers tensioning the caps, re connected the chains and turned the machine, rolled out the new tracks behind the machine and pulled the new tracks onto the machine, disconnected the chains and fitted off the new chains. Fitted the new sprocket segments and tensioned all bolts, adjusted the chain tension all ok. All major and minor boggies were inspected, The bar rubbers were inspected along with the equaliser bar and the boggle pads.	3083.86	29424.74	0	0	32508.6

160603-0050	SVC00169371	06/22/2016	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1ME507		CARRY OUT MACHINE REPAIRS	1ME507 repairs in Burnie yard. Removed the belly plates. Create a work list of what is required. Cut the lower section of the trash guard way to access the tank mount bolts. Removed all hoses and wiring. Remove the hydraulic oil and remove the tank from the machine. (Note the hydraulic oil did have a fair amount of water was in the oil. tested the tank to located the oil leaks. Disassemble the tank and pressure cleaned as needed, arrange the required welding repairs to be completed. Reassembled the tank after repair, blanked off and pressure tested the tank. The mount plates were removed and new mounts were fabricated and welded to the tank. A new fender bracket was fabricated painted and installed The left fender had to be straightened and welding repairs completed prior to reinstalling the tank. The tank was reinstalled with all new seals, the wiring was refitted and the system filled with hydraulic oil. The right side tilt cylidner was cut out to allow the blade to be removed. The blade was positioned in front of the machine and the draft arms were installed, all mount pins were cleaned up ready to install the blade. The front canopy was removed and new mount rubbers were installed, rubber spacers were installed either side of the bushes and the conopy refitted. The blade edges were torqued up with the hi torque. The machine was started and tested all ok.	9242.11	761.85	857.5	80	10941.46
160602-0003	SVC00169212	06/20/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25419	CHANGE BLOCKED HYD FILTERS	CHANGE BLOCKED HYD FILTERS BECAUSE OF RESTRICTION LIGHT COMING ON	196.89	54.7	0	0	251.59
160602-0063	SVC00169340	06/20/2016	1H0103	ID - EARTHMOVING	182_INT	R	Ground Engaging	1ME507		REPAIR CORNER TIP ON BLADE	Repair blade and build up the rear idlers. The rear idlers had the fill plug remove and were set up on a JIG to rotate the idler for the building up proces. Tooling was fabriceted to allow the idlers to stay assembled, whilst being welded. They were both drained of oil and refilled. The blade was turned over and both corner tip rear plates were completely cut out, New corner tip plates were fabricated and installed, new gussets were fitted as directed and the unit was fully welded out. The front edge at a last minuite change was extened the edge mount hoses were plug welded and re drilled. Several other cracks were repaired and the unit was loaded ready for shipment.	13808.08	1505.4	0	100	15413.48
160509-0046	SVC00167719	05/31/2016	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	25308	S1 A SERVICE	TRAVELLED TO MMG ROSEBERRY, CARRIED OUT S1 A SERVICE AS PER SCHEDULE. CHANGE ENG OIL AND FILTER, TAKE ENG OIL SAMPLE, CHECKED ALL FLUID LEVELS, GENERAL INSPECTION OVER UNIT.	249.38	239.68	0	48	537.06
160509-0047	SVC00167720	05/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25357	REPLACE CORNER EDGES & TURN CU	ONSITE AT MMG, REMOVED EDGES AND BOLTS AND NUTS, SUBCONTRACTOR GBM CARRIED OUT WELDING REPAIRS, CUT BROKEN SECTION OUT, WELD IN NEW SECTION, FIT UP EDGES WITH NEW BOLTS AND NUTS. SUBBI COSTS CHARGED TO SC 160520-0032 PO0061025	1487.85	131.8	0	50	1669.65
160517-0051	SVC00168174	05/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25367	REPAIR FLASHING LIGHT WIRING F	TRAVELLED TO MMG, REPOSITIONED LIGHT AND REPAIRED BROKEN WIRE AND TEST.	78.75	0	0	22	100.75
160519-0035	SVC00168280	05/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25378	TRIMBLE GPS POWER FAULT	REMOVED AND REPAIRED WIRING HARNESS FOR TRIMBLE SYSTEM, REFIT AND TEST OPERATION.	118.13	0	0	6	124.13
160520-0032	SVC00168328	05/30/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	25388	REPAIR CRACKS RHS CORNER BLADE	SUBCONTRACTOR GBM REPAIRED CRACKS RHS CORNER BLADE	0	0	1320	0	1320
160504-0047	SVC00167535	05/19/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507		REFIT TRIMBLE SYSTEM	REFIT TRIMBLE SYSTEM, REPAIR BRACKET AND TAP OUT THREADS FOR MAST	329.7	0	0	31.5	361.2
160411-0022	SVC00166177	05/17/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25983	TOP UP HYD OIL & REPAIR TANK L	TOP UP HYD OIL & REPAIR TANK LEAK	318.68	135.27	0	16	469.95
160413-0052	SVC00166331	05/17/2016	1H0103	ID - EARTHMOVING	187_INT	R	Tyres	1ME507	25021	ADJUST LHS TRACK	ADJUST TRACK TO SPEC AND REFIT COVER	86.1	3.49	0	0	89.59
160506-0050	SVC00167674	05/17/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25355	REPLACE RIPPER BOOT	FIT NEW RIPPER BOOT AS REQUIRED	118.13	0	0	5	123.13
160516-0004	SVC00168030	05/17/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25349	HYD LEAK @ BLADE TILT CYL HOSE	INSPECT FOR HYDRAULIC OIL LEAK AND TIGHTEN ALL HYDRAULIC CLAMPS FOR BLADE TEST OPERATION NO LEAKS EVIDENT	86.1	0	0	0	86.1
160421-0021	SVC00166761	05/06/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25230	REPAIR REVOLVING LIGHT WIRING	REPAIR REVOLVING LIGHT WIRING AND FIT PIN TO SHIN GUARD	121.81	0	0	6	127.81
160406-0079	SVC00166009	04/28/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25118	REPLACE RIPPER BOOT	REPLACE RIPPER BOOT	43.05	0	0	0	43.05
160408-0010	SVC00165714	04/28/2016	1H0103	ID - EARTHMOVING	187_INT	R	Electrical	1ME507	25135 HRS	REPAIR LIGHT PLUG & ADJUST DOO	REPAIR LIGHT PLUG WIRING & ADJUST DOOR	118.13	0	0	5	123.13
160318-0045	SVC00165201	04/20/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	25064	REPAIR CRACK IN RIPPER BOX MOU	REPAIR CRACK IN RIPPER BOX MOUNT, REMOVE RIPPER BOX FOR WELDING REPIARS, REFIT AFTER REPAIRS	1042.13	0	870	50	1962.13
160309-0003	SVC00164804	04/18/2016	1H0103	ID - EARTHMOVING	187_INT	R	Hydraulic	1ME507	25034	REPAIR HYDRAULIC TANK LEAK	REMOVE AND REPLACE FAULTY SEAL AT HYDRAULIC TANK AS REQUIRED, TEST OPERATION FOR LEAKS ALL GOOD.	211.58	12.82	0	10	234.4
160304-0007	SVC00164611	03/31/2016	1H0103	ID - EARTHMOVING	187_INT	S	Service	1ME507	25058	S1 C SERVICE	CARRIED OUT THE REQUIRED SERVICE AND REPLACED THE REVERS ALARM AS REQUESTED	236.25	514.21	0	45	795.46
160322-0044	SVC00165346	03/29/2016	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	N/A	SUPPLY UHF ANTENNA KIT & SPRIN	PARTS ONLY -- SUPPLY UHF ANTENNA KIT & SPRING LIGHT PARALLEL FROM MINECORP ROSEBERY	0	98.13	0	0	98.13
160305-0001	SVC00164677	03/23/2016	1H0103	ID - EARTHMOVING	187_INT	R	Ground Engaging	1ME507	25014	REPLACE RIPPER BOOT & SHIN GUA	Travel to site and Removed the shin guard and ripper boot. Note the pins were not easy to remove.	161.18	594.78	0	27.5	783.46
160226-0052	SVC00164192	03/15/2016	1H0103	ID - EARTHMOVING	187_INT	R	Sundries	1ME507	24980	RE-SHIM RHS PUSH ARM	TRAVELLED TO MMG, RE-SHIM RHS PUSH ARM AND REPAIR TILT CYL PIN RETAINER	243.6	57.72	0	55	356.32

160304-0019	SVC00164615	03/15/2016	1H0103	ID - EARTHMOVING	187_INT	R	Bodywork	1ME507	25010	ADJUST & REPAIR LHS ENGINE COV	TRAVELLED TO MMG, REMOVE LEFT HAND SIDE ENGINE COVER, STRAIGHTEN BENT BRACKET AND WELD REPAIR AS REQUIRED AND REFIT	78.75	57.21	0	55	190.96
160218-0008	SVC00163659	03/09/2016	1H0103	ID - EARTHMOVING	121_INT	R	Ground Engaging Engine	1ME507		SUPPLY RIPPER BOOTS & PINS	SUPPLY RIPPER BOOTS & PINS AND CONSUMABLES	0	711.85	0	0	711.85
140218-0008	9769	02/24/2016	1H0103	ID - EARTHMOVING	184_INT	R		1ME507	23208	INSPECT ENG & F/DRIVE OIL SAMP		0	0	0	0	0
140218-0008	SVC00125809	02/24/2016	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	23208	INSPECT ENG & F/DRIVE OIL SAMP	TRAVEL TO KOMATSU X2, REMOVE AIR CLEANER HOUSING AND INLET PIPING, REMOVE EXHAUST PIPING AND MUFFLER, REMOVE FUEL FILTER HOUSING, REMOVE INJECTOR INJECTOR LINES, REMOVE ROCKER COVERS, TIGHTEN INTERNAL FUEL LINES, SEAT INJECTOR LINES AND REFIT, REASSEMBLE FULE FILTER HOUSING, REASSEMBLE INLET SYSTEM WITH NEW O RINGS, REASSEMBLE EXHAUST SYSTEM WITH NEW PARTS, DRAIN FINAL DRIVE OILS AND REFILL, TEST DRIVE OK.	1169.5	1029.34	0	107.6	2306.44
160216-0003	SVC00160356	02/18/2016	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		SUPPLY FILTERS	SUPPLY FILTERS AS REQUIRED	0	154.64	0	0	154.64
160128-0012	SVC00162664	01/29/2016	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	24881	FIT LOCK OUT ISOLATOR & UNIT S	TRAVEL TO HBMI, FIT UP LOCABLE ISOLATOR, FIT 9KG FIRE EXTINGUISHER, FIT UNIT NUMBERS TO THE REAR AND SIDES OF MACHINE	275.63	280.23	0	46	601.86
160129-0001	SVC00162730	01/29/2016	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	24881	REPLACE BROKEN RHF DOOR GLASS	REMOVE AND REPLACE BROKEN WINDOW GLASS AS REQUIRED	0	0	387.27	0	387.27
160111-0106	SVC00162547	01/28/2016	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	24881	REPLACE FAULTY DOOR LATCHES	TRAVELLED TO HBMI, REPLACED FAULTY DOOR LATCH AND STRIKER, CHECKED ALL FLUID LEVELS	196.88	139.07	0	43	378.95
160108-0043	SVC00161848	01/13/2016	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	24827	REPLACE TRANS FILTER HOSES	TRAVELLED TO HBMI, REMOVED TRANSMISSION FILTER COVERS, REMOVED FLOOR PLATES, INSPECT FOR OIL LEAK, REMOVED LEAKING HOSES, FIT NEW HOSES, TOPPED UP TRANS OIL, TEST ALL OK.	472.5	0	366.61	56.5	895.61
160108-0003	SVC00161858	01/11/2016	1H0103	ID - EARTHMOVING	121_INT	R	Transmission	1ME507		HD50 & GREASE	SUPPLY HD50 & GREASE	0	200.9	0	0	200.9
151223-0012	SVC00161314	01/06/2016	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	24809	S1 A SERVICE	TRAVELLED TO JUDBURY, CARRIED OUT S1 A SERVICE AS PER SERVICE SHEET. REPLACED RIPPER BOOTS (SUPPLIED BY OPERATOR) AND CHECKED FINAL DRIVE BOLTS.	322.35	249.31	0	120	691.66
151105-0060	SVC00159329	12/21/2015	1H0103	ID - EARTHMOVING	182_INT	R	Suspension/UC	1ME507		REPAIRS TO CANNON	REPAIRS TO CANNON	2800.89	242.13	40.02	50	3133.04
151123-0004	SVC00159729	12/15/2015	1H0103	ID - EARTHMOVING	184_INT	R	Differential-FD	1ME507	24757	REPAIR DAMAGED RHS F/D ASSY	TAKE UNIT TO WASHBAY & HOT WASH, RETURN TO WORKSHOP SETUP & BUTT WELD BOTH PARTS TOGETHER USING PROCEDURE FROM WILLIAM ADAMS, REASSEMBLE & WITH TENSIONING ON SPRING AS PER SPEC SHEET	2139.9	20560.97	0	330.5	23031.37
151207-0014	SVC00160508	12/15/2015	1H0103	ID - EARTHMOVING	184_INT	R	Differential-FD	1ME507	24757	REMOVE & REFIT LHS FINAL DRIVE	TRAVELLED TO HBMI, RELEASED TRACK, SPLIT TRACK, REMOVED FINAL DRIVE ASSEMBLY AND RETURN TO W/SHOP, TRAVELLED BACK TO SITE, REFIT REPAIRED F/DRIVE, TOPPED UP OIL, TENSION BOLTS, FIT AXLE, REFITTED TRACK, TENSION TRACK, TENSION DRIVE	826.88	0	0	74.5	901.38
151204-0059	SVC00160445	12/11/2015	1H0103	ID - EARTHMOVING	186_INT	R	Differential-FD	1ME507	24757 HR	STRIP AND REBUILD L/HAND FINAL	STRIP AND REBUILD L/HAND FINAL	1955.63	4898.39	0	50	6904.02
151109-0077	SVC00159291	11/30/2015	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	23739	REMOVE & REFIT RHS CANNON FOR	STRIP FINAL DRIVE PRESS OUT PLANNETARY DRIVE PINS CRACK TEST ALL PLANNETARY GEARS INSPECT ALL PINS AND CARRIERS PRESS HUB APART AND CLEAN ALL PARTS REASSEMBLE HUB AND SET BEARING PRELOAD REASSEMBLE PLANETARIES AND REFIT TO HUB REFIT COVER AND TENSION ALL BOLTS TO SPECS	1765.07	27.33	0	149	1941.4
151118-0044	SVC00160047	11/26/2015	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	23740	REPLACE BROKEN GROUSER PLATE	REMOVE & REFIT RHS CANNON FOR WELDING REPAIRS, ASSEMBLE CANON AFTER REPAIRS, REFIT TO MACHINE , REFIT TRACK AND TEST OPERATION	0	115.89	0	0	115.89
151016-0011	SVC00158257	10/28/2015	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	24661 HRS	INSPECT CANON/TIGHT CHAIN FAUL	Travel to Cloyts Sand, Inspect for right hand track adjuster fault, remove inspection plate and back off cannon loose appears broken	78.75	0	0	77	155.75
150922-0044	SVC00156969	09/30/2015	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	24575	REPAIR COOLANT LEAK	TRAVEL TO HUON SAND PLANT REMOVED RH SIDE ENGINE COVERS, REMOVED ALTERNATOR AND ENGINE OIL COOLER END COVERS, FIT NEW O-RINGS AND REASSEMBLE, FIT IDLER PULLEY GREASE LINE AND CHANGE COOLANT, TEST OPERATION AND FOR COOLANT LEAK ALL GOOD.	401.1	573.22	0	119	1093.32
150917-0028	SVC00156728	09/24/2015	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	24540	S1 B SERVICE	Travel to Huonville Sand plant and carried out the required service and safety checks as per service schedule, remove broken bolt from final drive and fit new bolt.	318.68	508.77	0	36.5	863.95
150918-0012	SVC00156782	09/18/2015	1H0103	ID - EARTHMOVING	121_INT	R	Engine	1ME507		COOLANT 20LTR	COOLANT 20LTR	0	82.42	0	0	82.42
150827-0035	SVC00155733	08/31/2015	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	24164	REPAIR REVERSE ALARM WIRING	TRAVELED TO HBMI TO CHECK FOR REVERSE ALARM FAULT, ADJUSTED SWITCH REPAIR WIRING TO ALARM AND REAPIR WIRING TO REAR LIGHT, SLAVE START AND TIGHTEN BELTS	354.38	0	0	39	393.38
150803-0022	SVC00154498	08/12/2015	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	24136	SUPPLY 20LTR COOLANT TO OPERAT	CHECK TOP UP AND SUPPLY COOLANT TO OPERATOR AS REQUIRED	43.05	82.51	0	0	125.56
150715-0016	SVC00153454	07/21/2015	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	24419	REPLACE UHF COAX	TRAVELED TO HBMI TO REPAIR LIGHT WIRING , UHF POWER CABLE	157.5	36.98	0	41	235.48
150701-0021	SVC00152966	07/14/2015	1H0103	ID - EARTHMOVING	182_INT	R	Milling	1ME507		CUT OUT 2 HARDOX CUTTING EDGES	CUT OUT 2 HARDOX CUTTING EDGES & DRILL HOLES TO SUIT CUTTING EDGE BOLTS	698.25	329.27	0	35	1062.52
150629-0027	SVC00152926	07/09/2015	1H0103	ID - EARTHMOVING	186_INT	R	Trays/Buckets	1ME507	24411 hr	REPLACE CUTTING EDGES	REPLACE CUTTING EDGES	921.39	1122.92	0	45	2089.31
150625-0002	SVC00152455	06/30/2015	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	24411 hr	TEST COOLING SYSTEM FOR LEAKS	POSITION BLADE ON STANDS REMOVE OLD CUTTING EDGES ANDCORNER TIPS CLEAN UP BLADE AND REFIT EDGES AND TIPS TENSION ALL BOLTS CLEAN UP AFTER REPAIRS	921.38	317.67	0	46	1285.05
150325-0055	SVC00147666	06/22/2015	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507		REBUILD IDLER	TEST COOLING SYSTEM FOR LEAKS PRESSURE TEST COOLING SYSTEM FOUND SLIGHT LEAK AT ONE CORE REMOVE AND HAVE REPAIRED REFIT CORE WITH NEW SEAL PAD TIGHTEN ALL HOSES AND RETEST FOR FURTHER LEAKS FOUND TRANSMISSION COOLER GASKET LEAKING REMOVE SIDE COVER TIGHTEN COVER BOLTS AND RECHECK TESTED OK	0	153.44	0	0	153.44
150413-0055	SVC00148502	05/29/2015	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507		SUPPLY CUTTING EDGES	PARTS TO REBUILD IDLER	118.13	729.24	0	0	847.37
150507-0028	SVC00149855	05/27/2015	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	24369	REPAIR BLADE TILT CYLINDER	SUPPLY CUTTING EDGES TO REPLACE CORNER TIPS AS REQUESTED BY PAUL KELLEHER	912.98	1367.8	0	150	2430.78
											TRAVELLED TO DYSART, DISMANTLE CYLINDER AND CLEAN PARTS, ORDER SEALS, REASSEMBLE UNIT WITH NEW SEALS AND REFIT TO MACHINE, CHECK AND TOP UP HYDRAULIC OIL					

150511-0026	SVC00150051	05/25/2015	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE NEW EYE MACHINE NEW EYE ONTO BLADE CYLINDER ROD ONTO BLADE CYL	1409.64	3.46	458.5	50	1921.6
150514-0070	SVC00150234	05/19/2015	1H0103	ID - EARTHMOVING	181_INT	R	Hydraulic	1ME507		PAINT BLADE TILT CYLINDER EYE PAINT BLADE TILT CYLINDER EYE	34.13	37.4	0	0	71.53
150422-0050	SVC00149031	04/24/2015	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	24316	INSPECT REPORTED COOLANT LEAK S1 A SERVICE TRAVELLED TO HBMI, INSPECT COOLANT LEAK, BLOW OUT RADIATOR, GET UNIT HOT TO CHECK FOR COOLANT LEAK, LEAK FOUND EXTERNALLY COOLANT RESIDUE AROUND COOLER FLANGES TO BLOCK, NOT WET COLD OR HOT	196.88	0	0	43	239.88
150402-0073	SVC00148245	04/21/2015	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	24290 HRS	S1 A SERVICE TRAVELLED TO HBMI, CARRIED OUT S1 A SERVICE AS PER SCHEDULE	275.63	248.36	0	52	575.99
150223-0034	SVC00146077	03/30/2015	1H0103	ID - EARTHMOVING	121_INT	R	Sundries	1ME507		SUPPLY PARTS AS PER REQ 103-87 SUPPLY TIPS, PIN RETAINERS TEETH AS PER PAUL KELLEHER 103-8760	0	1309	0	0	1309
150224-0068	SVC00146391	03/12/2015	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	24117	REPLACE CORNER TIPS TRAVELLED TO HBMI, REPLACED WORN OUT CORNER TIPS, TRAVEL BACK TO SITE, TIGHTENED LOOSE UNDER CARRIAGE BOLTS AS REQUIRED	354.38	880.74	0	150	1385.12
150212-0026	9730	02/27/2015	1H0103	ID - EARTHMOVING	186_INT	R	Suspension/UC	1ME507	24086 HR	REMOVE EQUALISER BAR & REPLACE	0	0	0	0	0
150212-0026	SVC00145504	02/27/2015	1H0103	ID - EARTHMOVING	186_INT	R	Suspension/UC	1ME507	24086 HR	REMOVE EQUALISER BAR & REPLACE TRAVELLED TO HBMI AND REPAIRED BOTL THREAD AND STRAIGHTEN BENT RETAINER PLATE, FIT NEW PIN AND CONNECT TO TRACK FRAMES AND TENTION PINCH BOLTS TO SPEC, STRAIGHTEN REAR BELLY PLATE AND FIT TO MACHINE, FIT FRONT BELLY PLATE.	3751.14	3113.81	0	50	6914.95
150212-0025	SVC00146047	02/26/2015	1H0103	ID - EARTHMOVING	182_INT	R	Suspension/UC	1ME507		REPAIR FAILED EQUALISER BAR Repair equaliser bar. The bar was machined to expose the cracked area, heated and welded, the back side of the repaired area was built up for added strength. The bar was heated and destressed, cooled and crack tested. The end bores were machined out to remove the under cut from the repair process, then welded and machined back to finished size. circlip grooves were then machined into either side of the outer bores, the bar was then assembled ready for fitting.	3452.97	238.66	0	50	3741.63
150216-0074	SVC00145565	02/16/2015	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	24085	REPAIR UHF AND WORK LIGHTS TRAVELLED TO HBMI, REPAIRED UHF WIRING AND WORK LIGHTS AS REQUIRED	157.5	0	0	30	187.5
150128-0008	SVC00144776	01/30/2015	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	24030 HR	S1 D SERVICE COMPLETED D SERVICE AND SAFETY CHECKS AS PER SERVICE SCHEDULE	583.28	1109.05	0	32.5	1724.83
150128-0014	SVC00144775	01/30/2015	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	24030 HR	REPLACED MISSING BOLTS IN FRONT ROP STRAIGHTEN WORK LIGHT CHECK ENGINE COOLANT LEAK PRESSURE TEST COOLING SYSTEM AND INSPECT FOR LEAKS FOUND TOP AND BOTTOM RADIATOR HOSES LEAKING REMOVE FRONT BELLY PLATE AND TIGHTEN ALL HOSE CLAMPS PRESSURE TEST AGAIN AND RECHECK FOR LEAKS TOP UP COOLANT AND REFIT BELLY PLATE PARK UNIT OUTSIDE WORKSHOP AND CLEAN UP WORK AREA	546	0	0	62.2	608.2
141217-0006	SVC00142898	12/19/2014	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	23866	REPAIR BLADE RAM VALVE LEAK REPLACED LEAKING PLUG ON BLADE RAM VALVE, CARRIED OUT BY ENZED LAUNCESTON	0	0	289.32	0	289.32
141217-0027	SVC00143123	12/18/2014	1H0103	ID - EARTHMOVING	121ADMIN	R	Hydraulic	1ME507		COOLANT AND HYDRAULIC OIL COOLANT AND HYDRAULIC OIL	0	166.15	0	0	166.15
141201-0100	SVC00142480	12/09/2014	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	23855	S1 A SERVICE TRAVELLED TO BELL BAY, CARRIED OUT S1 A SERVICE AS PER SCHEDULE	282.98	230.21	0	182.5	695.69
140827-0036	SVC00137236	09/26/2014	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	23781	CHANGE TRANSMISSION OIL AND FI TRAVEL TO MORNINGTON WASTE SITE, CHANGE TRANSMISSION OIL AND FILTER AFTER 100 HRS OF USE AFTER REBUILD	393.75	852.92	0	63	1309.67
140915-0064	SVC00137905	09/26/2014	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	23806	REPAIR HYDRAULIC OIL LEAK TRAVEL TO MORNINGTON PARK WASTE, REPLACED LEAKING O RINGS ON RIPPER CIRCUIT, TOPPED UP HYD OIL	118.13	75.8	0	22.5	216.43
140925-0055	SVC00138487	09/26/2014	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	23811	REPLACE LEAKING O RINGS TRAVEL TO MORNINGTON, REMOVED BELLY PLTE, REMOVED SEAT PANEL ETC, FOUND LEAKING O RINGS, REPLACED O RINGS AND TESTED ALL OK, CLEANED AIR CON FILTERS, REASSEMBLED ALL PARTS	590.63	0.54	0	62.5	653.67
140904-0077	SVC00137349	09/16/2014	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	23794 HRS	REPAIR COOLANT LEAK TRAVEL TO MORNINGTON, CHECKED UNIT FOR COOLANT LEAK AND FOUND LEAKING RADIATOR SEALS, DISASSEMBLED, REASSEMBLED RADIATOR WITH NE SEALS AND REASSEMBLED ALL PARTS TO WORKING ORDER, FILLED MACHINE WITH COOLANT	991.73	867.18	0	93.5	1952.41
140909-0024	SVC00137557	09/12/2014	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	23803	CHECK TRANSMISSION OIL LEAK TRAVEL TO MORNINGTON, TIGHTENED LEAKING TRANSMISSION PLATE AS REQUIRED	98.44	0	0	44	142.44
140623-0109	SVC00132934	07/30/2014	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1ME507	23674 hr	REMOVE & RESEAL BRAKE VALVE REMOVE BRAKE VALVE ASSEMBLY STRIP CLEAN AND REASSEMBLE WITH NEW SEALS FIT AND TEST FOR LEAKS TESTED OK	791.19	134.1	0	35	960.29
140530-0008	SVC00131897	07/08/2014	1H0103	ID - EARTHMOVING	186_INT	R	Transmission	1ME507	23674 hr	CHECK TRANSMISSION PRESSURES CHECK TRANSMISSION PRESSURES DRAIN OIL AND REMOVE STRAINER TO CHECK FOR CONTAMINATION TEST TRANSMISSION PRESSURES FOUND LOW REMOVE AND CHECK STRAINER FOUND CONTAMINATION REMOVE TRANSMISSION STRIP CLEAN AND CHECK FOR WEAR REBUILD TRANSMISSION WITH NEW SEALS BEARINGS AND PLATES AS NEEDED REPLACE TRANSMISSION AND STEER PUMPS WITH REMAN UNIT REFIT TRANSMISSION FILL WITH OIL AND CHECK ALL PRESSURES REPAIR OIL LEAK AT HYD BANK REPLACE ALL COVERS AND PARK UNIT OUTSIDE WORKSHOP	12563.84	20199.99	0	50	32813.83
140701-0019	SVC00133708	07/08/2014	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		WELD ON BELLY PLATES MAKE UP & MOUNT BELLY PLATES CUT 20MM PLATE, TAP HOLE FOR DRAIN, RECUT OLD PLATE BACKEND OF DOZER, CLEANUP & PREP PLATES, REWELD PLATE BACK ON DOZER, DRILL & TAP 2 MOUNTING BLOCKS, WELD TAPPING BLOCKS IN PLACE & REMOUNT BELLY PLATES	580.13	199.68	0	29	808.81
140620-0027	9694	07/04/2014	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1ME507	23674 hr	RESEAL STEERING VALVE	0	0	0	0	0
140616-0035	SVC00132441	06/30/2014	1H0103	ID - EARTHMOVING	182_INT	R	Trays/Buckets	1ME507		WELD HARDOX COVER PLATES ON BLADE WELD HARDOXLINER PLATES ON BLADE, WELD CRACKS ON BLADE HORNS, WELD PLATES TO STOP LOGS FROM GOING OVER TOP OF BLADE	2074.3	1023.79	216	50	3364.09
140627-0060	SVC00133419	06/30/2014	1H0103	ID - EARTHMOVING	186_INT	R	Ground Engaging	1ME507	23674 hr	REPLACE RIPPER BOOTS AND PINS SUPPLY PINS AND TEETH AS REQUIRED	0	417.45	0	0	417.45
140613-0048	SVC00132448	06/27/2014	1H0103	ID - EARTHMOVING	186_INT	R	Transmission	1ME507		REMOVE CONVERTER HOUSING REMOVE CONVERTOR STRIP CLEAN AND REASSEMBLE WITH NEW SEALS AND O RINGS	2559.38	4310.41	0	50	6919.79

140613-0053	SVC00132447	06/27/2014	1H0103	ID - EARTHMOVING	186_INT	R	Brake	1ME507	23674 hr	REMOVE FINAL DRIVE ASSY` S	REMOVE FINAL DRIVE S JACK UP MACHINE AND TURN TRACKS TO ALLOW TRACKS TO BE BROKEN REMOVE BOTH FINAL DRIVE ASSY` S STRIP OUT BRAKE UNITS CLEAN PARTS AND INSPECT REBUILB WITH NEW BEARINGS BRAKE DISCS AND SEALS REFIT ALL PARTS TO MACHINE AND REFIT TRACKS	2677.52	801.74	0	50	3529.26
140612-0028	SVC00132353	06/17/2014	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		REMOVE BUSHINGS & MACHINE INSE	REMOVE BUSHINGS & MACHINE INSERTINHG DOLLEY	136.5	13.25	0	7	156.75
140520-0073	SVC00131352	05/28/2014	1H0103	ID - EARTHMOVING	184_INT	S	Engine	1ME507	23619	Change engine oil and filter	TRAVELLED TO JUDBURY, REPLACE ENG OIL AND FILTER. BLOW OUT RADIATOR AND COOLERS. REPAIR SIDE DOOR PANELS. TOP UP COOLANT.	157.5	269.62	0	46.4	473.52
140519-0045	SVC00130953	05/20/2014	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	23571	CHECK & ADJUST F/ PUMP TIMING	TRAVEL TO JUDBURY, CHECK AND SET FUEL PUMP TIMING AND TEST OK	354.38	0	0	123.1	477.48
140415-0038	SVC00129912	05/07/2014	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	23257	S1 A SERVICE	CARRIED OUT S1 A SERVICE AS PER SCHEDULE. CAPPO REQUESTED FINAL DRIVE AND HYDRAULIC OIL BE CHANGED DURING THIS SERVICE	680.4	763.96	0	37.5	1481.86
140415-0042	SVC00129644	05/07/2014	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	23527	TURN CUTTING EDGES WELD CRACKS	TRAVEL TO ARVE RD, TURN CUTTING EDGES , WELD CRACK IN FRONT OF BLADE.	630	324	0	146.7	1100.7
140429-0027	SVC00130229	05/06/2014	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	23516	CHECK FAULT WITH TEMP GUAGE	TRAVEL TO JUDBURY, CHECK FOR OVER HEATING FAULT, PICK UP NEW TEMP GUAGE AND TRAVEL BACK TO SITE AND FIT TO UNIT, REMOVE AND REPLACE TEMP SENSOR, REPAIR WIRING TO MAIN ENGINE HARNESS.	590.63	115.52	0	111.1	817.25
140414-0056	SVC00129314	04/16/2014	1H0103	ID - EARTHMOVING	121ADMIN	R	Sundries	1ME507		SUPPLY DRUM ENGINE OIL	SUPPLY DRUM ENGINE OIL + RIGGERS GLOVE + SUPER GLUE DANI BONNEY 103-8151	0	108.86	0	0	108.86
140320-0022	SVC00127658	03/28/2014	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	23356	100 HR ENGINE OIL CHANGE	TRAVELLED TO JACKSONS ROAD AND CARRIED OUT 100 HOUR SERVICE AS REQUIRED	157	233.02	0	65.1	455.12
140224-0055	SVC00126590	03/18/2014	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	23217	REPLACE CORNER TIPS	TRAVEL TO BRIGHTON, CHANGE OUT CORNER TIPS AS REQUIRED.	225	867.18	0	40.8	1132.98
140224-0057	SVC00126759	03/05/2014	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	23224 HR	REPLACE REVOLVING LIGHT	TRAVEL TO HBMI, REPLACE REVOLVING LAMP AND REPAIR LIGHT WIRING.	150	306.11	0	26.7	482.81
140217-0054	SVC00126303	02/27/2014	1H0103	ID - EARTHMOVING	186HEAVYMAC H	R	Starter Motor	1ME507	N/A	FINISH OFF STARTER MOTOR REBUI	REASSEMBLE STARTER MOTOR, FIT WICKS AND PLUGS FOR BUSHES, TEST FOR ADJUSTMENT OF DRIVE ASSEMBLY ALL GOOD	130	0	0	6.5	136.5
140122-0037	SVC00124597	02/12/2014	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	23177	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SCHEDULE. OILS CHARGED ONTO OTHER JOB	487.5	329.56	0	28.5	845.56
140122-0054	SVC00125316	02/12/2014	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	23177	REPLACE WORN INJECTOR LINES	REPLACE WORN INJECTOR LINES, REPLACE ENGINE OIL DIP STICK	198	1263.95	0	0	1461.95
140130-0067	SVC00124899	02/12/2014	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	23154	REPLACE BROKEN CONOPY MOUNTS	TRAVEL TO FORCETT, WENT TO REPLACE BOLTS BUT RUBBER BLOCKS BROKEN. TRAVEL BACK TO SITE, REPLACE RUBBER BLOCKS AND REPLACE BROKEN CANOPY BOLTS AS REQ'D	525	164.2	0	179.6	868.8
140203-0001	SVC00125007	02/06/2014	1H0103	ID - EARTHMOVING	121ADMIN	R	Engine	1ME507		SUPPLY OILS TRANS + ENGINE	SUPPLY OILS TRANS + ENGINE	0	222.6	0	0	222.6
130226-0005	SVC00105698	02/04/2014	1H0103	ID - EARTHMOVING	121ADMIN	R	Sundries	1ME507		SUPPLY RIPPER BOOT, PIN AND LO	SUPPLY RIPPER BOOT, PIN AND LOCK AS PER TODD MURRAY REQ#103-7273	0	372.94	0	0	372.94
140122-0044	SVC00124411	01/23/2014	1H0103	ID - EARTHMOVING	121ADMIN	R	Ground Engaging	1ME507		SUPPLY RIPPER BOOTS X 2 + PINS	SUPPLY RIPPER BOOTS X 2 + PINS X 2 + LOCKS X 2 + STANDARD GREASE X 1 CARTON PAUL KELLEHER	0	426.48	0	0	426.48
140120-0071	SVC00124242	01/22/2014	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	N/A	SUPPLY COOLANT, PARTS ONLY	SUPPLY COOLANT, PARTS ONLY	0	70.95	0	0	70.95
131209-0041	SVC00122665	12/13/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	22980 HR	supply coolant	SUPPLY COOLANT - PARTS ONLY	0	67.47	0	0	67.47
131002-0059	SVC00119271	11/29/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507		REBUILD ENGINE	REMOVED FRONT ROP AND ENGINE COVERS FOR ENGINE REMOVAL, REMOVE COOLERS, DEGASSED AIR CON, REMOVED CONDENSOR, REMOVED NOSE CONE, REMOVED JACK SHAFT AND HOUSING. DISCONNECT PUMP FROM PTO REMOVE ENGINE FROM MACHINE. FIT ENGINE TO STAND AND TAKE TO WASH BAY AND STEAM CLEAN, STRIP ENGINE ASSESORIES TO OVER HAUL ENGINE. REMOVE CRANK, PISTON AND LINERS AND OTHER ENGINE INTERNALS, CLEAN AND SEND FOR MACHINING, ASSESS CONDITION AND ORDER PARTS. ASSEMBLE CYLINDER HEAD, BOX UP CORE DEPOSITS, REMOVE BROKEN BOLTS ON HEAT EXCHANGER HOUSING. CLEAN OUT ENGINE BLOCK OIL GALLERIES, FIT NEW MAIN BEARINGS, FIT UP CRANK TO BLOCK USING FLEXI GAUGE, CEHCK MAIN BEARING CLEARANCES. REMOVE MAIN BEARING CAPS AND CLEAN OFF FLEXI GAUGE OIL AND REFIT MAIN BEARING CAPS, TENSION BOLTS TO SPEC. FIT REAR PTO HOUSING. FIT FRONT TIMING COVERS, COM AND GEARS, ALIGN TIMING MARKS AND FIT COVERS. FIT TRANSMISSION COOLER. FIT PISTION AND LINER KITS, TENSION CON ROD BOLTS, CHECK BEARING CLEARANCES WITH FLEXI GAUGE, REMOVE CAPS, CLEAN OFF FLEXI GAUGE OIL BEARINGS AND REFIT CAPS, TENSION TO SPEC, FIT NEW OIL PUMP, REFIT SUMP AND OIL PICK CLIPS, REFIT ENGINE ASSEMBLY IN CRADLE. FIT CYLINDER HEAD AND TENSION BOLTS TO SPEC, FIT NEW PTO GE3ARS AND FLY WHEEL, FIT CRANK DAMPER AND AUX PULLIES. CARRY OUT TOP END TUNE. FIT ROCKER BOX COVERS AND TENSION BOLTS TO SPEC. FIT WATER PUMP AND COOLING SYSTEM PIPING. FIT INTERCOOLER EXHAUST MANIFOLD AND TURBO. FIT TORQUE CONVERTER AND TENSION BELL HOUSING BOLTS TO SPEC. FIT ALTENATOR PULLEY ARRANGEMENT AND FILTER HOUSING. FIT FUEL PUMP ASSEMBLY AND SET TIMING MARKS. FIT STARTER MOTOR, ALTENATOR AND WIRING HARNESS. LIFT AND FIT ENGINE TO MACHINE.	16071	21020.37	677.5	0	37768.87
131104-0049	SVC00120662	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	22964	DIAGNOSE FAULT WITH ENGINE AFT	DIGNOSE ENGINE NOISE AND FUEL SMOKE, REMOVE TURNBO FROM MACHINE, REMOVE ROCKER COVERS, FUEL LINES AND INJECTORS, TURBO WAS OK, 1 INJECTOR WAS INCORRECT, REMAN INJECTOR AND REFIT, REFIT FUEL LINES, ROCKER COVER, TURBO AND MUFFLER ASSEMBLY, TEST OPERATION ALL GOOD.	2112	33.44	1637.35	0	3782.79

131108-0075	SVC00120644	11/28/2013	1H0103	ID - EARTHMOVING	186HEAVYMAC H	R	Drive Line	1ME507	22964 hrs	OVERHAUL TORQUE CONVERTER	OVER HAUL TORQUE CONVERTER AS REQUIRED	1040	569	0	50	1659
131111-0074	SVC00121530	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1ME507	22964H	REPLACE BLADE HOSES	REMOVE, FABRICATE AND REPLACE WORN BLADE HOSES AS REQUIRED	1852.5	492.99	0	0	2345.49
131111-0075	SVC00121525	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Transmission	1ME507	22964H	OVERHAUL TRANSMISSION DRIVESH	OVERHAUL TRANSMISSION DRIVESHAFT AS REQUIRED	195	267.14	0	0	462.14
131111-0076	SVC00121518	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Starter Motor	1ME507	22964H	REMOVE AND REPLACE STARTER MOT	REMOVE AND REPLACEU/S STARTER MOTOR AS REQUIRED	130	665	0	0	795
131111-0077	SVC00121521	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	22964H	REPLACE ENGINE MOUNTS F&R	REPLACE ENGINE MOUNTS FRONT AND REAR AS REQUIRED	422.5	711.05	0	0	1133.55
131111-0078	SVC00121519	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	22964H	REPLACE HEATER HOSES	REMOVE AND REPLACE WORN HEATER HOSES AS REQUIRED	130	80.16	0	0	210.16
131111-0079	SVC00121523	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Hydraulic	1ME507	22,964H	REPLACE HYDRAULIC TANK SUCTION	REPLACE HYDRAULIC TANK SUCTION HOSE AS REQUIRED	227.5	1000.3	0	0	1227.8
131111-0081	SVC00121517	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	22,964H	REPLACE CAB FLOOR MATS	REPLACE CAB FLOOR MATS AS REQUIRED	97.5	302.3	0	0	399.8
131111-0084	SVC00120680	11/28/2013	1H0103	ID - EARTHMOVING	186HEAVYMAC H	S	Transmission	1ME507	22964 hrs	TEST OIL COOLERS	REMOVE, PRESSURE TEST AND REPLACE OIL COOLERS AS REQUIRED	130	0	100	0	230
131118-0080	SVC00121520	11/28/2013	1H0103	ID - EARTHMOVING	186HEAVYMAC H	R	Engine	1ME507	22964 hrs	OVERHAUL FUEL PUMP	Dismantle inspect Springs on elements were broken and the elements were very worn. Overhauled the entire fuel pump using new components Governor was also overhauled , timing advance was inspected also. The pump housing was replaced with second hand part due to having a break through mounting holes.	227.5	0	6395.46	0	6622.96
131122-0024	SVC00121526	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Exhaust	1ME507		REPAIR EXHAUST SYSTEM	REMOVE AND REPLACE REPLACE EXHAUST SUPPORTS SYSTEM CHANGING SEALS AS REQUIRED	357.5	639.3	0	0	996.8
131122-0026	SVC00121527	11/28/2013	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	22964	REPLACE RADIATOR HOSES	REMOVE AND REPLACE WORN RADIATOR HOSES AS REQUIRED	276.25	183.46	0	0	459.71
131120-0096	SVC00121424	11/22/2013	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	22997	INSPECT ENGINE OIL LEAKS	INSPECT ENGINE OIL LEAK AROUND TIMING COVER AND INJECTORS.	150	0	0	0	150
131114-0038	SVC00120960	11/18/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22964	REPAIR UHF & ALTERNATOR FAULT	CHECK FOR UHF FAULT. REPAIR BROKEN COAX. LOCATE FAULT IN RADIO. CHECK FOR ALT FAULT AND SEND UHF TO PITT COMMUNICATIONS FOR REPAIR. PICK UP UHF AND NEW REVOLVING LAMP AND FIT TO UNIT AND REPAIR WIRING AS REQUIRED.	262.5	0	0	10	272.5
131112-0003	SVC00120722	11/13/2013	1H0103	ID - EARTHMOVING	184_INT	PW	Engine	1ME507	22964	REPLACE FUEL HOSES	REPLACE FUEL HOSES, 1/4 INCH HOSES WAS PREVIOUSLY FITTED THE SAME AS FACTORY BUT THE INTERNAL DIAMETER OF THE FITTINGS WERE SMALLER AND CAUSING FUEL STARVATION UNDER HIGH RPM, REMOVE 1/4 INCH HOSE AND REPLACE WITH 3/8 HOSE UNDER POLICY AGAINST CC184.	225	43.26	0	0	268.26
131101-0014	SVC00120342	11/11/2013	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	22961	MODIFY GUARD HINGES	MODIFY HINGES ON BELLY PLATES ON UNIT AS REQUIRED.	337.5	0	0	0	337.5
131102-0013	SVC00120425	11/05/2013	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE WASHERS AS REQUESTED	MACHINE WASHERS AS REQUESTED	32.5	0	0	0	32.5
131028-0019	SVC00119874	10/28/2013	1H0103	ID - EARTHMOVING	182_INT	R	Engine	1ME507		WELD UP CRACKS IN ALLUM MANIFOLD	WELD UP CRACKS IN ALLUM MANIFOLD AS REQUIRED.	422.5	0	0	22	444.5
130926-0050	SVC00118177	10/09/2013	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	22959	REMOVE AND RESEAL LH RIPPER LI	TRAVEL TO WILLIAM ADAMS TO GET PARTS. REMOVE AND RESEAL LH RIPPER LIFT CYLINDER WILLIAM ADAMS TO ASSIST IN REPAIRS. REPAIR WIPERS. REPLACE MISSING NOSE CONE WASHER	318.75	212.05	169.95	9.6	710.35
131002-0001	SVC00118687	10/08/2013	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	22960 HR	INSPECT COOLANT IN ENGINE OIL	RESEAL RIPPER LIFT CYLINDER - CARRIED OUT BY WILLIAM ADAMS INV SR200023082 TRAVEL TO JERICO, REMOVE BELLY PLATE AND SUMP TO INSPECT COOLANT IN OIL, REFIT SUMP.	873	166	0	101	1140
130917-0012	SVC00117378	09/30/2013	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	22959	REPAIR BELLY PLATE HINGES	FABRICATE NEW HINGES. REMOVE BELLY PLATES AND WASH OUT DIRT AROUND ENGINEER AND TRANS, REFIT BELLY PLATES AND WELD UP HINGES IN PLACE, CLEAN UP WORK AREA.	1814	0	0	0	1814
130925-0082	SVC00118113	09/30/2013	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	22959	REPLACE BLOWN HYDRAULIC HOSES	REMOVE LEAKING HYDRAULIC HOSES AND REPLACE WITH NEW HOSES.	107.5	66.76	0	0	174.26
130930-0066	SVC00118513	09/30/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22959	REPAIRS TO WORKLIGHTS & WIRING	REPAIR WORK LIGHTS AND WIRING AS REQUIRED.	300	0	0	5	305
130801-0021	SVC00114690	09/27/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22959	S1 C - 1000 HR SERVICE	CARRIED OUT S1 C - 1000 HR SERVICE AS PER SCHEDULE.	532	792.34	0	3.5	1327.84
130912-0029	SVC00117158	09/26/2013	1H0103	ID - EARTHMOVING	182_INT	R	Ground Engaging	1ME507		REPAIRS TO RIPPER AS REQUIRED	CUT OFF BROKEN ADAPTOR GOUGE OFF WEAR PLATES FIT NEW ADAPTER AND WELD RESHAPE RIPPER SHANK CUT OUT NEW WEAR PLATES AND FIT WELD ON BUILD UP WORN PART OF SHANK AND CLEAN UP UNIT/AREA.	1235	1364.76	0	30	2629.76
130910-0062	SVC00117035	09/24/2013	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	22957	Replace U/S Alternator	TRAVEL TO HBMI, CHECK FOR STARTING FAULT, FOUND TO HAVE FAULTY ALTERNATOR, REMOVE AND DISMANTLE, CARRY OUT TEMPORY REPAIRS TO KEEP MACHINE GOING, REFIT ALTERNATOR, ORDER NEW PARTS, PICK UP NEW ALTERNATOR AND TRAVEL BACK TO SITE, REMOVE OLD AND FIT NEW ALTERNATOR, TEST CHARGE RATE, REPAIR WORK LIGHTS AND REVOLVING LIGHT, RESOLDER PRINTED CIRCUIT BOARD, REFIT AND TEST, REPAIRED FUSE BOX WIRING AND WIRING TO ISOLATOR, REPLACE BLOWN GLOBES IN DASH.	825	766.63	0	115.2	1706.83
130719-0028	SVC00113650	07/23/2013	1H0103	ID - EARTHMOVING	121ADMIN	R	Sundries	1ME507		CONSUMABLES AS PER REQ 103-764	CONSUMABLES AS PER REQ 103-7640 TODD MURRAY ENG OIL GREASE GREASE GUN END	0	123	0	0	123
130701-0073	SVC00112817	07/18/2013	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE 2 NEW RIPPER PINS	MACHINE 2 NEW RIPPER PINS AS REQUESTED	340	86.94	0	17	443.94
130628-0003	SVC00112528	06/28/2013	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	NOT SUPPLIED	REPLACE SHIN GUARD BOLTS	TRAVEL TO PIPELINE, REPLACE SHIN GUARD BOLTS	75	0	0	24	99

130624-0093	SVC00112146	06/26/2013	1H0103	ID - EARTHMOVING	121ADMIN	R	Sundries	1ME507		CONSUMABLES 103-7585 TODD MURRAY	0	117.55	0	0	117.55
130520-0095	SVC00110251	06/13/2013	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	22742	Replace water pump	720	1121.42	0	115.2	1956.62
130501-0074	SVC00109876	05/15/2013	1H0103	ID - EARTHMOVING	184_INT	R	Service	1ME507	22724 HRS	S1 A SERVICE	801.5	267.85	0	57.6	1126.95
130429-0100	SVC00109152	04/30/2013	1H0103	ID - EARTHMOVING	186_INT	R	Trays/Buckets	1ME507		RIPPER BOOT 9W2452 + PIN 6Y339	0	357.96	0	0	357.96
130404-0081	SVC00108906	04/26/2013	1H0103	ID - EARTHMOVING	182_INT	R	Ground Engaging	1ME507		SUPPLY HARDOX CUTTING EDGES	2117.5	945.77	310	0	3373.27
130403-0063	SVC00108040	04/24/2013	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	22603	REPLACE CUTTING EDGES	1166.5	1051.74	0	0	2218.24
130423-0052	SVC00108868	04/24/2013	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		SUPPLY TRANSMISSION OIL	0	77.8	0	0	77.8
130415-0029	SVC00108475	04/18/2013	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	22629	INSPECT ENGINE & FD BAD SAMPLE	112.5	0	0	28.8	141.3
130312-0034	SVC00107364	03/26/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22538	REPLACE U/S WORK LIGHTS	307	428	0	57.6	792.6
130312-0076	SVC00106615	03/22/2013	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		SUPPLY TRANS OIL + RATCHET STR	0	160.95	0	0	160.95
130313-0055	SVC00106793	03/21/2013	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	NOT SUPPLIED	REPLACE CUTTING EDGE BOLTS	0	65.76	0	0	65.76
130222-0004	SVC00106018	03/07/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22506	REPLACE U/S UHF RADIO	337.5	300	0	57.6	695.1
130116-0093	SVC00103950	02/28/2013	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	22474	S1 B - 500 HR SERVICE	419.5	517.79	0	0	937.29
130125-0003	SVC00103874	02/27/2013	1H0103	ID - EARTHMOVING	182_INT	R	Ground Engaging	1ME507		REPAIR RIPPER, BUILD UP ADAPTO	325	193.97	0	0	518.97
121203-0029	SVC00101493	01/07/2013	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	22156	REPAIR WORKLIGHT	112.5	149.68	0	19.2	281.38
120913-0039	SVC00098459	10/16/2012	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	22100	S1 B - 500 HR SERVICE	561	736.35	0	0	1297.35
120910-0004	SVC00097303	09/26/2012	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	22000	INSPECT STEERING PUMPS	65	0	1299	0	1364
120831-0024	SVC00096120	09/05/2012	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	21978	REPLACE U/S TRANSMISSION HOSE	732	45.46	736.05	57.6	1571.11
120827-0011	SVC00095530	08/29/2012	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21952	REPLACE BLOWN STEERING HOSE	283.5	0	915.18	90	1288.68
120801-0030	SVC00094175	08/27/2012	1H0103	ID - EARTHMOVING	186_INT	R	Trays/Buckets	1ME507		SUPPLY LOCKS AND PINS	0	202.73	0	0	202.73
120813-0068	SVC00094975	08/21/2012	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	21905	REPLACE REAR WORK LIGHTS	286.5	212.85	0	54	553.35
120802-0049	SVC00094388	08/07/2012	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	21854	TOP UP PINION SHAFT OIL	98.5	5	0	0	103.5
120706-0071	SVC00092383	08/02/2012	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		REDESIGN & SET UP CAB PROTECTI	3495	608.17	0	0	4103.17
120730-0078	SVC00093922	07/31/2012	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		SUPPLY LOCKS AND PINS AS REQ'D	0	40.84	0	0	40.84
120315-0015	SVC00085783	07/30/2012	1H0103	ID - EARTHMOVING	181_INT	R	Bodywork	1ME507		STRAIGHTEN DOORS ON FRONT OF D	5618.5	1498.42	0	0	7116.92
120702-0069	SVC00093496	07/27/2012	1H0103	ID - EARTHMOVING	186_INT	R	Bodywork	1ME507		REFIT COVERS AND BLADE REFIT	5201	1015.89	0	0	6216.89
120723-0071	SVC00093500	07/26/2012	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	21854	S1 A SERVICE	236	392.99	0	3.5	632.49
120508-0015	SVC00089586	07/06/2012	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507		REPLACE TRACKS SPROCKET SEGMENT	11190.5	38878.05	2374.8	0	52443.35

120305-0061	SVC00090447	06/29/2012	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507		REMOVE BLADE - RADIATOR-TRACKS	REMOVE BLADE-NOSE CONE RADIATOR AND TRACKS FOR REPAIRS ROLL UP TRACKS AND SEND TO W ADAMS FOR REPAIRS REMOVE AND REPLACE ALL PULLEYS REMOVE AND REPLACE NOSE CONE PINS AND BUSHES REPLACE LIFT CYLINDER MOUNT BUSHES REFIT RADIATOR AND COOLER REPLACE MUFFLER REMOVE RESEAL AND REPLACE RIPPER LIFT CYLINDERS	11728.5	17928.14	250	90	29996.64
120618-0027	SVC00091278	06/28/2012	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		MACHINE NEW 3" IH ROD FOR RIPP	MACHINE NEW 3" IH ROD FOR RIPPER CYLINDER, BORE OUT CYLINDER TUBE EYE, WELD UP & REMACHINE TO SUIT BUSH	940.5	335.95	0	0	1276.45
120504-0041	SVC00088577	06/27/2012	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		BUILD UP IDLERS	BUILD 4X HAZELL ADAPTORS AND 1 FOR RODNEY COLLINS	8033	596	0	0	8629
120614-0004	SVC00091246	06/27/2012	1H0103	ID - EARTHMOVING	182_INT	R	Trays/Buckets	1ME507		BUILD UP BLADE CUTTING EDGE	SKIN THE BLADE ADD TRUNION BALLS REPAIR CRACKS BUILD UP CUT EDGE SUPPORT AREAS AND HARDENED BAR ON SIDES	4819.5	565.04	0	0	5384.54
120423-0069	SVC00087945	06/13/2012	1H0103	ID - EARTHMOVING	182_INT	R	Ground Engaging	1ME507		REPAIRS TO BLADE TRUNNIONS ETC	REPAIRS TO BLADE TRUNNIONS ETC. WELD AND MACHINE BORES TO SUIT BEARINGS.	4961.5	154.88	0	0	5116.38
120313-0046	SVC00085683	03/30/2012	1H0103	ID - EARTHMOVING	182_INT	R	Lathe	1ME507		CHECK & REPAIR VARIOUS PINS & REPAIR HEADER TANK & REPAIR REAR IDLER	CHECK & REPAIR VARIOUS PINS & BUSHES AS REQUIRED - MANUF NEW PINS FOR KNUCKLE, CYLINDER MOUNTS & LINK ARM MOUNTS, BORES MADE OVERSIZE TO 70MM & PINS MADE TO FIT, BOTH ON MACHINE & ON BLADE, WELD UP CRACKS REPAIR HEADER TANK & REMOVE PLATES FROM RIPPER BOX, CLEANUP & REPAIR BONNET, WELD BLADE	3391.5	571.37	0	0	3962.87
120314-0031	SVC00086675	03/30/2012	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507				3137.5	313.55	0	0	3451.05
120203-0003	SVC00085567	03/28/2012	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	N/A		DISMANTLE RIGHT HAND REAR IDLER AND ASSES FOR REPAIRS AND REBUILD IDLER	1039.5	735.66	0	0	1775.16
120208-0018	SVC00084398	03/20/2012	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21704	REPLACE U/S STEER PUMP	ONSITE AT MACHINE. INSPECT STEERING FAULT AND REMOVED AND REPLACED UNSERVICABLE STEERING PUMP	1405	6207.55	0	0	7612.55
120224-0048	SVC00084985	02/29/2012	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507		REFIT CUTTING EDGE	TRAVELLED TO PULP MILL. CARRIED OUT REPAIRS TO REFIT CUTTING EDGE	185.5	128.25	0	90	403.75
120224-0012	SVC00084862	02/27/2012	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	21735	TIGHTEN TRIMBLE POST & REPAIRS	TIGHTEN TRIMBLE POST & REPAIRS - TIGHTEN LOOSE TRIMBLE POST BOLTS, ATTEMPT TO REMOVE BROKEN BOLTS, ADJUST AND TIGHTEN LOOSE ARM REST ON SEAT.	133	6.65	0	18	157.65
120218-0023	SVC00084452	02/21/2012	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	21689	ADJUST UP BOTH TRACKS	TRAVELLED TO BELL BAY. ADJUSTED BOTH TRACKS ON UNIT	103.5	0	0	49.5	153
120111-0033	SVC00083696	02/20/2012	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507		SUPPLY LHS CANON	supply lhs cannon complete to take place of original which was destroyed.	0	0	10000	0	10000
120117-0019	SVC00082729	02/14/2012	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	21575	REPAIR COOLANT LEAK	TRAVELLED TO PULP MILL. INSPECT COOLANT LEAK, REMOVE GRILL AND CHECK RADIATOR CORES. FOUOD TO HAVE SEVERAL DAMAGED CORES, REFIT GRILL. ADD RADIATOR STOP LEAK. PICK UP COOLANT STOP LEAK FROM LAUNCESTON. TOPPED UP COOLANT. TO BE FIXED AFTER PULP MILL JOB.	290	66.34	0	54	410.34
120124-0018	SVC00083489	02/09/2012	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21627	REPLACE HYDRAULIC OIL S1 B - 500 HR SERVICE	REPLACE HYDRAULIC OIL - DUE TO BAD OIL SAMPLE AND OIL AGE, AS PER CAPPO, TOP UP COOLANT, CHANGE RIPPER BOOT 02/10 - TRAVELLED TO UNIT AND SERVICED ANSD PER SCHEDULE. REMOVED AND REPLACED CANOPY BUSHES.REPLACED ENGINE BAY DOOR LATCHES.REPLACED BROKEN BOLTS IN TRACK FRAME. REMOVED FIRE EXTINGUISHER BRACKET. SERVICED ON SUNDAY AT O/T RATES.	342	326.8	90	90	848.8
110927-0034	SVC00077491	01/31/2012	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	21016		02/10 - TRAVELLED TO UNIT AND SERVICED ANSD PER SCHEDULE. REMOVED AND REPLACED CANOPY BUSHES.REPLACED ENGINE BAY DOOR LATCHES.REPLACED BROKEN BOLTS IN TRACK FRAME. REMOVED FIRE EXTINGUISHER BRACKET. SERVICED ON SUNDAY AT O/T RATES.	1531	1374.14	0	495	3400.14
120122-0011	SVC00083273	01/31/2012	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	21310	INSPECT TRANSMISSION LEAK	INSPECT TRANSMISSION LEAK - W/ADAMS LAUNCESTON 23/11/2011 - TRANSMISSION FOUND TO BE LEAKING FROM HOSE UNDER BELLY PLATE, DAVE LANGDON TO ARRANGE H/BROS FIELD SERVICE TO FIX ON WEEKEND, TOP UP TRANNNY OIL	59	0	567.45	0	626.45
120126-0022	SVC00083194	01/30/2012	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21528	REPAIR BROKEN HYD TANK MOUNTS	TRAVELLED TO BELL BAY. REPAIRED BROKEN BOLTS ON HYDRAULIC TANK. TIGHTEN CUTTING EDGE AND INSPECT ENGINE OIL LEAKS	292	0	0	22.5	314.5
120105-0037	SVC00082158	01/27/2012	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	21509	S1 D - 2000 HR SERVICE	TRAVELLED TO PULP MILL. CARRIED OUT THE COMPLETION OF 2000HR SERVICE AS PER SCHEDULE	1117	1094.21	0	90	2301.21
111217-0010	SVC00082990	01/25/2012	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	21430	REPLACE BROKEN DOOR WINDOW	TRAVELLED TO BELLBAY. REPLACE BROKEN DOOR WINDOW	59	16.13	364.55	0	439.68
111221-0065	SVC00082313	01/17/2012	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	NOT SUPPLIED	REPAIR PRIMARY FUEL FILTER	TRAVELLED TO PULP MILL. PICKED UP PARTS FROM LAUNCESTON. REPLACED DAMAGED PRIMARY FUEL FILTER ASSEMBLY	167.5	250.23	0	45	462.73
111212-0050	SVC00081494	12/20/2011	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	21431	REPLACE BROKEN LHS CANON	TRAVEL TO PULP MILL. SPLIT LHS TRACK, REMOVE BROKEN CANON ASSEMBLY, CLEAN UP TRACK FRAME, REMOVE SECOND HAND CANON ASSEMBLY FROM WRECKED MACHIEEN, PICK UP NEW BOLTS AND SEALS, FIT SEALS AND CANON ASSEMBLY AND RE-FIT TRACK	2122.5	754.88	0	225	3102.38
111205-0053	SVC00081024	12/14/2011	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507		REPLACE CUTTING EDGE BOLTS	REPLACE CUTTING EDGE BOLTS	88.5	212.6	0	0	301.1
111125-0041	SVC00080880	12/07/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21282	replace u/s hydraulic hose	REPLACED LEAKING HOSE ON UNIT. WORK CARRIED OUT BY ENZED LAUNCESTON	44.25	0	295.4	0	339.65
111128-0022	SVC00080836	12/07/2011	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	21322	CHECK & REPAIR TRANS OIL LEAK	NEIL OWENS TRAVELLED TO BELLY BAY. REMOVE ALL COVERS, BELLY PLATES, DRAIN TRANSMISSION OIL. REPLACE HOSE TO TRANSMISSION, REFILL TRANSMISSION OIL AND TEST. TRAVEL BACK TO HOBART.	3480	1287.57	440.8	495	5703.37
110923-0036	SVC00079054	11/30/2011	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	20899	REPLACE SUPPLIED DOOR WINDOWS	CALL OUT ON A SATURDAY - REPLACED TRANSMISSION HOSE ON D8 HE109 ON PULPMILL SITE. WORK CARRIED OUT BY ENZED LAUNCESTON REPLACE SUPPLIED DOOR WINDOW. WORK CARRIED OUT BY EAGLE WINDSCREENS.	14.75	0	218.18	0	232.93
111121-0090	SVC00080521	11/30/2011	1H0103	ID - EARTHMOVING	184_INT	R	Suspension/UC	1ME507	21277	REPLACE U/S R/H TRACK IDLER	TRAVELLED TO SITE, PICKED UP SECOND HAND IDLER FORM ON THE WAY AND FITTED TO RIGHT SIDE OF TRACK AS REQUIRED	1342.5	0	0	698.4	2040.9
111111-0023	SVC00079669	11/25/2011	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	21296	REPLACE CORNER TIPS- TURN EDGE	TRAVEL TO BELL BAY. REPLACE/TURNED CUTTING EDGES. INSPECTED OIL LEAKS UNDER CAB. ADJUSTED FAN/ALT BELTS. REPLACED TRANS & DIFF STEER FITTERS.	2024	1123.12	0	450	3597.12
111115-0040	SVC00079893	11/22/2011	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	21154	REFIT CUTTING EDGE AND BOLTS	TRAVEL TO SITE AT BELL BAY AND INSTALL CUTTING EDGE ON BLADE. CLEAN UP WORK AREA AND RETURN TRAVEL. WORK CARRIED OUT BY KOMATSU	14.75	0	201.15	0	215.9
111109-0033	SVC00079566	11/17/2011	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	21268	S1 A - 250 HR SERVICE	TRAVEL TO BELL BAY. CARRIED OUT 250 HR SERVICE AS PER SCHEDULE.	295.5	54.13	0	247.5	597.13
111014-0040	SVC00078572	11/15/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	20989	Replace hydraulic hose	FIND LEAK AND REPLACE HYDRAULIC HOSE ON DOZER. WORK CARRIED OUT BY HYDRAQUIP	14.75	0	362.77	0	377.52
111107-0087	SVC00079312	11/08/2011	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	21180	REFIT CUTTING EDGE ETC	TRAVEL TO MILL SITE. FIT NEW BOLTS TO CUTTING EDGE WHERE IT HAD SNAPPED OFF. GRIND UP BLADE SURFACE TO REMOVE BURRED EDGES.	335	0	0	90	425
111021-0052	SVC00076707	11/04/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21022	REPLACE RIPPER HOSE	REPLACE RIPPER CYLINDER HOSE. WORK CARRIED OUT BY PIRTEK LAUNCESTON.	14.75	0	346.59	0	361.34

111101-0033	SVC00076817	11/04/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21087	REPLACE LIFT AND TILT HOSES	REPLACE RIPPER TILT AND LIFT CYLINDER HOSES. WORK CARRIED OUT BY PIRTEK LAUNCESTON	14.75	0	2081.92	0	2096.67
111102-0025	SVC00076690	11/04/2011	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	21096	CHECK AND ADJUST CAB DOORS	TRAVEL TO BELL BAY. REPLACE DOOR STRICKERS AND ADJUST. TEST OK	103.5	11	0	45	159.5
111017-0077	SVC00074347	11/02/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	21022	REPLACE TANK BREATHER & SEAL	REPLACED BREATHER AND BOLTS IN COVERS	88.5	322.61	0	0	411.11
111101-0072	SVC00074062	11/02/2011	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	21088	FIT TRIMBLE SYSTEM TO BLADE	TRAVEL TO MILL SITE. FIT UP PLATES FOR TRIMBLE SET UP. REMOVE SIDE GUARD TO CHECK HYDRAULIC TANK, FIT NEW BREATHER, REPLACE MISSING BOLTS IN COVERS AROUND TANK	459	0	0	360	819
110905-0039	SVC00073999	10/07/2011	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	20820	WELD CRACKS IN BLADE ETC	REPAIRS AS PER FAULT SHEET. REPAIR CRACK IN BLADE AND TRY TO FIT RAKE. REPLACE BROKEN BOLTS IN TRACK GUIDES. REPLACE TRACK FRAME PIVOT O'RING. CLEAN OFF OIL. FIT UP FLASHING LIGHT AND WIRE IN AND TEST. REPAIR LIGHTS. TURN CAB GUARD BUSHES. BLOW OUT RADIATOR AND AIR CON/AIR CLEANER. ADJUST DOOR LOCKS AND FIT NEW PADLOCKS.	1189	355.51	0	0	1544.51
110902-0020	SVC00075061	09/30/2011	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		SEPTEMBER CONSUMABLES	SEPTEMBER CONSUMABLES 103-4959 M OTTENS 103-4972 OTTENS 103-4986M OTTENS	0	658.65	0	0	658.65
110907-0040	SVC00077389	09/28/2011	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	20877	FIT TRAVEL ALARM FOR PULP MILL	TRAVEL TO PULPMILL. FIT AND WIRE UP NEW REVERSE ALARM AND REPAIR LIGHTS.	172.5	356	0	18	546.5
110905-0029	SVC00076399	09/13/2011	1H0103	ID - EARTHMOVING	181_INT	R	Bodywork	1ME507		SUPPLY AND FIT NEW HAZELL DECA	TRAVEL TO CAMBRIDGE AND PICK UP NEW DECALS. FIT NEW HAZELL DECALS TO UNIT AND HOBART AUTO GLASS TO SUPPLY NEW WINDOWS FOR CAB DOORS AS REQUESTED	177	0	1066.36	0	1243.36
110715-0048	SVC00074581	08/09/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE JULY PG 103-4776	STORE ISSUE JULY PG 103-4776	0	69.8	0	0	69.8
110808-0037	SVC00074497	08/09/2011	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	20844	REPAIR WORK LIGHT FAULT	TRAVEL TO HBMI. CHECK AND REPAIR WORK LIGHTS. LOCATE FAULTY FUSE HOLDER AND REPAIR	176	0	0	9	185
110801-0097	SVC00074293	08/04/2011	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	20802	REPAIR BROKEN PUSH ARM STEP	TRAVEL TO HBMI. REPAIR BROKEN STEP ON PUSH ARM	179.5	10	0	45	234.5
110705-0055	SVC00073048	07/13/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ JULY 2011 M.O 4700	REQ JULY 2011 M.O 4700	0	32.6	0	0	32.6
110506-0041	SVC00069586	07/12/2011	1H0103	ID - EARTHMOVING	184_INT	R	Sundries	1ME507	20545	REPAIR RIPPER H LINK	06/05 - TRAVELLED TO UNIT TO WELD RIPPER BAR H LINK. FOUND BROKEN BEYOND REPAIRING IN FIELD. REMOVED PLOUGH AND TOOL BAR AND REMOVED BROKEN H LINK. BROUGHT BACK TO WORKSHOP AND STEAM CLEANED AND PREPPED FOR MAJOR WELDING REPAIR. 09/05 - WELDED UP AND STRENGTHENED H LINK AND RETURNED TO UNIT. REASSEMBLED AND STRAIGHTENED AND REPAIRED BELLY PLATE MOUNTS. TESTED OPERATION OK.	2365.5	692.3	0	279	3336.8
110617-0046	SVC00071435	06/30/2011	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		REPAIR BELLY GUARDS	remove and repair belly guards also starighten mount points on the machine	1113	26.26	0	0	1139.26
110628-0045	SVC00072290	06/30/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE JUNE PG 103-4672	STORE ISSUE JUNE PG 103-4672	0	385.06	0	0	385.06
110601-0045	SVC00071849	06/27/2011	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	20711 hrs	S1 A - 250 HR SERVICE	S1 A - 250 HR SERVICE. Completed service as per service sheet. Removed the plough and adjusted the tracks.	390.5	230.74	0	2.7	623.94
110606-0057	SVC00071507	06/27/2011	1H0103	ID - EARTHMOVING	186_INT	R	Engine	1ME507	20711 hrs	REPLACE CRACKED SUMP	REPLACE CRACKED SUMP. Raised the machine, and removed the belly plates. Removed sump sections and cleaned parts. Reassembled the sump with new section. Straightened the belly paltes and refitted after welding repairs.	855.5	1493.92	0	0	2349.42
110525-0087	SVC00071408	06/17/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507		Top up hydraulic oil	TOP UP HYDRAULIC OIL IN UNIT - PARTS ONLY INVOICE	0	132.8	0	0	132.8
110530-0081	SVC00070897	06/07/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ MAY KEVIN 2011 BRENT	REQ MAY KEVIN 2011 BRENT	0	111.02	0	0	111.02
110531-0015	SVC00070597	05/31/2011	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	20621 HRS	REPAIR ENGINE OIL LEAK	TRAVELLED TO UXBRIDGE. CHECKED ENGINE OIL. FOUND BELLY PLATE PUSHED UP AND CRACKED IN SUMP. DRAINED ENGINE OIL AND CLEANED DAMAGED AREA. CARRIED OUT TEMP REPAIRS WITH BONDING PUTTY AND REFILLED OIL. RAN MACHINE AND CHECKED FOR LEAKS	394.25	0	0	108	502.25
110407-0002	SVC00067467	05/16/2011	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		LANCE PIN AS NEEDED	lance pin plus blade repairs as per Peter Stelfox	642	0	0	0	642
110503-0076	SVC00068992	05/06/2011	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	20470	FIT PLOUGH 1ME495 TO UNIT	Travelled to west uxbridge. modified rear of dozer to fit plough up to unit. Cut off ripper box extension	393.5	0	0	166.5	560
110418-0058	SVC00068489	04/27/2011	1H0103	ID - EARTHMOVING	184_INT	B	Bodywork	1ME507	20476	REPLACE DAMAGED WINDSCREEN	TRAVELLED TO PLENTY. REMOVED DAMAGED WINDOW GLASS AND FITTED NEW WINDOW	241.5	451.31	0	54	746.81
110426-0027	SVC00068436	04/27/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ APRIL 2011 P.K 4310	REQ APRIL 2011 P.K 4310	0	225	0	0	225
110408-0030	SVC00067548	04/19/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ 1ME507 APRIL 20111	REQ 1ME507 APRIL 20111	0	259.58	0	0	259.58
110412-0071	SVC00067937	04/19/2011	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	20429	REPLACE LEAKING FUEL LINE	TRAVELLED TO WEST UXBRIDGE. CHANGED OUT FUEL LINE AND HELP FIT CANNON	424.5	16.25	0	108	548.75
110413-0070	SVC00068082	04/19/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ APRIL 103-4270	PARTS REQ APRIL 103-4270	0	133.2	0	0	133.2
110401-0022	SVC00067634	04/13/2011	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	20427	S1 C - 1000 HR SERVICE	TRAVELLED TO UXBRIDGE AND CARRIED OUT 1000HR SERVICE AS PER SCHEDULE. REPAIRED SHORT IN REAR WORK LIGHTS	590	628.49	0	108	1326.49
110404-0097	SVC00067635	04/13/2011	1H0103	ID - EARTHMOVING	184_INT	R	Suspension/UC	1ME507	20427	REPLACE COLLAPSED BOGIE PINS	TRAVELLED TO UXBRIDGE. REMOVED RIGHT HAND CANNON ASSEMBLY AND LOAD ONTO TRUCK. DISASSEMBLE CANNON. REMOVED MAJOR BOGGIE BEARINGS AND FITTED NEW BEARINGS. REFITTED IDLER AND ROLLER. TRAVELLED BACK TO UXBRIDGE AND REPLACED CANNON SEAL AND BUSH. REFITTED CANNON TO TRACK FRAME AND RECONNECT TRACK AND TENSION MASTER LINK BOLTS TO SPEC	2736.5	1589.22	0	405	4730.72

110318-0018	SVC00066451	04/12/2011	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	20293	REPAIR OVERHEATING FAULT	TRAVELLED TO NATIONAL PARK. CLEAN AND BLOWN OUT RADIATOR CORE DUE TO OVERHEATING FAULT	324.5	0	0	122.4	446.9
110325-0068	SVC00067438	04/06/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE MARCH PG 103-4165	STORE ISSUE MARCH PG 103-4165	0	66.2	0	0	66.2
110315-0012	SVC00066552	03/23/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ MARCH 103-4859	PARTS REQ MARCH 103-4859	0	136.16	0	0	136.16
110224-0034	SVC00066226	03/18/2011	1H0103	ID - EARTHMOVING	186_INT	R	Radio	1ME507		REPAIRS TO FORESTRY RADIO	Repairs to Forestry radio carried out by Pitt Communications.	0	0	75	0	75
110218-0051	SVC00065077	02/24/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE FEB PG 103-3956	STORE ISSUE FEB PG 103-3956	0	66.2	0	0	66.2
110204-0041	SVC00064952	02/22/2011	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	20163	S1 A - 250 HR SERVICE	TRAVBELLED TO FLORENTINE VALLEY. CARRIED OUT 250HR SERVICE AS PER SCHEDULE. CLEANED OUT RADIATOR AND REPLACED PIN IN MOUND PLOW ARM	497	173.76	0	143.1	813.86
110208-0001	SVC00058060	02/18/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ FOR FEB 103-3869,3941,	REQ FOR FEB 103-3869	0	295.65	0	0	295.65
110128-0052	SVC00064811	02/10/2011	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507		CHECK BATTERIES & CHARGE RATE	TRAVELLED TO MAYDENA. UNIT NOT STARTING. REMOVED BATTERY BOX COVERS AND PANELS. REPLACED AU 4 BATTERIES WITH NEW ONES. REASSEMBLED AND TESTED CHARGE RATE. TIGHTENED A/C COMPACTOR BRACKETS	493.5	785.95	0	198	1477.45
110106-0081	SVC00064121	01/27/2011	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507		Repairs as per list	drain hydraulic oil level down to correct level. install knapsack for fire protection. inspect all oil and coolant levels . replace missing nut on diagonal brace bolt install plough and plumb up .	398.25	313.91	0	0	712.16
110107-0034	SVC00063734	01/20/2011	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE JAN PG 103-3707	STORE ISSUE JAN PG 103-3707	0	303.68	0	0	303.68
101006-0019	SVC00059809	11/03/2010	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	19884	REPLACE CUTTING EDGE BOLTS	06/10 - TRAVELLED TO WILLIAM ADAMS AND PICKED UP CUTTING EDGE BOLTS. TRAVELLED TO MWTS AND CUT OUT U/S BOLTS AND REPLACED AS REQUIRED. TENSIONED ALL BOLTS.	258.75	89.28	0	45	393.03
101102-0010	SVC00059896	11/03/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ NOVEMBER 103-3359	PARTS REQ NOVEMBER 103-3359	0	142.4	0	0	142.4
100920-0002	SVC00057561	10/29/2010	1H0103	ID - EARTHMOVING	182_INT	R	Sundries	1ME507		WELD REPAIRS AS REQUIRED	REMOVE AND REPLACE TRUNION BALLS AND END CAPS TO BLADE ARMS AND ASSIST MECHANICS TO REMOVE BOLTS	1403	55.56	0	0	1458.56
101008-0052	SVC00059370	10/25/2010	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	19922	REPLACE TRANSMISSION PLUG	REMOVED UNSERVICABLE TRANSMISSION PLUG. DRAIN PLUG AND FIT NEW ONE	69	159.92	0	0	228.92
101013-0057	SVC00058915	10/25/2010	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	19922	S1 B - 500 HR SERVICE	TRAVELLED TO MORNINGTON. CARRIED OUT 500HR SERVICE AS PER SCHEDULE. REPLACED RELIEF VALVE	666	620.61	0	53.1	1339.71
100914-0004	SVC00058863	10/13/2010	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	19865hr	CHECK OUT THE DIFF STEER UNIT	The machine was brought in due to an noise in the diff steer unit and wear in the draft arms. The floor plates were removed and the transmission oil drained the screens were removed for the transmission, all ok. The screens were refitted, NOTE the drain bung was damaged and has to be replaced. The diff steer motor was removed as was the bearing block, The internal unit of what could be visually looked at appeared to be ok. The bearing block was disassembled and the bearings inspected, they were ok to reuse. The motor was reinstalled, the make up valves were removed from the pump group and the sides swapped left to right. The unit was reassembled, the draft arms were removed and the trunnion balls were replaced, the draft arms had the knuckles removed and the new items were welded onto the draft arms. The machine also had a bad sos on the engine for coolant in the engien oil. The oil was removed and the cooling system pressurised for 8 hours with no sign of coolant entry into the sump area. The oil was refilled and the unit sent back to work, The filed reports have said the machine is ok No different to what it was some time ago.(Possibly more diff steer pump noise than anything.)	3009	1828.71	0	0	4837.71
101006-0027	SVC00058597	10/07/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE OCT PG 103-3204	STORE ISSUE OCT PG 103-3204	0	339.08	0	0	339.08
100908-0047	SVC00057430	09/15/2010	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	19810	CHECK NOISE IN STEERING	ONSITE AT BRIGHTON. LOCATE NOISE IN RIGHT HAND FINAL DRIVE. CHECKED LEVELS AND TAKEN SAMPLES. TEST BRAKE PRESSURES AND REFFERED UNIT TO WORKSHOP	374.5	0	0	18	392.5
100723-0009	SVC00054774	08/27/2010	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	19661	REPAIR HYD LEAKS UNDER FLOOR	TRAVELLED TO DOVER. IDENTIFY OIL LEAK. FOUND 1 HOSE HAD BURST AND 2 BADLY LEAKING. REPLACE 1 HOSE. RETURN TO HOBART FOR MORE PARTS. RETURN TO FOLLOWING MORNING AND CONTINUE WITH DAMAGED HOSE REPAIR	1382.5	575.57	0	378	2336.07
100820-0062	SVC00056191	08/23/2010	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	19702	GREASE NIPPLES IN RIPPER BAR.	REMOVED BROKEN GREASE NIPPLES IN RIPPER BAR. CLEANED OUT DIRT AND DEBRIS IN GALLERIES AND REPLACED NIPPLES. PUMPED GREASE INTO PINS UNTIL GREASE CLEARED ANY BLOCKAGE.	64	0	0	0	64
100802-0042	SVC00056005	08/18/2010	1H0103	ID - EARTHMOVING	184_INT	F	Electrical	1ME507	19665	FIT UP REVOLVING LIGHT	TRAVELLED TO BRIGHTON. FIT AND WIRE UP REVOLVING LAMP. CHECK FOR REVERSE ALARM FAULT AND REPAIR WIRING	340	139.74	0	23.4	503.14
100813-0048	SVC00055895	08/16/2010	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	19572	TIGHTEN TRUNNION CAP BOLTS ETC	ONSITE AT BRIGHTON. TIGHTENED BLADE TILT CYLINDER PIN RETAINER BOLTS ON LEFT AND RIGHT HAND SIDE AND TIGHTEN BLADE PUSH ARM TRUNION CAP BOLTS	98.5	0	0	0	98.5
100810-0059	SVC00055759	08/13/2010	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	19665	JUMP START & CHECK CHARGE RATE	TRAVELLED TO UNIT. CHECK STARTING FAULT ON UNIT. FOUND THAT UNIT HAD FLAT BATTERY. JUMP START UNIT AND CHECK CHARGE RATE	167.5	0	0	9	176.5
100809-0070	SVC00055532	08/12/2010	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	19680	REPAIR HYD LEAK - CONTROL BANK	TRAVELLED TO BRIGHTON. REPLACE BLOWN O-RING IN VALVE BANK UNDERNEATH FLOOR PLATE	378	15.72	0	28.8	422.52
100709-0009	SVC00055597	08/10/2010	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	19677	S1 A - 250 HR SERVICE	TRAVELLED TO MACHINE AND CARRIED OUT 250HR SERVICE AS PER SCHEDULE	387	274.57	0	2.7	664.27
100728-0016	SVC00055167	07/30/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ 1032778 P.K JULY 2010	REQ 1032778 P.K JULY 2010	0	88.33	0	0	88.33
100726-0037	SVC00054830	07/27/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ JULY 2010 1032771 J.J	REQ JULY 2010 1032771 J.J	0	271.58	0	0	271.58
100719-0060	SVC00054535	07/23/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ JULY 103-2717	PARTS REQ JULY 103-2717	0	239.52	0	0	239.52

100318-0028	SVC00048058	07/20/2010	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	19103hr	CARRY OUT REPAIRS	Carry out the requested repairs. Removed the push blade group and the ripper box. All the required areas were line bored and repaired, blade knuckles, ripper box and ripper frame mount, the lower blade bores were also line bored. The hydraulic tank was removed and replaired where the platform had been pressed up causing the tank to be damaged. The tank was disassembled cleaned and repaired by the weld shop. All the sheared off bolts were removed and all platform attachments were remounted, all removed items were refitted to the machine, all the oils were topped up and the machine inspected. 6T-4949 TO BE ADDED TO SERVICE CALL	5766	1539.74	0	0	7305.74
100318-0028	SVC00054285	07/20/2010	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	19103hr	CARRY OUT REPAIRS		0	87.42	0	0	87.42
100714-0086	SVC00053985	07/15/2010	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	19513	TIGHTEN TRUNNION CAPS & BOLTS	TRAVELLED TO STRINGERS CREEK. TIGHTEN PUSH ARM BOLTS. INSPECT WEAR IN BLADE PINS AND BUSHES	174.5	0	0	54	228.5
100625-0041	SVC00053302	07/05/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ JUNE 103-2536	PARTS REQ JUNE 103-2536	0	71.4	0	0	71.4
100531-0051	SVC00051297	06/22/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ MAY 103-2379	PARTS REQ MAY 103-2379	0	232	0	0	232
100604-0061	SVC00051610	06/07/2010	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	19310	REPAIR LIGHTS & REVERSE ALARM	TRAVELLED TO DOVER. REPAIR REVERSE ALARM AND REAR WIRING TO WORK LIGHTS	159.5	0	0	18	177.5
100527-0025	SVC00051236	05/31/2010	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	19330	S1 D - 2000 HR SERVICE	TRAVELLED TO MACHINE AND CARRY OUT 2000HR SERVICE AS PER SCHEDULE	962	1018.26	0	124.2	2104.46
080925-0022	SVC00017586	05/27/2010	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17270	S1 D - 2000 HR SERVICE.	TRAVELLED TO HOUPTON RD. CARRY OUT S1-D 2000HR SERVICE AS PER SCHEDULE, TIGHTEN BLADE CAPS AND REPAIR LOOSE LIGHT WIRING	472.5	757.09	0	74.7	1304.29
100526-0004	SVC00050790	05/27/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ MAY 103-2347	PARTS REQ MAY 103-2347	0	65.4	0	0	65.4
100428-0077	SVC00049766	05/26/2010	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	19145	REPLACE BLADE CYL CAP BOLTS	TRAVELLED TO DOVER. REPLACE BLADE LIFT CYLINDER BOLTS	433	170.46	0	198	801.46
100125-0046	SVC00045902	05/21/2010	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	19061	REPLACE U/S MUFFLER ETC	TRAVELLED TO HBMI AND INSPECT MUFFLER, INSIDE OF MUFFLER HAD COLLAPSED. REMOVE AND REPLACE MUFFLER	289	1515.62	0	43.2	1847.82
100302-0070	SVC00045416	05/21/2010	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	19061	S1 A - 250 HR SERVICE	TRAVELLED TO HBMI AND CARRIED OUT 250HR SERVICE AS PER SCHEDULE. REMOVE COLLAPSED MUFFLER AND FIT NEW ONE. REMOVE SIDE ROPS AND TIGHTEN HYDRAULIC TANK MOUNT BOLTS. REPORT ON BROKEN ROPS BRACKET AND REFIT SIDE ROPS. BLOW OUT RADIATOR AND COOLERS AND BLOW OUT ALTERNATOR. REPAIR THREAD ON HARD BAR PLUG AND REPLACE AIR FILTERS AND AIR PRE-CLEANER HOSE	484	464.05	0	0	948.05
100427-0016	SVC00049466	05/19/2010	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	19218 hrs	CHECK COOLANT SENSOR FAULT	TRAVELLED TO DOVER. CHECK FOR ALARM FAULT AND LOCATE FAULTY COOLANT FLOW SWITCH AND BYPASS. ORDER NEW ITEM AND REPLACE	327.5	352.31	0	180	859.81
100422-0025	SVC00048483	05/07/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE APRIL PG.103-2136,	STORE ISSUE APRIL PG.103-2136,	0	139	0	0	139
100419-0018	SVC00048372	04/20/2010	1H0103	ID - EARTHMOVING	186_INT	F	Sundries	1ME507	escort the machine	ESCORT THE MACHINE TO SITE	escort machine to site as requested.	275	0	0	0	275
100319-0001	SVC00047090	04/16/2010	1H0103	ID - EARTHMOVING	182_INT	R	Line Boring	1ME507	19103hr	LINE BORE BLADE PIVOT POINT &	LINE BORE BLADE PIVOT POINTS & TOOL BAR PIVOTS AS REQUIRED, REMOVE HARD BUSHES FROM KNUCKLE BLOCKS, SETUP & BORE TO SUIT NEW BUSH SIZE (HOLES FLOGGED OUT) SUPPLY NEW BUSHES & PINS FOR TOOL BAR PIVOT & BLADE MOUNT, MACHINE BLADE CYLINDER CAPS TO REDUCE PLAY ON BALL PIVOTS, WELD UP CRACKS IN HYD TANK & REPAIR BUCKLED HYD TANK SUPPORT, WELD GUARDING WHERE BROKEN & CRACKED, WELD DOUBLER PLATE TO SUPPORT BRACKET	5632.5	2231.5	0	150	8014
100219-0025	SVC00044711	02/24/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ FEB. 103-1763	PARTS REQ FEB. 103-1763	0	255.24	0	0	255.24
100108-0055	SVC00042238	01/29/2010	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ JAN 103-1463	PARTS REQ JAN 103-1463	0	11.95	0	0	11.95
091231-0026	SVC00042611	01/15/2010	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18801	REPAIR REVERSE ALARM FAULT	TRAVELLED TO MUSSELROE BAY AND CHECK FOR MUFFLER FAULT AND CARRY OUT TEMPORARY REPAIRS TO BRACKET. REPAIR REVERSE ALARM	303.5	0	0	108	411.5
091203-0049	SVC00040600	12/17/2009	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	18763	S1 B - 500 HR SERVICE	TRAVELLED TO MUSSELROE BAY AND CARRIED OUT 500HR SERVICE AS PER SCHEDULE. CHANGE CUTTING EDGES AND CORNER TIPS.	743	312.63	0	317.7	1373.33
091204-0028	SVC00040842	12/17/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	18763	REPLACE 3 RIPPER BOOTS	CARRY OUT REPAIRS TO REPLACE 3 RIPPER BOOTS ON UNIT	99.5	756.57	0	0	856.07
091204-0033	SVC00041263	12/17/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	18763	REPLACE CUTTING EDGES	REPLACE ALL EDGES AND BOLTS ON CUTTING EDGE	835	3090.61	0	0	3925.61
091207-0026	SVC00040902	12/08/2009	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	18671	REPLACE TRACK COVER BOLTS	ONSITE AT MUSSELROE BAY. REMOVE DAMAGED BOLTS FROM TRACK ADJUSTER COVERS, TENSION TRACKS AND REPLACE COVERS WITH NEW BOLTS	201.5	0	0	0	201.5
091108-0013	SVC00040098	11/27/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	18568 hrs	RETENSION CUTTING EDGE BOLTS	TRAVELLED TO UNIT AND RETENSION CUTTING EDGE BOLTS.	62	0	0	90	152
091116-0022	SVC00039402	11/27/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		STORE ISSUE NOV.PG REQ.1186,	STORE ISSUE NOV.PG REQ.1186,	0	202.52	0	0	202.52
091007-0022	SVC00037370	10/15/2009	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	18483	S1 A - 250 HR SERVICE	TRAVELLED TO HBMI AND CARRIED OUT 250HR SERVICE AS PER SCHEDULE	286	135.08	0	45.9	466.98
091008-0033	SVC00037497	10/15/2009	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	18483	REPAIR LEAK AT ENG OIL COOLER	TRAVELLED TO HBMI. REMOVE OIL COOLER PIPING AND REPLACE LEAKING O-RINGS AND TEST	583	73.48	0	43.2	699.68
091001-0019	SVC00037228	10/13/2009	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	18483	REPAIR LEAK AT HYDRAULIC TANK	TRAVELLED TO HBMI. ACCESS HYDRAULIC OIL LEAK AND ORDER NEW PARTS. REPLACE HYDRAULIC FILTER COVER AND REPLACE CUTTING EDGE BOLTS	418	351.19	0	77.4	846.59
091007-0014	SVC00037296	10/07/2009	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	N/A	FABRICATE RIPPER HOSE	TRAVELLED TO MONTROSE AND MAKE REPLACEMENT RIPPER HOSE AS REQUIRED	0	83.71	0	9	92.71
090928-0063	SVC00036904	09/29/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18500	CHECK & REPAIR STARTING FAULT	TRAVELLED TO HBMI. CHECK FOR STARTING FAULT AND LOCATE INTERMITTANT CHARGING FAULT	159.5	0	0	23.4	182.9
090910-0034	SVC00035822	09/25/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ SEPT 09 777	REQ SEPT 09 777	0	147.6	0	0	147.6
090828-0013	SVC00035107	09/24/2009	1H0103	ID - EARTHMOVING	186_INT	F	Tyres	1ME507		SUPPLY LABOUR TO BUILD TRACKS	Labour to assemble track omitted from previous invoice	0	0	1190	0	1190
090917-0077	SVC00036281	09/18/2009	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	18373	CHECK & ADJUST TRACKS	TRAVELLED TO HBMI. ADJUST TRACK TENSION	159.5	4.45	0	21.6	185.55

090909-0023	SVC00035785	09/17/2009	1H0103	ID - EARTHMOVING	184_INT	R	Radio	1ME507	18383	REPLACE UHF BRACKET	TRAVELLED TO HBMI. REPLACE UHF BRACKET ASSEMBLY AND RETUEN AERIAL AND TEST	126.5	41.09	0	21.6	189.19
090828-0039	SVC00035019	09/04/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REFER AUG REQ.PG 21409	REFER AUG REQ.PG 21409	0	115.78	0	0	115.78
071120-0007	SVC00002170	09/03/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REQ.PG 21409	REQ 16620	0	168.4	0	0	168.4
090622-0082	9322	09/03/2009	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507	18223	REPLACE THE TRACKS ETC.		0	-118	0	0	-118
090622-0082	SVC00032831	09/03/2009	1H0103	ID - EARTHMOVING	186_INT	R	Tyres	1ME507	18223	REPLACE THE TRACKS ETC.	Under carriage repairs, The tracks were removed and all the rollers and idlers, the idlers were disassembled and sent to the weld shop for repairs. The idles were built up and skimmed off to size they were then resealed and filled with new oil. The left rear minor boagy pins were removed and replaced as they were dry, The equalizer bar was removed and found to be cracked. A new item was arranged (REPAIRED NOT NEW). The new sprockets were installedand the tracks were refitted, the idlers were reinstalled with new bolts, the track guides were replaced as requiured and the bogie protection plates were turned.	7132.5	12181.54	0	0	19314.04
090819-0010	SVC00034682	08/27/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	18274	REPLACE BROKEN RIPPER PIN	TRAVELLED TO MORNINGTON. ORGANISE PARTS FOR RIPPER CYLINDER AND REFIT RIPPER CYLINDER AND WELD KEEPER PLATES	418	537.15	0	58.5	1013.65
090824-0065	SVC00034683	08/24/2009	1H0103	ID - EARTHMOVING	184_INT	R	Radio	1ME507	18214	UHF RADIO FAULT	TRAVELLED TO HBMI. CHECK FOR UHF RADIO FAULT AND REPAIR WIRING	165	0	0	43.2	208.2
090616-0052	SVC00033274	07/29/2009	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	18554	REPLACE LEAKING COOLANT HOSE	CARRY OUT REPAIRS TO REPLACE COOLANT HOSE FOR B COAD AT GLEN HUON	13.75	0	335.54	0	349.29
090702-0012	SVC00033158	07/29/2009	1H0103	ID - EARTHMOVING	182_INT	R	Milling	1ME507	18224	IDLER REPAIRS & EQUALISER BAR	Clean up equaliser bar and crack test, had found unrepairable cracks. rebuild up idlers and machine to dimensions.	5358.5	190.74	0	0	5549.24
090616-0014	SVC00031015	07/08/2009	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	18224hours	S1 C - 1000 HR SERVICE	Carry out the required service.	154	956.42	0	2.7	1113.12
090519-0026	SVC00029367	06/30/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18122	REPLACE BROKEN WORK LIGHTS	REPAIR SHORT IN WORK LIGHTS AND REPLACE BLOWN GLOBES AS REQUIRED	291.5	207.38	0	0	498.88
090601-0035	SVC00031292	06/19/2009	1H0103	ID - EARTHMOVING	186_INT	R	Suspension/UC	1ME507		SUPPLY UNDER CARRIDGE	supply new under carriage as required.	55	49125	0	0	49180
090317-0048	SVC00025810	06/16/2009	1H0103	ID - EARTHMOVING	186_INT	S	Service	1ME507	17980	S1 A - 250 HR SERVICE	The machine will be in the shop passed the end of the month, hence this is a parts only invoice. CARRY OUT S1-B SERVICE AS PER SCHEDULE	177.5	1050.74	0	0	1228.24
090609-0060	SVC00030615	06/10/2009	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	18152	REPAIR ENGINE GUARD.	ONSITE AT SOUTH CAPE. REPLACE STRIPPED ENGINE GUARD BOLT	93.5	0	0	0	93.5
090528-0069	SVC00030518	06/09/2009	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	18159	REPAIR BROKEN R/H TRACK	28/05 - TRAVEL TO HBMI AND ASSIST GETTING UNIT OFF HEAP. REMOVED R/H BROKEN TRACK. TRANSPORTED AND FITTED SECOND HAND EMECO TRACK AND ADJUSTED - FOUND STRETCHED BEYOND OPERATING LIMIT. 29/05 - TOOK DOWN 2ND EMECO SECOND HAND TRACK AND REMOVED AND REPLACED OUT TRACK. ADJUSTED AND TESTED OK.	1502	30.58	0	190.8	1723.38
090514-0049	SVC00029127	05/28/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REFER MAY REQ.PG 25174	REFER MAY REQ.PG 25174	0	97.14	0	0	97.14
090514-0036	SVC00029667	05/25/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	18113	TIGHTEN CUTTING EDGE BOLTS	TRAVELLED TO COPPLE CREEK. TIGHTEN ALL CUTTING EDGE BOLTS AND CHANGE GREASE NIPPLES	589	0	0	226.8	815.8
090414-0078	SVC00027319	05/12/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ APRIL 25157	PARTS REQ APRIL 25157	0	241.16	0	0	241.16
090428-0014	SVC00028262	05/08/2009	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	18554	REPAIR OVERHEATING FAULT	TRAVELLED TO PICTON. INSPECT OVERHEATING FAULT, REMOVE THERMOSTAT AND FOUND LOBE FAULTY. REASSEMBLT AND TEST. COOLANT FILTER HOSE BLOWN DURING TEST, FABRICATE NEW ONE AND FIT	922	229.3	0	131.4	1282.7
090313-0028	8230	05/06/2009	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	17980	Repairs as listed		0	-1836.29	0	0	-1836.29
090313-0028	SVC00026314	05/06/2009	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	17980	Repairs as listed	CARRY OUT REMOVAL OF COVERS AND INSPECT, REPAIR AND REPLACE TRANS CHARGE PUMP AND HOSES. REMOVE STARTER MOTOR AND SUPPLY NEW UNIT. RECTIFY LEAKING VALVE ON TOP OF TRANS, REMOVE DRIVE SHAFT AND FIT T/CONVERTER OUTPUT SEAL.	6701	6735.67	0	0	13436.67
090313-0028	SVC00028417	05/06/2009	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	17980	Repairs as listed	REPAIR AS LISTED	0	0	0	0	0
090414-0022	SVC00028118	04/28/2009	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	18028	REPLACE TRUNNION CAP BOLTS	TRAVELLED TO GEEVESTON AND WILLIAM ADAMS. PICK UP TRUNNION BOLTS. REMOVE AND FIT NEW BOLTS TO LEFT HAND SIDE OF UNIT	253	161	0	117	531
090421-0007	SVC00027634	04/28/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18022	REPLACE FAULTY IGNITION SWITCH	REPAIR WIRING AND REPLACE IGNITION SWITCH AND TEST GAUGES	141	85.22	0	0	226.22
090403-0026	SVC00027622	04/21/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18013	REPAIR NON STARTING FAULT	TRAVELLED TO GEEVESTON. REPLACE BLOWN FUSE FOR NON STARTING FAULT	121	0	0	36	157
090409-0047	SVC00027240	04/14/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	18015	REPAIR WORK LIGHT	TRAVELLED TO EDWARDS RD. REPAIR SHORT IN WORK LIGHT	249	0	0	72	321
090324-0041	SVC00026200	04/07/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ MARCH 26799	PARTS REQ MARCH 26799	0	15.84	0	0	15.84
090311-0007	SVC00026054	03/26/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	17942	REPLACE CUTTING EDGE BOLTS	CARRY OUT REPAIRS TO REPLACE CUTTING EDGE BOLTS	117	77.12	0	0	194.12
090318-0016	SVC00025816	03/26/2009	1H0103	ID - EARTHMOVING	182_INT	R	Trays/Buckets	1ME507	17980	REPAIRS TO CANOPY CRACKS	REPAIRS TO CANOPY CRACKS, REPAIR CYLINDER ROD, REPAIR BATTERY BOX SUPPORT PLATE, PLATE UNDER TRACK GUARDS, REPAIR RADIATOR GRILL, REPAIR CANOPY HINGES AND REBUSH, FIT MOUNTS TO DOZER	2721.5	323.3	0	0	3044.8
090218-0083	SVC00024453	02/27/2009	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	17903	REPLACE U/S TURBOCHARGER	TRAVELLED TO WEST UXBRIDGE. FIT TURBO O MACHINE, CHECK OIL PRESSURES AND OPERATION	787	5320.82	0	198	6305.82
090217-0025	SVC00024183	02/24/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	17870	REPAIR WORK LIGHTS & UHF.	TRAVELLED TO UXBRIDGE. REPAIR WORK LAMP WIRING AND 2-WAY RADIO FAULT	291.5	26	0	67.5	385
090211-0022	SVC00023925	02/19/2009	1H0103	ID - EARTHMOVING	184_INT	S	Transmission	1ME507	17864	REPLACE TRANS FILTER & SAMPLE	TRAVELLED TO UXBRIDGE. CHANGE TRANSMISSION FILTER AND TAKE OIL SAMPLE. CHECK CRACK IN CAB GUARDING. REMOVE LEFT HAND SIDE COVER AND LOCATE BROKEN BRACKET AND BROKEN BOLTS.CHECK HYDRAULIC OIL LEAK.	297	184.85	0	63.9	545.75
090203-0032	SVC00023687	02/18/2009	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	17820	REPLACE CUTTING EDGE BOLTS.	TRAVELLED TO WEST UXBRIDGE. REPLACE CUTTING EDGE BOLTS AND TIGHTEN	352	194.48	0	121.5	667.98

090202-0066	SVC00023635	02/05/2009	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	17745	REPAIR BURNT WIRING	TRAVELLED TO PLENT LINK RD. REPAIR BURNT WIRING TO LIGHTS	210	0	0	99	309
081203-0094	SVC00021036	01/27/2009	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REFER DEC REQ.26765 PG	REFER DEC REQ.26765 PG	0	437.92	0	0	437.92
090115-0043	SVC00022681	01/20/2009	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17738	S1 B - 500 HR SERVICE	TRAVELLED TO WEST UXBRIDGE TO CARRY OUT S1-B 500HR SERVICE AS PER SCHEDULE	320	642.72	0	92.7	1055.42
080811-0066	SVC00015371	01/13/2009	1H0103	ID - EARTHMOVING	186_INT	R	Sundries	1ME507	17100	PERFORM FULL INSPECTION	PERFORM FULL INSPECTION Fully wash machine Remove rain cap from exhaust stack remove exhaust stack remove defective muffler install new muffler and stack assembly. Check fuel gauge note this tested okay Repair threads in front grill. Threads were all damaged grind out holes and weld in new nuts replace bolts. Repair broken bracket on rear of tractor remove side fender and remove broken bracket modify and strengthen bracket reinstall as required. Inspect all bogie bushings. Repair back window and runner and straighten window track. Inspect tracks and grouser plates grousers are 90% worn track links are 75% worn. Remove complete assemblies take to weld shop for shoes to be reluged. Install track assemblies and adjust as required. Remove idlers and dismantle take idler wheels to weld shop for rebuilding. Reassemble idlers using new seals. Repair timing cover oil leak tightened loose bolts on timing cover remove and replaced broken bolts. Remove floor and clean Found that transmission pump was leaking transmission fluid. Remove transmission charge pump and dismantled ordered new seal kit and reassembled. Inspect transmission filter bypass alarm problem. Removed complete housing and dismantled cut open filters and inspected. Remove and replaced defective transmission hoses. Perform inspection of air conditioning system. Build up behind blade corner tips Remove excessive wear in blade control lever replace worn joints as required. Repair faulty lights and short circuit in wiper motor system. Remove and replace broken bolts in idler retaining caps Remove and replace wiper blades Repair reverse alarm Replace 2 way aerial.	13696.25	3872.09	0	0	17568.34
081215-0027	SVC00021592	12/23/2008	1H0103	ID - EARTHMOVING	184_INT	R	Tyres	1ME507	17633	REPLACE BROKEN GROUSER BOLTS	REPLACE CUTTING EDGE BOLTS AND TIGHTEN TRACK BOLTS	357.5	69.24	0	101.7	528.44
081222-0013	SVC00021915	12/22/2008	1H0103	ID - EARTHMOVING	184_INT	R	Radio	1ME507	17611	REPLACE UHF MICROPHONE	REPLACE UHF MIC AND CHECK COAX AND REPAIR	180	29.96	0	31.5	241.46
081222-0045	SVC00021962	12/22/2008	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	17502	FABRICATE HOSE - BLADE TILT	FABRICATE HOSE AS PER SAMPLE FOR BLADE TILE HOSE AND LEAVE IN "A" BOX	50	56.22	0	0	106.22
081125-0007	SVC00021852	12/19/2008	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	17545	REPLACE FRONT GRILLE BOLTS	TRAVELLED TO PLENTY LINK. REPAIR FRONT GRILL MOUNTING BOLTS	355	0	0	99	454
081204-0028	SVC00021068	12/05/2008	1H0103	ID - EARTHMOVING	184_INT	R	Trays/Buckets	1ME507	17483 HRS	REPAIR CRACKS IN BLADE	TRAVELLED TO BRACKEN RIDGE. REPAIR CRACKS IN BLADE	210	0	0	136.8	346.8
081110-0085	SVC00020417	11/27/2008	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REFER REQ.26575 PG	REFER REQ.26575 PG	0	236.35	0	0	236.35
081117-0017	SVC00020727	11/27/2008	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	17508.	Replace U/S Battery.	TRAVELLED TO BRACKEN RIDGE. REMOVE BATTERY COVER AND REPLACE BATTERY, CLEAN TERMINALS AND REASSEMBLE	410	208.18	0	207	825.18
081111-0030	SVC00019732	11/25/2008	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17481 HRS	S1 A - 250 HR SERVICE.	TRAVELLED TO BRACKEN RIDGE. CARRIED OUT S1-A 250HR SERVICE AS PER SCHEDULE. REPLACE DAMAGED PAD LOCKS	330	300.29	0	88.2	718.49
081120-0022	SVC00020303	11/20/2008	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	17475 HRS	INSPECT LEAKING HYD PUMP	TRAVELLED TO BRACKEN RIDGE. REMOVE BELLY PLATES AND INSPECT FOR OIL LEAK, OIL LEAKING FROM BETWEEN HYDRAULIC PUMPS, REPAIR AND REPLACE BELLY PLATES	240	0	0	81	321
081105-0028	SVC00019672	11/17/2008	1H0103	ID - EARTHMOVING	184_INT	R	Ground Engaging	1ME507	17463	REPLACE CUTTING EDGE BOLTS.	TRAVELLED TO BRACKEN RIDGE. REMOVE CUTTING EDGE AND REPLACE BOLTS, TIGHTEN BOLTS USING PALM	325	196.32	0	49.5	570.82
081117-0056	SVC00020182	11/17/2008	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	17350	FABRICATE HOSE FOR BLADE TILT	FABRICATE NEW HOSE FOR BLADE TILT CYLINDER	50	40.75	0	0	90.75
081017-0108	SVC00018655	11/13/2008	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		PARTS REQ. OCT 13346	PARTS REQ. OCT 13346	0	347.48	0	0	347.48
081027-0036	SVC00019721	11/12/2008	1H0103	ID - EARTHMOVING	184_INT	R	Engine	1ME507	17426.	REPLACE U/S FAN BELTS ETC.	27/10 - REMOVED ENGINE BELTS FROM HIRE D8R DZ138 AFTER NO NEW BELTS AVAILABLE AND TOOK TO UNIT AND FITTED. BELTS NEED TO BE REPLACED AS THEY ARE NOT QUITE THE SAME. 29/10 - TRAVELLED TO UNIT AND REPLACED OUT BELTS WITH NEW SETS. 04/11 - REFITTED BELTS TO DZ138 AND RAN AND TESTED OK.	876.25	186.66	0	187.2	1250.11
081013-0050	SVC00019043	10/28/2008	1H0103	ID - EARTHMOVING	184_INT	R	Bodywork	1ME507	13758	REPLACE BROKEN WINDSCREEN.	TRAVELLED TO ARVE LOOP. REMOVE AND REPLACE FRONT SCREEN AND WIPER, ADJUST BOTH TRACKS	390	243.46	0	187.2	820.66
081028-0070	SVC00019110	10/28/2008	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	17329	CAB FAN FAULT	TRAVELLED TO HOPETOUN RD. REPAIR CAB FAN FAULT AND REPAIR REAR WORK LIGHTS AND UHF	335	0	0	58.5	393.5
080818-0008	SVC00015775	10/17/2008	1H0103	ID - EARTHMOVING	182_INT	R	Drive Line	1ME507		BUILD UP IDLERS	BUILD UP IDLERS AND DUBLERS TO SIDE TO STRENGHTEN	2684.25	442.24	0	0	3126.49
080818-0037	SVC00015413	10/17/2008	1H0103	ID - EARTHMOVING	182_INT	R	Drive Line	1ME507		RELUG GROUSER PLATES	RELUG GROUSER WITH SECTION 92 RELUG BAR	11155.5	3322.31	0	0	14477.81
081015-0050	SVC00018451	10/15/2008	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17270 HRS	MISSING LABOUR 080925-0022	LABOUR MISSED OFF SERVICE CALL 080925-0022. CARRY OUT S1-D SERVICE ON DOZER AS PER SCHEDULE, TIGHTEN TRUNION BOLTS AND DISPOSE OF WASTE OILS AND FILTERS	420	0	0	108	528
081002-0016	SVC00017922	10/02/2008	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	16920 HRS	REPAIR AIR CON WIRING	TRAVELLED TO DOVER 28/8/08. REPAIR FAULT WITH AIR CONDITIONING WIRING	150	0	0	43.2	193.2
080926-0072	SVC00017617	09/26/2008	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	17111 HRS	INSPECT HYDRAULIC TANK	TRAVELLED TO HBMI. INSPECT HYDRAULIC TANK PLATE, TOP UP HYDRAULIC OIL LEVEL, FIT HARD BAR PLUG AND TIDY WIRING BEHIND SEAT	120	68.8	0	43.2	232

080915-0038	SVC00016675	09/25/2008	1H0103	ID - EARTHMOVING	122_INT	R	Sundries	1ME507		REFER REQ.13337 PG	REFER REQ.13337 PG	0	123.36	0	0	123.36
080923-0019	SVC00017089	09/24/2008	1H0103	ID - EARTHMOVING	184_INT	R	Transmission	1ME507	17180	REPLACE TRANS HOSES	REPLACE TRANSMISSION FILTER HOSES	135	60.56	0	0	195.56
080529-0023	SVC00015126	08/14/2008	1H0103	ID - EARTHMOVING	184_INT	R	Electrical	1ME507	17095	REPLACE U/S FUEL GAUGE.	ON SITE AT DRY POLES RD.REPLACE UNSERVICABLE FUEL GAUGE	152.5	65.66	0	0	218.16
080725-0004	SVC00014659	08/01/2008	1H0103	ID - EARTHMOVING	184_INT	R	Hydraulic	1ME507	17057.	REPLACE HYDRAULIC COOLER HOSE	TRAVELLED TO ELLENSDALE. REPLACE OIL COOLER HOSE ON UNIT	407.5	357.74	0	144	909.24
080711-0046	SVC00014442	07/29/2008	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		REFER REQ.13319 PG	REFER REQ.13319 PG	0	5.34	0	0	5.34
080701-0022	SVC00013219	07/26/2008	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17002HRS	S1 A - 250 HR SERVICE.	TRAVEL TO DRY POLES - S1A - SERVICE UNIT. REFIT NEW BOLTS IN THE BACK OF DOZER FRAME. RETENSION TRUNION BOLTS, REPLACE RIPPER BOOT PINS.	0	348.97	0	101.7	450.67
080701-0022	SVC00014275	07/26/2008	1H0103	ID - EARTHMOVING	184_INT	S	Service	1ME507	17002HRS	S1 A - 250 HR SERVICE.	LABOUR MISSING FROM INVOICE NUMBER SVC00013219	357.5	0	0	0	357.5
080711-0020	SVC00013616	07/15/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16898	FABRICATE RIPPER HOSE	FABRICATE NEW RIPPER HOSE	82.5	51.32	0	0	133.82
080612-0063	SVC00011949	07/05/2008	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		REFER REQ.13308	REER TO REQ 13308	0	398.97	0	0	398.97
080620-0071	SVC00013001	06/27/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507		REPLACE LIFT CYLINDER TUBE ASS	REPLACE LIFT CYLINDER TUBE ASSEMBLY - PARTS ONLY	0	354.6	0	3.5	358.1
071011-0044	SVC00000362	06/24/2008	1H0103	ID - EXCAVATING	189_INT	W	Tyres	1ME507	15690HRS	WET TURN TRACK PINS AND BUSHES	ODOMETER: 15690HRS	1856.25	0	0	2	1858.25
080620-0043	SVC00012528	06/23/2008	1H0103	ID - EXCAVATING	184_INT	R	Bodywork	1ME507	16854	REPLACE MISSING BOLTS	TRAVELLED TO DRY POLE RD TO REPLACE MISSING GRILL BOLTS ON UNIT	100	4.2	0	96	200.2
080520-0086	SVC00010816	06/19/2008	1H0103	ID - EXCAVATING	182_INT	R	Hydraulic	1ME507		REPAIR LEAK IN HYDRAULIC PIPE	REPAIR HOLE IN HYDRAULIC LINE, NEED'S REPLACING WITH NEW LINE REQUESTED BY PETER STELFOX	67.5	0	0	0	67.5
080612-0005	SVC00011921	06/16/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16822	FABRICATE NEW HOSE	FABRICATE NEW HOSE AS PER SAMPLE	35	47.14	0	0	82.14
080530-0040	SVC00011535	06/04/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16822	FABRICATE 2 HOSES	FABRICATE 2 NEW HOSES AS PER SAMPLES	101.25	103.32	0	12	216.57
080429-0071	SVC00009707	06/03/2008	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		PARTS REQ 17182	REFER TO PARTS REQ 17182	0	296.16	0	0	296.16
080529-0020	SVC00011423	05/30/2008	1H0103	ID - EXCAVATING	184_INT	R	Ground Engaging	1ME507	16735 HRS	REPLACE MISSING RIPPER PIN	TRAVELLED TO ADAMSONS RD. REPLACE MISSING RIPPER PIN BOLTS AND PLUG FUEL TANK DRAIN PIPE	150	0	0	88	238
080501-0047	SVC00011228	05/27/2008	1H0103	ID - EXCAVATING	184_INT	F	Ground Engaging	1ME507	16731	TURN & REPLACE CUTTING EDGES	5/5/08 - TRAVELLED TO MONTROSE/AUSTINS FERRY. PICK UP DOZER CUTTING TIPS AND BOLTS FROM WILLIM ADAMS AND DELIVER PARTS TO N OWENS.	605	952.6	0	228	1785.6
080514-0022	SVC00010381	05/27/2008	1H0103	ID - EXCAVATING	184_INT	S	Service	1ME507	16731	S1 B - 500 HR SERVICE.	16/5/08 - TRAVEL TO UNIT AT ESPERANCE AND REMOVE AND REPLACE CORNER TIPS AND TURN CENTRE EDGES	478.75	544.95	0	200	1223.7
080520-0092	SVC00010822	05/27/2008	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		REFER REQ.17198 KELLY G.	REFER TO REQ. 17198 FROM KELLY GORDON	0	175.26	0	0	175.26
080414-0019	SVC00008601	05/14/2008	1H0103	ID - EXCAVATING	184_INT	R	Radio	1ME507	16244 HRS	REPLACE VOLTAGE REDUCER.	TRAVELLED TO DOVER. CHECK FOR FORESTRY 2-WAY RADIO FAULT, FIT AND WIRE UP NEW VOLTAGE REDUCER, CHECK FOR RECEIVING FAULT AND RETURN RADIO AND TEST	420	369.02	0	176	965.02
080502-0007	SVC00009888	05/02/2008	1H0103	ID - EXCAVATING	184_INT	R	Trays/Buckets	1ME507	16613	REPAIR CRACKS IN BLADE	UNIT: 1ME507	230	0	0	140	370
080410-0094	SVC00008644	04/15/2008	1H0103	ID - EXCAVATING	184_INT	R	Trimming	1ME507	16534	REPLACE SEAT SUSPENSION BASE.	TRAVEL TO GEEVESTON - REPAIR ALL CRACKS IN BLADE. TRAVELLED TO ADAMSONS RD.REMOVE SEAT FROM BASE AND REASSEMBLE UNIT, TIGHTEN TRACK GUIDE, REPLACE AIR FILTERS, ATEMPT TO REFIT GRILL BOLTS, BRACKET BENT OUT OF SHAPE REQUIRES REMANUFACTURING	208.75	1188.67	0	176	1573.42
080326-0039	SVC00007624	04/14/2008	1H0103	ID - EXCAVATING	184_INT	R	Electrical	1ME507	16443	Replace work lights	TRAVELLED TO GARDEN ISLAND CREEK. REPAIR REAR LIGHT WIRING, FIT NEW WORK LIGHT TO DOZER, CHECK FOR ALTERNATOR LIGHT FAULT AND LOCATE FAULT ALTERNATOR	548.75	1413.11	0	76	2037.86
080401-0017	SVC00008389	04/14/2008	1H0103	ID - EXCAVATING	184_INT	S	Service	1ME507	16475 HRS	S1 A - 250 HR SERVICE.		278.75	488.36	0	76	843.11
080131-0019	SVC00004404	03/07/2008	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		PARTS REQ 17151 K GORDON		0	178.64	0	0	178.64
080212-0060	SVC00006407	03/07/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507		REPLACE DAMAGED HOSES ON RIP	TRAVELLED TO GARDEN ISLAND CREEK. REMOVE AND REPLACE HYDRAULIC HOSE, REFIT SEAT, FLOOR PLATES AND BELLY PLATES	403.75	120.79	0	128	652.54
080305-0060	SVC00006330	03/06/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16323HRS	REPAIR LEAKING HYRAULIC HOSE	ODOMETER: 16323KMS	677.5	170.68	0	174.4	1022.58
071004-0041	SVC00001607	02/26/2008	1H0103	ID - EXCAVATING	186_INT	R		1ME507	15690	INSPECT ENGINE BOTTOM END	INSPECT FOR OIL LEAK. REMOVE BELLY PLATES. CLEAN AROUND TRANSMISSION. REMOVE LEAKING HYRAULIC HOSE AND FIT NEW HOSE. REFIT BELLY PLATES. FIT DOOR SEAL AND REFIT CAB FLOOR AND SEAT	1937.5	3016.87	0	0	4954.37
080220-0022	SVC00005557	02/26/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16222	MAKE 2 HOSES AS PER SAMPLE	TRAVELLED TO HARDIE SPICER IN MONTROSE. MAKE 2 HOSES AS PER SAMPLE FOR BADEN FIELDING	78.75	120.46	0	12.8	212.01
080226-0015	SVC00005806	02/26/2008	1H0103	ID - EXCAVATING	184_INT	R	Electrical	1ME507	16284	REPAIR AIR CON FAULT	TRAVELLED TO HBMI. REPAIR AIR CONDITIONOR FAULTY AND LOCATE BROKEN WIRING ON RECEIVER DRIER AS REQUIRED	77.5	0	0	19.2	96.7

080222-0015	SVC00005683	02/25/2008	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	16226	REPAIR HYDRAULIC LINES & FIT	TRAVELLED TO WATERLOO X 2. CHECK AND REPAIR HYDRAULIC HOSES AND FITTINGS, ORDER NEW HYDRAULIC CLAMPS AND HAVE NEW HOSES MADE	433.75	257.55	0	272	963.3
080207-0025	SVC00005573	02/21/2008	1H0103	ID - EXCAVATING	184_INT	R	Ground Engaging	1ME507	16195	REPLACE MISSING RIPPER PIN.		0	320.75	0	0	320.75
080206-0008	SVC00004755	02/15/2008	1H0103	ID - EXCAVATING	184_INT	R	Radio	1ME507	16195	REPLACE UHF RADIO.	ODOMETER: 16195	201.25	290.08	0	38.4	529.73
080124-0073	SVC00004799	02/07/2008	1H0103	ID - EXCAVATING	184_INT	R	Ancillary Equip	1ME507	15904	CHECK AIR CONDITIONING SYSTEM.	TRAVEL TO HERMANS ROAD - CHECK FOR UHF RADIO FAULT, LOCATE FAULTY RADIO AND REPLACE. REPAIR DAMAGED FRONT AND REAR WORK LIGHT WIRING AND REPLACE WIRING CONNECTOR ON RELEIVER DRIVER FOR A/C SYSTEM. TRAVELLED TO HERMONS RD. REPAIR AIR CONDITIONING FAULT, REPLACE CAB FILTER AND REPAIR UHF AERIAL	176.25	67.93	0	28	272.18
080131-0055	SVC00004427	02/07/2008	1H0103	ID - EXCAVATING	184_INT	S	Service	1ME507	16173	S1 C -1000 HR SERVICE.	TRAVELLED TO HERMONS RD. CARRIED OUT SERVICE AND CHECK AS PER SCHEDUEL	335	590.39	0	56	981.39
080124-0064	SVC00004133	01/24/2008	1H0103	ID - EXCAVATING	188_INT	R	Electrical	1ME507	15988	REPAIR WORK LIGHT WIRING SERVIC	TRAVELLED TO DOVER ON 21.12.07. REPAIR WORK LIGHT WIRING AS REQUESTED	100	0	0	68.8	168.8
080104-0031	84	01/08/2008	1H0103	ID - EXCAVATING	182_INT	R	Engine	1ME507				0	0	0	0	0
071219-0020	SVC00000822	12/19/2007	1H0103	ID - EXCAVATING	184_INT	R	Radio	1ME507	15902	REPAIR UHF RADIO	TRAVELLED TO DOVER. REPAIR UHF RADIO AND FORESTRY AERIAL FOR TRANSMISSION FAULT	112.5	0	0	17.5	130
071120-0111	SVC00002263	12/06/2007	1H0103	ID - EXCAVATING	122_INT	R	Sundries	1ME507		PARTS AS PER REQ 16608		0	22.18	0	0	22.18
071127-0071	SVC00002713	12/06/2007	1H0103	ID - EXCAVATING	184_INT	S	Service	1ME507	15881	S1 A - 250 HR SERVICE.	TRAVELLED TO LEITHBRIDGE RD. SERVICE AND CHECK AS PER SCHEDUEL	180	730.48	0	40.6	951.08
071121-0029	SVC00002345	11/26/2007	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	15790	REPLACE HYDRAULIC HOSES	TRAVELLED TO NEW RD FRANKLIN. REPLACE LEAKING HYDRAULIC HOSE PUMP TO TRANSMISSION	298.75	42.86	0	97.6	439.21
071010-0015	SVC00001739	11/21/2007	1H0103	ID - EXCAVATING	182_INT	F	Sundries	1ME507		FABRICATE 5MM BOX AND 2 HANDLE	FABRICATE 5MM BOX AND 2 HANDLES GOUGE OUT CRACKS AND WELD UP	408.5	48.52	0	0	457.02
071120-0153	SVC00002318	11/21/2007	1H0103	ID - EXCAVATING	184_INT	R	Trays/Buckets	1ME507	15800	CHECK AND RE-SHIM BLADES	TRAVELLED TO FRANKLIN. CHECK AND RE-SHIM BLADE TRUNION, TIGHTEN ALL BOLTS IN TRACKSEGMENTS	292.5	0	0	112	404.5
071005-0002	SVC00001608	11/20/2007	1H0103	ID - EXCAVATING	186_INT	R	Drive Line	1ME507		REMOVE TRACK ASSEMBLIES	REMOVE TRACK ASSEMBLIES. POSITION MACHINE AS REQUIRED. REMOVE PLOUGH AS REQUIRED. LIFT OUT RIPPER TINES FROM RIPPER ASSEMBLY AS NECESSARY. WELD PLATES ON TO THE BOOGIES TO RETAIN THEM INTO POSITION. PLACE MACHINE OFF THE GROUND ON STANDS, REMOVE TRACK ASSEMBLIES. COIL UP TRACK ASSEMBLIES FOR DELIVERY TO WILLIAM ADAMS TO HAVE THEM TURN THE PINS AND BUSHES. INSTALL TRACKS AND ADJUST AS REQUIRED.	416.25	74	11776.87	0	12267.12
071120-0067	SVC00002223	11/20/2007	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	15790	REPLACE HYDRAULIC HOSES	TRAVEL TO NEW RD. REMOVE FLOOR PLATE AND INSPECT FOR OIL LEAKS, CLEANING TOP OF TRANSMISSION FOUND LEAKING HOSE, BARRY TO FABRICATE NEW HOSE FOR TRANSMISSION	161.25	0	0	60	221.25
071002-0008	SVC00000054	11/15/2007	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507		REPLACE BLOWN HYDRAULIC HOSES	TRAVELLED TO EAST BAGDAD X 3. REMOVE BELLY PLATES. CLEAN OUT RUBBISH FROM TRANSMISSION AND PUMPS. REMOVE DAMAGED HOSES AND CLEAN AROUND FITTINGS. MANUFACTURE AND FIT NEW HOSES.TOP UP HYDRAULIC OIL. TEST OPERATION CHECKING FOR LEAKS OK. REFIT BELLY PLATES, FLOOR AND SEAT. SUPPLY FITTING AND LEAVE IN "A" BOX MANUFACTURE HOSE AS PER SAMPLE AND LEAVE IN "A" BOX. TRAVEL TO HBMI X 2 AND MONTROSE. REMOVE BLOWN HOSE, TAKE TO HARDIE SPICER AND GET NEW HOSE MADE, RETURN TO HBMI AND FIT HOSE AND TEST	1066.25	427.31	0	315.2	1808.76
071114-0039	SVC00001968	11/14/2007	1H0103	ID - EXCAVATING	184_INT	R	Hydraulic	1ME507	18380 HRS	REPLACE HYDRAULIC HOSES	TRAVELLED TO HBMI AND NEW RD FRANKLIN. TOP UP HYDRALIC OIL, INSPECT SCREENS, CHECK PPS & CIRCUITS, ADJUST PRESSURES, TEST UNIT AND MAKE 2 HOSES AS PER SAMPLE	316.25	127.68	0	81.6	525.53
071003-0079	SVC00001602	11/13/2007	1H0103	ID - EXCAVATING	186_INT	R	Transmission	1ME507		REBUILD TRANSMISSION	REBUILD TRANSMISSION. REMOVE HYDRAULIC HOSES FROM RIPPER CONTROL VALVE, REMOVE RIPPER CONTROL VALVE. REMOVE INNER AND OUTER AXLES, INSTALL TOOLING TO REMOVE TRANSMISSION. REPLACE SPIDERS IN MAIN TAIL SHAFT. NOTE HAD TO GAS CUT BENT PIECE OF FRAME OUT TO ALLOW ACCESS TO THE TRANSMISSION. DRAIN TRANSMISSION OIL, REMOVE TAIL SHAFT,REMOVE TRANSMISSION AND DISMANTLE FOR INSPECTION. CLEANED ALL PARTS AND ORDERED REQUIRED PARTS. REPLACED 10 DRIVE DISCS IN CLUTCH PACKS, BEARINGS AND SEALS ALSO REPLACED SOME GEARS WHERE NECESSARY. REMOVED AND REPLACED TRANSMISSION GEAR SELECTOR CABLES AS REQUIRED. INSTALLED TRANSMISSION, REFILL WITH NEW OIL AND REPLACE TRANSMISSION FILTERS. TEST PRESSURES AS REQUIRED.	6266.25	3659.97	67	0	9993.22
071004-0027	SVC0000378	11/13/2007	1H0103	ID - EXCAVATING	186_INT	R		1ME507		CLEAN MACHINETO	CLEAN MACHINE. MACHINE DELIVERED TO WASH BAY, REMOVE ALL UNDER BELLY GUARDS AND DEGREASE MACHINE AS NECESSARY. PERFORM FULL STEAM CLEAN OF ALL COMPONENTS. REPLACE ALL BELLY GUARD BOLTS AND NUTS REINSTALL ALL GUARDS.	1206.25	740.58	0	0	1946.83
071004-0029	SVC00001606	11/13/2007	1H0103	ID - EXCAVATING	186_INT	R	Transmission	1ME507		Remove and rebuild torque conv	REMOVE AND REBUILD TORQUE CONVERTER. DRAIN TORQUE CONVERTER OIL, REMOVE VARIOUS HOSES, REMOVE CONVERTER AND TORQUE DIVIDER, DISMANTLE CONVERTER AND DIVIDER AS REQUIRED. CLEAN ALL PARTS AND ORDER NECESSARY PARTS. REPLACE BEARINGS AND SEALS AND SOME GEARS. REASSEMBLE CONVERTER AND DIVIDER, INSTALL BACK INTO MACHINE, REPLACE VARIOUS DEFECTIVE HYDRAULIC HOSES WHERE REQUIRED. REMOVE,DISMANTLE AND REASSEMBLE TRANSMISSION,START FITTING LEFT HAND SEGMENTS	4898.75	732.86	797.37	0	6428.98
071012-0008	SVC00001601	11/13/2007	1H0103	ID - EXCAVATING	186_INT	R	Differential-FD	1ME507		INSPECT FINAL DRIVES	INSPECT FINAL DRIVE. REMOVE SPROCKET ASSEMBLIES, NOTE SPROCKET SEGMENTS HAD WORKED LOOSE ON THE RIGHT FINAL DRIVE. ALSO DUO CONE SEALS WERE LEAKING ON THE RIGHT HAND SIDE. REMOVE COMPLETE FINAL DRIVE AND DISMANTLE AS REQUIRED, REPLACE DUO CONE SEALS, REASSEMBLE AND TEST OPERATION	2996.88	615.74	2180.5	0	5793.12
071112-0062	SVC00001831	11/13/2007	1H0103	ID - EXCAVATING	184FIELDSE	R	Electrical	1ME507		REPAIR FORESTRY RADIO	REPAIR FORESTRY RADIO AS REQUIRED	45	0	0	0	45
071018-0041	SVC0000736	10/23/2007	1H0103	ID - EXCAVATING	184_INT	R	Electrical	1ME507		REPAIR WIRING IN TRAVEL ALARM	REPAIR WIRING TO TRAVEL ALARM. REPAIR CHAFFED WIRING IN ENGINE HARNESS AND REPAIR UHF COX AS REQUIRED.	200	0	0	0	200
071002-0026	SVC0000153	10/16/2007	1H0103	ID - EXCAVATING	184FIELDSE	R		1ME507	15734	REALACE INJECTOR LINE	TRAVELLED TO EAST BAGDAD. REMOVE AND REPLACE BROKEN INJECTOR PIPE. TEST OPERATION OK.	150	202.47	0	70.4	422.87

Applied filters:
Equipment_ID
is 1ME507
Posted_Date is
on or after
01/01/1900