

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontractor Cost	Other Cost	Total Cost
97390	117183	09/09/2026	1HM368HB	ID - TRUCK	186G	R	Sundries	1VT899	0.0000	425265	Pre Disposal	CARRIED OUT PRE DISPOSAL WIPED AND CLEANED ALL CAB VACCUMED ALL THE DIRT AND CLEANED OUT RUBBISH	385	15	120	15	520
97318		09/08/2026	1HM368HB	ID - TRUCK	181G	R	Bodywork	1VT899	0.0000	0	REMOVE HAZELL SIGNAGE PREP FOR SALE		440	0	0	0	440
97250	116567	09/07/2026	1HM368HB	ID - TRUCK	186G	R	Electrical	1VT899	9740.0000	0	REPLACE U/S BATTERIES	CARRIED OUT REPLACMENT TO U/C BATTERY -REPLACED BATTERY ON TRUCK ALL OK	220	198.82	0	0	418.82
90447	109762	05/14/2026	1HM368HB	ID - TRUCK	186G		Chassis	1VT899	9740.0000	425265	INSPECT TRUCK - ISSUE FROM LKW		276	50	400.26	50	726.26
77929	94261	09/15/2025	1HM368HB	ID - TRUCK	184G	R	Clutch	1VT899	8858.0000	0	ADJUST CLUTCH	TRAVELLED TO LKW ADJUSTED CLUTCH & CHECKED OVER - ALL OK	100	15	0	165	265
77974	94736	09/15/2025	1HM368HB	ID - TRUCK	184G	R	Electrical	1VT899	9200.0000		BOWL CONTROLS & LIST OF REPAIRS	HOUR METER: 9,200 HRS - CHECKED LOSS OF REV UP / DOWN FUNCTIONS. FOUND NO POWER TO MOTOR. TRACED & FOUND RELAY IN CONTROL BOX TO BE U/S. REPLACED & TESTED - ALL OK AT TIME OF TESTING. - REPLACED 2x FAULTY PENDANTS. - REPLACED U/S HYDRAULIC FAN & OVER-RIDE SWITCH. - REMOVED & REPAIRED FAULTY DOOR HANDLE. FIX LOOSE MUD GUARD	1607.75	348.91	0	1540	3396.66
74742	89869	07/21/2025	1HM368HB	ID - TRUCK	184G	R	Sundries	1VT899	0.0000	0	PMI inspection	NOTES: NUMBER PLATE LIGHT BROKEN	1000	30	0	30	1030
72738	88392	06/13/2025	1HM368HB	ID - TRUCK	184G	R	Sundries	1VT899	8858.0000	0	CHANGE FLAT TYRE		300	0	0	0	300
72199	87362	06/03/2025	1HM368HB	ID - TRUCK	186G	R	Tyres	1VT899	0.0000	0	FORELANDER D901 X1 + TYRE DISPOSAL X1		24	405	0	0	429
71912	87210	05/28/2025	1HM368HB	ID - TRUCK	184G	S	Service Ear	1VT899	8858.0000	0	B SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - SPRING PIN BUSHES WORN - REAR TORQUE ROD BUSHES WORN - LIFT PUMP LEAKING	400	260.04	0	80	740.04
68941	84295	03/31/2025	1HM368HB	ID - TRUCK	184G	R	Sundries	1VT899	8858.0000	0	Inspection and repairs	FOUND REAR CHUTE TO BE BENT AND NOT ALLOWING EXTENSIONS BEND AND STRAIGHTEN, TEST ALL OK	802.34	90	0	0	892.34
67767	81098	03/07/2025	1HM368HB	ID - TRUCK	184G	S	Service Ear	1VT899	8858.0000	0	B SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - FOUND BLOWN DRIVE TYRE, LH 1ST DRVIE REMOVE AND REPLACE - FOUND WINDOW WASHER BLOCKED, PULL APART NOZZELS/HOSES AND CLEAR BLOCKAGES TEST ALL OK - FOUND LIVE DRIVE SHAFT COVER BROKEN AND BRACKET BROKEN IN HALF. REMOVE AND RE WELD BRACKET, WELD UP LIVE DRIVE COVER AS REQUIRED	766.38	431.42	0	75	1272.8
67838	80967	03/07/2025	1HM368HB	ID - TRUCK	184G	R	Electrical	1VT899	8858.0000	0	FIT REVERSE CAMERA		499.79	0	0	30	529.79
66788	79280	02/19/2025	1HM368HB	ID - TRUCK	186G	R	Tyres	1VT899	8858.0000	0	DRIVE TYRE FORLANDER 828 X1 + DIS X1		22.53	410	0	0	432.53
66613	80123	02/17/2025	1HM368HB	ID - TRUCK	184G	R	Bodywork	1VT899	0.0000	0	Check and repair window	ATTEND TO WINDOW STUCK DOWN FOUND MECHANISM TO BE BROKEN REMOVE DOOR CARD AND SCREW WINDOW UP REFIT COVER	103.35	0	0	0	103.35

65737	78437	01/31/2025	1HM368HB ID - TRUCK 186G	R	Chassis	1VT899	8858.0000	0	Tighten loose Gard Poles		93.28	0	0	0	93.28
63070	79314	12/16/2024	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	8858.0000	0	A/C and Lights repairs	CARRY OUT A/C AND LIGHT REPAIRS AS REQUIRED	1702.36	587.44	0	210	2499.8
62274	76046	12/02/2024	1HM368HB ID - TRUCK 184G	R	Tyres	1VT899	8242.3000	0	Swap out flat tyre and take to ruband	CHANGE OVER FLAT TYRE	299.98	0	0	0	299.98
										LOAD FLAT TYRE AND DROP OFF TO RUBAND					
60743	73834	11/04/2024	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	8242.3000	0	Fit supplied wiper blades + inspect		93.28	0	0	0	93.28
60130	72381	10/21/2024	1HM368HB ID - TRUCK 184G	S	Service Trai	1VT899	8242.3000	0	Carry Out B Service @ LKW	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES - REPLACE HEADLIGHT GLOBES - LH HEADLIGHT INOP ON LOW BEAM	675.22	331.4	0	700	1706.62
59303	71913	10/04/2024	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	0.0000	0	CARRY OUT INSPECTION	CHECK FOR BELT FAULT, FOUND A/C COMPRESSOR SEIZED	93.28	0	0	50	143.28
										NOTES: A/C COMPRESSOR TO BE REPLACED					
59077	72270	10/01/2024	1HM368HB ID - TRUCK 184G	R	Chassis	1VT899	8242.3000	0	SUPPLY 1' BALL VALVE		0	21.32	0	0	21.32
57877	70213	09/04/2024	1HM368HB ID - TRUCK 184G	R	Tyres	1VT899	8242.3000	0	TYRE REPAIRS	REMOVE AND REPLACED FLAT TYRES TRNASPORTED FLATS AND NEW TYRES TO LA AND RETURN LKW	583	820	0	655	2058
56605	68205	08/12/2024	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	8242.3000	0	weld delivery chute	WELD BROKEN CHUTE HOOKS ON DELIVERY CHUTE	186.56	0	0	145	331.56
55750	68304	07/26/2024	1HM368HB ID - TRUCK 184G	S	Service Trai	1VT899	0.0000	0	S1 B SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES	326.48	316.15	0	60	702.63
										FOUND TORQUE RODS ON RHS RTO BE LOOSE, UNSEIZED BOLTS AND RETIGHTEN ALL OK					
54004	65199	06/25/2024	1HM368HB ID - TRUCK 184G	R	Electrical	1VT899	8242.3000	0	Fit up light bar check fan and tail light fault	SUPPLIED AND FITTED LIGHT BAR TRAVELLED TO LA TO COLLECT PARTS FROM LKW	948.17	157.97	0	50	1156.14
										TESTED OK					
53311	63571	06/11/2024	1HM368HB ID - TRUCK 184G	R	Electrical	1VT899	8242.3000	0	Inspect and repair for rev up fault	CHECKED ENGINE NOT REVING UP THROUGH PENDANT CONTROLS TESTED THOROUGHLY FOR AN HOUR, CONTACT CLEANED CONNECTIONS. NO FAULTS FOUND	443.08	0	0	20	463.08
45603	56371	01/24/2024	1HM368HB ID - TRUCK 186G	R	Engine	1VT899	8242.3000	420235	Repair Fuel Pump Couplink	CHECK REPORTED FUEL PUMP FAULT: - FOUND FUEL PUMP COUPLING BROKEN - FIT COUPLER TO PUMP AND REFIT PUMP - ADJUST PUMP TIMING - ADVANCED PUMP TIMING, TESTED, ALL OK.	1476	337.76	0	90	1903.76
44732	57084	12/22/2023	1HM368HB ID - TRUCK 184G	R	Electrical	1VT899	8200.0000	0	Breakdown- Revving	INSPECTED BLACK SMOKE. FOUND ENGINE BRAKE ON WHILE BOWL DISCHARGING.	672.75	7.43	0	35	715.18
44415	53354	12/18/2023	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	8200.0000	0	Swap over Pause Valve - LKW	FIT NEW VALVE & REPAIRED TORN OFF MUDFLAP	1228.01	0	0	60	1288.01
44050	52521	12/11/2023	1HM368HB ID - TRUCK 184G	R	Sundries	1VT899	8200.0000	420500	A/C repairs	CHECKED NO A/C IN TRUCK FITTED GAUGES, COMPRESSOR NOT CUTTING IN. FOUND PRESSURE SWITCH FAULTY. REPLACED PRESSURE SWITCH AND RECIEVER DRIER. RE-GASSED WITH 750GM R134A. TESTED OK.	484	0	0	62.5	546.5
43989	53329	12/08/2023	1HM368HB ID - TRUCK 184G	R	Electrical	1VT899	8089.0000	0	Supply UHF - LKW	REMOVED DASH, INSTALLED NEW UHF, REFIT ALL COMPONENTS & TESTED OPERATION - ALL OK AT TIME OF TESTING	327	396.9	0	40	763.9
43389	52402	11/28/2023	1HM368HB ID - TRUCK 184G	R	Electrical	1VT899	0.0000	0	REPLACE STOLEN BATTERIES, SUPPLY SPARES	JOB CARRIED OUT - REPLACED STOLEN BATTERIES AND PUMPED UP FLAT TYRES.	528	367.76	0	80	975.76
40574	48137	10/02/2023	1HM368HB ID - TRUCK 186G	R	Tyres	1VT899	0.0000	419895	PUNCTURE REPAIR (1) - RUBAND	PUNCTURE REPAIR (1) - RUBAND	0	65	0	0	65
35240	40251	06/21/2023	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	8089.0000	419304	S1 B SERVICE	CARRY OUT SERVICE AND VEHICLE INSPECTION. CHECK ALL LIGHTS, CHECK FLUID LEVELS. CHECK SUSPENSION, BRAKES AND TYRES	449.46	428.45	0	20	897.91
30591	35707	04/06/2023	1HM368HB ID - TRUCK 186G	R	Electrical	1VT899	0.0000	416117	Replace batteries	TESTED BATTERIES, FOUND OUTPUT OF 9v, & BATTERY HEALTH AT 40%. REMOVED & REPLACED BATTERIES AS REQUIRED & RETESTED - ALL OK AT TIME OF TESTING	250.21	130	0	0	380.21

27710	32973	02/27/2023	1HM368HB ID - TRUCK 184G	R	Hydraulic	1VT899	0.0000	0	HYDRAULIC PUMP TEST	REMOVE PUMP FROM AGITTOR AND WASH FOR TESTING	171.26	0	0	90	261.26
24669	38731	01/12/2023	1HM368HB ID - TRUCK 186G	INT-R	Chassis	1VT899	0.0000	0	FAULT LIST	BEACON LIGHT ON ROOF ISNT FLASHING	608.93	248.07	0	30	887
HYDRULIC PUMP/ENGINE NOT TURNING THE BOWEL SMOOTHLY, WORSE WHEL WASHING OUT OR A SMALL LOAD OF CONCRETE ON BOARD.															
23904	28457	12/14/2022	1HM368HB ID - TRUCK 186G	R	Tyres	1VT899	0.0000	4124724	PIRELLI FR01 X2 + BAL X2 + DIS x2		0	1250	0	0	1250
23195	27535	11/29/2022	1HM368HB ID - TRUCK 187G	R	Hydraulic	1VT899	7457.0000	0	replace leaking hyd fitting	ARRANGE SUBLET TO PIRTEK	0	316.69	0	5	321.69
22900	26950	11/22/2022	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	7457.0000	412783	S1 B SERVICE	COMPLETE B SERVICE	394.35	97.46	0	15	506.81
SPRING PIN BUSHES BADLY WORN															
KING OINS 3-4MM															
TRUNION BUSHES 2MM PLUG															
ENGINE MOUNTS SPLITING RHF															
ADJUSTED FAN BELTS															
CLUTCH HAD 20MM FREE TRAVEL AT ALVE, ADJUSTED ACCORDINGLY															
22076	26138	11/04/2022	1HM368HB ID - TRUCK 186G	INT-A	Bodywork	1VT899	0.0000	0	replace damaged mudguard	REPLACED DAMAGED MUD GUARD AND BRACKETS AS REQUIRED	147.77	128.82	0	10	286.59
21714	25205	10/27/2022	1HM368HB ID - TRUCK 184G	R	Brake	1VT899	7281.0000	0	INSPECT AIR LOSS ISSUE	INSPECT AIR LOSS ISSUE, REMOVE AND REPLACE RIGHT REAR BRAKE	214.08	62.73	0	90	366.81
BOOSTER															
TRAVEL KINGSTON AND RETURN															
20164	25046	09/21/2022	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	7091.0000	407804	S1 B SERVICE	LF777 LF3328	733	375.19	0	40	1148.19
FF5363 FF5085															
COMPLETE B SERVICE															
ADJUST BRAKES															
ADJUST CLUTCH															
REPAIR TAIL LIGHT															
18948	33017	08/29/2022	1HM368HB ID - TRUCK 121G	R	Bodywork	1VT899	6770.0000	0	SEAT REPAIRS	REFITTED SEAT CHOCK ABSORBER AND REPLACED MISSING	0	39.85	0	0	39.85
HYDRAULIC TANK BREATHER.															
17182	20204	07/20/2022	1HM368HB ID - TRUCK 186G	INT-R	Clutch	1VT899	0.0000	404000	Replace clutch	REPLACED FAULTY CLUTCH	2348.92	1866.15	0	100	4315.07
REMOVED GEARBOX AND DRIVESHAFT															
REMOVED CLUTCH AND FLY WHEEL, FOUND FLY WHEEL TO BE															
CRACKED AND U/S															
COLLECTED NEW FLY WHEEL AND CLUTCH KIT FROM ABS															
CLEANED UP GEARBOX															
FITTED NEW CLUTCH AND FLY WHEEL															
RE-FITTED GEARBOX AND DRIVE SHAFT															
17135	21201	07/19/2022	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	6770.0000	404325	S1 B SERVICE	TEST DROVE OK					
B SERVICE											354.6	202.95	0	20	577.55
REPLACED LHS INDICATOR GLOBE															
NOTES:															
REAR MAIN LEAKING															
SMALL LEAK FROM SUMP															
HYDRAULIC PUMP WEAPING															
SPRING BUSHES HAVE SMALL MOVEMENT															
CLUTCH NEEDS TO BE REPLACED - NO ADJUSTMENT LEFT															
16808	19323	07/12/2022	1HM368HB ID - TRUCK 186G	INT-R	Electrical	1VT899	0.0000	404000	ELECTRICAL REPAIRS	CHECKED PENDANT NOT WORKING IN RPM.	248.31	0	0	10	258.31
TESTED PENDANT AND FOUND PENDANT FAULTY, FITTED SPARE UNIT.															
TESTED OK.															
CHECKED BLOWING ACCESORY FUSE, ISOLATED VOLATGE REDUCERS,															
DIDNT FIX FAULT.															
FOUND HOUR METER WIRING WIRED TO ACCESORIES AND DEAD															
SHORTED.															
REPAIRED HOUR METER WIRING.															
RE-FITTED REDUCERS AND INTERIOR.															
TESTED OK.															
SEAN WINTER X3 HOURS															

16675	21603	07/11/2022	1HM368HB ID - TRUCK 184G	R	Hydraulic	1VT899	0.0000	0	REPLACE BLOWN CHUTE HOSE	REMOVE AND REPLACE BLOWN CHUTE HOSE	171.26	11.48	0	40	222.74
15120	18039	06/02/2022	1HM368HB ID - TRUCK 186G	INT-R	Electrical	1VT899	6447.0000	400316	REPAIR FLASHING LIGHT	INSPECT FLASHING LIGHT NOT WORKING REPLACED FAULT GLOBE TEST ALL OK	123.11	6.71	0	0	129.82
14819	17776	05/27/2022	1HM368HB ID - TRUCK 186G	INT-R	Service Trai	1VT899	6447.0000	400316	S1 B SERVICE	COMPLETE B SERVICE REPLACE GLOBE IN ROTATING BEACON ADJUST CLUTCH	117.75	218.39	0	15	351.14
14601	16766	05/24/2022	1HM368HB ID - TRUCK 186G	R	Bodywork	1VT899	6144.0000	0	SEAT REPAIRS	REMOVE SEAT BASE FOR PAUL TO REPAIR AND REFIT. NO LABOUR CHARGE TO REMOVE AND REPLACE.	0	0	180	0	180
14432	16712	05/19/2022	1HM368HB ID - TRUCK 186G	INT-R	Electrical	1VT899	0.0000	400066	Repair light faults	DIAGNOSE U/S INDICATORS FOUND INDICATOR SWITCH TO BE FAULTY REPLACE SWITCH AND TEST	608.08	300.64	0	30	938.72
										CHECK OPERATION OF BOTH FRONT AND REAR CONTROLS. FOUND DAMAGED FRONT CONTROL RELAY GIVING INTERMITANT OPERATION OF FORWARD CONTROLS. REPLACED RELAY AS REQUIRED AND TEST					
										REPAIR DAMAGED TAILLIGHT WIRING. FIR NEW LOAD RESISTORS TO CIRCUIT					
12598	14870	04/04/2022	1HM368HB ID - TRUCK 182G	INT-R	Sundries	1VT899	0.0000	0	REPAIR & MODIFY CHUTES	REPAIR & MODIFY CHUTES AS REQUIRED, CHUTES REQUIRED TO BE TEST FITTED TO MAKE SURE THEY FIT CORRECTLY	231.02	0	0	20	251.02
12230	14372	03/28/2022	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	6144.0000	396931	S1 C SERVICE	ENGINE OIL FILTER: LF777 & LF3328	492.44	294.61	0	25	812.05
										FUEL FILTER: FF5363 & FF5085					
										AIR OUTER : AF1862M					
										AIR INNER : AF1863M					
										BOWL HYDRALIC : HF6177					
										COMPLETE C TYPE SERICE					
										NOTE: CLUTCH WORN AND WILL REQUIRE REPLACEMENT SOON					
7422	8430	11/29/2021	1HM368HB ID - TRUCK 186G	S	Service Trai	1VT899	5742.0000	390915	S1 A SERVICE	CARRIED OUT A TYPE SERVICE AS PER SERVICE SHEET	304.05	87.56	0	15	406.61
										NOTE: ROTATOR LIGHT ON BUT NOT ROTATING					
5776	6918	10/15/2021	1HM368HB ID - TRUCK 186G	INT-R	Electrical	1VT899	5419.0000	384500	ELECTRICAL REPAIRS	REAR SPRING PIN BUSHES WORN Fitted new UHF antenna, removed interior, mounted to roof and sealed up. Replaced UHF handpiece. Fitted new actuator for RPM. Tested ok.	266.04	591.77	0	15	872.81
5109	6090	09/29/2021	1HM368HB ID - TRUCK 186G	INT-S	Service Trai	1VT899	5302.0000	386203	S1 B SERVICE	300 HOUR SERVICE REPLACE RH PARK LIGHT GLOBE REPAIRE LH TAILLIGHT REPAIR UHF ANTENNA	380.06	460.06	0	19	859.12
4466	6316	09/14/2021	1HM368HB ID - TRUCK 186G	INT-R	Clutch	1VT899	0.0000	385297	Check and Adjust Clutch	ADJUSTED CLUTCH	152.03	34.62	0	8	194.65
										FREETRAVEL CLUTCH ROD ALMOST OUT OF ADJUSTMENT, CLUTCH WILL NEED REPLACING SOON					
4268	3999	09/08/2021	1HM368HB ID - TRUCK 186G	INT-R	Brake	1VT899	5175.0000	384940	REPAIR AIR LEAKES	REPLACED BROKEN RH MIRROR BRACKET FIND AIR LEAK IN CHASSIS CUT AND REPAIR , REPAIR AIR LEAK AT TRANSMISSION	58.5	0	0	0	58.5

3965	6108	09/01/2021	1HM368HB ID - TRUCK 186G	INT-R	Electrical	1VT899	0.0000	0	ELECTRICAL REPAIRS	FIT PENDANT CONTROL BASE AT REAR OF VEHICLE TEST OPERATION REMOVE DAMAGED TAIL LIGHT WIRING AND REINSTALL NEW LOOM FIT NEW TAILLIGHTS WITH LOAD RESISTORS INSTALL 2 WORK LAMPS AND RUN SWITCH TO CAB FIT THROTTLE POSITION SENSOR AND ADJUST SPEED TEST OPERATION OF INSIDE AND OUTSIDE CONTROLS CHECK RPM AND BOWL SPEED TO MANUFACTURE SPECS, ADJUST BOWL SPEED TO 18RPM IN BOTH MIX AND DISCHARGE	1482.2	729.25	0	50	2261.45
3242	5046	08/16/2021	1HM368HB ID - TRUCK 182G	R	Chassis	1VT899	0.0000	0	REPAIR CRACKS IN CHASSIS		427.01	0	0	0	427.01
2865	2605	08/05/2021	1HM368HB ID - TRUCK 186G	R	Suspension	1VT899	5138.0000	384612	TORQUE ROD REPAIRS	REMOVED ALL REAR TORQUE RODS AND PRESSED OUT WORN BUSHES. FITTED NEW BUSHES AND REFITTED THE RODS. CHECKED TRUNION BUSHES. OK.	722.1	362.4	0	0	1084.5
2647	4205	07/30/2021	1HM368HB ID - TRUCK 181G	R	Bodywork	1VT899	0.0000	384610	STRIP DOWN TRUCK,PREPARE AND PAINT CHASSIS AS PER QUOTE	REMOVE CRADLE AND FITTINGS FROM TRUCK NEEDLE GUN AND SANDBLAST CHASSIS TO REMOVE CONCRETE AND RUST PAINT CHASSIS BLACK PAINT AREAS ON CRADLE FIT BACK UP ONCE PAINTED (SECOND HAND BOWL TO BE FITTED) Checked operation of bowl controls prior to teardown. Found wiring to pump, batteries and fan box U/S Fitted and wired in new fan control box, through relay and switch. Re-wired battery feed and fitted fuse holder. Fitted new DIN plug to pause valve. Replaced throttle control sensor Replaced pendant plug. Re-fitted tail lights and rear lights. Tested ok.	8551.19	1538.38	1000	240	11329.57
1955	9849	07/14/2021	1HM368HB ID - TRUCK 182G	R	Sundries	1VT899	0.0000	0	CHANGE BOWL OVER		1786.38	4.33	0	0	1790.71
210526-00	SVC00265	06/08/2021	1H0368 IC-TRUCK F 192_INT	R	Brake	1VT899			BRAKE NOT RELEASING	BRAKE NOT RELEASING OPERATOR HAD CALLED WHERE A TRUCK WAS STUCK AND NOT RELEASEING PARK BRAKE. ATTENDED SITE AT RAEBURN, STATED UP TRUCK & BUILT UP PRESSURE. THERE WAS NO AIR COMING FROM THE RELEASE STICK IN THE CAB ITSELF HAD FOLLOWED THE LINES FROM THE CAB TO THE AIR TANKS BY-PASSED THE BRAKING SYSTEM TO MORE TRUCK FOR FURTHER INSPECTIONS UNDONE A HOSE AT THE BOOSTER / ALSO AIR PRESSURE TRACED BACK TO THE CIRCUIT PROTECTION VALVE. ALSO FOUND LEAK COMING FROM THE PRESSURE RELEASE SWITCHES REPLACED BOTH CIRCUIT PROTECTOR & 3 X PRESSURE SWITCHES.	622.18	1192.76	0	110	1924.94
154	1003	06/02/2021	1HM368HB ID - TRUCK 192G	S	Service Trailer	1VT899	0.0000	0	1vt899 SERVICE		669.34	196.95	0	33.47	899.76
210216-00	SVC00259	02/26/2021	1H0368 IC-TRUCK F 192_INT	S	Service	1VT899			S1B SERVICE	CARRY OUT S1 B SERVICE	289.61	307.31	0	10	606.92
210218-00	SVC00260	02/26/2021	1H0368 IC-TRUCK F 192_INT	R	Brake	1VT899			SLACK ADJUSTER	REMOVE AND REPLACE U/S EXHAUST CLAMP BOLT, REMOVE AND REPLACE SLACK ADJUSTER DUE TO BROKEN RELEASE PIN, ADJUST BRAKES, REPLACE CLEARANCE LIGHTS, TEST ALL FUNCTIONS, ALL OK.	306.65	194.98	0	10	511.63

201001-00	SVC00253	10/23/2020	1H0368	IC-TRUCK F 192_INT	S	Service	1VT899	372,680 KM	S1B SERVICE	CARRIED OUT S1B SERVICE AS PER SCHEDULE. TIGHTENED RHF WHEEL BEARINGAND TOP UP OIL. CHECK AND ADJUST CLUTCH AS REQUIRED. REPAIRED WIRING ON ALT. REMOVED JACK SHAFT AND REPLACED WORN UNI JOINTS. REFIT AND GREASE. TIGHTENED LOOSE BOLT ON PTO GUARD.	410.83	282.21	0	20	713.04
201002-00	SVC00253	10/23/2020	1H0368	IC-TRUCK F 192_INT	R	Engine	1VT899	372,680 KM	REPAIRS	REMOVED SUMP AND CLEAN OUT DUE TO BADLY LEAKING SUMP. REMOVED OLD GASKET CLEAN BLOCK AND SUMP. MARK AND CUT OUT NEW GASKET. PUNCHED BOLTS HOLES IN. REFIT SUMP WITH NEW GASKET AND SEALANT AND TIGHTEN ALL BOLTS., FILL ENGINE WITH OIL. CHECK OK. REPAIRED WIRING TO ALT.	1252.2	701.79	0	30	1983.99
200716-00	SVC00249	07/31/2020	1H0368	IC-TRUCK F 187_INT	R	Clutch	1VT899	368,575km	ADJUST CLUTCH	ADJUST CLUTCH	130.05	0	0	81.51	211.56
200622-00	SVC00247	06/30/2020	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	4026hr/367	S1B SERVICE	TEST UNIT - MONITOR CLUTCH S1 B SERVICE - COACH AND TRUCK	218.1	254.22	0	10.91	483.23
200519-00	SVC00246	05/22/2020	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899		DRIVER SIDE WINDOW REPAIR	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. WASH AND CLEAN ENGINE BAY TIGHTENED LOOSE BELTS GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTERS. CARRY OUT OIL SAMPLING(1) CHANGE AIR FILTERS. CHANGE FUEL FILTERS. CHECK ALL OTHER FLUID LEVELS. DRIVER SIDE WINDOW REPAIR JAMMING IN DOOR TUCK. REMOVED SKIN, FOUND BROKEN ACTUATOR ORDERED PARTS. REMOVED FAULTY PARTS, INSTALLED NEW ACTUATOR AND MOTOR. PUT NEW WINDOW TRACK RUBBER IN PLACE AND ALIGNED DOOR GLASS. REF: EQUIPMENT FAULT REPORT # 44947	126.45	509.79	0	6.33	642.57
200501-00	SVC00245	05/08/2020	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	38642hr	repair tail lights	REPAIR TAIL LIGHTS	154.7	0	0	7.74	162.44
200320-00	SVC00242	04/17/2020	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	3712hr	REPLACE MARKER PLATES & MUDFLA	DIAGNOSE FAULT WITH NO RIGHT HAND REAR TAIL LIGHT. FOUND CORRODED WIRES AT JOIN. CUT OUT SECTION OF WIRING FROM TAIL LIGHT ASSEMBLY TO CHASSIS LOOM AND REPLACED. REPLACE MARKER PLATES & MUDFLAP	270.31	216.51	0	13.52	500.34
200318-00	SVC00242	03/26/2020	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	361099KM	REPLACE 1ST DRIVE TYRES	SOURCED NEW REFLECTORS AND " DO NOT OVERTAKE" MARKERS REMOVE OLD ONES AND INSTALL. FIT NEW NUMBER PLATE LIGH AND FIT MUDFLAP. REPLACE 1ST DRIVE TYRES	0	1837.5	0	0	1837.5
200312-00	SVC00242	03/20/2020	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	361099KM	REPLACE WINDSCREEN	SUBLET - REPLACED 1ST DRIVE TYRES REPLACE WINDSCREEN - SUBLET	0	0	490	0	490

200219-00	SVC002411	03/06/2020	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	3707hr	S1A SERVICE	S1A SERVICE - UNIT # 899	218.43	433.92	0	10.93	663.28
										COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHECK ALL OTHER FLUID LEVELS. WINDSCREEN U/S					
200214-00	SVC002405	02/21/2020	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	359,738KM	CALL OUT BOOSTER		297.2	296.76	0	139.86	733.82
200123-00	SVC002396	02/17/2020	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	357658	REPAIR DASH VENT CONTROLS	REPAIR DASH VENT CONTROLS	698.6	78.39	0	34.93	811.92
										REMOVE PASSENGER SIDE LOWER DASH COMPONENTS. TEST WIRING AND ACTUATOR OUTPUT. ACTUATOR U/S, ORDER AND REPLACE @ DEVONPORT YARD ON 24/1/20					
191217-00	SVC002381	01/10/2020	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	3546HR/35	OIL PRESSURE FAULT	OIL PRESSURE FAULT	223	3	0	67.4	293.4
										TRACE FAULT WITH OIL PRESSURE LIGHT COMING ON - FOUND, RUBBED THROUGH WIRES. REPAIRED - ALL OK					
191118-00	SVC002362	12/13/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	3478hr	REPAIR ENGINE OIL LEAK	REPAIR ENGINE OIL LEAK.	290.8	344.13	0	14.54	649.47
										REMOVE AND REPLACE LEAKING OIL FILTER HOUSING PIPES & BANJO BOLTS.					
191204-00	SVC002373	12/13/2019	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	3478hr	ELECTRICAL FAULTS	ELECTRICAL FAULTS.	508.9	180.68	0	25.45	715.03
										FIND ELECTRICAL FAULT. FIND BLOWN FUSE WHICH STOPPED THE POWER WINDOWS, HEATER AND THERMO FAN FROM WORKING. FIND EARTH FROM LEAD BATTERIES LOOSE/ARCING OUT. LOAD TEST BATTERIES AND FIND U/S. REPLACE BATTERIES AND MANUFACTURE NEW EARTH LEAD TO CHASSIS. FIND EARTH FOR THERMO FAN SET UP INCORRECTLY AND ARCING OUT. REPLACE EARTH WIRE. ALL OK.					
191112-00	SVC002361	11/25/2019	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	3375HR/35	S1B SERVICE	S1 B SERVICE	254.45	367.64	0	12.73	634.82
										COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTERS. CHANGE AIR FILTERS. CHANGE FUEL FILTERS. CHECK ALL OTHER FLUID LEVELS.					
191113-00	SVC002361	11/25/2019	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	3375HR/35	REPLACE DRIVE TYRES	REPLACE DRIVE TYRES.	72.7	1680	0	3.64	1756.34
										DROP TRUCK & TYRES OFF AT DOWLINGS FOR NEW DRIVE TYRES. POSITION 7/8/9/10 OF DRIVE.					
190930-00	SVC002337	10/21/2019	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	3196hr	GUARD REPAIR	GUARD REPAIR.	145.4	102.9	0	7.27	255.57
										FIT NEW MUD GUARD.STRAIGHTEN POLES AND SAND BACK.					
190826-00	SVC002317	09/09/2019	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	3055HR	DRIVER WINDOW FAULT	DRIVER WINDOW FAULT.	290.8	628.8	0	14.54	934.14
										REPLACE DRIVERS SIDE DOOR SKIN CLIPS AND SEAL TO FIX WINDOW FAULT.					
190822-00	SVC002316	08/30/2019	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	3053hr	S1A SERVICE	S1 A SERVICE	109.05	265.14	0	5.46	379.65
										COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTERS. CHANGE AIR FILTERS. CHECK ALL OTHER FLUID LEVELS.					

190815-00	SVC002115	08/28/2019	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	2995HR	REPAIR F/LIGHT	REPAIR F/LIGHT.	78.9	0	0	3.95	82.85
190718-00	SVC002297	07/26/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	2914hr	ENGINE OIL LEAK	CHECK ROTATING LIGHT. REMOVE COVER & REPAIR EARTH WIRE. REPLACE ORING ON ROTATOR MOTOR. TEST ALL GOOD. ENGINE OIL LEAK	181.75	21.52	0	9.09	212.36
190508-00	SVC002255	06/20/2019	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	345430km/	REPLACE W/ NUTS & REPAIRS	REMOVE FILTER AND FILTER HOUSING SHROUD. OIL PIPES AND REPLACE BANJO WASHERS. TEST DRIVE. ALL OK. REPLACE W/ NUTS & REPAIRS.	363.5	180	290	18.17	851.67
190605-00	SVC002273	06/20/2019	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	345430km/	S1B SERVICE	REPAIR FUEL GAUAGE. REPAIR WATER TANK STRAP. REPAIR CAGE OVER JACK AXLE FROM PUMP.ORGANISE FOR SEAT TO BE RECOVERED AT CAPE COUNTRY UPHOLSTERY. REPLACE W/NUTS. S1 B SERVICE	399.85	216.94	0	19.99	636.78
190506-00	SVC002245	05/21/2019	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	341,982km	BLOWN BRAKE BOOSTER	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTERS.CARRY OUT OIL SAMPLING(1) CHANGE FUEL FILTERS.CHECK ALL OTHER FLUID LEVELS. BLOWN BRAKE BOOSTER.	407.05	65	0	145.35	617.4
190225-01	SVC002211	05/08/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899		REPLACE BROKEN OIL DIP STICK	TRAVEL TO DEVONPORT BATCH PLANT TO RECTIFY AIR LEAK. FOUND RH FRONT DRIVE BRAKE BOOSTER BLOWN. REMOVE OLD BOOSTER. CLEANED AREA. FIT UP NEW BOOSTER. ADJUST AND TEST BRAKES. ALL OK. SUPPLY NEW ENGINE OIL LEVEL DIP STICK PARTS ONLY.	0	48.04	0	0	48.04
190225-01	SVC002255	05/08/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899		REPLACE BROKEN OIL DIP STICK	RE-OPENED TO PROCESS A RETURN PO AND RE-INVOICE TO CORRECT PARTS SUPPLIER	0	0.01	0	0	0.01

190329-00	SVC002231	04/30/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	2241hr/345	Engine Miss	ENGINE MISS	671.85	0	1045	146.09	1862.94
PICK UP TRUCK FROM DPT YARD AND BRING BACK TO BURNIE WORKSHOP. TEST PRESSURE RELIEF VALVES ON FUEL RAIL. REPLACED COPPER WASHERS ON FUEL FILTER HOUSING LINES. REMOVE AND INSPECT TURBO INTAKE AND VARIABLE VEINS ON EXHAUST SIDE. DROP TRUCK INTO WEBSTERS TO HAVE FAULT CODES CHECKED AND DIAGNOSED. WEBSTERS: CHECKED FOR FAULTS ON COMPUTER. FOUND SHOT/OPEN CIRCUIT ON ENGINE COOLANT SENSOR & ACCELERATOR PEDAL. CHECKED OVER WIRING ALL LOOKED TO BE OK. ORGANISED FOR AUTO ELECTRICIAN TO COME IN.WENT THROUGH WIRING DIAGRAMS AND WORKED OUR WAY BACK TO ENGINE ECU IN CAB. FOUND LOOSE TERMINALS IN PLUG. TIGHTEN TERMINALS & FAULTS WENT AWAY. CLEAR FAULTS ALL OK. TRUCK WENT BACK TO YARD. REPORTED EXHAUST BRAKE NOT WORKING. PLUG IN COMPUTER & CHECKED FOR FAULTS. FOUND AN ACCELERATOR PEDAL CALIBRATION FAULT. CARRY OUT CALIBRATION. TEST OPERATION OF EXHAUST BRAKE. ALL OK.															
190417-00	SVC002241	04/29/2019	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	2559HR/345	S1A SERVICE	S1 A SERVICE	218.1	311.79	0	10.91	540.8
COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS.CHANGE ENGINE OIL AND FILTERS. CHANGE HYD FILTER. CHANGE WATER FILTER. CHECK ALL OTHER FLUID LEVELS. TIGHTENED LOOSE BANJO FITTINGS ON OIL FILTER HOUSING. FITTED NEW CLEARANCE LIGHT AND RE-SECURED OTHERS.															
190408-00	SVC002231	04/17/2019	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	2245HR	LIGHT REPAIR	LIGHT REPAIR.	44.6	74.5	0	2.23	121.33
REPLACE HEAD LIGHT GLOBES X 2. TEST ALL OK.															
190320-00	SVC002221	04/12/2019	1H0368	IC-TRUCK F 187_INT	R	Steering	1VT899	2230hr	REPLACE BLOWN STEER HOSE	REPLACE BLOWN STEER HOSE.	330.55	50.3	159.55	154.07	694.47
TRAVEL TO LATROBE TO INVESTIGATE STEERING ISSUE. FOUND POWER STEERING HOSE NEEDS REPLACING. CALL OUT ENZED TO REPLACE. TOP UP RESERVOIR WITH OIL. TEST OPERATION. ALL OK.															
190410-00	SVC002241	04/10/2019	1H0368	IC-TRUCK F 183_INT	R	Tyres	1VT899		REPAIR PUNTURED TYRE	1VT899 ISUZU AGIGATOR	0	0	50	0	50
REPAIR PUNTURED TYRE. (RUBAND TYRES BURNIE)															

190212-00	SVC00220	03/20/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	2245HR	REPLACE PRESSURE SENDER	REPLACE PRESSURE SENDER.	566.65	696.08	0	153.33	1416.06
										TRAVEL TO DEVONPORT BATCH PLANT. DIAGNOSE LOW POWER FAULT. TEST DRIVE AND TAKE TRUCK TO WEBSTERS. CHECK FUEL RAIL PRESSURE RELIEF VALVE TO BE FAULTY. REMOVED AND REPLACED WITH NEW UNIT. REMOVED AND REPLACED SEAT BELT DUE TO OLD ONE BEING DAMAGED AND FRAYED.					
190221-00	SVC00220	02/28/2019	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	2245HR	CAB CONTROL FAULT	CAB CONTROL FAULT.	109.05	0	0	5.45	114.5
181218-00	SVC00217	02/22/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	2229HR	ENGINE FAULT	MANUFACTURE NEW HANDLE FOR CAB BOWL CONTROL LEVER. ENGINE FAULT:	1242.1	6173.48	700	112.5	8228.08
										TRAVEL TO DEVONPORT BATCH PLANT. CHECK TRUCK RUNNING ROUGH, POSSIBLE INJECTOR OR FUEL FAULT. REMOVE FILTERS & TAKE TO WORKSHOP TO CHECK FOR CONTAMINENTS. REMOVE INJECTORS FOR TESTING. FOUND ALL FAULTY AS PER ATTACHED TEST DATA FORM BURNIE FUEL INJECTION SERVICE. FOUND THAT METAL HAD GONE THROUGH THE SYSTEM. REMOVED FUEL PUMP FOR TEST. FOUND TO HAVE FAILED. REPLACED WITH SERVICE EXCHANGED UNIT AND INJECTORS. RE-ASSEMBLED UNIT. TESTED ALL OK.					
190207-00	SVC00220	02/21/2019	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	2189HR	REPAIR FUEL SYSTEM	REPAIR FUEL SYSTEM.	3475.8	15.54	0	50	3541.34
										TEST SYSTEM AND FOUND FAULTY PUMP & INJECTORS AS PER PREVIOUS JOB ENGINE POWER FAULT. REFIT INJECTORS, FUEL RAIL PIPEWORK AND INJECTOR PUMP & RESET TIMING. REPLACE FILTERS AND PRIME UP SYSTEM. TEST DRIVE TRUCK. READJUST TIMING. CHECK FOR LEAKS. ALL OK. WASH TRUCK.					
181023-00	SVC00214	11/09/2018	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	1948HR/33	S1B SERVICE	S1B SERVICE CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET REPAIRED MEMORY IN RADIO TO STORE REQUIRED CHANNELS TIDY UP AND SECURE WIRING FROM UNDER THE DAHSBOARD	399.85	162.36	0	20	582.21
180802-00	SVC00209	08/17/2018	1H0368	IC-TRUCK F 187_INT	R	Transmissio	1VT899	1593 HRS/	OIL LEAK GEARBOX	OIL LEAK GEARBOX.	633.45	2375.81	275	31.67	3315.93
										REMOVE TAIL SHAFT & AIR LINES. PLACE BOX ON JACK & UNDO BELL HOUSING BOLTS. REMOVE GEARBOX. REMOVE CLUTCH & FLY WHEEL. GET WEBSTER TO DO REAR MAIN. FIT GENUINE FLY WHEEL & NEW CLUTCH. RE-FIT BOX, TAILSHAFT, WIRING & AIR LINES.					
180802-00	SVC00209	08/14/2018	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	326481 KM	REPLACE WINDSCREEN	REPLACE WINDSCREEN.	72.7	37	445.45	3.64	558.79
										SUBLET WINDSCREEN REPAIR EAGLE WINDSCREENS. REPLACE WIPER BLADES.					

180802-00	SVC00209	08/14/2018	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	1593 HRS/	Repair driver side window	REPAIR DRIVER SIDE WINDOW.	330.25	643.98	0	16.51	990.74
180808-00	SVC00209	08/14/2018	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	1593 HRS/	S1 A SERVICE	REMOVE, REPAIR & RE-FIT DRIVERS SIDE MIRROR. REPLACE WINDSCREEN WIPER BLADES. REPLACE RH DOOR WINDOW MECHANISM. LUBE TRACKS. TEST ALL GOOD. S1 A SERVICE	236.7	149.79	0	11.84	398.33
180808-00	SVC00209	08/14/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	1593 HRS	LOW POWER FAULT	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTERS. CHECK ALL OTHER FLUID LEVELS. LOW POWER FAULT.	218.1	93.19	0	10.91	322.2
180315-00	SVC00201	07/31/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	11,086 HRS	REPLACE OIL SEAL LIVE DRIVE	FUEL ISSUE. CHECK FUEL SYSTEM OVER. FOUND FUEL SUPPLY LINE HAS RETRICTIONS. REMOVE FUEL LINE & REPLACE. TEST ALL GOOD. CLEAN UP ONCE JOB IS COMPLETED. REPLACE OIL SEAL LIVE DRIVE.	535.13	72.12	0	26.75	634
180315-00	SVC00209	07/31/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	11,086 HRS	REPLACE OIL SEAL LIVE DRIVE	REMOVE DRIVELINE GUARD, DRIVELINE AND OIL FEED LINE. REMOVE OLD BOLTS AND REMOVE HOUSING. FOUND O RING OLD AND BRITTLE. CLEAN HOUSING. REPLACE O RING. USE VOLVO GREY AND RE-SEAL. REINSTALL. LET DRY WHILE REPLACED L/H REAR ENGINE MOUNT. CHECK ALL OK.	0	-10	0	0	-10
180625-00	SVC00207	07/31/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	1476 HRS/	COOLANT FAULT	REPAIR COOLANT FAULT.	2159.05	4256.88	0	162.5	6578.43
										TRAVEL TO DEVONPORT TO INVESTIGATE OVER HEATING. TOPPED UP COOLANT TO GET TO YARD. COOLANT LEAKING FROM ENG BREATHER. SPOKE TO DAMIAN AND DECIDED TO FLOAT TRUCK TO BURNIE WORKSHOP. TESTED RADIATOR CAP. ALL GOOD. PRESSURE TESTED SYSTEM ALL GOOD. FOUND COOLANT IN AIR DRIER EXHAUST. REMOVED COMPRESSOR LINE AND FOUND FULL OF COOLANT. REMOVED CAB REAR SUPPORT. GUARDS & AIR CLEANER. MARK & REMOVE ALL FUEL LINES & COMPRESSOR LINES. DRAIN COOLANT. REMOVE ROCKER COVER. TIME ENGINE TO TDC. DIFFICULT AS NOT TIMING MARK ON FLY WHEEL. REMOVE FUEL PUMP & AIR COMPRESSOR. FIT NEW AIR COMPRESSOR WITH GEAR FROM OLD ONE. INSTALL & TIME AIR COMPRESSOR. INSTALL & TIME FUEL PUMP. REFIT ROCKER COVER & NEW GASKET. INSTALL COOLANT, FUEL & AIR LINES WITH NEW WASHERS ON BANJO BOLTS. BLEED FUEL SYSTEM. RE-FIT CAB SUPPORT, AIR CLEANER & LH GUARD. REMOVE UPPER RED HOSE & THERMOSTAT HOUSING & CLEAN UP SEALING SURFACES. FIT NEW LOWER O RING & BLOCK GASKET. RE- FIT HOUSING TO BLOCK & TENSION UP. REFIT THERMOSTAT WITH NEW GASKET & DO UP. RE-FIT HOSE. FILL & BLEED COOLING SYSTEM. START & RUN ENGINE. ALL GOOD. CHECK OVER AIR, FUEL & COOLING SYSTEM. ALL GOOD. RE-FIT RH GUARD & HEADER TANK.					

180614-00	SVC002061	06/28/2018	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	324158 KM	REPAIR TANK STRAP RUBBERS	REPAIR TANK STRAP RUBBERS.	333.35	73.74	0	16.67	423.76
180613-00	SVC002061	06/21/2018	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	1439 HRS/€	S1 B SERVICE	REMOVE FUEL TANK. CLEAN STRAPS & BRACKETS UP. RE-PAINT AND INSTALL NEW RUBBERS. REFIT TANK. REPLACE DASH CLUSTER ILLUMINATION GLOBES. FIT NEW LOW PRESSURE WARNING SWITCH. S1 B SERVICE	366.6	156.24	0	18.33	541.17
180518-00	SVC002051	05/29/2018	1H0368	IC-TRUCK F 187_INT	S	Engine	1VT899	N/A	SUPPLY TOP UP OIL	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE FUEL FILTERS (2). CHECK ALL OTHER FLUID LEVELS. SUPPLY TOP UP OIL - PARTS ONLY	0	52.38	0	0	52.38
180509-00	SVC002041	05/10/2018	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899		REPAIR REAR GUARDS	CHARGE 2X 5LT 136094. DELVAC MX EXP 15W40 5 LITRE PACK	0	0	0	0	0
180403-00	SVC002021	04/13/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	1127 HRS/€	STARTING FAULT	STARTING FAULT	0	0	345	0	345
180326-00	SVC002021	04/06/2018	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	1127 HRS/€	REPAIR LIGHTS	TRUCK TAKES A LONG TIME TO START AND STOP. WEBSTERS TESTED CRANK ANGLE AND CAM POSITION. NOT IN CIRCUITS, NOT IN THESE SYSTEMS. TESTED FUEL SHUT OFF AND INJECTOR CUT OUT. NO FAULTS PRESENT AT ALL. WEBSTERS SUGGESTED PULLING PUMP AND INJECTORS FOR TEST. SENT BACK TO WORK AS IS. SUBLET ONLY REPAIR LIGHTS.	361.26	87.46	0	18.06	466.78
180315-00	SVC002011	03/23/2018	1H0368	IC-TRUCK F 187_INT	R	Suspensior	1VT899	11,085 HR€	repair rear suspension	RE-ATTACH PARK LIGHTS TO MUDGUARD. LHS BROKEN. PICK UP NEW ASSMEBLY FROM A/E AND FIT. REPLACED DAMANGED NUMBER PLATE LIGHT. REPAIR REAR SUSPENSION.	3327.84	885.49	0	50	4263.33
180313-01	SVC002011	03/22/2018	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	11,048 HR€	S1 A SERVICE	REMOVE AND REPLACE ALL TORQUE ROD BUSHES. SOURCE NEW BOLTS AND NUTS FOR TORQUE RODS. REMOVE OLD SPRING WEAR PADS ON EACH AXLE. FABRICATE NEW WEAR PADS AND INSTALL. ALIGN AXLES. REPLACE U BOLTS AND TORQUE. FIT WHEELS AND MUD GUARDS. REPLACE (8) MUD GUARD BRACKETS. S1 A SERVICE.	281.23	261.58	0	14.07	556.88
180315-00	SVC002011	03/22/2018	1H0368	IC-TRUCK F 187_INT	R	Suspensior	1VT899	11,048hr	REPAIR FRONT SUSPENSION	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CARRY OUT OIL SAMPLING (1). CHECK ALL OTHER FLUID LEVELS. REPAIR FRONT SUSPENSION.	521.75	11.26	0	26.08	559.09
										REMOVE OLD SHACKLE PINS AND BUSHES. CLEAN SURROUNDING AREA. FIT NEW BUSHES AND PINS. GREASE. PARTS CHARGED ON PREVIOUS JOB.					

180301-00	SVC00201	03/15/2018	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	11,046 HRS	REPAIR BOOSTER	REPAIR BOOSTER.	80.35	52.61	0	4.02	136.98
171208-00	SVC00197	02/26/2018	1H0368	IC-TRUCK F 187_INT	R	Suspensor	1VT899	N/A	REAR SUSPENSION REPAIR	REMOVE OLD R/REAR DRIVE BRAKE BOOSTER AND PLUMBING. FIT UP NEW BRAKE BOOSTER AND TEST. ALL OK. REAR SUSPENSION REPAIR.	0	1336.3	0	0	1336.3
171208-00	SVC00197	02/26/2018	1H0368	IC-TRUCK F 187_INT	R	Suspensor	1VT899	N/A	FRONT SUSPENSION REPAIR	PARTS ONLY STILL WAITING ON TRUCK. FRONT SUSPENSION REPAIR.	0	556	0	0	556
171208-00	SVC00197	02/26/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	N/A	ENG MOUNT OIL LEAK	PARTS ONLY STILL WAITING ON TRUCK. ENG MOUNT OIL LEAK.	0	276.43	0	0	276.43
170913-00	SVC00192	01/04/2018	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	311961 KM	ENGINE FAULT	PARTS ONLY. STILL WAITING ON TRUCK TO BECOME AVAILABLE. ENGINE FAULT.	496.36	130.2	1025.49	24.82	1676.87
171129-00	SVC00196	12/12/2017	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	10,704 HRS	S1 A SERVICE	INSPECT FUEL SYSTEMS FOR ISSUES. REMOVE ALL BANJO'S AND CHECK ON PRIMING. HAND PRIMER U/S. REMOVE & SOURCE NEW ITEM. FIT & TEST, ALL GOOD. TEST DROVE & ENGINE LIGHT CAME ON. GO TO WEBSTER'S TO GET FAULT CHECKED. TEMP SENSOR & ACC SENSOR. CHECKED WIRING AND FOUND FAULTY ACC SENSOR. PARTS ON ORDER.	285.4	316.08	0	14.27	615.75
170724-00	SVC00189	08/11/2017	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	10,210 HRS	S1 B SERVICE	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. CHANGE ENGINE OIL/FILTERS. CHECK ALL OTHER FLUID LEVELS. GREASE ALL LUBRICATION POINTS. REPAIRED AIR LEAK IN AIR LINE TO WATER TANK. LOOKED AND LOW POWER AND RUN ON ISSUE. RUN ON IS A COMPUTER ISSUE. LOW POWER WAS FINE ON TEST DRIVE. S1 B SERVICE	226.78	257.82	0	11.34	495.94
170713-00	SVC00189	07/20/2017	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	302,801km	CHECK ENGINE FAULT	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENG/OIL FILTER. CHANGE FUEL & AIR FILTERS. CHECK ALL OTHER FLUID LEVELS. GOOD VISUAL CHECK OVER UNIT. TEST ALL OK. CHECK ENGINE FAULT.	450.56	3.54	0	97.53	551.63
										TEST ENGINE PERFORMANCE AFTER DRIVER COMPLAINED OF LOW POWER. CHECKED OVER TRUCK AND INSPECTED TIMING, TURBO AND PLUMBING. REMOVED ROCKER COVER AND CARRIED OUT OVERHEAD TUNE. INSPECTED AND ADJUSTED VALVES. REFITTED ROCKER COVER. MECHANICALLY ALL COMPONENTS ARE FINE BUT FAULT IS STILL PRESENT. UNIT WILL HAVE TO GO TO ISUZU FOR COMPUTER CHECKS.					

170713-00	SVC001892	07/20/2017	1H0368	IC-TRUCK F 187_INT	R	Air Con	1VT899	10,174HR/	REPLACE MISSING A/C TENSIONER	REPLACE MISSING A/C TENSIONER PULLEY & BELT.	160.7	43.98	0	83.04	287.72
170529-00	SVC001867	05/31/2017	1H0368	IC-TRUCK F 187_INT	R	Exhaust	1VT899	9999 HRS	EXHAUST REPAIRS	TRAVEL TO DEVONPORT. INSPECT MISSING A/C PULLY. SOURCED NEW PULLY AND V BELT. FITTED TO UNIT. ADJUST UP & TEST. ALL OK. EXHAUST REPAIRS.	80.35	0	0	66.52	146.87
170511-00	SVC001866	05/17/2017	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	N/A	SUPPLY MUDGUARD BRACKETS	CARRY OUT REPAIRS TO EXHAUST AT MUFFLER. REPAIR FLANGE. REPAIR BRACKET AND FIT NEW BOLTS AND NUTS. SUPPLY MUDGUARD BRACKETS PARTS ONLY	0	164	0	0	164
170314-00	SVC001836	04/28/2017	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	9022 HRS	Engine Miss	ENGINE MISS.	6075	9860.03	620.09	50	16605.12
170419-00	SVC001845	04/28/2017	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	9022 HRS	REPLACE TURBOCHARGER	CARRY OUT INSPECTION OF MISS FIRE IN ENGINE AT DEVONPORT CONCRETE. PICK UP TRUCK AND BRING TO WORKSHOP AND FOUND NOT FIRING ON NUMBER 3 INJECTOR. REMOVED ALL INJECTORS.UNABLE TO REMOVE NUMBER 4 AS IT WAS SIEZED IN HEAD. CYLINDER HEAD WAS THEN REMOVED AND IT WAS FOUND THAT SOMETHING HAD DAMAGED NUMBER 5&6 PISTONS. WASTE GATE FROM TURBO HAD FALLEN APART AND CAUSED ALL DAMAGE. ALL PISTONS WERE THEN REMOVED AS DAMAGE WAS FOUND ON ALL 6. NUMBERS 5&6 LINERS WERE THEN REMOVED AND REPLACED. NEW PISTONS AND RINGS AND BIG END BEARINGS WERE ALSO REPLACED. NEW VALVES WERE FITTED TO HEAD AFTER INSPECTION FOUND THAT NUMBER 6 WAS BENT. HEAD WAS SENT TO HOBART AND REBUILT. CYLINDER HEAD REFITTED WITH. 010 SHIM ASSY TUNE UP CARRIED OUT AND RETURNED TO WORK.	425.82	3898.73	0	21.29	4345.84
170302-00	SVC001825	03/23/2017	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	9769 HRS	S1 A SERVICE	S1 A SERVICE	133.88	161.78	0	6.69	302.35
170216-00	SVC001816	02/23/2017	1H0368	IC-TRUCK F 187_INT	R	Transmissio	1VT899	9612 HRS	REPLACE GEAR CABLE	COMPLETE SERVICE AND SAFETY CHECK AS PER REQUIRED SCHEDULE. REPLACE GEAR CABLE.	566.23	167.67	0	278.31	1012.21
161215-00	SVC001792	01/24/2017	1H0368	IC-TRUCK F 187_INT	PW	Clutch	1VT899	9481 HRS	POLICY REPLACE THROW OUT BEARI	TRAVEL TO SHERAWATER PLANT TO CHECK LOOSE GEARS. MANUALLY GET INTO GEAR AND UNLOAD. ORGANISE PARTS FROM SUPPLIERS. TRAVEL TO SITE AGAIN AND REMOVED BROKEN GEAR STICK CABLE. FITTED NEW CABLE AND ADJUSTED TO SUIT. TEST OK. POLICY WORK	559.6	43.81	0	0	603.41
										REPLACE THROW OUT BEARING AFTER FITTING NEW CLUTCH. DUE TO BEARING BEING INSTALLED INCORRECTLY. BEARING WAS FITTED AROUND THE WRONG WAY. WHEN THE CLUTCH WAS DEPRESSED WITH THE ENGINE RUNNING THE FINGERS ON THE PRESSURE PLATE CAUGHT IN THE BEARING WHICH STOPPED THE BEARING FROM TURNING. CLUTCH REPLACED BY BURNIE W/SHOP.					

161221-00	SVC001796	01/10/2017	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	9483 HRS	ADJUST BOWL CONTROL	ADJUST BOWL CONTROL	200.88	0	0	72.54	273.42
161206-00	SVC001786	12/21/2016	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	9481 HRS	Rectify Oil Leak	TRAVEL TO DEVONPORT & CARRY OUT ADJUSTMENT OF CABLE CONTROLS FOR BOWL OPERATIONS. RECTIFY OIL LEAK.	1942.73	1333.18	206	50	3531.91
161109-00	SVC001776	11/25/2016	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	9352 HRS	S1 B SERVICE	S1 B SERVICE	314.78	477.94	25.38	15.74	833.84
161017-00	SVC001756	10/21/2016	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	9235 hrs	BRAKE INSPECTION	BRAKE INSPECTION	86.1	0	0	31.25	117.35
161013-00	SVC001756	10/19/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	9229 HRS	Bowl control repair	CARRY OUT BRAKE INSPECTION ON SITE AT DEVONPORT CONCRETE PLANT BOWL CONTROL REPAIR	243.93	0	0	50	293.93
160829-00	SVC001736	09/06/2016	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	9056 hrs 2	S1 B SERVICE	S1 B SERVICE.	238.88	186.55	0	17	442.43
160831-00	SVC001736	09/06/2016	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899		REPLACE CIRCUIT BREAKER	Completed service as per service sheet. REPLACE CIRCUIT BREAKER. REPLACED CORRODED CIRCUIT BREAKER IN THE BATTERY BOX AND REPAIRED SHORT.	68.25	0	0	0	68.25
160810-00	SVC001726	08/31/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	9003 hrs	REPLACE BOWL CONTROL	REPLACE BOWL CONTROL.	443.63	198.35	0	22.18	664.16
160818-00	SVC001726	08/30/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	280968 KM	REPLACE FUEL TANK STRAPS	CARRY OUT INSPECTION OF INTERNAL BOWL CONTROLS. SHIFT LEVER PLASTIC PIVOT FOUND TO BE BROKEN. NEW PARTS NOT AVAILABLE SO MODIFY AND FIT UPDATED LEVER ASSY.	68.25	0	156.1	3.41	227.76
160720-00	SVC001716	07/29/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	278630KM	Repair Seat	EQUIP ID 1VT899 280968 KMS REPAIR SEAT	0	0	220	0	220
160722-00	SVC001716	07/29/2016	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	279107 KM	REPLACE BOOST SENSOR	CARRY OUT REMOVAL AND REPLACEMENT OF BOOST SENSOR AND PRESSURE SWITCH	68.25	45.59	0	0	113.84
160725-00	SVC001716	07/27/2016	1H0368	IC-TRUCK F 184_INT	R	Exhaust	1VT899	277841 KLI	REPAIR LOOSE EXHAUST SYSTEM	CHECKED NOISE IN FRONT ENDS, ONLY THING FOUND WAS LOOSE EXHAUST, REPLACED MISSING NUTS ON EXHAUST AS REQUIRED, CHECKED OVER TRUCK, FOUND LIST OF ISSUES AND GAVE LIST TO CUSTOMER. COMPLTED BY CJD EQUIPMENT	0	0	100	0	100
160704-00	SVC001706	07/19/2016	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	278118 KM	Replace Engine Mount	REPLACE ENGINE MOUNT CARRY OUT REPLACEMENT OF LEFT HAND ENGINE MOUNT CARRY OUT CHECKS TO ENGINE AS CHECK ENGINE LIGHT ON	462	0	0	23	485
160615-00	SVC001696	06/30/2016	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	8868 hrs	S1 B SERVICE		225.75	164.69	0	15	405.44
160622-00	SVC001696	06/28/2016	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	277984KM	8 X ADVANCE 11R22.5 TYRES	8 X ADVANCE 11R22.5 GL663D DRIVE TYRES TYRERIGHT BURNIE	0	2763.6	0	0	2763.6

160616-00	SVC00169	06/23/2016	1H0368	IC-TRUCK F 184_INT	R	Engine	1VT899	277236 Klt	REPAIR POWER FAULT & BLACK SMO	TRAVELLED TO TRUCK BREAKDOWN. CHECKED TURBO AND AIR FILTERS. FOUND AIR FILTERS TO BE DIRTY. ORDERED NEW. ROAD TESTED TRUCK AND FOUND NO SMOKE PRESENT. WORK CARRIED OUT BY CJD EQUIP	0	0	517.48	0	517.48
160614-00	SVC00169	06/22/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	8868 hrs	REPLACE CAB MOUNTS	REPLACE CAB MOUNTS CARRY OUT REMOVAL AND REPLACEMENT OF CAB MOUNTS REMOVE AND REPLACE STEERING ROD ENDS AND SWAY BAR BUSHES REPLACE LEFT HAND ENGINE MOUNT	1341.38	948.7	0	50	2340.08
160614-00	SVC00169	06/22/2016	1H0368	IC-TRUCK F 187_INT	R	Suspensior	1VT899	8898 HRS	Replace torque rod bushes	REPLACE TORQUE ROD BUSHES	921.38	727.98	0	46	1695.36
160223-00	9786	05/17/2016	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899		REPLACE BOWL CONTROLS		0	0	0	0	0
160509-00	SVC00167	05/10/2016	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	267083 Klt	REPAIR HEATER FAN & REVERSE LI	ST LEONARDS AUTO ELECS CHECKED HEATER FAN, WIPERS AND REVERSE LAMPS ON VEHICLE, LOCATE, REPAIR AND SECURE DAMAGED GEARBOX WIRING AND RECHECK OPERATION, REPAIRED WIRING CONNECTIONS TO HYDRAULIC COOLING FAN AND CHECK OPERATION.	0	0	82	0	82
160226-00	SVC00164	02/27/2016	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	274326	REPLACE U/S COOLING FAN	CHECK COOLING FAN AND SUPPLY NEW REPLACEMENT UNIT, MODIFY WIRING CONNECTIONS TO SUIT CARRIED OUT BY ST LEONARD AUTO ELECTRICAL	0	0	180	0	180
160201-00	SVC00163	02/16/2016	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899	273,869 Klt	REPAIR REAR LIGHTS	CHECK OPERATION OF REAR LIGHTS, RIGHT HAND SIDE NOT WORKING, STRIP WIRING AND REPLACE, REPAIRED SEVERAL BROKEN WIRES, CEHCK ALL LIGHTS ALL GOOD	102.38	0	0	5	107.38
160129-00	SVC00162	02/05/2016	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	8630HRS 2	S1 B SERVICE		238.88	191.41	0	17	447.29
151214-00	SVC00160	12/14/2015	1H0368	IC-TRUCK F 121_INT	R	Tyres	1VT899	271895	PUNCTURE REPAIR RUBAND	PUNCTURE REPAIR RUBAND	0	40.91	0	0	40.91
151119-00	SVC00160	11/30/2015	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	8416 HRS 1	S1 B SERVICE SHEET	CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET. REPLACED DAMAGED REAR SIGNS.REPLACED BROKEN GREASE NIPPLES.	409.5	203.2	0	25.5	638.2
150826-00	SVC00155	11/17/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899		ENGINE VIBRATION	ENGINE VIBRATION. CHECKED ENGINE AND TRANSMISSION MOUNTS.TIGHTENED TRANS MOUNTING BOLT RHS. JACKED UP TO SEE IF THE MOUNTS WERE CRACKED IN THE RUBBER. CHECKED FLYWHEEL AND HARMONIC BALANCER. CHECKED WIRING FOR INJECTORS. UNABLE TO LOCATE SLIGHT VIBRATION. REPLACED LEAKING ELBOW FOR WATER SYSTEM.	375.38	5.74	0	18	399.12
150925-00	SVC00157	10/07/2015	1H0368	IC-TRUCK F 184_INT	R	Brake	1VT899	268188	REPLACE RH SR BRAKE BOOSTER	INSPECT UNIT FOR REPORTED AIR LEAK, DIG OUT BRAKE BOOSTER CAGE TOOL AND BLOCK OFF AIR LINE, UNDO SIEZED MOUNTING NUTS AND REMOVE SIEZED ADJUSTER PINS, CHISEL OFF MOUNTING BRACKET AND FIT NEW BRAKE BOOSTER, ADJUST BRAKES AS REQUIRED	354.38	47.66	0	17	419.04
150714-00	SVC00153	07/31/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	264323 KM	REPLACE L/HAND ENGINE MOUNT	REMOVE AND REPLACE LH ENGINE MOUNT AS REQUIRED	68.25	112.36	0	3.5	184.11
150713-00	SVC00153	07/16/2015	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	7999H 263	S1 B SERVICE	COMPLETED THE REQUIRED SRVICE AND SAFETY CHECKS AS PER SERVICE SCHEDULE REPAIRED THE FRONT SPRING PINS NOTE LH ENGINE MOUNT IS BROKEN, L&R CAB MOUNTS ARE WORN CLUTCH BEARING IS WORN COOLANT NEEDS TO BE REPLACED FUEL PRIMER IS LEAKING FUEL OIL IS LEAKING FROM LHS OF ENGINE FRONT SPRING NEED SHIMMING SWAY BAR BUSHES ARE U/S	273	180.67	0	18	471.67
150521-00	SVC00151	05/28/2015	1H0368	IC-TRUCK F 186_INT	R	Clutch	1VT899	7745 hrs	Replace Clutch Slave Cylinder	REPLACE CLUTCH SLAVE CYLINDER. REPLACED CLUTCH MASTER CYLINDER. REPLACED NUMBER PLATES.	238.88	100	0	12	350.88

150515-00	SVC001504	05/26/2015	1H0368	IC-TRUCK F 186_INT	R	Suspensior	1VT899	258900 KM	STEERING REPAIRS/WA	STEERING REPAIRS/WA. CHECKED THE STEERING AND FOUND THE TIE ROD BENT AFTER BEING TOWED FROM THE FRONT AXLE. LOOSENED THE TIE ROD AND PRESSED BACK IN SHAPE. CHECKED CAB MOUNTS AND FITTED RUBBER TO THE CAB ASSIST LEVERS TO STOP KNOCKING UNDER THE CAB.CHECKED THE REAR CAB MOUNTS. TIGHTENED LOOSE BOLTS HOLDING THE LIVE DRIVE COVER. PERFORMED STEER AXLE WHEEL ALIGNMENT.CHECKED AIR SUPPLY TO GB. ADJUSTED THE MASTER CYLINDER FREE TRAVEL.CHECKED CLUTCH DAMPER SPRINGS.GREASED THE THROUGH SHAFT AND THROW OUT BEARING.	409.51	6.85	0	20	436.36
150430-00	SVC001497	05/19/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	7690 HRS	DIAGNOSE AND REPAIR LOW POWER	DIAGNOSE AND REPAIR LOW POWER. FILL THE AGITATOR WITH 20MM AND TEST DROVE.FOUND DERATING ON HARD PULLS.TRAVELED BACK TO THE WORKSHOP,CHECKED WIRING,FUEL AND AIR FILTER.DELIVERED THE VEHICLE TO WEBSTERS FOR FAULT DOWN LOAD. ENGINE IS MISSING INTERMITTENTLY CHECK THE VEHICLE ON THE COMPUTER, FOUND THAT THERE WAS ALOT OF CODES, CHECK THE CODES AND DELETE THEM AS ABLE TO THEN CHECK, FOUND THAT THE MISS WAS COMING FROM THE INJECTOR HARNESS ON NO 6, CLIP MISSING, WILL NEED THE HARNESS TO BE REPLACED TO RECTIFY THE PROBLEM COMPLETELY, RUNG THE VEHICLE ON THE DYNO AND WAS UNABLE TO FAULT CARRIED OUT BY WEBSTER TRUCKS ENGINE MISS FIRE ATTENDED INTERMITTANT MISS IN MOTOR, ATTACHED ELECTRONIC DIAGNOSTIC SCAN TOOL TO VEHICLE, CHECKED FOR CODES, NO CODES FOUND, ROAD TESTED VEHICLE O SEE FAULT, DID NOT FAULT, VEHICLE DYNO TEST, 190 HP RW, UNABLE TO FAULT, CHECKED PUMP TIMING AND FOUND OUT BY 7 DEG, REALIGNED TIMING MARK ON PUMP, TESTED CRANK AND CAM SENSORS, FOUND CRANK SENSOR WORN AND FAULTY, DYNO TEST AGAIN, 210 HP RW, ROAD TESTED AND VEHICLE FAULTED AND STARTED MISSING, FITTED FUEL PRESSURE SENSOR, CHECKED OPERATION ALL OK. COMPLETED BY WEBSTER TRUCKS	238.88	0	1370.21	12	1621.09
150511-00	SVC001500	05/18/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	258718 KM	CHECK AND REPAIR COOLANT LEAK	PRESSURE TESTED THE COOLING SYSTEM AND FOUND LEAK BETWEEN THE THERMOSTAT HOUSING AND THE WATER PUM, DISASSEMBLED AND REPLACED GASKETS AND O RINGS, REASSEMBLED AND TOPPED UP COOLANT AND TEST DROVE ALL OK.	273.01	49.59	0	13.5	336.1
150424-00	SVC001493	05/07/2015	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899	258,081 Kl	REMOVE INJECTOR PLUGS,CHECK FO	LIFT THE CAB AND DISCONNECT PLUG FROM INJECTORS, TEST WIRING OK, CLEAN UP THE PLUGS AND INJECTORS WITH ANTI WATER/CORROSION SPRAY, CLEAN TERMINALS AND REFIT TO INJECTORS, START AND TEST OPERATION ALL GOOD.	238.88	0	0	12	250.88
150424-00	SVC001492	04/28/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	258081 KM	ADJUST VALVES,REPLACE ROCKER	ADJUST VALVES,REPLACE ROCKER. REMOVED THE ROCKER COVER AND ADJUSTED THE VALVES CLEARANCED, REPLACED LEAKING GASKET (PARTS EX STOCK) AND REFITTED THE ROCKER COVER.	152.25	0	0	7.5	159.75
150408-00	SVC001484	04/13/2015	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	256922 KM	S1 B SERVICE	COMPLETED SERVICE AND SAFETY CHECKS AS PER SERVICE SCHEDULE	189	160.63	0	14	363.63
150409-00	SVC001484	04/13/2015	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899		REPAIR LIGHTS	REPAIR LIGHTS. REPLACED PARK LIGHT GLOBE AND FITTED NEW RUBBER DRIVE BELT TO ROTATING LIGHT.	52.5	0	0	2.5	55

150305-00	SVC001467	03/31/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899		REPLACE LEAKING ROCKER COVER	REPLACE LEAKING ROCKER COVER. FITTED NEW PEDAL PAD.ROCKER COVER GASKET HERE TO BE FITTED.	34.13	90.08	0	0	124.21
150330-00	SVC001481	03/31/2015	1H0368	IC-TRUCK F 186_INT	R	Bodywork	1VT899		REPLACE MISSING MUD FLAP	REPLACED MISSING MUD FLAPS FROM STOCK AS REQUIRED	42	0	0	0	42
150204-00	SVC001451	02/06/2015	1H0368	IC-TRUCK F 121ADMIN	R	Tyres	1VT899	252,470	JKJUL 295/80R22.5 TYRE X 2 + D	JKJUL 295/80R22.5 TYRE X 2 + DISPOSAL X 1 + BALANCE POWDER X 2	0	862	0	0	862
150106-00	SVC001431	01/14/2015	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	7177H 251	S1 B SERVICE	COMPLETED SERVICE AND SAFETY CHECKS AS PER SERVICE SCHEDULE	157.5	129.94	0	11	298.44
150106-00	SVC001431	01/14/2015	1H0368	IC-TRUCK F 186_INT	R	Radio	1VT899	251,172 Klr	MODIFY UHF/TWO WAY RADIO WIRING	REMOVED UHF WIRING FROM SINGLE 12V BATTERY, REMOVED DASH FACIA AND REMOVE WIRING AND COMPONENTS FROM PHONE KIT, MODIFY WIRING AND FIT V/REDUCER FOR UHF ONLY. AM/FM RADIO HAS A SEPERATE REDUCER, TEST UHF NOT WORKING, FIT GME UNIT SUPPLIED AND TEST ALL GOOD, CHECK OPERATION OF ROTATING LIGHT, BLET IS BROKEN, REPLACE AND TEST ALL GOOD.	238.88	30.5	0	11.5	280.88
150106-00	SVC001431	01/13/2015	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	7177H 251	REPLACE FUEL TANK BREATHER	Remove and replace fuel tank breather as required	52.5	10.88	0	0	63.38
150106-00	SVC001431	01/13/2015	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899	7177h 251	REPAIR LIGHTS	REPAIR ROTATING LIGHT WIRING AND FIT NEW GLOBE REPAIR BAD CONNECTION ON PARK LIGHT RECHARGE BATTERY.	210	9.89	0	10	229.89
150106-00	SVC001431	01/09/2015	1H0368	IC-TRUCK F 182_INT	R	Sundries	1VT899		RELINE 2 CHUTES AS REQUIRED	RELINE 2 CHUTES AS REQUIRED WITH 5MM HDPE BLACK	157.5	234.35	0	8	399.85
141209-00	SVC001421	12/17/2014	1H0368	IC-TRUCK F 186_INT	B	Electrical	1VT899		FIT UP VOLTAGE REDUCER FOR	CHECK FOR BATTERIES GOING FLAT, FOUND 1AMP, TRACED FAULT TO TWO WAY AND UHF, WIRED DIRECT TO 12V SIDE OF 24 SYSTEM, RADIOS BEING LEFT ON OVER NIGHT AND WEEKENDS, OBTAIN A VOLTAGE REDUCER TO BE FITTED WHEN UNIT NEXT AVAILABLE	136.5	80	0	6.5	223
141202-00	SVC001421	12/04/2014	1H0368	IC-TRUCK F 186_INT	R	Brake	1VT899	249042 KM	check park brake operation	CHECK PARK BRAKE OPERATION. REPLACED MAXI BRAKES ON REAR AXLES THAT HAS BROKEN SPRINGS.	238.88	116	0	11	365.88
141105-00	SVC001401	11/28/2014	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	247042 KM	REPLACE REAR MAIN SEAL	REPLACE REAR MAIN SEAL. REMOVED THE GEARBOX AND CLUTCH ASSEMBLY. PICKED UP SEAL AND SEAL INSTALLER FROM WEBSTERS AND FITTED NEW REAR MAIN SEAL. NOTE.HAD TO MACHINE NEW BOLTS FOR THE INSTALLER BECAUSE IT WAS NOT SET UP FOR A LIVE DRIVE SEAL INSTALLATION. CKEANED OIL FROM THE CLUTCH AND CLUTCH PLATE AND COMPLETED REASSEMBLY. BURNT IN THE CLUTCH TO REMOVE THA LAST OF THE OIL. REAR MAIN SEAL 1096255412 SUPPLIED ON SERVICE CALL 141106-0049	1046.08	101.1	0	50	1197.18
141106-00	SVC001401	11/28/2014	1H0368	IC-TRUCK F 186_INT	R	Engine	1VT899	6911	SUPPLY CORRECT SEAL,READ NOTES	REPLACE REAR MAIN SEAL. SUPPLY CORRECT SEAL FOR ENGINE REAR MAIN. NOTE .SEAL NUMBER IS 1096255412	0	0	0	0	0
141103-01	SVC001411	11/19/2014	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899	247,042 Klr	Replace batteries	REMOVE AND REPLACE U/S BATTERIES AS REQUIRED CLEAN TERMINALS AND CHECK CHARGE RATE	170.63	158.32	0	0	328.95
141103-00	SVC001401	11/18/2014	1H0368	IC-TRUCK F 186_INT	R	Brake	1VT899	247042 KM	REPAIR AIR LEAK	REPAIR AIR LEAK. TRACED AIR LEAK TO FAULTY QUICK RELEASE VALVE. CLEANED CONCRETE FROM VALVE AND HOSES REMOVED VALVE, PICKED UP NEW ONE AND FITTED.	220.5	28.18	0	11	259.68
141106-00	SVC001401	11/18/2014	1H0368	IC-TRUCK F 186_INT	R	Sundries	1VT899	247042 KM	REPLACE AIR CON IDLER	REPLACE AIR CON IDLER. TRAVELED TO WEBESTERS AND PICKED UP NEW PULLEY AND BEARING. SWAPPED OVER ADJUSTER AND FITTED UP WITH NEW SUPPLIED BELT.	102.38	68.05	0	5	175.43
141103-00	SVC001401	11/10/2014	1H0368	IC-TRUCK F 186_INT	R	Suspension	1VT899	6911 HRS :	TORQUE ROD REPAIRS	TORQUE ROD REPAIRS. CLEANED OFF CONCRETE AND REMOVED TORQUE RODS, PRESSED OUT BUSHES AND PRESSED IN NEW ONES. REFITTED THE TORQUE RODS AND TENSIONED BOLTS.	275.63	109.08	0	13.5	398.21

141027-00	SVC00139	10/29/2014	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	244204	INSPECT CHECK ENGINE LIGHT FAULT	CHECKED ENGINE LIGHT, CHECKED CODES CARRIED OUT CHECKS ON WIRING TO FUEL PRESSURE SENSOR, ALL OK, REMOVED AND CLEANED SENSOR CLEARED CODES, TRUCK STILL PLAYED UP, ORDERED NEW FUEL SENSOR (DIRECT PURCHASE) AND INSTALLED TO TRUCK AT LATER DATE, CARRIED OUT CJD EQUIPMENT	0	0	614.46	0	614.46
141015-00	SVC00139	10/23/2014	1H0368	IC-TRUCK F 187_INT	R	Air Con	1VT899	244846 KLI	REPLACE A/C PULLEY BEARING	REPLACE A/C PULLEY BEARING	68.25	35.72	0	3.4	107.37
141007-00	SVC00139	10/20/2014	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	244846KM	S1 B SERVICE	S1 B SERVICE	415.8	64.51	0	189.2	669.51
141014-00	SVC00139	10/16/2014	1H0368	IC-TRUCK F 187_INT	R	Bodywork	1VT899	163369 KLI	REPAIR RHS MIRROR MOUNT	REPAIR RHS MIRROR MOUNT	68.25	0	0	3.4	71.65
140915-00	SVC00138	09/26/2014	1H0368	IC-TRUCK F 187_INT	R	Trays/Buck	1VT899	N/A	DE-DAG BOWL	DE-DAG BOWL	0	0	960	0	960
140731-00	SVC00135	08/13/2014	1H0368	IC-TRUCK F 186_INT	R	Electrical	1VT899	241,541 km	CHECK LIGHTS AND REPAIR AS NEC	CHECK CENTRAL LOCKING CIRCUIT, REMOVE RH DOOR TRIM, ISOLATE DOOR LOCKING SOLENOID, REASSEMBLE AND TEST OPERATION ALL OK. LOCATE AND REPAIR BROKEN WIR IN CLEARANCE LIGHTS, REPLACE NUMBER PLATE LIGHT AND REPAIR NUMBER PLATE BRACKET AS REQUIRED	238.88	22	0	0	260.88
140729-00	SVC00135	07/31/2014	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	241310	JUMP START, REPLACE BATTERIES	TRAVELLED TO TRUCK, JUMP STARTED AS REQUIRED, PICK UP MUFFLER FROM NORTHERN MUFFLERS, TEST BATTERIES, FOUND TO BE FAULTY, REPLACE BATTERIES, CLEAN UP TERMINALS, REPLACE TERMINALS AND RE CONNECT CIRCUIT BREAKER FOR ACCESSORY POWER SUPPLY. COMPLETED BY CJD EQUIPMENT	0	0	397.03	0	397.03
140729-00	SVC00135	07/31/2014	1H0368	IC-TRUCK F 184_INT	R	Exhaust	1VT899	241310	REPLACE U/S MUFFLER	REMOVE MUFFLER, FIT NEW MUFFLER, OLD MUFFLER HAD HOLES AND CRACKS THAT COULDN'T BE WELDED, COMPLETED BY CJD EQUIPMENT	0	0	476.91	0	476.91
140715-00	SVC00134	07/25/2014	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899		Replace Tyre	replace tyre	0	0	305	0	305
140717-00	SVC00134	07/25/2014	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	N/A	Keys locked in vehicle	KEYS LOCKED IN VEHICLE SUBLETS - JACKSONS SECURITY GAIN ENTRY TO LOCKED VEHICLEJACKSONS SECURITY, CALL OUT TO LAUNCESTON GAIN ENTRY TO LOCKED HB UNIT	0	0	77.28	0	77.28
140714-00	SVC00134	07/15/2014	1H0368	IC-TRUCK F 184_INT	R	Bodywork	1VT899	240958	INSPECT DOOR LOCK FAULT	CHECK BOWL CONTROL, REMOVE REAR CONTROL, LUBE AND CHECK, RETAP THREADS AS RUSTED, FIT NEW BOLTS, FOUND S/W CONTROL NOT WORKING CORRECTLY SO REPAIRED. CAB AND REDV CONTROL WORKING CORRECTLY. COMPLETED BY CJD EQUIPMENT.	0	0	250.34	0	250.34
140709-00	SVC00133	07/10/2014	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	240393	REPLACE REVERSE LIGHT	REPAIR REVERSE LIGHT - INSTALLED NEW LED LIGHT TO PLUG. CARRIED OUT BY CJD EQUIPMENT.	0	0	124.58	0	124.58
140701-00	SVC00133	07/08/2014	1H0368	IC-TRUCK F 184_INT	R	Bodywork	1VT899	239165	replace damaged mudguard	TRAVEL TO ST LEONARDS, FIT NEW MUDGAURD TO TRUCK, REMOVE AND TURN LOAD CHUTE RAM AROUND 90 DEG TO PROTECT HOSES AND FITTINGS	282.98	152.21	0	124	559.19
140613-00	SVC00132	06/16/2014	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	237667	REPAIR UHF & REVOLVING LIGHT	CHECK ROTATING BEACON ON VEHICLE, REPLACE FAULTY LAMP AND TEST, CHECK UHF OPERATION, LOCATE AND REPAIR WIRING CONNECTIONS AT BATTERY. COMPLETED BY ST LEONARDS AUTO ELECS	0	154.25	0	0	154.25
140417-00	SVC00129	04/23/2014	1H0368	IC-TRUCK F 121ADMIN	R	Tyres	1VT899	236546KM	11R22.5 ADVANCE GL665A X 1 + S	11R22.5 ADVANCE GL665A X 1 + SCRAP, TYRE CHANGED IN LAUNCESTON RUBAND DD 07241	0	377	0	0	377
140213-00	SVC00125	02/13/2014	1H0368	IC-TRUCK F 184_INT	S	Service	1VT899	229483 KLI	S1 B SERVICE	CARRY OUT BASIC SERVICE @229,483 KMS 6478 HRS, CHANGED TWO GUARD MOUNT BRACKETS, TIGHTENED UP MESH GUARD OVER PTO DRIVESHAFT AND ADDED AN EXTRA BOLTS AS IT HAD RATTLED OUT, USED 26LTRS OF ENGINE OIL AND GREASE. COMPLETED BY CJD EQUIPMENT	0	0	854.86	0	854.86
131204-00	SVC00122	12/04/2013	1H0368	IC-TRUCK F 121ADMIN	R	Tyres	1VT899	227989	ADVANCE 11R22.5 GL268 X4 + DIS	ADVANCE 11R22.5 GL268 X4 + DISPOSAL RUBAND DD 04978	0	1528	0	0	1528
131203-00	SVC00122	12/03/2013	1H0368	IC-TRUCK F 121ADMIN	R	Tyres	1VT899	227,790KM	PUNCTURE REPAIR RUBAND 4919	PUNCTURE REPAIR RUBAND 4919	0	40	0	0	40
131118-00	SVC00121	11/20/2013	1H0368	IC-TRUCK F 187_INT	R	Bodywork	1VT899	205692 km	REPAIR DIESEL TANK	REPAIR DIESEL TANK REPAIR WHERE TANK STRAP HAD WORN THROUGH TANK. job missed in february SUBLET WIGGIES RADIATORS.	0	0	320	0	320

131007-00	SVC001195	10/28/2013	1H0368	IC-TRUCK F 186_INT	S	Service	1VT899	224638 KLI	S1 B SERVICE	CARRY OUT BASIC SERVICE AT 6056 HOURS 224637KM ON 8/10/2013 AS PER SERVICE REPORT AND ADDITIONS BELTS, OUTER AIR FILTER CARRIED OUT BY CJD EQUIPMENT	0	0	1046.5	0	1046.5
130813-00	SVC001155	08/14/2013	1H0368	IC-TRUCK F 121ADMIN	R	Tyres	1VT899	221,267	FIT 4 DRIVE TYRES AT ST LEONAR	FIT 4 DRIVE TYRES AT ST LEONARDS TYRERIGHT RUBAND DD 00377 PRIMEWELL 11R22.5 PW602 + DISPOSAL AS PER EMAIL TODD RUSHER 13/8/13	0	1548	0	0	1548
130719-00	SVC001135	07/19/2013	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	216788	REPAIR REVERSE ALARM & WIRING	CHECK REVERSE ALARM ON VEHICLE, REPLACE FAULTY ALARM, REPLACE CORRODED WIRING TO ALARM, SECURE AND CONNECT WIRING, CHECK OPERATION. CARRIED OUT BY ST LEONARDS ELEC	32.5	113.5	0	0	146
130527-00	SVC001115	06/18/2013	1H0368	IC-TRUCK F 184_INT	S	Service	1VT899	215239 klr	S1 B SERVICE	CARRYOUT BASIC SERVICE, CHANGE ENGINE OIL, GREASE, FILTERS, CHECK OPERATING SYSTEMS AND ITEMS AS B SERVICE SCHEDULE - CABLE TIE AIR LINES ON TANKS AND ENGINE WIRING FR. OF ENGINE, TIGHTEN ROCKER COVER, WORK COMPLETED BY CJD EQUIPMENT	65	0	687.9	0	752.9
130606-00	SVC001115	06/18/2013	1H0368	IC-TRUCK F 184_INT	R	Steering	1VT899	215239 KLI	REPLACE U/S DRAG LINK	REPLACE DRAG LINK ASSEMBLY, ORDERED AT SERVICE ON 29/5 AND FITTED 3/6/13, WORK COMPLETED BY CJD EQUIPMENT	65	0	745.5	0	810.5
130416-00	SVC001085	04/23/2013	1H0368	IC-TRUCK F 184_INT	R	Electrical	1VT899	208550 KLI	REPAIR ENGINE MISFIRE	CHECK ENGINE MISSFIRE. CHECK ALL PLUGS AND SENSORS AROUND TURBO ACTUATOR, ALL IN ORDER, UNABLE TO LOCATE A CAUSE - FURTHER INVESTIGATION BY MOTORS & JLH AUTO - 2 FAULTY INJECTOR WIRES REPAIRED. COMPLETED BY CJD EQUIPMENT.	65	0	367.4	0	432.4
130409-00	SVC001085	04/10/2013	1H0368	IC-TRUCK F 186_INT	R	Tyres	1VT899	N/A	S/HAND TYRE + TYRE DISPOSAL RU	S/HAND TYRE + TYRE DISPOSAL RUBAND DD 74469	0	131.5	0	0	131.5
130225-00	SVC001065	04/03/2013	1H0368	IC-TRUCK F 187_INT	F	Sundries	1VT899	TBA	FIT UOP TOW POINT	FIT UP TOW POINT	65	20	0	0	85
130319-00	SVC001075	03/28/2013	1H0368	IC-TRUCK F 184_INT	S	Service	1VT899	208550 KLI	S1 B SERVICE	CARRYOUT 'B' SERVICE. CHANGE ENGINE OIL, GREASE, FILTERS, CHECK AND TOP UP FLUIDS, REPLACE FTON HUB OIL, CHECK LIGHTS, BELTS, BATTERY LEADS, OPERATING SYSTEMS, WHEELS, SUSPN., DRIVELINE. COMPLETED BY CJD EQUIPMENT	65	0	788.15	0	853.15
130312-00	SVC001065	03/19/2013	1H0368	IC-TRUCK F 186_INT	R	Tyres	1VT899	207,248	RUBAND SCRAP TYRE 73885	RUBAND SCRAP TYRE 73885	0	284	0	0	284
130116-00	SVC001045	03/08/2013	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	202,925KM	REPLACE FAULTY SPEED SENSOR	REPLACE FAULTY ENGINE SPEED SENSOR	97.5	20	0	0	117.5
130116-00	SVC001045	03/08/2013	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	202,925KM	INSTALL WHEEL NUT INDICATORS	FAULTY ENGINE SPEED SENSOR AND CONNECTION ACTIVATING FAULT LIGHT AND CAUSING STARTING PROBLEMS. INSTALL WHEEL NUT INDICATORS AND RE-TENSION WHEEL NUTS. 60 X 33MM WHEEL NUT INDICATORS	32.5	60	0	0	92.5
130121-00	SVC001045	02/26/2013	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	4800 hrs 20	LOW POWER PROBLEM	LOW POWER PROBLEM TEST FOR ENGINE MISSFIRE, CHECK INSPECT EXHAUST BRAKE FUNCTION, INSPECT INJECTOR HARNESS, FOUND TO BE OK, WEBSTERS TO PLUG INTO SYSTEM TO READ CODES. SUB WEBSTERS-TEST DRIVE VEHICLE ,OULD NOT FAULT, CONNECVT TO TECH2 FOUND CRANK SENSOR FAULT ACTIVE. REPLACE CRANK SENSOR WITH SECOND HJAND SENSOR AND CLEAR FAULT CODE. ROAD TEST ALL OK NO FAULT CODES PRESENT. ORDERED IN NEW SENSOR TO BE FITTED WHEN TRUCK AVAILABLE.	164	40	267.16	57.6	528.76
130218-00	SVC001055	02/18/2013	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	205,692 klr	THROTTLE OPERATION ON BOWL	THROTTLE OPERATION ON BOWL TRAVEL TO DPORT QMIX AND CEHCK THROTTLE NOT WORKING. CHECK SWITCH AND CABLE CHECK FUSES AND OPERATION. LOCATE DRIVER LEFT IDLE UP SWITCHIN THE HIGH IDLE POSITION.	32.5	20	0	57.6	110.1
130114-00	SVC001035	01/22/2013	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	202925KM	OVERHEATING FAULT	OVERHEATING FAULT INSPECTED TRUCK AND FOUND RADIATOR TOP TANK HOT BUT BOTTOM TANK COLD. REPLACE THERMOSTAT AND FAN CLUTCH.	328	903.22	0	0	1231.22
130116-00	SVC001035	01/22/2013	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	202,925KM	S1 D SERVICE	S1 D SERVICE CHANGE ENGINE OIL AND OIL FILTER. CHANGE FUEL AND AIR FILTERS. CHANGE GEARBOX AND DIFF OILS. GREASE AND CHECKS AS PER SERVICE SHEET.	295.5	491.93	0	3.5	790.93

121122-00	SVC00101(12/20/2012	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	198576KM	S1 A SERVICE	S1 A SERVICE CHANGE ENGINE OIL AND FILTERS. CLEAN AIR FILTER, GREASE AND CHECK ALL FLUID LEVELS. CHECK LIGHTS, STEERING, SUSPENSION, DRIVELINE AND CHECK BRAKES AS PER SERVICE SHEET.	180	123.68	0	3.5	307.18
121217-00	SVC00102(12/20/2012	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	200,717KM	295/80R22.5 PUNCTURE REPAIR	295/80R22.5 PUNCTURE REPAIR FIELD SERVICE CALL REPAIR TYRERIGHT LATROBE (LOCKETT & REEVES) 1 X PUNCTURE REPAIR	0	59.1	0	0	59.1
121123-00	SVC00101(12/11/2012	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	198576KM,	Replace batteries	REPLACE BATTERIES TRAVEL TO DEVONPORT CONCRETE AND REPLACE BATTERIES. TEST BATTERIES FOR CORRECT CHARGING.	271.5	143.86	0	96	511.36
121005-00	SVC00098(10/23/2012	1H0368	IC-TRUCK F 187_INT	R	Radio	1VT899	4212 hrs 19	UHF RADIO REPAIRS	UHF RADIO REPAIRS TRAVEL TO DPORT Q-MIX AND CHECK OPERATION OF UHF RADIO. LOCATE BLOWN FUSE. REMOVE AND CHECK RADIO AND CONNECTIONS, REPLAE FUSE AND TEST.	68	20	0	57.6	145.6
120924-00	SVC00097(10/08/2012	1H0368	IC-TRUCK F 187_INT	R	Transmissio	1VT899	192,771 km	GEARBOX CABLE REPAIRS	GEARBOX CABLE REPAIRS TRAVEL TO Q-MIX DPORT ANMD CHEXCK BEARBOX CABLE / LINKAGE. FOUND CLIP HAD BROKEN. WIRE UP FOR TEMP REPAIR AND ORDER PARTS.	150	25.68	0	57.6	233.28
120919-00	SVC00097(09/28/2012	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	189044 km	REPLACE CLUTCH PEDAL RUBBERS	REPLACE CLUTCH PEDAL RUBBERS PARTS ONLY	0	48.58	0	0	48.58
120817-00	SVC00095(09/07/2012	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	188,644 km	S1 B SERVICE	S1 B SERVICE CHECKS AS PER SHEET, ENG OIL AND FILTER, FUEL FILTER AND AIR CLEANER.GREASE AND CHECK LIGHTS, ALL FLUID LEVELS, CHECK AND ADJUST BRAKES AND CHECK CLUTCH.	88.5	254.86	0	3.5	346.86
120820-00	SVC00095(09/07/2012	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	188803 km	COOLANT LEAK	COOLANT LEAK TRAVEL TO DPORT AND CHECK COOLANT LEAK ON BOTTOM RADIATOR HOSE, REMOVE AND REPLACE HOSE CLAMP. CLEAN AND INSPECT HOSE FOR CRACKS AND SPLITTING. CHECK COOLANT LEVEL.	368	40	0	28.8	436.8
120806-01	SVC00094(08/29/2012	1H0368	IC-TRUCK F 187_INT	R	Steering	1VT899	185,466 km	WHEEL ALIGNMENT	CARRY OUT WHEEL ALIGNMENT BY ARD	29.5	0	504.55	0	534.05
120817-00	SVC00095(08/22/2012	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	188,644 km	REPLACE MUDFLAP	REPLACE MUDFLAP REMOVE AND REPLACE MUDFLAP PARTS FROM HOBART	49.75	20	0	0	69.75
120618-00	SVC00092(07/06/2012	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	184,929KM	STEER TYRES AND BALANCE	STEER TYRES AND BALANCE TYRERIGHT BURNIE 3607784 2 X ADVANCE 295/80-22.5 STEER TYRES 2 X POWDER BALANCE	0	1000	0	0	1000
120604-00	SVC00091(06/20/2012	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	184233 km	REPAIRS TO LIGHTS	CARRIED OUT REPAIRS TO LIGHTS. TRACE AND REPAIR FAULT IN WIRING TO LIGHTS AND REPLACED GLOBES	88.5	40	0	0	128.5
120608-00	SVC00091(06/20/2012	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	184,640 km	REPLACE WIPERS	REPLACE WIPERS. CARRY OUT REPAIRS TO REPLACE WIPER BLADES AND ADJUSTED MIRRORS	29.5	12.32	0	0	41.82
120411-00	SVC00089(05/25/2012	1H0368	IC-TRUCK F 187_INT	R	Trimming	1VT899	181,587KM	RE-ATTACH DASH PANELS	RE-ATTACH LOOSE DASH PANELS	13	10	0	0	23
120411-00	SVC00088(05/25/2012	1H0368	IC-TRUCK F 187_INT	R	Clutch	1VT899	181,587KM	ADJUST CLUTCH	Adjust clutch as required	42.5	10	0	0	52.5
120405-00	SVC00089(05/24/2012	1H0368	IC-TRUCK F 187_INT	R	Engine	1VT899	181574 km	OVERHEATING	UNIT OVERHEATING. WASH OUT RADIATOR AND CHECK COOLANT LEVEL AND CONDITION, DRAIN AND FLUSH RADIATOR, REMOVE AND TEST THERMOSTATS, REPLACE THERMOSTATS.	297.5	165.99	0	0	463.49
120216-00	SVC00084(04/26/2012	1H0368	IC-TRUCK F 187_INT	S	Service	1VT899	178,791 km	S1 A SERVICE	S1 A SERVICE CARRY OUT SERVICE AS PER SCHEDULE. GREASE AND CHECK FLUID LEVELS. ADJUST BRAKES AND CLUTCH.ORDER SEAT BELT LATCH AND FUEL TANK BREATHER. NEED TO REPLACE ROCKER COVER GASKET.	29.5	177.24	0	3	209.74
120217-00	SVC00087(04/11/2012	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	178,791 km	CHECK A/C CONTROLS	A/C REPAIRS REMOVE DASH PANELS AND CHECK CONTROLS FOR VENTS. FOUND WORN PLATE AND REASSEMBLE FOR REPAIRS WHEN PLATE ARRIVES.	118	45.76	0	0	163.76

120119-00	SVC00084	02/22/2012	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	N/A	PARTS ONLY - BRAKE BOOSTER	SUPPLY PARTS ONLY BRAKE BOOSTER	0	180	0	0	180
111215-00	SVC00081	01/24/2012	1H0368	IC-TRUCK F 187_INT	R	Tyres	1VT899	N/A	TYRE VALVE STEMS	TYRE VALVE STEMS TYRERIGHT 3606093 VALVE STEMS - DRIVE TYRES	0	44	0	0	44
111209-00	SVC00081	12/22/2011	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	177,094 km	READJUST SEAT	READJUST SEAT. Remove seat base and adjust seat hight. Reassmble and test.	59	20	0	0	79
111104-00	SVC00079	12/16/2011	1H0368	IC-TRUCK F 187_INT	R	Brake	1VT899	174628 km	REPLACE BRAKE BOOSTERS	REPLACE BRAKE BOOSTERS. Check and repair rear brake boosters. Adjust and test	361	278.88	0	0	639.88
111104-00	SVC00081	12/16/2011	1H0368	IC-TRUCK F 187_INT	R	Clutch	1VT899	174628 km	ADJUST CLUTCH	ADJUST CLUTCH - Check and adjust clutch and test.	29.5	20	0	0	49.5
110718-00	SVC00081	12/14/2011	1H0188	CONCRETE 187_INT	R	Bodywork	1VT899	TBA	REPLACE SEAT BELT	REPLACE SEAT BELT.	29.5	0	0	0	29.5
110715-00	SVC00075	11/25/2011	1H0188	CONCRETE 187_INT	R	Sundries	1VT899		CHECK CAB MOUNTS	CHECK CAB MOUNTS	59	0	0	0	59
110914-00	SVC00076	10/24/2011	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	173497KM	REPLACE CD RADIO	REPLACE CD RADIO. REPLACE FAULTY HEAD UNIT	200.5	258.62	0	0	459.12
111006-00	SVC00078	10/24/2011	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	174628KM	REPLACE SEAT BELT	REPLACE SEAT BELT ON DRIVERS SIDE AS IT WILL NOT RETRACT ANYMORE	13	265.2	0	0	278.2
111006-00	SVC00078	10/17/2011	1H0368	IC-TRUCK F 187_INT	R	Sundries	1VT899	174628KM	REPACE SEAT SHOCKY	REPACE SEAT SHOCKY, SHOCKEY NOT WORKING OVER BUMPS - SEAT BOTTOMS OUT	88.5	142.5	0	0	231
111006-00	SVC00078	10/17/2011	1H0368	IC-TRUCK F 187_INT	R	Bodywork	1VT899	174628KM	REPLACE CAB MOUNT	REPLACE CAB MOUNT BUSHES IN FRONT OF CAB	62.5	380.14	0	0	442.64
110901-00	SVC00076	09/26/2011	1H0368	IC-TRUCK F 187_INT	R	Electrical	1VT899	172407	REPLACE REVERSE ALARM	REPLACE REVERSE ALARM.	59	52.95	0	0	111.95
110729-00	SVC00074	08/16/2011	1H0188	CONCRETE 187_INT	R	Brake	1VT899	171,461 km	Replace brake booster	REPLACE BRAKE BOOSTER. Check brakes and replace brake booster RHS front diff.	55.5	79	0	0	134.5
110729-00	SVC00074	08/16/2011	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	TBA	TAIL LIGHT REPAIRS	SUBLET AE AUTO ELECTRICS. CHECK FUSES FOR BLOWING ON WINDOW AND HORN CHECK THROUGH WIRING, SET UP SHORT LGIHT AND FOUND RELATED TO TAIL LAMPS, TRACED AND CHECKED WIRING REMOVE AND REPLACED TAIL LIGHT ASSEMBLIES, MOUNT ANS SOLDER WIRING, MOUNT AND WIRE REVERSE LIGHTS AND NEW NUMBER PLATE LAMP. TEST OPERATION OF ALL LIGHTS AND REPLACE BLOWN FRONT PARK LIGHT GLOBE AS REQUIRED.	0	0	569.05	0	569.05
110715-00	SVC00074	08/15/2011	1H0188	CONCRETE 187_INT	PW	Bodywork	1VT899	TBA	REPAIR DASH AND THROTTLE	REPAIR DASH AND THROTTLE. check dash and replace clips and plugs to repair, adjust throttle on aggi.	59	0	0	0	59
110630-00	SVC00072	08/09/2011	1H0188	CONCRETE 186_INT	R	Bodywork	1VT899		REPAIR TRIM OF DRIVERS SEAT	REMOVED DRIVERS SEAT AND HAD REPAIRED , RE-INSTALLED. SUPPLY AND INSTALL NEW PLASTIC MUDGUARDS AND NEW BRACKETS TO VEHICLE.	88.5	743.46	245	0	1076.96
110629-00	SVC00072	07/15/2011	1H0188	CONCRETE 181_INT	R	Bodywork	1VT899		SANDBLAST AND PAINT CHASSIS AN	PRESSURE WASH CHASSIS SANDBLAST CHASSIS AND WHEELS REMOVE WHEELS AND RESPRAY WHITE PAINT CHASSIS IN GLOSS 2 PACK BLACK REMOVE QUICK MIX SIGNAGE FROM TRUCK MASK UP AND PAINT TRUCK CAB IN HAZELL COLOURS POLISH REMAINDER OF CAB TOUCH UP CHIPS AND SCRATCHES IN WHITE PAINT FIT NEW HAZELL SIGNAGE TO TRUCK	2507.5	502.87	769	0	3779.37
110617-00	SVC00072	06/30/2011	1H0188	CONCRETE 187_INT	A	Electrical	1VT899	TBA	REPLACE REVOLVING LIGHT	REPLACE REVOLVING LIGHT. travel to Dport Qmix and replace revolving light.	72.5	66	0	0	138.5
110603-00	SVC00071	06/22/2011	1H0188	CONCRETE 187_INT	S	Service	1VT899	169,055 km	S1 B SERVICE	S1 B SERVICE as per sheet. eng oil and filter, fuel filter, clean air filter, grease and adjust brakes.	206.5	221.26	0	15	442.76
110418-00	SVC00068	05/18/2011	1H0188	CONCRETE 187_INT	R	Engine	1VT899	166,880 km	ENG OIL LEAK	ENG OIL LEAK check eng oil leak and locate side cover/oil cooler leaking.	444.5	424.33	0	30	898.83
110504-00	SVC00069	05/12/2011	1H0188	CONCRETE 187_INT	A	Bodywork	1VT899	166880 km	RERPAIR MUDGUARD	RERPAIR MUDGUARD. CARRIED OUT ACCIDENT REPAIRS TO DAMAGED LEFT HAND SIDE MUDGUARD	29.5	0	0	15	44.5
110504-00	SVC00069	05/12/2011	1H0188	CONCRETE 187_INT	A	Electrical	1VT899	166880km	REVERSE BEEPER	REVERSE BEEPER. CARRIED OUT ACCIDENT REPAIRS TO DAMAGED WIRING TO BEEPER	29.5	0	0	30	59.5
110117-00	SVC00064	05/02/2011	1H0188	CONCRETE 187_INT	R	Engine	1VT899	158466km	REPLACE ALT BELTS	REPLACE ALT BELTS. check alt belts , remove and replace with correct sized genuine parts from websters.	69	0	0	15	84
110304-00	SVC00065	03/08/2011	1H0188	CONCRETE 187_INT	A	Bodywork	1VT899	162590km	REPAIR DASH	REPAIR DASH. travel to devonport q-mix and replace clips on dash and reassemble.	29.5	88.2	0	54	171.7

110207-01	SVC00065	02/25/2011	1H0188	CONCRETE 187_INT	R	Tyres	1VT899	158,603km	PUNCTURE REPAIR SC66037	PUNCTURE REPAIR SC66037 dmc tyres po#3603139	0	45	0	0	45
110117-00	SVC00064	01/31/2011	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	158466km	REPLACE DASH LIGHTS	1 x 295/80r22,5 puncture repair REPLACE DASH LIGHTS. remove dash and speedo and replace dash illumination globes. reassemble and test.	69	0	0	30	99
110119-00	SVC00064	01/27/2011	1H0188	CONCRETE 187_INT	B	Bodywork	1VT899	158466km	REPAIRS TO SEAT	REPAIRS TO SEAT . sublet complete canvas and upholstery	0	0	70	0	70
101229-00	SVC00063	01/18/2011	1H0188	CONCRETE 187_INT	A	Bodywork	1VT899		REPLACE WINDSCREEN	REPLACE WINDSCREEN.	0	0	409.09	0	409.09
110117-00	SVC00063	01/17/2011	1H0188	CONCRETE 187_INT	S	Service	1VT899	158466km	SERVICE A	SERVICE A checks as per sheet grease , oil levels, check brakes.grease	241.5	3.74	0	123	368.24
101206-00	SVC00062	12/30/2010	1H0188	CONCRETE 187_INT	R	Engine	1VT899	150430km	TRUCK STOPPING INJECTERS	TRUCK STOPPING INJECTORS. follow on from s/c101018-0047. truck faulted again after injector had been replaced and websters hooked up computer to ecu. noted that rear 3 injectors had a short so replaced no 6 injector into no 5 injector. fitted origional injector back into no 6. had trouble geting no 5 inj out, as it had rusted in tight. test drove all ok. sublet WEBSTERS	0	0	391.8	0	391.8
101119-00	SVC00061	12/08/2010	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	154585km	CHECK BATTERIES	CHECK BATTERIES. test batteries and charging. both batteries had dry cells. original batteries. replace batteries. parts from century batteries.	207	138.32	0	118	463.32
101119-00	SVC00061	11/29/2010	1H0188	CONCRETE 187_INT	R	Engine	1VT899	154585km	REPAIR BROKEN EXHAUST	REPAIR BROKEN EXHAUST, travel to devonport and remove broken exhaust. repair at wiggies, refit to truck and test.	138	20	0	65.8	223.8
101018-00	SVC00059	11/26/2010	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	150950km	ELEC FAULT SHUTING DOWN	ELEC FAULT SHUTING DOWN. sevice eng light comming on and truck shutting down intermittantly.shut down under sock after returning from west coast, started up twice then kept running dropped load off at turners beach and returned to yard no problem. called websters to hook up tech 2 next morning,found code 159 in ecu. injector B+ shorting to ground on line 2(rear injectors). tested wirring and opened looms under cab,swapped over repaired ecu still ran ok no faults. checked injectors and found suspicious worn wiringin no6 inj wirring.. repaired wiring and tested. next morning fault happened again.opened loom from junction box to ecu, all looked good. changed over number 4 and 3 injector to try and isolate which injector has the shorted coil , believe that last time this fault occured ,the code was 158 front set shorted to ground,websters swapped the front and rear injectors over numbers 1,6,3,4. and left 5 and 2. if 159 occurs replace inj 6, if 158 replace number 3 inj, travel 240kms 27/10/10checked fault again and found inj no 6 was faulty,replaced inj and sent back to work	737.5	0	1558.31	0	2295.81
101025-00	SVC00061	11/26/2010	1H0188	CONCRETE 187_INT	R	Sundries	1VT899	151494km	REPAIR AIRLEAK	REPAIR AIRLEAK.travel to ulverstyone , locate and repair air leak near g/box. parts from stock	69	0	0	36	105
100916-00	SVC00058	10/08/2010	1H0188	CONCRETE 187_INT	S	Service	1VT899	148277 KM	S1 B SERVICE	Travel to Ulverstone S1 B SERVICE. checks as per sheet , eng oil and filter, fuel filter and grease. check and adjust brakes and lights.	345	124.98	0	12.7	482.68
100915-00	SVC00057	09/30/2010	1H0188	CONCRETE 187_INT	R	Hydraulic	1VT899	148720km	BLOWN HYD/HOSE	WORK CARRIED OUT RELATES TO AGITATOR 1QB67 BLOWN HYD/HOSE; travel to devonport q/mix carry put repairs to blown hyd hose,remove hose, new one made up through pirtek,fit new hose and top up hydraulic resivor and test.	259	33.2	277.59	118	687.79
100715-00	SVC00056	08/26/2010	1H0188	CONCRETE 187_INT	F	Sundries	1VT899	143535km	TOW HOOKS	TOW HOOKS supply and fit . parts from websters	69	98.03	0	0	167.03
100708-00	SVC00054	08/13/2010	1H0188	CONCRETE 187_INT	R	Electrical	1VT899		REPLACE TAIL LIGHT GLOBES	REPLACE TAIL LIGHT GLOBES. parts only	0	45.7	0	0	45.7
100714-00	SVC00054	07/30/2010	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	143535km	REPAIR TAILLIGHTS	REPAIR TAILLIGHTS. replace globe and temp repair. order new taillights and fit new lamps.	541.5	442.09	0	15	998.59
100729-00	SVC00054	07/30/2010	1H0188	CONCRETE 184_INT	R	Brake	1VT899	9866	FABRICATE NEW AIR LINES	LOCATE PARTS AND FABRICATE AND FIT NEW AIR LINE HOSE NEAR AIR TANKS	88.5	0	0	0	88.5
100414-00	SVC00050	06/16/2010	1H0188	CONCRETE 187_INT	R	Engine	1VT899	137442km	Replace sump gasket	REPLACE SUMP GASKET	165	181.77	0	15	361.77

100524-00	SVC000510	06/16/2010	1H0188	CONCRETE 187_INT	R	Clutch	1VT899	140116km:	CHECK AND REPLACE CLUTCH	CHECK AND REPLACE CLUTCH. check slipping clutch and adjust. not ok.order new clutch from websters. 25/05/10 remove clutch and get quinn eng to machine flywheel.check for correct specs because flywheel and clutch plate had unusual wear marks . wear depth on flywheel max 49mm this one was 47.8mm (48mm std) stonehouse to adjust clutch on flywheel.raised the fingers up 120 thou.replace rear eng seal. reassemble and test.Original problem may have been incorrect machining of flywheel the last time.	918.5	1101.53	145	10	2175.03
100414-00	SVC000501	05/26/2010	1H0188	CONCRETE 187_INT	S	Service	1VT899	137442km:	SERVICE A	SERVICE A. grease checks and blow out air cleaner.	132	4.61	0	15	151.61
100428-00	SVC000502	05/26/2010	1H0188	CONCRETE 187_INT	R	Electrical	1VT899	134599km:	ELEC FAULT DROPPING POWER	ELEC FAULT DROPPING POWER.ecu light coming on.. sublet websters devonport. 17/02/10 engine derating- check fault codes inspected fault codes found inj elec trouble code present.carried out diagnostic proceedure as per isuzu instructions. could not locate any faults with inj harness. removed ecu forinspection and found water damage present.replaced ecu and downloaded all software from old ecu and test. all ok. truck later returned with similar fault.swapped front three inj with rear ones to help diagnose and eliminate a faulty injector. truck picked up to test drive but fault never reoccured.	0	0	4537.52	0	4537.52
100329-00	SVC000479	04/13/2010	1H0188	CONCRETE 122_INT	R	Tyres	1VT899	N/A	TYRE REPAIRS DOWLING MCCARTHY	TYRE REPAIRS DOWLING MCCARTHY	0	2240	0	0	2240
091202-00	SVC000422	01/08/2010	1H0188	CONCRETE 122_INT	R	Sundries	1VT899		FIRST AID KIT AS PER SHANE DAL	FIRST AID KIT AS PER SHANE DAL	0	70	0	0	70
091009-00	SVC000417	12/23/2009	1H0188	CONCRETE 184_INT	R	Hydraulic	1VT899	123930	REPLACE HYDRAULIC VENT CAP	SUPPLY AD FIT HYDRAULIC VENT CAP	13.75	0	123.08	0	136.83
091130-00	SVC000409	12/22/2009	1H0188	CONCRETE 187_INT	R	Engine	1VT899	128382km:	REPLACE ALT BELTS	REPLACE ALT BELTS. parts suplied through bsc travel 60kms. Parts previously ordered on service call 090928-0023	55	0	0	54	109
091109-00	SVC000401	11/30/2009	1H0188	CONCRETE 184_INT	S	Service	1VT899	127480 km	SERVICE B	CARRIED OUT SERVICE AS PER SERVICE SHEET.	330	138.33	0	72	540.33
091102-00	SVC000389	11/06/2009	1H0188	CONCRETE 185_INT	R	Engine	1VT899	124713	REPLACE ACCELERATOR CABLE	BROKEN ACC. CABLE ON AGITATOR CHECK FOR NO ACC ON AGITATOR DISMANTLE LEVERS AND INSPECT - CABLE BROKEN REMOVE CABLE, TRY TO FREE UP BRAKE ON LEVERS, REASSEMBLE & FIT NEW CABLE REMOVE BROKEN BOLTS AND RELAY FOR LEVERS TO BODY	13.75	0	500.57	0	514.32
090928-00	SVC000386	10/30/2009	1H0188	CONCRETE 184_INT	R	Engine	1VT899	123000km:	CHECK LOOSE BELTS ON ENG ANDTI	Travelled to devonport check and replace v belts.	309.5	104.53	0	108	522.03
091019-00	SVC000383	10/29/2009	1H0188	CONCRETE 184_INT	R	Radio	1VT899	125523km:	REPAIR RADIO	REPAIR RADIO .Repair dry solder joint on pcb. return to d'port and fit radio and test.	110	0	0	54	164
090804-00	SVC000352	09/03/2009	1H0369	NOTHERN 184_INT	R	Trays/Buck	1VT899	see s dale	REPLACE SHOOT JACK	REPLACE SHOOT JACK	0	710	0	0	710
090804-00	SVC000337	08/11/2009	1H0369	NOTHERN 184_INT	R	Electrical	1VT899	119841	REPAIR SPEEDO/HOUR METER	SPEEDO AND HOUR METERS NOT WORKING , HOUR METER-7272 , REMOVED SPEEDO SENSOR AND MADE UP SPACER PIN , FITTED SPEEDO SENSOR AND TESTED , TESTED HOUR METER VOLTAGE , REMOVED METER AND REPLACED , SUPPLIED HOUR METER.	13.75	0	394.93	0	408.68
090727-00	SVC000333	07/29/2009	1H0369	NOTHERN 184_INT	R	Electrical	1VT899	119229	REPLACE INDICATOR LENS	REMOVE BROKEN INDICATOR LENS , SOURCE NEW INDICATOR LENS , FIT NEW LENS	13.75	0	156.22	0	169.97
090622-00	SVC000315	06/25/2009	1H0369	NOTHERN 184_INT	R	Trimming	1VT899	116063	REPAIR DRIVERS SEAT BASE	REMOVE SEAT BASE, TAKE TO HAVE REPAIRED, PICK UP AND FIT TO TRUCK	13.75	0	282.38	0	296.13
090615-00	SVC000311	06/24/2009	1H0369	NOTHERN 184_INT	R	Service	1VT899	16,500 KM:	REPLACE OUTER AIR FILTER	REPLACE OUTER AIR FILTER : TRAVEL TO DEVONPORT REMOVE AND REPLACE OUTER AIR FILTER. * ALL FILTERS SUPPLIED THROUGH NORTH WEST TRUCK CENTRE ! TRAVEL DISTANCE 80 KMS	82.5	52.9	0	74.7	210.1

090609-00	SVC000306	06/10/2009	1H0369	NOTHERN	184_INT	S	Service	1VT899	116,063 KM	A - TYPE SERVICE	S1-A SERVICE : TRAVEL TO DEVONPORT Q/MIX CARRY OUT SERVICE AND CHECKS ON UNIT.	196	8.2	0	27	231.2
090428-00	SVC000285	05/06/2009	1H0369	NOTHERN	184_INT	R	Clutch	1VT899	111660	REPLACE CLUTCH ASSEMBLY	REPLACE CLUTCH ASSEMBLY AND FABRICATE NEW LONGER PUSH ROD FOR SLAVE CYLINDER	13.75	0	1779.82	0	1793.57
090130-01	SVC000255	03/19/2009	1H0369	NOTHERN	122_INT	R	Tyres	1VT899	105927	TYRE REPAIR RUBAND 39880	TYRE REPAIR RUBAND 39880	0	1230	0	0	1230
081215-00	SVC000246	02/26/2009	1H0369	NOTHERN	184_INT	R	Engine	1VT899	97598	REGAS AIR CON.	REGAS AIR CON ON UNIT	0	0	410.34	0	410.34
090210-00	SVC000248	02/26/2009	1H0369	NOTHERN	184_INT	S	Service	1VT899	106,838 km	D - TYPE SERVICE		223.5	282.3	0	0	505.8
090217-00	SVC000247	02/25/2009	1H0369	NOTHERN	184_INT	R	Ancillary Ec	1VT899	97598	REGAS AIR CON SYSTEM.	REPLACE CHAFFED HOSE AND REGAS AIR CON	13.75	0	410.34	0	424.09
090213-00	SVC000242	02/17/2009	1H0369	NOTHERN	184_INT	S	Service	1VT899	107069	CHANGE DIFF OILS	FINISHED OFF SERVICE AND CHANGE OUT DIFFERENTIAL OILS	113.5	746.9	0	2.7	863.1
081127-00	SVC000211	12/05/2008	1H0369	NOTHERN	184_INT	R	Electrical	1VT899	N/A	REPAIR SPEEDO	CASRRY OUT REPAIR TO SPEEDO ON UNIT	0	0	272.99	15	287.99
081119-00	SVC000206	11/27/2008	1H0369	NOTHERN	184_INT	R	Engine	1VT899	98022.	REPAIR BROKEN AIR CON BELT.	REPLACE BROKEN AIR CONDITIONER BELT	0	0	141.79	15	156.79
081028-00	SVC000191	11/10/2008	1H0369	NOTHERN	184_INT	R	Engine	1VT899	97533	REPLACE TAPPET GASKET & REPAIR	REMOVE AND REPLACE TAPPET COVER GASKET	0	0	173.48	15	188.48
081013-00	SVC000191	10/29/2008	1H0369	NOTHERN	184_INT	S	Service	1VT899	96026.	S1 B SERVICE & REPAIRS	CARRY OUT S1-B SERVICE AS PER SCHEDULE, SUPPLY AND FIT NEW UHF, REMOVED DASH AND FITTED UHF, FITTED AERIAL AND WIRED IN AND SUPPLY BATTERY TERMINALS	0	0	1762.89	15	1777.89
080912-00	SVC000167	09/17/2008	1H0369	NOTHERN	184_INT	R	Engine	1VT899	92000	REPAIR ENGINE SHUTDOWN FAULT.	CARRY OUT INSPECTION OF ENGINE SHUTDOWN FAULTS, SUPPLY TURBO WAIST GATE OPERATING SOLENOID AND RECITIFY WIRING TO ECU	0	0	495	15	510
080827-00	SVC000161	09/03/2008	1H0369	NOTHERN	184_INT	R	Brake	1VT899	95062.	Replace Brake Boosters.	ASSESS FAULTY BRAKE BOOSTER REMOVE AND REPLACE BRAKE BOOSTERS ADJUST BRAKES AND RAOD TEST OPERATION OK	0	0	961.96	15	976.96
080730-00	SVC000151	08/12/2008	1H0369	NOTHERN	184_INT	S	Service	1VT899	90589.	S1 B SERVICE.	CARRY OUT SERVICE AS PER SCHEDULE AND SAFETY CHECK	0	0	709.82	17.7	727.52
080730-00	SVC000151	08/12/2008	1H0369	NOTHERN	184_INT	F	Electrical	1VT899	92081.	SUPPLY & FIT REVOLVING LIGHT.	SUPPY AND FIT ROTATING LIGHT AND HARD WIRE IN PLACE. REMOVED INTERIOR LIGHT ASSEMBLY AND MOUNT ROTATING LIGHT, WIRE IN SWITCH AND FUSE AND TEST ALL OK	0	0	438.13	15	453.13
080523-00	SVC000111	05/30/2008	1H0369	NOTHERN	184_INT	R	Ancillary Ec	1VT899	102417.	REPLACE BOWL BEARINGS ETC.	CARRY REMOVAL AND REPLACEMENT OF ALL BEARINGS IN BOWL ROLLERS. TENSION FAN AND ALTENATOR BELTS. FIT LEFT HAND FRONT AIR DEFLECTOR AND SUPPLY ROPE CLAMP	0	0	1316.6	0	1316.6
080516-00	SVC000111	05/27/2008	1H0369	NOTHERN	122_INT	R	Tyres	1VT899		SERVICE CALL 45304	1VT899 DOWLING McCARTHY TYRES PUNCTURE REPAIR	0	30	0	0	30
080510-00	SVC000106	05/19/2008	1H0369	NOTHERN	184_INT	S	Service	1VT899	85007.	SI B SERVICE & REPAIRS.	Perform service and safety check as per shedule Drain and flush gearbox, manufacture new breather, replace wiper blades.	0	0	1220.66	0	1220.66
080510-00	SVC000106	05/19/2008	1H0369	NOTHERN	184_INT	R	Engine	1VT899	85007.	REPAIR OVERHEATING FAULT.	Assess overheating problem. Remove inter cooler and clean out inter cooler fins and radiator fins. reassemble and test operation.	0	0	227.48	0	227.48
080108-00	SVC000048	03/26/2008	1H0369	NOTHERN	122_INT	R	Sundries	1VT899		FRM R/O 13696 COOLOING FAN		0	0	416.63	0	416.63
071101-00	SVC000031	03/07/2008	1H0369	NOTHERN	122_INT	R	Brake	1VT899		repair brakes		0	0	420.25	0	420.25

Applied filters:Posted_Date is on or after 01/01/1900Equipment_ID is 1VT899