

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontractor Cost	Other Cost	Total Cost
78346	99023	09/23/2025	1HM184HBG	ID - WSHOP - FIELD	5186G	R	Chassis	1VT1227	210634.00	0	Pre Disposal Inspection	CARRY OUT PRE DISPOSAL INSPECTION REMOVED TRACKER 12430 AND GIVEN TO SEAN	2464.5	11.12	0	0	2475.62
76126	91492	08/13/2025	1HM184HBG	ID - WSHOP - FIELD	5186G	R	Engine	1VT1227	210634.00	0	Reassemble engine		1092	0	0	0	1092
68337	84936	03/19/2025	1HM186HBG	ID - WORKSHOP - ME	186G	R	Engine	1VT1227	0.0000	0	ENGINE REPAIR		1438.42	0	0	0	1438.42
63039	77501	12/16/2024	1HM192HBG	ID - LAUNCESTON W	184G	R	Electrical	1VT1227	210634.00	0	FIELD SERVICE		93.28	514.5	0	0	607.78
62963	76368	12/13/2024	1HM192HBG	ID - LAUNCESTON W	186G	R	Electrical	1VT1227	210634.00	0	TRANSFER FIT UP		225.25	523.58	0	0	748.83
62344	80801	12/03/2024	1HM192HBG	ID - LAUNCESTON W	184G	R	Sundries	1VT1227	210131.00	0	REPLACE FAULTY UHF AS REQUIRED		0	0	540.91	0	540.91
60321	72108	10/25/2024	1HM192HBG	ID - LAUNCESTON W	192G	R	Sundries	1VT1227	210131.00	0	Jumpstart	JUMP START VEHICLE & CHECK BATTERIES. ALL - OK.	46.64	0	0	0	46.64
60147	72883	10/22/2024	1HM192HBG	ID - LAUNCESTON W	192G	R	Sundries	1VT1227	210131.00	0	clean out truck prior to transfer		529.47	0	0	0	529.47
58015	70158	09/06/2024	1HM192HBG	ID - LAUNCESTON W	192G	S	Service Trailer	1VT1227	210131.00	0	CARRY OUT SERVICE, REPAIR WINDSCREEN	CARRIED OUT B SERVICE & VEHICLE INSPECTION. CHECKED ALL LIGHTS, CHECKED FLUID LEVELS. CHECKED SUSPENSION, BELTS, BRAKES & TYRES. LUBRICATED ALL GREASE POINTS. ROAD TESTED - ALL OK AT TIME OF TESTING BLED COOLING SYSTEM CARRIED OUT JUMP START CHECK CHARGING SYSTEM.	606.32	151.5	0	33	790.82
43076	51723	11/21/2023	1HM192HBG	ID - LAUNCESTON W	192G	R	Electrical	1VT1227	0.0000	0	Electrical Works & Air Con Repairs	CHARGE OUT	0	2036.36	0	0	2036.36
41724	49507	10/24/2023	1HM192HBG	ID - LAUNCESTON W	192G	R	Sundries	1VT1227	184739.00	0	Supply Air Line Fittings	ARRANGE & SUPPLY PARTS	44	38.22	0	5	87.22

38363	46372	08/17/2023	1HM192HBG	ID - LAUNCESTON W 192G	S	Service Trai	1VT1227	0.0000	0	Vehicle B Service & List Of Works	OD: 197,622	3269.5	1448.53	0	0	4718.03
											JL CARRIED OUT SERVICE AS PER SERVICE SHEET FIT NEW FIRE EXTCUT PIN FOR VICE, FIT INTO PLACE FIT NEW TRAILER PLUG CHECK OVER WIRING FOR WORK LIGHTS & 2ND BATTERIES NOT CHARGING FOUND 2 X FUSES BLOWN REPLACED, TESTED ALL OK REPAIR SPARE WHELL HOLDER DRAINED WASTE OIL DRUM CLEANED DEBRIE OUT OF TANK HEATED YP THE REST OF THE OLD HIGHU/S TAPE SCRAPED OFF, CLEANED, FIT NEW TAPE TEST DROVE, CHECKED OVER TRUCK - ALL OK					
											MW ASSISTED JL ON JOBS 9 BATTERIES TYRE RECOVERY) REWIRED REAR WORK LIGHTS REWIRED NEW REVERSE LIGHT					
36620	44573	07/17/2023	1HM192HBG	ID - LAUNCESTON W 192G	R	Tyres	1VT1227	0.0000	0	CHANGE FLAT TYRE	CHANGE FLAT TYRE	327	2048.18	0	0	2375.18
34322	38391	06/01/2023	1HM192HBG	ID - LAUNCESTON W 192G	R	Bodywork	1VT1227	184739.00	0	New Oil Drain Hose	ARRANGE SUBLET NEW OIL DRAIN HOSE	0	347	0	5	352
32014	36676	05/09/2023	1HM192HBG	ID - LAUNCESTON W 192G	R	Sundries	1VT1227	0.0000	0	Supply Welding Equipment		0	141	0	0	141
26213	33722	02/16/2023	1HM192HBG	ID - LAUNCESTON W 192G	R	Engine	1VT1227	184739.00	0	Complete Repairs	COMPLETE B SERVICE, FIT NEW CENTRE BEARING, FIX UP HI VIS TAPE & ANTI SLIP TAPE, FIT NEW SHOCK ABSORBERS ORGANISE NEW TYRES	934.38	3069.14	0	0	4003.52
23857	28858	12/14/2022	1HM192HBG	ID - LAUNCESTON W 192G	INT-S	Service Trai	1VT1227	159201.00	177652	CARRY OUT SERVICE AS DUE	OD: 177063]14.12 DR CARRIED OUT SERVICE AS PER SERVIVE SHEET	815.58	357.31	0	48	1220.89
											HB REPLACED COOLANT PIPES REPLACED BREAKE FLUID REPLACED POWER STEERING FLUID CHECKED SHOCKS/ SPRING BUSHES					
20051	34042	09/19/2022	1HM192HBG	ID - LAUNCESTON W 192G	F	Chassis	1VT1227	159201.00	0	SET UP TRUCK TOOLBOX ECT	OD: 165,000 SET UP TRUCK TOOL BOX	765.1	165.04	0	0	930.14

18648	22886	08/22/2022	1HM184HBG	ID - WSHOP - FIELD § 182G	R	Sundries	1VT1227	159201.00	0	REPAIRS TO TOOL BOX	REMOVE AND REPAIR DRAW ROLLERS AND BENT FRAMEWORK. FIT AND ADJUST DRAWS TO SUIT. STRAIGHTEN OUT BENT DOOR FRAME. PREP NEW DOOR SKIN FOR PRESSING. FABRICATE AND FIT FRAMEWORK INTO NEW DOOR SKIN. FIT NEW LOCKS AND HINGES TO DOOR. TEST FIT NEW DOOR TO TRAY. PREP AND PAINT NEW DOOR AND REPAIRS. FIT DOOR POST PAINT. COMPLETE FINAL INSPECTION OF REPAIRS.	3422.86	767.57	0	150	4340.43
14835	22943	05/27/2022	1HM184HBG	ID - WSHOP - FIELD § 181G	A	Bodywork	1VT1227	159201.00	0	REPAIRS TO TOOL BOXES	REPAIR DAMAGE TO TOOLBOX ON RHS OF TRUCK PAINT NEW DOOR FABRICATED BY WELDING SHOP	1018.36	90.2	0	30	1138.56
13647	15947	05/03/2022	1HM184HBG	ID - WSHOP - FIELD § 186G	INT-R	Electrical	1VT1227	0.0000	0	Check battery fault	REPLACE BATTERIES	228.03	488.78	0	0	716.81
3071	3648	08/11/2021	1HM184HBG	ID - WSHOP - FIELD § 186G	R	Brake	1VT1227	0.0000	159161	FRONT BRAKE REPAIRS	DISASSEMBLED FRONT BRAKES AND SENT ROTORS FOR MACHINING. REPACKED BEARINGS ,CLEAND ABS CHOPPING RINGS, REPLACED PADS AND COMPLETED ASSEMBLY. TENSIONED WHEEL NUTS AND TEST DROVE.	1314.17	1040.91	0	0	2355.08
1215	1982	06/28/2021	1HM184HBG	ID - WSHOP - FIELD § 184G	R	Engine	1VT1227	0.0000	159201	1VT1227 REPAIR DPD FAULT	INSPECT DPD FAULT CODE, CLEAR CODE AND CHANGE ENGINE OIL . REMOVE MUFFLER , CLEAN INTERNALLY AND REFIT IN REVERSE POSITION AS ADVISED, CARRY OUT FORCED BURN	756.82	188.76	0	0	945.58
433	5259	06/08/2021	1HM184HBG	ID - WSHOP - FIELD § 184G	R	Engine	1VT1227	0.0000	0	1VT1227 REPAIR EXHAUST LEAKS	supply part only no labour to fit	0	9.1	0	0	9.1
210423-00	SVC002636	05/26/2021	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	155,749	KL	S1 B SERVICE	S1 B SERVICE AS PER SERVICE SHEET	326.8	66.64	0	0	393.44
201106-00	SVC002575	04/23/2021	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	142,918	KM	S1 B SERVICE	S1 B SERVICE AS PER SERVICE SHEET CHECK ALL TYRE PRESSURES	326.8	208.9	0	0	535.7
210111-00	SVC002592	02/26/2021	1H0184	ID - WSHOP - FIELD § 186_INT	R	Tyres	1VT1227	146985		W/FORCE 225/70R19.5 X2 + DISX2	W/FORCE 225/70R19.5 X2 + DISX2	0	618	0	0	618

201201-00:SVC002566	12/09/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Engine	1VT1227	145,031 KM	CHECK ENGINE CODE ON DISPLAY	CHECK ENGINE CODE ON DISPLAY, REPAIR WIRING TO TURBO ACTUATOR, FOUND TURBO FAULTY, REMOVE AND REPLACE TURBO , FIT NEW MODIFIED TURBO OIL SUPPLY PIPE. ROAD TESTED OK	1288.85	2342.12	0	0	3630.97
201124-00:SVC002562	11/26/2020	1H0184	ID - WSHOP - FIELD § 186_INT	R	Tyres	1VT1227	144119	MICH 195H 225/70R19.5 X2 + BAL		0	750	0	0	750
201020-00:SVC002542	11/13/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Bodywork	1VT1227	141,301 KM	repairs after accident	REMOVE TOOL BOX FROM REAR OF TRUCK FOR REPAIRS AFTER ACCIDENT STRAIGHTEN AND REPAIR TOOL BOX REFIT TOOL BOX TO REAR OF TRUCK	416	44.82	0	0	460.82
200831-00:SVC002516	09/04/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	136,201 KM	REPAIR REMOTE OIL PUMP	STRIP AND LUBRICATE REMOTE DRUM PUMP, REASSEMBLE AND TEST OPERATION. TESTED OK DRAIN REMOTE WASTE OIL TANK AND CLEAN TRUCK INTERIOR AND WINDOWS	285.95	0	0	0	285.95
200817-00:SVC002508	08/18/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Engine	1VT1227	136,404 KM	CHECK ENGINE LIGHT ON DISPLAY	CHECK ENGINE LIGHT ON DISPLAY, CLEARED CODE AND CHECKED UNIT OVER. FAULT NOT RETURNED	81.7	0	0	0	81.7
200729-00:SVC002499	08/06/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Tyres	1VT1227	135686 KM	replace rear tyres	REPLACE REAR TYRES REMOVE RIGHT REAR INNER TYRE AND FIT SPARE AFTER SIDE WALL FAILURE REMOVE REAR WHEELS , HAVE NEW TYRES FITTED AND REFIT WHEELS	330.55	0	1232.72	0	1563.27
200618-00:SVC002477	06/24/2020	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	131,687 KM	S1 B SERVICE AND REPAIR EXHAUS	S1 B SERVICE AND REPAIR EXHAUST CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET REMOVE AND REPLACE DAMAGED SECTION OF EXHAUST PIPE AND TEST BURN FUNCTION REPAIR LIGHT WIRING	531.05	364.46	0	0	895.51
200507-00:SVC002459	06/17/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	130,306KM	REPLACE FAULTY OXY/ACCET REEL	REPLACE FAULTY OXY/ACCET REEL AND CONNECT TO BOTTLES	81.7	418	0	0	499.7
200518-00:SVC002466	05/28/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	129990 KM	FIT UP TARP	FIT UP TARP BETWEEN TOOLBOXES TO COVER OIL DRUMS AND PARTS REQUIRED FOR REPAIRS	163.4	0	135	0	298.4
200108-00:SVC002387	04/23/2020	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	122543 KM	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET. REPAIR WORK LIGHT REPLACE REVERSE LIGHTS REPLACE AIR CON BELT	367.65	171.99	0	0	539.64

200406-00	SVC00243	04/23/2020	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	128214 km	CHECK REMOTE BATTERY CHARGING	CHECK REMOTE BATTERY CHARGING FAULT AND REPLACE FAULTY CHARGE SOLINOID CLEAN UP TRUCK AFTER REPAIRS	490.2	294.15	0	0	784.35
190903-00	SVC00232	09/26/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	117503 KM	FIT REVERSE CAMERA TO UNIT		490.2	409.09	0	0	899.29
190813-00	SVC00231	08/20/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	115123	REPAIR CHECK ENGINE LIGHT FAUL	REPAIR CHECK ENGINE LIGHT FAULT AND REPLACE BROKEN SAFE-T-STEP, REPAIR WIRING FAULT IN INJECTOR HARNESS	245.1	51.25	0	0	296.35
190625-00	SVC00227	07/05/2019	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	112500KM	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET	163.4	114.32	0	0	277.72
190617-00	SVC00227	06/17/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Engine	1VT1227	112096	PERFORM ROADSIDE REGEN		89.2	0	0	12.5	101.7
190429-00	SVC00225	05/15/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	109460 KM	REPLACE U/S BATTERIES	REPLACE U/S BATTERIES IN JUMP START SYSTEM, CHECK WIRING AND CHARGE RATE TO BATTERY PACK	122.55	518.33	0	0	640.88
190221-00	SVC00220	02/23/2019	1H0184	ID - WSHOP - FIELD § 184_INT	A	Bodywork	1VT1227	104912 HR	REPAIR DAMAGED TOOLBOX DOOR HI	REPAIR DAMAGED TOOLBOX DOOR HINGE, TOOLBOX DOOR OPEN WHILE WORKING IN THE WORKSHOP, WHILE FITTER WENT TO THE STORE TO COLLECT PARTS AND PERSON FROM LIGHT VEHICLES MOVED THE TRUCK AND STRUCK THE DOOR ON ANOTHER VEHICLE.	72.7	78.64	0	0	151.34
190213-00	SVC00220	02/22/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Bodywork	1VT1227		REPAIR TOOL BOX RUNNERS AND DO	REPAIR TOOL BOX RUNNERS AND DOOR STRUTS	326.8	120	0	0	446.8
190118-00	SVC00218	01/27/2019	1H0184	ID - WSHOP - FIELD § 184_INT	R	Tyres	1VT1227	102032 KM	CHANGE BLOWN TYRE	CHANGE BLOWN TYRE CHANGE OUT BLOWN LEFT HAND INNER REAR TYRE	89.2	176.8	0	0	266
181217-00	SVC00217	12/24/2018	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	101000 KM	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET	326.8	203.41	0	0	530.21
181031-00	SVC00214	11/06/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	97646 KM	SET UP GREASE UNIT	SET UP GREASE UNIT IN TRUCK AND BLEED AIR FROM SYSTEM	285.95	95.27	0	0	381.22
180824-00	SVC00210	09/18/2018	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	91359 KM	S1 service	CARRIED OUT S1 SERVICE AS PER SERVICE SHEET	285.95	134.2	0	0	420.15
180910-00	SVC00212	09/18/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Engine	1VT1227	92799 KM	REPAIR OIL LEAK	REMOVE BELLY PLATE, REMOVE REPAIR AND REFIT TURBO DRAIN PIPE, STEAM CLEAN ENGINE AND CHECK FOR LEAKS, REFIT BELLY PLATE	468.1	17.91	0	0	486.01
180820-00	SVC00210	08/28/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	90490 KM	REPAIR FUEL LEAK	DRAIN FUEL SUB TANK AFTER FITTING DAMAGED ON WORK SITE REMOVE RESEAL AND REFIT FITTING IN BOTTOM OF FUEL TANK, TESTED OK	204.25	0	0	0	204.25
180806-00	SVC00209	08/07/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227		TEST AND TAG EQUIPMENT	TEST & TAG EQUIPMENT	0	0	27	0	27

180522-00	SVC00205	05/29/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227		Replace starter motor	Removed and replaced faulty starter motor	120.53	291.4	0	0	411.93
180502-00	SVC00204	05/07/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Engine	1VT1227	82750 KM	change coolant	CHANGE COOLANT AFTER ENGINE REPAIRS AND CHECK FOR LEAKS	120.53	91.55	0	0	212.08
180326-00	SVC00202	04/20/2018	1H0184	ID - WSHOP - FIELD § 186_INT	R	Engine	1VT1227	82658 KMS	CHECK OVER HEATING FAULT	CHECK OVER HEATING FAULT. REMOVED INJECTORS AND CHARGED CYLINDERS TO CHECK FOR LEAK INTO COOLING SYSTEM. TRACED TO NUMBER THREE AND FOUR. REMOVED THE CYLINDER HEAD AND FOUND BURNT PISTONS NUMBER ONE AND FOUR. REMOVED PISTONS AND LINERS,HONED LINERS,REPLACED PISTONS,PINS AND RINGS.COMPLETED BOTTOM END ASSEMBLY. HAD CYLINDER HEAD TESTED.OK MACHINED .004" FROM THE HEAD. REFITTED THE HEAD WITH THICKEST HEAD GASKET TO COMPENSATE FOR MACHINING. HAD INJECTORS CHECKED,REPLACED NUMBER ONE AND FOUR. COMPLETED REASSEMBLY AND TEST DROVE. REPAIRED WIRE TO VVT CONTROL , BROKEN AT THE BACK OF THE PLUG.. NOTE ONLY HAS WATER IN THE COOLING SYSTEM.	4436.5	2522.84	1480.9	0	8440.24
180308-00	SVC00201	03/13/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	81669 KM	REPLACE REVOLVING LIGHT	REMOVE AND REPLACE FAULTY REVOLVING LIGHT. TEST OPERATION AND WORKED OK	80.35	157.05	0	0	237.4
180301-00	SVC00201	03/06/2018	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	81568 KM	S1 B SERVICE	CARRIED OUT S1 B SERVICE AS PER SERVICE SHEET	124.28	194.77	0	11	330.05
180216-00	SVC00200	02/28/2018	1H0184	ID - WSHOP - FIELD § 184_INT	R	Tyres	1VT1227	81007	225/70R19.5 MAXIS UR275 X 4 +	FIX PUNCTURE REPAIR AND TAKE TRUCK TO RUBANDS FOR NEW TYRES	128.03	1466	0	0	1594.03
180108-00	SVC00198	01/08/2018	1H0184	ID - WSHOP - FIELD § 121_INT	R	Tyres	1VT1227	77847	Puncture repair	PUNCTURE REPAIR CARRIED OUT BY RUBAND	0	0	45	0	45
171207-00	SVC00197	12/13/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	76734 KM	Repair brake light fault	CHECK BRAKE LIGHT FAULT , TRACED TO FAULTY SWITCH ON PEDAL, REMOVE AND REPLACE SWITCH. CLEAN ABS SENSOR AND WIRING CONNECTIONS, TEST ALL OK.	200.88	17.95	0	0	218.83

171211-00	SVC001971	12/12/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	76817 KM	CHANGE OVER GENERATORS	CHANGE OVER GENERATORS, OLD GENERATOR DOESNT HAVE ENOUGH OUTPUT CAUSING COMPRESSOR MOTOR TO BURN OUT.	160.7	0	0	0	160.7
170817-00	SVC001915	10/20/2017	1H0184	ID - WSHOP - FIELD § 184_INT	S	Service	1VT1227	71168 KM	S1 B SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PR SERVICE SCHEDULE	361.58	200.3	0	0	561.88
171012-00	SVC001940	10/17/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Tyres	1VT1227	73560 KLM	REPLACE STEER TYRES & ROTATE	REPLACE STEER TYRES & ROTATE OLD STEERS TO REAR	0	673	20	0	693
170829-00	SVC001915	09/05/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	71650 KM	FIT REAR SAFETY STEP	PARTS ONLY SUPPLY REAR SAFETY STEP TO TOW BALL	0	106.22	0	0	106.22
170817-00	SVC001896	08/28/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Sundries	1VT1227	71168 KM	FIT UP GAS BOTTLES	FIT UP GAS BOTTLES AND FIT HOSES AND REGULATORS. MADE UP BRAKETS TO FIT COVER OVER ENGINE OIL DRUM	321.4	13.72	0	0	335.12
170606-00	SVC001875	07/20/2017	1H0184	ID - WSHOP - FIELD § 184_INT	F	Sundries	1VT1227	67100 KM	SET UP OIL, AIR AND GAS	SET UP OIL, AIR AND GAS REPAIR GENSET AND SET UP BULK OIL OUTLET , REMOVE THE LARGE COMPRESSOR AND FIT SMALLER UNIT, MOUNT EXTRA AIR TANK. SET UP OIL DRAIN FOR WASTE OIL TANK.	1236.87	447.87	0	0	1684.74
170523-00	SVC001865	07/06/2017	1H0184	ID - WSHOP - FIELD § 184_INT	F	Sundries	1VT1227	69257 KM	CHANGE OVER TRUCKS	CHANGE OVER TRUCKS CHANGE OVER PARTS AND TOOLING FROM 1VT675 TO NEW FIELD SERVICE TRUCK 1VT1227 CLEAN OLD UNIT READY FOR CHANGE OVER	2661.62	479.39	0	0	3141.01
170605-00	SVC001885	07/06/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Electrical	1VT1227	69257 KM	REPAIR LIGHTS	REPAIR LIGHT WIRING IN TOOL BOXES	160.7	0	0	0	160.7
170602-00	SVC001872	07/04/2017	1H0184	ID - WSHOP - FIELD § 184_INT	R	Hydraulic	1VT1227	69257 KM	REPAIR OIL LEAKS AT HIAB CONTR	CHECK OIL LEAK AT HIAB CONTROLS, FOUND LEAK AT CONTROL SOLINOID. CLEAN PART AND FOUND TO BE CRACKED. REMOVE AND REPLACE SOLINOID AND VALVE. OPERATE UNIT AND CHECK FOR LEAKS ,TESTED OK	364.45	568	0	0	932.45
170518-00	SVC001863	06/07/2017	1H0184	ID - WSHOP - FIELD § 186_INT	F	Sundries	1VT1227	66779 KMS	pre registration inspection	PRE REGISTRATION INSPECTION. CHECKED OVER VEHICLE FOR REGISTRATION, FOUND NOT FITTED WITH REVERSE LIGHTS.FITTED UP REVERSE LIGHTS AND ALARM .DELIVERED VEHICLE TO INSPECTION AND RETURNED.	763.97	66.64	180	38	1048.61

170427-00	SVC001856	05/31/2017	1H0184	ID - WSHOP - FIELD	181_INT	R	Bodywork	1VT1227	66832km	REPAIRS TO TRUCK AS REQUIRED	REPAIRS TO TRUCK AS REQUIRED STRAIGHTEN DOORS ON TOOL BOXES CUT AND POLISH CAB AND REMAINDER OF BOXES NOT BEING PAINTED PAINT DOORS ON TOOL BOXES AND LOWER SECTION WHERE REQUIRED REMOVE RED SCROLLS AND PIN LINES FROM CAB AND TOOL BOXES FIT NEW HB DECALS AND UNIT NUMBERS REPAIRED FAULTS WITH BRAKE LIGHTS AND WIRING AT THE REAR OF THE VEHICLE REPLACE WINDSCREEN COMPLETED BY NOVUS	2886.29	225.14	600.73	160	3872.16
-----------	-----------	------------	--------	--------------------	---------	---	----------	---------	---------	------------------------------	--	---------	--------	--------	-----	---------

Applied filters:Posted_Date is on or after 01/01/1900Equipment_ID is 1VT1227