

RITCHIE BROS. Diagnostic Report
 Auctioneers[®]
2010 International WorkStar 7400
Test Information

Engine	International 570 / Maxxforce 9 &10 (9.3)
Engine Serial	INT *570231220714286M07*5007708270--
VIN	1HTWGAZR9AJ281419
Driveline	Class 8 6x4
Body	Truck
Test Time	Oct. 24, 2026, 8:38 a.m.
File Length	34.205 s

Usage

Label	Value	Units
Engine Odometer	278,592	mi
Odometer (Instrument Cluster #1)	278,807	mi
Engine Total Hours of Operation	19,747.95	h

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Manufacturer Assignable SPN	Out of Calibration	1
Active	Body Controller	Manufacturer Assignable SPN	Abnormal Update Rate	1
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Failure	1
Previous	Body Controller	J1939 Network #2	Abnormal Update Rate	1
Previous	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	6
Previous	Body Controller	Manufacturer Assignable SPN	Current Above Normal	2
Previous	Body Controller	Cab HVAC Recirculation Door Control Actuator	Erratic, Intermittent, or Incorrect	6
Previous	Body Controller	Cab HVAC System Controller	Abnormal Update Rate	2
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	J1587	Abnormal Update Rate	14