

H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

Unit JD34 – Deere 750J Dozer

10:41 AM 26/10/2010

HOURS

BRANDT TRACTOR REPAIRED THE MONITOR THE
LIGHT WOULD NOT GO OFF WITH
THE KEY

4:26 PM 06/12/2010


HOURS 1749 NEXT SERVICE DUE AT 1976
SERVICE TECH TRAVIS
CHECKED MACHINE OVER
INSTALLED A ROAD RADIO
REPLACED THE FAN HYD MOTOR

9:25 AM 16/02/2011

HOURS 1873 NEXT SERVICE DUE AT 1976
SERVICE TECH TRAVIS
CHECKED MACHINE OVER

2:58 PM 08/03/2011

HOURS 1968 NEXT SERVICE DUE AT 2218
SERVICE TECH DEAN
SERVICED THE ENGINE 10/30
REPLACED THE OIL AIR AND FUEL FILTERS
REPLACED THE CUTTING EDGES AND CORNER BITS



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

9:13 AM 14/03/2011

HOURS 1985

SERVICE TECH TRAVIS

CHECK OUT CODES 522445.5 NAD 522447.7

COULD NOT FIND THE TROUBLE

CALLED BRAND TRACTOR CLINT SAID HE WOULD HAVE

A SERVICE TECH IN THE MORNING

4:15 PM 17/03/2011

HOUR 1993

SERVICE TECH MATT (BRANDT)

MATT CALLED AND SAID HE FOUND THE BROKEN WIRE

RUN A JUMPER WIRE WORKS GOOD

NO CODES

11:35 AM 29/03/2011

HOURS 2036 EXT SERVICE AT 2218

SERVICE TECH ROB

CHECKED MACHINE OVER

TURNED THE FAN TO THE CORRECT WAY


4:46 PM 5/27/2011

HOURS 2136 NEXT SERVICE DUE AT 2218

SERVICE TECH TRAVIS

CHECKED MACHINE OVER

CODE NO 96.3



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

3:21 PM 7/4/2011

HOURS

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

4:03 PM 7/5/2011

HOURS 2207 NEXT SERVICE DUE AT 2457

SERVICE TECH ROB

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

8:05 AM 08/04/2011

HOURS 2232 NEXT SERVICE DUE AT 2457

SERVICE TECH JOE

CHECKOVER

9:05 AM 27/09/2011

SERVICE TECH DEAN

SERVICED ENGINE 15/40


REPLACED OIL AIR AND FUEL FILTERS

6:23 AM 11/21/2011

HOURS 2741 NEXT SERVICE DUE AT 2749

SERVICE TECH CHRIS

SERVICED THE ENGINE 10/30



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE CUTTING EDGES AND THE CORNER BITS

7:06 AM 2/3/2012

HOURS 3042 NEXT SERVICE DUE AT 3292

SERVICE TECH TRAVIS

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

TURNED THE CUTTING EDGES AND REPLACED THE CORNER BITS

7:31 AM 2/28/2012

HOURS 3074 NEXT SERVICE DUE AT 3292

SERVICE TECH DEAN

CHECKED MACHINE OVER

REPLACED THE TRACK GROUPS

INSTALLED NEW SEGMENTS

REPLACED THE GREASE LINES ON THE HARD BAR

REMOVED SHIMS ON THE CENTRE BALL FOR THE DOZER

REPLACED THE TRANSMISSION AND HYD FILTERS

REPLACED THE BEARING ON THE FAN IDLER PULLEYS

REPLACED THE TRANSMISSION AND HYD FILTERS


CHANGED OIL IN THE FINAL DRIVES

ORDERED A NEW FUEL GAUGE SENDING UNIT

10:57 AM 6/26/2012

HOURS 3300 NEXT SERVICE DUE AT 3550

SERVICE TECH TRAVIS



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUELFILTERS

11:20 AM 8/9/2012

HOURS 3597 NEXT SERVICE DUE AT 3847

SERVICE TECH TRAVIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REPLACED THE CUTTING EDGES AND CORNER BITS

10:44 AM 9/6/2012

HOURS 3736 NEXT SERVICE DUE AT 3847

SERVICE TECH TRAVIS

CHECKED MACHINE OVER

BLOW THEW RAD OUT

FIRE EXT APRIL 2012

7:45 AM 11/2/2012

HOURS 3829 NEXT SERVICE DUE AT 4079

SERVICE TECH TRAVIS


SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

11:39 AM 11/8/2012

HOURS 3843 NEXT SERVICE DUE AT 4079

SERVICE TECH RYAN



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | VOC 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

CHECKED OUT THE CODES 604.4

REPLACED THE CAB WIRING HARNESS

CHECKED MACHINE OVER

10:37 AM 2/16/2013

HOURS 4020 next service due at

SERVICE TECH TRAVIS

CHECKED MACHINE OVER

TURNED THE CUTTING EDGES

REPLACED THE CORNER BITS

FIRE EXT APRIL 2012

1:44 PM 3/12/2013

HOURS 4070 NEXT SERVICE DUE AT 4320

SERVICE TECH RYAN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

8:09 AM 6/7/2013

HOURS 4335 NEXT SERVICE DUE AT 4585

SERVICE TECH CHRIS


SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FEUL FILTERS

FIRE EXT DEC 2012

9:11 AM 6/10/2013

HOURS 4335 NEXT SERVICE DUE AT 4585



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICE TECH CHRIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT DEC 2012

CUT ICE LUGS OFF

2:41 PM 6/24/2013

HOURS

SERVICE TECH RYAN

CHECKED OUT OIL LEAK

FOUND THE LINE ON THE FAN SOLINIOD VALVE HAD A HOSE THAT WAS LOOSE

TIGHTEN HOSE

ONE OF THE HOSES ON THE PRESSURE SENSOR WAS LEAKING REPLACED THE HOSE

1:47 PM 7/12/2013

HOURS 4480 NEXT SERVICE DUE AT 4585

SERVICE TECH CHRIS

THE OPERATOR CALLED IN AND SAID THE MACHINE WAS SMOKING BAD

DEAN CHECKED IT OUT THE TURBO HAD FAILED

GOT EXCHABGE FROM BRANDT

INSTALLED NEW TURBO CHECKED OIL PRESSURE IT WAS AT 46 POUNDS


INSTALLED A NEW ENGINE OIL FILTER

REPLACED THE ENGINE AIR FILTERS

CLEANED OUT THE AIR INTAKE PIPING

REMOVED THE LINE TO THE AIR TO AIR COOLER AND CHECKED IT

4:54 PM 8/13/2013



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 6672 NEXT SERVICE DUE AT 6872

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT DEC 2012

2:18 PM 10/24/2013

HOURS 4870

SERVICE TECH JOE

REPLACED THE INJECTORS

BRANDT TRACTOR CAME DOWN AND PROGRAMED THE INJECTORS

12:53 PM 11/27/2013

HOURS 4870 NEXT SERVICE DUE AT 5120

SERVICE TECH JOE

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT NOV 2013

REPLACED THE DECAL SENSOR

INSTALLED A NEW ENGINE OIL PAN GASKET

CHANGED OIL IN THE HYD TRANSMISSION AND FINAL DRIVES

REPLACED THE HYD AND TRANSMISSION FILTERS


REPLACED THE FAN BELT TENSIONER

AND BELT

REPLACED THE MISSING BOTTOM ROLLAR

REPLACED THE CUTTING EDGES

REPLACED THE TURBO LUBE LINE



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

CHANGED OIL IN THE WINCH
INSTALLED TARPS ON THE RAD

9:44 AM 3/14/2014

HOURS 5259 NEXT SERVICE DUE AT 5355

SERVICE TECH GORDON

CHECKED MACHINE OVER

FIRE EXT JAN 2014

REPLACED THE FAN BELT

REPAIRED THE LIGHTS

REMOVED THE SUCK FAN

FUEL GAUGE DOESNT WORK

12:44 PM 5/23/2014

HOURS 5390 NEXT SERVICE DUE AT 5640

SERVICE TECH CHRIS

INSTALLED NEW TRACK GROUPS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

OUTER LEFT A LITTLE LOW ON OIL

SEGMENTS NEED CHANGING


7:38 AM 8/28/2014

HOURS 5654 NEXT SERVICE DUE AT 5904

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

REPLACED THE DUO CONE SEAL ON THE LEFT HAND FINAL DRIVE

9:51 AM 16/01/2015

HOURS

SERVICE TECH RANDY

CHECKED OUT THE CODES ENGINE SPEED SENSOR NO SIGNAL 657.10

REPLACED THE SENSOR STILL HAS CODES

CHECKED WIRING HARNESS FOUND A WIRE WORE THRU ON THE FRAME

REPAIRED NO CODES

1:22 PM 17/02/2015

HOURS 5990 NEXT SERVICE DUE AT 6240

SERVICE TECH RYAN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2014

REPLACED THE BEARINGS IN THE TILT CYLINDERS AND ANGLE CYLINDERS

9:54 AM 23/04/2015

HOURS 6156 NEXT SERVICE DUE AT 6240

SERVICE TECH RYAN

CHECKED OUT THE HYD OIL LEAK


FOUND FAN REVERSING VALVE TO HAVE A CHECK VALVE LEAKING

RESEALED THE CHECK VALVE

INSTALLED NEW CUTTING EDGES AND CORNER BITS

INSTALLED A SAFTEY CHAIN ON THE FUEL CAP

INSTALLED A NEW POWER INVERTER



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

FIRE EXT MAY 2014

1:04 PM 09/06/2015

HOURS 6245 NEXT SERVICE DUE AT 6495

SERVICE TECH BRAXTON

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JAN 2015

11:01 AM 06/07/2015

HOURS

SERVICE TECH CRAIG

REPLACED THE TRANSMISSION WIRING HARNESS

CHECKED OVER

REPLACED THE RIGHT TRAVEL MOTOR SPEED SENSOR

2:14 PM 16/07/2015

HOURS

SERVICE TECH RANDY

REPLACED THE PRESSURE HOSE FOR THE FAN DRIVE MOTOR

11:26 AM 19/08/2015


HOURS 6510 NEXT SERVICE DUE AT 6750

SERVICE TECH RYAN

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT JAN 2015



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

4:52 PM 25/09/2015

HOURS 6620 NEXT SERVICE DUE AT 6760

SERVICE TECH CHRIS

CHECKED MACHINE OVER

REPLACED THE FUEL LEVEL GAUGE

REPLACED THE POOR HYD HOSES

CHECKED OUT THE CODES

REPLACED THE CHARGE PRESSURE SENSOR

WASHED THE MACHINE

REPLACED THE CAB TIP PUMP

FIRE EXT MAY 2015

REPLACED THE HYD OIL FILTER

8:39 AM 07/12/2015

HOURS 6685 NEXT SERVICE DUE AT 6760

SERVICE TECH CHRIS

CHECKED MACHINE OVER

REPLACED THE SEGMENTS

REPAIRED THE TWO WAY RADIO

INSTALLED THE REVERSABLE FAN


FIRE EXT MAY 2015

GREASED THE MACHINE

CHECKED THE PIVOT SHAFT BEARINGS

7:52 AM 16/03/2016

HOURS 6715 NEXT SERVICE DUE AT 6760



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICE TECH CHRIS

CHECKED MACHINE OVER

INSTALLED THE BLOW FAN

REPLACED THE INNER AND OUTER AIR FILTERS

5:00 PM 28/04/2016

HOURS 6815 NEXT SERVICE DUE AT 7065

SERVICE TECH GORDON

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2015

12:40 PM 29/04/2016

HOURS 6815 NEXT SERVICE DUE AT 7065

SERVICE TECH CHRIS

REPLACED THE CORNER BITS AND CUTTING EDGES

REPLACED THE HYD BLADE CONTROL LEVER

8:49 AM 07/11/2016

HOURS 6865 NEXT SERVICE DUE AT 7065

SERVICE TECH RYAN


CHECKED MACHINE OVER

CHANGED HYD AND TRANSMISSION OIL

REPLACED THE HYD AND TRANSMISSION FILTERS

FIRE EXT APRIL 2016

2:23 PM 24/02/2017



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 6978 NEXT SERVICE DUE AT 7065

SERVICE TECH RYAN

CHECKED MACHINE OVER

FIRE EXT APRIL 2016

INSTALLED NEW CORNER BITS AND EDGES

5:17 PM 24/05/2017

HOURS 7027 NEXT SERVICE DUE AT 7277

SERVICE TECH COLE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY2018

REPAIRED THE OIL LEAKS ON THE TRAVEL MOTORS

4:04 PM 05/06/2017

HOURS 7042 NEXT SERVICE DUE AT 7277

SERVICE TECH GORDON

CHECKED OUT THE MISSING PAD BOLTS

FOUND THE PADS HAD THE WRONG SIZE BOLT HOLE

COLE CHECKED MACHINE OVER

THE A/C DID NOT WORK


FOUND THE PRESSURE LINE OF THE COMPRESSOR HAD A HOLE IN IT

REPLACED THE LINE AND RECHARGED

WORKS GOOD

FIRE EXT MAT 2017

3:41 PM 09/08/2017



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 7262 NEXT SERVICE DUE AT 7512

SERVICE TECH SLADE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2017

SOME TRACK PADS ARE STARTING TO CRACK

REPLACED THE PADS WITH GOOD USED

10:47 AM 28/09/2017

HOURS 7409 NEXT SERVICE DUE AT 7512

SERVICE TECH COLE

CHECKED MACHINE OVER

REPLACED THE ENGINE AIR FILTERS

INSTALLED NEW CAB AIR FILTERS

REMOVED THE RAD ASSEMBLY AND WASH OUT

INSTALLED THE RAD ASSEMBLY AND REPLACED THE RAD HOSES

FIRE EXT JUNE 2017

FLIPPED THE CUTTING EDGES AND INSTALLED NEW CORNER BITS

6:15 AM 23/01/2018

HOURS 7549 NEXT SERVICE DUE AT 7799


SERVICE TECH AYDEN

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2017

1:32 PM 01/06/2018



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 7719 NEXT SERVICE DUE AT 7799

SERVICE TECH NEIL;

CHECKED MACHINE OVER

FIRE EXT MAY 2018

2:28 PM 27/08/2018

HOURS 7866 NEXT SERVICE DUE AT 8116

SERVICE TECH DENNIS

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2018

6:19 AM 15/10/2018

HOURS 7875 NEXT SERVICE DUE AT 8116

SERVICE TECH AYDEN AND MURRAY

REMOVED THE RAD AND WASHED

REPLACED THE FRONT CRANK SEAL AND COVER

REPLACED THE OIL PAN GASKET

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT MAY 2018


REPLACED TWO BROKEN PADS

WELDED THE ICE LUGS ON

1:30 PM 12/11/2018

HOURS 7880 NEXT SERVICE DUE AT 8130

SERVICE TECH SLADE



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | VOC 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICED THE ENGINE 10/30

CHECKED ENGINE TIMING

REMOVED THE ENGINE

REMOVED THE FRONT COVER

FOUND THE CAM IDLER GEAR WAS OUT OF TIME

INSTALLED THE GEAR CORRECTLY

INSTALLED THE FRONT COVER

REPLACED THE OIL PAN GASKET

REPLACED THE FRONT SEAL

INSTALLED A NEW REAR SEAL

REPLACED THE POOR HYD HOSES UNDER THE ENGINE

REPLACED THE RUBBERS IN THE REAR CAB MOUNTS

FIRE EXT MAY 2018

10:33 AM 15/01/2019

HOURS 8018 NEXT SERVICE DUE AT 8116

SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

REPLACED THE MAG FOR THE BLADE FLOAT

FORE EXT MAY 2018


5:15PM 28/01/2019

HOURS 8129 NEXT SERVICED DUE TA 8215

SERVICIE TECH MURRAY

MARCH15/2019

HOURS 8090 SERVICE DUE AT 8340



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICE TECH DENNIS

250 HR SERVICE 10W30 OIL.

CHANGED THE AIR OIL AND FUEL FILTERS

CHECKED MACHINE OVER

REPLACED THE FUEL RETURN LINE

CHANGED ALL THE FAN HOSES FROM BULKHEAD CONNECTOR TO THE FAN MOTOR

3:12 PM 22/05/2019

HOURS 8114 NEXT SERVICE DUE AT 8340

SERVICE TECH DENNIS

CHECKED THE MACHINE OVER

FIRE EXT MAY 2018

2:07 PM 15/07/2019

HOURS 8115 NEXT SERVICE DUE AT 8340

SERVICE TECH COLE

CHECKED THE MACHINE OVER

CHANGED THE TRANSMISSION OIL AND FILTERS

CHANGED THE HYD OIL AND FILTERS

CHANGED OIL IN THE FINAL DRIVES

REPLACED THE LIFT CYLINDER HOSES ON BOH SIDES


WASHED THE MACHINE

FIRE EXT JULY 2019

3:06 PM 23/08/2019

HOURS 8175 NEXT SERVICE DUE AT 8340

SERVICE TECH AYDEN



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

CHECKED THE MACHINE OVER

FIRE EXT JULY 2020

INSTALLED A NEW FUEL TANK SENDER

8:54 AM 20/02/2020

HOURS 8190 NEXT SERVICE DUE AT 8340

SERVICE TECH DENNIS

CHECKED THE MACHINE OVER

REPLACED THE BATTERY'S

FIRE EXT JULY 2019

10:50 AM 08/05/2020

HOURS 8244 NEXT SERVICE DUE AT 8340

SERVICE TECH AYDEN

CHECKED MACHINE OVER

REPLACED POOR HYD HOSES FOR TILT/ANGLE CYLINDERS.

FLIPPED THE CUTTING EDGES, NEW CORNERS.

UN PLUGGED FAN SOLENOID

CUT ICE LUGS

REPLACED CRACKED TRACK PADS.

*****TRACK PADS ON THIS MACHINE ARE IN VERY POOR SHAPE.*****


FIRE EXT APRIL/2020

9:02 AM 08/07/2020

HOURS 8276

SERVICE TECH SLADE

REPLACED THE BLOWER MOTORS FOR THE A/C CONDENSOR



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

7:12 AM 10/07/2020

HOURS 8293 NEXT SERVICE DUE AT 8340

SERVICE TECH SLADE

OPERATOR COMPLAINED THE MACHINE WAS HEATING UP

REPLACED THE ENGINE COOLING FAN

REPLACED THE THERMSTAT

BLOW OUT THE RAD

10:53 AM 23/08/2020

HOURS 8438 NEXT SERVICE DUE AT 8688

SERVICE TECH COLE

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FOUND THE FUEL TRANSFER PUMP LEAKING

REPLACED WITH A NEW ONE FROM BRANDT

REPAIRED THE FLOAT DETENT ON THE HYD CONTROLL LEVER

FIRE EXT APRIL 2020

1:34 PM 22/10/2020

HOURS 8519 NEXT SERVICE DUE AT 8738


SERVICE TECH COLE

CHECKED THE MACHINE OVER

REPAIRED THE HOSE GAURDS ON THE BLADE ANGLE CLYINDERS

FIRE EXT APRIL 2020

7:27 AM 13/11/2020



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 8523 NEXT SERVICE DUE AT 8738

SERVICE TECH AYDEN

CHECKED MACHINE OVER

REPLACED R/H ANGLE CYLINDER WITH OURS OUT OF STOCK

NEW DOGBONE BUSHINGS

CARRIER ROLLERS GETTING POOR.

FIRE EXT APRIL/2020

9:52 AM 12/04/2021

HOURS 8555 NEXT SERVICE DUE AT 8738

SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

RESEALED THE FRONT COVER ON THE WINCH

RESEALED THE COVER ON THE LEFT TRAVEL MOTOR

RIGHT HAND FINAL DRIVE WAS OVER FULL ON OIL

REPAIRED THE BOLT HOLES FOR THE STUMP PAN

FIRE EXT APRIL 2021

6:18 AM 10/06/2021

HOURS

SERVICE TECH MURRAY


CHECK OUT THE OIL LEAK UNDER THE CAB

FOUND THE HOSE FOR THE BLADE LIFT HAD

BLOWN THE CRIMP END OFF

HAD BRANDT TRACTOR MAKE UP A NEW HOSE

10:59 AM 07/07/2021



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

HOURS 8733 NEXT SERVICE DUE AT 9033

SERVICE TECH MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

WASHED THE RADS OUT

7:09 AM 24/05/2022

HOURS 8976 NEXT SERVICE DUE AT 9276

SERVICE TECH MURRAY

SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

REMOVED THE WORN OUT TRACK GROUPS

REMOVED THE TRACK FRAMES

INSTALLED NEW HARD BAR BUSHINGS

INSTALLED THE TRACK FRAMES OF OFF JD 29

THEY HAD NEW ROLLERS AND IDLERS INSTALLED

INSTALLED NEW SEGMENTS

INSTALLED NEW ITR TRACK GROUPS

CHANGED OIL IN THE FINAL DRIVES

REMOVED THE COOLING PACKAGE AND WASHED

INSTALLED THE COOLING PACKAGE


REPLACED THE DOOR WIPER ON THE LEFT SIDE

9:07 AM 15/07/2022

HOURS 9000 NEXT SERVICE DUE AT 9250

DATED ON JULY 12 2022

OPERATOR RAY



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

NO COMMENTS

10:47 AM 09/08/2022

HOURS 9022 NEXT SERVICE DUE AT 9276

OPERATOR MIKE

NO COMMENTS

DATED AUGUST 1/2022

1:26 PM 03/11/2022

HOURS 9108 NEXT SERVICE DUE AT 9408

SERVICE TECH WES

SERVICED THE ENGINE 10/30

REPLACED THE OIL AIR AND FUEL FILTERS

MAIN CFRAME BEARINGS WONT TAKE GREASE

THE EXHAUST MANIFOLD IS CRACKED

REPLACED THE COVER ON THE AIR FILTER HOUSING

ALT SQUEELS ON START UP

REPLACED THE EXHAUST MANIFOLD WITH NEW ONE FROM BRANDT TRACTOR

FIRE EXT APRIL 2023

10:33 AM 01/12/2023

HOURS 9224 NEXT SERVICE DUE AT 9408


SERVICE TECH MURRAY

CHECKED THE MACHINE OVER

SENT THE MACHINE TO RITCHIE BROS TO HAVE IT SAND BLASTED AND PAINTED

INSTALLED NEW DECALS

REPLACED THE LIGHTS IN THE GRILL



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

REPLACED THE BATTERY

4:51 PM 28/03/2024

HOURS 9257 NEXT SERVICE DUE AT 9408

SERVICE TECH WESTLY

CHECKED THE MACHINE OVER

REPLACED THE BEARING ON THE FAN BELT TENSIONER

REPLACED THE LEAKING TRANSMISSION OIL LINES

REPLACED A FLANGE 90 DEGREE ELBOW

REPLACED THE RIGHT HAND ANGLE CYLINDER

FIRE EXT NOV 2024

11:58 AM 18/06/2024

HOURS 9321 NEXT SERVICE DUE AT 9408

SERVICE TECH AYDEN

REPLACED THE LEAKING A/C LINE

RECHARGED THE SYSTEM

9:50 AM 28/06/2024

HOURS 9355 NEXT SERVICE DUE AT 9655

SERVICE TECH AYDEN


SERVICED THE ENGINE 15/40

REPLACED THE OIL AIR AND FUEL FILTERS

FIRE EXT NOV 2023

9:42 AM 20/09/2024

HOURS 9375 NEXT SERVICE DUE AT 9655



H.F. Nodes Construction Ltd.

Box 373 | Pouce Coupe | British Columbia | V0C 2C0
Phone: 250-786-5474 | Fax: 250-786-5807 | Email: info@hfnodes.com

SERVICE TECH SLADE

CHECKED THE MACHINE OVER

REPLACED THE PINS AND BUSHINGS IN THE C FRAME TO MAIN FRAME

REPAIRED THE GREASE FITTINGS AND GREASE

FIRE EXT NOV 2023

7:43 AM 26/11/2024

HOURS

SERVICE TECH WESTLY

REPLACED THE HYD FAN MOTOR