Search Work Orders - All History(All work types)

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Ayden Neufe	23-Sep-2026		874	Equipment	AT462	11325hr 11625ns Engine service Dec25 fire extinguisher Lubed door hinge				Closed	23-Sep-2026	Normal	Non PM
Ayden Neufe	25-Aug-2026		830	Equipment	AT462	11206hr Replaced blown lift hose on left side				Closed	25-Aug-2026	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Murray Lawr	11-Aug-2026		810	Equipment	AT462	Hours 1476 next service due at 1630 Exhaust manifold leaking ------- Murray Lawrence added [08/14/2026 07:38 AM] ------ Replaced exhaust manifold gaskets Replaced manifold studs and nuts Replaced thermostats Welded cracks on tailgate Calibrated transmission				Closed	18-Aug-2026	Normal	Non PM
Slade Odden	23-Jul-2026		782	Equipment	AT462	Hours 11,021 next service due at 11,321 Service the engine, 15w40 oil The tailgate has some cracks in it. The middle left tire is missing the bead lock and has spun half a turn .				Closed	24-Jul-2026	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	16-Jul-2026		772	Equipment	AT462	10964hrs next service at 11078hrs Needs seat shock ------- Wes DeVuyst added [07/16/2026 08:16 AM] ---------- Built hoses at shop replaced rubbed through hoses on truck.				Closed	21-Jul-2026	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	14-Jul-2026		766	Equipment	AT462	10950hrs next service at 11078hrs Leaking hydraulic line under dump box. Operator complained of cab door latch. ------- Wes DeVuyst added [07/13/2026 09:39 AM] ---------- Checked for leaking hydraulic hose, removed and replaced. Covered rubbed through lines with heater hose tied up lines. Checked operation/ leaks. Checked door latch, found latch handle bent and a bit loose on inside. Cab door latch works properly.				Closed	21-Jul-2026	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Murray Lawr	30-Mar-2026		659	Equipment	AT462	Hours 10859 next service due at 11078 Check the machine over Do check list ------- Murray Lawrence added [04/07/2026 05:24 PM] ---------- Hrs 10859 Ns 11078 Removed scr and dpf mufflers knocked out filters Reinstalled empty mufflers Installed egr blocker plates Triple threat deleted ecm Found tailgate chains in very poor condition Installed new chains on both sides Calibrated transmission				Closed	10-Apr-2026	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	05-Dec-2025		501	Equipment	AT462	Hours 10774 next service due at Check the machine over ------- Wes DeVuyst added [12/16/2025 10:07 AM] ---------- 10779hrs next service at 11078hrs Serviced engine. Changed Diff oils/filters Changed precleaner fan motor. Cleaned a/c evaporator Removed and replaced R/H lift cylinder Changed transmission oil/filters, calibrate transmission Removed and replaced Espare heater with a webasto heater Installed weather strip for cab filter.				Closed	17-Dec-2025	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	05-Oct-2025		447	Equipment	AT462	10614hrs next service at 10914hrs Service engine ------- Wes DeVuyst added [10/05/2025 09:57 AM] ---------- Serviced engine Replaced R/H signal bulb				Closed	06-Oct-2025	Normal	Non PM
Slade Odden	19-Sep-2025		415	Equipment	AT462	Hours 10,507 next service due at 10,654 Complaints of unit using coolant, found egr cooler leaking internally Replace the failed egr cooler. Installed new egr valve , calibrate and test unit.				Closed	19-Sep-2025	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Slade Odden	26-Aug-2025		362	Equipment	AT462	Hours 10,354 next service due at 10,654 300 hr service, 15w40 oil Re calibrate the turbo actuator. Blow out rads, replace fire ext May/2025 ------- Slade Odden added [08/26/2025 04:28 PM] ---------- Replaced the alternator belt as well				Closed	29-Aug-2025	Normal	Non PM
Wes DeVuys	07-Aug-2025		317	Equipment	AT462	10259hrs next service at 10367hrs A/C not working ------- Wes DeVuyst added [08/06/2025 12:21 PM] ---------- Changed cab filters. Recharged a/c. Removed and cleaned evaporator core, blew out drain lines. Blew out rads.				Closed	13-Aug-2025	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Slade Odden	31-Jul-2025		309	Equipment	AT462	Hours 10,233 Check active codes Ecu 641.07. Ecu 2795.07 Found turbo actuator stuck Replaced actuator, calibrate and test. Repair coolant leak at thermostat housing, top up coolant Installed new shock for the operators seat				Closed	01-Aug-2025	Normal	Non PM
Ayden Neufe	02-Jul-2025		246	Equipment	AT462	10067hr 10367ns Service ------- Ayden Neufeld added [07/01/2025 03:55 PM] ---------- Serviced engine				Closed	06-Jul-2025	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Ayden Neufe	06-Jun-2025		192	Equipment	AT462	Hours 9945 next service due at 9794 High temperature codes ------- Ayden Neufeld added [06/06/2025 06:36 AM] ------ Blew out all coolers and replaced engine air filter				Closed	06-Jun-2025	Normal	Non PM
Wes DeVuys	15-May-2025		117	Equipment	AT462	Hours 9792 next service due at 10092 Fire ext A/C Evaporator needs to be cleaned and the condenser. The compressor is making short cycles. Topped up the a/c but it did not help Checked the evaporator core it was plugged Cleaned it out test the A/C works good Repaired the rubbed wire on the Air throttle valve				Closed	16-May-2025	Normal	Non PM

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	oblem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
						The oil line on the remote mount for the engine oil filter are starting leak The line are on order from Brandt Tractor May 8 2025 Replaced the rear camera Installed the new remote oil filter lines Replaced the surge tank it was all cloudy inside							
			109	Equipment	AT462	Hours 9645 next service due at 9794 Fire ext Checked out the engine codes ECU57.07 Replaced the intake throttle valve				Closed	22-Apr-2025	Normal	Non PM