

Search Work Orders - All History(All work types)

Assigned To	Scheduled Dat	Due Date	WO #	Entity Type	Entity Name	blem Descript	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	03-Sep-2026		846	Equipment	AT463	9723hrs next service at 10023hrs Service engine. ----- Wes DeVuyst added [09/03/2026 07:36 AM] -- ----- Serviced engine. Installed grease whip line for lift cylinder. Greased drive line.				Closed	04-Sep-2026	Normal	Non PM
Slade Odden	05-Aug-2026		792	Equipment	AT463	Hours 9538 next service due at 9764 Weld cracks on the tailgate, Right arm is bent. Flip bolts around so they don't hook on the box.				Closed	05-Aug-2026	Normal	Non PM
Murray Lawr	29-Jul-2026		790	Equipment	AT463	Hours 9464 next service due at 9764 300 hrs service Hrs 9464 Ns 9764				Closed	29-Jul-2026	Normal	Non PM
						Hours 9310 next service							

Filter:
26-Oct-26

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Slade Odden	27-Mar-2026		655	Equipment	AT463	<p>due at 9520</p> <p>Operator complained of engine codes</p> <p>Checked it out and it was for the SCR muffler</p> <p>----- Slade Odden added</p> <p>[03/27/2026 04:58 PM] --</p> <p>-----</p> <p>Brought unit into shop , got all the codes to clear except the SCR fault. Ecu 4364.01 Zeroed the soot load counter, removed the ecu and sent to triple threat diesel for programming. Removed both mufflers, took the particulate filters out, re installed</p> <p>Put in the egr blocker plates.</p> <p>Repair coolant leak off surge tank, re seal the turbo oil pressure line</p>				Closed	10-Jun-2026	Normal	Non PM

Filter:
26-Oct-26

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
						Replace one bad fan hose, r/h side, replace one bad diff lock hose on the middle axle.							
						<p>9222hrs next service at 9520hrs Found clutch material in filter, screen and on drain plug for middle axle ----- Wes DeVuyst added [11/28/2025 02:34 PM] -- -----</p> <p>**Removed and replaced middle axle** needs oil sample taken at 9270hrs.</p> <p>Serviced engine. Changed axle oils. Replaced engine remote oil filter lines. Replaced coolant line to surge tank. Changed transmission</p>							

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	28-Nov-2025		526	Equipment	AT463	filters, calibrated transmission. Removed R/H lift cylinder, resealed and replaced rod end bushing, Drilled for grease fitting. Changed hydraulic oil, changed hydraulic tank breather filter. ----- Wes DeVuyst added [12/01/2025 09:40 AM] ----- Installed box heater Installed fitting for L/H lift cylinder				Closed	02-Dec-2025	Normal	Non PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Stephen Bro	19-Dec-2025		449	Equipment	AT463	Hours 9187 next service due at 9329 Tail gate on the box needs repair Tail gate anchor arms for the chains arnt heavy enough.				Closed	21-Dec-2025	Normal	Non PM
Wes DeVuys	03-Oct-2025		440	Equipment	AT463	9169hrs next service at 9329hrs Pedestal for tail gate chain broken ----- Wes DeVuyst added [10/02/2025 01:05 PM] -- ----- Removed old pedestal installed pedestal taken off from unit in yard.				Closed	06-Oct-2025	Normal	Non PM
Ayden Neufe	27-Sep-2025		435	Equipment	AT463	9165 Welded tailgate bracket back on left side for chain Fixed air seat inflation issue				Closed	29-Sep-2025	Normal	Non PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	06-Sep-2025		389	Equipment	AT463	9025hrs next service at 9325hrs Service engine ----- Wes DeVuyst added [09/06/2025 11:32 AM] -- ----- Service engine. Checked codes/cleared. Adjusted body position sensor. Replaced R/H turn signal bulb. Checked engine air filter was clean/very little hours on it, blew it out.				Closed	08-Sep-2025	Normal	Non PM
Murray Lawr	22-Jul-2025		286	Equipment	AT463	Hours 8894 ns 9066 Replaced broken ground speed radar on frame				Closed	22-Jul-2025	Normal	Non PM
Slade Odden	17-Jul-2025		275	Equipment	AT463	Hours 8884 Complaints of seat not working properly. Replaced the failed seat shock, test.				Closed	18-Jul-2025	Normal	Non PM

Filter:
26-Oct-26

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Murray Lawr	24-Jun-2025		229	Equipment	AT463	<p>Hours 8776</p> <p>Complaints of air conditioning not working very well.</p> <p>----- Slade</p> <p>Odden added [06/24/2025 07:25 AM] --</p> <p>-----</p> <p>Blew out rads, they were very dirty.</p> <p>Replaced the reciever dryer.</p> <p>When pulling out the evaporator to clean it, it got damaged .</p> <p>New evaporator on order.</p> <p>-----</p> <p>Murray Lawrence added [06/24/2025 05:22 PM] --</p> <p>-----</p> <p>Installed new evaporator</p> <p>Vacuumed system for 30 mins</p> <p>Recharged to 5.7 pounds</p>				Closed	30-Jun-2025	Normal	Non PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	11-Jun-2025		209	Equipment	AT463	Hrs8766 next service 9066hrs Ayden found fan tensioner really stiff/siezed ----- Wes Devuyst added [06/10/2025 02:40 PM] -- ----- Changed fan tensioner Changed engine oil 8766hrs ns 9066hrs				Closed	11-Jun-2025	Normal	Non PM
Ayden Neufe	05-Jun-2025		190	Equipment	AT463	8733hrs 8801ns Smoked compressor clutch off on A/C Installed a new A/C compressor ----- Ayden Neufeld added [06/05/2025 09:06 AM] -- ----- Compressor replaced Vacuumed system and charged				Closed	06-Jun-2025	Normal	Non PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Wes DeVuys	14-May-2025		134	Equipment	AT463	Hours 8611 next service due at 8801 Fire ext Feb 2026 Wiring for the rear frame controller is broken The hoses are in poor condition as well Replaced the wiring for the Rear frame controller Replaced the poor hoses for the rear frame hydraulics Replaced the left hand fan hydraulic motor Do a software update				Closed	19-May-2025	Normal	Non PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
Slade Odden	28-Apr-2025		118	Equipment	AT463	Hours 8504 next service due at 8801 Fire ext The hoses in the articulation joint need to replaced. The wiring harness is poorThe harness is ordered. Serviced the engine 15/40				Closed	27-Apr-2025	Normal	Non PM
Slade Odden	08-Mar-2025		67	Equipment	AT463	Hours 8295 next service due at 8517 Check over Found the oil drain hose on the oil pan to be leaking Drain the fuel tank Removed the DEF tank Removed the fuel tank replaced the hose for the oil pan drain Replaced the def tank and the fuel tank Filled with fuel Build a guard for the auto greaser lines ----- ----- -----				Closed	14-Mar-2025	Normal	PM

Assigned To	Scheduled Date	Due Date	WO #	Entity Type	Entity Name	Problem Description	Job	WO Job	Location	Status	Status Date	Priority	Type
						PM 1 - 300 Hr Do check list Take oil samples Oil Change Inspection Lube Fill the auto greaser if equiped							