



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

R&B Trucking Inc
4780 Frank Kenny Road
Ottawa, ON K0A 3H0
Mobile: (613) 229-3851
rbacnting@gmail.com

2005 Kenworth T800 Base (#KW-05)

VIN: 1XKDDU9XX5J980145
License Plate: 5811PR
Mileage In: 330,576 km
Mileage Out: 330,576 km

DIESEL FUEL			
Description	Price	QTY	Subtotal
Part: DIESEL FUEL	\$1.85	110	\$203.50
Shop Supplies (4%): \$8.14		HST (13%): \$27.51	Total: \$239.15

INSPECTION OF UNIT	
Total: \$352.56	

DIAGNOSTIC SCAN	
Total: \$99.89	

BOOST PRESSURE				
Description	Price	QTY	HRS	Subtotal
Labor: Inspection identified a boost leak at the precoolers outlet elbow O-ring, as well as additional boost leaks at the turbocharger charge-air side flex pipes and clamps. Connected pressure tester to verify extent of leaks. All boost leaks must be repaired before any further diagnostics can be performed accurately.			9	\$1,350.00
Upon removal of all components, it was found that the lower precoolers mounting hardware had broken off inside the precoolers mount. The failed mounting hardware is the root cause of the turbo flex pipes cracking due to excessive movement and flexing.				
To complete the repair, the broken mounting bolts were welded to and extracted from the lower precoolers mount. After removal, the original threads were found to be excessively damaged due to the bolts remaining broken for an extended period.				
The damaged mounting holes were drilled and re-threaded to accept larger mounting bolts. The precoolers was then temporarily installed to verify proper hole alignment and mounting position. Once fitment was confirmed, all previously removed components were reinstalled, and the precoolers was mounted for final installation after all turbo flex joints were properly aligned and adjusted.				



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

BOOST PRESSURE				
Part: HOSE-HUMP DBL 4"X6" Part #: HE8716	\$56.56	4		\$226.24
Part: CLAMP-HOSE T BOLT Part #: F16-6009031B413SB0 CLAMP-HOSE T BOLT	\$23.44	8		\$187.52
Part: EXHAUST BELLOWS Part #: 233-8004	\$684.48	1		\$684.48
Part: CLAMP V BAND Part #: 241-2634	\$52.73	3		\$158.19
Part: CLAMP TURBO Part #: 283-2381	\$52.81	1		\$52.81
Part: EXHAUST BELLOWS Part #: 243-2531	\$745.83	1		\$745.83
Part: O RING Part #: U10776	\$13.99	1		\$13.99
Shop Supplies (4%): \$136.76 HST (13%): \$462.26 Total: \$4,018.08				

AIR FILTER				
Description	Price	QTY	HRS	Subtotal
Labor: Replaced engine air filter as original was damaged and not able to be reinstalled.			0.25	\$37.50
Part: FILTER-AIR Part #: AF1968MFLG	\$93.74	1		\$93.74
Shop Supplies (4%): \$5.25 HST (13%): \$17.74 Total: \$154.23				

DIAGNOSTIC CONNECTOR				
Description	Price	QTY	HRS	Subtotal
Labor: While attempting to connect to the truck for diagnostics, communication could not be established. Inspection found the fuse supplying the diagnostic connector to be blown. The fuse was replaced, restoring power to the diagnostic connector. The ELD also regained power, as it is supplied by the same fuse.			1.25	\$187.50
Part: FUSE Part #: 731.1301	\$3.73	1		\$3.73
Shop Supplies (4%): \$7.65 HST (13%): \$25.85 Total: \$224.73				

CLUTCH ADJUSTMENT				
Description			HRS	Subtotal
Labor: Performed clutch adjustment.			1	\$150.00



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

CLUTCH ADJUSTMENT

Shop Supplies (4%): \$6.00 HST (13%): \$20.28 **Total: \$176.28**

P/S DOOR NOT STAYING CLOSED

Description	Price	QTY	HRS	Disc	Subtotal
-------------	-------	-----	-----	------	----------

Labor: Passenger door will not stay closed, inspected door and found door latch will not stay in locked position. Door latch will require replacement and inspection of door handles done when door panel is removed for latch installation. With interior door panel removed, release hinge for interior handle is stiff and not returning to correct position. Removed and freed up unit before reinstallation, reinstalled and confirm that all cables and latches operate correctly.			10	\$450.00	\$1,050.00
--	--	--	----	----------	------------

Part: LATCH DOOR CAB LOCK RH	\$225.93	1			\$225.93
------------------------------	----------	---	--	--	----------

Part: SEAL CAB DOOR	\$260.07	1			\$260.07
---------------------	----------	---	--	--	----------

Part: HINGE	\$616.20	1			\$616.20
-------------	----------	---	--	--	----------

Part: FREIGHT	\$45.00	1			\$45.00
---------------	---------	---	--	--	---------

Discount (17%): \$450.00 Shop Supplies (4%): \$87.89 HST (13%): \$297.06 **Total: \$2,582.15**

VALVE ADJUSTMENT

Description	HRS	Subtotal
-------------	-----	----------

Labor: Performed valve adjustment and verified correct jake brake adjustment.	3.5	\$525.00
---	-----	----------

Shop Supplies (4%): \$21.00 HST (13%): \$70.98 **Total: \$616.98**

OIL TEMP GAUGE

Description	Price	QTY	HRS	Subtotal
-------------	-------	-----	-----	----------



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

OIL TEMP GAUGE

Labor: Oil temperature gauge related to sensor in oil pan possibly, more diagnostic required. 3 \$450.00

Compared resistance values to new sensor before replacement and found both to be in spec. Inspected connector and found pins to be spread and have poor contact with sensor terminals. Replaced with new pigtail and pins, ran unit and confirmed sensor operation by watching oil temp reading on gauge during road test.

Part: SENSOR OIL TEMPERATURE	\$163.11	1	\$163.11
Part: CONNECTOR SHELL CAVITY	\$7.15	1	\$7.15
Part: TERMINAL	\$2.29	2	\$4.58
Part: SEAL	\$3.13	2	\$6.26

Shop Supplies (4%): \$25.24 HST (13%): \$85.32 **Total: \$741.66**

BRAKE CHAMBER

Description	Price	QTY	HRS	Subtotal
Labor: Replaced front right drive axle brake chamber due to having broken spring on parking side. Aired unit up and verified no leaks.			1	\$150.00

Part: CHAMBER 3030 COMBO W CLEVIS Part #: SB3030CC	\$77.93	1	\$77.93
---	---------	---	---------

Shop Supplies (4%): \$9.12 HST (13%): \$30.82 **Total: \$267.87**

DUST SHIELD

Description	Price	QTY	HRS	Subtotal
Labor: Replaced steer axle drivers side dust shield.			1.5	\$225.00
Part: DUSTSHIELD	\$137.68	1	\$137.68	
Part: SPRING	\$6.48	1	\$6.48	
Part: GUIDE-SHOE BRAKE	\$16.75	1	\$16.75	

Shop Supplies (4%): \$15.44 HST (13%): \$52.18 **Total: \$453.53**

TRANS OUTPUT SEAL

Description	Price	QTY	HRS	Subtotal
Labor: Replaced transmission output seal and housing gasket. Upon removal, found tone wheel assembly to have groove cut into sealing surface and required replacement. Replaced with new tone wheel and installed all new seals and gaskets. Installed driveshaft with new strap kit.			3	\$450.00



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

TRANS OUTPUT SEAL

Part: KIT OIL SEAL	\$88.59	1	\$88.59
Part: EXCITER RING	\$93.77	1	\$93.77
Part: FREIGHT	\$25.00	1	\$25.00
Part: STRAP KIT	\$36.99	1	\$36.99
Part: 75W90 BULK	\$16.54	4	\$66.16

Shop Supplies (4%): \$30.42 HST (13%): \$102.82 Total: \$893.75

TORQUE RODS

Description	Price	QTY	HRS	Subtotal
Labor: Replaced front drive axle torque rods.			4	\$600.00
Part: TORQUE ROD	\$430.52	2		\$861.04
Part: 5/8-11X4 UNC HEX BOLT GR8 YZ	\$2.11	4		\$8.44
Part: 5/8-11X5 UNC HEX BOLT GR8 YZ	\$2.50	4		\$10.00
Part: 5/8-11 UNC STOVER LOCKNUT GRC ZN	\$0.44	8		\$3.52
Part: SAE FLT WASHER F436 YZ 5/8	\$0.24	16		\$3.84

Shop Supplies (4%): \$59.47 HST (13%): \$201.02 Total: \$1,747.33

REPLACE KING PIN CAPS

Description	Price	QTY	HRS	Subtotal
Labor: Replaced missing king pin cap on DR side of unit			2	\$300.00
Part: KING PIN CAP	\$34.34	1		\$34.34

Shop Supplies (4%): \$13.37 HST (13%): \$45.20 Total: \$392.91

AIR LEAK

Description	Price	QTY	HRS	Subtotal
Labor: Aired up unit to pull out of shop. Heard audible air leak. Inspected unit and found quick release valve leaking located at drivers side frame rail behind cab. Fabricated new mounting bracket as old bracket was rotten off. Replaced valve. Aired up unit again and verified repair.			2.5	\$375.00
Part: VALVE QR	\$83.58	1		\$83.58
Part: 3/8 PIPE TO 1/2 HOSE	\$7.99	2		\$15.98
Part: 1/2 FEMALE TO 3/8 FEMALE	\$6.58	2		\$13.16
Part: 1/2 PIPE TO 5/8 HOSE	\$9.34	2		\$18.68
Part: 3/8 NIPPLE	\$3.59	1		\$3.59
Part: 3/8 TEE	\$10.19	1		\$10.19



Wyss Diesel Inc
14245 Concession 10-11 Road
Crysler, ON K0A 1R0
(613) 518-9977
service@wyssdiesel.com
wyssdiesel.com
HST# 711287102 RT0001

Invoice #5888

Created: 07/10/2026 at 11:10AM
Invoiced: 08/13/2026 at 2:02PM
Payment Term: On Receipt
Payment Due: 08/13/2026
Service Writer: Kaelin Bachelder

AIR LEAK			
Part: 3/8 TO 3/8 90 ELBOW	\$5.60	1	\$5.60
Shop Supplies (4%): \$21.03		HST (13%): \$71.09	Total: \$617.90

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. There is no warranty for used parts or customer supplied parts. Please contact us promptly if you have any questions about anything we did.

Signature _____

Labor	\$6,685.00
Parts	\$5,319.64
Subtotal	\$12,004.64
Discount	\$450.00
Shop Supplies	\$462.18
EPA	\$0.00
HST	\$1,562.18
Grand Total	\$13,579.00
Paid to Date	(\$0.00)

REMAINING BALANCE	\$13,579.00
--------------------------	--------------------