

VEHICLE MAINTENANCE LOG

Rego
YEAR 2001
TYPE Tipper Truck
MAKE Mack Trident
MODEL CLS07A
VIN/CHASSIS NO. 6FMS24E27A1B07082
ENGINE NO. 5529M81250570

DATE OF SERVICE	SERVICE/MAINTENANCE DESCRIPTION	PERFORMED BY
1.7.13	Blue slip inspection. Find and repair fuel leak at #6 EUP. Remove injector line and wiring. Remove EUP, clean and change o'ring. Check jack shaft between diffs damaged. Repair electric malfunction light on dash. Mack C Service. Drag link ball joint worn at rear of drag link. Fix oil leak front of diff pinion seal. Torque rodd bush worn out rear diff rod in front of torque rod. Replace missing reflectors. fix lights as discussed. Fix air leak at tailgate. Fix air leak in drivers seat. Fix seatbelt N/S. Wiper blade replaced N/S	Southern truck centre wollongong
6.7.13	Service call, supply and fit new led beacon, ew led work lamp and connect to reverse circuit, repair mirror lights and check all lights.	Electri-Cool Auto Electrical Services
16.7.13	Service call to fit and supply new main ignition solenoid	Electri-Cool Auto Electrical Services
10.2.14	Service call - diagnose blown ignition fuse due to short at pto buzzer	Electri-Cool Auto Electrical Services
13.4.14	Replace brake shoe kits, fit new brake drums and hub seals	rapid truck repairs
8.5.14	Engine Service, oil and fuel filter. Remove and replace intake pipe and pressure test hose. replace exhaust clamp under DS door. Remove and replace fan belt tensioner INOP and fan belt worn. Remove and replace diff breathers blocked.	Southern truck centre wollongong
2.7.14	Service and inspection for registration	Southern truck centre wollongong
3.7.14	check hi-beam circuit, supply and fit new relay, remove all headlamps. Supply and fit 4 new headlamp inserts and 4 new h4 globes and check operations	Electri-Cool Auto Electrical Services
29.7.14	Rectify engine warning light on	Southern truck centre wollongong
5.8.14	fault code on dash. Inspected and tested wiring. All good. Removed and replaced throttle pedal and tested	Southern truck centre wollongong
10.8.14	YEARLY SERVICE	Tri Clark Brothers
5.1.15	supply and fit new small led beacon	Electri-Cool Auto Electrical Services
25.2.15	YEARLY SERVICE	Tri Clark Brothers
28.4.15	Supply and fit new 39mt startermotor and check	Electri-Cool Auto Electrical Services
24.6.15	Supply and fit new H/D batteries, clean fuse and relay box for reverse circuit and diagnose faulty switch	Electri-Cool Auto Electrical Services
19.12.15	Diagnose faulty master switch, supply and fit new master switch and lock out	Electri-Cool Auto Electrical Services

25.1.16	Change input shaft, bearing and install gearbox	tcb
4.2.16	Check exhaust brake problem, due to charging problem, supply and fit new alternator and re-check	Electri-Cool Auto Electrical Services
20.6.16	Replace 8 x rear radius red bushes. Replaced 3 x rear torque rod bushes. Full Steam Clean. Greased. Adjust brakes. LH head light replay replace. LH Rear sterr mud flap replaced. Weld RHF rear spring hangers back on. Paint chassis and spril areas. Replaced LH spotter mirror and mirror and mirror. Fixed earth on RH middle body light. Fixed number plate light and earth. Fixed LHR reverse light, full of water. Exhaust stack hole replaced clamp. Resecured RHR Mud flap. Cable tie loose hoses, wires. Replaced rear red reflectors. clean out air tanks and check ADR35. Replace RH Fuel tank rubbers.	Noel and Neville TCB
1.7.16	Clean out trailer plug fitting. Move number plate light. Removed stick off back of truck. Repair air leak RUF drive booster. Cleanout cabin.	noel TCB
6/07/16	draglink assembly, king pin kit, pair, tie rod end L/H R/H	multispare
7/07/16	jake solenoid	multispare
8/07/16	drag link assembly	multispare
11/07/16	jake brake terminal	multispare
21/07/16	rocker switch	multispare
27/07/16	jake solenoid, jake brake tune up kit.	multispare
3/08/16	SERVICE AND JAKE SPRINGS	TCB NOEL
2/03/17	YEARLY SERVICE	TCB
22/05/17	puncture repair	trend tyre power taren point
31/05/17	Replaced L/H/R wheel stud, lock tightened in and torqued wheel. Replaced drivers seat air lines x 3, one still to be replaced, waiting on parts.	nev tcb
13/09/17	Supply and fit muffler, flex, elbow, clamps and raincap to exhaust on mack tipper	Tony Mufflers
14/08/17	Replaced mirror air cleaner top supports rusted away, new parts and reused and repaired some old parts	nev tcb
6/02/18	Fit new suspension stops to rear axle	TCB
24/04/18	Carry out major service. Replace coolant	TCB
15/06/18	Supply and fit new marker lamp on mirror, repair number plate lamp circuit, supply and fit H4 headlight globe and repair connection problem and check	Electri-Cool Auto Electrical Services
19/06/18	L/H rear steer shackle spring pins and bushes new steer springs rear clamp, weld. Steer front spring pin, get grease and R/H lock pin weld. R/H/F slash adjuster. L/H/F drive slash adjuster washer cir dip. Air tank shuttle valve /one way valve. Tail shaft front shaft. 3x unis/ 1x centre bearing, rear yoke front diff loose and seal. Top radiator hoses x2 coolant	TCB
22/06/18		TCB
23/08/18	Power steering hose replaced	Mobile Hosefixers
5/10/18	Replaced clutch brake & adjusted (hrs 650078)	tcb
24/01/19	Changed radiator, water pump, coolant, fan belts	TCB

11/01/19	Top up A/C and check cooling, rectify and repair connection for R/Left combination lights. Pressurise A/C system, diagnose leak at pressure switch. S/F new pressure switch, remove condensor fan motor and repair.	Electri-Cool Auto Electrical Services
2/02/19	Check , test and diagnose faulty wipermotor and remove.	Electri-Cool Auto Electrical Services
6/02/19	New Tyres	Helensburgh Tyres
18/02/19	Clean and blow out evaporator and fan unit, top up A/C and check cooling	Electri-Cool Auto Electrical Services
7/05/19	supply & fit new H4 Headlight globe on MACK	Electri-Cool Auto Electrical Services
26/07/19	Oil and filter, coolant filter, gearbox filter, clean air filter, grease/adjust clutch and brakes, replace L/H front hub eye glass and topped up both oils, replaced PTO controls and spoil	TCB Nev
22/02/20	Spring assembly, pin spring shc, pin sprin sha, seal - oil, oil seal	Southern truck centre wollongong
22/02/20	Remove and replace front left leaf spring	TDC Plant Maintenance
16/04/20	Brake drum, seal, bearing set, cam shaft, cam repair kit, slack adj manual	multispares
16/04/20	New drum/brakes, wheel bearings, S-cam and bushes, slack adjuster, adjust all brakes, topped up front hubs (leaking)	TCB Nev
24/04/20	Seal hub, gasket	multispares
7/07/20	R/R front hub seals and wheel bearings both side, fill hub oil and adjust brakes	TDC Plant Maintenance
9/07/20	Engine service	TDC Plant Maintenance
13/07/20	New tarp	Cramaro Enviro Tarping Systems
14/07/20	R/R front hub seal left side, replace brakes and reassemble	TDC Plant Maintenance
6/10/20	Filter kit - Mack E7 centrimax	multispares
5/11/20	Filter kit	multispares
23/11/20	Repair Tarp frame	TCB
30/11/20	Strip and fit truck tyre	Helensburgh Tyres
24/02/21	Fix trident blinkers	TCB
5/05/21	Strip and fit truck tyre	Helensburgh Tyres
6/05/21	Air breather filter, air filter, fuel filter	multispares
6/05/21	Repair drivers door handle	TCB
6/05/21	Repair windscreen washer hose	TCB
7/05/21	Carried out service. Spent extra time to get grease into points that wouldn't take grease. Repair engine oil leak from centroful filter	TCB
8/05/21	Diganose faulty switch on reverse lights	TCB
8/05/21	Tighten hose fittings at bottom of power steering reservoir	TCB
10/05/21	Service - General check over grease, brakes adjust oil & air filter change, moisture filter replaced. Lights all checked. Tightened shocks RHS 1st drive & 2nd drive	TCB
28/05/21	Returned - gasket (shift lever housing), 6 bolt gasket kit	multispares
31/05/21	Prepare gearbox to be removed	TCB Mitch
1/06/21	New clutch, machine flywheel, Replace crossover shaft and bushes	TDC Plant Maintenance
1/06/21	Remove and replace both rear engine mounts	TCB
2/06/21	MV3 Park brake control	multispares
2/06/21	Remove power yoke and replace yoke seal. Refitted yoke with new washer and nut. Rechecked front diff oil levels - all good. Replace intercooler bolt	TCB

3/06/21	Install clutch and gearbox. Replace clutch cross shafts and bearing bushes	TDC Plant Maintenance
3/06/21	Transmission pinion/gasket/shaft, ball bearing, gasket, oil seal, plug, needle roller bearing, switch	Southern truck centre wollongong
4/06/21	Transmission gasket, Bulldog gearbox oil, kit B/ring strap	Southern truck centre wollongong
7/06/21	Speed monitor	Southern truck centre wollongong
7/06/21	Fault light on dash, no power. Inspected for problem, found speedo not working. Removed speedo sensor inspected - seemed fine. Refitted speed sensor and adjusted. Took for road test - all good	TCB Mitch
7/06/21	Repair air leak behind dash. Replaced park brake valve	TCB Mitch
8/06/21	Remove and replace front engine mount	TCB Mitch
8/06/21	Reverse lights not working. Found two reverse switches in top of gearbox, swapped the 2 switches over - rechecked operation - all good	TCB Mitch
8/06/21	degreased and washed. Fitted reflective tape. Adjusted drivers door to open and close properly.	TCB Mitch
8/06/21	Assess and repair power issue	TDC Plant Maintenance
9/06/21	Repair air leak under cab for low range airline to gear box	
11/06/21	Grind flywheel	Southern Engine Reconditioning
16/06/21	Adjust door closing, diagnose warning light inoperable	TCB Mitch
17/06/21	Checked engine oil level and topped up	TCB
18/06/21	Pressure switch	Southern truck centre wollongong
18/06/21	Kit seal	Southern truck centre wollongong
18/06/21	New registration plates - XO63AU	RMS
18/06/21	Inspect for defects, change licence plates, R/R park brake switch	TCB Mitch
25/06/21	Seal pinion input	Southern truck centre wollongong
29/06/21	Pinion seal	multispares
2/07/21	Refill wiper	Napa
20/07/21	Lock Handle & Hinge	Southern truck centre wollongong
23/07/21	R/R door handle	TDC Plant Maintenance
9/09/21	Filter kit	Southern truck centre wollongong
13/09/21	Retainer	Southern truck centre wollongong
13/09/21	Service - carried out service replaced filter kit fuel + oil. Replaced oil 32l, greased and checked over.	TCB Mitch
15/09/21	Globe H4 12V 60/55w Halogen Plus30	multispares
15/09/21	Fixed mirror clearance lights that were not working, replaced globes to get lights working. Repaired body marker lights on LHS. R&R wiper blades. Remove and replace axle 2 RHS slack adjuster & axle 3 LHS slack adjuster	TCB Mitch
28/09/21	Headlight inoperable LHS. Removed & replaced headlight globe. R/R missing intercooler bolt bottom RHS & fitted fiber washer between intercooler and bracket.. Checked boost pressure - all good	TCB Mitch
3/03/22	Window winder handle - removed and replaced drivers side window winder handle	Top Dead Mechanical
7/04/22	Replaced drivers window winder regulator	Top Dead Mechanical
11/04/22	Job: Grease and Brake Adjust Carried out grease brake adjust	Top Dead Mechanical

1/06/22	pre-rego inspection - carried out inspection and noted down list of repairs, carried out grease and brake adjust	Top Dead Mechanical
30/05/22	screws, washer, packing, holder	Mack
30/05/22	seal door - returned	Mack
11/04/22	support, window regulator, sealing compound	Mack
13/04/22	seal door	Mack
23/05/22	bracket, hinge, screw, packing, washer, holder	Mack
14/06/22	Drain tap fitting, rear brake relay valve replace	Top Dead Mechanical
20/06/22	bearing set cone and cup x 2	multispares
20/06/22	cr standard seal - tool fit + brake drum, drive axle gasket + gasket hub cap	multispares
16/06/22	Fixed RHS mirror light, Torqued LHS mirror bracket	Top Dead Mechanical
25/06/22	Fixed L/H tail light	BSC Auto Electrical
30/06/22	3 1/2 raincap zinc plated	multispares
25/07/22	Air filter	multispares
27/07/22	Check valve SC3 1/2" M&F + 1/2 x 1/2 swivel male elbow + adaptor 1/4 NPSF	multispares
29/07/22	oil seal	Southern truck centre wollongong
29/07/22	compressed-air tank + valve cable drain + valve	Southern truck centre wollongong
1/08/22	M12 thrust washer o ring + M22	multispares
1/08/22	GP Fitting	multispares
6/09/22	Welding parts on tailgate	TCB
27/9/22	filter kit	Southern truck centre wollongong
27/9/22	checked service history and moved truck on to pit and organised parts	TDC Heavy Mechanical
28/9/22	carried out service replacing engine oil, engine oil filter, fuel filters and air cleaner filters, then carried out grease and brake adjustment and checked over	TDC Heavy Mechanical
30/09/22	job: broken indicator stalk. replaced leaking brake booster on axle 3 l/h/s	TDC Heavy Mechanical
28/09/22	spring brake champter type 30/30 sealed	multispares
11/02/22	job: noise from rear. Checked over for reported noise, took for drive then check over rear end brakes and suspension, found everything all good and unable to find noise.	TDC Heavy Mechanical
28/9/22	switch, turn signal	Southern truck centre wollongong
10/02/23	Welding parts on tailgate	TCB
23/12/22	supply and fit squaker to truck	BSC Auto Electrical
12/01/22	balance bag - Kapsen 2958022 steers	Helensburgh Tyres
13/02/23	Front spring pin falling out RHS axle 1, removed realigned and refit, refit pinch bolt and grease pin.	TDC Heavy Mechanical
14/02/23	Grease and brake adjustment, fitted new pinch bolt	TDC Heavy Mechanical
15/02/23	Removed and replaced slack adjuster, replaced missing mud flap, tighten ac belt	TDC Heavy Mechanical
16/02/23	Service truck. Oil/filters, Grease, brake /clutch adjust. Replace rear diff oil	ROC Plant and Maintenance
26/02/23	Steer box rebuilt	ROC Plant and Maintenance
25/2/23	steering filter - paper type	multispares
16/2/23	repair wiring for RH clearance lights, replaced high beam and low beam globe and 2 roof light globes, and repair wiring on both mirrors for lights	BSC Auto Electrical
25/02/23	steering filter - paper type	multispares

22/05/23		
23/05/23	adjusted tarp operation as LHS getting stuck, tested and all ok	TDC Heavy Mechanical
14/03/23	4mtr mesh replacement, electric conversion kit	Cramaro Enviro Tarping Systems
31/03/23	Haulstar 1122.5 145/145 HD368 Drive	Helensburgh Tyres
6/06/23	minor prime mover service	ROC Plant and Maintenance
6/06/23	replace engine oil and filter, fuel filter, air filter, diff oil, inspect transmission oil level, inspect brakes and tyres	ROC Plant and Maintenance
13/06/23	check valve SC3 1/2" M&F + 1/2 x 1/2l male elbow	Multispares
9/06/23	Valve	Southern truck centre wollongong
13/06/23	replaced leaking air switches for inner axle lock and cross locks, carried out pre rego inspection	TDC Heavy Mechanical
14/06/23	replaced check valve on air tank	TDC Heavy Mechanical
21/06/23	shackle pin front of front, bush - shackle/spring, drain tap	Multispares
21/06/23	coupling duomatic female & male	Multispares
22/06/23	coupling duomatic female	Multispares
22/06/23	repair parkers, replaced LH door mechanism	BSC Auto Electrical
25/06/23	replace front spring eye bushes, replace duo couplings for trailer connection	ROC Truck and Maintenance