

Vehicle History Summary

Tri Clark Brothers Pty Ltd

Fleet #	
Registration	
Make	Mack
Model	CLS07A
VIN / Chassis	6FMS24E27A1B07082
Build Date	2001

Number	Date	Usage	Type	Repairer Notes	Repairer
S-382			B - 10k		
S-347	2026-07-25		C - 60k	Serviced with last rego check.	Neville Scott
O-74	2026-06-24	0	Registration		
R-683	2026-06-11	0	Defect Notice	Removed drivers and passenger sides glass tint to self clear defect.	Neville Scott
				Pre rego and service. ... Changed engine oil and filters. ... Changed fuel filters. ... Changed coolant filter. ... Changed gear box air filters. ... Cleaned air filters and replaced dust canisters. ... Re- sealed top oil cooler orings x7. ... Replaced front drive axle 30/30 boosters. ... Replaced electric horn. ... Replaced reverse gear box switch. ... Cleaned out adr35 shuttle valve. ... Replaced air tank drain valve. ... Adjusted brakes and greased. ... Steam cleaned ... Freed up ring feeder.	Neville Scott, Travis Clark
S-326	2026-06-05		B - 10k		
R-682	2026-06-04	0	Fault	replaced reverse switch	
R-568	2026-05-26	0	body Repair	Neville Investigated and found that this fault was fixed by Trav. Unsure of Details- Ash	
R-558	2026-05-26	0	Auto	Neville Investigated and found that this fault was fixed by Trav. Unsure of Details- Ash	
R-601	2025-07-28	0	Engine	... Replace rear engine mounts. ... Replace A/C main bolt and nut.	Neville Scott
				front shackle pins back in with locknut. grease, brake adjust, repair coolant leak from compressor line, repair headlight, replace rear marker plates and reflectors, repair crossover brackets, repair washer jets and lines, replace floor in battery boxes, reline axle 2 L/H, replace SR1 and pressure protection valves.	Neville Scott, Travis Clark
R-582	2025-06-20	0	Pre rego check		
O-39	2025-06-01	0	Registration		
R-560	2025-05-16	0	Auto		
R-330	2025-03-13	0	Auto		
R-230	2024-05-13	0	Steering	Replaced steering column and top bearing with new ones from mack, aligned and greased.	Neville Scott
R-218	2024-05-13	0	Lights		Bailey Cooper
				10k yearly service. 1... Refitted right hand front shackle pin and welded stop bolt back on. 2... Front right tyre low tread will be going to johnys tyres after oit job. 3... steering shaft and top bearing excessive movement, ordering from mack. 4... Made dash switches top back plate was broken. 5... Changed front steer hub oil was dirty.	Neville Scott
S-142	2024-05-03		B - 10k		
R-181	2024-04-08	0	Body	see attached mechanic notes	Neville Scott
R-156	2024-03-20	0	Tyres	Helensburgh tyres strip and fit Truck Tyre	
R-89	2024-03-04	0	welding		Chris Trigg
R-133	2024-02-26	0	Auto		