

03985261

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
A936044

Date Inspection Started

03

11

25

DAY

MO.

YR.

Date Inspection Completed

13

11

25

DAY

MO.

YR.

Inspection Expiry Date

DAY

MO.

YR.

Station Number

A2089

Station Name

Integrity Ventures Steinbaum

City

Mechanic Number

M193176

Mechanic Signature

Station Phone Number

(204) 320-9695

Vehicle Owner

Ken Hovord

Address

106339 Viscount Dr. Red Deer AB T4B 0S2

City

Red Deer

Province

AB

Postal Code

T4B 0S2

Phone

(204) 392-3327

☒ Pass/Safe Vehicle

☐ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number

C1JN926

Prov.

MB

NSC #

-

Odometer Reading

2,140,670

Odom. Type

☒ km ☐ mi

Vehicle Identification Number

4V4UN69E49JN88883T

Make

Volvo

Model

VNL

Year

2018

Unit #

95901

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck

GVWR

KGS

Truck Tractor

Trailer

Semi-Trailer

Bus

School Bus

Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
		Section 1 - Power Train: Defects (if any) Exhaust stack pipe loose - 2E Engine oil leak present at the oil separator (level 3) - 2H A2 input shaft seal leaking (level 2) - 4H																																																																						
X	X	Section 2 Suspension: Defects (if any) A2 left shock leaned empty - 7C																																																																						
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Air leak present with the fifth wheel slide release cylinder engaged - 13E Air leak present - 13E A1 and A2 right/left, and A3 left brake rotors fail for wear - 18C A3 left brake adjuster seized/stripped (caliper replacement required) - 18D-i																																																																						
X	X	Section 4 - Steering: Defects (if any) Steering shaft joint worn - 1K																																																																						
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) Both cab signal lights moisture present - 1A Front left signal light not amber - 1A																																																																						
X	X	Section 7 - Electrical System: Defects (if any) Battery hold-down loose - 2a																																																																						
X	X	Section 8 - Body: Defects (if any) Both hood splash shields loose - 21A Cab levelling valve rod worn - 3E Left cab shock loose - 3F																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any)																																																																						
X	X	<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>13</td><td>15</td><td></td><td></td><td>95</td><td>95</td><td>110</td><td>110</td></tr><tr><td>2</td><td>8</td><td>8</td><td>10</td><td>10</td><td>95</td><td>95</td><td>100</td><td>100</td></tr><tr><td>3</td><td>8</td><td>8</td><td>16</td><td>16</td><td>95</td><td>95</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	13	15			95	95	110	110	2	8	8	10	10	95	95	100	100	3	8	8	16	16	95	95	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	13	15			95	95	110	110																																																																
2	8	8	10	10	95	95	100	100																																																																
3	8	8	16	16	95	95	100	100																																																																
4																																																																								
5																																																																								
X	X	Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Section 3 continued: A3 right caliper slider pins seized (caliper replacement required) - 18D-i A2 left brake pad material separated - 18F-i-vii A2 left caliper slider pins worn (caliper replacement required) - 18D-iv

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: