

B39-2
NOV



SHOP REPAIR SHEETS



START DATE: 08/17/2026

HOURS:

UNIT #: LSB-3 - Lead Super B Tridem Trailer

KMS:

MAKE/MODEL: Hi boy

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

Axle 1 p.s shock mount

Description of work done	Vendor	Part #
Weld axle 1 p.s shock mount	Shop	

END DATE: 08/17/2026

Notes:

Mechanic:

Curtis Smigelski

SIGNATURE:



DEFICIENCY REPORT

Report Date: 08/11/2026

Make: Black lead

Model: Black lead

Unit Number: ^{LSB-3}~~882~~ Lead Super B
Tridem Highboy

Hours:

KMS:

Next Service:

Deficiency: Axle #1 P.S bottom shock mount broken

Person Reporting: Mark Pilon

A handwritten signature in black ink, appearing to be 'Mark Pilon', written in a cursive style.

Image:



SHOP REPAIR SHEETS



START DATE: 08/10/2026

HOURS:

UNIT #: LSB-3 - Lead Super B Tridem Trailer

KMS:

MAKE/MODEL: Hi boy

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

No lights on rear right of trailer

Description of work done	Vendor	Part #
Repair wiring at rear of trailer and replace red tail light	Shop	

END DATE: 08/10/2026

Notes:

Mechanic:

Curtis Smigelski

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 12/05/2025

HOURS:

UNIT #: LSB-3 - Lead Super B Tridem Trailer

KMS:

MAKE/MODEL: Superior

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No

If YES, Deficiency Requiring Attention Please Indicate Reported Date:

If NO, Deficiency Requiring Attention:

No lights

Description of work done	Vendor	Part #
Repaired trailer wiring for marker lights replaced light cord	Artic truck jrf	Light cord

END DATE: 12/05/2025

Notes:

Mechanic:

Ryan Macinnis

R

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/06/2025	HOURS:	
UNIT #: LSB-3 - Lead Sup or B Tridem Trailer	KMS:	
MAKE/MODEL: Altek Sup or B Train Lead Tridem Trailer	NEXT SERVICE:	
WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? No		
If NO, Deficiency requiring attention: Lock up brakes on ALL		
Description of work done	Vendor	Part #
Free up brake by backing up the slack adjuster.. smack with the han mer to the drum (still locked up), its over cammed Brought in to the shop, remove tires and drums to verify over cammed.. remove brake shoes (thin), install new brake shoes, install drums and tires, set brakes.. verify repairs by applying brakes multiple times. Torque wheels to 500 ft. Lbs and provide torque tag..	Fleet run	
END DATE: 02/06/2025		
Mechanic: Raphie Laurente		

RL

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/03/2025

HOURS:

UNIT #: LSB-3 - Lead Sup r B Tridem Trailer

KMS:

MAKE/MODEL: Log trailer

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? Yes

If NO, Deficiency requiring attention:

Description of work done

Vendor

Part #

-fixed front bunk lights replaced 2 wire
from front of trailer to junction box

N/a

N/a

END DATE: 02/03/2025

Mechanic: Jason Watson

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 02/03/2025

HOURS:

UNIT #: LSB-3 - Lead Super B Tridem Trailer

KMS:

MAKE/MODEL: Alter super b train lead

NEXT SERVICE:

WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:

Cvip plus repairs

Description of work done	Vendor	Part #
Did cvip, plus repairs. Replaced #1 axle shocks, fixed rh mod ship signal light	JRF, artic	Shocks, 3 wire, butt connectors

END DATE: 02/03/2025

Mechanic: Scott Belcourt

SIGNATURE:



WORK ORDER REPAIR SHEET



START DATE:

Nov 20/24

UNIT#/MAKE/MODEL

LSB-3

HOURS

KMS

CORRECTIVE ACTIONS/COMMENTS:

- Broken Fitting above #3 axle ~~page 18~~
- Needed different fittings so it will be easier
if it breaks off in the future again

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
	(1) 3/8" straight fittings	JRF	Conner U	Nov 20/24
	(1) 3/8" fitting	Nape	↓	↓

END DATE:

Nov 20/24

HOURS/KMS

NEXT SERVICE DUE:

HRS

Supervisor Sign Off:

Conner U



WORK ORDER REPAIR SHEET



START DATE:

March 28/24

UNIT #

LSB3/4

HOURS/KMS

MAKE/MODEL

log trailer

CORRECTIVE ACTIONS/COMMENTS:

Found Male and Female trailer plug to be corrected
- Removed and replaced Both Male and Female trailer plugs

Work Order	Parts/Parts #	Vendor/Invoice #	Mechanic Sign Off	Sign Off Date
RTR Both male	Male trailer plugs	JRF	Connor V	
and Female trailer	Female trailer plug	JRF	Connor V.	
plugs.				

END DATE:

March 28/24

HOURS/KMS

Supervisor Sign Off: _____



Shop Repair/Work Order



Date: 01/23/24

Unit Number: LSB-3 / LSB-4

Make/Model: _____

Kilometers: 179

Hours: 1 1/2

Work Order	Parts	Vendors
air Bag & wiring	air Bag	crate
~~air~~	Duncen Box	JRF

Corrective Action Taken:

~~Rept~~ R3R air Bag #1 LH LSB-4

R3R Duncen Box LSB-3

Scot B



Shop Repair/Work Order



Date: Jan 10
Unit Number: LSB 3
Make/Model: _____

Kilometers: _____
Hours: _____

^{Part} ~~Work Order~~	^{Workorder} ~~Parts~~	Vendors
Scam	~~Arctic~~ seized	Arctic
Scam tube kit	~~Arctic~~ Scam	Arctic
	brake hardware kit	JRF

Corrective Action Taken:

Replaced .5 cam and cam Tube Pass side middle axle

B39-3
NOV



SHOP REPAIR SHEETS



START DATE: 02/04/2025		HOURS:
UNIT #: LSB-4 - Pup Sup r B Tandem Trailer		KMS:
MAKE/MODEL: ALTEK : UPER B PUP		NEXT SERVICE:
WAS THERE A DEFICENTCY REPORT ASSIGNED WITH THIS TASK? No		
If NO, Deficiency requiring attention: Cvip plus repairs		
Description of work done	Vendor	Part #
Did cvip, plus repairs. Repars done fixed lights, replaced #1 lh break shoes put torque tag in truck for driver to see, replaced #1 lh and #2 lh dust covers, tide up loose air lines, got the welder to weld steps back on for air tank cover	JRF, artic	Dust covers, lights, pigtails, 2 wire, brake shoes
END DATE: 02/04/2025		
Mechanic: Scott Belcourt		

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 01/15/2025

HOURS:

UNIT #: LSB-4 - Pup Super B Tandem Trailer

KMS:

MAKE/MODEL: Altek Super B

NEXT SERVICE:

WAS THERE A DEFICIENCY REPORT ASSIGNED WITH THIS TASK? No

If NO, Deficiency requiring attention:

Complaint- Right rear light box smashed

Description of work done	Vendor	Part #
Cut out and welded new light boxes- Jody JRF		(2) 3" red lights (1) 3 wire pigtail
Wired in lights- Connor V		

END DATE: 01/15/2025

Mechanic: Connor Vanderveen

SIGNATURE:



Deficiency Reports



Report Date Dec 11/20

Unit Number h53-4

Make _____

KMS _____

Model Super B-Short Loader

Hours _____

Next Service _____

Deficiency: Junction Box, Leveling Valve, Straighten guard

Person Reporting(please print): Richard Gordon

Corrective Action: Replaced Junction Box on pop as well as the leveling valve.

Completion Date: Dec 13/24

KMS uit

Completed By: hanten hofeme

Hours NA



WORK ORDER REPAIR SHEET



START DATE:

Dec 13/24

UNIT#/MAKE/MODEL

LSB-4

HOURS

N/A

KMS

N/A

CORRECTIVE ACTIONS/COMMENTS:

- Replaced Junction Box on pup

- Replaced leveling valve

Work Order

Parts/Parts #

Vendor/Invoice #

Mechanic Sign Off Sign Off Date

Junction Box

x1 Box

JRF

Dec 13/24

Leveling valve

x1 valve

Artic

Dec 13/24

Strengthen guard

Dec 13/24

END DATE:

Dec 13/24

HOURS/KMS

N/A

NEXT SERVICE DUE:

N/A

HRS

Supervisor Sign Off:



SHOP REPAIR SHEETS



START DATE: 01/04/2026	HOURS:	
UNIT #: LSB-4 - Pup Super B Tandem Trailer	KMS:	
MAKE/MODEL: Altek	NEXT SERVICE:	
WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No		
If YES, Deficiency Requiring Attention Please Indicate Reported Date:		
If NO, Deficiency Requiring Attention:		
Hooked up to truck and o through		
Description of work done	Vendor	Part #
Hooked up trailer to truck and went through it, plus greased	Na	Na
END DATE: 01/04/2026		
Notes:		
Mechanic:		
Scott Belcourt		

SB

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 10/28/2025	HOURS:	
UNIT #: LSB-4 - Pup Super 3 Tandem Trailer	KMS:	
MAKE/MODEL: Altek pup	NEXT SERVICE:	
WAS THERE A DEFICENCY REPORT ASSIGNED WITH THIS TASK? (Please Indicate): No		
If YES, Deficiency Requiring Attention Please Indicate Reported Date:		
If NO, Deficiency Requiring Attention: Wheel pull cvip plus repairs		
Description of work done	Vendor	Part #
Did wheel pull cvip plus repairs, fixed lights, replaced reflective tape, replaced #1RH, #2RH, #2LH s-cam, s-cam tubes and wheel seals, replaced #1RH, #2RH brake shoes, greased, torqued all tr axles put torque tag on red glad hand, and rec tags on wheels	JRF, artic	Wheel seals, s-cams, s-cam tube kits, pig tails, lights. Brake shoes
END DATE: 10/29/2025		
Notes:		
Mechanic: Scott Belcourt		

SB

SIGNATURE:



SHOP REPAIR SHEETS



START DATE: 06/23/2025

HOURS:

UNIT #: LSB-4 - Pup Super B Tandem Trailer

KMS:

MAKE/MODEL: Atek

NEXT SERVICE:

WAS THERE A DEFICIENCY REPORT ASSIGNED WITH THIS TASK? Yes

If NO, Deficiency requiring attention:

Description of work done	Vendor	Part #
Diagnose marker lights fault, remove 7wire plug and replace new plug, replace 7wire female plug from the trailer, verify repairs by testing all lights.		

END DATE: 06/23/2025

Mechanic: Raphie Laurence

RL

SIGNATURE: