Unit # RC 3

CAT D60

Mileage_____ Hrs_____ E01-16 BLUE

SERIAL #L1X1538

Date	Description of Work	Parts Costs	Labour Costs
May/13 WO#0043	Strip down and paint (new decals), remove torque and change fly wheel, install new crank seal (rear), install new lights and wire, install new amp gauge. (LEO& GILBERT) HRS 1910.3		
Nov 8-14	Install new starter. Installer 2 new batteries.		
June5/17 WO#0248	Remove stump pans & wash, check trans (not going into gear properly), check all trans filters & suction screens. Repair all oil leaks, install new winch pump, reseal mounting bracket, new gaskets & seals, fabricate new pump drive coupling (Swisco) install new hydraulic hose on trans filter to pump, test & seems all good. Reinstall stump pans & side plates. New oil in trans. (4 pails 10w-30). Pretty sure that trans wash sucking air at winch pump. 2399.0 Hrs		
Aug9/21 WO#0476	Start to disassemble unit to pull torque converter. Pulled dash and hood. Contine RC3 dissassembly of torque converter. Pulled torque converter and flywheel. Pulled drive gear and seal and installed neew seal and installed flywheel. Bolted and torqued to 150 lbs. Installed converter, valves, and hoses. Will complete next day off.		
Mar3/21 WO/0478	Complete assembly. Wait for oil. Filled trans and converter. Took unit outside and Gilber loaded it and took to plant. Installed sidepantls and tested in yard at plant. Gilbert tested unit for approx.. 1 hour and installed stump plans after and replaced leaking coupler on front of dozer.		