Unit # BTP 41 FUTURE 700 GRADER

E01-18 BLUE

SERIAL # 7-10M-180

Date	Description of Work	Parts Costs	Labour Costs
Jan/13 WO#0005	Repair starter switch, service change engine oil & check all fluids. Check cutting edges, put new cutting edges. Check lights. Service air filters, repair hyd hose, check all tire pressure, change fuel filters. Send steering valve to (Flodraulic) who sent out new ones. (GILBERT) HRS 3,902.2	477.75	
Jul/13 WO#58	Repair hyd. hose Change right side door windows (LEO) HRS 3,911.7		
Feb/14 WO#0107	Service change engine oil, changed fuel & check air filters, check all fluids, check brass guides an tandem boxes, checked all lights, check air in tires, make new gaskets for tandem boxes, change oil in transition & torque drive, change cooler lines. Brass guides check out ok. HRS 3929.2		
Mar 26/15 WO164	Wash, service, check fluids, remove drop box & trans, replace tourque seal, change oil in trans & torque		
July 22-16 WO 0213	Repair 4 speed trans new input shaft. Repair shuttle shift trans. Install exchange shuttle shift from Artec Gear. Hrs 3997		
Mar28/17 WO#0236	Remove Transmission, install new gasket, remove and install new bushing on Hyd pump. HRS 4006		