E01-45
BLUE

Unit # BTP 107

1979 GMC SIGN

Mileage_____ Hrs_____

Date	Description of Work	Parts Costs	Labour Costs
Feb17-15	CVIP, repair fuel leak at carburator. Check all lights. Install reflectors. Repair heater switch. 29726.3 kms		
OCT16/25 WO#0592	INSTALL NEWE FLAT DECK. WIRE NEW DECK. NEW BATTERY. INSTALL CARB KIT. (B&D) CVIP		