Maintenance History (All work types) - TR536
Custom Date Range: 1/1/2023 - 4/14/2026

Work Order ID	Description	Direct Labor $	Sublet Vendor Labor $	Part $	Total $	Total Labor Hrs	Status Date
56154	1 - SUNDANCE RADIO COMMUNICATIONS: CHECK RADIO	$0.00	$47.50	$0.00	$47.50	0.00	1/5/2023
56526	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	$0.00	$95.00	$0.00	$95.00	0.00	1/19/2023
56673	1 - PET AUTO BODY: REPLACE GRILL	$0.00	$930.00	$4,246.24	$5,176.24	0.00	1/25/2023
56859	1 - SUMMIT MOTORS: REPLACE VVA ACTUATOR HEAD ASSEMBLY	$0.00	$1,761.30	$0.00	$1,761.30	0.00	2/3/2023
56136	1 - CVIP 2 - SECURE SUPPLY HYDRAULIC LINE	$487.50	$0.00	$20.04	$507.54	6.50	1/5/2023
56309	1 - A SERVICE	$206.25	$0.00	$57.59	$263.84	2.75	1/16/2023
56886	1 - REPLACE TRAILER LIGHT CORD	$37.50	$0.00	$89.76	$127.26	0.50	2/10/2023
56954	1 - A SERVICE 2 - SWAP DRIVERS AND PASSENGERS SEATS	$300.00	$0.00	$13.78	$313.78	4.00	2/10/2023
57747	1 - REPAIR MARKER LIGHTS INOPERABLE 2 - CHECK ENGINE LIGHT ON	$437.50	$0.00	$217.25	$654.75	5.50	3/24/2023
57915	1 - A SERVICE	$262.50	$0.00	$40.41	$302.91	3.50	3/30/2023
58315	1 - B SERVICE	$112.50	$0.00	$0.00	$112.50	1.50	4/21/2023
58403	1 - REPAIR BROKEN CHAINS ON GATE AND REWELD BOOMER	$56.25	$0.00	$0.00	$56.25	0.75	4/27/2023
58527	1 - A SERVICE 2 - REPLACE HYDRAULIC RETURN LINE 3 - REPLACE AXLE #1 AIRLINES 4 - REPLACE AXLE #1 LEFT SIDE HUBCAP 5 - CHECK A/C	$468.75	$0.00	$435.41	$904.16	6.25	5/9/2023
62183	1 - SUNDANCE RADIO COMMUNICATIONS: REPROGRAM RADIO	$0.00	$95.00	$0.00	$95.00	0.00	12/11/2023
58845	1 - REPAIR AIR LEAK UNDER PASSENGER SIDE SEAT	$93.75	$0.00	$0.00	$93.75	1.25	6/2/2023
58892	1 - REPAIR A/C	$225.00	$0.00	$157.69	$382.69	3.00	6/8/2023
58961	1 - REPAIR AIR LEAK AT CAB AIRBAG 2 - B SERVICE 3 - REPLACE ANTENNA ADAPTER	$212.50	$0.00	$169.29	$381.79	2.50	6/12/2023
59096	1 - REPAIR A/C 2 - REPAIR DRIVERS SIDE DOOR STOP	$237.50	$0.00	$371.98	$609.48	3.00	6/20/2023
59269	1 - A SERVICE	$262.50	$0.00	$75.32	$337.82	3.50	7/4/2023
59396	1 - REPLACE HYDRAULIC HOSE	$93.75	$0.00	$1,734.77	$1,828.52	1.25	7/10/2023
59674	1 - B SERVICE	$150.00	$0.00	$0.00	$150.00	2.00	7/21/2023
59919	1 - A SERVICE	$206.25	$0.00	$14.76	$221.01	2.75	7/31/2023
60380	1 - A SERVICE 2 - REPLACE DRIVERS SIDE CONVEX MIRROR	$281.25	$0.00	$187.07	$468.32	3.75	8/25/2023

60862	1 - REPLACE AXLE #2 RIGHT SIDE AXLE STUDS	$112.50	$0.00	$0.00	$112.50	1.50	9/19/2023
60948	1 - A SERVICE	$206.25	$0.00	$15.20	$221.45	2.75	10/4/2023
61185	1 - REPLACE RAD 2 - REPLACE RIGHT SIDE STACK PIN AND BUSHING	$262.50	$0.00	$868.93	$1,131.43	3.50	10/25/2023
63106	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	$0.00	$100.00	$0.00	$100.00	0.00	1/31/2024
61375	1 - REPLACE POWER STEERING PUMP 2 - REPLACE CB ANTENNA ADAPTER 3 - REPAIR COOLANT LEAK 4 - REPLACE CHARGE AIR COOLER 5 - INSTALL PYRO GAUGE	$450.00	$1,443.78	$728.13	$2,621.91	6.00	11/2/2023
61382	1 - REPAIR HYDRAULIC TANK LEAKING 2 - ADJUST CLUTCH 3 - A SERVICE 4 - REPLACE #3 U-JOINT	$450.00	$0.00	$62.12	$512.12	6.00	11/2/2023
61583	1 - REPAIR TARP INOPERABLE	$37.50	$0.00	$117.68	$155.18	0.50	11/10/2023
61863	1 - A SERVICE 2 - REPLACE CLUTCH BRAKE	$243.75	$0.00	$15.20	$258.95	3.25	11/21/2023
64264	1 - SUNDANCE RADIO COMMUNICATIONS: REPLACE RADIO	$0.00	$480.00	$0.00	$480.00	0.00	5/3/2024
62707	1 - CVIP 2 - REPAIR OIL COOLER 3 - REPLACE U-JOINT 4 - REPLACE AXLE #1 LEFT SIDE WHEEL SEAL	$1,050.00	$0.00	$641.85	$1,691.85	14.00	1/17/2024
62868	1 - A SERVICE	$206.25	$0.00	$43.70	$249.95	2.75	1/24/2024
63172	1 - GREASE	$37.50	$0.00	$0.00	$37.50	0.50	2/7/2024
63290	1 - B SERVICE 2 - REPLACE PASSENGER SIDE EXHAUST CLAMP	$150.00	$0.00	$11.86	$161.86	2.00	2/16/2024
63671	1 - A SERVICE 2 - REPLACE AIR LINE	$262.50	$0.00	$83.04	$345.54	3.50	3/19/2024
63983	1 - VALVE SET 2 - ENGINE OIL LEAK	$300.00	$0.00	$0.00	$300.00	4.00	4/5/2024
64195	1 - WEAK JAKES 2 - REPLACE AXLE #2 AND #3 SPRING WEAR PADS 3 - INSTALL COOLANT SUPPORT BRACKET	$787.50	$0.00	$407.11	$1,194.61	10.50	4/18/2024
64204	1 - INSTALL MUDFLAPS 2 - CAC SHIMMED	$187.50	$0.00	$136.92	$324.42	2.50	4/18/2024
64776	1 - A-SERVICE 2 - REPLACE DRIVER SIDE MIRROR BULB 3 - INSTALL U JOINT GREASE NIPPLE	$225.00	$0.00	$46.28	$271.28	3.00	5/21/2024
65399	1 - GREATWEST KENWORTH: CHECK FOR OIL IN SURGE TANK/OIL LEAK/COOLANT LEAK (WARRANTY)	$0.00	$0.00	$0.00	$0.00	0.00	6/11/2024
65646	1 - A-SERVICE 2 - EXHAUST PIPE REPLACED	$300.00	$0.00	$79.59	$379.59	4.00	6/21/2024
65697	1 - REPLACE STEERING U-JOINT	$75.00	$0.00	$30.43	$105.43	1.00	6/25/2024

65747	1 - B-SERVICE 2 - REPLACE AXLE #2 DRIVER SIDE AIRBAG 3 - REPLACE DRIVER SIDE FENDER SIGNAL 4 - REPLACE AXLE #3 RHS AIRBAG 5 - REPAIR CEL	$331.25	$0.00	$522.18	$853.43	4.25	6/28/2024
66003	1 - B SERVICE	$112.50	$0.00	$0.00	$112.50	1.50	7/11/2024
66176	1 - A SERVICE 2 - REPLACE AXLE #2 SPRINGS	$1,875.00	$0.00	$311.94	$2,186.94	25.00	7/19/2024
66549	1 - REPAIR AC 2 - REPAIR COOLANT LEAK	$150.00	$0.00	$326.46	$476.46	2.00	8/7/2024
66871	1 - ELITE DIESEL PERFORMANCE: CHECK ENGINE LIGHT ON	$0.00	$339.20	$534.45	$873.65	0.00	9/3/2024
66827	1 - REPLACE COOLANT LINE 2 - REPLACE FLEX PIPE AND CLAMPS 3 - REPLACE AXLE #2 RIGHT SIDE AND AXLE #3 LEFT SIDE AIRBAGS 4 - REPLACE REAR MOTOR MOUNTS 5 - TIE UP ABS WIRES AND FUEL LINES 6 - REPLACE POWER STEERING PUMP 7 - REPLACE A/C CONDENSER 8 - REPLACE AXLE #2 AND #3 TORQUE RODS 9 - REPLACE AIR LINE	$881.25	$0.00	$1,799.23	$2,680.48	11.75	8/23/2024
66883	1 - CVIP 2 - REPLACE BOTH MIRRORS 3 - REPLACE CAB AIRBAGS AND SHOCK 4 - REPLACE STEADY BEARING 5 - REPLACE U-JOINT 6 - REPLACE AXLE #2 AND #3 BRAKE SHOES AND DRUMS 7 - REPAIR TRANSMISSION LEAK 8 - REPLACE DRIVERS SEAT	$1,125.00	$0.00	$2,257.67	$3,382.67	15.00	8/23/2024
66959	1 - A SERVICE	$150.00	$0.00	$17.38	$167.38	2.00	8/27/2024
67121	1 - B SERVICE	$225.00	$0.00	$12.15	$237.15	3.00	9/6/2024
67222	1 - REPAIR TRANSMISSON OIL LEAK 2 - REPAIR REAR TAIL LIGHT WIRING	$300.00	$0.00	$44.37	$344.37	4.00	9/12/2024
67454	1 - A SERVICE	$187.50	$0.00	$46.75	$234.25	2.50	9/26/2024
67894	1 - REPAIR UPPER RAD PIPE BRACKET	$37.50	$0.00	$0.00	$37.50	0.50	10/18/2024
68047	1 - A SERVICE 2 - REPLACE #1 DIFF TORQUE ROD 3 - REPLACE HYDRAULIC HOSE 4 - REPAIR COOLANT LEAK	$412.50	$0.00	$161.90	$574.40	5.50	10/25/2024
69324	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	$0.00	$100.00	$0.00	$100.00	0.00	1/23/2025
68343	1 - B SERVICE	$112.50	$0.00	$51.54	$164.04	1.50	11/12/2024
68614	1 - A SERVICE	$225.00	$0.00	$47.19	$272.19	3.00	11/28/2024
68665	1 - REPLACE HEADLIGHTS	$262.50	$0.00	$0.00	$262.50	3.50	12/3/2024
69569	1 - IN CIRCLES GLASS: INSTALL WINDSHIELD	$0.00	$100.00	$0.00	$100.00	0.00	2/5/2025
69212	1 - A SERVICE	$187.50	$0.00	$17.59	$205.09	2.50	1/15/2025

69891	1 - IN CIRCLES GLASS: INSTALL DRIVERS SIDE WINDSHIELD	$0.00	$100.00	$0.00	$100.00	0.00	2/19/2025
69872	1 - SUNDANCE RADIO COMMUNICATIONS: REPLACE RADIO	$0.00	$304.95	$0.00	$304.95	0.00	2/19/2025
69907	1 - REPLACE TARP RELAY 2 - CLEAN AND TEST BATTERIES	$131.25	$0.00	$70.56	$201.81	1.75	2/14/2025
70410	1 - OK TIRE: SERVICE CALL TO BOOST TRUCK	$0.00	$229.75	$0.00	$229.75	0.00	3/13/2025
69992	1 - REPLACE BATTERIES	$75.00	$0.00	$488.80	$563.80	1.00	2/20/2025
70012	1 - REPAIR WEBASTO INOPERABLE	$75.00	$0.00	$0.00	$75.00	1.00	2/21/2025
70294	1 - LABEL DASH 2 - REPLACE STEERING SHAFT U-JOINTS	$187.50	$0.00	$22.21	$209.71	2.50	3/5/2025
70510	1 - A SERVICE 2 - REPLACE AXLE #1 DRIVERS SIDE WHEEL SEAL 3 - REPLACE AXLE #3 UPPER TORQUE ROD	$412.50	$0.00	$106.52	$519.02	5.50	3/26/2025
70516	1 - REPLACE AXLE #2 AND #3 DRIVERS SIDE TORQUE ARMS 2 - REPLACE AIR FILTERS 3 - REPLACE AIR TEMP SENSOR	$337.50	$0.00	$693.92	$1,031.42	4.50	3/26/2025
70608	1 - REPLACE HYDRAULIC OIL	$75.00	$0.00	$0.00	$75.00	1.00	4/2/2025
71114	1 - WARD TIRE: ALIGNMENT	$0.00	$412.00	$0.00	$412.00	0.00	4/24/2025
70792	1 - CHECK ENGINE LIGHT ON	$112.50	$0.00	$15.89	$128.39	1.50	4/9/2025
70796	1 - B SERVICE 2 - REPLACE MIRRORS 3 - REPLACE AXLE #3 TORQUE ROD	$262.50	$0.00	$353.35	$615.85	3.50	4/9/2025
70757	1 - REPAIR LEAK TARP INOPERBALE	$56.25	$0.00	$70.56	$126.81	0.75	4/8/2025
70952	1 - REMOVE DRIVERS SIDE FENDER FOR WELDING	$37.50	$0.00	$0.00	$37.50	0.50	4/17/2025
71060	1 - A SERVICE	$206.25	$0.00	$56.65	$262.90	2.75	4/22/2025
71637	1 - A SERVICE 2 - REPAIR RIGHT SIDE MARKER LIGHT	$243.75	$0.00	$48.13	$291.88	3.25	5/20/2025
72290	1 - REPLACE WIPER MOTOR	$93.75	$0.00	$156.64	$250.39	1.25	6/24/2025
72307	1 - A SERVICE	$187.50	$0.00	$17.59	$205.09	2.50	6/25/2025
72452	1 - REPAIR AIR LEAK	$56.25	$0.00	$0.00	$56.25	0.75	7/7/2025
72751	1 - REPLACE SHIFTER DETENT SPRINGS	$75.00	$0.00	$12.90	$87.90	1.00	7/22/2025
72806	1 - B SERVICE 2 - INSTALL AXLE #3 RIGHT SIDE DUSTSHIELD 3 - REPLACE LEFT SIDE FENDER LIGHT	$187.50	$0.00	$23.18	$210.68	2.50	7/23/2025
72965	1 - B SERVICE	$150.00	$0.00	$0.00	$150.00	2.00	7/31/2025
73063	1 - A SERVICE 2 - REPLACE CLUTCH BRAKE	$281.25	$146.80	$266.84	$694.89	3.75	8/7/2025
73117	1 - REPAIR ENGINE OIL LEAK	$2,437.50	$132.12	$67.47	$2,637.09	32.50	8/18/2025

73119	1 - CVIP 2 - REPLACE AXLE #2 INPUT U-JOINT 3 - REPLACE AXLE #2 AND #3 RIGHT SIDE BRAKE SHOES AND DRUMS 4 - REMOVE RADIATOR AND FAN HUB 5 - REPLACE AXLE #3 RIGHT SIDE SLACK ADJUSTER 6 - INSTALL RADIATOR 7 - REPLACE COOLANT HOSE 8 - REPLACE A/C HOSE	$1,518.75	$0.00	$1,125.38	$2,644.13	20.25	8/19/2025
73473	1 - REPLACE BATTERIES	$75.00	$0.00	$658.60	$733.60	1.00	9/2/2025
73638	1 - REPAIR AIR LEAK 2 - REPAIR TRAILER LIGHTS	$112.50	$0.00	$10.46	$122.96	1.50	9/11/2025
73683	1 - REPAIR A/C INOPERABLE	$187.50	$0.00	$12.70	$200.20	2.50	9/15/2025
73710	1 - REPAIR AIR LEAK	$112.50	$0.00	$0.00	$112.50	1.50	9/16/2025
73721	1 - A SERVICE 2 - ADJUST CLUTCH 3 - REPAIR PTO LIGHT 4 - MISCELLANEOUS REPAIRS	$337.50	$154.14	$34.97	$526.61	4.50	9/16/2025
74002	1 - B SERVICE 2 - REPLACE HYDRAULIC HOSE 3 - REPAIR AIR TANK FITTING LEAK	$187.50	$0.00	$201.38	$388.88	2.50	10/7/2025
74266	1 - REPAIR LEAD NOT DUMPING 2 - REPAIR LEAD MARKER LIGHTS	$112.50	$0.00	$8.58	$121.08	1.50	10/20/2025
74280	1 - A SERVICE	$187.50	$146.80	$49.41	$383.71	2.50	10/20/2025
74843	1 - A SERVICE 2 - REPLACE AXLE #2 INPUT U-JOINT 3 REPAIR AXLE #2 PASSENGER SIDE AIR LINE	$318.75	$146.80	$308.60	$774.15	4.25	11/17/2025
75067	1 - REPLACE ALL TIRES	$195.00	$0.00	$4,043.70	$4,238.70	3.00	11/28/2025
75644	1 - A SERVICE	$281.25	$139.46	$168.58	$589.29	3.75	1/20/2026
75691	1 - REPLACE FUEL HAND PRIME PUMP	$18.75	$0.00	$198.09	$216.84	0.25	1/21/2026
75800	1 - REPLACE DRIVERS SIDE CONVEX MIRROR	$37.50	$0.00	$0.00	$37.50	0.50	1/26/2026
75826	1 - REPLACE AIR DRYER 2 - REPAIR AIR LEAK	$318.75	$0.00	$92.63	$411.38	4.25	1/30/2026
75948	1 - REPLACE AXLE #3 RIGHT SIDE LEAF SPRING	$225.00	$0.00	$86.14	$311.14	3.00	2/6/2026
76055	1 - A SERVICE 2 - REPLACE AXLE #2 DRIVERS SIDE SLACK ADJUSTER	$337.50	$139.46	$161.00	$637.96	4.50	2/12/2026
76346	1 - CVIP 2 - REPLACE TRANSMISSION OUTPUT U-JOINT 3 - REPLACE A/C AND FAN BELTS 4 - REPLACE AXLE #3 RIGHT SIDE BRAKE POT 5 - REPLACE TORSION BARS 6 - REPLACE U-BOLTS 7 - REPAIR LIGHTS 8 - REMOVE FENDERS 9 - REPLACE TIE ROD ENDS 10 - REMOVE GPS/CAMERA/RADIO	$2,550.00	$0.00	$2,241.52	$4,791.52	34.00	3/6/2026

76551	1 - IN CIRCLES GLASS: INSTALL WNDSHIELD	$0.00	$200.00	$0.00	$200.00	0.00	4/15/2026
76894	1 - CVIP 2 - REPAIR AXLE #2 LEFT SIDE U-BOLT 3 - REPAIR STEADY BEARING YOKE 4 - RIG UP	$2,118.75	$693.25	$1,348.27	$4,160.27	28.25	4/8/2026
76552	1 - PET AUTO BODY: PAINT	$0.00	$6,970.00	$0.00	$6,970.00	0.00	4/15/2026
76565	1 - CLEAR FINISH POLISHING: FULL TRUCK, NO BACK AND GRILL	$0.00	$1,199.00	$0.00	$1,199.00	0.00	4/15/2026
Totals:		$31,301.25	$16,606.31	$31,289.35	$79,196.91	416.75	

Filter:
Thursday, April 16, 2026