

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
E-1201	SA3 SWING GRADER (SELL)								

	01-2012-933	REPAIR	CLOSED	05/08/2012		F			
	BINDLOSS GRADER CARMIN COOPER								
	WELD ON UNIT NUMBERS ON WING AND VEE								
	BUILD BLADE RACK AND DROP HITCH								
	INSTALL FLAGS ON MULBOARD								
	INSTALL DECALS AND NUMBERS								
							08	TIRES AND RIMS	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							27	ELECTRICAL SYSTEM	99
							33	COMMUNICATIONS	99
							37	HYDRAULIC SYSTEM	99
							57	CIRCLE AND MOLDBOARD	99
							58	ATTACHMENTS	
							61	CABLE AND CABLE CLAMPS	99
							68	STEAM AND PAINT	
							80	FABRICATION AND WELDING	

	01-2012-1692	REPAIR	CLOSED	07/10/2012		O			
	FIRST SERVICE								
	CHANGE OIL & FILTER								
	REPLACE HYDRAULIC FILTER								
							69	TRAVEL TIME	
							67	SERVICE	
							37	HYDRAULIC SYSTEM	99
							00	ENGINE	99

	01-2012-2055	REPAIR	CLOSED	08/09/2012		W			
	TIGHTEN LOOSE FITTING								
	SUPPLY HYD OIL								
							37	HYDRAULIC SYSTEM	99
							21	COOLING SYSTEM	
							69	TRAVEL TIME	

	01-2012-2091	REPAIR	CLOSED	08/13/2012		P			
	REPLACE TRANS FILTER								
	REPAIR BLADE CARRIER RACK								
							69	TRAVEL TIME	
							80	FABRICATION AND WELDING	
							02	TRANSMISSION	99

	01-2012-2515	REPAIR	CLOSED	09/13/2012		O			
	SOS								

CHANGE ENG OIL & FILTER
REPLACE ALL FILTERS
FILL OUT TIRE SHEET

				02	TRANSMISSION	99	
				00	ENGINE	99	
				11	AIR INTAKE SYSTEMS	99	
				20	FUEL SYSTEM	99	
				37	HYDRAULIC SYSTEM	99	
				34	AIR CONDITIONING AND HEATIN	99	
				69	TRAVEL TIME		
				67	SERVICE		

|01-2012-2879 REPAIR CLOSED 10/12/2012 C
|REPLACE REAR CAB GLASS

				62	BODY		
				52	CAB AND CONTROLS	99	
				69	TRAVEL TIME		

|01-2012-3046 REPAIR CLOSED 10/30/2012 C
|INSTALL PLOW WING
|CHECKOVER

				59	AUXILLIARY EQUIPMENT		
				66	INSPECTIONS / DIAGNOSTICS		

|01-2013-107 REPAIR CLOSED 01/11/2013 P
|REPLACE CAB FILTERS

				34	AIR CONDITIONING AND HEATIN	99	
--	--	--	--	----	-----------------------------	----	--

|01-2013-157 REPAIR CLOSED 01/18/2013 E
|REPLACE REAR GLASS BROKEN

				69	TRAVEL TIME		
				52	CAB AND CONTROLS	99	

|01-2013-586 REPAIR CLOSED 03/22/2013 E
|REPLACE BROKEN REAR WINDOW

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							52	CAB AND CONTROLS	
	01-2013-623	REPAIR	CLOSED	03/26/2013		O			
	CHANGE ENGINE OIL AND FILTERS TAKE SAMPLES								
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							20	FUEL SYSTEM	99
							11	AIR INTAKE SYSTEMS	99
							00	ENGINE	99
							02	TRANSMISSION	99
	01-2013-652	REPAIR	CLOSED	04/02/2013		C			
	REPLACE (2) WINDOWS/SEAL								
							52	CAB AND CONTROLS	99
	01-2013-972	REPAIR	CLOSED	05/07/2013		F			
	SEND BERT DOWN TO BINDLOSS TO HELP CARMIN AND KEVIN REMOVE WINGS.								
							37	HYDRAULIC SYSTEM	99
	01-2013-1238	REPAIR	CLOSED	05/24/2013		P			
	CAB FILTERS FOR GRADER HYD OIL FOR GRADER TOP UP								
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
	01-2013-2060	REPAIR	CLOSED	07/29/2013		O			
	SOS CHANGE ENG OIL & FILTER REPLACE ALL FILTERS								
							37	HYDRAULIC SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
							20	FUEL SYSTEM	99
							02	TRANSMISSION	99
							00	ENGINE	99
							11	AIR INTAKE SYSTEMS	99

|01-2013-3407 REPAIR CLOSED 11/15/2013 O

|2000 HR SERVICE

SOS

CHANGE ENG OIL & FILTER(OW30)

REPLACE BLADE SLIDES

SUPPLIED WITH ALLAN WRENCH AND 30MM WRENCH FOR WEARSTRIP CHANGES

	11	AIR INTAKE SYSTEMS	99	
	17	BOLTS- NUTS- WASHERS AND MI	99	
	06	FRONT AXLE	99	
	00	ENGINE	99	
	02	TRANSMISSION	99	
	03	DRIVELINE AND 'U' JOINTS		
	20	FUEL SYSTEM	99	
	34	AIR CONDITIONING AND HEATIN	99	
	37	HYDRAULIC SYSTEM	99	
	52	CAB AND CONTROLS	99	
	62	BODY	99	
	57	CIRCLE AND MOLDBOARD	99	
	68	STEAM AND PAINT		
	67	SERVICE		
	71	SHOP TOOLS	99	
	80	FABRICATION AND WELDING		
	99	MISCELLANEOUS		

|01-2014-44 REPAIR CLOSED 01/02/2014 F

|FINISH FENDER INSTALLINSTALL FRONT AND REAR MUDFLAPS

RETURN JAN 24/2014 FENDER PARTS CREDITED TO US BY FINNING

	66	INSPECTIONS / DIAGNOSTICS		
	67	SERVICE		
	62	BODY		
	27	ELECTRICAL SYSTEM		
	17	BOLTS- NUTS- WASHERS AND MI	99	

|01-2014-175 REPAIR CLOSED 01/15/2014 P

|CARMEN REPLACE (2) WIING BLADES BOLTS AND NUTS

	17	BOLTS- NUTS- WASHERS AND MI	99	
--	----	-----------------------------	----	--

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							64	GROUND ENGAGING TOOLS	99
	01-2014-256	REPAIR	CLOSED	01/24/2014	C				
	CARMEN ADD ENGINE OIL 30W ADD HYD OIL TO TANDEMS REPLACE 2 CAT MIRRORS								
							52	CAB AND CONTROLS	99
							00	ENGINE	99
							37	HYDRAULIC SYSTEM	99
	01-2014-864	REPAIR	CLOSED	04/14/2014	O				
	CHANGE OIL AND FILTERS								
							37	HYDRAULIC SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
							20	FUEL SYSTEM	99
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
	01-2014-1443	REPAIR	CLOSED	06/09/2014	C				
	REPLACED DOOR GLASS								
							52	CAB AND CONTROLS	99
							69	TRAVEL TIME	
	01-2014-1905	REPAIR	CLOSED	07/14/2014	C				
	FINNING MECH R&R DIFF AND INSPECT REFERENCE 2013 WORK ORDER3407								
							04	FINAL DRIVE / DIFFERENTIAL	99
	01-2014-1933	REPAIR	CLOSED	07/16/2014	C				
	SUPPLY CAT OW20 OIL REPLACE CAB AIR FILTERS CHANGE CARBIDE GRADER BLADES								
							02	TRANSMISSION	99
							34	AIR CONDITIONING AND HEATIN	99
							64	GROUND ENGAGING TOOLS	99

|01-2014-2058 REPAIR CLOSED 07/29/2014 C
|REPLACE MOLD BOARD WEAR STRIPS AND ENDPLATES.

WENT DOWN SLIDES WERE FINE OPERATOR DIDNT REALIZE THAT SLIDES WERE TWO PI
ECE. LOWERED TRANSMISSION LEVEL TO NORMAL OPERATING LEVELS WAS OVER BY 1
1/2 INCHES ON DIPSTICK

	69	TRAVEL TIME	
	57	CIRCLE AND MOLDBOARD	99
	64	GROUND ENGAGING TOOLS	

|01-2014-2313 REPAIR CLOSED 08/18/2014 C
|OPERATOR REPLACE WATER SEPERATOR FILTER

	20	FUEL SYSTEM	99
--	----	-------------	----

|01-2014-3260 REPAIR CLOSED 11/18/2014 C
|TRANS/HYD LEAK
KEVIN GOODINE PICKED UP OIL

	27	ELECTRICAL SYSTEM	
	02	TRANSMISSION	99

|01-2014-3397 REPAIR CLOSED 12/02/2014 C
|TRIED TO DO JOYSTICK CALIBRATION BUT COULDNT DUE TO TRANNY CODES.
FINNING LOOKING AFTER TRANY CODES

	02	TRANSMISSION	
--	----	--------------	--

|01-2015-339 REPAIR CLOSED 02/05/2015 C
|REPLACED AIR TANK RELIEF VALVE
REPLACE GOVERNOR

	24	COMPRESSED AIR SYSTEM	99
	58	ATTACHMENTS	
	69	TRAVEL TIME	

|01-2015-416 REPAIR CLOSED 02/17/2015 O
|500 HR SERVICE
OIL AND FILTERS
R/R BLADE SLIDES

	57	CIRCLE AND MOLDBOARD	99
	52	CAB AND CONTROLS	99
	27	ELECTRICAL SYSTEM	99
	20	FUEL SYSTEM	99
	34	AIR CONDITIONING AND HEATIN	99

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Status	Work Order Open Date	Class	Repair Reason	Task ID	Task Description	WAC
							37	HYDRAULIC SYSTEM	99
							02	TRANSMISSION	99
							00	ENGINE	99
							11	AIR INTAKE SYSTEMS	99
	01-2015-1122	REPAIR	CLOSED	04/28/2015		C			
	OPERATOR REPLACE AIR FILTERS								
							11	AIR INTAKE SYSTEMS	99
	01-2015-1654	REPAIR	CLOSED	06/04/2015		C			
	CHANGE HYD FILTERS AND OIL WRONG OIL WAS USED IN UNIT								
							37	HYDRAULIC SYSTEM	99
	01-2015-1732	REPAIR	CLOSED	06/10/2015		C			
	CHANGED ENGINE OIL AND FILTER CHANGED HYDRAULIC OIL AND FILTERS NO HYDRAULIC CAP OIL DIPSTICK WAS FOUND ON THE GROUND FOUND ANTI FREEZE IN THE HYDRAULIC OIL								
							37	HYDRAULIC SYSTEM	99
							00	ENGINE	99
							69	TRAVEL TIME	
							67	SERVICE	
							66	INSPECTIONS / DIAGNOSTICS	
	01-2015-2212	REPAIR	CLOSED	07/14/2015		C			
	REPLACE BLADES WITH CARBIDE BLADES THESE ARE STILL THE OLD YELLOW TYPE								
							64	GROUND ENGAGING TOOLS	99
	01-2015-2841	REPAIR	CLOSED	08/28/2015		C			
	OPERATOR REPLACE CARBIDE BLADES WEARPRO 1" CARBIDES								
							64	GROUND ENGAGING TOOLS	99
	01-2015-3097	REPAIR	CLOSED	09/21/2015		O			
	COMPLETE 4000 HR SERVICE DO NOT DO ANY ENGINE STUFF ITS GOING TO CAT FOR LOW OIL PRESSURE								

ALL SOS (5)

CHANGE TRANY OIL ND FILTERS

CHANGE TANDEM OILS

				67	SERVICE	
				57	CIRCLE AND MOLDBOARD	99
				52	CAB AND CONTROLS	99
				00	ENGINE	99
				02	TRANSMISSION	99
				08	TIRES AND RIMS	99
				11	AIR INTAKE SYSTEMS	99
				37	HYDRAULIC SYSTEM	99
				34	AIR CONDITIONING AND HEATIN	99
				27	ELECTRICAL SYSTEM	
				28	BATTERIES	

01-2015-3754	REPAIR	CLOSED	11/13/2015	E
--------------	--------	--------	------------	---

|REPLACE RIGHT HAND DOOR GLASS

				52	CAB AND CONTROLS	
				69	TRAVEL TIME	

01-2015-3875	REPAIR	CLOSED	11/24/2015	T
--------------	--------	--------	------------	---

|TIRECRAFT SERVICE TRUCK/TIREGUY TIRECRAFT INVOICE ETC429450
REPLACE (6) TR17.5R25SNOWPLUS GR TIRES

				08	TIRES AND RIMS	99
--	--	--	--	----	----------------	----

01-2015-4179	REPAIR	CLOSED	12/29/2015	C
--------------	--------	--------	------------	---

|CHANGED FUEL FILTERS
CHANGED AIR FILTERS

				11	AIR INTAKE SYSTEMS	99
				20	FUEL SYSTEM	99

01-2016-94	REPAIR	CLOSED	01/06/2016	C
------------	--------	--------	------------	---

|CODES:
(4386-3) AUXILIARY LEVER # 8 POSTION SENSOR (VOLTAGE HIGHER THAN NORMAL
)

(4387-3) AUXILIARY LEVER #9 POSTION SENSOR (VOLTAGE HIGHER THAN NORMAL)

				67	SERVICE	
				69	TRAVEL TIME	

01-2016-127	REPAIR	CLOSED	01/07/2016	C
-------------	--------	--------	------------	---

|WELDING REPAIR AT OYEN WELDING
INVOICE #7923

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							80	FABRICATION AND WELDING	99
	01-2016-1239	REPAIR	CLOSED	04/19/2016		C			
	KEVIN GOODINE INSTALL SLOPE METER								
							52	CAB AND CONTROLS	99
	01-2016-1463	REPAIR	CLOSED	05/03/2016		P			
	KEVIN GOODINE REPLACE MOLDBRD WEAR STRIPS/BLADE SHIFT SLIDES								
							57	CIRCLE AND MOLDBOARD	99
	01-2016-1697	REPAIR	CLOSED	05/18/2016		C			
	KEVIN GOODINE REPLACE COOLANT RESORVOIR AND COOLANT HOSE ANTIFREEZE DID NOT NEED RESORVOIR -RETURN TO FINNING								
							21	COOLING SYSTEM	99
	01-2016-1759	REPAIR	CLOSED	05/20/2016		O			
	OPERATOR CHANGE OIL AND FILTER CHANGE ALL FILTERS 2PAILS 0W4020L SOS SAMPLES								
							20	FUEL SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							11	AIR INTAKE SYSTEMS	99
							02	TRANSMISSION	99
							00	ENGINE	99
	01-2016-2202	REPAIR	CLOSED	06/20/2016		C			
	AS PER OIL SAMPLES CHANGE HYD OIL CHANGE OIL IN RH FRONT HUB CHANGED RIGHT HAND HEADLIGHT SOS SAMPLES								
							00	ENGINE	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							24	COMPRESSED AIR SYSTEM	99
							67	SERVICE	
							71	SHOP TOOLS	99

			80	FABRICATION AND WELDING	99	
			69	TRAVEL TIME		

|01-2016-2361 REPAIR CLOSED 06/30/2016 C

|CHECK OUT AIR SYSYTEM LEAK, CHANGED GOVERNOR. FIXED PROBLEM

 CHECK OUT NO A/C, FOUND LEAKING SUCTION LINE TO COMP.

			69	TRAVEL TIME		
			24	COMPRESSED AIR SYSTEM		
			34	AIR CONDITIONING AND HEATIN		

|01-2016-2429 REPAIR CLOSED 07/05/2016 R

|REPLACE PLM WITH CALAMP SYSTEM-TBD 59 / GEM ID #303029

 ESN # 4861023866 / IMEI # 358683065685936.

			33	COMMUNICATIONS		
--	--	--	----	----------------	--	--

|01-2016-2989 REPAIR CLOSED 08/10/2016 O

|500 HR SERVICE

CHANGE ENGINE OIL AND FILTERS

CHANGE ALL FILTERS

SOS SAMPLES

			34	AIR CONDITIONING AND HEATIN	99	
			37	HYDRAULIC SYSTEM	99	
			20	FUEL SYSTEM	99	
			11	AIR INTAKE SYSTEMS	99	
			00	ENGINE	99	
			02	TRANSMISSION	99	
			67	SERVICE		
			69	TRAVEL TIME		

|01-2016-3006 REPAIR CLOSED 01/03/2017 C

|OPERATOR

 CARBIDE BLADES

			64	GROUND ENGAGING TOOLS	99	
--	--	--	----	-----------------------	----	--

|01-2016-3687 REPAIR CLOSED 09/29/2016 C

|LOAD TEST BATTERIES

REPLACED BATTERIES

			28	BATTERIES	99	
--	--	--	----	-----------	----	--

|01-2016-4526 REPAIR CLOSED 12/08/2016 C

|CHECKED OUT LOWER MOLDBOARD BRG. THEY ARE WORN BADLY AND NEED TO BE REPLA

 CED

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							57	CIRCLE AND MOLDBOARD	
	01-2017-43	REPAIR	CLOSED	01/03/2017		C			
	REPLACE LOWER BLADE BUSHINGS. REPLACED ALL OILS AND FILTERS CHECKED TRANS SCREENS								
							57	CIRCLE AND MOLDBOARD	99
	01-2017-47	REPAIR	CLOSED	01/03/2017		O			
	1000 HR. SERVICE CHANGE ALL OILS AND FILTERS TAKE SAMPLES								
							57	CIRCLE AND MOLDBOARD	
							67	SERVICE	
							80	FABRICATION AND WELDING	
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							02	TRANSMISSION	99
							00	ENGINE	99
							11	AIR INTAKE SYSTEMS	99
	01-2017-157	REPAIR	CLOSED	01/12/2017		E			
	WASH UNIT								
							68	STEAM AND PAINT	
	01-2017-160	REPAIR	CLOSED	01/12/2017		C			
	PLOW LIGHTS FOR UNIT, ALSO CALLED BULLHORN LIGHTS								
	KEVIN GOODINE PICKED UP								
							66	INSPECTIONS / DIAGNOSTICS	
							27	ELECTRICAL SYSTEM	99
	01-2017-343	REPAIR	CLOSED	01/26/2017		C			
	WENT TO MACHINE FOR TRANY LEAK FOUND TWO HOSE CLAMPS THAT WERE LOOSE TIGH TENED THEM UP ALL GOOD								
							17	BOLTS- NUTS- WASHERS AND MI	99
							02	TRANSMISSION	
							69	TRAVEL TIME	

|01-2017-499 REPAIR CLOSED 02/07/2017 C
|COMPLETE SET OF AIR CLEANER (INNER + OUTER)

| 11 AIR INTAKE SYSTEMS 99 |

|01-2017-561 REPAIR CLOSED 02/10/2017 C
|INSTALLED NEW HOSE CLAMP ON SUCTION SCREEN HOSE

| 02 TRANSMISSION |
| 34 AIR CONDITIONING AND HEATING 99 |
| 69 TRAVEL TIME |

|01-2017-663 REPAIR CLOSED 02/23/2017 O

|6000 HR SERVICE
CHANGE ENGINE OIL AND FILTERS
CHANGE FUEL FILTERS
CHANGE HYDRAULIC OIL AND FILTERS
CHANGE ALL AIR FILTERS

| 67 SERVICE |
| 37 HYDRAULIC SYSTEM 99 |
| 20 FUEL SYSTEM 99 |
| 02 TRANSMISSION 99 |
| 00 ENGINE 99 |
| 11 AIR INTAKE SYSTEMS 99 |
| 07 TANDEM AND AXLE 99 |

|01-2017-664 REPAIR CLOSED 02/23/2017 I

|COMPLETE INSPECTION
R AND R REAR WINDOW.

| 00 ENGINE |
| 67 SERVICE |
| 66 INSPECTIONS / DIAGNOSTICS |
| 48 FRAME AND CHASSIS |
| 52 CAB AND CONTROLS 99 |
| 99 MISCELLANEOUS 99 |

|01-2017-1375 REPAIR CLOSED 04/25/2017 O

|DAVE PICKED UP OIL AND FILTERS TO DO SERVICE ON GRADER

| 69 TRAVEL TIME |

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99

	01-2017-1917	REPAIR	CLOSED	06/02/2017		C			
	BOLTS BROKEN ON MOLBOARD KNUCKLE, DROPPED CARRIER ONTO TIE-ROD AND BENT I T.								
	REPLACE TIE-ROD AND TIE-ROD ENDS								
	SET TOE-IN TO 1/8 INCH								
	RE-SHIM BLADE LIFT CYLINDERS PROPERLY AND ORDER NEW INSERTS								
							69	TRAVEL TIME	
							57	CIRCLE AND MOLDBOARD	99
							48	FRAME AND CHASSIS	
							44	STEERING	99

	01-2017-1946	REPAIR	CLOSED	06/05/2017		C			
	REPAIR FRONT FENDER								
							80	FABRICATION AND WELDING	
							08	TIRES AND RIMS	
							17	BOLTS- NUTS- WASHERS AND MI	99

	01-2017-3046	REPAIR	CLOSED	08/08/2017		O			
	500 HR SERVICE								
	CHANGE ENGINE OIL AND FILTERS								
	CHANGE ALL FILTERS								
	SOS SAMPLES								
							11	AIR INTAKE SYSTEMS	99
							00	ENGINE	99
							37	HYDRAULIC SYSTEM	99
							20	FUEL SYSTEM	99
							80	FABRICATION AND WELDING	

	01-2017-3064	REPAIR	CLOSED	08/09/2017		R			
	CHECK RADIO AND REPAIR AS IS NECESSARY.								
	SET "SAB NB" AS START CHANNEL FROM "SAB HH".								
	OPERATOR WILL DO SOME RADIO CHECKS TO TEST!!								
							59	AUXILLIARY EQUIPMENT	99
							33	COMMUNICATIONS	

	01-2017-3183	REPAIR	CLOSED	08/16/2017		C			
	BLADE TILT HYD HOSE IS LEAKING								
	REPLACE HOSE								

				37	HYDRAULIC SYSTEM	99
01-2017-4694	REPAIR	CLOSED	12/07/2017	C		
BLADE SLIDES						
				64	GROUND ENGAGING TOOLS	99
01-2017-4713	REPAIR	CLOSED	12/11/2017	O		
UPDATE HRS WHEN UNIT ARRIVES.						
6000 HR SERVICE.						
CHANGE HYDRALIC OIL AND FILTERS.						
CHANGE TRANY OIL AND FILTERS.						
AND TRANY/DIFF SCREENS.						
				56	BELTS	99
				67	SERVICE	
				80	FABRICATION AND WELDING	
				99	MISCELLANEOUS	99
				37	HYDRAULIC SYSTEM	99
				27	ELECTRICAL SYSTEM	
				20	FUEL SYSTEM	99
				02	TRANSMISSION	99
				00	ENGINE	99
				11	AIR INTAKE SYSTEMS	99
				07	TANDEM AND AXLE	99
01-2018-617	REPAIR	CLOSED	02/26/2018	C		
SEAT SHOCK NEEDS REPLACED AS THE SEAT WILL NOT BOUNCE BACK TO POSITION AFTER A BUMP						
				99	MISCELLANEOUS	99
				69	TRAVEL TIME	
				52	CAB AND CONTROLS	99
01-2018-811	REPAIR	CLOSED	03/13/2018	C		
PIN FOR BLADE						
				58	ATTACHMENTS	99
01-2018-1076	REPAIR	CLOSED	04/09/2018	C		
FAB COUPLER FOR INSTALLING FOLLOW ME WOBBLIES						
REMOVE WING AND BOTTOM MAST FROM GRADER						

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							69	TRAVEL TIME	
							67	SERVICE	
							99	MISCELLANEOUS	99
							80	FABRICATION AND WELDING	
							71	SHOP TOOLS	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							37	HYDRAULIC SYSTEM	99
	01-2018-1698	REPAIR	CLOSED	05/25/2018		T			
	FIX RIGHT FRONT TIRE								
							08	TIRES AND RIMS	99
	01-2018-1738	REPAIR	CLOSED	05/28/2018		C			
	- FUEL FILLER CAP PICKED UP FOR UNIT -								
							20	FUEL SYSTEM	99
	01-2018-2124	REPAIR	CLOSED	06/15/2018		P			
	KELLY SEIPPERT TOOK FIRE EXTINGUISHER								
							86	SAFETY SUPPLIES	99
	01-2018-2213	REPAIR	CLOSED	06/19/2018		C			
	BLOWN HYD HOSE ON WOBBLE WHEELS								
	MAKE NEW HOSE OPERATOR WILL INSTALL								
							37	HYDRAULIC SYSTEM	99
	01-2018-2302	REPAIR	CLOSED	06/25/2018		R			
	TRADE OUT RADIO & CODE PLUG								
							33	COMMUNICATIONS	
	01-2018-2324	REPAIR	CLOSED	06/25/2018		O			
	500 HR SERVICE								
	CHANGE ENGINE OIL AND FILTERS								
	CHANGE ALL FILTERS								

SOS SAMPLES

	20	FUEL SYSTEM	99	
	37	HYDRAULIC SYSTEM	99	
	11	AIR INTAKE SYSTEMS	99	
	00	ENGINE	99	

01-2018-2538	REPAIR	CLOSED	07/04/2018	C
--------------	--------	--------	------------	---

|MOUNTING A 20LBS FIRE EXTINGUISHER ONTO THE GRADER.

	86	SAFETY SUPPLIES	99	
	69	TRAVEL TIME		
	80	FABRICATION AND WELDING		

01-2018-2726	REPAIR	CLOSED	07/17/2018	C
--------------	--------	--------	------------	---

| - JOHN MYLES PICKED UP TRANY COVER SEAL FOR UNIT -

	02	TRANSMISSION	99	
--	----	--------------	----	--

01-2018-3899	REPAIR	CLOSED	09/21/2018	C
--------------	--------	--------	------------	---

|SEPT 21/18 REPORTED HEATER MOTOR KEEPS BLOWING CIRCUIT BREAKER

SEPT 24/18 CHECKED AMPERAGE AT HEATER MOTOR IT WAS RUNNING AT 6.5 AMPS WH
ICH IS GOOD ALSO FOUND HEATER MOTOR HAD PAPER STUCK IN IT REMOVED ALL THI
S. MADE UP A LIGHT IN CIRCUIT BREAKER SPOT AND FOUND WHEN PACKERS WERE PU

	11	AIR INTAKE SYSTEMS	99	
	27	ELECTRICAL SYSTEM	99	
	99	MISCELLANEOUS	99	
	69	TRAVEL TIME		

01-2018-3909	REPAIR	CLOSED	09/24/2018	T
--------------	--------	--------	------------	---

|CHECK TIRES

	69	TRAVEL TIME		
--	----	-------------	--	--

01-2018-4369	REPAIR	CLOSED	10/25/2018	T
--------------	--------	--------	------------	---

|FIX FLAT

	69	TRAVEL TIME		
	08	TIRES AND RIMS	99	

01-2018-4754	REPAIR	CLOSED	11/26/2018	O
--------------	--------	--------	------------	---

|500 HR SERVICE

CHANGE ENGINE OIL AND FILTERS
CHANGE ALL FILTERS
SOS SAMPLES

	11	AIR INTAKE SYSTEMS	99	
--	----	--------------------	----	--

Equipment ID	Work Order ID	Type	Status	Open Date	Class	Reason	ID	Task Description	WAC
							02	TRANSMISSION	99
							00	ENGINE	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
	01-2019-1313	REPAIR	CLOSED	04/04/2019		C			
	CIRCLE FRAME PIVOT BALL BOLTS BROKE OFF FELL DOWN AND BENT TIE ROD								
WELDER (BRADEN) REMOVED THE OLD DRAWBAR STUD ASSY. AND WELDED ON A NEW ON E. HE WELDED THE FIRE EXTINGUISHER BRACKET BACK ON AS WELL.									
REASSEMBLED THE CIRCLE DRAWBAR BALL ASSY. USING A NEW BALL, STUD, ALL NEW									
							04	FINAL DRIVE / DIFFERENTIAL	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							03	DRIVELINE AND ''U'' JOINTS	99
							57	CIRCLE AND MOLDBOARD	99
							69	TRAVEL TIME	
							99	MISCELLANEOUS	99
							80	FABRICATION AND WELDING	99
	01-2019-1466	REPAIR	CLOSED	04/16/2019		P			
	REPLACE BURNT OUT BEACON								
JOHN HOGAN TOOK HYDRAULIC OIL									
							37	HYDRAULIC SYSTEM	99
							27	ELECTRICAL SYSTEM	99
	01-2019-1516	REPAIR	CLOSED	04/23/2019		T			
	REPLACE THE LEFT FRONT DRIVE WITH USED TIRE TO MATCH								
CUPPING AND VIBRATION IN HIGH GEAR									
							08	TIRES AND RIMS	99
							69	TRAVEL TIME	
	01-2019-1688	REPAIR	CLOSED	05/02/2019		E			
	LEFT AND RIGHT HAND DOOR GLASS								
WENT DOWN TO BINDLOSS SHOP ON MAY 2/19 AND THE GLASS I GOT FROM PARTS WAS INCORRECT. SO I REMOVED BOTH PIECES OF GLASS.									
CAME BACK ON MAY 3/19 TO INSTALL BOTH NEW DOOR GLASS. THE LEFT SIDE WAS C									
							52	CAB AND CONTROLS	
							69	TRAVEL TIME	
							63	GLASS	99
	01-2019-1736	REPAIR	CLOSED	05/03/2019		R			
	INSTALL NEW 2019 CODE PLUG								

			33	COMMUNICATIONS	

01-2019-1789	REPAIR	CLOSED	05/07/2019	P	
JOHN HOGAN TOOK R.H. UPPER WINDSHIELD WIPER BLADE					
			52	CAB AND CONTROLS	99

01-2019-1798	REPAIR	CLOSED	05/08/2019	C	
REPORTED HYD. LINE LEAKING					
REPLACED TRANSMISSION LUBE HOSE-MAY 8/19					
			62	BODY	
			69	TRAVEL TIME	
			27	ELECTRICAL SYSTEM	
			37	HYDRAULIC SYSTEM	99
			02	TRANSMISSION	

01-2019-2058	REPAIR	CLOSED	05/23/2019	O	
JOHN HOGAN TOOK OUTER AND INNER AIR FILTERS FOR UNIT					
			11	AIR INTAKE SYSTEMS	99

01-2019-2769	REPAIR	CLOSED	06/27/2019	O	
JOHN HOGAN TOOK OUTER FILTER					
			11	AIR INTAKE SYSTEMS	99

01-2019-2911	REPAIR	CLOSED	07/04/2019	T	
PUT USED 17.5R25 ON THE LEFT REAR DRIVE					
1 -ORING					
			08	TIRES AND RIMS	
			69	TRAVEL TIME	

01-2019-2935	REPAIR	CLOSED	07/05/2019	P	
SUPPLY JACK					
			53	TRAILER PARTS	99

01-2019-3106	REPAIR	CLOSED	07/15/2019	C	
- OPERATOR REPLACE BLADE SLIDES -					

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							57	CIRCLE AND MOLDBOARD	99

	01-2019-3129	REPAIR	CLOSED	07/16/2019		C			
	REMOVE GUIDE BOLTS ON MOLDBOARD								
	JULY 16/19 ASSISTED OPERATORS WITH INSTALLING NEW BRASS SLIDES AND ALSO R								
	EPAIRED R/H FRONT STEERING TIRE FENDER								
							57	CIRCLE AND MOLDBOARD	
							69	TRAVEL TIME	
							80	FABRICATION AND WELDING	

	01-2019-3161	REPAIR	CLOSED	07/17/2019		C			
	OPERATOR COMPLAINT OF STEERING MALFUNCTION CODE								
	HOOKED UP ET AND CHECKED CODES THERE WAS A STEERING CODE IN THE LOGGED SE								
	CTION THAT HAPPENED 3 TIME 400 HRS AGO THE ONLY OTHER CODE THAT WAS THE								
	RE WAS A LOGGED CODE THAT HAPPENED AT THIS TIME BUT WAS INACTIVE THE COD								
							69	TRAVEL TIME	
							27	ELECTRICAL SYSTEM	

	01-2019-3349	PM	CLOSED	07/29/2019		O			
	4000 HOUR SERVICE								
	INSPECT AND MAINTAIN MACHINE AS PER OMM.								
	CHANGE FUEL FILTERS								
	CHECK/CHANGE AIR FILTERS								
	CHANGE ENGINE OIL & FILTER, OBTAIN SAMPLE								
							27	ELECTRICAL SYSTEM	99
							19	EXHAUST SYSTEM	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99
							11	AIR INTAKE SYSTEMS	99
							02	TRANSMISSION	99
							00	ENGINE	99
							80	FABRICATION AND WELDING	
							99	MISCELLANEOUS	99
							63	GLASS	99
							A	A PREVENTIVE MAINTENANCE IN	
							M	ANNUAL INSPECTION	
							52	CAB AND CONTROLS	99
							48	FRAME AND CHASSIS	
							67	SERVICE	
							66	INSPECTIONS / DIAGNOSTICS	

	01-2019-3655	REPAIR	CLOSED	08/14/2019		C			
	WHEN DOING THE SERVICE AND DRAINING THE OIL FROM LH TANDEM SOME LARGE PIE								
	CES OF METAL WERE FOUND IN THE BOTTOM OF THE TANDEM								
	THE FRONT BRAKE AND WHEEL OF THE LH SIDE DOES NOT TURN FREELY SO SUSPECT								
	THE BRAKES HAVE FAILED AND THAT IS WHERE THE PIECES COME FROM								
							99	MISCELLANEOUS	99
							80	FABRICATION AND WELDING	

				07	TANDEM AND AXLE	99	
				41	BRAKES	99	
				37	HYDRAULIC SYSTEM	99	

|01-2019-4688 REPAIR CLOSED 10/08/2019 R
|RADIO HAS NO VOLUME
REPLACED RADIO S/N 866IVL1954

				33	COMMUNICATIONS	99	
--	--	--	--	----	----------------	----	--

|01-2019-4826 REPAIR CLOSED 10/16/2019 C
|COMPLAINT OF OIL LEAKING FROM TRANS/DIFF AREA

FOUND A RHOSE LEAKING ND ORDERED 291-6128 WILL BE REPLACED WHEN HOSE AR
RIVES

				69	TRAVEL TIME		
				37	HYDRAULIC SYSTEM	99	

|01-2019-5125 REPAIR CLOSED 11/04/2019 P
|JOHN HOGAN TOOK CABIN AIR FILTERS

				11	AIR INTAKE SYSTEMS	99	
--	--	--	--	----	--------------------	----	--

|01-2019-5659 REPAIR CLOSED 12/12/2019 C
| DEC. 11/19 @ 8140 HRS. - REQUESTED THAT I TRAVEL TO E-1201 IN BINDLOSS
TO CHECK & REPAIR DIAGNOSTIC CODES.
27 - E192(3) STEERING MALFUNCTION
27 - E877(1) (LOGGED INACTIVE) HIGH TRANS OIL TEMP.
53 - 248-9 (LOGGED INACTIVE) CDL DATA LINK

				27	ELECTRICAL SYSTEM		
				69	TRAVEL TIME		

|01-2019-5677 REPAIR CLOSED 12/12/2019 C
|REMOVE STUCK PINS ON WING BLADE MOUNT

				69	TRAVEL TIME		
				80	FABRICATION AND WELDING		

|01-2019-5732 REPAIR CLOSED 12/19/2019 C
| DEC. 18/19 @ 8151 HRS. - RECEIVED A REQUEST TO CHECK E-1201 FOR HAVING
LOST PRIMARY STEERING AND ENGAGING THE SECONDARY STEERING SYSTEM. CODES
PRESENT.

DEC. 18/19 @ 8151 HRS. - TRAVELLED TO E-1201 IN THE BINDLOSS SHOP. DID

Work Orders List
by Equipment ID

Equipment	ID	Work Order ID	Type	Status	Open Date	Class	Reason	ID	Task Description		WAC
								69	TRAVEL TIME		
								44	STEERING		99
								27	ELECTRICAL SYSTEM		99
								00	ENGINE		99
	01-2020-1331	PM	CLOSED		04/23/2020	O					
	PM 500 HOUR SERVICE BY OPERATOR INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST. CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE CHECK/CHANGE AIR FILTERS CHANGE FUEL FILTERS										
								00	ENGINE		99
								02	TRANSMISSION		99
								11	AIR INTAKE SYSTEMS		99
								20	FUEL SYSTEM		99
								37	HYDRAULIC SYSTEM		99
								M	ANNUAL INSPECTION		
								A	A PREVENTIVE MAINTENANCE IN		
	01-2020-1346	REPAIR	CLOSED		04/27/2020	C					
	APRIL 27, 2020 R/H DOOR GLASS REPLACED AND CLEANED										
								63	GLASS		99
								69	TRAVEL TIME		
								52	CAB AND CONTROLS		
	01-2020-1944	REPAIR	CLOSED		06/16/2020	C					
	- REPLACING AIR CLEANER CHECK VALVE										
								11	AIR INTAKE SYSTEMS		99
	01-2020-2267	REPAIR	CLOSED		07/03/2020	C					
	REPORTED UNIT HAS HYD. OIL LEAK AT REAR OF MACHINE WENT TO CHECK UNIT FOR LEAK AND FOUND THE PLATES ON BACK OF TRANSMISSION ARE LEAKING. PUT IN ORDER FOR PARTS. GUARDS ARE IN CEREAL SHOP JULY 6/20 RESEALED PLATES AND PLUGS ON REAR OF TRANS EXCEPT FOR THE ONE PLUG UNDER LINE THAT NEEDS REPLACED. HAVE PUT IN ORDER FOR HOSE AND PLUG.										
								14	CHEMICALS		99
								02	TRANSMISSION		99
								37	HYDRAULIC SYSTEM		99
								69	TRAVEL TIME		
	01-2020-2698	REPAIR	CLOSED		07/30/2020	O					
	GORD TOOK OUTER, INNER AND CAB AIR FILTERS										

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							08	TIRES AND RIMS	
							69	TRAVEL TIME	

	01-2021-251	REPAIR	CLOSED	01/21/2021		C			
	- JOHN PICKED UP A FUEL CAP FILTER								
	- JOHN CAME BACK AND TOOK NEW FUEL CAP FOR UNIT (MAY RETURN FILTER)								
							20	FUEL SYSTEM	99

	01-2021-320	REPAIR	CLOSED	01/28/2021		C			
	CIRCLE TO BE RESHIMMED ON TOP-DONE								
	CIRCLE WEAR MATRERIAL NEEDS REPLACED UNDERNEATH								
	CYLINDER SOCKET INSERTS NEED REPLACED								
	BELLY PAN NEEDS NEW BOLTS-DONE								
	DRAWBAR CARRIER NEEDS SHIMS REMOVED-DONE								
							24	COMPRESSED AIR SYSTEM	
							41	BRAKES	
							37	HYDRAULIC SYSTEM	
							07	TANDEM AND AXLE	99
							11	AIR INTAKE SYSTEMS	99
							14	CHEMICALS	99
							17	BOLTS- NUTS- WASHERS AND MI	99
							67	SERVICE	
							69	TRAVEL TIME	
							58	ATTACHMENTS	
							62	BODY	99
							48	FRAME AND CHASSIS	
							57	CIRCLE AND MOLDBOARD	

	01-2021-1341	REPAIR	CLOSED	04/27/2021		C			
	APRIL 27/21 WENT TO UNIT AND STARTED IT ENGINE WAS HAMMERING. SHUT OFF #2								
	INJECTOR AND ENGINE BECAME QUIET.DID CUT OUT TEST ON INJECTORS AND FOUND								
	# 1,3,5 WERE NOT MUCH DIFFERENCE IN WORKING OR NOT. #2 INJECTOR FOUND TH								
	ERE WAS NO DIFFERENCE AND #4,6 MADE A DIFFERENCE WHEN INJECTOR WAS ON OR								
	OFF. DECIDED TO ORDER INJECTORS FOR THIS UNIT. MAY 3/21 REPLACED INJECTOR								
							69	TRAVEL TIME	
							00	ENGINE	99
							37	HYDRAULIC SYSTEM	99
							27	ELECTRICAL SYSTEM	99
							20	FUEL SYSTEM	

	01-2021-1756	REPAIR	CLOSED	05/20/2021		T			
	THE RIGHT REAR DRIVE TIRE WAS LOSING AIR. PULLED OLD ORING OUT AND FOUND								
	IT WAS PINCHED. PUT NEW ORING IN AND TOLD OPERATOR TO KEEP AN EYE ON THE								
	TIRE IF IT GOES FLAT AGAIN THEN WILL HAVE TO REPLACE THE RIGHT DRIVE TIRE								
	S OR SEE IF THERE IS SOMETHING PUNCTURING THE TIRE.								
							08	TIRES AND RIMS	
							69	TRAVEL TIME	

|01-2021-1839 REPAIR CLOSED 05/28/2021 T
|RIGHT REAR DRIVE TIRE IS LEAKING AIR AGAIN WILL GO OUT PULL TIRE RIGHT OF
F AND INSPECT TIRE AND RIM AS WELL SOAK TIRE DOWN PRIOR TO PEELING TIRE O
FF. WILL TAKE A PATCH WITH ME IN CASE IT NEEDS A PATCH.

SPRAYED THE ENTIRE TIRE DOWN AND DIDNT SEE NOTHING BUBBLE OR SPRAY BACK A

	69	TRAVEL TIME	
	08	TIRES AND RIMS	99

|01-2021-1998 REPAIR CLOSED 06/02/2021 T
|THE RIGHT REAR DRIVE TIRE HAD A PATCH AND THE PATCH LET GO SO I PUT A NEW
PATCH IN AND AIRED BACK UP SOAKED IT DOWN AND NO LEAKS.

	08	TIRES AND RIMS	
	69	TRAVEL TIME	

|01-2021-3484 REPAIR CLOSED 08/23/2021 R
|INSTALL JENNER FIRE CODE PLUG

	33	COMMUNICATIONS	
--	----	----------------	--

|01-2021-3767 PM CLOSED 09/01/2021 O
|PM 500 HOUR SERVICE BY OPERATOR
COMPLETED 9 SEPT 2021
INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE
CHECK/CHANGE AIR FILTERS

	20	FUEL SYSTEM	99
	37	HYDRAULIC SYSTEM	99
	34	AIR CONDITIONING AND HEATIN	99
	11	AIR INTAKE SYSTEMS	99
	00	ENGINE	99
	02	TRANSMISSION	99
	67	SERVICE	99
	57	CIRCLE AND MOLDBOARD	99
	M	ANNUAL INSPECTION	
	A	A PREVENTIVE MAINTENANCE IN	

|01-2021-4028 REPAIR CLOSED 09/15/2021 T
|RIGHT REAR DRIVE WAS LEAKING AIR. PULLED THE TIRE OFF AND THE PATCH THAT
WAS IN THERE BEFORE LET GO. CLEANED UP THE AREA AND PUT NEW PATCH ON AND
AIRED IT UP SOAKED IT DOWN TO MAKE SURE IT WASNT LEAKING.

TIRE SIZE:17.5R25

Equipment ID	Work Order ID	Type	Status	Open Date	Class	Reason	ID	Task Description	WAC
							69	TRAVEL TIME	
							08	TIRES AND RIMS	
	01-2021-4831	REPAIR	CLOSED	10/28/2021		C			
	OCT 28/21 FOUND THE R/H TANDEM IS LEAKING OIL AT PIVOT LEVEL WAS DOWN 1I N-REFILLED OCT 28/21 REPLACE 6 WIPER BLADES-DONE OCT 28/21 TURBO DRAIN LINE LEAKING PARTS ORDERED - DONE NOV/1/21 REPLACED TURBO DRA IN CONNECTOR LINE								
							02	TRANSMISSION	
							00	ENGINE	99
							37	HYDRAULIC SYSTEM	
							19	EXHAUST SYSTEM	99
							30	STARTER	
							71	SHOP TOOLS	99
							52	CAB AND CONTROLS	99
							66	INSPECTIONS / DIAGNOSTICS	
	01-2022-185	REPAIR	CLOSED	01/12/2022		T			
	REPAIR TIRE FIND BAD PATCH REPLACE BOTH RIGHT SIDE TIRES WITH GOOD USED TIRES AND REPLACE O-RINGS 17 .5/25 SNOW PLUS USED								
							08	TIRES AND RIMS	99
	01-2022-1531	REPAIR	CLOSED	04/29/2022		P			
	JOHN HOGAN TOOK UPPER AND LOWER BLADE SLIDES								
							57	CIRCLE AND MOLDBOARD	99
	01-2022-1553	REPAIR	CLOSED	05/02/2022		C			
	JOHN HOGAN REPLACE BROKEN SLIDE BOLT AND NUT								
							57	CIRCLE AND MOLDBOARD	99
	01-2022-1559	REPAIR	CLOSED	05/02/2022		C			
	MAY 2/22 DID CUT OUT TEST AND ALL CHECKED OUT. ALL CHECKED OUT AND RAN GO OD. NO MORE ENGINE KNOCK.								
							00	ENGINE	
	01-2022-1891	REPAIR	CLOSED	05/24/2022		R			
	REMOVE OLD EQUIPMENT & INSTALL TITAN DEVICE								

			33	COMMUNICATIONS	
01-2022-2317	REPAIR	CLOSED	06/13/2022	C	
STEPHEN PICKED UP A SHOVEL TO CLEAN BLADE					
			17	BOLTS- NUTS- WASHERS AND MI	99
			71	SHOP TOOLS	99
01-2022-2398	REPAIR	CLOSED	06/21/2022	C	
OPERATOR STATES THAT AS SOON AS HE TAKES THE UNIT OUT OF NEUTRAL A WARNING SOUNDS STATING THAT THE PARKING BRAKE IS STILL ENGAGES.					
PARK BRAKE PRESSURE SENSOR HAS FAILED CAUSING THE ECM TO THINK THE PARK BRAKE IS ENGAGED WHEN IT IS NOT RESULTING IN THE SHUT DOWN WARNING.					
			69	TRAVEL TIME	
			27	ELECTRICAL SYSTEM	99
			41	BRAKES	
01-2022-2724	PM	CLOSED	07/06/2022	O	
PM 2000 HOUR SERVICE BY TECHNICIAN COMPLETED 30 JULY 2022					
INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST					
CHANGE FUEL FILTERS					
CHECK AIR PRECLEANER					
			37	HYDRAULIC SYSTEM	99
			34	AIR CONDITIONING AND HEATING	99
			20	FUEL SYSTEM	99
			07	TANDEM AND AXLE	99
			11	AIR INTAKE SYSTEMS	99
			00	ENGINE	99
			02	TRANSMISSION	99
			67	SERVICE	99
			A	A PREVENTIVE MAINTENANCE IN	
			M	ANNUAL INSPECTION	
01-2022-2783	REPAIR	CLOSED	07/08/2022	C	
OPERATOR STATES THAT THE BLOWER FAN IN THE CAB WAS WORKING SPORADICALLY AND FINALLY QUIT OUTRIGHT.					
INTERNAL FAILURE IN THE FAN MOTOR CAUSING A HIGH RESISTANCE RESULTING IN THE MOTOR NO LONGER TURNING. WILL CHANGE THE MOTOR AND THE RESISTOR.					
			69	TRAVEL TIME	
			34	AIR CONDITIONING AND HEATING	99
01-2022-2989	REPAIR	CLOSED	07/22/2022	T	
INSTALL 6 NEW KALTIRE RECAPS					
17.5R25					
INTEGRA TIRE ARDELL HAYWORTH INSTALLED TIRES					
6-O-RINGS					

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							08	TIRES AND RIMS	99

	01-2022-3081	REPAIR	CLOSED	07/28/2022		P			
ISSUED 4 GRADER BOLTS AND NUTS TO OPERATOR FOR REPAIRS									
WELDER TORCHED OUT 3 STUCK BOLTS.									
							57	CIRCLE AND MOLDBOARD	99
							80	FABRICATION AND WELDING	

	01-2022-3400	REPAIR	CLOSED	08/16/2022		R			
AVL NOT REPORTING FOR SOME TIME									
ATTEMPTING TO REBOOT AND RESTART									
PROGRAMMED A DIFFERENT UNIT FOR THIS MACHINE									
STARTED TO TRAVEL TO SITE TO INSTALL DEVICE AND FOUND DIFFERENT DEVICE HAD FAILED									
							33	COMMUNICATIONS	

	01-2022-4702	REPAIR	CLOSED	11/01/2022		C			
JOHN HOGAN EMAILED IN FOR SUPPLIES FOR UNIT									
							03	DRIVELINE AND 'U' JOINTS	99

	01-2022-4799	REPAIR	CLOSED	11/07/2022		C			
RIGHT SIDE TANDEM SEAL LEAKING									
11/7/2022 RB									
							07	TANDEM AND AXLE	99
							80	FABRICATION AND WELDING	

	01-2023-163	REPAIR	CLOSED	01/09/2023		C			
ROSS CROWLE WAS IN AND ORDERED A TOW STRAP FOR UNIT									
							58	ATTACHMENTS	99

	01-2023-225	REPAIR	CLOSED	01/12/2023		C			
FABRICATED PIN FOR HITCH ATTACHMENT									
							80	FABRICATION AND WELDING	

|01-2023-334 REPAIR CLOSED 01/20/2023 C
|OPERATOR STATES THE UNIT WILL NOT WARM UP MORE THAN 120 DEGREES F

SUSPECT THERMOSTAT HAS FAIL IN THE OPEN POSITION ALLOWING COOLANT TO FLOW
FREELY THROUGH THE ENDING RESULTING IN SLOW OR NO HEAT IN THE SYSTEM.

	18	FASTNERS & TIE DOWNS	99	
	07	TANDEM AND AXLE	99	
	34	AIR CONDITIONING AND HEATIN	99	
	21	COOLING SYSTEM	99	

|01-2023-353 REPAIR CLOSED 01/23/2023 C
|JOHN HOGAN PICKED UP WINSHIELD WASHER FLUID

	63	GLASS	99	
--	----	-------	----	--

|01-2023-738 PM CLOSED 02/14/2023

|PM 500 HOUR SERVICE BY OPERATOR
COMPLETED 22 FEB 2023

INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.
CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE
CHECK/CHANGE AIR FILTERS

	M	ANNUAL INSPECTION		
	A	A PREVENTIVE MAINTENANCE IN		
	66	INSPECTIONS / DIAGNOSTICS	99	
	20	FUEL SYSTEM	99	
	37	HYDRAULIC SYSTEM	99	
	11	AIR INTAKE SYSTEMS	99	
	00	ENGINE	99	

|01-2023-821 REPAIR CLOSED 02/22/2023 C
|GORD OLDS WAS IN FOR NUTS, BOLTS, AND WASHER FOR THE WING BLADE

	64	GROUND ENGAGING TOOLS	99	
--	----	-----------------------	----	--

|01-2023-868 REPAIR CLOSED 02/27/2023 C
|JOHN HOGAN PICKED UP SANDVIK POINTS

	64	GROUND ENGAGING TOOLS	99	
--	----	-----------------------	----	--

|01-2023-966 REPAIR CLOSED 03/02/2023 C
|- REPLACE LEAKING SIDE SHIFT HOSES

	57	CIRCLE AND MOLDBOARD	99	
--	----	----------------------	----	--

|01-2023-982 REPAIR CLOSED 03/06/2023 C
|VOLUME CONTROL NOT WORKING
REPLACED AM/FM RADIO WITH USED RADIO

WORKED FOR ONE DAY, BECAME STATICKY
PROBABLE ANTENNA TROUBLE, WAITING FOR PARTS

33

COMMUNICATIONS

| 01-2023-1531 REPAIR CLOSED 04/18/2023 C
| APR 18/23 REPLACED L/H DOOR GLASS AND TIGHTENED ENG DIPSTICK TUBE
| ORDERED PARTS FOR HEATER CONTROL .A/C SWITCH/WATER VALVE/HEATER HOSE FOR
| CAB

CLH MAY 2/23

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							34	AIR CONDITIONING AND HEATIN	99
							52	CAB AND CONTROLS	99
							63	GLASS	99
							69	TRAVEL TIME	

	01-2023-1662	REPAIR	CLOSED	04/25/2023		C			
	JOHNNY HOGAN PICKED UP FOR UNIT:								
	3 CANS OF MOLLY DRY								
	3 CANS OF BRAKE CLEAN								
	2 SAFETY FLAGS								
							86	SAFETY SUPPLIES	99
							17	BOLTS- NUTS- WASHERS AND MI	99

	01-2023-1810	REPAIR	CLOSED	05/02/2023		C			
	JOHN HOGAN EMAILED IN FOR CARBIDES								
							64	GROUND ENGAGING TOOLS	99

	01-2023-1959	REPAIR	CLOSED	05/11/2023		C			
	OPERATOR STATES THE RH FRONT FENDER IS CONTACTING THE INNER SIDE WALL OF THE TIRE.								
	RETAINING BOLT FOR THE FRONT BUSHING HAS FALLEN OUT AS WELL AS THE KEY. W								
	ITH NO KEY THE FENDER HAS ENOUGH FREE PLAY THAT EVENTUALLY THE REAR BUSHI								
							58	ATTACHMENTS	99
							06	FRONT AXLE	

	01-2023-2421	REPAIR	CLOSED	06/08/2023		R			
	COMPLAINT THAT EQUIPMENT WAS NOT REPORTING								
	ATTENDED EQUIPMENT AND HAD TITAN PERFORM A RESET								
	APPEARS TO BE REPORTING								
							33	COMMUNICATIONS	

	01-2023-2771	REPAIR	CLOSED	06/27/2023		O			
	PM 1000 HOUR SERVICE								
	COMPLETED 10 JULY 2023								
	INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST								
	CHANGE FUEL FILTERS								
	CHECK AIR PRECLEANER								
							28	BATTERIES	99
							20	FUEL SYSTEM	99
							34	AIR CONDITIONING AND HEATIN	99
							37	HYDRAULIC SYSTEM	99
							02	TRANSMISSION	99
		00	ENGINE	99					
		11	AIR INTAKE SYSTEMS	99					

			67	SERVICE	99	
			69	TRAVEL TIME		

	01-2023-2905	REPAIR CLOSED	07/04/2023	R		
	DEVICE WAS PRODUCING TOW ALERTS					
	ATTENDED MACHINE AND FOUND KEY ON WIRE CONNECTION HAD FAILED, CONNECTED KEY ON WIRE TO AM/FM RADIO KEY ON WIRE					
	APPEARS TO HAVE RESOLVED TOW ALERT NOTIFICATIONS AND COMMS RADIO POWER PROBLEM					
			33	COMMUNICATIONS		

	01-2023-3033	REPAIR CLOSED	07/11/2023	C		
	JULY 11/23 REPLACED BATTERIES AND CHECKED CHARGING SYSTEM IT IS PUTTING OUT 27 VOLTS-PWB					
	BATTERIES ARE ON WORK ORDER # 2771 JUST LABOR ON THIS WORK ORDER					
			28	BATTERIES		
			69	TRAVEL TIME		

	01-2023-3123	REPAIR CLOSED	07/17/2023	C		
	JULY 17/23 REPLACED 2 LOWER REAR WEAR GUIDES ON CIRCLE AND ADJUSTED THE REST OF THE LOWER AND UPPER WEAR GUIDES-PWB					
			57	CIRCLE AND MOLDBOARD		

	01-2023-3473	REPAIR CLOSED	08/03/2023	C		
	JOHN HOGAN EMAILED IN FOR WIPER BLADES					
			58	ATTACHMENTS	99	

	01-2023-3555	REPAIR CLOSED	08/09/2023	CW		
	ORDERING NEW BLADE PIVOT PINS AND WE HAVE REPAIRED TUBE IN OLD BARN					
	CALVIN TO LANCE OUT OLD PINS					
	SEPT 6/23 DONE BY OUR CONTRACTOR FROM SUNVALLEY FROM MEDICINEHAT					
			57	CIRCLE AND MOLDBOARD		
			64	GROUND ENGAGING TOOLS	99	
			80	FABRICATION AND WELDING		
			37	HYDRAULIC SYSTEM	99	

	01-2023-4862	REPAIR CLOSED	10/25/2023	C		
	JOHN HOGAN PICKED UP LIGHTS					
			27	ELECTRICAL SYSTEM	99	

	01-2024-195	REPAIR CLOSED	01/10/2024	C		
	JOHN HOGAN ORDERED PARTS FOR V PLOW NOSE SHOE					

AS PER 2023 W/O 5059

Equipment ID	Work Order ID	Job Type	Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							64	GROUND ENGAGING TOOLS	99

	01-2024-522	REPAIR	CLOSED	02/06/2024		C			
JOHN HOGAN EMAILED IN FOR BLADE BOLTS									
							64	GROUND ENGAGING TOOLS	99
							27	ELECTRICAL SYSTEM	99

	01-2024-654	REPAIR	CLOSED	02/21/2024		C			
STEERING CODES PROMPTING UNIT SHUT DOWN.									
**COULD NOT GET THE CODE TO SHOW WHILE TESTING THE MACHINE. NO DAMAGE TO HARNESS OR CONNECTORS. RESISTORS PINS OUT OK. POTENTIAL ISSUE IN THE VALVE/ACTUATORS. DECISION WAS MADE TO REPLACE THE ENTIRE STEERING VALVE RATHER									
							69	TRAVEL TIME	
							44	STEERING	99

	01-2024-1647	REPAIR	CLOSED	05/03/2024		C			
JOHN HOGAN EMAILED TO REQUEST A FIRST AID KIT									
							86	SAFETY SUPPLIES	99

	01-2024-1753	REPAIR	CLOSED	05/14/2024		C			
MAY 13/24 WENT TO UNIT HOOKED UP GAUGES. SYSTEM WAS LOW. CHARGED UP AND NOW RUNNING AT ALSO BLEW OUT OUTER CAB FILTER. -2F-PWB OPERATOR ALSO BLEW OUT RAD WHILE I WAS THERE									
							69	TRAVEL TIME	
							34	AIR CONDITIONING AND HEATING	

	01-2024-1847	REPAIR	CLOSED	05/21/2024		C			
HAD OPERATOR INSTALL LOCK PIN AND STEERING PROBLEM WENT AWAY DUE TO ARTICULATION WORN.									
MAY 21/24 WENT TO UNIT AND FOUND THE ARTICULATION PINS ARE WORN ALSO BUSHINGS									
							69	TRAVEL TIME	
							18	FASTENERS & TIE DOWNS	99
							48	FRAME AND CHASSIS	
							58	ATTACHMENTS	99

	01-2024-1877	PM	CLOSED	05/22/2024					
PM 500 HOUR SERVICE BY OPERATOR									
COMPLETED 26 JUN 2024									
INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.									

CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE
CHECK/CHANGE AIR FILTERS

				M	ANNUAL INSPECTION	
				A	A PREVENTIVE MAINTENANCE IN	
				37	HYDRAULIC SYSTEM	99
				20	FUEL SYSTEM	99
				11	AIR INTAKE SYSTEMS	99
				00	ENGINE	99

01-2024-1948 REPAIR CLOSED 05/27/2024 C
JOHN HOGAN EMAILED IN FOR ENGINE OIL

				00	ENGINE	99
--	--	--	--	----	--------	----

01-2024-2614 REPAIR CLOSED 07/03/2024 C
BRADEN CAME IN AND TOLD ME TO GET THE EXTINGUISHER FOR UNIT AND JOHN WOULD BE IN TO PICK IT UP

				86	SAFETY SUPPLIES	99
--	--	--	--	----	-----------------	----

01-2024-2863 REPAIR CLOSED 07/16/2024 T
TIRE WAS LEAKING TURNED OUT TO BE THE O RING SEAL CHANGED O RING

				08	TIRES AND RIMS	
--	--	--	--	----	----------------	--

01-2024-3311 PM CLOSED 08/08/2024
RESAMPLE HYDRAULIC OIL HIGH PARTICULATE INCREASE FROM PREVIOUS SAMPLE

DROVE TO UNIT SOUTH OF OYEN AND TOOK SAMPLE

				A	A PREVENTIVE MAINTENANCE IN	
				M	ANNUAL INSPECTION	
				69	TRAVEL TIME	
				67	SERVICE	

01-2024-3312 PM CLOSED 08/08/2024 I
BOTH WHEEL BEARING COMPONENTS EXHIBITING ELEVATED IRON AND CHROMIUM, INDICATING LOSS OF PRELOAD AND EXCESSIVE WEAR

DROVE TO UNIT SOUTH OF OYEN, CHECKED WHEEL BEARINGS AND NO ISSUES COULD BE

				66	INSPECTIONS / DIAGNOSTICS	
				M	ANNUAL INSPECTION	
				A	A PREVENTIVE MAINTENANCE IN	

01-2024-3344 REPAIR CLOSED 08/09/2024 T
TRAVEL 85/27-0 LEFT FRONT DRIVE TIRE LEAKING O RING CHANGE O-RING LEFT REAR DRIVE A BIT LOW ADDED AIR

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							08	TIRES AND RIMS	
	01-2024-4480	REPAIR	CLOSED	10/23/2024		C			
	JOHN HOGAN EMAILED IN FOR COOLANT AND HYD OIL								
							00	ENGINE	99
							02	TRANSMISSION	99
	01-2024-4510	REPAIR	CLOSED	10/25/2024		C			
	DURING SERVICE IN CEREAL, JOHNNY HOGAN CALLED AND REQUESTED I RUN A FEW JUGS OF COOLANT TO HIS OPERATOR JUST NORTH OF TOWN AS HE HAD A MAJOR COOLANT LEAK AND IT STARTED TO OVERHEAT. GOT TO UNIT AND FOUND THE HOSE ON THE RESERVOIR CAME LOOSE AND PUKED A LOT OF COOLANT OUT. REATTACHED AND DID THE CLAMP UP, FIGURED IT COOLED OFF BY THE TIME I GOT THERE IN THE COLD W								
							21	COOLING SYSTEM	
	01-2024-5100	REPAIR	CLOSED	12/10/2024		C			
	OPERATOR STATES THERE IS MULTIPLE ALARMS RELATED TO THE PARK BRAKE AND THE TRANSMISSION TEMP.								
	MULTIPLE DAMAGED WIRES CAUSING ISSUES IN THE REAR MAIN HARNESS.								
	177-3: TRANSMISSION OIL TEMP SENSOR; VOLTAGE ABOVE NORMAL								
							27	ELECTRICAL SYSTEM	
							69	TRAVEL TIME	
	01-2025-796	REPAIR	CLOSED	02/28/2025		C			
	FEB 28/25 FOUND THE STARTER IS LEAKING OIL AND TRANSMISSION VENT WAS LEAKING OIL POSSIBLE OVERFULL AT ONE TIME.CLEANED VENT. ALSO HEUI PUMP MOUNT SEAL LEAKING. ENGINE OILCOOLER LEAKING. ORDERED PARTS FEB 28/25								
	MAR 6/25 REPLACED BALLS AND GASKET ON STARTER AND SILICONED GASKET ON BALL SIDE. REPLACED HOUSING GASKET ON HIEU PUMP ALSO REPLACED GASKETS ON ENG								
							69	TRAVEL TIME	
							66	INSPECTIONS / DIAGNOSTICS	
							67	SERVICE	99
							21	COOLING SYSTEM	99
							02	TRANSMISSION	
							00	ENGINE	
	01-2025-1103	PM	CLOSED	03/31/2025		O			
	PM 12000 HOUR SERVICE								
	COMPLETED 3 APR 2025								
	INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST								
	CHANGE FUEL FILTERS								
	CHECK AIR PRECLEANER								
							00	ENGINE	99
							02	TRANSMISSION	99
							11	AIR INTAKE SYSTEMS	99
							20	FUEL SYSTEM	99
							37	HYDRAULIC SYSTEM	99

			34	AIR CONDITIONING AND HEATIN	99
			67	SERVICE	
			69	TRAVEL TIME	
			A	A PREVENTIVE MAINTENANCE IN	
			M	ANNUAL INSPECTION	

01-2025-1104 PM CLOSED 03/31/2025

PM VALVE TRAIN INSPECTION

INSPECT VALVE TRAIN AND INJECTOR WIRING HARNESS

ADJUST VALVE CLEARANCES AS REQUIRED

CONSIDER REPLACING HARNESS IF WIRES ARE EXCESSIVELY HARD OR HAVE BEEN PREVIOUSLY SPLICED

			M	ANNUAL INSPECTION	
			A	A PREVENTIVE MAINTENANCE IN	
			69	TRAVEL TIME	
			67	SERVICE	99
			00	ENGINE	

01-2025-1699 REPAIR CLOSED 05/15/2025 C

TRAVEL TO UNIT SOUTH OF THE 570 WATER BUILDING

-FOLLOW TRAIL OF OIL LEAKED ON THE ROAD TO THE GRADERS LOCATION

-DUMP SOME OIL INTO MACHINE FOR TESTING AS IS HAD NONE IN IT

-FOUND MAIN FAN HOSE RUNNING FROM THE PUMP ACROSS THE DIFF UNDER THE ENGINE TO THE VALVE BLOCK HAD BLOWN OUT, CAUSING RAPID EXPULSION OF FLUID ONT

			37	HYDRAULIC SYSTEM	99
			66	INSPECTIONS / DIAGNOSTICS	
			69	TRAVEL TIME	

01-2025-1770 REPAIR CLOSED 05/23/2025 C

			00	ENGINE	99
--	--	--	----	--------	----

01-2025-2165 REPAIR CLOSED 06/17/2025 T

INTEGRA TIRE FIXED THIS TIRE AT THE CEREAL SHOP

			08	TIRES AND RIMS	99
--	--	--	----	----------------	----

01-2025-2685 PM CLOSED 07/24/2025 O

PM 500 HOUR SERVICE BY OPERATOR

COMPLETED 5 AUG 2025

INSPECT AND MAINTAIN MACHINE AS PER CHECKLIST.

CHANGE ENGINE OIL AND FILTER, OBTAIN SAMPLE

CHECK/CHANGE AIR FILTERS

			67	SERVICE	99
			M	ANNUAL INSPECTION	

Work Orders List
by Equipment ID

Equipment ID	Work Order ID	Job Type	Work Order Status	Work Order Open Date	Work Class	Repair Reason	Task ID	Task Description	WAC
							A	A PREVENTIVE MAINTENANCE IN	
	01-2025-3255	REPAIR	CLOSED	09/02/2025		C			
	TRAVEL TO UNIT SOUTH OF CEREAL FROM JOB NORTHEAST OF OYEN. GET THERE AND CONFIRM AC IS WEAK BUT WORKING. RECOVERED ROUGHLY 2.3LBS FROM THE SYSTEM. RECHARGED TO SPEC (3.9LBS) AND TESTED TO MAKE SURE IT WAS COLDER AND IT WAS GOOD. PACKED UP AND RETURNED TO YTOWN.								
							69	TRAVEL TIME	
							34	AIR CONDITIONING AND HEATIN	
	01-2025-3496	REPAIR	CLOSED	09/18/2025		C			
	BRUCE G CALLED IN FOR OIL. DARCY MILLER PICKED UP.								
							00	ENGINE	99
	01-2025-3659	REPAIR	CLOSED	09/30/2025		C			
	BRUCE G PICKED UP BLADE BOLTS								
							57	CIRCLE AND MOLDBOARD	99

-----END OF REPORT-----