T15-1
DEC

Maintenance Log

Date Started	Unit	Make/Model
Sept 6/2026	Single axle	Kenworth
Date Finished	**Mileage**	**Year**
Sept 17/2026	318 168 20 670 kms	2018
Location	**License Plate #**	**SN#**
Shop	T 370	2NKHHN8X4CM456324

Type of Maintenance: ~~J45043~~.

Description of Repairs:

Service air + oil + Grease
Change rear spring pin bushings both sides
Change fan belt
Measure brakes
Remove Hyd cylinder to repair leak
Repaired bent mirror brackets
Repaired loose steps on walking deck
Changed fuses for left rear signal and back up lights

Parts Used:

Fan belt 0808427HD
Air Filters
Oil Filters
19L 15w40
2 Spring pin bushings
1- Windshield.

Follow-Up, if Required:

Work Performed By: Mark Berger.

Management Sign Off:

Maintenance Log

Date Started	Unit	Make/Model
Dec 02/24	20253 hrs	T370 KW
Date Finished	**Mileage**	**Year**
Dec 02/24	31919	2012
Location	**License Plate #**	**SN#**
RF	JG8973	2NKHHN8X4CM956324

Type of Maintenance:
Services & Check over

Description of Repairs:
Replace passangers head light bulb.
Change oil & filter, grease
Set back brakes

Parts Used:
1-H11 55w-bulb . 1-1748 oil filter . 22L. 15w-40 .
- bulk grease .

Follow-Up, if Required:

Work Performed By: Peter

Management Sign Off:

Maintenance Log

Sept 01 2024

Date Started	Unit	Make/Model
~~July 5 2024~~	T370 -	Kenworth
Date Finished	**Mileage**	**Year**
Sept 01 2024	306.552 km	T370
Location	**License Plate #**	**SN#**
RedEarth	J48973	2NKHHN8X4CM956324

Type of Maintenance:
Service, grease inspect Replace Rear shocks - Cvip.

Description of Repairs:
Replace Rear shocks.
Measure shoes & drums

Parts Used:
2-65411, 1-air filter 1-Oil filter 22L-15w-40

Follow-Up, if Required:
No

Work Performed By:
[signature]

Management Sign Off:

Maintenance Log

Date Started	Unit	Make/Model
Aug 4 /23		T-370 Kenworth
Date Finished	Mileage	Year
Aug 5/23	288074	2012
Location	License Plate #	SN#
Red Earth Creek	J48913	2NKHHN8X4CM956324

Work Required: Pre inspection for CVIP.

Description of Repairs:
Remove wheels & drums measure & inspect brakes & drums
Replace front spring bushing & assemblies.
Replace Rear Spring wear Pads.

Parts Used:
2- Spring Pin assemblies - front -
2 - Spring seat wear Pads. 56557-004
Hendrickson 2 Leaf wear pad kit (Lonetech)

Follow-Up, if Required:
None.

Work Performed By: [signature]

Management Sign Off: [signature]

Maintenance Log

Date Started	Unit	Make/Model
July 31/22		Kw. T370
Date Finished	**Mileage**	**Year**
Aug 03/22	270,339 Km	2012
Location	**License Plate #**	**SN#**
Shop	J48973	2NKHHN8X4CM956324

Work Required:

Pre - CVIP

Description of Repairs:

Replace front seals, Remove all tires drums. Measure
Replace broken muffler & stack. torque wheels 450 ft
Replace Rear brake Pots & 2-24" air Lines

Parts Used:

2-Hub caps. RC-HC4024 (x2) Reorder Please
2-front seals stemco 382-8036 (x2) Reorde please
1-3" to 5" adaptor 1-5" muffler. 1-windshield.
2-3030 Brake Pots. 2-24" air Lines 1-filter kit trans.
#29548988

Follow-Up, if Required:

20L-trans fluid

Work Performed By: [signature]

Management Sign Off:

Kent Landon

780-467-1488