F.19-1
DEC

Work Order No.	EQUIPMENT	Description	Type of Service	Hours/KM	Task (Time code)	Date Complete (Leave Blank if Not Closed)	Name
VIK1964A	CC-003	Mpunt deck , tools boxes			reactive	09-Apr-19	Brett
VIK2020	CC-003	Installed GPS			reactive	02-May-19	Brendan
VIK2282	CC-003	Service (oil change replaced filter, inspected, checked fluids, topper washer fluid		17447		12-Oct-19	Brendan
VIK3526	CC-003	Service Engine and air, service, check over, book and send to Ford for steering wheel shakes	Proactive	44,405	11, 10	14-Aug-20	Kyle, Brett
VIK3569	CC-003	125/122Q E WRL Duratrac BSL TL, balance, TPMS Reset or New valve stem	Reactive	44,444	26, 16	17-Aug-20	Brett, Kyle, Foutain Tire
VIK3865	CC-003	Service engine and air. Grease front end.	Proactive	51,600	11	13-Oct-20	Kyle Stegmaier
VIK4435	CC-003	Semi-Annual - Light Duty. Regular Service - GAS. Service engine, wire and install beacon light.	Proactive	57,696	11	09-Apr-21	Brett Cissell
VIK4509	CC-003	Replaced light. Rotated tires front to back. Torqued lug nuts to 150ft/lb. Placed re-torque tag in cab (Dan Theoret).	Proactive	3,449 / 59,663	11	26-May-21	Dan Theoret
VIK4718	CC-003	air filters. Replaced burnt out RH front headlight bulb (Dan Theoret).	Proactive	3,673 / 65,715	11	07-Sep-21	Dan Theoret
VIK4923	CC-003	transfer case oil. Replaced engine, cab air filters. Replaced hood latch sensor (Dan Theoret).	Proactive	4,002 / 73,829	11	02-Dec-21	Dan Theoret
VIK5172	CC-003	Rotated tires front to back. Torqued lug nuts to 165 ft/lbs. Placed retorque tag in cab (Dan Theoret).	Proactive	4,487 / 82,246	11	18-Mar-22	Dan Theoret
VIK5376	CC-003	McLeod).	Proactive	89,075	11, 25, 89	04-Jul-22	Mike McLeod
VIK5509	CC-003	Need to check air bag light code on. Needs new tires all round before winter or earlier (Mike McLeod).	Proactive	95,631	11	15-Aug-22	Mike McLeod
VIK5628	CC-003	leak. Checked evap lines and found no cracked or broken fittings. Clear code for now. Screw license plate back on	Proactive	103,434	11	26-Sep-22	Mike McLeod
VIK5799	CC-003	Inspection	Proactive	1	910	24-Nov-22	Brent Blake
VIK5803	CC-003		Proactive	2	910	25-Nov-22	Brent Blake
VIK5808	CC-003	Regular Service - Gas. Change engine oil & filter. CHNGD AIR & CAB FLTRS.	Proactive	114885km	911	27-Nov-22	Mike McLeod
VIK6067	CC-003	Regular Service Gas. Change Engine Oil & Filter.	Proactive	123460km		13-Feb-23	Kyle Stegmaier
VIK6197	CC-003	Install hitch	Proactive		920	10-May-23	Kyle Stegmaier
VIK6198	CC-003	Drill holes in frame. Install spacers. Install hitch.	Proactive		920	11-May-23	Kyle Stegmaier
VIK6199	CC-003	Find proper trailer wire color codes and install traile rplug.	Proactive		919	11-May-23	Kyle Stegmaier
VIK6420	CC-003	Service and servcice on front and rear diffs.	Proactive		911	19-Jun-23	Mike McLeod
VIK6455	CC-003	Service	Proactive		911	17-Jul-23	Mike McLeod
VIK6476	CC-003	Change filter a oil in tranny. Get 4 new tires put on.	Proactive		917	04-Aug-23	Mike McLeod
VIK6485	CC-003	Order tie rod. Change right side lower tie rod & test drive.	Reactive		920	05-Aug-23	Mike McLeod
VIK6357	CC-003	Service Engine	proactive	156038 KMS	911	18-Aug-23	Kyle Stegmaier
VIK6533	CC-003	Remove sign racks and sand bags off deck. Remove deck boards and replace fuel pump.	Reactive	161642 KMS	914	17-Sep-23	Kyle Stegmaier
VIK6539	CC-003	Service engine air and trans oil and filter - extracted broken bolt.	Proactive	161627 kms	911	19-Sep-23	Kyle Stegmaier & Mike Mcleod
VIK6605	CC-003	Take passenger side toolbox door off. Hammer out bent tool box. Drill and bolt door back on & set door handle	Reactive		920	07-Oct-23	Mike McLeod
VIK6661	CC-003	Service Engine - grease fron u joints	Proactive	175652kms	911	09-Nov-23	Kyle Stegmaier
VIK6689	CC-003	Replace signal light bulb	Reactive		919	16-Nov-23	Kyle Stegmaier
VIK6754	CC-003	Inspect	Proactive		910	18-Dec-23	Kyle Stegmaier
VIK6794	CC-003	Get running - order parts	proactive		980	11-Jan-24	Kyle Stegmaier
VIK6795	CC-003	front brake pads.	Proactive	186710 KMS	911	15-Jan-24	Kyle Stegmaier
VIK6799	CC-003	Replace rear drive shaft	Reactive		917	16-Jan-24	Kyle Stegmaier
VIK6846	CC-003	Drop off for seat repair.	Reactive		920	15-Feb-24	Kyle Stegmaier
VIK7528	CC-003	New windshield	Reactive		920	11-Mar-24	Arby's Glass
VIK6907	CC-003	Replace leaking AC line and recharge AC system	Reactive		913	18-Mar-24	Kyle Stegmaier
VIK6910	CC-003	Order parts, replace starter, replace spark plug coil #1	Proactive	186768 kms	911	19-Mar-24	Kyle Stegmaier
VIK7017	CC-003	Service #. Chip out packed direct up around tranny linkages and wiring. Check # over and top up fluids.	Proactive	193368 KMS	911	18-Jun-24	Mike McLeod
VIK7105	CC-003	Bring in # and check over. Start chipping out packed dirt up on tranny and transfercase.	Proactive		917	11-Jul-24	Mike McLeod
VIK7107	CC-003	Continue chipping packed dirt up on tranny and transfercase & rims. Wash underneath out and rims.	Reactive		917	12-Jul-24	Mike McLeod
VIK7150	CC-003	Replace cab filter.	Reactive		911	17-Jul-24	Kyle Stegmaier
VIK7156	CC-003	Purchase cab filter	Reactive		911	17-Jul-24	Kyle Stegmaier
VIK7182	CC-003	Engine overheated. Found rads extremely plugged. Remove rad shroud and grill. Wash out rads.	Reactive		913	21-Jul-24	Kyle Stegmaier
VIK7238	CC-003	Inspect truck vibration. Mud in wheels.	Reactive		910	04-Aug-24	Kyle Stegmaier
VIK7254	CC-003	Service. Check over front end and wheel bearings. Check over # and greased. Washed rads out.	Proactive	198830 KMS	911	09-Aug-24	Mike McLeod
VIK7611	CC-003	Replace battery	Reactive		919	07-Apr-25	Mike McLeod

LSL7779	CC-003	Hooked up AC gauges to unit and found that the pressures were low. Added 0.6lbs of refrigerant to get the pressures	Reactive		913	30-May-25	Brown's Industrial Sales Cold Lake
LSL7785	CC-003	Check fuse on horn not working. Give Kyle a hand to take out A/C commpressor and put in new one.	Reactive		913	05-Jun-25	Mike Mcleod
LSL7799	CC-003	Service Engine. Replace AC compressor.	Reactive	217459 KMS	911	05-Jun-25	Kyle Stegmaier
LSL7786	CC-003	Replaced air and cab filters. Check wiring and test for horn not working.	Reactive	217459 KMS	919	06-Jun-25	Mike McLeod
LSL7804	CC-003	Recharge AC System.	Reactive		913	08-Jun-25	Kyle Stegmaier
LSL7915	CC-003	Changed oil and filter, air filter - good, changed cab filter. Check # over and top up fluid and greased. Changed front end and passenger sid wheel bearing. Ordered wheel bearing hub and replaced on front passenger side.	Reactive	222683 KMS	911	02-Jul-25	Mike McLeod
LSL8045	CC-003	Wheel Balance, TPMS reset or new valve stem	Reactive		916	24-Jul-25	Fountain Tire
LSL8051	CC-003	Horn inoperable from key and from steering wheel. Disconnected horn and applied power to it. Pass. Checked ground. Pass. Checked for power. None. Checked fuse. Good. Moved onto relay and found it's missing. Swapped A/C comp relay to horn relay position. Horn now sounds. Need to install a new relay and it will be good. MPI completed. Engine air filter dirty. Need to install relay in A/C clutch position of fuse box. RH inner axle tube seal leaking. Cel on. Engine oil dipstick broken. Multiple lights out. Tires worn out. Long drag link and track bar ball joint loose. Install new relay into fuse box - Horn/A/C relay. Installed relay, tested function. All okat at this time. Removed engine air filter. RH fender liner, started, trans dipstick tube, etc. to gain access and room to remove old tube. Found tube was seized into engine and had to heat up block, cut tube in order to turn aan remove it. Contacted advisor for additional time. Adjusted and routed new tube. Applied anti-seize to tube and reinstalled all that was removed for access. Installed dipstick. All okay. Perform 2 wheel alignment. Uneven wear/loose steering. Removed and replaced long drag link. All okay. Removed and replaced track bar balljoint and bushing. All okay	Reactive	226351 KMS	920	28-Jul-25	Lacombe Ford
LSL8101	CC-003	Bring # in. Changed oil and filter, air and cab filters. Check # over and top up fluid levels. Replaced rear brake pads and lube caliper slide pins. Take carburetor intake off and clean carb out and put back together. Weld change link on sign holder frame and make secure cable for signs. Park #.	Reactive		911	09-Aug-25	Mike McLeod
LSL8245	CC-003	Changed oil and filter, air and cab filters. Check over # and greased. Top up fluids. Washed # and Rads out and engine compartment.	Proactive	232835 KMS	911	13-Sep-25	Mike McLeod
LSL8306	CC-003	Bring in #. Troubleshoot misfiring - check coils, spark plug leads, etc. Order parts.	Reactive	236063 KMS	913	01-Oct-25	Mike McLeod
LSL8309	CC-003	Replaced #3, #5, and #8 coils and check spark plugs. Order new spark plugs and replaced all plugs and torqued to 18 FT/LBS. Dig out cracked out broken spark plug boot stuck down in #4 spark plug hole. Cleaned PCV valve on passenger side. Replaced back up camera.	Reactive	236063 KMS	913	02-Oct-25	Mike McLeod
LSL8311	CC-003	Pick up coil from Lacombe Ford. Put new coil in #4 spark plug. Put intake back on and clear codes. Test drive #.	Reactive		913	03-Oct-25	Mike McLeod
LSL8314	CC-003	Fire up RE-071 and bring in and unstrap sliptank and feed wiring out from battery and put slip tank on CC-003 and feed wiring to battery and hook up to battery bolt down slip tank and fix leaking fuel nozzle ready for Maury's worker to pick up.	Reactive		924	04-Oct-25	Mike McLeod
LSL8407	CC-003	Service and changed drivers headlight.	Reactive	241,200 KMS	911	30-Oct-25	RPM Mechanical
LSL8512	CC-003	Fire up # and warm up and bring in. Changed oil, filter, air and cab filters ok. Check # over and top up fluids and grease. Changed signal bulb on front drivers side and test. Park #.	Reactive	249480 KMS	911	04-Dec-25	Mike McLeod
LSL8647	CC-003	Diagnosed bad erg valve	Reactive		913	20-Jan-26	RPM Mechanical Services
LSL8649	CC-003	Left rear idler replacement	Reactive		920	21-Jan-26	RPM Mechanical Services
LSL8706	CC-003	Changed oil & filter, air filter ok. Changed cab filter. Checover # and greased and top up fluids. Order and replaced both hood shocks.	Reactive	255534 KMS	911	17-Feb-26	Mike McLeod
LSL8828	CC-003	Replaced alternator	Reactive		919	24-Mar-26	RPM Mechanical Services
LSL8842	CC-003	Changed oil and filter, air and cab filters - Ok. Check over # and top up fluids. Replaced both windsheild wiper blades. Take all wheels off and clean rims and rotate tires. Adjust air pressure levels on tires. Replaced both side mirrors motors and test. Replaced driver's side seat belt locking buckle.	Proactive	260260 KMS	911	03-Apr-26	Mike McLeod
LSL9356	CC-003	Service.	Proactive	279415 kms	911	25-Aug-26	QuickLane (Edmonton)
LSL9689	CC-003	looked at bad driveline	Reactive		917	27-Oct-26	RPM Mechanical Services (Taye)
LSL9682	CC-003	pulled drive shaft and took in for rebuild	Reactive		917	28-Oct-26	RPM Mechanical Services (Jaimy)
LSL9699	CC-003	new drive line	Reactive		917	31-Oct-26	RPM Mechanical Services (Taye)
LSL9732	CC-003	radiator replacement	Reactive		913	12-Nov-26	RPM Mechanical Services (Taye)

Land
Equipment = 5, Status = 1

Record#	Trans#	Date	Description	Vendor/Employee/Equipment	Type	
10164	307546	07/28/2025	Front end work	138 Lacombe Ford Sales Ltd.	4	Subcontract
10167	0581100304	07/24/2025	New tires	107 Fountain Tire	4	Subcontract
10928	462958	09/16/2025	Backup camera	138 Lacombe Ford Sales Ltd.	1	Material
11134	463735	10/01/2025	Coils	138 Lacombe Ford Sales Ltd.	1	Material
11206	463810	10/03/2025	Coils	138 Lacombe Ford Sales Ltd.	1	Material
11207	463782	10/02/2025	Coils	138 Lacombe Ford Sales Ltd.	1	Material
11645	1343	11/02/2025	Mechanic services Oct 27-Nov 1	627 RPM Mechanical Services	4	Subcontract
11653	1343	11/02/2025	Mechanic services Oct 27-Nov 1	627 RPM Mechanical Services	1	Material
11662	500-889599	10/30/2025	Oil	629 Northern Metalic Sales(R.M.) Ltd.	1	Material
12758	1370	01/27/2026	Mechanic services (Jan 19-23)	627 RPM Mechanical Services	4	Subcontract
12760	1370	01/27/2026	Mechanic services (Jan 19-23)	627 RPM Mechanical Services	4	Subcontract
13032	469657	02/17/2026	Lift assy	138 Lacombe Ford Sales Ltd.	1	Material
13445	471016	03/24/2026	Alternator	138 Lacombe Ford Sales Ltd.	1	Material
13520	1387	03/30/2026	Mechanic services (03/21-03/28)	627 RPM Mechanical Services	4	Subcontract
13544	471304	03/31/2026	Door mirror drive motor	138 Lacombe Ford Sales Ltd.	1	Material
13584	471356	04/01/2026	Seat belt	138 Lacombe Ford Sales Ltd.	1	Material
14857	1686-139188	06/17/2026	Oil, air filter	11 Uni-Select Inc.	1	Material
1500	59	04/10/2021	Repairs	228 Gun Metal Mechanical	4	Subcontract
1511	LR100161109	03/31/2021	V-First	139 Lacombe Registries Ltd.	4	Subcontract
15370	033FT0002194	07/06/2026	Flat repair	107 Fountain Tire	4	Subcontract
16292	637999	08/25/2026	Oil change		4	Subcontract
16352	715FT0001518	08/29/2026	New tires	107 Fountain Tire	4	Subcontract
1705	060521	06/05/2021	Supplies	260 Diaz, Sebastian	1	Material
17509	479392	10/28/2026	U-joint kit	138 Lacombe Ford Sales Ltd.	1	Material
17545	6216680-00	10/30/2026	Weld yoke, install u-joints, steady bearing	706 Pat's Driveline	4	Subcontract
17631	1474	11/02/2026	Mechanic Service-Taye (10/26-10/31)	627 RPM Mechanical Services	4	Subcontract
17639	1474	11/02/2026	Mechanic Service-Taye (10/26-10/31)	627 RPM Mechanical Services	4	Subcontract
17655	1473	11/02/2026	Mechanic Service-Jaimy (10/26-10/31)	627 RPM Mechanical Services	4	Subcontract
17756	059-905777	11/12/2026	Air flow cleaner, rubber step	22 Gregg Distributors Co. Ltd.	1	Material
17857	1480	11/16/2026	Mechanic service-Taye (11/09-11/15)	627 RPM Mechanical Services	4	Subcontract
17863	1480	11/16/2026	Mechanic service-Taye (11/09-11/15)	627 RPM Mechanical Services	1	Material
1981	397418	09/07/2021	Turn signal bulbs	138 Lacombe Ford Sales Ltd.	1	Material
1984	578-697352	09/07/2021	Turn signal bulbs	134 NAPA Auto Parts-Lacombe	1	Material
251	Tirecraft	11/23/2019	Service	17 Smith, Myles	2	Labour
2606	10315	08/27/2022	Doug Newell	155 Spirit Wolf Projects	1	Material
2719	0581082305	09/23/2022	Changeover	107 Fountain Tire	4	Subcontract
3381	1369590	02/13/2023	Oil, filters	368 Veg Auto & Industrial(2013) Supply Ltd.	1	Material
3472	426734	04/13/2023	Brake pads	138 Lacombe Ford Sales Ltd.	1	Material
3473	426828	04/13/2023	Thermostat and seal	138 Lacombe Ford Sales Ltd.	1	Material
3474	426843	04/14/2023	Brake caliper anchor	138 Lacombe Ford Sales Ltd.	1	Material
3491	0801078650	04/18/2023	Flat repair	107 Fountain Tire	4	Subcontract
3603	1686-77497	05/12/2023	Safety pins	11 Uni-Select Inc.	1	Material
3613	427951	05/09/2023	Hitch and pin	138 Lacombe Ford Sales Ltd.	1	Material
3641	1009	05/20/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
3839	6739053123	05/31/2023	To record May VISA expenses		1	Material
3840	6739053123	05/31/2023	To record May VISA expenses		4	Subcontract
4021	6739063023	06/30/2023	To record June VISA expenses		4	Subcontract
4113	430955	07/18/2023	Filter, additive	138 Lacombe Ford Sales Ltd.	1	Material
4118	431022	07/18/2023	Filter, additive	138 Lacombe Ford Sales Ltd.	1	Material
4328	0581087270	08/04/2023	Flat repair/changeovers	107 Fountain Tire	4	Subcontract
4391	431917	08/09/2023	Sender, gasket	138 Lacombe Ford Sales Ltd.	1	Material
4419	1018	08/19/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract

458	1686-20166	05/06/2020	Fuel hose, hitch, fuses	11 Uni-Select Inc.	1	Material
459	1686-20160	05/06/2020	Fuel hose, hitch, fuses	11 Uni-Select Inc.	1	Material
460	1686-20159	05/06/2020	Fuel hose, hitch, fuses	11 Uni-Select Inc.	1	Material
4647	433862	09/19/2023	Filters, battery	138 Lacombe Ford Sales Ltd.	1	Material
4648	433838	09/18/2023	Filters, battery	138 Lacombe Ford Sales Ltd.	1	Material
4662	1023	09/23/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
4822	0581088353	10/06/2023	Flat repair	107 Fountain Tire	4	Subcontract
489	1686-20262	05/07/2020	Fuel hose, hitch, fuses	11 Uni-Select Inc.	1	Material
490	1686-20180	05/06/2020	Fuel hose, hitch, fuses	11 Uni-Select Inc.	1	Material
4900	1686-85635	10/11/2023	Seat covers	11 Uni-Select Inc.	1	Material
4914	3353	10/04/2023	Truck Wash	215 2639864 Alberta Ltd.	3	Equipment
5126	312023	10/31/2023	To record October VISA expenses		4	Subcontract
5203	1030	11/11/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5322	1031	11/18/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5553	IN0006547	11/09/2023	Flat repair	500 TreadPro Wainwright	4	Subcontract
5618	1036	12/23/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5697	3425	01/04/2024	Washes	215 2639864 Alberta Ltd.	1	Material
5728	1037	01/13/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5757	439007	01/11/2024	Belt, tensioner, idlers	138 Lacombe Ford Sales Ltd.	1	Material
5766	439152	01/16/2024	Drive shaft	138 Lacombe Ford Sales Ltd.	1	Material
5772	1038	01/20/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5905	440309	02/07/2024	Filter, gasket	138 Lacombe Ford Sales Ltd.	1	Material
5956	1042	02/17/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
6060	02292024	02/29/2024	To record February VISA expenses		1	Material
6118	2070	03/11/2024	Windshield (CC-003)	202 Arby's Glass	4	Subcontract
6144	441915	03/19/2024	Starter, spark plug coil	138 Lacombe Ford Sales Ltd.	1	Material
6149	441761	03/14/2024	AC Line	138 Lacombe Ford Sales Ltd.	1	Material
6166	1047	03/23/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
6201	03312024	03/31/2024	To record March VISA expenses		4	Subcontract
6429	3511	05/02/2024	Equipment Washes	215 2639864 Alberta Ltd.	1	Material
6604	CM441915	03/19/2024	Starter, spark plug coil	138 Lacombe Ford Sales Ltd.	1	Material
6821	1686-98407	06/18/2024	Oil	11 Uni-Select Inc.	1	Material
7198	1068	07/16/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
7204	1068	07/16/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
7230	1068	07/16/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
7417	1070	08/03/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
829	0581070573	08/17/2020	New Tires	107 Fountain Tire	1	Material
8308	452507	12/13/2024	Lift assemblies	138 Lacombe Ford Sales Ltd.	1	Material
8456	2602	04/05/2025	Windshield	202 Arby's Glass	4	Subcontract
8468	456643	04/07/2025	Battery	138 Lacombe Ford Sales Ltd.	1	Material
9305	W14949	06/05/2025	Diagnose AC issue	575 Brown's Industrial Sales	4	Subcontract
9309	458989	06/05/2025	AC o-ring, kit	138 Lacombe Ford Sales Ltd.	1	Material
9334	1096	06/07/2025	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
9340	1096	06/07/2025	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
9636	459908	06/30/2025	Seal assembly, hardware	138 Lacombe Ford Sales Ltd.	1	Material
9637	459906	06/30/2025	Seal assembly, hardware	138 Lacombe Ford Sales Ltd.	1	Material
9638	459900	06/30/2025	Hub assy	138 Lacombe Ford Sales Ltd.	1	Material
9782	460050	07/04/2025	Brake pads	138 Lacombe Ford Sales Ltd.	1	Material