F19-2
DEC

Work Order No.	EQUIPMENT	Description	Type of Service	Hours/KM	Task (Time code)	Date Complete (Leave Blank if Not Closed)	Name
VIK2183	CC-009	Unload; Test run; Remount GPS to fix issue of interfering with brake switch; test run-good		15547		09-Sep-19	Brett
VIK2216	CC-009	Service (oil change, replace air filter, Inspection, Topped washer fluid, Light check)		17682		20-Sep-19	Brendan
VIK3541	CC-009	CVIP	Proactive	30,812	11	28-Apr-20	DMC Heavy Duty
VIK3659	CC-009	Service Engine, grease, rotate tires	Proactive	48,517	11, 16	04-Sep-20	Kyle
VIK3988	CC-009	Change oil and filter, air filter, cab filter. Check fluid levels and check # over. Replaced driver side tail light.	Proactive	56,247	11	30-Oct-20	Mike McLeod
VIK4438	CC-009	Wire and install beacon lights.	Reactive	57,230		09-Apr-21	Brett Cissell
VIK4538	CC-009	Rear brake pads, rotors replaced. Rotated tires front to back. Back up beeper found to be non-operational. Replaced	Proactive	2,338 / 62,733	11	11-Jun-21	Dan Theoret
VIK4677	CC-009	engine oil and filter. Replaced transmission oil and filter. Replaced engine and cab air filters. Deck mounted toolbox	Proactive	2,587 / 69,830	11	16-Aug-21	Dan Theoret
VIK4740	CC-009	**Repair.** Replaced broken front driver door window (Dan Theoret).	Reactive	2,697 / 73,048	20	21-Sep-21	Dan Theoret
VIK4796	CC-009	**Repair.** Replaced broken front driver door glass (Dan Theoret).	Reactive	2,738 / 75,181	20	10-Oct-21	Dan Theoret
VIK4889	CC-009	Replaced engine, cab air filters. Rotated tires front to back. Torqued lug nuts to 165 ft/lbs. Placed retorque tag in cab.	Proactive	2,953 / 77,452	11	22-Nov-21	Dan Theoret
VIK4925	CC-009	broken mirror lense (Dan Theoret). Put Viking stickers on. Put in radio brkt and radio. Put in antenna (Mike McLeod).	Reactive	2,955 / 77,539	19, 25	03-Dec-21	Dan Theoret
VIK5034	CC-009	transfer case oil. Replaced cab, engine air filters. Verified operator complaint of passenger side mirror being broken.	Proactive	3,303 / 84,211	11	25-Jan-22	Dan Theoret
VIK5452	CC-009	deck light, replace drag link and right outer tie rod, rear caliper service, replace front shocks.	Reactive	89,915	13	17-Jun-22	Lacombe Ford
VIK5451	CC-009	**CVIP.**	Proactive	89,915	10	20-Jun-22	Lacombe Ford
VIK5450	CC-009	**Regular Service - GAS.** Brakes are a bit soft at the foot (Callum Deditch)	Proactive	89,940	11, 19	24-Jun-22	Callum Deditch
VIK5617	CC-009	**Regular Service - GAS.**	Proactive	99,014		14-Sep-22	Kyle Stegmaier
VIK5629	CC-009	Put in new battery - AOK. All tires at 3/32. Dropped off at Fountain Tire to put new ones on (Mike McLeod).	Proactive	100,244	19	26-Sep-22	Mike McLeod
VIK5796	CC-009	**Inspection**	Proactive	1	910	24-Nov-22	Brent Blake
VIK5806	CC-009		Proactive	2	910, 911	25-Nov-22	Brent Blake
VIK5817	CC-009		Proactive	1	910, 919	29-Nov-22	Brent Blake
VIK5857	CC-009	added 75w140.	Proactive	108686km		12-Dec-22	Brent Blake
VIK6019	CC-009	ft./Lbs	Proactive	113308km		21-Jan-23	Brent Blake
VIK6298	CC-009	Rear driveshaft U-joint by Diff End.			917	23-May-23	Mike McLeod
VIK6310	CC-009	**Disconnect Gooch's reel trailer & put on jack stands. Srvie & Check over.**		126573 KMS	911	05-Jun-23	Mike McLeod
VIK6451	CC-009	pins.	Reactive	132448 KMS	921	13-Jul-23	Mike McLeod
VIK6452	CC-009	**Service & tranny oil & filter servcie. Front drivesahft pinion seal changed. Tire rotation**	Reactive	132448 KMS	917	14-Jul-23	Mike McLeod
VIK6482	CC-009	**Wash**	Proactive	135798 KMS	989	05-Aug-23	Mike McLeod
VIK6486	CC-009	**Bring in and check over**	Proactive	135798 KMS	910	06-Aug-23	Mike McLeod
VIK6381	CC-009	**All lights are good. All fluid levels are good. wiper blades are good. Bsttery is good. Windsheild is cracked - advised**	Proactive	142261 KMS	911	30-Aug-23	Koch Ford Sales(Athabasca) Ltd.
VIK6601	CC-009	**Service & sliptank washed & get welded at pump collar**	Proactive	149312 KMS	911	05-Oct-23	Mike McLeod
VIK6759	CC-009	Inspect	Proactive	158499 KMS	910	18-Dec-23	Kyle Stegmaier
VIK6784	CC-009	Install tire and torque	Proactive	158499 KMS	916	09-Jan-24	Kyle Stegmaier
VIK7527	CC-009	New windshield	Reactive		920	11-Mar-24	Arby's Glass
VIK7003	**CC-009**	**Bring in # and drain oil. Check # over.**	**Proactive**	**163971 KMS**	**910**	**12-Jun-24**	**Mike McLeod**
VIK7004	**CC-009**	**Service**	**Proactive**	**163970 KMS**	**911**	**13-Jun-24**	**Mike McLeod**
VIK7109	CC-009	Check # over.	Proactive	166066 KMS	910	12-Jul-24	Mike McLeod
VIK7235	CC-009	Diag and repair clearance light wiring on deck.	Proactive	167432 KMS	919	03-Aug-24	Kyle Stegmaier
VIK7344	CC-009	**Service and check over #.**	**Proactive**		**911**	**04-Sep-24**	**Mike McLeod**
VIK7577	CC-009	seat belt buckle replaced seat base. Truck needs engine work - CEL on.	Proactive		910	11-Feb-25	Paxton Morrison
LSL7737	CC-009	Changed oil and filter, air and cab filters. Checkover # and top up fluids and creased. Check engine light - Same codes (catalyst Bnk 1 & Bnk 2)	Reactive	182072 KMS	911	18-May-25	Mike McLeod
LSL7791	CC-009	Rotate tires. Checked front brake pads and order pads and replace. Fix toolbox hinges and set lock handle and lube parts. Park Unit.	Reactive	184640 KMS	921	07-Jun-25	Mike McLeod
LSL8100	CC-009	Bring # in. Changed oil and filter, air and cab filters. Check # over and grease and top up fluid levels. Found driver side exhaust manifold cracked and get pricing on parts. Take carburetor intake off and carb clean carberetor and put back together and park #. LACOMBE FORD CHNGD OUT DR/SIDE MANIFOLD	Reactive	189423 KMS	911	09-Aug-25	Mike McLeod

LSL8436	CC-009	Changed oil and filter, air and cab filters. Changed oil in rear diff. Changed oil in transfercase. Changed filter on sliptank and put some conditioner in sliptank. Park #	Proactive	196071 KMS	911	07-Nov-25	Mike McLeod
LSL8854	CC-009	Unnload old drill pipe and garbage on deck. Wash # down. Bring in shop and go over # and make list of parts and new tires. Go through history.	Reactive		989	14-Apr-26	Mike McLeod
LSL8855	CC-009	Changed air and cab filters. Take all wheels off and wash and load in CC-008. Order parts. Replaced 2 left side coils and spark plug leads and replaced 2 right side coils and leads. Replaced bulb on driver side marker lite in headlight. Replaced both side mirror motors.	Reactive	204960 KMS	911	15-Apr-26	Mike McLeod
LSL8856	CC-009	Replaced bulb on top of headlight on driver's side. Replaced handle for tilt back on driver's seat. Replaced torn boot on front drive shft from from differential to transfercase. Finish replacing last 3 coils and 4 spark plug leads. Charge up battery.	Reactive	204960 KMS	911	16-Apr-26	Mike McLeod
LSL8858	CC-009	Changed oil and filter. Replaced batter and clean and test trailer plug. Put 2 new end caps on running board on passenger side. Park #.	Reactive	204960 KMS	911	17-Apr-26	Mike McLeod
LSL8994	CC-009	Replace hood latch. Check tire pressures and adjust. Check # over and order back up camera.	Reactive	208140 KMS	920	02-Jun-26	Mike McLeod
LSL8995	CC-009	Find pigtail for back up camera and research wiring diagram and order pigtail.	Reactive	208140 KMS	919	03-Jun-26	Mike McLeod
LSL8997	CC-009	Remove wiring from sliptank up to hard wiring wire in engine compartment. Take slip tank off and extend wiring and put on in-line fuse and alligator clips and take sliptank and put in yard.	Reactive		924	04-Jun-26	Mike McLeod
LSL9323	CC-009	Serviced	Proactive	212146 KMS	911	17-Aug-26	Fountain Tire (Bonnyville)
LSL9644	CC-009	BRING IN #. & CLEAN OUT CAB. TAKE OLD TOOLBOX OFF ON PASS/SIDE OFF DECK. FIND MATERIALIN YRD & CUT PIECE OF GRATING & WELD ON SIDE RAIL TO FILL IN GAP WHERE THE TOOLBOX WAS. WIRE IN A BEACON & TEST. WASH #.	Reactive		924	14-Oct-26	Mike McLeod

Land
Equipment = 60, Status = 1

Record#	Trans#	Date	Description	Vendor/Employee/Equipment	Type	
10402	461572	08/11/2025	Manifold, gaskets, hardware	138 Lacombe Ford Sales Ltd.	1	Material
10942	309083	09/15/2025	Replace exhaust manifold	138 Lacombe Ford Sales Ltd.	1	Material
11800	1347	11/09/2025	Mechanic service (Nov 3-7)	627 RPM Mechanical Services	1	Material
12599	011-429275	01/13/2026	Battery	32 Northern Truck & Industrial Supplies Ltd.	1	Material
12600	011-429273	01/13/2026	Battery	32 Northern Truck & Industrial Supplies Ltd.	1	Material
127	101919	10/19/2019	Car Wash	98 Jubenville, Jonathan	5	Other
13380	500262	03/16/2026	Replace spark plugs		4	Subcontract
13744	471894	04/16/2026	Coil assy's, boot	138 Lacombe Ford Sales Ltd.	1	Material
13745	471869	04/16/2026	Coil assy's, boot	138 Lacombe Ford Sales Ltd.	1	Material
13749	471848	04/15/2026	Coil assy, wire assy	138 Lacombe Ford Sales Ltd.	1	Material
13768	471951	04/17/2026	Battery	138 Lacombe Ford Sales Ltd.	1	Material
13769	471897	04/17/2026	Step/extension	138 Lacombe Ford Sales Ltd.	1	Material
13772	CM471894	04/17/2026	Coil assy's, boot	138 Lacombe Ford Sales Ltd.	1	Material
14197	473102	05/16/2026	Wiper blades	138 Lacombe Ford Sales Ltd.	1	Material
1447	000302	03/11/2021	CVIP	239 Windle Mechanical Inc.	4	Subcontract
14620	473803	06/04/2026	Back up camera, bracket, wiring	138 Lacombe Ford Sales Ltd.	1	Material
14621	CM473762	06/03/2026	Back up camera, bracket, wiring	138 Lacombe Ford Sales Ltd.	1	Material
14622	473762	06/03/2026	Back up camera, bracket, wiring	138 Lacombe Ford Sales Ltd.	1	Material
14625	473743	06/02/2026	Latch	138 Lacombe Ford Sales Ltd.	1	Material
14787	473890	06/12/2026	Wiring assy	138 Lacombe Ford Sales Ltd.	1	Material
14848	CM473762A	06/17/2026	Back up camera, bracket, wiring	138 Lacombe Ford Sales Ltd.	1	Material
1501	59	04/10/2021	Repairs	228 Gun Metal Mechanical	4	Subcontract
1520	LR100161118	03/31/2021	V-First	139 Lacombe Registries Ltd.	4	Subcontract
153	Car Wash	11/02/2019	Truck Wash	98 Jubenville, Jonathan	5	Other
1602	1686-40471	04/19/2021	Slip tank nozzle	11 Uni-Select Inc.	1	Material
16160	033FT0003578	08/17/2026	Oil change	107 Fountain Tire	4	Subcontract
2066	1686-49291	10/01/2021	Ball & Pintle / Hitch	11 Uni-Select Inc.	1	Material
2067	1686-49285	10/01/2021	Ball & Pintle / Hitch	11 Uni-Select Inc.	1	Material
2087	399216	10/08/2021	Window	138 Lacombe Ford Sales Ltd.	1	Material
2170	402512	12/02/2021	Air bag pigtail	138 Lacombe Ford Sales Ltd.	1	Material
2172	401767	11/22/2021	Mirror	138 Lacombe Ford Sales Ltd.	1	Material
250	Tirecraft	11/23/2019	Service	17 Smith, Myles	2	Labour
2664	416348	09/01/2022	Hood latch	138 Lacombe Ford Sales Ltd.	1	Material
2726	1686-65583	09/12/2022	Oil	11 Uni-Select Inc.	1	Material
2774	0581082359	09/26/2022	Changeover	107 Fountain Tire	4	Subcontract
3281	0581084416	02/14/2023	Flat repair	107 Fountain Tire	4	Subcontract
3708	428581	05/23/2023	Drive shaft bolts	138 Lacombe Ford Sales Ltd.	1	Material
3709	578-735581	05/23/2023	U-joints	134 NAPA Auto Parts-Lacombe	1	Material
3710	578-735533	05/23/2023	U-joints	134 NAPA Auto Parts-Lacombe	1	Material
3731	1465930	05/30/2023	Diesel fuel nozzle	368 Veg Auto & Industrial(2013) Supply Ltd.	1	Material
3764	1021060	05/31/2023	Diesel nozzle	377 BTB Two Hills Auto & Ind. Supply Ltd.	1	Material
4088	430852	07/14/2023	Pinion seal	138 Lacombe Ford Sales Ltd.	1	Material
4096	0581086898	07/14/2023	Wheel balance	107 Fountain Tire	4	Subcontract
4245	312023	07/31/2023	To record July VISA expenses		4	Subcontract
4517	422086	08/30/2023	Service	446 Koch Ford Sales(Athabasca) Ltd.	3	Equipment
454	8048	04/28/2020	CVIP	118 DMC Heavy Duty Repairs	4	Subcontract
46	19082843580265	08/28/2019	CC-009		4	Subcontract
4798	302023	09/30/2023	To record September VISA expenses		1	Material
4824	1686-85549	10/10/2023	Diesel additive	11 Uni-Select Inc.	1	Material
4967	5909	10/19/2023	Weld repairs	221 Wolf Creek Metal Worx Inc.	1	Material
5479	437670	12/07/2023	Brakes	138 Lacombe Ford Sales Ltd.	1	Material

5623	1036	12/23/2023	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5723	1037	01/13/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
5749	438826	01/08/2024	Brake pads	138 Lacombe Ford Sales Ltd.	1	Material
5750	0581090166	01/09/2024	Changeover	107 Fountain Tire	4	Subcontract
5898	440332	02/08/2024	Belt, tensioner, pulley	138 Lacombe Ford Sales Ltd.	1	Material
603	0581069390	06/05/2020	New tires	107 Fountain Tire	1	Material
6117	2071	03/11/2024	Windshield (CC-009)	202 Arby's Glass	4	Subcontract
6155	1686-93443	03/21/2024	Seat covers	11 Uni-Select Inc.	1	Material
6203	03312024	03/31/2024	To record March VISA expenses		4	Subcontract
7414	1070	08/03/2024	Kyle Stegmaier	405 Full Curl Mechanical	4	Subcontract
8355	452681	12/19/2024	Wiring assembly	138 Lacombe Ford Sales Ltd.	1	Material
8420	LR600091346	02/27/2025	Registrations	139 Lacombe Registries Ltd.	1	Material
920	591	09/04/2020	New windshield	202 Arby's Glass	1	Material
9240	LR400096134	06/03/2025	Renewals CC-006/CC-009	139 Lacombe Registries Ltd.	1	Material
9322	459080	06/07/2025	Brakes	138 Lacombe Ford Sales Ltd.	1	Material