Vehicle Service Records (VSR Explorer)
Repair history D-202275

Registration nr:	711VYQ	**Chassis ID:**	D-202275	**VIN:**	YV5RG40D7FD202275
Market type:	-	**Country:**	-	**Delivery date:**	2015-10-12

(A) 2025-04-12 | Mileage: 1209825 km | Order No: 8449320

PC	Type	Code	Description (Original)	#
R	Other	K	CONTACT PH: KEN 0419 753 701	
R	Operation	LO-600	PWR STEER OIL LEAK AT POWER STEER PUMP	3
R	Operation	LO-210	REPAIR OIL LEAK AT OIL THERMOSTAT VALVE	1.25
	Description / Note		Inspect vehicle for oil leak.	
R	Part	VO-21488833	STEERING PUMP	1
R	Part	VO-23871482	PISTON COOLING VALVE	1
R	Part	VO-977030	O'RING (P/S MOUNT)	1
R	Part	VO-85103703	O'RING	1
R	Part	VO-24011167	CONNECTOR	1
R	Part	VO-1161995	ATF OIL	1
R	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
	Description / Note		R&R power steering pump.	
	Description / Note		Fill with new fluid and bleed system.	
	Description / Note		Road test vehicle - Found OK.	
	Description / Note		R&R oil thermostat valve.	
	Description / Note		Clean area and check for further leaks - Found OK.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2025-02-21 | Mileage: 1202192 km | Order No: 8324276

PC	Type	Code	Description (Original)	#
I	Operation	LO-397	TIME FOR CAMPAIGN L5185	2.5

(A) 2025-02-21 | Mileage: 1202192 km | Order No: 415898

PC	Type	Code	Description (Original)	#
R	Operation	LO-397	TIME FOR CAMPAIGN L5185	2.5
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2025-01-31 | Mileage: 1202192 km | Order No: 8323758

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
R	Operation	LO-720	REPLACE BOTH STEER SPRINGS	8
R	Part	VO-21175831	BUSHING	2
R	Part	VO-21960567	FLANGE SCREW	4
R	Part	VO-21960568	FLANGE SCREW	2
R	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	9
R	Part	VO-23219848	SHACKLE	2
R	Part	VO-23219839	SHACKLE	2
R	Part	VO-22944256	NUT M24FL	8
R	Part	AU2-WUR0890200	RUST OFF PLUS	1
R	Part	VO-22935392	U-BOLT	4
R	Part	VO-23236847	FRONT SPRING	2
R	Part	VO-FFS	FREIGHT SYDNEY - PINKENBA	5
R	Part	AU2-WUR0890200	RUST OFF PLUS	1
R	Part	AU2-WUR0893241	RUST OFF ICE BLUE	1
R	Part	MK-NARV56306	CABLE TIE 1=25PC	1
R	Operation	LO-397	TIME FOR CAMPAIGN L5185	2.5
R	Operation	LO-818	REPLACE BOTH REAR CAB SHOCKIES	2
R	Part	VO-21739593	SHOCK ABSORBER	2
R	Part	VO-22128971	SHOCK ABSORBER	2
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 / 0419 753 701	
	Description / Note		Removed & replaced all rear cab shockies, checked	
	Description / Note		operation, all okay.	
	Description / Note		Removed wheels, removed componets, removed & replace left	
	Description / Note		& right steer spring shackles bushes & steer springs,	
	Description / Note		refit components, refit wheels. checked operation, all okay.	
R	Other	91	WORKSHOP CONSUMABLES	
	Description / Note		L5185 VOLVO FH, FM PRE 2016W3 TELEMATICS WITH TESP 3G SUNSET INITIATIV	
W	Part	VO-23544009	TELEMATICS CONTROL	1
W	Part	VO-23004613	SIM CARD	1
W	Part	VO-23311714	ANTENNA	1
W	Part	VO-23518995	CABLE	1

PC	Type	Code	Description (Original)	#
W	Part	VO-85166246	CONVERSION KIT	1

(A) 2024-07-23 | Mileage: 1168497 km | Order No: 8445730

PC	Type	Code	Description (Original)	#
R	Other	K	CONTACT PH: KEN CALLED IN	
	Description / Note		KLM.....	
	Description / Note		HRS.....	
R	Operation	LO-510	REPAIR FOR VERY WEAK ENGINE BRAKE	6
R	Part	VO-21634024	PRESSURE SENSOR EXH BACK	1
R	Part	VO-21582423	ROUND 4 WIRE PLUG KIT	1
R	Part	VO-23532368	AVU VALVE	1
R	Part	VO-22889891	ACTUATOR SERVICE K	1
R	Part	VO-21596642	VCB VALVE	1
R	Part	VO-1677370	VEB O-RING	2
	Description / Note		Checked engine and exhaust brake system and found both	
	Description / Note		functions not working.	
	Description / Note		Replaced exhaust actuator due to air leaking past seal.	
	Description / Note		Removed rocker cover then tested engine brake solenoid and	
	Description / Note		found internally shorted. Replaced solenoid, refitted cover	
	Description / Note		then road tested and confirmed operation, all ok.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2023-03-13 | Mileage: 1092507 km | Order No: 8307010

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
	Description / Note		Contact:Ken 0419 753 701	
R	Operation	LO-311	CHECK BOTH BATTERIES BOILING.	1.88
	Description / Note		REPLACE BOTH BATTERIES AS PER CUSTOMER, ALSO CHECK CHARGE	
R	Other	97	ENVIRONMENTAL CHARGE	
R	Part	AU2-23446985	VOLVO EFB 12V 225A N200	2
	Description / Note		3150 13/3/2023	
	Description / Note		RATE.	

PC	Type	Code	Description (Original)	#
	Description / Note		Disconnected batteries, r/r boiled batteries, cut off	
	Description / Note		melted terminal covers, reconnected batteries, checked	
	Description / Note		charging rate at alternator, found it to be 28.7 volt	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2023-02-28 | Mileage: 1090678 km | Order No: 8306620

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844	
R	Operation	LO-871	a/c not cold	7.5
	Description / Note		blows air not cold	
R	Part	VO-23437874	CONDENSER	1
R	Part	OTH-84191414	ORIFICE TUBE VALVE	1
R	Part	VO-23847736	DECAL	1
R	Part	VO-979652	HOSE	0.5
	Description / Note		/ 0419 753 701	
	Description / Note		Carried out A/C performance test.	
	Description / Note		A/C compressor not engaging.	
	Description / Note		Checked A/C fuse. OK.	
	Description / Note		Checked A/C compressor power supply. No power. Removed	
	Description / Note		cover from firewall and checked for power at XC203. No	
	Description / Note		power.	
	Description / Note		Connected laptop and read fault codes. Inactive fault for	
	Description / Note		CCM LIN10 communication Net, Bus off.	
	Description / Note		Went through GD. Checked Power at CCM and signal. OK.	
	Description / Note		Checked A/C control panel connector and pins. OK.	
	Description / Note		Connected A/C machine and checked pressure, No refrigerant	
	Description / Note		in system. Inspected system for leaks.	

PC	Type	Code	Description (Original)	#
	Description / Note		Found leak from Condensor.	
	Description / Note		Remove and replaced condensor,accumulator and orifice	
	Description / Note		tube. Vaccum A/C system. Rechecked and found it to be	
	Description / Note		losing vacuum. Pressurised A/C system with nitrogen and	
	Description / Note		inspected for leaks. Found evaperator core leaking as	
	Description / Note		well.	
	Description / Note		Remove and replaced evaperator core. Vacuumed down A/C	
	Description / Note		system, was now holding vacuum. Charged A/C system with	
	Description / Note		650g of R134a.	
	Description / Note		Connected laptop,calibrated CCM servo motors and cleared	
	Description / Note		fault codes. Checked operation of A/C system.	
R	Other	91	WORKSHOP CONSUMABLES	
W	Part	VO-23858694	ACCUMULATOR	1
W	Part	VO-82348991	EVAPORATOR	1
W	Operation	VO-8743100	Evaporator, replace	0.5
W	Operation	VO-8740500	Dryer, replace	0.2

(A) 2022-10-17 | Mileage: 1065570 km | Order No: 8303087

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 /	
R	Operation	LO-871	A/C NOT COLD BLOWS AIR	4
R	Other	873	HEATER NOT WORKING	
	Description / Note		CHECK AND REPAIR.	
R	Part	VO-82348991	EVAPORATOR	1
R	Part	OTH-84191414	VALVE	1
R	Part	VO-23858694	ACCUMULATOR	1
R	Part	VO-23515346	VENTILATION FILTER	1
R	Part	VO-23515329	VENTILATION FILTER	1
R	Part	VO-84223447	HEAT CONTROL VALVE	1
R	Part	VO-3090885	O'RING KIT A/C	1

PC	Type	Code	Description (Original)	#
	Description / Note		3145	
	Description / Note		0419 753 701	
	Description / Note		traced fault to leaking evaporator	
	Description / Note		drained and vacuumed system	
	Description / Note		stripped dash and removed ac unit from cab	
	Description / Note		stripped ac unit	
	Description / Note		replaced evaporator and heater control valve	
	Description / Note		reassembled ac unit and refitted to cab	
	Description / Note		replaced acumulator and orifice tube	
	Description / Note		reassembled dash	
	Description / Note		vacuumed and recharged ac system	
	Description / Note		connected laptop	
	Description / Note		carried out climate control stepper motor calibration	
	Description / Note		tested operation	
	Description / Note		monitored climate unit signals with tech tool	
	Description / Note		CHECKED OPERATION AND FOUND WORKING AS IT SHOULD	
R	Other	97	ENVIRONMENTAL CHARGE	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-09-14 | Mileage: 1057912 km | Order No: 3307209

PC	Type	Code	Description (Original)	#
R	Operation	LO-270	Rectify Truck Shutting Down	2.5
	Description / Note		High crankcase pressure warning coming up on dash.	
R	Part	VO-21634017	SENSOR, CRANKCASE PRESS	1
	Description / Note		Ken: 0419 753 701 or (07) 5534 2844	
	Description / Note		**********	
	Description / Note		Complaint: Intermittent engine shutdown.	

PC	Type	Code	Description (Original)	#
	Description / Note		Cause: Faulty crankcase pressure sensor.	
	Description / Note		Correction: Connected PC and checked fault codes. Found	
	Description / Note		faults logged for crankcase pressure P051A13- Crankcase	
	Description / Note		pressure sensor open circuit, P113500- Crankcase pressure	
	Description / Note		value too high. Monitored sensors through PC, found	
	Description / Note		crankcase pressure reading not correct. Set up breakout	
	Description / Note		box on crankcase pressure sensor and checked voltages, all	
	Description / Note		ok. checked continuity of wiring between E-ECU and sensor	
	Description / Note		connector, all ok. replaced crankcase pressure sensor.	
	Description / Note		Crankcase pressure reading ok now. Cleared faults and	
	Description / Note		sent truck.	
R	Other	94	Environmental Levy	
R	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.34
R	Other	91	Workshop Consumables	

(A) 2022-08-18 | Mileage: 1045220 km | Order No: 8301776

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
R	Operation	LO-410	CLUTCH - ISSUE	14
	Description / Note		TRUCK LOST DRIVE AND CAN SMELL BURNT CLUTCH SMELL	
R	Part	VO-85022461	CLUTCH KIT	1
R	Part	VO-22327063	SOLENOID VALVE	1
R	Part	VO-20992763	AIR HOSE	1
R	Part	VO-85108352	R/M SEAL F16 & FH12/16	1
R	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
R	Part	VO-25339078	NUT M14 FINE PITCH	4
R	Part	VO-3199066	SEAL RING	4
R	Other	40	SUBLET - MACHINE FLYWHEEL	
R	Part	VO-1652986	SPIGOT BRG	1
R	Part	VO-85013166	CYLINDER	1
R	Part	VO-20722721	AIR INLET	1
R	Part	VO-20860677	SEALING RING	1

PC	Type	Code	Description (Original)	#
	Description / Note		NEW SERIAL # 666482000262 0122	
	Description / Note		OLD SERIAL #	
R	Part	AU2-PERM26210	PX 262 PERM ST TL	1
R	Part	VO-21344746	SCREW	2
R	Part	VO-23139092	PIPE	1
R	Part	AU2-9770-5073	HOT SHOT DEGREASER	2
R	Part	AU2-CAL85121715	DIFF OIL 85W140 BULK	30
R	Part	AU2-AMP22567321	VOLVO VCS COOLANT 5LTR	1
R	Other	97	ENVIRONMENTAL CHARGE	
	Description / Note		TOWED IN	
	Description / Note		tow vehicle into workshop, download fault codes.	
	Description / Note		remove gearbox and found bellhousing full of clutch dust	
	Description / Note		and had to be wash down.	
	Description / Note		remove clutch and flywheel.cleaned out flywheel housing	
	Description / Note		and replaced rear main seal.	
	Description / Note		machine flywheel and refit with new clutch.	
	Description / Note		replaced clutch servo and pwm valve and refit gearbox.	
	Description / Note		program and calibrated.	
	Description / Note		checked and topped up diff oils and coolant	
	Description / Note		wash over vehicle and road test nd check over.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-07-14 | Mileage: 1035767 km | Order No: 8300769

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844	
R	Operation	LO-210	ENGINE LOW POWER FAULT	2.5
	Description / Note		BOOST SLOW TO BUILD	

PC	Type	Code	Description (Original)	#
R	Part	VO-21834205	FILTER	1
R	Part	VO-23294956	FILTER	1
	Description / Note		*** POSSIBLE POLICY CLAIM ***	
	Description / Note		/ 0419 753 701	
R	Part	VO-85122800	ATF DEX 3	3
	Description / Note		RAOD SPEED SLOW TO BUILD	
	Description / Note		TO 100 KPH	
	Description / Note		Plug in laptop,check fault codes.	
	Description / Note		Found no codes that would cause low power or slow to	
	Description / Note		build boost.	
	Description / Note		Unable to conect up to trailer but test drove and monitor	
	Description / Note		back pressure boost pressure and fuel pressure.	
	Description / Note		Back pressure under full load max23Kpa.	
	Description / Note		Fuel pressure between 450-500Kpa.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-05-05 | Mileage: 1015768 km | Order No: 8435282

PC	Type	Code	Description (Original)	#
R	Operation	LO-260	Coolant leak	2.5
R	Part	VO-21313188	CONNECTOR	1
R	Part	VO-984998	HOSE CLAMP	2
	Description / Note		Pressure tested cooling system	
R	Other	20	hose for oil cooler to transmission cool	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-01-13 | Mileage: 979263 km | Order No: 8153419

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Joel: 5534 2844	
R	Operation	LO-260	TOP TANK SPLIT	23
R	Part	VO-85021957	RADIATOR, EXCH - FH(4)	1

PC	Type	Code	Description (Original)	#
R	Part	VO-22560373	HOSE BOTTOM RAD - FM/FH(4)	1
R	Part	AU2-AMP22567335	VOLVO VCS COOLANT 20L*	40
R	Part	VO-3979639	GASKET - PREHEATER	2
R	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
R	Part	MK-NARV56306	CABLE TIE 1=25PK (4.8x300mm)	1
R	Part	VO-85013941	COMPRESSOR, EXCH	1
R	Part	VO-471708	SEALING RING - BLACK	1
R	Part	VO-992065	O-RING - COMPRESSOR MOUNT	1
R	Part	VO-20538793	SEAL STRIP, R/COVER GASKET	1
R	Part	VO-21351717	INJECTOR SLEEVE	6
R	Part	VO-1161963	RUBBER GREASE	1
R	Part	VO-21406638	ROCKER ARM - EXHAUST	1
R	Part	VO-21344774	FLANGE BOLT M10 x 50mm ENG	6
R	Other	97	ENVIRONMENTAL CHARGE	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-12-22 | Mileage: 975369 km | Order No: 8433762

PC	Type	Code	Description (Original)	#
R	Operation	LO-560	Replace air compressor	3.5
	Description / Note		and oil feed pipe,	
R	Part	VO-85013941	COMPRESSOR, EXCH	1
R	Part	VO-471708	SEAL RING	1
R	Part	VO-992065	O-RING	1
R	Part	VO-990424	AIR COMP OIL FEED LINE	1
R	Part	VO-977639	NIPPLE	2
R	Part	VO-21339891	RUBBER HOSE	0.5
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-09-15 | Mileage: 935550 km | Order No: 8293670

PC	Type	Code	Description (Original)	#
R	Operation	LO-810	ac not getting cold	3.6
R	Operation	LO-3000	FRIDGE NOT WORKING	0.6
	Description / Note		LIGHTS AT CONTROL PANNEL WORKING	
R	Part	VO-82174077	REFRIGERATOR	1
R	Part	VO-23515346	VENTILATION FILTER	1
R	Part	VO-23515329	VENTILATION FILTER	1
R	Part	VO-979652	HOSE	0.5

PC	Type	Code	Description (Original)	#
R	Part	VO-60110514	HOUSING OBD2 PLUG	1
R	Part	VO-20716774	TERMINAL OBD	7
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-03-05 | Mileage: 887581 km | Order No: 4280827

PC	Type	Code	Description (Original)	#
R	Operation	VO-3971000	Dynafleet, programming	0.7
	Description / Note		Update with conversion kit 85157513	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-03-05 | Mileage: 887581 km | Order No: 8430560

PC	Type	Code	Description (Original)	#
R	Operation	VO-3971000	Dynafleet, programming	0.7
	Description / Note		Update with conversion kit 85157513	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-02-10 | Mileage: 893995 km | Order No: 8430258

PC	Type	Code	Description (Original)	#
R	Operation	LO-430	INTERMITTENTLY WILL NOT SELECT A GEAR	3
R	Part	VO-22647976	GEAR SELECTOR	1
	Description / Note		Connect laptop and check for fsult codes - None present.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-01-28 | Mileage: 888560 km | Order No: 8288677

PC	Type	Code	Description (Original)	#
R	Operation	LO-560	truck wont build up air	6
R	Part	VO-85023292	AIR DRIER, EXCH	1
R	Part	VO-3199066	SEAL RING	4
R	Part	VO-20733172	SILENCER	1
	Description / Note		VEHICLE GOT TOWED IN WITH ALL 4X DRIVE AXLES REMOVED.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-12-29 | Mileage: 887581 km | Order No: 8429790

PC	Type	Code	Description (Original)	#
R	Operation	VO-3971000	Dynafleet, programming	0.7
	Description / Note		Update with conversion kit 85157513	

PC	Type	Code	Description (Original)	#
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-11-18 | Mileage: 878372 km | Order No: 7610611

PC	Type	Code	Description (Original)	#
R	Operation	VO-2551800	Engine turbocharger, replace. Chassis mo	7.6
R	Part	VO-85020372	EXCH TURBOCHARGER	1
R	Part	VO-20784537	GASKET - TURBO BASE	1
R	Part	VO-21940615	SEALING RING	1
R	Part	VO-22206133	GASKET	1
R	Part	VO-420643	GASKET - OIL RETURN TURBO	1
R	Part	VO-469601	SEALING RING TURBO OIL DRAIN	1
R	Part	VO-990950	LOCK NUT M8 FLANGE	1
R	Part	VO-993811	BOLT TURBO MOUNT	4
R	Part	VO-994441	BOLT M8*50 FLANGE 8.8G	1
R	Part	VO-20920705	SILENCER	1
	Description / Note		TW2003233204 SERIAL NO	
R	Part	VO-20855371	GASKET EXH MANIFOLD	6
R	Part	AU2-CAL85121799	ENG.OIL 5L VDS4 EURO5	4
R	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
R	Part	AU2-WUR0673207510	BUFF PAD 3" COARSE	2
R	Part	VO-21834205	AIR FILTER-OUTER	1
R	Part	VO-23294956	AIR FILTER-INNER	1
R	Part	VO-8148729	CONNECTOR	1
R	Part	VO-21312238	CHARGE AIR HOSE	1
R	Part	VO-20592783	CLAMP	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-10-26 | Mileage: 870748 km | Order No: 8429111

PC	Type	Code	Description (Original)	#
R	Operation	LO-210	Replace rear engine mounts	8.55
R	Part	VO-21416525	RUBBER CUSHION	2
R	Part	VO-990971	HEXAGON NUT	4
R	Part	VO-22901068	FLANGE SCREW	4
	Description / Note		Remove gearbox, replace engine mounts and refit gearbox.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-10-07 | Mileage: 864536 km | Order No: 8286065

PC	Type	Code	Description (Original)	#
R	Operation	LO-870	A/C FAN BLOWER N/W INTERMITTENTLY	1.3
R	Operation	LO-210	ENGINE MALFUNCTION FAULT ON DASH	7
	Description / Note		CHECK & REPORT	
R	Part	VO-82349001	REGULATOR CONTROL	1
R	Part	AU2-WUR089365	CONTACT CLEANER RINSE	1
R	Part	VO-21382371	FAN	1
R	Part	VO-22889891	ACTUATOR SERVICE K	1
R	Part	VO-20479636	SEALING STRIP	1
R	Part	VO-1547254	THERMOSTAT SEAL	1
R	Part	VO-21503575	SEALING RING	1
R	Part	MK-NARV56306	CABLE TIE 1=25PC	1
R	Part	VO-990950	NUT M8 FL LOCKING	4
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-08-31 | Mileage: 850182 km | Order No: 8428548

PC	Type	Code	Description (Original)	#
I	Other	220	RECTIFY ENGINE OIL LEAK	
	Description / Note		POSSIBLE HEAD GASKET LEAKING - HAS BEEN REPLACED IN THE	
I	Part	VO-21510072	CYLINDER HEAD GASK	1
I	Part	VO-21447682	GASKET	1
I	Part	VO-20526428	VEB O-RING	1
I	Part	VO-1677370	VEB O-RING	2
I	Part	VO-20479636	SEAL	1
I	Part	VO-1547254	O-RING T/STAT	2
I	Part	VO-420643	GASKET Turbo Drain	1
I	Part	VO-22206133	GASKET	1
I	Part	VO-20852765	GASKET	4
I	Part	VO-22241727	PIPE	1
I	Part	MK-NARV56306	CABLE TIES	1
I	Part	VO-21426987	SPEED MONITOR	1
I	Part	VO-983472	CABLE TIE, Injector Harness	8
I	Part	VO-980881	CABLE TIE	4
I	Part	VO-8131393	RETAINING CLIP, NEW TYPE	4

(A) 2020-07-08 | Mileage: 828558 km | Order No: 8428003

PC	Type	Code	Description (Original)	#
R	Other	K	Km.....hr.....	
R	Other	270	RECTIFY MISS WHEN COLD	

PC	Type	Code	Description (Original)	#
	Description / Note		VEHICLE REPORTED TO MISS AND SMOKE FROM COLD	

(A) 2020-06-19 | Mileage: 0 km | Order No: 8283534

PC	Type	Code	Description (Original)	#
I	Other	20	SUBLET WAGGA TRUCKS	

(A) 2020-05-22 | Mileage: 807999 km | Order No: 8427482

PC	Type	Code	Description (Original)	#
R	Operation	LO-270	Rectify engine derate	7
R	Part	VO-6781769	SPLICE-RED(22-18)	4
R	Part	VO-983472	CABLE TIE, Injector Harness	10
R	Part	VO-23243881	EXHAUST PIPE 672 LONG	1
R	Part	VO-1629499	V-CLAMP EXHAUST 153mm	1
R	Part	VO-990951	NUT M10	1
R	Part	VO-994195	BOLT M10	1
R	Part	AU2-WUR05392812	HOSECLMP-FUEL-B9MM	1
	Description / Note		Connect laptop and check for fault codes - Code P2BA800	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-04-23 | Mileage: 798286 km | Order No: 8282011

PC	Type	Code	Description (Original)	#
R	Operation	LO-321	CHECK ALTERNATOR FAULT ON DASH, COMING	2
	Description / Note		ON INTERMITTEMTLY	
R	Part	VO-85020832	ALTERNATOR, EXCH	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-11-02 | Mileage: 732744 km | Order No: 8425018

PC	Type	Code	Description (Original)	#
W	Operation	VO-2112600	Cylinder head, replace	11.4
W	Part	VO-85022413	CYL HEAD EXCH D13C	1
W	Part	VO-1547254	O-RING T/STAT	2
W	Part	VO-20479636	SEAL	1
W	Part	VO-20538793	SEALING STRIP	1
W	Part	VO-20855371	GASKET	6
W	Part	VO-21282255	GASKET	1
W	Part	VO-21344774	BOLT M10X50	6
W	Part	VO-21503575	SEALING RING	1

PC	Type	Code	Description (Original)	#
W	Part	VO-21510072	CYLINDER HEAD GASK	1
W	Part	VO-21940615	SEALING RING	1
W	Part	VO-22206133	GASKET	1
W	Part	VO-276948	O RING KIT	6
W	Part	VO-420643	GASKET Turbo Drain	1
W	Part	VO-469601	TURBO O-RING	1
W	Part	VO-21884469	FILLER CAP	1
W	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
W	Part	VO-85103205	PAINT green volvo	1
W	Part	AU2-WUR05392812	HOSECLMP-FUEL-B9MM	2
W	Part	VO-21447682	GASKET	1
W	Part	VO-21613426	THERMOSTAT	1
R	Part	VO-22343361	CABLE HARNESS	1
R	Part	VO-22899626	PRESSURE SENSOR	2
R	Part	MK-NARV56306	CABLE TIES	1
R	Operation	LO-270	REPLACED ENGINE HARNESS	6
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2170800	Oil sump, install	1
W	Operation	VO-2170600	Oil sump, remove	0.3
W	Operation	LO-221	Oil sump, remove/install. Sump removed	1.1
W	Operation	VO-2100600	Cylinder Compression, test	0.2
W	Operation	VO-2301600	Cylinder balancing, check	0.2
W	Operation	VO-2161100	Connecting rod bearings, replace (all).	1.5
	Description / Note		Oil sump removed	
W	Operation	VO-2160300	Main bearings, replace (all). Oil sump r	2.8
W	Operation	VO-2533600	Engine brake function, test	0.4
W	Operation	VO-2141700	Valve guide wear, check. all	0.4
R	Operation	LO-386	REPLACED OIL PRESSURE SENSOR	0.4
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-09-12 | Mileage: 708029 km | Order No: 7596446

PC	Type	Code	Description (Original)	#
	Description / Note		KEN SAWTELL 07 5534 2844	
R	Operation	LO-460	VIBRATION THROUGH VEHICLE	4
R	Operation	VO-1940100	Action service fee. national	2
R	Other	92	UTE MILEAGE 100 km's Ö Å1.48/km.	
R	Part	VO-995906	BOLT M14*46 FINE 10.9G	4

PC	Type	Code	Description (Original)	#
R	Part	VO-25339078	HEXAGON NUT	4
R	Part	VO-1068253	UNI-TAILSHAFT	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-06-05 | Mileage: 658676 km | Order No: 8423916

PC	Type	Code	Description (Original)	#
R	Operation	LO-170	Check and report on brake fault codes	0.5
	Description / Note		Connect laptop and check fault codes - Codes present for	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-05-30 | Mileage: 685540 km | Order No: 8273435

PC	Type	Code	Description (Original)	#
R	Operation	LO-254	EMISSION FAULT SYMBOL ON DASH	7.5
	Description / Note		ENGINE IS DERATING	
R	Part	VO-22670998	TANK	1
R	Part	VO-22716720	COMBINED TANK UNIT	1
R	Part	AU2-CUMCC36059	ADBLUE 20ltr Drum	2
R	Part	VO-22851845	PUMP UNIT	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-03-06 | Mileage: 631295 km | Order No: 8422961

PC	Type	Code	Description (Original)	#
W	Operation	VO-7211100	Front spring, replace (right hand side)	2.3
W	Part	VO-257913	FRONT SPRING	1
	Description / Note		CC: 200438915	

(A) 2019-02-28 | Mileage: 619950 km | Order No: 413889

PC	Type	Code	Description (Original)	#
W	Operation	VO-8743100	Evaporator, replace	0.25
W	Part	VO-85013654	COMPRESSOR, EXCH	0.5
W	Part	VO-82348991	EVAPORATOR	0.5
W	Part	VO-82356760	O-RING	0.5
W	Part	VO-82386482	O-RING	0.5
W	Part	VO-84437717	HOSE	0.5
W	Part	VO-82693739	ACCUMULATOR	0.5
W	Part	VO-3090885	O-RING KIT A/C	0.5
W	Other	87	Charge for A/C Gas	

PC	Type	Code	Description (Original)	#
W	Operation	VO-8741400	Cooling unit, performance test	0.15
W	Operation	VO-8701000	Air conditioning system, remove	0.4
W	Operation	VO-8701200	Air conditioning system, install	0.6
W	Operation	VO-8743300	A/C compressor, replace	0.6
W	Operation	VO-8740500	Dryer, replace	0.1
W	Operation	VO-8746800	High pressure hose, replace	0.35
	Description / Note		CC: 200437572	

(A) 2019-02-28 | Mileage: 619950 km | Order No: 8270888

PC	Type	Code	Description (Original)	#
R	Operation	VO-8743100	Evaporator, replace	0.25
R	Part	VO-85013654	COMPRESSOR, EXCH	0.5
R	Part	VO-82348991	EVAPORATOR	0.5
R	Part	VO-82356760	O-RING	0.5
R	Part	VO-82386482	O-RING	0.5
R	Part	VO-84437717	HOSE	0.5
R	Part	VO-82693739	ACCUMULATOR	0.5
R	Part	VO-3090885	O-RING KIT A/C	0.5
R	Other	87	Charge for A/C Gas	
R	Operation	VO-8741400	Cooling unit, performance test	0.15
R	Operation	VO-8701000	Air conditioning system, remove	0.4
R	Operation	VO-8701200	Air conditioning system, install	0.6
R	Operation	VO-8743300	A/C compressor, replace	0.6
R	Operation	VO-8740500	Dryer, replace	0.1
R	Operation	VO-8746800	High pressure hose, replace	0.35
	Description / Note		<< Goodwill Assistance covered 50% of parts and labour >>	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2019-01-31 | Mileage: 619950 km | Order No: 8270005

PC	Type	Code	Description (Original)	#
W	Operation	VO-8743100	Evaporator, replace	0.5
W	Part	VO-85013654	COMPRESSOR, EXCH	1
W	Part	VO-82348991	EVAPORATOR	1
W	Part	VO-82356760	O-RING	1
W	Part	VO-82386482	O-RING	1
W	Part	VO-84437717	HOSE	1
W	Part	VO-82693739	ACCUMULATOR	1
W	Part	VO-3090885	O-RING KIT A/C	1

PC	Type	Code	Description (Original)	#
W	Other	87	Charge for A/C Gas	
W	Operation	VO-8741400	Cooling unit, performance test	0.3
W	Operation	VO-8701000	Air conditioning system, remove	0.8
W	Operation	VO-8701200	Air conditioning system, install	1.2
W	Operation	VO-8743300	A/C compressor, replace	1.2
W	Operation	VO-8740500	Dryer, replace	0.2
W	Operation	VO-8746800	High pressure hose, replace	0.7
	Description / Note		CC: 200437572	

(A) 2018-10-17 | Mileage: 578907 km | Order No: 8421495

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706800	36 Months ECU download and oil sample. O	0.9
	Description / Note		Only valid for Australian market	
W	Part	VO-8394887	KIT OIL TEST	4

(A) 2018-09-21 | Mileage: 0 km | Order No: 413637

PC	Type	Code	Description (Original)	#
R	Other	20	Sublet Zupps Trucks	
	Description / Note		Clear Defect	

(A) 2018-09-20 | Mileage: 0 km | Order No: 8266570

PC	Type	Code	Description (Original)	#
R	Other	20	Sublet Zupps Trucks	
	Description / Note		Clear Defect	

(A) 2018-08-29 | Mileage: 865718 km | Order No: 4280541

PC	Type	Code	Description (Original)	#
W	Operation	VO-4317000	Gearbox, remove	0.36
W	Operation	VO-4132000	Clutch cylinder, replace. Gearbox remove	0.08
	Description / Note		removed	
W	Operation	VO-4317200	Gearbox, install	0.6
W	Operation	VO-4007000	Clutch, gearbox, pulling position, calib	0.08
W	Part	VO-85013166	CYLINDER use 85020472	0.4

(A) 2018-08-13 | Mileage: 553461 km | Order No: 8621202

PC	Type	Code	Description (Original)	#
R	Other	3110000	WEEKEND BREAKDOWN BP CLUDEN ROAD HOUSE	
R	Other	30	ATTEND TO NOT STARTING BP CLUDEN	
R	Part	AU2-20935640	Volvo MAINT N200	2
	Description / Note		INVOICE 31937	

(A) 2018-07-30 | Mileage: 865719 km | Order No: 8421035

PC	Type	Code	Description (Original)	#
W	Operation	VO-2160100	Crankshaft seal, replace (rear)	3.4
W	Part	VO-22191895	CRANKSHAFT SEAL	1

(A) 2018-07-28 | Mileage: 865718 km | Order No: 8420690

PC	Type	Code	Description (Original)	#
	Description / Note		AIRBAG MODULE, REPLACE. FH/FM (4)	
W	Operation	VO-8842000	Airbag module, replace	0.3
W	Operation	VO-7218200	Front spring, both side, replace. only c	5.4
W	Part	VO-84433698	AIRBAG MODULE light	1
W	Part	VO-257913	FRONT SPRING	2
W	Part	VO-22935392	U-BOLT 225mm	4

(A) 2018-07-24 | Mileage: 865718 km | Order No: 8420651

PC	Type	Code	Description (Original)	#
R	Operation	LO-410	CHECK AND RECTIFY CLUTCH FAULTS	4
W	Operation	VO-2123300	Flywheel housing, replace. Flywheel and	6.3
R	Part	VO-22327063	SOLENOID VALVE PWM	1
R	Part	VO-85013166	CYLINDER use 85020472	0.4
R	Part	VO-20992763	CLUTCH CYLINDER AIR HOSE	1
W	Part	VO-22190294	TIMING GEAR PLATE	1
W	Part	VO-8192804	SCREW	8
W	Part	VO-21344746	BOLT M16X82	14
W	Part	VO-992065	O-RING	1
W	Part	VO-471708	SEAL RING	1
W	Part	VO-977030	O'RING	1
W	Part	VO-21447682	GASKET	1
W	Part	VO-995906	BOLT M14X46	4
W	Part	VO-25339078	NUT M14	4
R	Part	VO-1652986	SPIGOT BEARING	1
R	Part	MK-NARV56306	CABLE TIE 1=25PK	1
R	Part	VO-85108352	SEAL REAR MAIN D16/12	1

PC	Type	Code	Description (Original)	#
R	Part	VO-9701-MDQ68DOT12M1	12mm x 12m thread connector	1
W	Operation	VO-4317000	Gearbox, remove	0.9
W	Operation	VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2
	Description / Note		removed	
W	Operation	VO-4317200	Gearbox, install	1.5
W	Operation	VO-4007000	Clutch, gearbox, pulling position, calib	0.2
W	Operation	VO-2153100	Timing gears, replace (all). Casing and	1.4
W	Operation	VO-2162100	Flywheel, replace. Gearbox and clutch re	0.6
W	Operation	VO-2563200	Air filter housing, replace	0.5
W	Operation	VO-2120600	Timing gear plate, replace. Timing gears	1
W	Operation	VO-1820400	Wash of engine. Including engine encapsu	0.5
W	Operation	VO-2580400	AdBlue tank, remove	0.8
W	Operation	VO-2580500	AdBlue tank, install	0.7
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2018-03-23 | Mileage: 495301 km | Order No: 8419431

PC	Type	Code	Description (Original)	#
R	Operation	LO-250	REPLACED TURBOCHARGER	4.5
	Description / Note		(preventative maintenance by owner)	
R	Part	VO-85020372	TURBOCHARGER, EXCH	1
R	Part	VO-276807	D12 TURBO GASKET KIT	1
R	Part	VO-22718180	KIT EX Man Kit D13A D13C D13K	1
W	Operation	VO-1706700	30 Months ECU download and oil sample. O	0.9
W	Part	VO-8394887	KIT OIL TEST	4
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2018-03-02 | Mileage: 481670 km | Order No: 8526150

PC	Type	Code	Description (Original)	#
R	Operation	LO-859	CAB TILT ALARM RINGING	0.5
	Description / Note		DARYL CALLED TO CHECK IF WE HAVE A SENSOR IN STOCK	
R	Part	VO-20382529	SWITCH CAB LOCK	1
	Description / Note		PARTÄ 20382529.	
	Description / Note		Cause: Faulty RH cab lock switch.	
	Description / Note		Check cab is locked down, all ok, test both cab lock	

PC	Type	Code	Description (Original)	#
	Description / Note		sensors, found RH side faulty, R&R sensor and retest, all	
	Description / Note		ok.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2018-02-09 | Mileage: 420030 km | Order No: 4280467

PC	Type	Code	Description (Original)	#
R	Part	VO-20920705	SILENCER	1
	Description / Note		MUFFLER TO BE CREDITED AS AUTHORIZED BY MICHAEL GOMERSALL AN	

(A) 2018-02-08 | Mileage: 457475 km | Order No: 8418997

PC	Type	Code	Description (Original)	#
W	Part	VO-22321903	EXHAUST PIPE	1
	Description / Note		VO/22321903 WAS FITTED BY BRANCH 4700	
W	Operation	VO-2522800	Flexible exhaust pipe, replace	0.3

(A) 2018-01-31 | Mileage: 420030 km | Order No: 8419021

PC	Type	Code	Description (Original)	#
W	Other	2586200	SCR catalytic muffler, replace	
W	Part	VO-20920705	SILENCER	1

(A) 2018-01-17 | Mileage: 451577 km | Order No: T61777

PC	Type	Code	Description (Original)	#
W	Operation	VO-2586200	SCR catalytic muffler, replace	1.9
W	Operation	VO-7211100	Front spring, replace (right hand side)	2.4
W	Part	VO-25339078	HEXAGON NUT	4
W	Part	VO-257938	FRONT SPRING	1
W	Part	VO-994102	HEXAGON SCREW	4

(A) 2017-11-09 | Mileage: 420030 km | Order No: 8419021

PC	Type	Code	Description (Original)	#
W	Operation	VO-2586200	SCR catalytic muffler, replace	
W	Part	VO-20920705	SILENCER	1

(A) 2017-11-09 | Mileage: 420030 km | Order No: 8418209

PC	Type	Code	Description (Original)	#
R	Operation	VO-1701200	Fault codes, reading	0.2
R	Part	VO-20920705	SILENCER	1

PC	Type	Code	Description (Original)	#
R	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
R	Operation	VO-2500500	Response, test drive	0.4
R	Operation	VO-2522200	Exhaust system complete, replace	1.4
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2017-10-05 | Mileage: 401199 km | Order No: 8417911

PC	Type	Code	Description (Original)	#
W	Operation	VO-2850800	Exhaust back pressure sensor, replace	0.2
W	Operation	VO-1706600	24 Months ECU download and oil sample. O	0.9
	Description / Note		Only valid for Australian market	
W	Part	VO-85139619	EXH BACK PRESS SENSOR	1
W	Part	VO-21582423	ROUND 4 WIRE PLUG KIT	1
W	Part	VO-8394887	KIT OIL TEST	4
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-1701200	Fault codes, reading	0.2

(A) 2017-09-29 | Mileage: 396286 km | Order No: 8256830

PC	Type	Code	Description (Original)	#
W	Operation	VO-2531400	Control cylinder exhaust brake, replace	0.6
W	Part	VO-22889891	ACTUATOR SERVICE K	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2840700	Sensor values, check	0.2
W	Operation	VO-3710200	Electric wires and connections, check	0.4

(A) 2017-09-26 | Mileage: 394190 km | Order No: 8417836

PC	Type	Code	Description (Original)	#
W	Operation	VO-2510400	Gaskets, exhaust manifold, replace	1.8
W	Part	VO-276807	D12 TURBO GASKET KIT	1
W	Part	VO-1543499	NUT 10MM	4
W	Part	VO-20855371	GASKET	6
W	Other	20	Machine manifold	
W	Part	VO-21312238	CHARGE AIR HOSE	1
	Description / Note		Fastbrake Machining	
W	Operation	VO-2501200	Intercooler system, leakage test	0.6
W	Operation	VO-2652200	Charge air hose, replace	0.1

(A) 2017-06-13 | Mileage: 331801 km | Order No: 8524005

PC	Type	Code	Description (Original)	#
R	Operation	LO-210	R&R LEAKING EXHAUST FLEX	1.75
	Description / Note		AND RE-REPAIR DAMAGED AIRLINE FROM HOT EXHAUST.	
R	Part	VO-22321903	EXHAUST PIPE	1
R	Part	VO-992304	PIPE RETAINER 12MM	1
R	Part	VO-980833	PLASTIC PIPE,12MM	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2017-06-05 | Mileage: 327367 km | Order No: 7570581

PC	Type	Code	Description (Original)	#
	Description / Note		DARRYL 0409 340 793 WORKSHOP MANAGER	
R	Operation	LO-261	Replace heater hose clamp on pipe from	1
R	Part	VO-994556	HOSE CLAMP	2
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2017-04-10 | Mileage: 297882 km | Order No: 8416368

PC	Type	Code	Description (Original)	#
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
	Description / Note		NOTE: Please reference AST 28 202 01 before	
W	Operation	VO-1706500	18 Months ECU download and oil sample. O	0.9
W	Part	VO-8394887	KIT OIL TEST	4

(A) 2017-02-20 | Mileage: 239380 km | Order No: 8251238

PC	Type	Code	Description (Original)	#
I	Other	810	CHECK AEROFOIL NOISY/BANGING	
I	Part	VO-20549020	BEARING	1
	Description / Note		Fit new bushing to pipe to support aerofoil. Tested	
	Description / Note		operation, all OK	

(A) 2017-02-15 | Mileage: 239380 km | Order No: 412737

PC	Type	Code	Description (Original)	#
R	Operation	LO-810	CHECK AEROFOIL NOISY/BANGING	0.4
R	Part	VO-20549020	BEARING	1
	Description / Note		Fit new bushing to pipe to support aerofoil. Tested	
	Description / Note		operation, all OK	

PC	Type	Code	Description (Original)	#
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2017-01-30 | Mileage: 260273 km | Order No: 8250681

PC	Type	Code	Description (Original)	#
W	Operation	VO-8743100	Evaporator, replace	0.5
	Description / Note		C3628 Cab, interior lights, cable harness, install. FH (4)	
W	Operation	LO-3540800	Interior Lights, Cable Harness, Install	0.5
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2549400	ACM, SW, update. only campaign	0.2
W	Part	VO-82348991	EVAPORATOR	1
W	Part	VO-82356760	O-RING	1
W	Part	VO-82386482	O-RING	1
W	Part	VO-82693739	ACCUMULATOR	1
W	Part	VO-22935545	WIRES	8
W	Part	VO-82354791	VENTILATION FILTER	1
W	Part	VO-82348995	VENTILATION FILTER	1
W	Part	VO-84180960	HOSE	1
W	Operation	VO-8741400	Cooling unit, performance test	0.3
W	Operation	VO-8701200	Air conditioning system, install	1.2
W	Operation	VO-8701000	Air conditioning system, remove	0.8

(A) 2016-12-23 | Mileage: 0 km | Order No: 8250152

PC	Type	Code	Description (Original)	#
I	Other	810	CAB ROOF FOIL BUSH MISSING	
	Description / Note		Please order VO - 20549020	

(A) 2016-12-13 | Mileage: 239380 km | Order No: 8249622

PC	Type	Code	Description (Original)	#
R	Operation	LO-810	CHECK AEROFOIL NOISY/BANGING	0.4
R	Part	VO-20549020	BEARING	1
	Description / Note		Fit new bushing to pipe to support aerofoil. Tested	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2016-10-31 | Mileage: 212212 km | Order No: 8248423

PC	Type	Code	Description (Original)	#
R	Operation	LO-561	AIR DRYER FAULT ON DASH	0.5
	Description / Note		Removed and replaced suzi line - split and leaking.	

PC	Type	Code	Description (Original)	#
R	Part	AU2-TRAIL200103	SUZI COIL - SHORT TAIL	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2016-09-26 | Mileage: 191550 km | Order No: 8247506

PC	Type	Code	Description (Original)	#
W	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
	Description / Note		oil changes included only in some models	
W	Operation	VO-1706400	12 Months ECU download and oil sample. O	0.9
W	Operation	VO-8100300	12 Months cab inspection	0.4
W	Operation	VO-3656500	Wiring harness, install. Only campaign	3
W	Part	VO-8394887	OIL TEST KIT	4
R	Part	VO-82354791	VENTILATION FILTER	1
R	Part	VO-82348995	VENTILATION FILTER	1
I	Part	MK-NARV56306	CABLE TIE 1=10PK	1
I	Part	MK-NARV56300	CABLE 1=10PK TIE	1
R	Other	1774600	Annual service - PARTS	
W	Operation	VO-1702600	Program control unit	0.1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-3710200	Electric wires and connections, check	0.4

(A) 2016-09-23 | Mileage: 188427 km | Order No: 8615396

PC	Type	Code	Description (Original)	#
R	Other	1701000	SYSTEM FAULT ON DISPLAY AND ALARM.	
	Description / Note		CURRENT ENGINE HOURS 2535 HOURS.	

(A) 2016-08-16 | Mileage: 170489 km | Order No: 8414600

PC	Type	Code	Description (Original)	#
W	Operation	VO-8600100	Cab tilt pump, check. Campaign only	0.5
	Description / Note		C3538 Cab tilt pump, filler plug, replace. FH (4)	
W	Operation	VO-8350500	Window lift, replace	0.9
W	Part	VO-22861085	REPAIR KIT	1
W	Part	VO-84062949	ELECTRIC MOTOR	1
W	Part	VO-84226000	COVER PLATE	1
W	Operation	VO-8600200	Cab tilt cylinder check. Campaign only	0.7

(A) 2016-07-12 | Mileage: 148679 km | Order No: 8414359

PC	Type	Code	Description (Original)	#
	Description / Note		2014 hr	
R	Operation	LO-258	Adblue fault	1.9
R	Part	VO-21516229	FILTER	1
R	Part	VO-21954674	STRAINER	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2016-05-31 | Mileage: 121656 km | Order No: 8414044

PC	Type	Code	Description (Original)	#
W	Operation	VO-2520300	Exhaust pipe, replace (EPG housing to fl	0.5
W	Other	K	1655 hr	
W	Part	VO-22321903	EXHAUST PIPE	1
	Description / Note		flex pipe)	

(A) 2016-05-09 | Mileage: 107231 km | Order No: 7559130

PC	Type	Code	Description (Original)	#
	Description / Note		Paul in the office: 0411-663-714	
W	Operation	VO-2531400	Control cylinder exhaust brake, replace	0.6
W	Part	VO-21887528	ACTUATOR SERVICE K	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-1701200	Fault codes, reading	0.2
W	Operation	VO-2533600	Engine brake function, test	0.4
W	Operation	VO-2534000	Warm hold function, test	0.2
W	Operation	VO-2500500	Response, test drive	0.4

(A) 2016-04-12 | Mileage: 93223 km | Order No: 8413719

PC	Type	Code	Description (Original)	#
	Description / Note		1271hrs	
W	Operation	VO-1706300	6 Months ECU download and oil sample. On	0.9
W	Part	VO-8394887	KIT OIL TEST	4

(A) 2016-03-18 | Mileage: 87705 km | Order No: 8413549

PC	Type	Code	Description (Original)	#
I	Operation	LO-8000	Water leaking into cab	2.99
I	Operation	LO-350	Headlight surround cracked	3.85
I	Part	VO-21874457	PANEL	1
W	Operation	VO-2530400	Solenoid valve exhaust brake, replace	0.5

PC	Type	Code	Description (Original)	#
	Description / Note		S3485 Instrument cluster, SW update. FH/FM (4)	
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-3815800	IC, SW update. Campaign only	0.3
W	Operation	VO-1701200	Fault codes, reading	0.2
W	Part	VO-21887528	VEB ACTUATOR SERVIC KIT D13/16	1
I	Other	20	Paint panel	
I	Part	MK-5166-252CTGBLACK	SIKAFLEX, SEALANT	1

(A) 2015-11-05 | Mileage: 14408 km | Order No: 8066018

PC	Type	Code	Description (Original)	#
W	Operation	VO-2530000	Exhaust brake, exhaust pressure governor	0.6
I	Other	350	TURN OFF THE DAY RUNNING LIGHT.	
I	Other	2750300	CHECK CRUISE CONTROL OPERATION	
	Description / Note		WITH THE DRIVER.	
W	Part	VO-21994000	PIPE SET	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-1701200	Fault codes, reading	0.2

(A) 2015-11-02 | Mileage: 0 km | Order No: 8412575

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2015-10-29 | Mileage: 11084 km | Order No: 8412563

PC	Type	Code	Description (Original)	#
W	Operation	VO-2850000	Combined control system. Secondary opera	0.5
	Description / Note		156 hr	
W	Part	VO-21994000	PIPE SET	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-1701200	Fault codes, reading	0.2

(A) 2015-10-28 | Mileage: 8512 km | Order No: 8412548

PC	Type	Code	Description (Original)	#
	Description / Note		123hr	
W	Operation	VO-1721000	Warranty service. After 4 weeks or maxim	2
	Description / Note		maximum 10 000 km.	

PC	Type	Code	Description (Original)	#
I	Operation	LO-170	Set speed	1
	Description / Note		Re attach loose / incorrectly installed RH interior cab roof	
	Description / Note		trim.	
	Description / Note		Speed limiter set to low, adjust K-factor to achieve 100km/h	
	Description / Note		Check & clear all inactive fault codes 17012-3.	

(A) 2015-09-21 | Mileage: 1234 km | Order No: 8064449

PC	Type	Code	Description (Original)	#
I	Operation	LO-820	PAINT 2X AIR DEFLCETOR PANELS	4
	Description / Note		- GENERAL	
I	Other	MTPAINT	PANELSHOP PAINT	
I	Other	91	PANELSHOP CONSUMABLES	
	Description / Note		REFER JOE SCALIA	
	Description / Note		ORDER NO;411856	

(A) 2015-09-07 | Mileage: 70 km | Order No: 8063862

PC	Type	Code	Description (Original)	#
W	Operation	VO-2580000	Emissions after-treatment. Secondary ope	1.5
W	Other	20	PIRTEK	
W	Part	VO-20748166	CONNECTOR,SAE 3/8	1
W	Part	VO-993960	HOSE CLAMP 16-25mm	1
W	Part	VO-20915849	HOSE CLAMP 16-27mm	1
W	Part	VO-3944785	AIR FILTER - COMP/ ADBLUE	1
W	Part	VO-20823440	RUBBER STOP	1
W	Part	VO-21032572	CLAMP	1
W	Part	VO-21429181	HOSE	4
W	Part	VO-22679934	T-PIPE	1
I	Part	MK-NARV56310	CABLE TIE 1=10PK	1

(A) 2015-09-03 | Mileage: 68 km | Order No: 8063432

PC	Type	Code	Description (Original)	#
I	Operation	LO-171	PRE DELIVERY	6.5
I	Other	10	VEHICLE DETAIL	
I	Other	10	TARE WEIGHT	
I	Other	10	CUSTOM BADGE	

PC	Type	Code	Description (Original)	#
I	Operation	LO-360	DISABLE LOW AMP WARNING PARAMETER	1
I	Operation	LO-360	SET/PROGRAM ENGINE IDLE SHUTDOWN 3 (OR)	1
	Description / Note		MINUTES	
I	Operation	LO-360	TEST/CHECK PTO SOLENOIDS ARE CONNECTED	1
	Description / Note		WITH AIR, POWERED, EARTHED AND WORKING	
I	Operation	LO-360	SUPPLY ACCESSORY WIRE FOR UHF	2.5
	Description / Note		AND ADVISE TREVOR AT PRO AUDIO	
I	Part	MK-NARV56306	CABLE TIE 1=25PK	1
I	Part	MK-NARV56820BK	TAPE NITTO BLACK	1
I	Part	VO-9130476	SPLICE BLUE, HEAT SHRINK	4
I	Part	VO-6781769	SPLICE RED	4
I	Operation	LO-852	SHEEP SKIN SEAT COVERS	1
I	Part	OTH-VSHEEPPAIRV1BV4	VOLVO SHEEP PAIR V4	1
I	Other	237	ADD BLUE FILL UP	
	Description / Note		35L OF ADD BLUE USED	